

WASC-2371
WAI-1224

RARDE-ESG
PHOTO LOG
1995

WASC-2371

REPORT NO. ESG 2060/94
FORMER RARDE

WALTHAM ABBEY (NORTH SITE)
REMEDIATION PROJECT
PHOTOGRAPHIC LOG

INDEX FOR
PHOTOGRAPHIC RECORD

Environmental Services Group
Property Services Department
Royal Ordnance plc
Westcott
Aylesbury
Bucks. HP18 0NZ

DATE: September 1995 (Issue A)



BRITISH AEROSPACE
DEFENCE
ROYAL ORDNANCE
ENVIRONMENTAL SERVICES GROUP



WASC
2371

PROPERTY SERVICES GROUP
PROPERTY SERVICES DEPARTMENT
ROYAL ORDNANCE PLC
WESTCOTT
AYLESBURY
BUCKS. HP18 0NZ

INDEX FOR
PHOTOGRAPHIC RECORD



REPORT NO. ESG 2060/94

FORMER RARDE

WALTHAM ABBEY (NORTH SITE)

REMEDIATION PROJECT

PHOTOGRAPHIC LOG

INDEX FOR
PHOTOGRAPHIC RECORD

Environmental Services Group
Property Services Department
Royal Ordnance plc
Westcott
Aylesbury
Bucks. HP18 0NZ

DATE: September 1995 (Issue A)



BRITISH AEROSPACE
DEFENCE

ROYAL ORDNANCE
ENVIRONMENTAL SERVICES GROUP

REMEDIATION RECORD

NEGATIVE REFERENCE: B

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1	SEP '91	P	AREA 'P' SOUTH - LOOKING NORTH (BUILDING A238 TO RIGHT OF SHOT)	i
2			NOT USED	
3	SEP '91	B	SOUTH ELEVATION OF BUILDING L137	ii
4	SEP '91	M	BUILDING L149 PART EAST ELEVATION (MILLSTONE IN FOREGROUND)	iii
5	SEP '91	M	BUILDING L149 PART EAST ELEVATION	iv
6	SEP '91	L / M	NORTHERN VIEW ACROSS QUEENS MEAD TOWARDS BUILDING L148	v
7	SEP '91	S	BRIDGE No. 29 - EAST OF BUILDING L136	vi
8	SEP '91	S	BARGES NORTH OF BUILDING L136	vii
9	SEP '91	S	BARGE ADJACENT TO BUILDING L111	viii
10	SEP '91	S	BARGE ADJACENT TO BUILDING L111	ix
11	SEP '91	S	BUILDING L109 TRAVERSE	x
12	SEP '91	M	EAST ELEVATION OF BUILDING L108 AND ASBESTOS LAGGED STEAM MAIN PIPE (IN FOREGROUND)	xi
13	SEP '91	S	BUILDING L199 (SOUTH WEST CORNER)	xii
14	SEP '91	B	TIP REF.: 11038 NORTH OF BURNING GROUND	xiii
15	SEP '91	S	TYPICAL EARTH CLOSET ADJACENT BUILDING U9	xiv
16	SEP '91	S	TYPICAL CHEMICAL TOILET	xv
17	SEP '91	S	'BARREL GRAVEYARD' (TYPICAL VIEW OF ROTTING STEEL BARRELS)	xvi
18	SEP '91	H	WEST ELEVATION OF BUILDING H26	xvii
19	SEP '91	S	WATER POWERED PRESS HOUSE - BUILDING 103 (HYDRAULIC GUNPOWDER PRESS)	xviii
20	SEP '91	S	WATER POWERED PRESS HOUSE - BUILDING 103 (INTERNAL VIEW OF WATER WHEEL DRIVE SHAFT)	xix
21	SEP '91	S	WATER POWERED PRESS HOUSE - BUILDING 103 (WATER WHEEL AND SUSPICIOUS CANISTER)	xx
22	SEP '91	S	INFORMAL TIP	xxI
23	SEP '91	S	INFORMAL TIP - VARIOUS CONSTITUENTS INCLUDING CHEMICAL / LABORATORY WARE	xxii
24	SEP '91	B	BURNING GROUND - LOOKING NORTH EAST (TIP REF.: 11038 IN BACKGROUND)	xxiii
24a	SEP '91	S	PART VIEW LOOKING WEST ACROSS ACID FACTORY (SUPPORT STEELWORK FORM SOME EXPERIMENTAL USAGE OF THIS AREA)	xxiv

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: C

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1			NOT USED	
2			NOT USED	
3			NOT USED	
4			NOT USED	
5			NOT USED	
6			NOT USED	
7			NOT USED	
8			NOT USED	
9	SEP '91	S	MILLHEAD STREAM (BURIED ASBESTOS SHEETING)	xxv
10	SEP '91	S	ENTRANCE TO BUILDING E2	xxvi
11	SEP '91	S	BUILDING S31	xxvii
12	SEP '91	S	BUILDING E2	xxviii
13	SEP '91	S	NITRO GLYCERINE SHUTE - BUILDING E2 - E3	xxix
14	SEP '91	S	BUILDING E2, NITRO GLYCERINE POPPING POND	xxx
15	SEP '91	S	BUILDING E3 (INTERNAL)	xxxi
16	SEP '91	S	PART FILLED CANAL ADJACENT BUILDING 62	xxxii
17	SEP '91	S	BUILDING 73 - EDMONSEY MEAD	xxxiii
18	SEP '91	S	TRAVERSE 76 (ADJACENT BUILDING E14)	xxxiv
19	SEP '91	S	BARGE 101 NEAR TRAVERSE 76	xxxv
20	SEP '91	S	BARGE 101 (INTERNAL)	xxxvi
21	SEP '91	S	BRIDGE No. 15	xxxvii
22	SEP '91	H	BUILDINGS A201 / A202	xxxviii
23	SEP '91	N	BUILDING S16 SOUTH ELEVATION	xxxix
24	SEP '91	N	NEW HILL - LOOKING SOUTH	xl

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: D

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1	SEP '91	N	BUILDING S25 CHANNEL	xli
2	SEP '91	N	CHANNEL EXITING BUILDING S16 (WEST)	xlii
3	SEP '91	N	INTERNAL VIEW OF BUILDING S25	xliii
4	SEP '91	N	NEW HILL - BUILDING S16 ENTRANCE (STEAM MAIN ROUTE POST VISIBLE)	xliv
5	SEP '91	N	MANHOLE NEAR BUILDING S16	xliv
6	SEP '91	N	CATTLEGATE WAY LOOKING EAST	xlvi
7	SEP '91	N	NEW HILL - BUILDINGS S10 AND S11	xlvii
8	SEP '91	N	NEW HILL - BUILDING S13	xlviii
9	SEP '91	N	NEW HILL - BUILDING S5 LOOKING WEST ALONG CATTLEGATE WAY	xlix
10	SEP '91	S	GRAND MAGAZINE	1
11			NOT USED	
12			NOT USED	
13			NOT USED	
14			NOT USED	
15			NOT USED	
16	SEP '91	P	SOCIAL CLUB - BUILDING A250	li
17	SEP '91	P	AREA 'P' TENNIS COURTS	lii
18	SEP '91	P	VIEW NORTH TOWARDS BUILDING A282	liii
19	SEP '91	P	TENNIS COURTS	liv
20	SEP '91	P	BUILDING A210	lv
21	SEP '91	P	BUILDING A210	lvi
22	SEP '91	P	BUILDINGS A210 AND A214	lvii
23	SEP '91	P	BUILDING A214 (TO RIGHT OF SHOT) WITH BUILDING A221 IN DISTANCE	lviii
24	SEP '91	M	BUILDING L162 IN BACKGROUND (CORDITE CONTAMINATED AREA)	lix
25	SEP '91	M	BUILDING L160 IN THE GASWORKS AREA	lx

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: E

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1	SEP '91	H	NORTH ELEVATION OF BUILDING A200	lxi
2	SEP '91	M	EAST ELEVATIONS OF BUILDINGS L176 AND L168	lxii
3	SEP '91	M	LOOKING NORTH AT ROUNDABOUT WITH LONG WALK IN BACKGROUND	lxiii
4	SEP '91	M	LOOKING EAST AT ROUNDABOUT WITH AREA 'H' IN BACKGROUND	lxiv
5	SEP '91	M	BRIDGE No. 4 - BUILDING L167 - BUILDING L170	lxv
6	SEP '91	L	LONG WALK LOOKING NORTH	lxvi
7	SEP '91	H	VIEW LOOKING SOUTH ACROSS AREA 'H' FROM HOPPIT ROAD - BUILDING H8 TO RIGHT OF SHOT	lxvii
8	SEP '91	S	ASBESTOS FOUND LYING ON SURFACE (GENERAL PROBLEMS WHERE OVERGROWN STEAM MAIN ROUTES AREA)	lxviii
9	SEP '91	H	MILLHEAD LOCK	lxix
10	SEP '91	H	BUILDING H67 SOUTH ELEVATION	lxx
11	SEP '91	H	VIEW OF NORTH ELEVATIONS OF BUILDINGS H17 AND H10 VIEWED FROM BUILDING H8	lxxi
12	SEP '91	H / M	ROUNDABOUT VIEWED FROM BUILDING H8 AND HOPPIT ROAD	lxxii
13	SEP '91	H	BUILDINGS H17 AND H10 VIEWED FROM BUILDING H8	lxxiii
14	SEP '91	H	OVERGROWN CANAL NORTH OF HOPPIT POOL	lxxiv
15	SEP '91	H	NORTH OF HOPPIT POOL - BUILDING A292 IN BACKGROUND	lxxv
16	SEP '91	H	NORTH OF HOPPIT POOL	lxxvi
17	SEP '91	H	BUILDINGS H72 AND H10 - NORTH ELEVATIONS (STEAM MAIN ROUTE)	lxxvii
18	SEP '91	H	BUILDING H12 - LOOKING SOUTH (STEAM MAIN ROUTE)	lxxviii
19	SEP '91	H	BUILDING H13 - LOOKING SOUTH TOWARDS HIGHBRIDGE STREET	lxxix
20	SEP '91	P	NORTH AREA 'P' - BUILDING A234 TO RIGHT OF PICTURE	lxxx
21	SEP '91	B	BURNING GROUND - BUILDINGS L102 AND L103 IN BACKGROUND	lxxxii
22	SEP '91	T	TETRYL FACTORY AREA - SUSPECT PIT	lxxxiii
23	SEP '91	S	TETRYL FACTORY AREA LOOKING SOUTH	lxxxiv
24	SEP '91	B	BURNING GROUND LOOKING SOUTH - BUILDING L102 TO RIGHT OF PICTURE	lxxxv
24a	SEP '91	S	INFORMAL PIT	lxxxv

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: A

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1			NOT USED	
2	OCT '92	H	H16 FOUNDATION SLAB PRIOR TO USE AS WASTE SAMPLING AREA	lxxxvi
3	OCT '92	H	VIEW NORTH ACROSS H16 FOUNDATION SLAB WITH BUILDING H12 IN CENTRE OF PHOTOGRAPH	lxxxvii
4	OCT '92	H	SOUTHERLY VIEW ACROSS SITE OF FORMER BUILDING H19 WITH BUILDING IN BACKGROUND	lxxxviii
5	OCT '92	H	WEST VIEW ACROSS SITE OF FORMER BUILDING H19 TOWARDS HOUSING IN WALTON GARDENS	lxxxix
6	OCT '92	H	INTERNAL VIEW OF BUILDING H12	xc
7	OCT '92	H	NORTH ENTRANCE TO BUILDING H12	xc i
8	OCT '92	H	HOPPIT POOL SLUICES VIEWED FROM BRIDGE No. 17	xcii
9	OCT '92	H	BUILDING H8 - SOUTH ELEVATION	xciii
10	OCT '92	H	BUILDING H8 - SOUTH ENTRANCE	xciv
11	OCT '92	H	BUILDING H7 SOUTH ELEVATION	xcv
12	OCT '92	H	MILLHEAD LOCK SITUATED NORTH EAST OF BUILDING H67	xcvi
13	OCT '92	S	MILLHEAD STREAM NORTH OF MILLHEAD LOCK	xcvii
14	OCT '92	S	TYPICAL WASTE TIP SITUATED WITH SSSI	xcviii

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: 1/5192

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1			NOT USED	
2			NOT USED	
3			NOT USED	
4			NOT USED	
5	OCT '92	T	TETRYL FACTORY - BREAKING OUT CONCRETE FOUNDATION BASES	1
6	OCT '92	T	TETRYL FACTORY - BREAKING OUT CONCRETE FOUNDATION BASES	2
7	OCT '92	P	MOBILE LAB. FOR 'ASBESTOS IN AIR' MONITORING WITHIN BUILDINGS	3
8	OCT '92	P	INTERIOR VIEW OF BUILDING A210 - SAMPLING (AIR MONITORING PUMP)	4
9	OCT '92	P	INTERIOR VIEW OF BUILDING A210 - SAMPLING (AIR MONITORING PUMP)	5
10	OCT '92	P	INTERIOR VIEW OF BUILDING A210 - SAMPLING (AIR MONITORING PUMP)	6
11	OCT '92	P	INTERIOR VIEW OF BUILDING A210 - SAMPLING (AIR MONITORING PUMP)	7
12	OCT '92	P	PERSONNEL DECONTAMINATION UNIT	8
13	OCT '92	P	PIPE CLAD IN ASBESTOS LAGGING, WRAPPED PRIOR TO DISPOSAL	9
14	OCT '92	T	HEAVY CONCRETE FOUNDATION BASE BROKEN UP, FOR DISPOSAL	10
15	OCT '92	P	LINK BETWEEN BUILDING A235 & BUILDING A238 - NORTH ELEVATION	11
16	OCT '92	P	EAST ELEVATION OF BUILDING A266 - TIMBER & ASBESTOS CONSTRUCTION	12
17	OCT '92	P	N/W ELEVATION OF BUILDING A288 (TOILET EXTENSION TO BLDG. A269)	13
18	OCT '92	P	NORTH ELEVATION OF BUILDING A289 - ASBESTOS ROOF SHEETS	14
19	OCT '92	P	NORTH EAST ELEVATION OF BUILDING A289 - ASBESTOS ROOF SHEETS	15
20	OCT '92	P	EAST ELEVATION OF BUILDING A271 - OVERGROWN WITH TREES & SHRUBS	16
21	OCT '92	P	EAST ELEVATION OF BUILDING A271 - OVERGROWN WITH TREES & SHRUBS	17
22	OCT '92	P	EAST ELEVATION OF BUILDING A273 - ASBESTOS ROOFING & GABLE CLAD.	18
23	OCT '92	P	WEST ELEVATION OF BUILDING A273 - ASBESTOS ROOF SHEETING	19
24	OCT '92	P	SOUTH WEST ELEVATION OF BUILDING A272 - ASPHALT FLAT ROOF	20
25	OCT '92	P	EAST ELEVATION OF BUILDING A282 - ASBESTOS WALL & ROOF CLADDING	21
26	OCT '92	P	EAST ELEVATION OF BUILDING A284 - ASBESTOS ROOF & GABLE CLADDING	22
27	OCT '92	P	EAST ELEVATION OF BUILDING A284 - ASBESTOS ROOF & GABLE SHEETING	23
28	OCT '92	P	VIEW FROM BLDG. A269 (UPSTAIRS) - BLDG'S A266, A230 & A288 IN PICTURE	24
29	OCT '92	P	VIEW WEST SHOWING ROOF OF BUILDING A273 IN THE FOREGROUND	25
30	OCT '92	P	VIEW S/W SHOWING ROOF OF BUILDING A272 - ASBESTOS ROOF SHEETS	26
31	OCT '92	P	WEST ELEVATION OF POWDERMILL LANE GATES BETWEEN A269 & A238	27
32	OCT '92	P	WEST ELEVATION OF POWDERMILL LANE GATES - CANON BALL BOLLARDS	28
33	OCT '92	S	REMOVAL OF ASBESTOS FROM TETRYL DRYING STOVES - ASBESTOS POOR	29
34	OCT '92	M	INTERNAL VIEW OF BUILDING L162	30
35	OCT '92	M	INTERNAL VIEW OF BUILDING L162 - ASBESTOS ROOF SHEETING	31
36	OCT '92	S	ASBESTOS COLLECTION FROM TETRYL DRYING STOVES - BAD TERRAIN	32
37	OCT '92	S	ASBESTOS COLLECTION FROM TETRYL DRYING STOVES - BAD TERRAIN	33

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: 2/5193

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1	OCT '92	S	SURFACE WATER EARTHENWARE DRAIN	34
2	OCT '92	S	ASBESTOS SHEETING AS FOUND - GENERAL POOR CONDITION OF SHEETS	35
3	OCT '92	S	ASBESTOS SHEETING AS FOUND - GENERAL POOR CONDITION OF SHEETS	36
4	OCT '92	S	ASBESTOS SHEETING AS FOUND - GENERAL POOR CONDITION OF SHEETS	37
5	OCT '92	S	COLLECTING LABORATORY GLASSWARE AND BOTTLED CHEMICALS	38
6	OCT '92	S	SITE CLEARANCE PLANT TO ENABLE ACCESS FOR GENERAL CLEARANCE	39
7	OCT '92	M	SOUTH EAST ELEVATION OF BUILDING L113 - GENERAL POOR CONDITION	40
8	OCT '92	M	NORTH WEST ELEVATION OF BUILDING L113	41
9	OCT '92	M	SOUTH WEST ELEVATION OF BUILDING L112 - ASBESTOS SHEET ROOFING	42
10	OCT '92	M	NORTH EAST ELEVATION OF BUILDING L112 - SOLVENT STORAGE PLACE	43
11	OCT '92	M	WEST ELEVATION OF BUILDING L197 - ASBESTOS END PANELS	44
12	OCT '92	M	EAST ELEVATION OF BUILDING L197 - ASBESTOS END PANELS	45
13	OCT '92	M	EAST ELEVATION OF BUILDING L161 - GARAGE / STORE	46
14	OCT '92	M	WEST ELEVATION OF BUILDING L161 - GARAGE / STORE	47
15	OCT '92	M	NORTH ELEVATION OF BUILDING L161 - GARAGE / STORE (POOR STATE)	48
16	OCT '92	M	NORTH ELEVATION OF BUILDING L162 - GENERAL POOR CONDITION	49
17	OCT '92	M	SOUTH ELEVATION OF BUILDING L162 - GENERAL POOR CONDITION	50
18	OCT '92	M	EAST ELEVATION OF BUILDING L163 - OVERGROWN WITH VEGETATION	51
19	OCT '92	M	NORTH EAST ELEVATION OF BUILDING L163 - OVERGROWN WITH TREES	52
20	OCT '92	M	NORTH ELEVATION OF BUILDING L127 - GARAGE WITH VEHICLE HOIST	53
21	OCT '92	M	SOUTH WEST ELEVATION OF BUILDING L127 - GARAGE	54
22	OCT '92	M	NORTH WEST ELEVATION OF No. 1 GREENHOUSE - POOR CONDITION	55
23	OCT '92	M	ELEVATION OF No. 2 GREENHOUSE - GENERAL POOR CONDITION	56
24	OCT '92	M	NORTH ELEVATION OF BUILDING L169 - ASBESTOS SHEET ROOFING	57
25	OCT '92	M	EAST ELEVATION OF BUILDING L169 - ASBESTOS SHEET ROOFING	58
26	OCT '92	M	SOUTH WEST ELEVATION OF BUILDING L169 - ASBESTOS SHEET ROOFING	59
27	OCT '92	M	EAST ELEVATION OF BUILDING L173 - GENERAL POOR CONDITION	60
28	OCT '92	M	NORTH ELEVATION OF BUILDING L173 - GENERAL POOR CONDITION	61
29	OCT '92	P	EAST ELEVATION OF BUILDING A210 (D) - WELDING SHOP (FOREGROUND)	62
30	OCT '92	P	NORTH ELEVATION OF BUILDING A210 (D) - WELDING SHOP	63
31	OCT '92	P	EAST ELEVATION OF BUILDING A211 - ASBESTOS ROOF SHEETING	64
32	OCT '92	P	SOUTH WEST ELEVATION OF BUILDING A211 - ASBESTOS ROOF SHEETING	65
33	OCT '92	P	NORTH ELEVATION OF BUILDING A212 - ASBESTOS ROOF SHEETING	66
34	OCT '92	P	EAST ELEVATION OF BUILDING A212 - ASBESTOS ROOF SHEETING	67
35	OCT '92	P	NORTH EAST ELEVATION OF BUILDING A219 - TRANSPORT OFFICES	68
36	OCT '92	P	SOUTH EAST ELEVATION OF BUILDING A219 - TRANSPORT OFFICES	69
37	OCT '92	P	SOUTH WEST ELEVATION OF BUILDING A219 - TRANSPORT OFFICES	70

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: 3/5903

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1	OCT '92	P	SOUTH ELEVATION OF BUILDING A210 (B) - SOUTH CONCRETE BUNKER	71
2	OCT '92	P	WEST ELEVATION OF BUILDING A210 (B) - SOUTH CONCRETE BUNKER	72
3	OCT '92	P	WEST ELEVATION OF BUILDING A210 (A) - NORTH CONCRETE BUNKER	73
4	OCT '92	P	EAST ELEVATION OF BUILDING A210 (A) - NORTH CONCRETE BUNKER	74
5	OCT '92	P	PHASE 1 DEMOLITION IN PROGRESS - ASBESTOS ROOFING ETC. REMOVED	75
6	OCT '92	P	PHASE 1 DEMOLITION IN PROGRESS	76
7	OCT '92	P	PHASE 1 DEMOLITION IN PROGRESS	77
8	OCT '92	S	PIPE WRAPPED WITH BLUE ASBESTOS BRAID	78
9	OCT '92	S	FALLEN TELEGRAPH POLE	79
10	OCT '92	S	CLEARANCE OF BUILDING 92 (A) - GENERALLY OVERGROWN WITH TREES	80
11	OCT '92	S	CLEARANCE OF BUILDING 92 (A)	81
12	OCT '92	S	CLEARED RAILWAY ROUTE ADJACENT TO BUILDINGS 93A AND 96A	82
13	OCT '92	S	CLEARED RAILWAY ROUTE ADJACENT TO BUILDINGS 93A AND 96A	83
14	OCT '92	S	TYPICAL STEAM MAIN THROUGH WOODS - GENERAL POOR CONDITION	84
15	OCT '92	S	LONG WALK LOOKING NORTH - BUILDINGS 107 AND 108 ON LEFT	85
16	OCT '92	B/S	BURNING GROUND - TEMPORARY ACCESS ROAD	86
17	OCT '92	B/S	BURNING GROUND - TEMPORARY ACCESS ROAD	87
18	OCT '92	S	ELEVATION OF WALL (BASE) OF BUILDING S46 - ASBESTOS LAGGED PIPES	88
19	OCT '92	S	ELEVATION OF BUILDING S48 - BASE OF EXTERNAL WALL	89
20	OCT '92	S	SITE CLEARANCE WORKS BY BUILDING 18 - TREE FELLING	90
21	OCT '92		WALL PLAQUE - RE ENFIELD SITE (LOANED)	91
22	OCT '92		WALL PLAQUE - RE ENFIELD SITE (LOANED)	92
23	OCT '92		WALL PLAQUE - RE ENFIELD SITE (LOANED)	93
24	OCT '92		WALL PLAQUE - RE ENFIELD SITE (LOANED)	94
25	OCT '92		WALL PLAQUE - RE ENFIELD SITE (LOANED)	95

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: 4/5904

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1	OCT '92	B	CONSTRUCTION OF ACCESS ROAD TO WEST SIDE OF BURNING GROUND	96
2	OCT '92	B	CONSTRUCTION OF ACCESS ROAD TO WEST SIDE OF BURNING GROUND	97
3	OCT '92	B	CONSTRUCTION OF ACCESS ROAD TO WEST SIDE OF BURNING GROUND	98
4	OCT '92	H	NORTH EAST ELEVATION OF BUILDING H67 - GENERAL POOR CONDITION	99
5	OCT '92	H	NORTH ELEVATION OF BUILDING H67 - GENERAL POOR CONDITION	100
6	OCT '92	H	NORTH EAST ELEVATION OF BUILDING H67	101
7	OCT '92	H	SOUTH ELEVATION OF ENTRANCE TO BUILDING H67 - POOR CONDITION	102
8	OCT '92	H	SOUTH EAST ELEVATION OF BUILDING H68 - GENERAL POOR CONDITION	103
9	OCT '92	H	WEST ELEVATION OF BUILDING H68 - GENERAL POOR CONDITION	104
10	OCT '92	H	SOUTH ELEVATION OF STRUCTURE H68a - FIRING TUNNEL / PCC PIPE	105
11	OCT '92	H	SOUTH EAST ELEVATION OF BUILDING H7 - MAGAZINE	106
12	OCT '92	H	NORTH ELEVATION OF BUILDING H7 - MAGAZINE	107
13	OCT '92	H	SOUTH ELEVATION OF BUILDING H17 - SEWER PUMPING STATION	108
14	OCT '92	H	NORTH ELEVATION OF BUILDING H17 - SEWER PUMPING STATION	109
15	OCT '92	H	ACTIVE SEWER PUMPING STATION	110
16	OCT '92	H	NORTH WEST ELEVATION OF BUILDING H66 - ASBESTOS ROOF SHEETS	111
17	OCT '92	H	SOUTH EAST ELEVATION OF BUILDING H66 - ASBESTOS ROOF SHEETS	112
18	OCT '92	H	EAST ELEVATION OF BUILDING H11 - OVERGROWN WITH VEGETATION	113
19	OCT '92	H	WEST ELEVATION OF BUILDING H11 - SOLVENT AND CHEMICAL STORE	114
20	OCT '92	H	SOUTH WEST ELEVATION OF BUILDING H72	115
21	OCT '92	H	NORTH WEST ELEVATION OF BUILDING H72	116
22	OCT '92	H	SOUTH WEST ELEVATION OF BUILDING H72 (A)	117
23	OCT '92	H	SOUTH WEST ELEVATION OF BUILDING H69	118
24	OCT '92	H	NORTH ELEVATION OF BUILDING H69 - MAGAZINE (POOR CONDITION)	119
25	OCT '92	H	SOUTH WEST ELEVATION OF BUILDING H70 - GENERAL POOR CONDITION	120
26	OCT '92	H	NORTH EAST ELEVATION OF BUILDING H70 - BLDG H67 IN BACKGROUND	121
27	OCT '92	L	NORTH WEST ELEVATION OF BUILDING L165 (AFTER LEAN-TO REMOVAL)	122
28	OCT '92	L	NORTH WEST ELEVATION OF BUILDING L165 (AFTER LEAN-TO REMOVAL)	123
29	OCT '92	H	NORTH ELEVATION OF BUILDING H65 - LOCKER MAGAZINE	124
30	OCT '92	H	SOUTH ELEVATION OF BUILDING H65 - LOCKER MAGAZINE	125
31	OCT '92	H	SOUTH EAST ELEVATION OF BUILDING H13 - GENERAL POOR CONDITION	126
32	OCT '92	H	NORTH WEST ELEVATION OF BUILDING H13	127
33	OCT '92	H	NORTH WEST ELEVATION OF BUILDING H12 - GENERAL POOR CONDITION	128
34	OCT '92	H	INTERNAL ELEVATION OF BUILDING H12 - GENERAL POOR CONDITION	129
35	OCT '92	H	INTERNAL ELEVATION OF BUILDING H12 - GENERAL POOR CONDITION	130
36	OCT '92	H	SOUTH WEST ELEVATION OF BUILDING H14 - GENERAL POOR CONDITION	131
37	OCT '92	H	NORTH EAST ELEVATION OF BUILDING H14 - STORE SHED / MAGAZINE	132

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: 5/6285

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1	NOV '92	H	SOUTH WEST ELEVATION OF BUILDING H15 - CONCRETE AIR RAID SHELTER	133
2	NOV '92	H	SOUTH WEST ELEVATION OF BUILDING H15 - CONCRETE AIR RAID SHELTER	134
3	NOV '92	H	SOUTH WETS ELEVATION OF BUILDING H24 - SEWAGE PUMP HOUSE	135
4	NOV '92	H	NORTH EAST ELEVATION OF BUILDING H24 - SEWAGE PUMP HOUSE	136
5	NOV '92	H	EAST ELEVATION OF BUILDING H23 - STORAGE SHED	137
6	NOV '92	H	SOUTH WEST ELEVATION OF BUILDING H23 - STORAGE SHED	138
7	NOV '92	H	SOUTH ELEVATION OF BLDG H23 - SHED OVERGROWN WITH VEGETATION	139
8	NOV '92	H	EAST ELEVATION OF BUILDING H25 - SURGERY / WOMENS HOSPITAL / FLATS	140
9	NOV '92	H	WEST ELEVATION OF BUILDING H25 - SURGERY / WOMENS HOSPITAL / FLATS	141
10	NOV '92	H	WEST ELEVATION OF BUILDING H25 (A) - GENERAL POOR CONDITION	142
11	NOV '92	H	SOUTH ELEVATION OF BUILDING H26 - GENERAL POOR CONDITION	143
12	NOV '92	H	EAST ELEVATION OF BUILDING H26 - SANDHURST RESIDENTIAL HOSPITAL	144
13	NOV '92	H	NORTH WEST ELEVATION OF BUILDING H26 - SANDHURST HOSPITAL	145
14	NOV '92	H	SOUTH WEST ELEVATION OF BUILDING H26 - SANDHURST HOSPITAL	146
15	NOV '92	P	EAST ELEVATION OF BUILDING A235	147
16	NOV '92	P	NORTH ELEVATION OF LINK BETWEEN BLDG A238 AND BLDG A234	148
17	NOV '92	P	NORTH ELEVATION OF LINK BETWEEN BLDG A238 AND BLDG A234	149
18	NOV '92	S	ELEVATION OF BUILDING ARS 1 - GENERAL POOR CONDITION	150
19	NOV '92	S	ELEVATION OF BUILDING ARS 1 - GENERAL POOR CONDITION	151
20			NOT USED	
21	NOV '92	N	SQUIRREL EATING AN APPLE	152
22	NOV '92	N	SITE WASTE TRANSFER STATION	153
23	NOV '92	N	SITE WASTE TRANSFER STATION	154
24	NOV '92	S	MINI EXCAVATOR EN-ROUTE TO NEXT TASK	155
25	NOV '92	S	R.O. SUPERVISOR CO ORDINATING SITE WORK WITH TREE FELLING GANG	156
26	NOV '92	S	SOUTH WEST ELEVATION OF BUILDING S34 BLAST WALL	157
27	NOV '92	S	NEWTON'S POOL / SOUTH WEST ELEVATION OF BUILDING S34 BLAST WALL	158
28	NOV '92	S	NEWTON'S POOL - OVER WATER CABLEWAY EQUIP.. VIEWED FROM WEST	159
29	NOV '92	S	VIEW LOOKING NORTH EAST - BUILDING S34 (DEBRIS IN FOREGROUND)	160
30	NOV '92	S	SOUTH WEST ELEVATION OF NEWTON'S POOL WEIR - POOR CONDITION	161
31	NOV '92	S	NORTH ELEVATION OF BUILDING 46A - NEWTON'S POOL IN FOREGROUND	162
32	NOV '92	S	ELEVATION OF AIR RAID SHELTER ADJACENT TO BUILDING 14	163
33	NOV '92	S	No. 1 BORE HOLE NORTH OF SSSI	164
34	NOV '92	S	EAST PERIMETER ROAD LOOKING SOUTH WEST	165
35	NOV '92	S	VESSEL FOUND ADJACENT TO BUILDING 14	166
36	NOV '92	S	WEST PERIMETER FENCE - DISTRESSED ROOK RESCUED	167
37	NOV '92	S	R.O.SUPERVISOR WITH ROOK - ALONG THE WEST PERIMETER FENCE	168

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: 6/6286

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1	NOV '92	M	VIEW SHOWING JCB KNOCKING ROOF IN OF BUILDING L117	169
2	NOV '92	P	SOUTHERN ASPECT OF BLDG A210 - DEMOLITION OF CONCRETE BUNKER	170
3	NOV '92	P	SOUTHERN ASPECT OF BLDG A210 SHOWING 'PULVERISER' ON 360 MACHINE	171
4	NOV '92	S	DAMPING DOWN BUILDING 22A AFTER FIRING OF EXTERNAL AIR DUCTING	172
5	NOV '92	S	DAMPING DOWN BUILDING 22A AFTER FIRING OF EXTERNAL AIR DUCTING	173
6	NOV '92	P	INTERNAL VIEW OF R.O. PROJECT OFFICE	174
7	NOV '92	P	INTERNAL VIEW OF R.O. PROJECT OFFICE	175
8	NOV '92	S	EAST ELEVATION OF BUILDING 22A - QUINAN STOVE / DERELICT	176
9	NOV '92	S	NORTH ELEVATION OF BUILDING 22A - QUINAN STOVE / DERELICT	177
10	NOV '92	S	SOUTH WEST ELEVATION OF BUILDING 22A SHOWING FRONT DUCTING	178
11	NOV '92	S	PART NORTH ELEVATION OF BUILDING 22A - BLAST WALL TO RIGHT	179
12	NOV '92	S	SOUTH ELEVATION OF BUILDING E10	180
13	NOV '92	S	EAST ELEVATION OF BUILDING E10 - SAFETY STORE	181
14	NOV '92	S	WEST ELEVATION OF BUILDING E6 - CONTROL ROOM	182
15	NOV '92	S	NORTH EAST ELEVATION OF BUILDING E6 - CONTROL ROOM	183
16	NOV '92	S	SOUTH WEST ELEVATION SHOWING ENTRANCE TO BUILDING E15	184
17	NOV '92	S	NORTH EAST ELEVATION OF BUILDING E15 - GENERATOR ROOM	185
18	NOV '92	S	NORTH WEST ELEVATION OF BUILDING E9 - REFRIGERATION HOUSE	186
19	NOV '92	S	SOUTH WEST ELEVATION OF BUILDING E9 - REFRIGERATION HOUSE	187
20	NOV '92	S	WEST ELEVATION OF BUILDING E2 - NITRATION PLANT	188
21	NOV '92	S	SOUTH WEST ELEVATION OF BUILDING E2 - NITRATION PLANT	189
22	NOV '92	S	INTERNAL ELEVATION OF BUILDING E2 - NITRATION PLANT	190
23	NOV '92	S	INTERNAL VIEW OF BUILDING E2 - NITRATION PLANT	191
24	NOV '92	S	SOUTH WEST ELEVATION OF ENTRANCE TO BUILDING E2	192
25	NOV '92	S	ELEVATION OF BLDG U6 - SMALL STORAGE HUT OVERGROWN BY TREES	193
26	NOV '92	S	ELEVATION OF BLDG U6 - SMALL STORAGE HUT OVERGROWN BY TREES	194
27	NOV '92	S	SOUTH ELEVATION OF BUILDING S31	195
28	NOV '92	S	NORTH EAST INTERNAL ELEVATION OF BUILDING S31	196
29	NOV '92	S	SOUTH EAST ELEVATION OF BUILDING S90 - DERELICT BOILER HOUSE	197
30	NOV '92	S	NORTH WEST ELEVATION OF BUILDING S90 - DERELICT BOILER HOUSE	198
31	NOV '92	S	SOUTH EAST ELEVATION OF BLDG S90 - OVERGROWN WITH VEGETATION	199
32	NOV '92	S	NORTH ELEVATION OF BUILDING S90 - OVERGROWN WITH VEGETATION	200
33	NOV '92	S	WEST INTERNAL ELEVATION OF BUILDING S30 - BLAST WALLS ONLY	201
34	NOV '92	S	SOUTH WEST ELEVATION OF BUILDING S29	202
35	NOV '92	S	NORTH EAST ELEVATION OF BUILDING S29	203
36	NOV '92	S	NORTH EAST ELEVATION OF BUILDING S29A	204
37	NOV '92	S	NORTH WEST ELEVATION OF BUILDING S29A	205

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: 7/6287

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1	NOV '92		ROAD SWEEPER - SITE ROAD NETWORK SWEEPED ON A REGULAR BASIS	206
2	NOV '92	P	ESSEX FIRE & RESCUE SERVICE VEHICLE - POWDERMILL LANE ENTRANCE	207
3	NOV '92	H I/S	NORTH EAST ELEVATION OF BUILDING A201/2 - ASBESTOS CLAD BIKESHED	208
4	NOV '92	H I/S	NORTH ELEVATION OF BUILDING A201/2 - ASBESTOS CLAD BIKESHED	209
5	NOV '92	H I/S	EAST ELEVATION OF BUILDING A291	210
6	NOV '92	H I/S	NORTH EAST ELEVATION OF BUILDING A291	211
7	NOV '92	H I/S	SOUTH EAST ELEVATION OF BUILDING A292	212
8	NOV '92	H I/S	WEST FACT OF BUILDING A292 - FENCE GUARDING SETTLEMENT PIT	213
9	NOV '92	H	NORTH EAST ELEVATION OF BUILDING H1 - PREFABRICATED STRUCTURE	214
10	NOV '92	H	WEST ELEVATION OF BUILDING H1 - PREFABRICATED STRUCTURE	215
11	NOV '92	H	EAST ELEVATION OF BUILDING H2 - PREFABRICATED STRUCTURE	216
12	NOV '92	H	WEST ELEVATION OF BUILDING H2 - PREFABRICATED STRUCTURE	217
13	NOV '92	H	SOUTH ELEVATION OF BUILDING H3 - PREFABRICATED STRUCTURE	218
14	NOV '92	H	NORTH ELEVATION OF BUILDING H3 - PREFABRICATED STRUCTURE	219
15	NOV '92	M	WEST ELEVATION OF BUILDING L183	220
16	NOV '92	M	NORTH EAST ELEVATION OF BUILDING L183	221
17	NOV '92	M	SOUTH EAST ELEVATION OF BUILDING L158 - GENERAL POOR CONDITION	222
18	NOV '92	M	NORTH ELEVATION OF BUILDING L158	223
19	NOV '92	M	SOUTH EAST ELEVATION OF BUILDING L187	224
20	NOV '92	M	NORTH EAST ELEVATION OF BUILDING L187	225
21	NOV '92	M	SOUTH EAST ELEVATION OF BUILDING L156 - GENERAL POOR CONDITION	226
22	NOV '92	M	WEST ELEVATION OF BUILDING L156	227
23	NOV '92	H	EAST ELEVATION OF BUILDING H23 - GENERAL POOR CONDITION	228
24	NOV '92	H	SOUTH ELEVATION OF BUILDING H23 - OVERGROWN WITH VEGETATION	229
25	NOV '92	H	WEST ELEVATION OF BUILDING H23 - OVERGROWN WITH VEGETATION	230
26	NOV '92	M	INTERNAL VIEW OF BUILDING L183 - GENERAL POOR CONDITION	231
27	NOV '92	M	INTERNAL VIEW OF BUILDING L183 - GENERAL POOR CONDITION	232
28	NOV '92	M	NORTH ELEVATION OF BUILDING L117	233
29	NOV '92	M	NORTH EAST ELEVATION OF BUILDING L117	234
30	NOV '92	H	SOUTH ELEVATION OF BUILDING H21	235
31	NOV '92	H	NORTH WEST ELEVATION OF BUILDING H21	236
32	NOV '92	S	WEST ELEVATION OF BUILDING 22A - PREPARATION FOR FIRING DUCTING	237
33	NOV '92	S	WEST ELEVATION OF BUILDING 22A - EXTERNAL DUCTWORK BEING FIRED	238
34	NOV '92	S	ELEVATION OF BUILDING 22A - EXTERNAL DUCTWORK BEING FIRED	239
35	NOV '92	M	REMOVAL OF STEAM MAIN SUPPORT STEELWORK	240
36	NOV '92	M	ELEVATION OF BUILDING L117 BUILDING BEING PREPARED FOR FIRING	241
37	NOV '92	M	SOUTH EAST ELEVATION OF BUILDING L117	242

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: 8/6340

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1			NOT USED	
2			NOT USED	
3			NOT USED	
4			NOT USED	
5			NOT USED	
6			NOT USED	
7			NOT USED	
8			NOT USED	
9			NOT USED	
10			NOT USED	
11			NOT USED	
12			NOT USED	
13			NOT USED	
14			NOT USED	
15			NOT USED	
16	NOV '92	S	BAGGED ASBESTOS IN GUNCOTTON STOVES - AWAITING DISPOSAL	243
17	NOV '92	S	BAGGED ASBESTOS IN GUNCOTTON STOVES - AWAITING DISPOSAL	244
18	NOV '92	S	BAGGED ASBESTOS IN GUNCOTTON STOVES - AWAITING DISPOSAL	245
19	NOV '92	S	ASBESTOS BOARD DEBRIS, AS FOUND, ADJACENT TO GUNCOTTON STOVES	246
20	NOV '92	S	INITIAL 'PICK UP' OF DEBRIS LYING AROUND SSSI AREA	247
21	NOV '92	S	INITIAL 'PICK UP' OF DEBRIS LYING AROUND SSSI AREA	248
22	NOV '92	S	BAGGED ASBESTOS NEAR GUNCOTTON STOVES	249
23	NOV '92	S	SHEET ASBESTOS PRIOR TO BAGGING - ASBESTOS DEBRIS 'AS FOUND'	250
24	NOV '92	S	SHEET ASBESTOS AT GUNCOTTON STOVES - ASBESTOS DEBRIS 'AS FOUND'	251
25	NOV '92	S	SHEET ASBESTOS PRIOR TO BAGGING - ASBESTOS BOARDING 'AS FOUND'	252
26	NOV '92	S	SHEET ASBESTOS AT GUNCOTTON STOVES - SHEET ASBESTOS 'AS FOUND'	253
27	NOV '92	S	SHEET ASBESTOS - COLLECTED AND BAGGED AWAITING DISPOSAL	254
28	NOV '92	S	ASBESTOS AT GUNCOTTON STOVE - BAGGING OF ASBESTOS DEBRIS	255
29	NOV '92	M	NORTH ELEVATION OF BUILDING L127 - ASBESTOS CLAD BUILDING	256
30	NOV '92	M	WEST ELEVATION OF BUILDING L161 - GENERAL POOR CONDITION	257
31	NOV '92	M	SOUTH WEST ELEVATION OF BUILDING L112	258
32	NOV '92	M	SOUTH WEST ELEVATION OF BUILDING L113	259
33	NOV '92	M	NORTH ELEVATION OF BUILDING L117	260
34			NOT USED	
35			NOT USED	
36	NOV '92	M	INTERNAL VIEW OF BUILDING L117 (LOCKER MAGAZINE)	261
37	NOV '92	M	NORTH ELEVATION OF BUILDING L117 - TIMBER IMPORTED FOR FIRING	262

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: 9/8224

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1			NOT USED	
2			NOT USED	
3			NOT USED	
4			NOT USED	
5			NOT USED	
6			NOT USED	
7			NOT USED	
8	NOV '92	T	TETRYL FACTORY SITE - CORE DRILLING / BURSTING	263
9	NOV '92	T	TETRYL FACTORY SITE - CORE DRILLING / BURSTING	264
10			NOT USED	
11			NOT USED	
12			NOT USED	
13			NOT USED	
14			NOT USED	
15			NOT USED	
16	NOV '92	T	CORE DRILLING FOUNDATION BASES	265
17	NOV '92	B	L.G.C. SAMPLING GROUND WATER FROM SITE BORE HOLES	266
18	NOV '92	S	COPPER LIGHTNING CONDUCTORS FROM ROOFS OF MAGAZINES	267
19	NOV '92	N	COPPER LIGHTNING CONDUCTORS - ACCUMULATION FOR SALVAGE	268
20	NOV '92	M	COPPER LIGHTNING CONDUCTORS - ACCUMULATION FOR SALVAGE	269
21	NOV '92	T	TETRYL FACTORY SITE - BURSTING OF FOUNDATION CONCRETE	270
22	NOV '92	T	TETRYL FACTORY SITE - BURSTING OF FOUNDATION CONCRETE	271
23	NOV '92	P	WEST ELEVATION OF BUILDING A210 - SERVICES PIPEWORK, SOME LAGGED	272
24	NOV '92	P	NORTH ELEVATION OF BUILDING A210 - ASBESTOS LAGGED PIPES WRAPPED	273
25	NOV '92	P	NORTH ELEVATION OF BUILDING A212 - ASBESTOS LAGGED PIPES WRAPPED	274
26	NOV '92	M	NORTH EAST ELEVATION OF BUILDING L113 - ASBESTOS LAGGED PIPES	275
27	NOV '92	M	PIPES NEAR BUILDING L153 WRAPPED FOR REMOVAL	276
28	NOV '92	P	PERSONNEL DECONTAMINATION UNIT	277
29	NOV '92	S	STEAM MAIN PIPE IN SSSI AREA - ASBESTOS LAGGED PIPE WRAPPED	278
30	NOV '92	S	STEAM MAIN PIPE NEAR BUILDING 88A - ASBESTOS LAGGED PIPE WRAPPED	279
31	NOV '92	N	NORTH EAST VIEW OF GATE IN AREA N - HOLE CUT IN GATE BY INTRUDERS	280
32			NOT USED	
33			NOT USED	
34			NOT USED	
35			NOT USED	
36			NOT USED	
37			NOT USED	

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: 10/6853

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1			NOT USED	
2			NOT USED	
3			NOT USED	
4			NOT USED	
5			NOT USED	
6			NOT USED	
7			NOT USED	
8			NOT USED	
9			NOT USED	
10			NOT USED	
11			NOT USED	
12	NOV '92	H	INTERNAL VIEW OF BUILDING H12 - REMOTE CORING OF BRICK WALLS	281
13	NOV '92	H	INTERNAL VIEW OF BUILDING H12 - REMOTE CORING OF BRICK WALLS	282
14	NOV '92	H	INTERNAL VIEW OF BUILDING H12 - REMOTE CORING OF BRICK WALLS	283
15	NOV '92	H	INTERNAL VIEW OF BUILDING H12 - REMOTE CORING OF BRICK WALLS	284
16	NOV '92	H	INTERNAL VIEW OF BUILDING H12 - REMOTE CORING OF BRICK WALLS	285
17	NOV '92	H	INTERNAL VIEW OF BUILDING H12 - REMOTE CORING OF BRICK WALLS	286
18	NOV '92	H	INTERNAL VIEW OF BUILDING H12 - REMOTE CORING OF BRICK WALLS	287
19	NOV '92	H	MAN HOLE BETWEEN BUILDING H10 & H71	288
20	NOV '92	S	INTERNAL VIEW OF BUILDING L190 - REMOTE FLOOR CORING IN PROGRESS	289
21			NOT USED	
22	NOV '92	S	BARGE IN CANAL WEST OF BUILDING 107 /108 - GENERAL POOR CONDITION	290
23	NOV '92	S	BARGE IN CANAL WEST OF BUILDING 107 /108 - GENERAL POOR CONDITION	291
24	NOV '92	S	POWDER BARGE IN CANAL AT 88A	292
25	NOV '92	S	POWDER BARGE IN CANAL AT 88A	293

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: 11/6956

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1	NOV '92	H	MAN HOLE COVER BETWEEN BUILDINGS H10 & H71 (NORTH SIDE)	294
2	NOV '92	H	MAN HOLE COVER BETWEEN BUILDINGS H10 & H71 (NORTH SIDE)	295
3	NOV '92	S	GENERAL VIEW OF TRACK SOUTH OF BLDG U4 - HEAVY USE BY VEHICLES	296
4	NOV '92	S	VIEW SOUTH SHOWING GENERAL CLEARANCE AROUND BUILDING U4	297
5	NOV '92	S	GENERAL VIEW OF WASTE MATERIAL SOUTH OF U4	298
6	NOV '92	S	OUTSIDE BUILDING U4 - COPPER EARTHING STRIP, RETRIEVAL FOR SALVAGE	299
7	NOV '92	S	CLEARING WASTE FROM AREA SOUTH OF BUILDING U4	300
8	NOV '92	S	SETTLEMENT TANK NORTH WEST OF BUILDING 83B	301
9	NOV '92	S	GENERAL VIEW OF WASTE NORTH OF BUILDING U4 - VIEW LOOKING NORTH	302
10	NOV '92	S	OLD TELEGRAPH POLES STOCKPILED	303
11	NOV '92	S	VIEW OF TYPICAL TRACK WITHIN WOODED AREAS OF SSSI	304
12	NOV '92		MAP READING BY ROYAL ORDNANCE - ON SITE CO ORDINATION	305
13	NOV '92	S	TRIAL TRENCHING OF TRAVERSE (TYPICAL) - DIFFICULT ACCESS	306
14	NOV '92	M	DISMANTLING GREENHOUSE No. 1	307
15	NOV '92	M	DEMOLITION OF BUILDINGS	308
16	NOV '92	S	VIEW OF WASTE MATERIAL IN WASTE DUMP SOUTH OF BUILDING U4	309
17	NOV '92	S	VIEW OF WASTE MATERIAL IN WASTE DUMP SOUTH OF BUILDING U4	310
18	NOV '92	S	ASBESTOS UNCOVERED IN WASTE DUMP SOUTH OF BUILDING U4	311
19	NOV '92	S	WASTE DUMP REMOVAL SOUTH OF BUILDING U4	312
20	NOV '92	S	ASBESTOS IN WASTE DUMP SOUTH OF BUILDING U4	313
21	NOV '92	S	ASBESTOS IN WASTE DUMP SOUTH OF BUILDING U4	314
22	NOV '92	S	BAGGED ASBESTOS AT BUILDING 23	315
23	NOV '92	S	ASBESTOS WASTE IN BUILDING 23 - CONDITION PRIOR TO CLEAN UP	316
24	NOV '92	S	REMOVING WASTE FROM TIP	317
25	NOV '92	S	VIEW LOOKING NORTH TO E10 - FENCE GUARDING PITS	318
26	NOV '92	S	WEST ELEVATION OF BUILDING E12	319
27	NOV '92	S	SOUTH ELEVATION OF BUILDING E10	320
28	NOV '92	S	REMOVAL OF WASTE BY LORRY - NORTH OF BUILDING 83B	321
29	NOV '92	L	ELEVATION OF BUILDING L191 - CORE SAMPLING	322
30	NOV '92	S	WEST ELEVATION OF BUILDING 22A - AFTERMATH OF FIRED DUCTWORK	323
31	NOV '92	S	TREE CLEARANCE - LOGGING	324
32	NOV '92	S	TREE CLEARANCE - CHIPPING	325
33	NOV '92	N	DEMONSTRATION ON DIFFICULT TERRAIN OF TRACKED DUMPER	326
34	NOV '92	N	DEMONSTRATION ON DIFFICULT TERRAIN OF TRACKED DUMPER	327
35	NOV '92	N	DEMONSTRATION ON DIFFICULT TERRAIN OF TRACKED DUMPER	328
36	NOV '92	N	DEMONSTRATION ON DIFFICULT TERRAIN OF TRACKED DUMPER	329
37	NOV '92	N	DEMONSTRATION ON DIFFICULT TERRAIN OF TRACKED DUMPER	330

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: 12/7113

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1	NOV '92	H	TYPICAL STEAM MAIN SUPPORT - SOUTH OF BUILDING H17	331
2	NOV '92	H	TYPICAL STEAM PIPE SUPPORT BASE	332
3	NOV '92	H	STEAM PIPE SUPPORT SOUTH OF BUILDING H12 (UNUSUAL - ALL CONCRETE)	333
4	NOV '92	S	PALLETING RECLAIMED 'STOCK' (BRICKS) FOR FUTURE USE (SOUTH OF U4)	334
5	NOV '92	S	R.O. SUPERVISING THE RECLAMATION OF BRICKS SOUTH OF BUILDING U4	335
6	NOV '92	S	WASTE TIP REFERENCE 11013 - VIEW LOOKING SOUTH	336
7	NOV '92	S	COMMENCEMENT OF BREAKING OUT SURFACE SLABS WEST OF BLDG 83B	337
8	NOV '92	S	GENERAL CLEARANCE OF TIMBER FROM WASTE TIP REFERENCE 11013	338
9	NOV '92	B	TIMBER STACKED IN BURNING GROUND AS FUEL FOR 'HEAT TREATMENT'	339
10	NOV '92	S	GENERAL VIEW - TIMBER CLEARANCE FOR ACCESS	340
11	NOV '92	S	GUNPOWDER PRESS HOUSE, EAST OF BURNING GROUND VIEWED FROM WEST	341
12	NOV '92	S	GENERAL VIEW - WASTE TIP REF.: 11036 ADJACENT TO G.P. PRESS HOUSE	342
13	NOV '92	S	GENERAL VIEW OF WASTE TIP REF.: 11036 - GUNPOWDER PRESS HOUSE	343
14	NOV '92	S	VIEW OF WASTE TIP REF.: 11036 - ADJACENT GUNPOWDER PRESS HOUSE	344
15	NOV '92	S	VIEW OF WASTE TIP REF.: 11036 - ADJACENT GUNPOWDER PRESS HOUSE	345
16	NOV '92	S	VIEW OF WASTE TIP REF.: 11036 - ADJACENT GUNPOWDER PRESS HOUSE	346
17	NOV '92	S	VIEW OF WASTE TIP REF.: 11036 - ADJACENT GUNPOWDER PRESS HOUSE	347
18	NOV '92	S	VIEW OF WASTE TIP REF.: 11036 - ADJACENT GUNPOWDER PRESS HOUSE	348
19	NOV '92	S	VIEW OF BRIDGE 10 LOOKING NORTH (PRESS HOUSE S31 IN BACKGROUND)	349
20	NOV '92	S	ELEVATION OF BUILDING X16 (BUILDING NORTH WEST OF BRIDGE 10)	350
21	NOV '92	B	WASTE TIP REF.: 11038 SITUATED NORTH OF THE BURNING GROUND	351
22	NOV '92	N	GENERAL CLEARANCE	352
23	NOV '92	M	REMOTE CONTROLLED CORING IN BUILDING L149 - REMOTE OPERATOR	353
24	NOV '92	M	REMOTE CONTROLLED CORING OF CONCRETE FLOOR IN BUILDING L149	354
25	NOV '92	N	CLEARED PATHWAYS	355
26	NOV '92	N	STEEL PLATES IN BUILDING S19	356
27	NOV '92	N	CLEARING PATHWAYS TO BUILDINGS	357
28	NOV '92	N	CLEARED PATHWAY	358
29	NOV '92	N	CLEARED ROADS AT BUILDING S21 - NARROW GAUGE TRACK VISIBLE	359
30	NOV '92	N	SOUTH ELEVATION OF BUILDING S22	360
31	NOV '92	N	NORTH ELEVATION OF BUILDING S25	361
32	NOV '92	N	SOUTH ELEVATION OF BUILDING S25	362
33	NOV '92	N	TYPICAL OVERGROWN PATHWAY - OVERGROWN BY TREES AND SHRUBS	363
34	NOV '92	N	INTERNAL VIEW OF BUILDING S25	364
35	NOV '92	N	TYPICAL OVERGROWN DRAINAGE CHANNEL FROM BUILDING S16	365
36	NOV '92	N	CLEARING DRAINAGE CHANNEL FROM BUILDING S16	366
37	NOV '92	N	DRAINAGE CHANNEL RUNNING SOUTHWARD FROM BUILDING S16	367

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: 13/7562

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1	NOV '92	M	WEST ELEVATION OF BUILDING L167	368
2	NOV '92	M	SOUTH WEST ELEVATION OF BUILDING L167	369
3	NOV '92	M	SOUTH ELEVATION OF BUILDING L157	370
4	NOV '92	M	WEST ELEVATION OF BUILDING L157	371
5	NOV '92	M	WEST ELEVATION OF BUILDING L148 / L153	372
6	NOV '92	M	PART EAST AND NORTH ELEVATIONS OF BUILDING L157	373
7	NOV '92	M	LOOKING SOUTH - BUILDING L157 IN FOREGROUND	374
8	NOV '92	M	PART EAST ELEVATION OF BUILDING L153	375
9	NOV '92	M	WEST ELEVATION O BUILDING L149	376
10	NOV '92	M	PART NORTH AND EAST ELEVATIONS OF BUILDING L153	377
11	NOV '92	M	EAST ELEVATION OF BUILDING L148	378
12	NOV '92	M	PART EAST ELEVATION OF BUILDING L148	379
13	NOV '92	M	SOUTH EASTERN ASPECT OF BUILDING L145	380
14	NOV '92	M	NORTH EASTERN ASPECT OF BUILDING L149	381
15	NOV '92	M	NORTH EASTERN ASPECT OF BUILDING L149	382
16	NOV '92	M	NORTH EASTERN ASPECT OF BUILDING L145	383
17	NOV '92	M	SOUTH ELEVATION OF BUILDING L136	384
18	NOV '92	M	SOUTH WESTERN ASPECT OF BUILDING L136	385
19	NOV '92	L	NORTH WESTERN ASPECT OF BUILDING L122	386
20	NOV '92	B	WEST ELEVATION OF BUILDING L102 - FILLED CANAL IN FOREGROUND	387
21	NOV '92	B	NORTH ELEVATION OF BUILDING L103	388
22	NOV '92	B	EAST ELEVATION OF BUILDINGS L102 / L103	389
23	NOV '92	B	NORTH EASTERN ASPECT OF BUILDING L101	390

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: 14/7575

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1	NOV '92	N	WEST ELEVATION OF BUILDING X3 - BUNKER TYPE	391
2	NOV '92	N	SOUTH ELEVATION OF BUILDING X3	392
3	NOV '92	B	PREPARATION OF FIRE IN BURNING GROUND FOR 'HEAT TREATMENT'	393
4	NOV '92	B	PREPARATION OF FIRE IN BURNING GROUND FOR 'HEAT TREATMENT'	394
5	NOV '92	B	PREPARATION OF FIRE IN BURNING GROUND FOR 'HEAT TREATMENT'	395
6	NOV '92	B	PREPARATION OF FIRE IN BURNING GROUND FOR 'HEAT TREATMENT'	396
7	NOV '92	B	'HEAT TREATMENT' OF MATERIALS AT BURNING GROUND (IN PROGRESS)	397
8	NOV '92	T	REMEDIATION OF TETRYL FACTORY SITE	398
9	NOV '92	T	REMEDIATION OF TETRYL FACTORY SITE	399
10	NOV '92	T	EXPOSURE OF SUSPECT PIT AT NORTH END OF TETRYL FACTORY SITE	400
11	NOV '92	T	EXPOSURE OF SUSPECT PIT AT NORTH END OF TETRYL FACTORY SITE	401
12	NOV '92	T	EXPOSURE OF SUSPECT PIT AT NORTH END OF TETRYL FACTORY SITE	402
13	NOV '92	T	REMEDIATION OF TETRYL FACTORY SITE VIEWED SOUTHERLY	403
14	NOV '92	T	REMEDIATION OF TETRYL FACTORY SITE VIEWED SOUTHERLY	404
15	NOV '92	T	EXPOSURE OF SUSPECT PIT AT NORTH END OF TETRYL FACTORY SITE	405
16	NOV '92	T	EAST SIDE OF TETRYL FACTORY SITE - WASTE DUMP	406
17	NOV '92	T	REMEDIATION OF TETRYL FACTORY SITE	407
18	NOV '92	T	REMEDIATION OF TETRYL FACTORY SITE	408
19	NOV '92	T	REMEDIATION OF TETRYL FACTORY SITE	409
20	NOV '92	T	'YELLOW' DISCOLOURATION OF FOUNDATIONS TO TETRYL FACTORY SITE	410
21	NOV '92	T	BREAKING OF CONCRETE FOUNDATIONS OF FORMER TETRYL FACTORY	411
22	NOV '92	T	EXPOSURE OF DRAINS TO FORMER TETRYL FACTORY SITE	412
23	NOV '92	T	BROKEN FOUNDATIONS OF FORMER TETRYL FACTORY	413
24	NOV '92	T	REMEDIATION OF TETRYL FACTORY SITE	414
25	NOV '92	S	TRACKED DUMPER BY BUILDING E12 REMOVING WASTE FROM CANAL	415
26	NOV '92	S	TRACKED DUMPER TIPPING WASTE BY BUILDING E12	416
27	NOV '92	H I/S	SOUTH ELEVATION OF BUILDING A203	417
28	NOV '92	H I/S	NORTH ELEVATION OF BUILDING A200	418
29	NOV '92	H I/S	EAST ELEVATION OF BUILDING A201 / 2	419
30	NOV '92	H I/S	CLOSE UP OF FRACTURED PIER TO NORTH EAST CORNER OF BUILDING A201/2	420
31	NOV '92	H I/S	WEST ELEVATION OF BUILDING A200	421
32	NOV '92	P	NORTH WESTERN ASPECT OF BUILDING A210	422
33	NOV '92	P	WEST ELEVATION OF BUILDING A210	423
34	NOV '92	P	NORTH EASTERN ASPECT OF BUILDING A214 (BLDG A210 IN BACKGROUND)	424
35	NOV '92	M	SOUTH ELEVATION OF BUILDING L176 - BRIDGE No. 2 IN FOREGROUND	425
36	NOV '92	M	NORTH WESTERN ASPECT OF BUILDING L176	426
37	NOV '92	M	NORTH ELEVATION OF BUILDING L168	427

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: 15/7600

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1	NOV '92	S	KUBOTA EXCAVATOR ACCIDENT IN SOFT GROUND	428
2	NOV '92	S	KUBOTA EXCAVATOR ACCIDENT IN SOFT GROUND	429
3	NOV '92	S	FALLOW DEER IN SSSI	430
4	NOV '92	S	FALLOW DEER IN SSSI	431
5	NOV '92	S	NARROW GAUGE RAILWAY UNCOVERED IN SSSI, BETWEEN BLDG'S 22 & 23	432
6	NOV '92	S	NARROW GAUGE RAILWAY UNCOVERED IN SSSI, BETWEEN BLDG'S 22 & 23	433
7	NOV '92	P	FITTING OUT SITE ADMINISTRATION OFFICES - BUILDING A320	434
8	NOV '92	H I/S	WEST ELEVATION OF BUILDING A200	435
9	NOV '92	H I/S	NORTH ELEVATION OF BUILDING A200	436
10	NOV '92	H I/S	EAST ELEVATION OF BUILDING A201/2	437
11	NOV '92	H I/S	VIEW OF FRACTURED PIER TO NORTH EAST CORNER OF BUILDING A201/2	438
12	NOV '92	P	SOUTH ELEVATION OF BUILDING A210 (BOILER HOUSE)	439
13	NOV '92	P	NORTH ELEVATION OF BUILDING A210 (BOILER HOUSE)	440
14	NOV '92	M	SOUTH ELEVATION OF BUILDING L182	441
15	NOV '92	M	NORTH WEST ASPECT OF BUILDING L176	442
16	NOV '92	M	SOUTH ELEVATION OF BUILDING L176	443
17	NOV '92	M	WEST ELEVATION OF BUILDING L167	444
18	NOV '92	M	EAST AND NORTH ELEVATIONS OF BUILDING L167	445
19	NOV '92	M	WEST ELEVATION OF BUILDING L157	446
20	NOV '92	M	NORTH EAST ELEVATION OF BUILDING L157	447
21	NOV '92	M	WEST ELEVATION OF BUILDING L148 / L153	448
22	NOV '92	M	NORTH EAST ELEVATION OF BUILDING L153	449
23	NOV '92	M	NORTH EAST ELEVATION OF BUILDING L149	450
24	NOV '92	M	SOUTH ELEVATION OF BUILDING L149	451
25	NOV '92	M	ELEVATION OF BUILDING L148	452
26	NOV '92	M	NORTH EAST ELEVATION OF BUILDING L145	453
27	NOV '92	M	SOUTH ELEVATION OF BUILDING L136	454
28	NOV '92	M	SOUTH AND WEST ELEVATIONS OF BUILDING L136	455
29	NOV '92	L	SOUTH AND WEST ELEVATIONS OF BUILDING L122	456
30	NOV '92	S	VIEW OF TYPICAL WASTE DUMP - MIXED WASTE	457
31	NOV '92	S	TYPICAL WASTE DUMP REF.: 11036	458
32	NOV '92	S	TYPICAL WASTE DUMP REF.:11036 - CONTAINS ASBESTOS	459
33	NOV '92	S	DEPICTS A DATED TELEGRAPH POLE FOUND IN SSSI	460
34	NOV '92	S	WASTE DUMP REF.:11038, SITUATED NORTH OF THE BURNING GROUND	461
35	NOV '92	P	NORTH ELEVATION OF BUILDING A238	462
36	NOV '92	P	SOUTH ELEVATION OF BUILDING A221 - DIRECTORS HOUSE (OCCUPIED)	463
R	NOV '92	P	EAST ELEVATION OF BUILDING A200 (WALTON HOUSE)	464

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: 16/7809

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1			NOT USED	
2	NOV '92	P	NORTH ELEVATION OF BUILDING A230	465
3	NOV '92	P	NORTH ELEVATION OF BUILDING A231	466
4	NOV '92	P	NORTH ELEVATION OF BUILDINGS A232 - A234	467
5	NOV '92	P	SOUTH ELEVATION OF BUILDING A221 (MRS BELLAMY'S HOUSE)	468
6	NOV '92	P	NORTH ELEVATION OF BUILDING A238	469
7	NOV '92	H	NORTH ELEVATION OF BUILDING H25	470
8	NOV '92	H	SOUTH ELEVATION OF BUILDING H26	471
9	NOV '92	H	WEST ELEVATION OF BUILDING H8	472
10	NOV '92	H	EAST ELEVATION OF BUILDING H8	473
11	NOV '92	M	WEST ELEVATION OF BUILDING L157	474
12	NOV '92	M	WEST ELEVATION OF BUILDING L153 / L148	475
13	NOV '92	L	WEST ELEVATION OF BUILDING L185	476
14	NOV '92	L	SOUTH ELEVATION OF BUILDING L122	477
15	NOV '92	M	EAST ELEVATION OF BUILDING L107	478
16	NOV '92	M	SOUTH ELEVATION OF BUILDING L138	479
17			NOT USED	
18	NOV '92	M	WEST ELEVATION OF BUILDING L133	480
19	NOV '92	M	NORTH ELEVATION OF BUILDING L143	481
20	NOV '92	S	SOUTH ASPECT OF 'WATERMAN'S COTTAGE'	482
21	NOV '92	S	SOUTH ELEVATION OF BUILDING 103 - PRESS HOUSE	483
22	NOV '92	S	BUILDING 103 PRESS HOUSE BLAST WALL	484
23	NOV '92	S	SOUTH ELEVATION OF BUILDING S31	485
24	NOV '92	S	ELEVATION OF BUILDING S90	486
25	NOV '92	S	BUILDING S90	487

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: 17/7810

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1	NOV '92	S	ASBESTOS FOUND IN UNDERGROWTH	488
2	NOV '92	S	ASBESTOS FOUND IN UNDERGROWTH	489
3	NOV '92	T	CONCRETE FOUNDATION EXPOSED IN FORMER TETRYL FACTORY	490
4	NOV '92	P	EXPOSED GAS PIPE TO BUILDING A221	491
5	NOV '92	B	GENERAL VIEW OF BURNING GROUND	492
6	NOV '92	S	RUBBISH COLLECTION BY BUILDING 88A	493
7	NOV '92	S	VIEW FROM TOW PATH OPPOSITE BUILDING 88A	494
8	NOV '92	S	TYPICAL STEAM MAIN ROUTE THROUGH UNDERGROWTH	495
9	NOV '92	S	TRANSPORTATION OF BAGGED ASBESTOS ON SITE	496
10	NOV '92	S	DIGGING OUT ASBESTOS FROM STEAM MAIN ROUTE ADJACENT TO BLDG 88A	497
11	NOV '92	S	DIGGING OUT ASBESTOS FROM STEAM MAIN ROUTE ADJACENT TO BLDG 88A	498
12	NOV '92	S	CANAL SOUTH OF BUILDING 88A - LOOKING EAST	499
13	NOV '92	S	CANAL SOUTH OF BUILDING 88A - LOOKING EAST	500
14	NOV '92	S	INTERNAL VIEW OF BUILDING 88A - WEST WALL	501
15	NOV '92	S	INTERNAL VIEW OF BUILDING 88A - EAST AND NORTH WALLS	502
16	NOV '92	S	CANAL SOUTH OF BUILDING 88A	503
17	NOV '92	S	STEAM MAIN SUPPORTS	504
18	NOV '92	S	STEAM MAIN SUPPORTS	505
19	NOV '92	S	STEAM MAIN SUPPORTS	506
20	NOV '92	S	STEAM MAIN SUPPORTS	507
21	NOV '92	S	SOUTH OF BUILDING 88A - STEAM MAIN ROUTES	508
22	NOV '92	S	CANAL SOUTH OF BUILDING 88A	509
23	NOV '92	S	SOUTH ELEVATION OF BUILDING 88B	510
24	NOV '92	S	STEAM MAIN IN SSSI	511
25	NOV '92	S	SOUTH OF BUILDING 88A	512
26	NOV '92	S	SOUTH OF BUILDING 88A	513
27	NOV '92	S	DIGGING OUT WASTE FROM CANAL ADJACENT TO BUILDING 62	514
28	NOV '92	S	EXCAVATION AND BAGGING OF ASBESTOS FOUND IN WASTE DUMP	515
29	NOV '92	S	WASTE DUG FROM CANAL ADJACENT TO BUILDING 62	516
30	NOV '92	S	CANAL WEST OF BUILDING 62 - LOOKING SOUTH	517
31	NOV '92	S	CANAL CLEARANCE WEST OF BUILDING 76	518
32	NOV '92	S	NORTH WEST ELEVATION OF BUILDING E14	519
33	NOV '92	S	WEST ELEVATION OF BUILDING 76	520
34	NOV '92	S	SOUTH WEST ELEVATION OF BUILDING E14	521
35	NOV '92	S	SOUTH ELEVATION OF BLDG 76 VIEWED FROM TOP OF BLDG E14 TRAVERSE	522
36	NOV '92	S	CANAL NORTH OF BUILDING E14 LOOKING TOWARDS BUILDING 88A	523
37	NOV '92	S	VIEW OF BUILDING 88A FROM ROOF OF BUILDING E14	524

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: 18/7998

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1	DEC '92	H	SOUTH ELEVATION OF BUILDING H26	525
2	DEC '92	H	SOUTH WEST ELEVATION OF BUILDING H26	526
3	DEC '92	H	NORTH WEST ELEVATION OF BUILDING A203 (BRIDGE 17 IN FOREGROUND)	527
4	DEC '92	H	NORTH AND EAST ELEVATIONS OF BUILDING H7	528
5	DEC '92	L	NORTH AND WEST ELEVATIONS OF BUILDING L122	529
6	DEC '92	M	NORTH AND WEST ELEVATIONS OF BUILDING L145	530
7	DEC '92	M	WEST ELEVATION OF BUILDING L148	531
8	DEC '92	S	SOUTH WEST ELEVATION OF 'WATERMAN'S COTTAGE'	532
9	DEC '92	S	NORTH ELEVATION OF 'WATERMAN'S COTTAGE'	533
10	DEC '92	H	EAST ELEVATION OF BUILDING A203	534
11	DEC '92	P	EAST ELEVATION OF BUILDING A268	535
12	DEC '92	P	EAST ELEVATION OF BUILDING A26	536
13	DEC '92	P	NORTH ELEVATION OF BUILDING A238 (MAIN GATE TO SITE)	537
14	DEC '92	P	SOUTH ELEVATION OF BUILDING A221	538
15	DEC '92	P	EAST ELEVATION OF BUILDING A221	539
16	DEC '92	P	WEST ELEVATION OF BUILDING A268	540
17	DEC '92	P	NORTH AND WEST ELEVATIONS OF BUILDING A269	541
18	DEC '92	M	NORTH EAST ELEVATION OF BUILDING L177	542
19	DEC '92	M	SOUTH EAST ELEVATION OF BUILDING L177	543
20	DEC '92	M	NORTH ELEVATION OF BUILDING L168	544
21	DEC '92	L	NORTH EAST ELEVATION OF BUILDING L165	545
22	DEC '92	L	WEST ELEVATION OF BUILDING L165	546
23	DEC '92	M	SOUTH AND WEST ELEVATIONS OF BUILDING L168	547

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: 19/8812

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1	DEC '92	P	ROYAL ORDNANCE OFFICE CHRISTMAS TREE	548
2	DEC '92	S	RECOVERED TETRYL DEPOSIT FROM CANAL BED NORTH OF BUILDING S31	549
3	DEC '92	S	RECOVERED TETRYL DEPOSIT FROM CANAL BED NORTH OF BUILDING S31	550
4	DEC '92	S	CLEARING OUT BUILDING E2	551
5	DEC '92	S	CLEARING OUT BUILDING E2	552
6	DEC '92	H	SOIL STRIP OF STEAM MAIN ROUTES IN AREA 'H'	553
7	DEC '92	S	REMOVAL OF CONTAMINATED SOIL FORMER STEAM MAIN ROUTES	554
8	DEC '92	S	CLEARING OUT BUILDING E3	555
9	DEC '92	S	TREE FELLING AT BUILDING 103 'PRESS HOUSE'	556
10	DEC '92	S	TREE FELLING AT BUILDING 103 'PRESS HOUSE'	557
11	DEC '92	S	STOCKPILED WOOD CHIPPING'S FROM TREE FELLING	558
12	DEC '92	S	WEST ELEVATION OF BUILDING 103 'PRESS HOUSE'	559
13	DEC '92	S	TREE FELLING AT WASTE TIP ADJACENT TO BUILDING 103	560
14	DEC '92	S	TREE FELLING AT WASTE TIP ADJACENT TO BUILDING 103	561
15	DEC '92	S	TREE FELLING AT BUILDING S30 - VIEW LOOKING WEST	562
16	DEC '92	S	INVESTIGATING EXISTING SERVICE ROUTES	563
17	DEC '92	S	INVESTIGATING EXISTING SERVICE ROUTES	564
18	DEC '92	S	INVESTIGATING EXISTING SERVICE ROUTES	565
19	DEC '92	P	NORTH EAST ELEVATION OF BUILDING A214	566
20	DEC '92	P	NORTH EAST ELEVATION OF BUILDING A214	567
21	DEC '92	P	NORTH EAST ELEVATION OF BUILDING A214	568
22	DEC '92	P	NORTH EAST ELEVATION OF BUILDING A214	569
23	DEC '92	P	NORTH EAST ELEVATION OF BUILDING A214	570
24	DEC '92	P	NORTH EAST ELEVATION OF BUILDING A214	571
25	DEC '92	P	NORTH EAST ELEVATION OF BUILDING A214	572
26	DEC '92	P	NORTH EAST ELEVATION OF BUILDING A214	573
27	DEC '92	P	NORTH EAST ELEVATION OF BUILDING A214	574
28	DEC '92	P	NORTH EAST ELEVATION OF BUILDING A214	575
29	DEC '92	P	NORTH EAST ELEVATION OF BUILDING A214	576
30	DEC '92	P	NORTH EAST ELEVATION OF BUILDING A214	577
31	DEC '92	P	NORTH EAST ELEVATION OF BUILDING A214	578
32	DEC '92	H	H16 SAMPLING SLAB PREPARATION	579
33	DEC '92	H	H16 SAMPLING SLAB PREPARATION	580
34	DEC '92	H	H16 SAMPLING SLAB PREPARATION	581
35	DEC '92	H	H16 SAMPLING SLAB PREPARATION	582
36	DEC '92	H	H16 SAMPLING SLAB PREPARATION	583
R	DEC '92	H	H16 SAMPLING SLAB PREPARATION	584

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: 20/9355

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1	JAN '93	S	FLOODED CANAL WEST OF LONG WALK - LOOKING NORTH AT BRIDGE 7	585
2	JAN '93	S	FLOODED CANAL WEST OF LONG WALK - LOOKING NORTH AT BRIDGE 7	586
3	JAN '93	S	AREA EAST OF BUILDING L128 - SHOWING FLOODING	587
4	JAN '93	S	NORTH WEST ACCESS BRIDGE TO BUILDING L128 - BRIDGE No. 7	588
5	JAN '93	S	FLOODING IN OLD MILLHEAD STREAM VIEWED FROM WEST SIDE OF BUILDING L128 - LOOKING SOUTH	589
6	JAN '93	S	FLOODING IN CANAL SOUTH OF BUILDING 107 AND 108	590
7	JAN '93	S	FLOODING WEST OF LONG WALK	591
8	JAN '93	S	FLOODING IN CANAL WEST OF BUILDING S30 - LOOKING SOUTH	592
9	JAN '93	S	VIEW SOUTH OF BUILDING S28 (WEST)	593
10	JAN '93	S	FLOODING IN CANAL WEST OF BUILDING S30 (WEST)	594
11	JAN '93	S	ASBESTOS MATERIAL STACKED FOR DISPOSAL	595
12	JAN '93	S	ASBESTOS MATERIAL STACKED FOR DISPOSAL	596
13	JAN '93	S	FLOODED POND NORTH OF BUILDING E2	597
14	JAN '93	S	ARTEFACT FOUND NEAR POND NORTH OF BUILDING E2	598
15	JAN '93	S	FLOODED CONTAMINATED POND NORTH OF BUILDING E2	599
16	JAN '93	S	FLOODED CONTAMINATED POND NORTH OF BUILDING E2	600
17	JAN '93	S	FLOODED POND NORTH WEST OF BUILDING E2	601
18	JAN '93	M	NOTICE ON DOOR IN BUILDING L145 PRIOR TO STRIPPING OUT BUILDING L148	602
19	JAN '93	S	CRACKED WILLOW DAMAGED IN GATE	603
20	JAN '93	B	BUILDING 96 - COLLAPSING THE ROOF TO MAKE IT SAFE	604
21	JAN '93	B	GENERAL VIEW OF BUILDING 96	605
22	JAN '93	B	GAS CYLINDER ADJACENT TO BUILDING L103	606
23	JAN '93	S	FLOODED AREA OF SSSI	607
24	JAN '93	S	REMOVAL OF CONCRETE AND MASONRY WEST OF BUILDING 103	608
25	JAN '93	S	CONTAMINATION ON AREA WEST OF BUILDING 103	609
26	JAN '93	S	ROAD SWEEPER (KEEPING SITE ACCESS ROUTES CLEAN)	610
27	JAN '93	M	SOUTH EAST CORNER OF AREA 'M' - REMOVAL OF CORDITE CONTAMINATED SOIL	611
28	JAN '93	M	SOUTH EAST CORNER OF AREA 'M' - REMOVAL OF CORDITE CONTAMINATED SOIL	612
29	JAN '93	M	SOUTH EAST CORNER OF AREA 'M' - REMOVAL OF CORDITE CONTAMINATED SOIL	613
30	JAN '93	M	SCREENING CORDITE CONTAMINATED SOIL	614
31	JAN '93	M	SCREENING CORDITE CONTAMINATED SOIL	615
32	JAN '93	M	SCREENING CORDITE CONTAMINATED SOIL	616
33	JAN '93	M	SCREENING CORDITE CONTAMINATED SOIL	617
34	JAN '93	M	SCREENING CORDITE CONTAMINATED SOIL	618
35	JAN '93	M	SCREENING CORDITE CONTAMINATED SOIL	619
36	JAN '93	M	SCREENING CORDITE CONTAMINATED SOIL	620
36 a	JAN '93	M	SCREENING CORDITE CONTAMINATED SOIL	621

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: 21/9361

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1	JAN '93	B	CLEARANCE OF CANAL WEST OF BUILDING L103	622
2	JAN '93	B	GAS CYLINDERS REMOVED FROM WASTE FILLED CANAL WEST - BLDG L103	623
3	JAN '93	H	EXCAVATED MATERIAL FROM FILLED CANALS BEING TIPPED ON H16 SAMPLING SLAB	624
4	JAN '93	H	MACHINE TRACKING BETWEEN BAYS OF CONTAMINATED MATERIAL ON H16 SLAB	625
5	JAN '93	H	SAMPLING IN PROGRESS - CONTAMINATED WASTE (H16 SAMPLING AREA)	626
6	JAN '93	H	SAMPLING IN PROGRESS - CONTAMINATED WASTE (H16 SAMPLING AREA)	627
7	JAN '93	B	FURTHER EXCAVATION OF CONTAMINATED WASTE WEST OF BLDG. L103	628
8	JAN '93	B	GAS CYLINDERS REMOVED FROM WASTE FILLED CANAL WEST - BLDG L103	629
9	JAN '93	B	INSPECTION OF GAS CYLINDERS FROM FILLED CANAL WEST BLDG L103	630
10	JAN '93	H	VIEW OF CONTAMINATED WASTE SAMPLING AREA ON H16	631
11	JAN '93	H	CONTAMINATED WASTE STORED ON H16 SAMPLING AREA	632
12	JAN '93	B	GAS CYLINDERS REMOVED FROM WASTE FILLED CANAL WEST - BLDG L103	633
13	JAN '93	B	GAS CYLINDERS REMOVED FROM WASTE FILLED CANAL WEST - BLDG L103	634
14	JAN '93	B	GAS CYLINDERS REMOVED FROM WASTE FILLED CANAL WEST - BLDG L103	635
15	JAN '93	B	EXCAVATION OF WASTE FILLED CANAL WEST OF BUILDING L103	636
16	JAN '93	B	GAS CYLINDERS REMOVED FROM WASTE FILLED CANALS	637
17	JAN '93	B	EXCAVATION OF WASTE FILLED CANAL IN PROGRESS - WEST OF BLDG L103	638
18	JAN '93	B	VIEW OF CANOPY TO BUILDING L103 ON CANAL SIDE	639
19	JAN '93	B	CONTAMINATED WASTE IN CANAL WEST OF BLDG L103 (ADJACENT TO BLDG ENTRANCE)	640
20	JAN '93	B	SOUTH VIEW SHOWING EXCAVATION OF WASTE FILLED CANAL WEST OF BLDG L103	641
21	JAN '93	B	CONTAMINATED WASTE IN CANAL WEST OF BUILDING L103	642
22	JAN '93	S	CONTAMINATED WASTE TIP SOUTH EAST OF BUILDINGS 107 AND 108	643
23	JAN '93	S	PIPE BRIDGES OVER WASTE FILLED CANALS, WEST OF BURNING GROUND	644
24	JAN '93	H	H16 SAMPLING AREA	645
25	JAN '93	H	H16 SAMPLING AREA	646
26	JAN '93	H	CONTAMINATED BOTTLES FROM WASTE ON H16 SAMPLING ARE	647
27	JAN '93	B	FUSE RECOVERED FROM NORTH END OF BURNING GROUND	648
28	JAN '93	B	FUSE RECOVERED FROM NORTH END OF BURNING GROUND	649
29	JAN '93	L	FLOODED AREA WEST OF INCORPORATING MILLS (QUEENS MEAD)	650
30	JAN '93	B	FLOODED CANAL WEST OF BUILDING L103	651
31	JAN '93	S	FLOODED CANAL WEST OF BUILDING 76	652
32	JAN '93	S	FLOODED AREA AROUND MACHINE (LOOKING NORTH TOWARDS BLDG 62)	653
33	JAN '93	S	FLOODED CANAL WEST OF BUILDING 76	654
34	JAN '93	S	FLOODED CANAL - BUILDING E14 RIGHT OF PICTURE	655
35	JAN '93	T	FLOODED TETRYL AREA, VIEW TOWARDS HORSEMILL STREAM	656
36	JAN '93	S	FLOODED PONDS NORTH OF BUILDINGS E2	657
37	JAN '93	S	EXTENT OF EROSION DUE TO FLOOD WEST OF BUILDING E12	658

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: 22/9590

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1	JAN '93	M	EAST ELEVATION OF BUILDING L148	659
2	JAN '93	M	EAST ELEVATION OF BUILDING L148	660
3	JAN '93	M	VIEW ALONG EAST ELEVATION OF BUILDING L148	661
4	JAN '93	M	VIEW ALONG EAST ELEVATION OF BUILDING L148	662
5	JAN '93	M	EXTERNAL VIEW OF BUILDING L148	663
6	JAN '93	M	WEST ELEVATION OF BUILDING L148	664
7	JAN '93	M	INTERNAL VIEW OF BUILDING L148	665
8	JAN '93	M	INTERNAL VIEW OF BUILDING L148	666
9	JAN '93	M	INTERNAL VIEW OF BUILDING L148	667
10	JAN '93	M	INTERNAL VIEW OF BUILDING L148	668
11	JAN '93	M	INTERNAL VIEW OF BUILDING L148	669
12	JAN '93	M	INTERNAL VIEW OF BUILDING L148	670
13	JAN '93	M	INTERNAL VIEW OF BUILDING L148	671
14	JAN '93	M	INTERNAL VIEW OF BUILDING L148	672
15	JAN '93	M	INTERNAL VIEW OF UNDER FLOOR VOID IN BUILDING L148	673
16	JAN '93	M	INTERNAL VIEW OF UNDER FLOOR VOID IN BUILDING L148	674
17	JAN '93	M	INTERNAL VIEW OF UNDER FLOOR VOID IN BUILDING L148	675
18	JAN '93	M	INTERNAL VIEW OF UNDER FLOOR VOID IN BUILDING L148	676
19	JAN '93	M	INTERNAL VIEW OF UNDER FLOOR VOID IN BUILDING L148	677
20	JAN '93	M	INTERNAL VIEW OF UNDER FLOOR VOID IN BUILDING L148	678
21	JAN '93	M	INTERNAL VIEW OF UNDER FLOOR VOID IN BUILDING L148	679
22	JAN '93	M	INTERNAL VIEW OF UNDER FLOOR VOID IN BUILDING L148	680
23	JAN '93	M	INTERNAL VIEW OF UNDER FLOOR VOID IN BUILDING L148	681
24	JAN '93	M	INTERNAL VIEW OF UNDER FLOOR VOID IN BUILDING L148	682
25	JAN '93	M	INTERNAL VIEW OF UNDER FLOOR VOID IN BUILDING L148	683
26	JAN '93	M	INTERNAL VIEW OF UNDER FLOOR VOID IN BUILDING L148	684
27	JAN '93	M	INTERNAL VIEW OF UNDER FLOOR VOID IN BUILDING L148	685
28	JAN '93	M	INTERNAL VIEW OF UNDER FLOOR VOID IN BUILDING L148	686
29	JAN '93	M	INTERNAL VIEW OF UNDER FLOOR VOID IN BUILDING L148	687
30	JAN '93	M	INTERNAL VIEW OF UNDER FLOOR VOID IN BUILDING L148	688
31	JAN '93	M	INTERNAL VIEW OF UNDER FLOOR VOID IN BUILDING L148	689
32	JAN '93	M	INTERNAL VIEW OF UNDER FLOOR VOID IN BUILDING L148	690
33	JAN '93	M	INTERNAL VIEW OF UNDER FLOOR VOID IN BUILDING L148	691
34	JAN '93	M	INTERNAL VIEW OF UNDER FLOOR VOID IN BUILDING L148	692
35	JAN '93	M	INTERNAL VIEW OF UNDER FLOOR VOID IN BUILDING L148	693
36	JAN '93	M	INTERNAL VIEW OF UNDER FLOOR VOID IN BUILDING L148	694
37	JAN '93	M	VIEW DOWN UNDER FLOOR VOID IN BUILDING L148	695

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: 23/9591

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1	JAN '93	S	TIP SITE 11036 (DISCOVERING BURIED ASBESTOS)	696
2	JAN '93	S	TIP SITE 11036 (DISCOVERING BURIED ASBESTOS)	697
3	JAN '93	S	TIP SITE 11036 (TREES GROWING OUT OF TIP)	698
4	JAN '93	S	TIP SITE 11036 (DISCOVERY OF ASBESTOS AND CHEMICALS)	699
5	JAN '93	S	TIP SITE 11036 (DISCOVERY OF CHEMICALS)	700
6	JAN '93	S	TIP SITE 11036 (DISCOVERY OF ASBESTOS)	701
7	JAN '93	S	TIP SITE 11036 (DISCOVERY OF ASBESTOS)	702
8	JAN '93	S	TIP SITE 11036 (DISCOVERY OF ASBESTOS AND VEHICLE BATTERY)	703
9	JAN '93	S	TIP SITE 11036 (DISCOVERY OF ASBESTOS AND VEHICLE BATTERY)	704
10	JAN '93	S	TIP SITE 11036 (DISCOVERY OF ASBESTOS AND METALS)	705
11	JAN '93	S	TIP SITE 11036 (DISCOVERY OF ASBESTOS AND METALS)	706
12	JAN '93	S	TIP SITE 11036 (REMAINS OF DEMOLISHED STRUCTURES WITHIN RUBBISH DUMP)	707
13	JAN '93	M	CORDITE REMOVAL	708
14	JAN '93	M	CORDITE REMOVAL	709
15	JAN '93	M	CORDITE REMOVAL	710
16	JAN '93	M	INTERNAL VIEW OF UNDERCROFT IN BUILDING L153	711
17	JAN '93	M	INTERNAL VIEW OF UNDERCROFT IN BUILDING L153	712
18	JAN '93	M	INTERNAL VIEW OF BUILDING L153 (ENTRANCE TO UNDERCROFT)	713
19	JAN '93	S	TIP SITE 11036 (ASBESTOS WITHIN RUBBISH DUMP)	714
20	JAN '93	S	TIP SITE 11036 (ASBESTOS WITHIN RUBBISH DUMP)	715
21	JAN '93	S	TIP SITE 11036 (TREES GROWING IN WASTE)	716
22	JAN '93	S	PIT LOCATED ADJACENT TO BUILDING S31	717
23	JAN '93	S	EXCAVATION NORTH EAST OF BUILDING S29	718
24	JAN '93	S	HERONRY DEMARCATION TAPE	719
25	JAN '93	M	REMOVAL OF CORDITE	720
26	JAN '93	M	REMOVAL OF CORDITE	721
27	JAN '93	M	REMOVAL OF CORDITE	722
28	JAN '93	M	CORDITE REMOVAL (CORDITE VISIBLE IN STICK FORM)	723
29	JAN '93	M	CORDITE REMOVAL	724
30	JAN '93	S	TIP SITE 11036 (ASBESTOS REMOVAL)	725
31	JAN '93	S	TIP SITE 11036 (CHEMICAL GLASSWARE)	726
32	JAN '93	S	TIP SITE 11036 (ASBESTOS REMOVAL)	727
33	JAN '93	S	TIP SITE 11036 (ASBESTOS REMOVAL)	728
34	JAN '93	S	TIP SITE 11036 (ASBESTOS REMOVAL)	729
35	JAN '93	M	HOLDING AREA FOR REMOVED CONCRETE FOUNDATIONS	730
36	JAN '93	M	HOLDING AREA FOR REMOVED CONCRETE FOUNDATIONS	731
37	JAN '93	M	HOLDING AREA FOR REMOVED CONCRETE FOUNDATIONS	732

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: 24/9990

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1	JAN '93	H	INTERNAL VIEW OF BUILDING H10	733
2	JAN '93	H	INTERNAL VIEW OF BUILDING H10	734
3	JAN '93	H	INTERNAL VIEW OF BUILDING H10	735
4	JAN '93	H	INTERNAL VIEW OF BUILDING H10	736
5	JAN '93	H	INTERNAL VIEW OF BUILDING H10	737
6	JAN '93	H	INTERNAL VIEW OF BUILDING H10	738
7	JAN '93	M	CORDITE AREA EXCAVATION - LOOKING NORTH	739
8	JAN '93	M	CORDITE AREA EXCAVATION - LOOKING NORTH	740
9	JAN '93	M	CORDITE AREA EXCAVATION - LOOKING NORTH	741
10	JAN '93	M	CORDITE AREA EXCAVATION - LOOKING NORTH	742
11	JAN '93	M	CORDITE AREA EXCAVATION - LOOKING NORTH	743
12	JAN '93	M	CORDITE AREA EXCAVATION - LOOKING SOUTH WEST	744
13	JAN '93	M	CORDITE AREA EXCAVATION	745
14	JAN '93	M	CORDITE AREA EXCAVATION - LOOKING WEST	746
15	JAN '93	M	CORDITE AREA EXCAVATION (ASBESTOS WASTE)	747
16	JAN '93	M	CORDITE AREA EXCAVATION (SCREENING PLANT)	748
17	JAN '93	M	CORDITE AREA EXCAVATION (SCREENING PLANT)	749
18	JAN '93	M	CORDITE AREA EXCAVATION (SCREENING WASTE)	750
19	JAN '93	M	CORDITE AREA EXCAVATION (SCREENING PLANT)	751
20	JAN '93	S	TAKING OUR STEAM MAIN FOUNDATIONS NORTH OF BUILDING L136	752
21	JAN '93	S	WEST ELEVATION OF BUILDING L135	753
22	JAN '93	M	EAST ELEVATION OF BUILDING L148	754
23	JAN '93	B	EXPOSED FUSE ADJACENT TO BUILDING 96	755
24	JAN '93	B	EXPOSED FUSE ADJACENT TO BUILDING 96	756
25	JAN '93	B	INSPECTION OF GAS CYLINDERS BY ROYAL ORDNANCE ADJACENT TO BLDG L175	757

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: 25/0129

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
0	JAN '93	S	POWDER BARGE (RCHME REF.: 104)	758
1	JAN '93	S	POWDER BARGE (RCHME REF.: 104)	759
2	JAN '93	S	VIEW THROUGH EAST SECURITY FENCE	760
3	JAN '93	S	POWDER BARGE WEST OF BLDG 76 - LOOKING NORTH EAST (RCHME REF.: 101)	761
4	JAN '93	S	POWDER BARGE WEST OF BUILDING 76 - LOOKING EAST (RCHME REF.: 101)	762
5	JAN '93	S	POWDER BARGE WEST OF BLDG 76 - LOOKING SOUTH (RCHME REF.: 101)	763
6	JAN '93	S	POWDER BARGE WEST OF BLDG 76 - LOOKING NORTH (RCHME REF.: 101)	764
7	JAN '93	S	POWDER BARGE WEST OF BLDG 76 - LOOKING NORTH EAST (RCHME REF.: 101)	765
8	JAN '93	S	LOCK GATES (RCHME REF.: 225)	766
9	JAN '93	S	VIEW LOOKING WEST ON BUILDING L109	767
10	JAN '93	S	POWDER BARGE (RCHME RE.: 157)	768
11	JAN '93	S	POWDER BARGES (RCHME 157-160)	769
12	JAN '93	S	POWDER BARGES (RCHME 157-160)	770
13	JAN '93	S	POWDER BARGES (RCHME 157-160)	771
14	JAN '93	S	SITE OPERATIVES (TEMPORARY SAFETY FENCING)	772
15	JAN '93	M	INTERNAL VIEW OF BUILDING L148 (STRIPPING OUT)	773
16	JAN '93	M	INTERNAL VIEW OF BUILDING L148 (STRIPPING OUT)	774
17	JAN '93	M	INTERNAL VIEW OF BUILDING L148 (STRIPPING OUT)	775
18	JAN '93	M	INTERNAL VIEW OF BUILDING L148 (STRIPPING OUT)	776
19	JAN '93	M	INTERNAL VIEW OF BUILDING L148 (STRIPPING OUT)	777
20	JAN '93	M	SOUTH EAST ELEVATION OF BUILDING L148	778
21	JAN '93	M	INTERNAL VIEW OF BUILDING L148 (STRIPPING OUT)	779
22	JAN '93	M	INTERNAL VIEW OF BUILDING L148 (STRIPPING OUT)	780
23	JAN '93	M	INTERNAL VIEW OF BUILDING L148 (STRIPPING OUT)	781
24	JAN '93	M	INTERNAL VIEW OF BUILDING L148 (STRIPPING OUT)	782
25	JAN '93	M	INTERNAL VIEW OF BUILDING L148 (STRIPPING OUT)	783
26	JAN '93	M	INTERNAL VIEW OF BUILDING L148 (STRIPPING OUT)	784
27	JAN '93	M	INTERNAL VIEW OF BUILDING L148 (STRIPPING OUT)	785
28	JAN '93	M	INTERNAL VIEW OF BUILDING L148 (STRIPPING OUT)	786
29	JAN '93	M	INTERNAL VIEW OF BUILDING L148 (STRIPPING OUT)	787
30	JAN '93	P	WEST ELEVATION OF BUILDING A269	788
31	JAN '93	P	NORTH ELEVATION OF BUILDING A269	789
32	JAN '93	M	INTERNAL VIEW OF BUILDING L148 (ASPHALT FLOOR SURFACE REMOVAL)	790
33	JAN '93	M	INTERNAL VIEW OF BUILDING L148 (STRIPPING OUT)	791
34	JAN '93	M	INTERNAL VIEW OF BUILDING L148 (VACUUMING INTERNAL SURFACES)	792
35	JAN '93	M	INTERNAL VIEW OF BUILDING L148 (ASPHALT FLOOR SURFACE REMOVAL)	793
36	JAN '93	P	WEST ELEVATION OF BUILDING A269	794
37	JAN '93	P	WEST ELEVATION OF BUILDING A269	795

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: 26/0130

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1	JAN '93	B	EMBLEM IN BUILDING L102 (ROYAL GUNPOWDER FACTORY DEPICTED)	796
2	JAN '93	B	EMBLEM IN BUILDING L102 (ROYAL GUNPOWDER FACTORY DEPICTED)	797
3	JAN '93	B	EMBLEM ON BRIDGE No. 16 - EAST OF BUILDING 96	798
4	JAN '93	B	EMBLEM ON SIDE OF AQUEDUCT - BRIDGE No. 14 (NORTH EAST OF BLDG 96)	799
5	JAN '93	S	EMBLEM ON BRIDGE No. 16	800
6	JAN '93	S	CLOSE UP VIEW OF EMBLEM ON BRIDGE No. 16	801
7	JAN '93	S	EMBLEM ON BRIDGE No. 16	802
8	JAN '93	B	EMBLEM ON SIDE OF AQUEDUCT - BRIDGE No. 14 (NORTH EAST OF BLDG 96)	803
9	JAN '93	B	BRIDGE No. 16 - SOUTH ELEVATION	804
10	JAN '93	B	BRIDGE No. 19 - CARRYING BRIDGE TO BUILDING 96	805
11	JAN '93	B	BRIDGE No. 16 - SOUTH ELEVATION	806
12	JAN '93	B	BRIDGE No. 16 - SOUTH ELEVATION	807
12 R	JAN '93	B	SOUTH EAST VIEW OF BURNING GROUND	808

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: 27/0536

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1			NOT USED	
2			NOT USED	
3	FEB '93	M	CORDITE EXPOSED IN CORDITE AREA	809
4	FEB '93	M	CORDITE EXPOSED IN CORDITE AREA	810
5	FEB '93	M	CORDITE EXPOSED IN CORDITE AREA	811
6	FEB '93	M	CORDITE EXPOSED IN CORDITE AREA	812
7			NOT USED	
8			NOT USED	
9	FEB '93	B	INVESTIGATING CONTAMINATED MATERIAL FROM TIP No. 11038 - BURNING GROUND NORTH	813
10	FEB '93	B	LOOKING THROUGH TIP No. 11038 NORTH BURNING GROUND	814
11	FEB '93	M	CONCRETE BASE OF BUILDING L169 (SET OUT FOR SAMPLING OF WASTE)	815
12	FEB '93	M	CONCRETE BASE OF BUILDING L169 (SET OUT FOR SAMPLING OF WASTE)	816
13	FEB '93	M	CONCRETE BASE OF BUILDING L169 (SET OUT FOR SAMPLING OF WASTE)	817
14	FEB '93	L	VIEW LOOKING NORTH FROM BUILDING L169 ACROSS 'QUEENS MEAD'	818
15	FEB '93	M	WASTE BEGIN DELIVERED TO SAMPLING SLAB AT L169	819
16	FEB '93	M	EXCAVATION IN CORDITE AREA (BUILDING L160 IN TOP RIGHT)	820
17	FEB '93	M	EXCAVATION IN CORDITE AREA (BUILDING L160 IN TOP RIGHT)	821
18	FEB '93	M	EXCAVATION IN CORDITE AREA (BUILDING L160 IN TOP RIGHT)	822
19	FEB '93	M	EXCAVATION IN CORDITE AREA	823
20	FEB '93	M	EXCAVATION IN CORDITE AREA	824
21	FEB '93	M	CORDITE FOUND	825
22	FEB '93	M	CORDITE FOUND	826
23	FEB '93	M	SOUTH ELEVATION OF BUILDING L148	827
24	FEB '93	M	STOCKPILE OF ASBESTOS CONTAMINATED SOIL	828
25	FEB '93	M	ASBESTOS CONTAMINATED SOIL STRIPPED ALONG WEST ELEVATION OF BUILDING L157	829
26	FEB '93	L	ASBESTOS CONTAMINATED SOIL STRIPPED ALONG WEST ELEVATION OF BUILDING L157	830
27	FEB '93	M	WASTE SAMPLING AT L169 SAMPLING AREA (P.P.E.)	831
28	FEB '93	P	JUNCTION OF POWDERMILL LANE AND FLAGSTAFF ROAD LOOKING SOUTH	832
29	FEB '93	M	BUILDING L157 UNDERCROFT	833
30	FEB '93	S	FALLEN TREE WEST SSSI	834
31	FEB '93	S	FALLEN TREE WEST SSSI	835
32	FEB '93	S	FALLEN TREE WEST SSSI	836
33	FEB '93	S	STEAM PIPE ROUTE NORTH OF BUILDING 76	837
34	FEB '93	S	STEAM PIPE ROUTE NORTH OF BUILDING 76 (ASBESTOS CONTAMINATION)	838
35	FEB '93	S	STEAM PIPE ROUTE NORTH OF BUILDING 76 (ASBESTOS CONTAMINATION)	839
36	FEB '93	S	GROUND UNDER STEAM PIPE ROUTE NORTH BUILDING 76 (ASBESTOS CONTAMINATION)	840
36 A	FEB '93	S	STEAM PIPE ROUTE NORTH OF BUILDING 76 (ASBESTOS CONTAMINATION)	841

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: 28/1012

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1	FEB '93	S	WASTE TIP SOUTH OF BUILDING S32 (ASBESTOS)	842
2	FEB '93	S	WASTE TIP SOUTH OF BUILDING S32 (ASBESTOS)	843
3	FEB '93	S	WASTE TIP SOUTH OF BUILDING S32 (ASBESTOS)	844
4	FEB '93	M	MILLSTONE FOUND WHILST SCRAPPING	845
5	FEB '93	M	INTERNAL VIEW OF BUILDING L157 - 1ST STAGE DECONTAMINATION	846
6	FEB '93	M	INTERNAL VIEW OF BUILDING L157 - 1ST STAGE DECONTAMINATION	847
7	FEB '93	M	INTERNAL VIEW OF BUILDING L157 - 1ST STAGE DECONTAMINATION	848
8	FEB '93	M	INTERNAL VIEW OF BUILDING L157 - 1ST STAGE DECONTAMINATION	849
9	FEB '93	M	INTERNAL VIEW OF BUILDING L157 (PRIOR TO DECONTAMINATION)	850
10	FEB '93	M	INTERNAL VIEW OF BUILDING L157 (PRIOR TO DECONTAMINATION)	851
11	FEB '93	M	INTERNAL VIEW OF BUILDING L157 (BAGGED ASBESTOS)	852
12	FEB '93	M	INTERNAL VIEW OF BUILDING L157 (CONTAMINATED STEELWORK STACKED)	853
13	FEB '93	M	INTERNAL VIEW OF BUILDING L157 (BAGGED CONTAMINATED MATERIAL)	854
14	FEB '93	M	INTERNAL VIEW OF BUILDING L157 (BAGGED CONTAMINATED MATERIAL)	855
15	FEB '93	M	INTERNAL VIEW OF BUILDING L157 (BAGGED CONTAMINATED MATERIAL)	856
16	FEB '93	M	INTERNAL VIEW OF BUILDING L157 (PRIOR TO DECONTAMINATION)	857
17	FEB '93	M	INTERNAL VIEW OF BUILDING L157 (BAGGED CONTAMINATED MATERIAL AND TIMBER)	858
18	FEB '93	M	INTERNAL VIEW OF BUILDING L157 - DECONTAMINATION OPERATIVES	859
19	FEB '93	M	INTERNAL VIEW OF BUILDING L157 - DECONTAMINATION OPERATIVES	860
20	FEB '93	M	INTERNAL VIEW OF BUILDING L157 - DECONTAMINATION OPERATIVE	861
21	FEB '93	M	INTERNAL VIEW OF BUILDING L157 (ASBESTOS REMOVAL CONTRACTOR'S NEGATIVE AIR TENT)	862
22	FEB '93	M	BUILDING L157 - EXTERNAL SAVE ALL DRAIN	863
23	FEB '93	M	CORDITE SCREENING PLANT	864
24	FEB '93	M	GRADED ARISINGS FROM CORDITE CONTAMINATED AREAS	865
25	FEB '93	M	STOCKPILING SCREENED CORDITE ARISINGS	866
26	FEB '93	M	STOCKPILING OF ARISINGS FROM CORDITE CONTAMINATED AREA	867
27	FEB '93	M	SCREENED ARISINGS FROM CORDITE CONTAMINATED AREA	868
28	FEB '93	M	CLOSE UP OF GRADED ARISINGS FROM CORDITE CONTAMINATED AREA	869
29	FEB '93	M	GRADED ARISINGS FROM CORDITE CONTAMINATED AREA	870
30	FEB '93	M	CLOSE UP OF GRADED ARISINGS FROM CORDITE CONTAMINATED AREA	871
31	FEB '93	M	COARSE SCREENED ARISINGS FROM CORDITE CONTAMINATED AREA	872
32	FEB '93	M	CLOSE UP OF GRADED ARISINGS FROM CORDITE CONTAMINATED AREA	873
33	FEB '93	M	MILLSTONE EXCAVATED FROM CORDITE AREA	874
34	FEB '93	M	MILLSTONE EXCAVATED FROM CORDITE AREA	875
35	FEB '93	M	MILLSTONES EXCAVATED FROM CORDITE AREA	876

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: 29/1013

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1	FEB '93	M	REMOVAL OF CORDITE CONTAMINATED GROUND	877
2	FEB '93	M	REMOVAL OF CORDITE CONTAMINATED GROUND	878
3	FEB '93	M	REMOVAL OF CORDITE CONTAMINATED GROUND	879
4	FEB '93	S	ONE OF THE OLDEST EXAMPLES OF HORSE CHESTNUT TREE	880
5	FEB '93	S	ONE OF THE OLDEST EXAMPLES OF HORSE CHESTNUT TREE	881
6	FEB '93	S	ROYAL ORDNANCE SUPERVISOR CHECKING TREE TAGS PRIOR TO FELLING	882
7	FEB '93	H	TREES GROWING OUT OF BUILDING H72	883
8	FEB '93	N	VIEW OF SUSPECT PIT AT NEW HILL - LOOKING SOUTH	884
9	FEB '93	N	VIEW LOOKING NORTH AT NEW HILL ALONG LINE OF SUSPECT PITS	885
10	FEB '93	N	SUSPECT PIT AT NEW HILL NEAR TO EAST ACCESS GATE	886
11	FEB '93	N	SUSPECT PIT AT NEW HILL NEAR TO EAST ACCESS GATE	887
12	FEB '93	N	SUSPECT PIT AT NEW HILL NEAR TO EAST ACCESS GATE	888
13	FEB '93	N	SUSPECT PIT AT NEW HILL NEAR TO EAST ACCESS GATE	889
14	FEB '93	S	BAGGED ASBESTOS AWAITING COLLECTION FROM WASTE TIPS	890
15	FEB '93	S	VIEW OF WASTE TIP, DENSE ASBESTOS CONTAMINANTS REMOVED BY SPECIALIST CONTRACTORS	891
16	FEB '93	M	VIEW OF CANAL 'OPENED UP' IN THE CORDITE CONTAMINATED AREA (BUILDING L159 IN THE BACKGROUND) (BAGGED ASBESTOS)	892
17	FEB '93	M	VIEW OF CANAL 'OPENED UP' IN THE CORDITE CONTAMINATED AREA	893
18	FEB '93	M	VIEW OF CANAL 'OPENED UP' IN THE CORDITE CONTAMINATED AREA	894
19	FEB '93	M	VIEW OF CANAL 'OPENED UP' IN THE CORDITE CONTAMINATED AREA	895
20	FEB '93	M	ASBESTOS BEING REMOVED FROM FILLED CANAL IN CORDITE CONTAMINATED AREA (ASBESTOS CONTAMINANTS)	896
21	FEB '93	M	LICENSED ASBESTOS CONTRACTOR BAGGING ASBESTOS IN CORDITE CONTAMINATED AREA BUILDING A214 TOWER IN BACKGROUND)	897
22	FEB '93	H	SERVICE TRENCH BETWEEN BUILDING A203 AND BRIDGE No. 17	898
23	FEB '93	H	SERVICE TRENCH BETWEEN BUILDING A203 AND BRIDGE No. 17	899
24	FEB '93	H	SERVICE TRENCH BETWEEN BUILDING A203 AND BRIDGE No. 17	900
25	FEB '93	H	WEST SIDE OF BUILDING LOOKING NORTH (HOPPIT POOL TO THE LEFT)	901
26	FEB '93	H	SERVICE TRENCH TO BUILDING A200 FROM BUILDING A201/2	902
27	FEB '93	H	SERVICE TRENCH TO BUILDING A200	903
28	FEB '93	H	SERVICE TRENCH TO BUILDING A200	904
29	FEB '93	H	SERVICE TRENCH UNDER ROAD NORTH OF BUILDING A203	905
30	FEB '93	H	SERVICE TRENCH NORTH OF BUILDING A203 (ENTRY TO A203 PLANT ROOM)	906
31	FEB '93	H	TRENCH NORTH OF BUILDING A203	907
32	FEB '93	H	SERVICE TRENCH BETWEEN BUILDING A203 AND BRIDGE No. 17	908
33	FEB '93	H	STOCKPILING CLEAN CONCRETE WASTE EAST OF H8	909
34	FEB '93	H	VIEW OF FELLED TREES - LOOKING EAST FROM H8	910
35	FEB '93	H	STOCKPILING OF CONCRETE WASTE EAST OF H8	911
36	FEB '93	H	STOCKPILING OF CONCRETE WASTE EAST OF H8	912
37	FEB '93	M	WASTE MATERIAL LAID OUT ON L169 PRIOR TO SAMPLING	913

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: 30/1014

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1	FEB '93	H	SOUTH EAST VIEW OF STOCKPILING 'SPECIAL WASTE' ON H19 AREA	914
2	FEB '93	H	NORTH VIEW OF STOCKPILED 'SPECIAL WASTE' ON H19 AREA	915
3	FEB '93	H	NEW WATER VALVE INSTALLATION NORTH OF BUILDING A203	916
4	FEB '93	H	NEW WATER VALVE INSTALLATION NORTH OF BUILDING A203	917
5	FEB '93	M	GENERAL VIEW OF SOIL REMOVAL IN CORDITE CONTAMINATED AREA	918
6	FEB '93	M	GENERAL VIEW OF SOIL REMOVAL IN CORDITE CONTAMINATED AREA	919
7	FEB '93	M	REMOVAL OF CORDITE CONTAMINATED SOIL (CORDITE STICKS)	920
8	FEB '93	M	REMOVAL OF CORDITE CONTAMINATED SOIL (CORDITE STICKS)	921
9	FEB '93	M	REMOVAL OF CORDITE CONTAMINATED GROUND	922
10	FEB '93	M	REMOVAL OF CORDITE CONTAMINATED GROUND (CORDITE STICKS)	923
11	FEB '93	M	REMOVAL OF CORDITE CONTAMINATED GROUND	924
12	FEB '93	P	TRACKING SERVICES WITH 'CAT' SOUTH OF BUILDING A231	925
13	FEB '93	M	INTERNAL VIEW OF BUILDING L153 (CEILING REMOVED - 1ST STAGE DECONTAMINATION)	926
14			NOT USED	
15	FEB '93	M	INTERNAL VIEW OF BUILDING L153 (CORE HOLES IN WALL)	927
16	FEB '93	M	INTERNAL VIEW OF BUILDING L153 - 1ST STAGE DECONTAMINATION	928
17	FEB '93	M	INTERNAL VIEW OF BUILDING L153 - STRIPPING OUT (VACUUMING TIMBER PARTITIONS)	929
18	FEB '93	M	INTERNAL VIEW OF BUILDING L153 - STRIPPING OUT (VACUUMING TIMBER PARTITIONS)	930
19	FEB '93	M	BUILDING L153 - CARTING AWAY WASTE	931
20	FEB '93	M	BUILDING L153 - STRIPPING OUT (CONTAMINATED TIMBER STORE)	932
21	FEB '93	M	BUILDING L153 - STRIPPING OUT (CONTAMINATED TIMBER STORE)	933
22	FEB '93	M	BUILDING L153 - STRIPPING OUT (CONTAMINATED TIMBER STORE)	934
23	FEB '93	H	BLANKED OFF HYDRANT NEAR HIGHBRIDGE STREET (WEST)	935
24	FEB '93	H	BLANKED OFF HYDRANT NEAR HIGHBRIDGE STREET (NORTH EAST)	936
25	FEB '93	H	BLANKING OFF A HYDRANT NEAR HIGHBRIDGE STREET (NORTH EAST)	937
26	FEB '93	M	EXCAVATION OF CORDITE CONTAMINATED GROUND - SCREENING PLANT BEYOND	938
27	FEB '93	M	OPENING UP OF FILLED CANAL BRANCH IN CORDITE CONTAMINATED AREA	939
28	FEB '93	M	REMOVAL OF CORDITE CONTAMINATED GROUND	940
29	FEB '93	M	REMOVAL OF CORDITE CONTAMINATED GROUND	941
30	FEB '93	M	REMOVAL OF CORDITE CONTAMINATED GROUND	942
31	FEB '93	M	OPENING UP OF FILLED CANAL IN CORDITE CONTAMINATED AREA	943
32	FEB '93	M	OPENING UP OF FILLED CANAL IN CORDITE CONTAMINATED AREA	944
33	FEB '93	M	OPENING UP OF FILLED CANAL IN CORDITE CONTAMINATED AREA	945
34	FEB '93	M	OPENING UP OF FILLED CANAL IN CORDITE CONTAMINATED AREA (TIMBER PILES DELINEATED CANAL EDGES)	946
35	FEB '93	M	OPENING UP OF FILLED CANAL IN CORDITE CONTAMINATED AREA (BUILDING L159 - CENTRE)	947
36	FEB '93	M	OPENING UP OF FILLED CANAL IN CORDITE CONTAMINATED AREA	948

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: 31/1373

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1	MAR '93	M	OPENING UP OF FILLED CANAL IN CORDITE CONTAMINATED AREA	949
2	MAR '93	M	OPENING UP OF FILLED CANAL IN CORDITE CONTAMINATED AREA	950
3	MAR '93	M	OPENING UP OF FILLED CANAL IN CORDITE CONTAMINATED AREA	951
4	MAR '93	M	OPENING UP OF FILLED CANAL IN CORDITE CONTAMINATED AREA	952
5	MAR '93	M	OPENING UP OF FILLED CANAL IN CORDITE CONTAMINATED AREA	953
6	MAR '93	M	OPENING UP OF FILLED CANAL IN CORDITE CONTAMINATED AREA	954
7	MAR '93	M	OPENING UP OF FILLED CANAL IN CORDITE CONTAMINATED AREA	955
8	MAR '93	M	OPENING UP OF FILLED CANAL IN CORDITE CONTAMINATED AREA	956
9	MAR '93	M	OPENING UP OF FILLED CANAL IN CORDITE CONTAMINATED AREA	957
10	MAR '93	H	SERVICE TRENCH ADJACENT TO BUILDING H26	958
11	MAR '93	H	SERVICE TRENCH NORTH OF HIGHBRIDGE STREET GATE	959
12	MAR '93	P	INTERNAL VIEW OF BUILDING A210 (CORDITE CONTAMINATED MATERIAL STOCKPILED FOR DRYING OUT)	960
13	MAR '93	M	INTERNAL VIEW OF BUILDING L168	961
14	MAR '93	M	INTERNAL VIEW OF BUILDING L168	962
15	MAR '93	M	REMOVAL OF CORDITE CONTAMINATED GROUND	963
16	MAR '93	M	REMOVAL OF CORDITE CONTAMINATED GROUND	964
17	MAR '93	H	REMOVAL OF CORDITE CONTAMINATED GROUND	965
18	MAR '93	H	EXCAVATED FOUND IN USE AS A FOUNDATION	966
19	MAR '93	H	EXCAVATION OF SERVICES ADJACENT TO BUILDING H26 (MILLSTONE FOUND IN USE AS A FOUNDATION)	967
20	MAR '93	H	EXCAVATION FOR SERVICES SOUTH OF BUILDING H26	968
21	MAR '93	H	EXCAVATION FOR SERVICES SOUTH OF BUILDING H26	969
22	MAR '93	H	EXCAVATION FOR SERVICES SOUTH OF BUILDING H26	970
23	MAR '93	H	EXPOSED TIE ROD FOR MILLHEAD STREAM CONCRETE PILED REVETMENT	971
24	MAR '93	M	INTERNAL VIEW OF BUILDING L157 (HOLES THROUGH FLOOR HAVE BEEN SEALED TO PREVENT ESCAPE OF ASBESTOS FIBRES)	972
25	MAR '93	M	INTERNAL VIEW OF BUILDING L157 - ASBESTOS REMOVAL	973
26	MAR '93	M	INTERNAL VIEW OF BUILDING L157 - ASBESTOS REMOVAL	974
27	MAR '93	M	INTERNAL VIEW OF BUILDING L157 - INITIAL STRIP OUT	975
28	MAR '93	M	INTERNAL VIEW OF BUILDING L157 - ASBESTOS REMOVAL	976
29	MAR '93	M	INTERNAL VIEW OF BUILDING L157 (REMOVAL OF ASPHALT FROM CORRIDOR FLOOR)	977
30	MAR '93	M	INTERNAL VIEW OF BUILDING L157	978
31	MAR '93	M	INTERNAL VIEW OF BUILDING L157	979
32	MAR '93	M	INTERNAL VIEW OF BUILDING L157	980
33	MAR '93	H	SERVICES TRENCH FROM BLDG A203- A200 (NEW SERVICES BEING INSTALLED)	981
34	MAR '93	H	SERVICES TRENCH TO BUILDING A200	982
35	MAR '93	H	SERVICES TRENCH TO BUILDING A200	983
36	MAR '93	H	STOCKPILING OF 'SPECIAL WASTE' ON H19 AREA	984
36 A	MAR '93	H	EXCAVATION FOR SERVICES EAST OF BUILDING H26	985

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: 32/1374

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1			NOT USED	
2	MAR '93	H	SERVICE TRENCH EAST OF BUILDING H26	986
3	MAR '93	H	SERVICE TRENCH EXCAVATION	987
4	MAR '93	H	'SPECIAL WASTE' STOCKPILED WEST OF BUILDING H23	988
5	MAR '93	H	'SPECIAL WASTE' STOCKPILED ON H19 AREA	989
6	MAR '93	M	BUILDING L148 - TIDYING UP EXTERNALLY	990
7	MAR '93	M	BUILDING L153 - TIDYING UP EXTERNALLY	991
8	MAR '93	M	INTERNAL VIEW OF BUILDING L148 (BAGGING ASPHALT FROM CORRIDOR FLOOR)	992
9	MAR '93	M	INTERNAL VIEW OF BUILDING L148 (REMOVAL OF ASPHALT FROM CORRIDOR FLOOR)	993
10	MAR '93	M	INTERNAL VIEW OF BUILDING L148 (BAGGING ASPHALT FROM CORRIDOR FLOOR)	994
11	MAR '93	M	INTERNAL VIEW OF BUILDING L148 (VACUUMING ROOF)	995
12	MAR '93	M	INTERNAL VIEW OF BUILDING L148 (VACUUMING ROOF & WALLS - TYPE 'H' VACUUM IN USE)	996
13	MAR '93	M	INTERNAL VIEW OF BUILDING L148 (GENERAL VIEW OF VACUUMING - TYPE 'H' VACUUM IN USE)	997

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: 33/1575

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1	MAR '93	S	BAGGED ASBESTOS STOCKPILED AWAITING MOVE TO HOLDING / SAMPLING AREA	998
2	MAR '93	S	BAGGED ASBESTOS STOCKPILED AWAITING MOVE TO HOLDING / SAMPLING AREA	999
3	MAR '93	S	ASBESTOS REMOVAL IN PROGRESS FORM WASTE DUMP	1000
4	MAR '93	B	FILLED CANAL - EXCAVATION OF WASTE (BURNING GROUND NORTH)	1001
5	MAR '93	S	FILLED CANAL - EXCAVATION OF WASTE (BURNING GROUND NORTH)	1002
6	MAR '93	B	VARIOUS PRESSURE CYLINDERS FOUND IN WASTE FROM CANAL EXCAVATION (BURNING GROUND NORTH)	1003
7	MAR '93	B	EXCAVATION OF FILLED CANAL (BURNING GROUND NORTH)	1004
8	MAR '93	B	TRACKED DUMPER TRANSPORTING WASTE MATERIAL	1005
9	MAR '93	B	PRESSURE CYLINDER FOUND IN CANAL WASTE	1006
10	MAR '93	B	360° MACHINE CLEARING FILLED CANAL (BRIDGE No. 16 IN BACKGROUND)	1007
11	MAR '93	B	WASTE DUMP EAST OF BURNING GROUND (REF.: 11038)	1008
12	MAR '93	B	TREE CLEARANCE OVER WASTE TIP (BRIDGE No. 10 IN BACKGROUND)	1009
13	MAR '93	M	CORDITE RECOVERED FROM AREA 'M'	1010
14	MAR '93	M	CORDITE RECOVERED FROM AREA 'M'	1011
15	MAR '93	M	CORDITE RECOVERED FROM AREA 'M'	1012
16	MAR '93	M	CORDITE RECOVERED FROM AREA 'M'	1013
17	MAR '93	M	CORDITE RECOVERED FROM AREA 'M'	1014
18	MAR '93	H	SERVICE TRENCH WEST BANK OF MILLHEAD STREAM (INSTALLATION OF ISLAND SITE SERVICES)	1015
19	MAR '93	H	SERVICE TRENCH WEST BANK OF MILLHEAD STREAM	1016
20	MAR '93	H	SERVICE TRENCH WEST BANK OF MILLHEAD STREAM	1017
21	MAR '93	H	SERVICE TRENCH WEST BANK OF MILLHEAD STREAM	1018
22	MAR '93	H	SERVICE TRENCH WEST BANK OF MILLHEAD STREAM	1019
23	MAR '93	H	NEW SERVICES TRENCH - EXISTING TIMBER BOARDING	1020
24	MAR '93	H	SERVICE TRENCH WEST BANK OF MILLHEAD STREAM	1021
25	MAR '93	H	TRIAL PIT AT CORNER OF BUILDING A200	1022
26	MAR '93	H	TRIAL PIT AT CORNER OF BUILDING A200	1023
27	MAR '93	H	TRIAL PIT AT CORNER OF BUILDING A200	1024
28	MAR '93	H	TRIAL PIT AT CORNER OF BUILDING A200	1025
29	MAR '93	H	TRIAL PIT AT CORNER OF BUILDING A200	1026
30	MAR '93	H	TRIAL PIT AT CORNER OF BUILDING A200	1027
31	MAR '93	H	EXCAVATION OF TRIAL PIT AT BUILDING A200	1028
32	MAR '93	H	TRIAL PIT AT CORNER OF BUILDING A200	1029
33	MAR '93	H	BUILDING A203 - DUCT IN SERVICE TRENCH	1030
34	MAR '93	H	BUILDING A203 - DUCT IN SERVICE TRENCH	1031
35	MAR '93	H	BUILDING A202 - TELEPHONE DRAW PIT WEST SIDE OF BUILDING	1032
36	MAR '93	H	SERVICE TRENCH ON WEST SIDE OF BUILDINGS A202 AND A203	1033
36 A	MAR '93	H	SERVICE TRENCH AT BRIDGE No. 17	1034

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: 34/2032

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1	10/3/93	H	VIEW ACROSS MILLHEAD STREAM SHOWING SERVICE TRENCH ON WEST BANK (LOOKING SOUTH WEST)	1035
2	10/3/93	S	EXCAVATION OF WASTE TIP REF.: 11034 LOOKING SOUTH	1036
3	10/3/93	H	VIEW OF ROOF OF BUILDING A201/2 (DILAPIDATION OF ROOF)	1037
4	10/3/93	H	BUILDING A201 AND A202 - FLAT ROOF LOOKING EAST (POOR CONDITION)	1038
5	10/3/93	H	BUILDING A201 AND A202 - FLAT ROOF LOOKING WEST (POOR CONDITION)	1039
6	10/3/93	H	VIEW FROM A201 FLAT ROOF TOWARDS AREA 'H'	1040
7	10/3/93	H	BUILDING A201 - VALLEY GUTTER SHOWING DAMAGED SLATES (WEST)	1041
8	10/3/93	H	BUILDING A201 - VALLEY GUTTER SHOWING DAMAGED SLATES (EAST)	1042
9	10/3/93	H	BUILDING A201 - VALLEY GUTTER SHOWING DAMAGED SLATES (EAST)	1043
10	10/3/93	H	BUILDING A201 - VALLEY GUTTER SHOWING DAMAGED HIP SLATES	1044
11	10/3/93	H	BUILDING A201 - SHOWING DAMAGED HIP SLATES	1045
12	10/3/93	H	BUILDING A201 - ROOF SHOWING PATCH TO HIP END (POOR CONDITION)	1046

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: 35/2033

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1	11/3/93	H	'SPECIAL WASTE' STOCKPILE AT H19 AREA	1047
2	11/3/93	H	'SPECIAL WASTE' STOCKPILE AT H19 AREA (LOADING OFF SITE TRANSPORT)	1048
3	11/3/93	H	'SPECIAL WASTE' STOCKPILE AT H19 AREA (LOADING OFF SITE TRANSPORT)	1049
4	11/3/93	H	AIR MONITOR AT H19 'SPECIAL WASTE' STOCKPILE	1050
5	11/3/93	H	AIR MONITOR AT H19 'SPECIAL WASTE' STOCKPILE	1051
6	11/3/93	H	AIR MONITOR AT H19 'SPECIAL WASTE' STOCKPILE	1052
7	11/3/93	H	AIR MONITOR AT H19 'SPECIAL WASTE' STOCKPILE	1053
8	11/3/93	H	AIR MONITORING AT H24 LOCATION NEAR 'SPECIAL WASTE' STOCKPILE	1054
9	11/3/93	H	AIR MONITORING AT H24 LOCATION NEAR 'SPECIAL WASTE' STOCKPILE	1055
10	11/3/93	H	AIR MONITORING AT H19	1056
11	11/3/93	H	'SPECIAL WASTE' REMOVAL - LORRY CLEANING (PRESSURE WASHER)	1057
12	11/3/93	H	'SPECIAL WASTE' REMOVAL - LORRY CLEANING (PRESSURE WASHER)	1058
13	11/3/93	H	VIEW OF H16 WASTE SAMPLING AREA (DAMPENING DOWN WASTE TO CONTROL DUST)	1059
14	12/3/93	B	BURIED STRUCTURE EAST OF BURNING GROUND	1060
15	12/3/93	B	BURIED STRUCTURE EAST OF BURNING GROUND	1061
16	12/3/93	B	BURIED STRUCTURE EAST OF BURNING GROUND	1062
17	12/3/93	B	ASBESTOS DUMP EAST OF BURNING GROUND TIP REF.: 11038	1063
18	12/3/93	B	ASBESTOS DUMP EAST OF BURNING GROUND TIP REF.: 11038	1064
19	12/3/93	B	ASBESTOS DUMP EAST OF BURNING GROUND TIP REF.: 11038	1065
20	12/3/93	B	ASBESTOS DUMP EAST OF BURNING GROUND TIP REF.: 11038	1066
21	12/3/93	B	ASBESTOS DUMP EAST OF BURNING GROUND TIP REF.: 11038	1067
22	12/3/93	B	WASTE TIP REF.: 11038 - NORTH BURNING GROUND - REMOVAL	1068
23	12/3/93	B	WASTE TIP REF.: 11038 - NORTH BURNING GROUND - AFTER REMOVAL	1069
24	12/3/93	B	WASTE TIP REF.: 11038 - NORTH BURNING GROUND (WHITE DEPOSITS IN GRAVEL'S)	1070
25	12/3/93	B	WASTE TIP REF.: 11038 - NORTH BURNING GROUND	1071
26	12/3/93	B	WASTE TIP REF.: 11038 - NORTH BURNING GROUND	1072
27	12/3/93	B	ASBESTOS DUMP SOUTH EAST OF BURNING GROUND	1073
28	12/3/93	P	WASTE FROM AROUND THE SITE BEING SORTED OUT TO RETRIEVE SCRAP METALS	1074
29	12/3/93	H	MOBILE SITE LABORATORY - AIR MONITORING	1075
30	12/3/93	H	MOBILE SITE LABORATORY - AIR MONITORING	1076
31	12/3/93	H	MOBILE SITE LABORATORY - AIR MONITORING	1077
32	12/3/93	H	TRIAL PIT AT H19 - LOOKING N/E TO DETERMINE DEPTH OF FILLED GROUND	1078
33	12/3/93	H	TRIAL PIT AT H19 - CLOSE UP OF FILLED IN LEVELS	1079
34	12/3/93	H	TRIAL PIT AT H19 - LOOKING N/E TO DETERMINE DEPTH OF FILLED GROUND	1080
35	12/3/93	P	BUILDING A238 - REFURBISHMENT OF ROOF	1081

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: 36/2034

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1	8/3/93	H	'SPECIAL WASTE' LORRIES LEAVING HIGHBRIDGE STREET	1082
2	8/3/93	H	'SPECIAL WASTE' LORRIES LEAVING HIGHBRIDGE STREET	1083
3	8/3/93	H	LOADING 'SPECIAL WASTE' LORRIES ON H19 AREA	1084
4	8/3/93	H	LOADING 'SPECIAL WASTE' LORRIES ON H19 AREA	1085
5	9/3/95	H	SERVICE TRENCH WEST BANK MILLHEAD STREAM	1086
6	9/3/95	H	SERVICE TRENCH SHOWING EXISTING SERVICES	1087
7	9/3/95	H	SERVICE TRENCH SHOWING EXISTING SERVICES	1088
8	9/3/95	H	SERVICE TRENCH SHOWING REVETMENT TIE RODS	1089
9	9/3/95	H	SERVICE TRENCH SHOWING EXISTING SERVICES	1090
10	9/3/95	H	SERVICE TRENCH SHOWING EXISTING SERVICES	1091
11	9/3/95	H	SERVICE TRENCH (WATER ONLY) SOUTH OF H10	1092
12	9/3/95	H	SERVICE TRENCH (ELECTRICITY ONLY) EAST OF H10	1093
13	9/3/95	H	SERVICE TRENCH (WATER ONLY) SOUTH OF H6 AND H5	1094
14	9/3/95	H	SERVICE TRENCH (WATER ONLY) SOUTH OF H10	1095
15	9/3/95	H	SERVICE TRENCH (ELECTRICITY ONLY) NORTH OF H10 - H17	1096
16	9/3/95	H	SERVICE TRENCH (ELECTRICITY ONLY) NORTH OF H10 - H17	1097
17	9/3/95	H	SERVICE TRENCH (ELECTRICITY ONLY) NORTH OF H10 - H17	1098
18	9/3/95	H	SERVICE TRENCH (ELECTRICITY ONLY) H17 - H8	1099
19	10/3/95	B	EXCAVATION OF WASTE TIP REF.: 11032	1100
20	10/3/95	B	WASTE TIP REF.: 11032	1101
21	10/3/95	B	EXCAVATION OF WASTE TIP REF.: 11032	1102
22	10/3/95	S	RCHME SURVEYING (GRAND MAGAZINE)	1103
23	10/3/95	S	RCHME SURVEYING (GRAND MAGAZINE)	1104
24	10/3/95	S	GRAND MAGAZINE	1105
25	10/3/95	S	GRAND MAGAZINE	1106
26	10/3/95	S	GRAND MAGAZINE	1107
27	10/3/95	S	GRAND MAGAZINE (TREE MARKED FOR FELLING)	1108
28	10/3/95	S	TREES ADJACENT TO GRAND MAGAZINE MARKED FOR FELLING	1109
29	10/3/95	S	GRAND MAGAZINE	1110
30	10/3/95	S	RCHME PLANE TABLE	1111
31	10/3/95	S	GRAND MAGAZINE	1112
32	10/3/95	S	RCHME PLANE TABLE	1113
33	10/3/95	S	RCHME SURVEYING (ASBESTOS IN FOREGROUND)	1114
34	10/3/95	H	SERVICE TRENCH (ELECTRICITY ONLY) H8 - H17	1115
35	10/3/95	H	SERVICE TRENCH (ELECTRICITY ONLY) AT ENTRANCE TO BUILDING H8	1116
36	10/3/95	H	SERVICE TRENCH BETWEEN BUILDING A203 AND A202 (BRIDGE No. 17 ACCESS)	1117
37	10/3/93	H	'SPECIAL WASTE' ON H19 SAMPLING AREA	1118

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: 37/2613

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1	15/3/93	N	SUSPECT PIT	1119
2	15/3/93	S	VIEW TOWARDS BUILDING 88A	1120
3			NOT USED	
4	15/3/93	S	VIEW OF OLD RIVER LEA - LOOKING EAST FROM BRIDGE No. 10	1121
5	15/3/93	S	VIEW LOOKING SOUTH TO WASTE TIP REF.: 11032	1122
6	15/3/93	S	VIEW FROM REMEDIATED WASTE TIP REF.: 11038 - LOOKING TOWARDS BRIDGE No. 16	1123
7	15/3/93	S	PHEASANT	1124
8	19/3/93	H	INSTALLATION OF NEW WATER MAIN	1125
9	19/3/93	H	NEW WATER MAIN INSTALLED IN AREA 'H'	1126
10	19/3/93	H	NEW WATER MAIN INSTALLED IN AREA 'H'	1127
11	19/3/93	H	SERVICE TRENCH	1128
12	19/3/93	H	BACKFILLING WATER MAIN TRENCH	1129
13	19/3/93	H	TRENCH FOR NEW WATER MAIN	1130
14	19/3/93	H	EXCAVATION FOR NEW WATER MAIN	1131
15	23/3/93	H	INTERNAL VIEW OF BUILDING A202 (REFURBISHMENT OF FLOOR JOISTS)	1132
16	23/3/93	H	EXISTING SERVICES SOUTH OF BUILDING A202 - UNDER PAVING	1133
17	23/3/93	M	BUILDING L148 - 1ST STAGE DECONTAMINATION	1134
18	23/3/93	M	LVRPA IMPORTED SOIL BEING STOCKPILED NORTH OF BUILDING L148	1135
19	23/3/93	M	BUILDING L153 - 1ST STAGE DECONTAMINATION	1136
20	23/3/93	M	LVRPA IMPORTED SOIL BEING STOCKPILED NORTH OF BUILDING L148	1137
21	23/3/93	M	INTERNAL VIEW OF BUILDING L153 - 1ST STAGE DECONTAMINATION	1138
22	23/3/93	M	INTERNAL VIEW OF BUILDING L153 - 1ST STAGE DECONTAMINATION (WALL CORING POSITION)	1139
23	23/3/93	M	VIEW FROM BUILDING L153 TOWARDS BUILDING L148	1140
24	23/3/93	M	VIEW FROM BUILDING L153 TOWARDS BUILDING L157	1141
25	23/3/93	M	BUILDING L153 - 1ST STAGE DECONTAMINATION	1142
26	23/3/93	M	BUILDING L153 - 1ST STAGE DECONTAMINATION (VACUUMING ROOF STRUCTURE)	1143
27	23/3/93	M	BUILDING L153 - 1ST STAGE DECONTAMINATION	1144
28	23/3/93	M	BUILDING L153 - 1ST STAGE DECONTAMINATION	1145
29	24/3/93	H	BACKFILLING OF NEW WATER MAIN IN SERVICES TRENCH	1146
30	24/3/93	H	BACKFILLING OF NEW WATER MAIN IN SERVICES TRENCH	1147
31	29/3/95	H	NEW ELECTRICAL TAPE INSTALLATION FOR ISLAND SITE SERVICES	1148
32	29/3/95	P	TEMPORARY CANOPY OVER BUILDING A269	1149
33	29/3/95	H	B.T. DRAW PIT ON NEW ISLAND SITE SERVICES ROUTE	1150
34	29/3/95	H	INSTALLATION OF TELECOM'S DUCTING SOUTHERN POINT IN AREA 'H'	1151
35	29/3/95	H	B.T. DRAW PIT IN AREA 'H'	1152
36	29/3/95	H	DUCTS FROM B.T. DRAW PIT	1153
36 A	29/3/95	H	DUCTS FROM B.T. DRAW PIT	1154

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: 38/2756

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1	MAR '93	M	BUILDING L148 - DRILLING FOR TIMBER SAMPLES	1155
2	MAR '93	M	BUILDING L148 - DRILLING FOR TIMBER SAMPLES	1156
3	MAR '93	M	BUILDING L148 - DRILLING FOR TIMBER SAMPLES	1157
4	MAR '93	M	BUILDING L148 - DRILLING FOR TIMBER SAMPLES	1158
5	MAR '93	M	BUILDING L148 - DRILLING FOR TIMBER SAMPLES	1159
6	MAR '93	M	BUILDING L148 - DRILLING FOR TIMBER SAMPLES	1160
7	MAR '93	M	BUILDING L148 - DRILLING FOR TIMBER SAMPLES	1161
8	MAR '93	M	BUILDING L145 - WOOD SHAVING SAMPLES	1162
9	MAR '93	M	BUILDING L148 - PAINTED NOTICE ON CORRIDOR FLOOR	1163
10	MAR '93	M	BUILDING L148 - BAGGED ASBESTOS WASTE AWAITING DISPOSAL	1164
11	MAR '93	M	BUILDING L148 - CONTAMINATED METAL AWAITING TREATMENT AND DISPOSAL	1165
12	MAR '93	M	BUILDING L148 - BAGGED WASTE AND OTHER WASTE AWAITING DISPOSAL	1166
13	MAR '93	M	BUILDING L148 - BAGGED WASTE AWAITING DISPOSAL	1167
14	MAR '93	M	BUILDING L148 - CONTAMINATED TIMBER AWAITING DISPOSAL	1168
15	MAR '93	M	BUILDING L148 - BAGGED ASBESTOS WASTE AWAITING DISPOSAL	1169
16	MAR '93	M	BUILDING L148 - CONTAMINATED TIMBER AWAITING DISPOSAL	1170
17	MAR '93	M	BUILDING L148 - CONTAMINATED RUBBLE AWAITING DISPOSAL	1171
18	MAR '93	M	BUILDING L148 - CONTAMINATED METAL AWAITING TREATMENT AND DISPOSAL	1172

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: 39/3132

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1	MAR '93	S	WASTE TIP ADJACENT TO WEST BOUNDARY - NEAR EDMONSEY SLUICE	1173
2	MAR '93	S	WASTE TIP AT WEST BOUNDARY - SOUTH OF EDMONSEY SLUICE	1174
3	MAR '93	S	STEAM MAIN FOUNDATION BASE - NORTH OF BUILDING L128	1175
4	MAR '93	S	DRAIN TO DRAINAGE DITCH ADJACENT BRIDGE No. 52	1176
5	MAR '93	S	SEPTIC TANK ARRANGEMENT ADJACENT TO BRIDGE No. 52 & BUILDING U7	1177
6	MAR '93	B	BUILDING 96 VIEWED FROM WEST	1178
7	MAR '93	S	BUILDING L108 - VIEWED FROM NORTH (BUILDING L136 IN BACKGROUND)	1179
8	MAR '93	S	WASTE TIP REF.: 11036 - LOOKING WEST	1180
9	MAR '93	S	BUILDING RCHME 171 HIDDEN BY UNDERGROWTH	1181
10	MAR '93	L	L.V.R.P.A. IMPORTED SOIL BEING STOCKPILED NORTH OF BUILDING L122	1182
F	MAR '93	S	RETAINING WALL SOUTH OF BUILDINGS 107 & 108 (BRICK ARCH TO STRUCTURE JUST VISIBLE ABOVE WATER LINE)	1183

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: 40/3131

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1	31/3/93	H	REMOVAL OF WASTE FROM H16 SAMPLING AREA	1184
2	31/3/93	H	LAYING TELECOM DUCTING IN ISLAND SITE SERVICE TRENCH	1185
3	31/3/93	H	NEW SERVICE TRENCH FROM A203 - A200	1186
4	31/3/93	H	NEW SERVICE TRENCH BESIDE A201/2 (STEPS TO BRIDGE No. 17)	1187
5	31/3/93	H	NEW SERVICE TRENCH BESIDE A201/2	1188
6	31/3/93	H	NEW SERVICE TRENCH BESIDE A201/2	1189
7	31/3/93	H	NEW SERVICE TRENCH BESIDE A201/2, VIEWED FROM STEPS TO BRIDGE No. 17	1190
8	31/3/93	H	NEW SERVICE TRENCH AT WEST SIDE OF BRIDGE No. 17	1191
9	31/3/93	H	HOPPIT POOL - LOOKING NORTH (REMAINS OF GUNPOWDER BUILDINGS AND CANAL INLETS)	1192
10	31/3/93	H	NEW SERVICE TRENCH VIEWED FROM SOUTH SIDE OF H10	1193
11	31/3/93	H	NEW SERVICE TRENCH (HOPPIT POOL TO LEFT OF PICTURE)	1194
12	31/3/93	H	NEW SERVICE TRENCH - TOWARDS H6	1195
13	31/3/93	H	NEW SERVICE TRENCH - TOWARDS H10 (SOUTH EAST CORNER)	1196
14	31/3/93	H	NEW SERVICE TRENCH BESIDES H10 (SOUTH EAST CORNER)	1197
15	31/3/93	H	NEW SERVICE TRENCH FROM H10 - H17	1198
16	31/3/93	H	NEW SERVICE TRENCH AT H10 - WEST ELEVATION	1199
17	31/3/93	H	FALLEN PLASTER IN BUILDING A203 LADIES TOILETS	1200
18	31/3/93	H	SANITARY TOWEL DISPENSER AND BUNNY BURNER IN LADIES TOILET - A203	1201
19	1/4/93	M	TYPICAL INTERNAL VIEW OF BUILDING L145 (OVERHEAD HEATING PANELS BACKED WITH AMOSILE ASBESTOS)	1202
20	1/4/93	M	BUILDING L145 (ENCLOSURE FOR ASBESTOS REMOVAL WORKS)	1203
21	1/4/93	M	BUILDING L145 (OVERHEAD HEATING PANELS)	1204
22	1/4/93	M	CORRIDOR IN BUILDING L145 (ASBESTOS REMOVAL WORKS - INSPECTION)	1205
23	1/4/93	M	CORRIDOR IN BUILDING L145	1206
24			NOT USED	
25	1/4/93	M	BUILDING L145 (ENCLOSURE FOR ASBESTOS REMOVAL WORKS)	1207
26	1/4/93	M	CORRIDOR IN BUILDING L145 (1ST STAGE STRIP OUT IN PROGRESS)	1208
27	1/4/93	M	CORRIDOR IN BUILDING L145 (SHOWS TOOLS FOR STRIP OUT WORKS)	1209
28	2/4/93	P	BROKEN PIPE IN SERVICE TRENCH (DAMAGED BY ELECTRICITY COMPANY DURING INSTALLATION OF SUPPLY AT BUILDING 269)	1210
29	2/4/93	P	BROKEN PIPE IN SERVICE TRENCH AT BUILDING A269	1211
30	2/4/93	P	BROKEN PIPE IN SERVICE TRENCH AT BUILDING A269	1212
31	2/4/93	H	NEW SERVICE TRENCH (SOUTH) HIGHBRIDGE STREET	1213
32	2/4/93	S	EXCAVATING FILLED CANAL WEST OF BUILDING 103	1214
33	2/4/93	B	ASBESTOS COLLECTED FROM WASTE TIP REF.: 11036 ADJACENT TO BURNING GROUND	1215
34	2/4/93	S	VIEW SOUTH FROM PRESS HOUSE TOWARDS BRIDGE No. 8	1216
35	2/4/93	S	VIEW TOWARDS PRESS HOUSE BUILDING 103 (CLEARANCE OF TREES)	1217
36	7/4/93	H	NEW SERVICE TRENCH (WATER MAIN) VALVE PIT CONSTRUCTION	1218
36 A	7/4/93	H	WASTE TIP SOUTH OF BURNING GROUND - REMOVAL OF WASTE	1219

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: 41/3130

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1	7/4/93	S	BAGGED ASBESTOS AND SOIL WASTE LAID OUT ON SAMPLING SLAB	1220
2	7/4/93	S	BAGGED ASBESTOS AND SOIL WASTE LAID OUT ON SAMPLING SLAB	1221
3	7/4/93	S	BAGGED ASBESTOS AND SOIL WASTE STOCKPILED WEST OF BUILDING 83B	1222
4	7/4/93	S	NEWTON'S POOL SLUICE VIEWED FROM WEST	1223
5	7/4/93	S	NEWTON'S POOL LOOKING TOWARDS BUILDING S34	1224
6	7/4/93	S	NEWTON'S POOL SLUICE VIEWED FROM WEST	1225
7	7/4/93	S	NEWTON'S POOL SLUICE VIEWED FROM WEST	1226
8	7/4/93	S	NEWTON'S POOL DISCHARGE INTO OLD RIVER LEA	1227
9	7/4/93	S	NEWTON'S POOL DISCHARGE INTO OLD RIVER LEA	1228
10	7/4/93	S	VIEW OF BUILDING S34 AND CAR PARK - LOOKING EAST	1229
11	7/4/93	S	NEWTON'S POOL LOOKING NORTH (BUILDING S34 IN BACKGROUND)	1230
12	7/4/93	S	NEWTON'S POOL LOOKING WEST TOWARDS OLD RIVER LEA	1231
R	7/4/93	S	VIEW OF BUILDING S34 AND CAR PARK - LOOKING WEST	1232

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: 42/4690

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1	14/4/93	H	STRIPPING ASBESTOS OFF ROOF OF BUILDING H67 - LOOKING WEST	1233
2	14/4/93	H	BUILDING H67 - STRIPPING ASBESTOS OFF OF ROOF - LOOKING WEST	1234
3			NOT USED	
4	14/4/93	H	BUILDING H67 - STRIPPING ASBESTOS OFF OF ROOF - LOOKING SOUTH	1235
5	14/4/93	H	BUILDING H67 - STRIPPING ASBESTOS OFF OF ROOF - LOOKING EAST	1236
6	14/4/93	H	BUILDING H67 - STRIPPING ASBESTOS OFF OF ROOF - LOOKING WEST	1237
7	14/4/93	H	BUILDING H67 - WATER TANK HOUSING ON ROOF	1238
8	14/4/93	H	ROOF OF BUILDING H67 - LOOKING NORTH TO BUILDING H68	1239
9	14/4/93	H	LOOKING NORTH TO DISUSED LOCKS BEYOND BUILDING H70	1240
10	19/4/93	P	EXCAVATION OF FOUNDATION TO FORMER BUILDING A250	1241
11	19/4/93	P	EXCAVATION OF FOUNDATION TO FORMER BUILDING A250	1242
12	19/4/93	P	EXCAVATION OF FOUNDATIONS IN PMLH AREA	1243
13	19/4/93	P	EXCAVATION OF FOUNDATION IN PMLH AREA - LOOKING EAST	1244
14	19/4/93	P	VIEW WESTWARDS TO TENNIS COURTS AND MoD HOUSING BEYOND	1245
15	19/4/93	P	EXCAVATION OF FOUNDATIONS IN PMLH AREA	1246
16	19/4/93	P	REFURBISHMENT OF BUILDING A269 - LOOKING EAST	1247
17	19/4/93	P	EXCAVATION OF FOUNDATIONS IN PMLH AREA	1248
18	19/4/93	P	VIEW LOOKING SOUTH ACROSS AREA 'P' TOWARDS TENNIS COURTS	1249
19	19/4/93	P	BRIDGE No. 1 - CONSULTANT CARRYING OUT BRIDGE ASSESSMENT	1250
20	19/4/93	H	VIEW FROM BUILDING A203 TOWARDS BUILDING H12	1251
21	19/4/93	H	VIEW FROM BUILDING A203 OVER AREA 'H' TOWARDS BUILDING H16	1252
22	19/4/93	H	STRIPPING ASBESTOS ROOFING FORM BUILDING H66	1253
23	19/4/93	P	WASTE MATERIAL STOCKPILED ON A219 CAR PARK	1254
24	19/4/93	H	WASHING DOWN ROAD SWEEPER BY BUILDING H13	1255
25	19/4/93	M	ASBESTOS LAGGED HEATING PANELS PRIOR TO WRAPPING - FROM BUILDING L145	1256
26	19/4/93	M	ASBESTOS LAGGED HEATING PANELS WRAPPED FOR DISPOSAL (BUILDING L145)	1257
27	19/4/93	M	ASBESTOS COVERED HEATERS - SEALED (BUILDING L145)	1258
28	22/4/93	H	EXISTING SERVICES IN NEW SERVICES TRENCH - AREA 'H'	1259
29	22/4/93	H	EXISTING SERVICES IN NEW SERVICES TRENCH - AREA 'H'	1260
30	22/4/93	H	EXISTING SERVICES IN NEW SERVICES TRENCH - AREA 'H'	1261
31	22/4/93	H	EXISTING SERVICES IN NEW SERVICES TRENCH - AREA 'H'	1262
32	22/4/93	H	TAPPING OFF EXISTING WATER MAINS	1263
33	22/4/93	H	TAPPING OFF EXISTING WATER MAINS	1264
34	22/4/93	S	SAMPLING OF BAGGED ASBESTOS CONTAMINATED SOILS -ON SAMPLING SLAB	1265
35	22/4/93	S	SAMPLING OF BAGGED ASBESTOS CONTAMINATED SOILS -ON SAMPLING SLAB	1266
36	22/4/93	S	SAMPLING OF BAGGED ASBESTOS CONTAMINATED SOILS -ON SAMPLING SLAB	1267
37	22/4/93	S	SAMPLING OF BAGGED ASBESTOS CONTAMINATED SOILS -ON SAMPLING SLAB	1268

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: 43/4689

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1	23/4/93	S	STEAM MAIN FOUNDATION BASE NORTH OF BUILDING L126	1269
2	23/4/93	S	STEAM MAIN FOUNDATION BASE NORTH OF BUILDING L126	1270
3	23/4/93	H	BUILDING H67 - ASBESTOS SHEETS ON ROOF	1271
4	23/4/93	H	BUILDING H67 - ASBESTOS SHEET REMOVAL FROM ROOF IN PROGRESS	1272
5	23/4/93	H	BUILDING H67 - ASBESTOS SHEET REMOVAL FROM ROOF	1273
6	26/4/93	H	BUILDING H67 - DECONTAMINATION BY WASHING OF LIGHT FITTINGS	1274
7	26/4/93	H	BUILDING H67 - DECONTAMINATION BY WASHING OF LIGHT FITTINGS	1275
8	27/4/93	P	WOOD CHIPPING PROGRESS	1276
9	28/4/93	M	BUILDING L145 - DECONTAMINATION BY WASHING OF LIGHT FITTINGS	1277
10	28/4/93	M	SEALED ASBESTOS COVERED HEATERS IN SKIP AWAITING REMOVAL	1278
11	28/4/93	M	EAST ELEVATION OF BUILDING L145 - STRIPPING OUT IN PROGRESS	1279
12	28/4/93	L	WATER BOWSER IN ACTION	1280
13	28/4/93	S	EXCAVATION OF TIP REF.: 11036 - LOOKING WEST	1281
14	28/4/93	S	EXCAVATION OF TIP REF.: 11036 - LOOKING SOUTH	1282
15	28/4/93	S	EXCAVATION OF TIP REF.: 11036 - LOOKING SOUTH	1283
16	28/4/93	S	BAGGED ASBESTOS ON WASTE TIP REF.: 11032 - WITH EXCAVATION OF WASTE TIP REF.: 11036 IN FOREGROUND	1284
17	28/4/93	N	REMOVAL OF TRANSFORMERS FROM BUILDING S2 AT NEW HILL	1285
18	28/4/93	N	REMOVAL OF TRANSFORMERS FROM BUILDING S2 AT NEW HILL	1286
19	28/4/93	H	BUILDING H67 - REMOVAL OF PARQUET FLOORING IN PROGRESS	1287
20	28/4/93	H	BUILDING H67 - REMOVAL OF PARQUET FLOORING IN PROGRESS	1288
21	28/4/93	H	BUILDING H67 - REMOVAL OF PARQUET FLOORING IN PROGRESS	1289
22	28/4/93	H	BUILDING H67 - EXPOSED CEILING TIMBERS IN CORRIDOR	1290
23	28/4/93	H	BUILDING H67 - SHOWING TEST EQUIPMENT	1291
24	28/4/93	H	BUILDING H67 - ASBESTOS BOARDS STACKED ON ROOF	1292
25	28/4/93	H	BUILDING H67 - ASBESTOS BOARDS STACKED ON ROOF	1293
26	28/4/93	H	BUILDING H67 - LIFTING OF ASBESTOS BOARDS ON ROOF	1294
27	28/4/93	P	BUILDING A269 - SCAFFOLD AROUND EAST FACE	1295
28	28/4/93	P	BUILDING A269 - SCAFFOLD AROUND EAST FACE	1296
29	28/4/93	P	BUILDING A269 - SCAFFOLD AROUND EAST FACE	1297
30	30/4/93	H	ARCHAEOLOGICAL EXCAVATION BELOW FORMER BUILDING A292	1298
31	30/4/93	H	ARCHAEOLOGICAL EXCAVATION BELOW FORMER BUILDING A292	1299
32	1/5/93	B	WASTE MATERIAL IN BURNING GROUND AWAITING 'HEAT TREATMENT'	1300
33	1/5/93	B	WASTE MATERIAL IN BURNING GROUND UNDERGOING 'HEAT TREATMENT'	1301
34	1/5/93	B	WASTE MATERIAL IN BURNING GROUND UNDERGOING 'HEAT TREATMENT'	1302
35	1/5/93	B	WASTE MATERIAL IN BURNING GROUND SMOULDERING AFTER 'HEAT TREATMENT'	1303
36	5/5/93	M	EXCAVATION OF MILLHEAD STREAM BANK IN CORDITE CONTAMINATED AREA	1304
36 A	5/5/93	T	VIEW OF WASTE TIP REF.: 11013	1305

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: 44/4691

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1	5/5/93	M	EXCAVATION OF CANAL BANK TO TAKE GABION	1306
2	5/5/93	M	WIRE CAGES FOR GABION	1307
3	5/5/93	M	VIEW OF FILLED GABION	1308
4	5/5/93	M	THE FILLING OF GABION IN PROGRESS	1309
5	6/5/93	P	INSTALLATION OF BORE HOLE SOUTH OF BUILDING A250	1310
6	6/5/93	P	INSTALLATION OF BORE HOLE SOUTH OF BUILDING A250	1311
7	6/5/93	P	INSTALLATION OF BORE HOLE SOUTH OF BUILDING A250	1312
8	6/5/93	P	INSTALLATION OF BORE HOLE SOUTH OF BUILDING A250	1313
9	6/5/93	P	INSTALLATION OF BORE HOLE SOUTH OF BUILDING A250	1314
10	6/5/93	H	EXPOSED FOUNDATION OF BUILDING A211 BELOW BUILDING A292	1315
11	6/5/93	H	EXPOSED FOUNDATION OF BUILDING A211 BELOW BUILDING A292	1316
12	6/5/93	H	LOADING SPECIAL WASTE ON H19 AREA	1317
13	6/5/93	H	BUILDING H25 LOOKING SOUTH WEST	1318

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: 45/4945

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1			NOT USED	
2	MAY '93	M	RECONSTRUCTION OF RIVER WALL USING STONE FILLED GABIONS	1319
3	MAY '93	M	RECONSTRUCTION OF RIVER WALL USING STONE FILLED GABIONS	1320
4	MAY '93	M	RECONSTRUCTION OF RIVER WALL USING STONE FILLED GABIONS	1321
5	MAY '93	M	RECONSTRUCTION OF RIVER WALL USING STONE FILLED GABIONS	1322
6			NOT USED	
7			NOT USED	
8			NOT USED	
9			NOT USED	
10	MAY '93	H	WEST ELEVATION OF BUILDING A200 - WALTON HOUSE	1323
11	MAY '93	P	BOREHOLE RIG	1324
12	MAY '93	P	TRIAL PIT EXCAVATION IN PROGRESS PRIOR TO SAMPLING	1325
R	MAY '93	M	BLUE ASBESTOS IN SIDE OF RIVER BANK EXCAVATION	1326

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: 46/5730

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1	12/5/93	H	BUILDING H25 - LOOKING SOUTH WEST	1327
2	12/5/93	H	EAST ELEVATION BUILDING H25	1328
3	12/5/93	P	SAMPLE FROM INSIDE DRAIN PIPE IN EXCAVATED CANAL	1329
4	12/5/93	P	SAMPLE OF SOOT FROM EXCAVATED CANAL	1330
5	12/5/93	P	LOCATION OF SAMPLES TAKEN IN EXCAVATED CANAL	1331
6	12/5/93	P	LOCATION OF SAMPLES TAKEN IN EXCAVATED CANAL	1332
7	14/5/93	P	SAWPIT EXCAVATION	1333
8	14/5/93	P	SAWPIT EXCAVATION	1334
9	17/5/93	M	ASBESTOS CONTAMINATION IN CANAL EXCAVATION	1335
10	17/5/93	M	ASBESTOS CONTAMINATION IN CANAL EXCAVATION	1336
11	17/5/93	M	ASBESTOS CONTAMINATION IN CANAL EXCAVATION	1337
12	17/5/93	M	ASBESTOS CONTAMINATION IN CANAL EXCAVATION	1338
R	17/5/93	M	CANAL EXCAVATION LOOKING EAST IN CORDITE CONTAMINATED AREA	1339

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: 47/5729

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1	17/5/93	M	CORDITE DISCOVERED IN CANAL EXCAVATION	1340
2	17/5/93	M	RETRIEVING CORDITE FROM CANAL EXCAVATION	1341
3	17/5/93	M	RETRIEVING CORDITE FROM CANAL EXCAVATION	1342
4	17/5/93	M	REMOVAL OF TREE STUMP IN CORDITE CONTAMINATED AREA	1343
5	17/5/93	M	REMOVAL OF TREE STUMP IN CORDITE CONTAMINATED AREA	1344
6	17/5/93	M	REMOVED TREE STUMP IN CORDITE CONTAMINATED AREA	1345
7	17/5/93	M	CORDITE FOUND IN REMOVED TREE STUMP EXCAVATION	1346
8	17/5/93	M	CORDITE FINDS - DISPLAYED, FROM CORDITE CONTAMINATED AREA	1347
9	21/5/93	M	TRIAL PIT 'A' IN CORDITE CONTAMINATED AREA	1348
10	21/5/93	M	TRIAL PIT 'B' IN CORDITE CONTAMINATED AREA	1349
11	21/5/93	M	TRIAL PIT 'B' IN CORDITE CONTAMINATED AREA	1350
12	21/5/93	M	TRIAL PIT 'C' IN CORDITE CONTAMINATED AREA	1351
13	21/5/93	M	TRIAL PIT 'D' IN CORDITE CONTAMINATED AREA	1352
14	21/5/93	M	TRIAL PIT 'E' IN CORDITE CONTAMINATED AREA	1353
15	21/5/93	M	TRIAL PIT 'F' IN CORDITE CONTAMINATED AREA	1354
16	21/5/93	M	TRIAL PIT 'G' IN CORDITE CONTAMINATED AREA	1355
17	21/5/93	M	TRIAL PIT 'H' IN CORDITE CONTAMINATED AREA	1356
18	21/5/93	H	BUILDING H67 AFTER 'HEAT TREATMENT'	1357
19	21/5/93	H	WEST END OF BUILDING H67 AFTER 'HEAT TREATMENT' - LOOKING SOUTH	1358
20	21/5/93	H	WEST END OF BUILDING H67 AFTER 'HEAT TREATMENT' - LOOKING NORTH	1359
21	21/5/93	H	BUILDING H67 - CONTAMINATED METAL WORK READY FOR 'HEAT TREATMENT'	1360
22	21/5/93	H	BUILDING H67 - CONTAMINATED METAL WORK READY FOR 'HEAT TREATMENT'	1361
23	21/5/93	H	'HEAT TREATMENT' OF BUILDING H67 - LOOKING NORTH	1362
24	21/5/93	H	'HEAT TREATMENT' OF BUILDING H67 - LOOKING NORTH	1363
25	21/5/93	H	'HEAT TREATMENT' OF BUILDING H67 - LOOKING NORTH	1364
26	21/5/93	H	'HEAT TREATMENT' OF BUILDING H67 - LOOKING NORTH	1365
27	21/5/93	H	'HEAT TREATMENT' OF BUILDING H67 - LOOKING NORTH	1366
28	21/5/93	H	BUILDING H67 AFTER 'HEAT TREATMENT' - LOOKING SOUTH WEST	1367
29	21/5/93	H	'HEAT TREATMENT' OF BUILDING H67 IN PROGRESS	1368
30	24/5/93	S	BRIDGE No. 8 - HOLE IN DECK REQUIRED BY BRIDGE CONSULTANT	1369
31	24/5/93	M	CANAL TRIAL PIT 1 IN CORDITE CONTAMINATED AREA	1370
32	24/5/93	M	CANAL TRIAL PIT 1 IN CORDITE CONTAMINATED AREA	1371
33	24/5/93	M	CANAL TRIAL PIT 2 IN CORDITE CONTAMINATED AREA	1372
34	24/5/93	M	CANAL TRIAL PIT 3 IN CORDITE CONTAMINATED AREA	1373
35	24/5/93	M	CANAL TRIAL PIT 3 IN CORDITE CONTAMINATED AREA	1374
36	24/5/93	M	CANAL TRIAL PIT 3 IN CORDITE CONTAMINATED AREA	1375
37	24/5/93	M	CANAL TRIAL PIT 4 IN CORDITE CONTAMINATED AREA	1376

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: 48/5898

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1	24/5/93	M	CANAL TRIAL PIT 4 IN CORDITE CONTAMINATED AREA	1377
2	25/5/93	M	EXCAVATION OF CANAL IN CORDITE CONTAMINATED AREA	1378
3	25/5/93	M	EXCAVATION OF CANAL IN CORDITE CONTAMINATED AREA	1379
4	25/5/93	M	TREE STUMP REMOVED FROM CANAL IN CORDITE CONTAMINATED AREA	1380
5	25/5/93	M	TREE STUMP REMOVED FROM CANAL IN CORDITE CONTAMINATED AREA	1381
6	25/5/93	M	TREE STUMP REMOVED FROM CANAL IN CORDITE CONTAMINATED AREA	1382
7	25/5/93	P	BUILDING A250 - LOOKING SOUTH WEST	1383
8	25/5/93	P	BUILDING A250 - LOOKING SOUTH EAST	1384
9	25/5/93	P	EAST ELEVATION OF BUILDING A230 - TENNIS HUT	1385
10	25/5/93	P	WEST ELEVATION OF BUILDING A230 - TENNIS HUT	1386
11	25/5/93	P	BASE SLAB OF BUILDING A213	1387
12	25/5/93	P	NORTH ELEVATION OF BUILDING A234	1388
13	25/5/93	P	NORTH ELEVATION OF BUILDING A232	1389
14	25/5/93	P	NORTH ELEVATION OF BUILDING A231	1390
15	25/5/93	P	NORTH ELEVATION OF BUILDING A231	1391
16	25/5/93	P	NORTH ELEVATION OF BUILDING A230	1392
17			NOT USED	
18	25/5/93	H	SUSPECTED CONTAMINATED PIPEWORK FROM BUILDING H67 - (RETURNED TO BUILDING FOR 'HEAT TREATMENT')	1393
19			NOT USED	
20	27/5/93	H	EXCAVATION FOR NEW DRAIN NORTH OF BUILDING A200	1394
21	27/5/93	H	TRAP DOOR IN FLOOR FO BUILDING A201	1395
22	27/5/93	N	BUILDING S16 - EXCAVATION OF TRIAL TRENCH IN MOUND IN PROGRESS	1396
23	27/5/93	S	EXPOSED FOUNDATIONS OF BUILDING 63	1397
24	27/5/93	S	EXPOSED FOUNDATIONS OF BUILDING 63	1398
25	27/5/93	N	BUILDING S16 - VIEW OF TRIAL TRENCH IN MOUND	1399
26	27/5/93	N	BUILDING S16 - EXCAVATION OF TRIAL TRENCH IN PROGRESS	1400
27	27/5/93	N	BUILDING S16 - WASTE TIP ADJACENT EAST SIDE OF MOUND	1401
28	27/5/93	N	BUILDING S16 - EXCAVATION OF TRIAL TRENCH IN NORTH FACE OF MOUND IN PROGRESS	1402
29	27/5/93	N	BUILDING S16 - EXCAVATION OF TRIAL TRENCH IN PROGRESS ON NORTH SIDE OF MOUND	1403
30	27/5/93	S	REMAINS OF BUILDING 46 FOUNDATIONS	1404
31	27/5/93	S	REMAINS OF BUILDING 46 FOUNDATIONS	1405
32	27/5/93	H	DRAIN LAYING IN PROGRESS OF BUILDING A200	1406
33	27/5/93	P	BUILDING A222 LOOKING NORTH WEST	1407
34	27/5/93	P	SOUTH ELEVATION OF BUILDING A234	1408
35	27/5/93	P	SOUTH ELEVATION OF BUILDING A231	1409
36	27/5/93	P	SOUTH ELEVATION OF BUILDING A232	1410
R	27/5/93	P	SOUTH ELEVATION OF BUILDING A230	1411

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: 49/5897

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1	28/5/93	S	BUILDING S36 AT NEWTON'S POOL	1412
2	28/5/93	S	BUILDING S36 AT NEWTON'S POOL	1413
3	28/5/93	S	BUILDING S50 AT NEWTON'S POOL	1414
4	28/5/93	S	BUILDING S50 AT NEWTON'S POOL	1415
5	28/5/93	S	VIEW LOOKING TOWARDS TRAVERSE AT NEWTON'S POOL	1416
6	28/5/93	S	VIEW LOOKING TOWARDS MAIN ENTRANCE TO BUILDING S34	1417
7	28/5/93	S	VIEW LOOKING TOWARDS BUILDING S38 AT NEWTON'S POOL	1418
8	28/5/93	S	VIEW LOOKING TOWARDS BUILDING S38 AT NEWTON'S POOL	1419
9	28/5/93	S	EAST ELEVATION OF BUILDING S34	1420
10	28/5/93	S	BUILDING S34 LOOKING WEST AT NEWTON'S POOL	1421
11	28/5/93	S	BUILDING S34 LOOKING WEST FROM WALL AT NEWTON'S POOL	1422
12	28/5/93	H	WEST ELEVATION OF BUILDING H71	1423
13	28/5/93	H	BUILDING H71 IN FOREGROUND WITH BUILDING H10 BEYOND	1424
14	28/5/93	H	EAST ELEVATION OF BUILDING H10	1425
15	28/5/93	H	NORTH ELEVATION OF BUILDING H10	1426
16	28/5/93	H	NORTH ELEVATION OF BUILDING H10	1427
17	28/5/93	H	BUILDING H12 LOOKING FROM TOP OF MOUND	1428
18	28/5/93	H	BUILDING H12 LOOKING NORTH WEST FROM TOP OF MOUND	1429
19	28/5/93	H	BUILDING H12 - LOOKING WEST	1430
20	28/5/93	H	BUILDING H12 - LOOKING SOUTH AT MAIN ENTRANCE	1431
21	28/5/93	N	WASTE TIP REF.: 11050 - EAST SIDE OF BUILDING S16	1432
22	28/5/93	N	WASTE TIP REF.: 11050 - EAST SIDE OF BUILDING S16	1433
23	28/5/93	N	WASTE TIP REF.: 11050 - EAST SIDE OF BUILDING S16	1434
24	28/5/93	N	WASTE TIP REF.: 11050 - EAST SIDE OF BUILDING S16	1435
25	28/5/93	N	WASTE TIP REF.: 11050 - EAST SIDE OF BUILDING S16	1436
26	28/5/93	M	BUILDING L147	1437
27	28/5/93	M	EAST ELEVATION OF BUILDING L157 (COVERED ASBESTOS SKIP IN FOREGROUND)	1438
28	28/5/93	M	EAST ELEVATION IF BUILDING L145 AND BUILDING L148	1439
29	28/5/93	M	BUILDING L140 AMENITIES BLOCK	1440
30	28/5/93	M	SOUTH ELEVATION OF BUILDING L140	1441
31	28/5/93	M	DETERIORATION OF FLAT ROOF TO BUILDING L145	1442
32	28/5/93	M	DETERIORATION OF FLAT ROOF TO BUILDING L145	1443
33	28/5/93	M	DETERIORATION OF FLAT ROOF TO BUILDING L145	1444
34	28/5/93	M	DETERIORATION OF FLAT ROOF TO BUILDING L145	1445
35	28/5/93	M	DETERIORATION OF FLAT ROOF TO BUILDING L145	1446
36	28/5/93	M	NORTH ELEVATION OF BUILDING L145 EXTENSION	1447
36 A	28/5/93	M	SCREENING PLANT IN CORDITE CONTAMINATED AREA	1448

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: 50/6287

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1	28/5/93	S	NEWTNS RECOVERED FROM NEWTON'S POOL PRIOR TO PUMP DOWN	1449
2			NOT USED	
3	2/6/93	M	STRIP OUT WORKS - BUILDING L148	1450
4	2/6/93	M	EXPOSING DRAIN RUN AT BUILDING L145	1451
5	2/6/93	M	BROKEN CABLE DUCT COVER AT BUILDING L145	1452
6	2/6/93	M	REMOVAL OF CORDITE CONTAMINATED SOILS	1453
7	2/6/93	M	REMOVAL OF CORDITE CONTAMINATED SOILS	1454
8	2/6/93	M	REMOVAL OF CORDITE CONTAMINATED SOILS	1455
9	2/6/93	M	REMOVAL OF CORDITE CONTAMINATED SOILS	1456
10	2/6/93	M	CORDITE FOUND IN EXCAVATION	1457
11	3/6/93	M	BUILDING L145 - EXPOSED DRAIN RUN LOOKING WEST	1458
12	3/6/93	M	BUILDING L145 - EXPOSED DRAIN RUN	1459
13	3/6/93	M	BUILDING L145 - EXPOSED DRAIN RUN	1460
14	3/6/93	M	BUILDING L145 - EXPOSED DRAIN RUN	1461
15	3/6/93	M	BUILDING L145 - EXPOSED DRAIN RUN	1462
16	3/6/93	M	BUILDING L145 - EXPOSED DRAIN RUN	1463
17	3/6/93	M	BUILDING L145 - EXPOSED DRAIN RUN	1464
18	3/6/93	M	BUILDING L145 - EXPOSED DRAIN RUN LOOKING WEST	1465
19	3/6/93	M	BUILDING L145 - EXPOSED DRAIN RUN LOOKING WEST	1466
20	3/6/93	L	BUILDING L122 - NOTICE BOARD	1467
21	3/6/93	L	BUILDING L122 - NOTICE BOARD	1468
22	3/6/93	H	BUILDING A203 - NEW CAVITY TRAY INSTALLATION AT 1ST FLOOR LEVEL	1469
23	3/6/93	H	BUILDING A203 - NEW CAVITY TRAY INSTALLATION AT 1ST FLOOR LEVEL	1470
24	3/6/93	H	BUILDING A203 - NEW CAVITY TRAY INSTALLATION AT 1ST FLOOR LEVEL	1471
25	3/6/93	H	BUILDING A203 - VIEW OF NEW RAISED PARAPET WALL	1472

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: 51/7209

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1	3/6/93	N	MOUND OF S16 (TRIAL TRENCHING OF MOUND)	1473
2	3/6/93	N	VIEW TOWARDS BUILDING S16 MOUND (TRIAL TRENCHING OF MOUND)	1474
3	3/6/93	N	VIEW TOWARDS BUILDING S16 MOUND (TRIAL TRENCHING OF MOUND)	1475
4	3/6/93	N	BUILDING S16 - EXCAVATE MATERIAL FROM MOUND (SOUTH SIDE)	1476
5	3/6/93	N	BUILDING S16 - VIEW OF SCRAPED AREA UNDER CONCRETE STRUCTURE	1477
6	3/6/93	N	BUILDING S16 - EXCAVATE MATERIAL FROM MOUND - LOOKING WEST	1478
7	3/6/93	N	STEAM PIPE FOUNDATION BASES ADJACENT TO BUILDING S16	1479
8	3/6/93	N	STEAM PIPE FOUNDATION BASES ADJACENT TO BUILDING S16	1480
9	3/6/93	N	VIEW LOOKING SOUTH WEST BY BUILDING S16	1481
10	3/6/93	B	ASBESTOS FOUND IN SOIL AT WASTE TIP REF.: 11038	1482
11	3/6/93	B	ASBESTOS FOUND IN SOIL AT WASTE TIP REF.: 11038	1483
12	3/6/93	B	BAGGING OF ASBESTOS FOUND IN TIP REF.: 11038	1484
13	3/6/93	M	CONCRETE RUBBLE IN FILLED CANAL (HIGH WATER TABLE)	1485
14	3/6/93	M	CONCRETE RUBBLE IN FILLED CANAL (HIGH WATER TABLE)	1486
15	3/6/93	M	TYPICAL CANAL INFILL MATERIAL	1487
16	3/6/93	M	CONCRETE RUBBLE IN FILLED CANAL (HIGH WATER TABLE)	1488
17	3/6/93	M	REMOVAL OF CORDITE CONTAMINATED SOILS	1489
18	3/6/93	M	REMOVAL OF CORDITE CONTAMINATED SOILS	1490
19	3/6/93	M	REMOVAL OF CORDITE CONTAMINATED SOILS	1491
20	3/6/93	M	REMOVAL OF CORDITE CONTAMINATED SOILS	1492
21	3/6/93	M	REMOVAL OF CORDITE CONTAMINATED SOILS	1493
22	3/6/93	M	TRYING TO RECOVER LOST TWO-WAY RADIO	1494
23	3/6/93	M	TRYING TO RECOVER LOST TWO-WAY RADIO	1495
24	4/6/93	M	STEEL SCRAP BEING LOADED FOR DISPOSAL	1496
25	7/6/93	P	L.G.C. BOREHOLE SAMPLING	1497
26	7/6/93	H	BUILDING A203 - PARAPET WALL RAISED SHOWING NEW CAVITY TRAY AND DAMP PROOF COURSE	1498
27	7/6/93	H	BUILDING A203 - PARAPET WALL RAISED SHOWING NEW CAVITY TRAY AND DAMP PROOF COURSE	1499
28	7/6/93	H	BUILDING A203 - TEMPORARY PROTECTION TO PARAPET WALL	1500
29	7/6/93	H	BUILDING A203 - PARAPET WALL BEING RAISED	1501
30	7/6/93	H	BUILDING A203 - FINISHED RAISED PARAPET WALL	1502
31	7/6/93	H	CUT OUTS IN WALL TO TAKE NEW CAVITY TRAYS	1503
32	7/6/93	H	BUILDING A203 - FINISHED RAISED PARAPET WALL	1504
33	7/6/93	H	CUT OUTS IN BUILDING A203 - TO TAKE NEW CAVITY TRAYS	1505
34	8/6/93	P	NORTH EASTERN ASPECT OF BUILDING A270	1506
35	8/6/93	P	WEST ELEVATION OF BUILDING A270	1507
36	8/6/93	P	NORTH ELEVATION OF BUILDING A250	1508
R	8/6/93	P	NORTH EASTERN ASPECT OF BUILDING A250	1509

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: 52/8086

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1	8/6/93	P	EAST ELEVATION OF BUILDING A250	1510
2	8/6/93	P	VIEW LOOKING NORTH WEST OF BUILDING A250	1511
3	8/6/93	P	VIEW LOOKING NORTH EAST OF BUILDING A250	1512
4	8/6/93	P	WEST ELEVATION OF BUILDING A250	1513
5	9/6/93	H	BUILDING A203 - INSTALLATION OF NEW CAVITY TRAYS	1514
6			NOT USED	
7			NOT USED	
8			NOT USED	
9			NOT USED	
10	11/6/93	M	EXCAVATION OF CANAL IN CORDITE CONTAMINATED AREA	1515
11	11/6/93	M	EXCAVATION OF CANAL IN CORDITE CONTAMINATED AREA	1516
12	14/6/93	M	EXCAVATION OF CANAL IN CORDITE CONTAMINATED AREA	1517
13	14/6/93	M	VIEW OF CANAL IN CORDITE CONTAMINATED AREA	1518
14	14/6/93	M	EXCAVATION OF CANAL IN CORDITE CONTAMINATED AREA	1519
15	14/6/93	M	EXCAVATION OF CANAL IN CORDITE CONTAMINATED AREA	1520
16	14/6/93	M	GENERAL SURFACE EXCAVATION IN CORDITE CONTAMINATED AREA	1521
17	14/6/93	M	GENERAL SURFACE EXCAVATION IN CORDITE CONTAMINATED AREA	1522
18	14/6/93	M	GENERAL SURFACE IN PROGRESS IN CORDITE CONTAMINATED AREA	1523
19	14/6/93	M	SCREENING PLANT IN CORDITE CONTAMINATED AREA	1524
20	14/6/93	M	LORRY TRANSPORTING SCREENED CORDITE CONTAMINATED MATERIAL	1525
21	14/6/93	M	LORRY TRANSPORTING SCREENED CORDITE CONTAMINATED MATERIAL	1526
22	14/6/93	M	LORRY TIPPING SCREENED CORDITE CONTAMINATED MATERIAL	1527
23	14/6/93	M	LORRY TIPPING SCREENED CORDITE CONTAMINATED MATERIAL	1528
24	14/6/93	M	CORDITE AND ASBESTOS FOUND IN EXCAVATION IN CORDITE CONTAMINATED AREA	1529
R	14/6/93	M	CORDITE FOUND IN EXCAVATION IN CORDITE CONTAMINATED AREA	1530

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: 53/9803

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1	22/6/93	M	CUTTING DEAD ELECTRICITY CABLES IN CORDITE CONTAMINATED AREA	1531
2	22/6/93	M	EXCAVATION OF CANAL IN CORDITE CONTAMINATED AREA	1532
3	22/6/93	M	EXCAVATION OF CANAL AND UNCOVERING OF DEAD ELECTRICITY CABLES IN CORDITE CONTAMINATED AREA	1533
4	22/6/93	M	EXCAVATION OF CANAL ADJACENT TO 'GABION' WALL IN CORDITE CONTAMINATED AREA	1534
5	22/6/93	M	EXCAVATION OF CANAL ADJACENT TO 'GABION' WALL IN CORDITE CONTAMINATED AREA	1535
6	22/6/93	M	VIEW LOOKING SOUTH WEST TOWARDS BUILDING A214 FROM CORDITE CONTAMINATED AREA	1536
7	22/6/93	M	EXCAVATION NEAR FOOTBRIDGE IN CORDITE CONTAMINATED AREA	1537
8	24/6/93	M	BUILDING L145 - EXPOSED DRAIN RUN AFTER EXPLOSIVELY CONTAMINATED PIPEWORK HAS BEEN REMOVED	1538
9	24/6/93	M	BUILDING L145 - EXPOSED DRAIN RUN AFTER EXPLOSIVELY CONTAMINATED PIPEWORK HAS BEEN REMOVED	1539
10			NOT USED	
11	24/6/93	P	VIEW OF MAIN ENTRANCE IN POWDERMILL LANE	1540
12	26/6/93	H	CHLORINATION OF NEW WATER MAIN IN PROGRESS AT HIGHBRIDGE STREET	1541
13	26/6/93	H	SAMPLING LOCATIONS ON WEST FACE OF H12 MOUND	1542
14	26/6/93	H	SAMPLING LOCATIONS ON WEST FACE OF H12 MOUND	1543
15	26/6/93	H	SAMPLING LOCATIONS ON WEST FACE OF H12 MOUND - LOOKING SOUTH	1544
16			NOT USED	
17			NOT USED	
18			NOT USED	
19			NOT USED	
20			NOT USED	
21	2/7/93	M	DE-WATERING OF CANAL IN CORDITE CONTAMINATED AREA	1545
22	2/7/93	M	EXCAVATION OF CANAL BANKS IN CORDITE CONTAMINATED AREA - LOOKING EAST	1546
23	2/7/93	M	EXCAVATION OF CANAL BANKS IN CORDITE CONTAMINATED AREA - LOOKING EAST	1547
24	2/7/93	M	LOADING SCREENING PLANT IN CORDITE CONTAMINATED AREA	1548
R	2/7/93	M	EXCAVATION OF CANAL BANKS IN CORDITE CONTAMINATED AREA - LOOKING EAST	1549

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: 54/9804

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1	2/7/93	M	WEST END OF EXCAVATED CANAL IN CORDITE CONTAMINATED AREA	1550
2	2/7/93	M	EXCAVATION OF CANAL IN PROGRESS IN CORDITE CONTAMINATED AREA	1551
3	2/7/93	M	EXCAVATION OF CANAL IN PROGRESS IN CORDITE CONTAMINATED AREA	1552
4			NOT USED	
5	2/7/93	S	BAGGING ASBESTOS ON EAST TIP RE.: 11032	1553
6	2/7/93	S	BAGGING ASBESTOS ON EAST TIP RE.: 11032	1554
7	2/7/93	S	BAGGING ASBESTOS ON EAST TIP RE.: 11032	1555
8	3/7/93	H	EXCAVATION IN PROGRESS IN FOR NEW ROAD NORTH OF BUILDING A203	1556
9	5/7/93	M	ASBESTOS UNCOVERED IN SOIL IN CORDITE CONTAMINATED AREA	1557
10	5/7/93	M	ASBESTOS UNCOVERED IN SOIL IN CORDITE CONTAMINATED AREA	1558
11	5/7/93	M	ASBESTOS UNCOVERED IN SOIL IN CORDITE CONTAMINATED AREA	1559
12	5/7/93	M	ASBESTOS UNCOVERED IN SOIL IN CORDITE CONTAMINATED AREA	1560
13	5/7/93	M	ASBESTOS UNCOVERED IN SOIL IN CORDITE CONTAMINATED AREA	1561
14	5/7/93	M	COMPLETED EXCAVATION OF CANAL IN CORDITE CONTAMINATED AREA	1562
15	5/7/93	M	COMPLETED EXCAVATION OF CANAL IN CORDITE CONTAMINATED AREA - LOOKING EAST	1563
16	5/7/93	M	GENERAL EXCAVATION IN CORDITE CONTAMINATED AREA	1564
17	5/7/93	M	EXCAVATED MATERIAL LOADED INTO VOLVO DUMP TRUCK IN CORDITE CONTAMINATED AREA	1565
18	5/7/93	M	EXCAVATED CANAL IN CORDITE CONTAMINATED AREA - LOOKING WEST	1566
19	5/7/93	M	GENERAL VIEW OF CANAL AWAITING SURVEYING IN CORDITE CONTAMINATED AREA	1567
20	5/7/93	M	MANOEUVRING BOAT TO TAKE LEVELS AND SAMPLES IN CANAL - CORDITE CONTAMINATED AREA	1568
21	5/7/93	M	SORTING OUT SAMPLE JARS PRIOR TO SAMPLING CANAL IN CORDITE CONTAMINATED AREA	1569
22	5/7/93	M	LOCATING BOAT PRIOR TO LEVELLING OF CANAL IN CORDITE CONTAMINATED AREA	1570
23	5/7/93	M	PUMP USED FOR 'DE-WATERING' OF CANAL IN CORDITE CONTAMINATED AREA	1571
24	5/7/93	M	PUMP USED FOR 'DE-WATERING' OF CANAL IN CORDITE CONTAMINATED AREA	1572
25	5/7/93	M	SURVEYING OF CANAL IN PROGRESS IN CORDITE CONTAMINATED AREA	1573
26	5/7/93	M	SAMPLING OF CANAL IN PROGRESS IN CORDITE CONTAMINATED AREA	1574
27	5/7/93	M	SAMPLING OF CANAL IN PROGRESS IN CORDITE CONTAMINATED AREA	1575
28	6/7/93	M	BOAT MOORED IN CANAL IN CORDITE CONTAMINATED AREA	1576
29	6/7/93	M	SAMPLING OF CANAL IN PROGRESS IN CORDITE CONTAMINATED AREA	1577
30	7/7/93	H	VIEW OF BUILDING H37 FOUNDATION SLAB	1578

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: 55/9806

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1	8/7/93	B	VIEW LOOKING NORTH WEST TOWARDS BUILDING L178	1579
2	8/7/93	B	VIEW LOOKING NORTH TOWARDS BUILDING L175 AND L178	1580
3	8/7/93	B	BUNDED BASE ADJACENT TO BURNING GROUND ACCESS ROAD	1581
4	8/7/93	B	EXCAVATION OF WASTE TIP REF.: 11038 IN PROGRESS	1582
5	8/7/93	P	EXCAVATED CANAL LOOKING EAST IN PMLH AREA	1583
6	8/7/93	P	EXCAVATION OF CANAL IN PROGRESS IN AREA 'P'	1584
7	8/7/93	P	GENERAL EXCAVATION LOOKING SOUTH WEST IN AREA 'P'	1585
8	8/7/93	P	VIEW LOOKING NORTH TOWARDS BUILDING A230 - A234 IN AREA 'P'	1586
9	8/7/93	M	STOCKPILED MATERIAL ADJACENT TO CANAL IN CORDITE CONTAMINATED AREA	1587
10	8/7/93	M	STOCKPILED EXCAVATED MATERIAL ADJACENT TO BUILDING L159	1588
11	8/7/93	M	EXCAVATED MATERIAL LAID OUT TO DRY IN CORDITE CONTAMINATED AREA	1589
12	8/7/93	M	EXCAVATED MATERIAL LAID OUT TO DRY IN CORDITE CONTAMINATED AREA	1590
13	14/7/93	P	GENERAL EXCAVATION WORKS IN PROGRESS	1591
14	14/7/93	P	GENERAL EXCAVATION WORKS IN PROGRESS	1592
15	14/7/93	P	VIEW TOWARDS BUILDING A250 SHOWING AREA TO BE SAMPLED	1593
16	14/7/93	P	GENERAL VIEW OF EXCAVATION IN 'P' AREA LOOKING WEST	1594
17	14/7/93	P	GENERAL VIEW OF EXCAVATION IN 'P' AREA LOOKING SOUTH WEST	1595
18	14/7/93	P	GENERAL VIEW OF EXCAVATION IN 'P' AREA LOOKING SOUTH WEST	1596
19	14/7/93	P	REPAIRED BURST WATER MAIN IN AREA 'P'	1597
20	14/7/93	P	GENERAL EXCAVATIONS IN 'P' AREA LOOKING WEST	1598
21	14/7/93	P	MATERIAL FROM CORDITE CONTAMINATED AREA STOCKPILED EAST OF A210	1599
22	14/7/93	P	MATERIAL FROM CORDITE CONTAMINATED AREA STOCKPILED EAST OF A210	1600
23	14/7/93	P	MATERIAL FROM CORDITE CONTAMINATED AREA STOCKPILED SOUTH OF A214	1601
24	14/7/93	P	MATERIAL FROM CORDITE CONTAMINATED AREA STOCKPILED SOUTH OF A214	1602
25	14/7/93	P	MATERIAL FROM CORDITE CONTAMINATED AREA STOCKPILED NORTH OF A214	1603
26	14/7/93	M	BLDG L168 - MATERIAL STOCKPILED FROM CORDITE CONTAMINATED AREA	1604
27	14/7/93	M	BUILDING L157 - REMOVAL OF ASPHALT FLOORING FROM CORRIDORS	1605
28	14/7/93	M	ORIGINAL SITE NOTICES PLACED ALONGSIDE SITE AMENITIES	1606
29	14/7/93	S	L.G.C. SAMPLING HORSEMILL STREAM LOOKING EAST	1607
30	14/7/93	S	L.G.C. SAMPLING HORSEMILL STREAM LOOKING EAST	1608
31	14/7/93	S	L.G.C. FILLING SAMPLE BOTTLES WITH WATER FROM HORSEMILL STREAM	1609
32	15/7/93	H	BUILDING H37 - REINFORCEMENT IN CONCRETE IN FOUNDATION	1610
33	15/7/93	H	BUILDING H37 - BRAKING OUT CONCRETE FOUNDATION	1611
34	19/7/93	P	TRIAL TRENCH TT3 NORTH OF BUILDINGS A230 - A234 LOOKING NORTH	1612
35	19/7/93	P	TRIAL TRENCH TT1 NORTH OF BUILDINGS A230 - A234 LOOKING SOUTH	1613
36	19/7/93	H	CLEANING KUBOTA AFTER WORKING ON 'SPECIAL WASTE' AT H16 AREA	1614
37	19/7/93	H	CLEANING KUBOTA AFTER WORKING ON 'SPECIAL WASTE' AT H16 AREA	1615

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: 56/9805

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1	20/7/93	B	WASTE TIP REF.: 11038 - BURNING GROUND NORTH	1616
2	20/7/93	B	WASTE TIP REF.: 11038 - BURNING GROUND NORTH	1617
3	20/7/93	B	WASTE TIP REF.: 11032 - BURNING GROUND SOUTH SURVEY WORK	1618
4	21/7/93	P	TRIAL TRENCH TT1 NORTH OF BUILDINGS A230 - A234 VIEW LOOKING NORTH	1619
5	21/7/93	P	TRIAL TRENCH TT1 NORTH OF BUILDINGS A230 - A234 VIEW ON EAST FACE	1620
6	21/7/93	P	TRIAL TRENCH TT2 NORTH OF BUILDINGS A230 - A234 LOOKING EAST	1621
7	21/7/93	P	TRIAL TRENCH TT3 NORTH OF BUILDINGS A230 - A234 LOOKING NORTH	1622
8	21/7/93	P	TRIAL TRENCH TT3 NORTH OF BUILDINGS A230 - A234 LOOKING SOUTH	1623
9	21/7/93	S	WASTE TIP REF.: 11002 - LAGOON NORTH EAST OF BUILDING E2	1624
10	21/7/93	S	WASTE TIP REF.: 11002 - LAGOON NORTH EAST OF BUILDING E2	1625
11	21/7/93	S	WASTE TIP REF.: 11002 - LAGOON NORTH EAST OF BUILDING E2	1626
12	21/7/93	S	WASTE TIP REF.: 11002 - LAGOON NORTH EAST OF BUILDING E2	1627
13	21/7/93	S	WASTE TIP REF.: 11002 (FULL CONTAINER OF HYDROFLUORIC ACID FOUND IN TIP)	1628
14	21/7/93	S	WASTE TIP REF.: 11002 (WHITE POWDER FOUND IN TIP)	1629
15	21/7/93	S	WASTE TIP REF.: 11002 (NATURE OF THE MATERIAL)	1630
16	21/7/93	S	LAGOON NORTH WEST OF BUILDING E2 (PARTIALLY FILLED WITH WASTE)	1631
17	21/7/93	S	WASTE TIP REF.: 11002 - NORTH EAST OF BUILDING E2	1632
18	23/7/93	S	'BARREL GRAVEYARD' HAND CLEARANCE	1633
19	23/7/93	S	'BARREL GRAVEYARD' HAND CLEARANCE	1634
20	23/7/93	S	BUILDING U9 NEAR THE 'BARREL GRAVEYARD'	1635
21	23/7/93	S	'BARREL GRAVEYARD' - CLEARANCE	1636
22	23/7/93	S	CANAL SOUTH WEST OF BUILDING S34	1637
23	23/7/93	S	ASBESTOS CLEARANCE FROM WASTE TIP REF.: 11002 NORTH EAST OF BUILDING E2	1638
24	23/7/93	S	WASTE TIP REF.: 11002 - NORTH EAST OF BUILDING E2 (NATURE OF THE MATERIAL)	1639
R	23/7/93	S	WASTE TIP REF.: 11002 - NORTH EAST OF BUILDING E2 (NATURE OF THE MATERIAL)	1640

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: 57/0095

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1	23/7/93	H	TORRENTIAL RAIN STORM (BUILDING A200)	1641
2	23/7/93	H	TORRENTIAL RAIN STORM (BUILDING A200)	1642
3			NOT USED	
4			NOT USED	
5	27/7/93	S	SOUTH ELEVATION OF BUILDING 103 (GUNPOWDER PRESS HOUSE)	1643
6	27/7/93	S	SOUTH ELEVATION OF BUILDING 103 (WATERWHEEL GUNPOWDER PRESS HOUSE)	1644
7	27/7/93	S	SOUTH ELEVATION OF BUILDING 103 (GUNPOWDER PRESS HOUSE)	1645
8	27/7/93	S	SOUTH ELEVATION OF BUILDING 103 (GUNPOWDER PRESS HOUSE)	1646
9	27/7/93	S	SOUTH ELEVATION OF BUILDING 103 (GUNPOWDER PRESS HOUSE)	1647
10	27/7/93	S	SOUTH EASTERN ASPECT OF BUILDING 103 (GUNPOWDER PRESS HOUSE)	1648
11	27/7/93	S	PART OF EAST ELEVATION OF BUILDING 103 (GUNPOWDER PRESS HOUSE)	1649
12	27/7/93	S	EAST ELEVATION OF BUILDING 103 (GUNPOWDER PRESS HOUSE)	1650
13	27/7/93	S	EAST ELEVATION OF BUILDING 103 (GUNPOWDER PRESS HOUSE)	1651
14	27/7/93	S	PART OF WEST ELEVATION OF BUILDING 103 (GUNPOWDER PRESS HOUSE)	1652
15	27/7/93	S	WEST ELEVATION OF BUILDING 103 (GUNPOWDER PRESS HOUSE)	1653
16	27/7/93	S	SOUTH WESTERN ASPECT OF BUILDING 103 (GUNPOWDER PRESS HOUSE)	1654
17	27/7/93	S	SOUTH WESTERN ASPECT OF BUILDING 103 (GUNPOWDER PRESS HOUSE)	1655
18	27/7/93	S	WEST ELEVATION OF BUILDING 103 (GUNPOWDER PRESS HOUSE)	1656
19	27/7/93	S	SOUTH WESTERN ASPECT OF BUILDING 103 (GUNPOWDER PRESS HOUSE)	1657
20	27/7/93	S	SOUTH WESTERN ASPECT OF BUILDING 103 (GUNPOWDER PRESS HOUSE)	1658
21	27/7/93	S	SOUTH ELEVATION OF BUILDING 103 (GUNPOWDER PRESS HOUSE)	1659
22	27/7/93	S	BUILDING 103 (WATERWHEEL OF GUNPOWDER PRESS HOUSE)	1660
23			NOT USED	
24	27/7/93	S	BUILDING 103 (WATERWHEEL OF GUNPOWDER PRESS HOUSE)	1661
25	27/7/93	P	WATER MAIN REPAIR NORTH OF BUILDING A250 (‘VIKING JOHNSON COUPLING’)	1662
26	27/7/93	P	WATER MAIN REPAIR NORTH OF BUILDING A250	1663
27	27/7/93	P	WATER MAIN REPAIR NORTH OF BUILDING A250	1664
28	27/7/93	P	WATER MAIN REPAIR NORTH OF BUILDING A250	1665
29	27/7/93	P	WATER MAIN REPAIR NORTH OF BUILDING A250	1666
30	27/7/93	P	WATER MAIN REPAIR NORTH OF BUILDING A250	1667
31	27/7/93	P	BUILDING A238 - GATE HOUSE (SECURITY CHECK IN PROGRESS)	1668
32	27/7/93	P	VIEW NORTH FROM POWDERMILL LANE	1669
33	27/7/93	P	VIEW NORTH FROM POWDERMILL LANE	1670
34	27/7/93	P	VIEW WEST FROM POWDERMILL LANE	1671
35	27/7/93	P	VIEW NORTH FROM POWDERMILL LANE	1672
36	27/7/93	P	VIEW NORTH FROM POWDERMILL LANE	1673
R	27/7/93	P	VIEW WEST FROM POWDERMILL LANE	1674

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: 58/1170

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1	30/7/93	H	HIGHBRIDGE STREET ENTRANCE (ARCHAEOLOGICAL FIND - BURIED STRUCTURE)	1675
2	30/7/93	H	HIGHBRIDGE STREET ENTRANCE (ARCHAEOLOGICAL FIND - BURIED STRUCTURE)	1676
	30/7/93	H	HIGHBRIDGE STREET ENTRANCE (ARCHAEOLOGICAL FIND - BURIED STRUCTURE)	1677
4	30/7/93	H	HIGHBRIDGE STREET ENTRANCE (ARCHAEOLOGICAL FIND - BURIED STRUCTURE)	1678
5	30/7/93	H	BUILDING H25 - INTERNAL ASBESTOS STRIP	1679
6	30/7/93	H	BUILDING H25 - INTERNAL ASBESTOS WALL PANELS STRIPPED OUT	1680
7	4/8/93	H	DEMOLITION OF BUILDING H16 (HYDRAULIC PULVERISER)	1681
8	4/8/93	H	DEMOLITION OF BUILDING H16 (HYDRAULIC PULVERISER)	1682
9	4/8/93	P	DEMOLITION OF BUILDING A250 (DAMPENING DOWN OF DUST)	1683
10	4/8/93	P	DEMOLITION OF BUILDING A250 (DAMPENING DOWN OF DUST)	1684
11	4/8/93	H	DEMOLITION OF CONTRACTORS PLANT - VOLVO DUMP TRUCK	1685
12	4/8/93	H	DEMOLITION OF BUILDING H67	1686
13	4/8/93	H	DEMOLITION OF BUILDING H67	1687
14	5/8/93	H	DEMOLITION OF BUILDING H25	1688
15	5/8/93	H	DEMOLITION OF BUILDING H25	1689
16	5/8/93	H	DEMOLITION OF BUILDING H25	1690
17	5/8/93	H	DEMOLITION OF BUILDING H25	1691
18	5/8/93	H	DEMOLITION OF BUILDING H25	1692
19	5/8/93	H	DEMOLITION OF BUILDING H25	1693
20	5/8/93	H	DEMOLITION OF BUILDING H25	1694
21	5/8/93	H	DEMOLITION OF BUILDING H25	1695
22	5/8/93	H	DEMOLITION OF BUILDING H25	1696
23	5/8/93	H	DEMOLITION OF BUILDING H25	1697
24	5/8/93	H	DEMOLITION OF BUILDING H25	1698
25	5/8/93	H	DEMOLITION OF BUILDING H25	1699
26	5/8/93	H	DEMOLITION OF BUILDING H25	1700
27	5/8/93	H	DEMOLITION OF BUILDING H25	1701
28	9/8/93	H	STENT FOUNDATIONS:- PLANT ARRIVAL	1702
29	9/8/93	H	STENT FOUNDATIONS:- PLANT ARRIVAL	1703
30	12/8/93	H	VOLVO DUMP TRUCK - 20 TONNE	1704
31	12/8/93	H	DEMOLITION ARISINGS STOCKPILED AT H67	1705
32	12/8/93	H	DEMOLISHED BUILDING H69	1706
33	12/8/93	H	DEMOLITION ARISINGS STOCKPILED AT H67	1707
34	12/8/93	H	AREA ADJACENT TO H10 PREPARED FOR MATERIAL STOCKPILING	1708
35	12/8/93	H	BUILDING H30 SLAB (AFTER DEMOLITION)	1709

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: 59/1171

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1	12/8/93	S	NEWTON'S POOL - COFFERDAM INSTALLATION	1710
2	12/8/93	S	NEWTON'S POOL - COFFERDAM INSTALLATION	1711
3	12/8/93	S	NEWTON'S POOL - COFFERDAM INSTALLATION	1712
4	12/8/93	S	NEWTON'S POOL - COFFERDAM INSTALLATION	1713
5	13/8/93	S	NEWTON'S POOL - COFFERDAM INSTALLATION	1714
6	13/8/93	S	NEWTON'S POOL - COFFERDAM INSTALLATION	1715
7	13/8/93	S	NEWTON'S POOL - COFFERDAM INSTALLATION	1716
8	13/8/93	S	NEWTON'S POOL - COFFERDAM INSTALLATION	1717
9	13/8/93	S	NEWTON'S POOL - COFFERDAM INSTALLATION	1718
10	13/8/93	S	NEWTON'S POOL - COFFERDAM INSTALLATION (SHEET PILES USED FOR THE COFFERDAM)	1719
11	13/8/93	S	NEWTON'S POOL - COFFERDAM INSTALLATION	1720
12	13/8/93	S	NEWTON'S POOL - COFFERDAM INSTALLATION (CONTRACTORS ACCOMMODATION)	1721
R	13/8/93	S	LAGOON NORTH WEST OF BUILDING E2	1722

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: 60/1772

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1	16/8/93	S	NEWTON'S POOL - VIEWED FROM EAST SIDE	1723
2	16/8/93	S	NEWTON'S POOL - COFFERDAM (WATER INGRESS)	1724
3	16/8/93	S	NEWTON'S POOL - COFFERDAM (WATER INGRESS)	1725
4	16/8/93	S	NEWTON'S POOL - COFFERDAM (WATER INGRESS)	1726
5	16/8/93	S	NEWTON'S POOL - COFFERDAM	1727
6	16/8/93	S	NEWTON'S POOL - COFFERDAM INSTALLATION	1728
7	16/8/93	S	ROAD REPAIR AT NEWTON'S POOL TO ASSIST ACCESS FOR HEAVY PLANT	1729
8	16/8/93	S	ACCESS ROUTE TO NEWTON'S POOL	1730
9	16/8/93	S	LAGOON NORTH WEST OF BUILDING E2	1731
10	16/8/93	S	LAGOON NORTH WEST OF BUILDING E2	1732
11	16/8/93	T	BLUE ASBESTOS AND TETRYL CONTAMINATION DISCOVERED	1733
12	16/8/93	T	BLUE ASBESTOS AND TETRYL CONTAMINATION DISCOVERED	1734
13	16/8/93	S	LAGOON NORTH WEST OF BUILDING E2	1735
14	16/8/93	S	BAGGING ASBESTOS CONTAMINATED SOIL	1736
15	16/8/93	S	BAGGING ASBESTOS CONTAMINATED SOIL	1737
16	16/8/93	S	CANAL CLEARANCE ADJACENT TO BUILDING E2 AND E3	1738
17	16/8/93	S	CANAL CLEARANCE ADJACENT TO BUILDING E2 AND E3	1739
18	16/8/93	S	CANAL CLEARED SOUTH WEST OF BUILDING S34	1740
19	19/8/93	S	'BARREL GRAVEYARD' TRIAL HOLES	1741
20	19/8/93	S	'BARREL GRAVEYARD' TRIAL HOLES	1742
21	19/8/93	S	'BARREL GRAVEYARD' TRIAL HOLES	1743
22	19/8/93	S	'BARREL GRAVEYARD' TRIAL HOLES	1744
23			NOT USED	
24	19/8/93	S	'BARREL GRAVEYARD' TRIAL HOLES	1745
25	20/8/93	B	WASTE CORDITE LAID OUT FOR FIRING	1746
26	20/8/93	B	WASTE CORDITE LAID OUT FOR FIRING	1747
27	20/8/93	B	WASTE CORDITE LAID OUT FOR FIRING (COMMENCEMENT OF FIRE)	1748
28	20/8/93	B	WASTE CORDITE (COMMENCEMENT OF FIRING)	1749
29	20/8/93	B	WASTE CORDITE BEING FIRED	1750
30	20/8/93	B	WASTE CORDITE BEING FIRED	1751
31	20/8/93	B	WASTE CORDITE BEING FIRED	1752
32	20/8/93	B	WASTE CORDITE BEING FIRED	1753
33	20/8/93	S	LAGOON WEST OF BUILDING E2	1754
34	20/8/93	S	LAGOON WEST OF BUILDING E2 - EXCAVATION OF WASTE	1755
35	20/8/93	S	CANAL CLEARANCE BETWEEN BUILDINGS E2 AND E3 - REFUELLING MACHINERY	1756
36	20/8/93	S	CANAL CLEARANCE BETWEEN BUILDINGS E2 AND E3 (NOTE LARGE BOULDERS OF MASONRY WITHIN THE FILL)	1757
R	20/8/93	S	CANAL CLEARANCE BETWEEN BUILDINGS E2 AND E3 - ARTEFACTS FOUND (POTENTIALLY CONTAMINATED PROCESS PIPEWORK)	1758

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: 61/3712

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1	23/8/93	P	EXCAVATION OF TRIAL PIT P10 - NORTH OF BUILDING A232	1759
2	23/8/93	P	EXCAVATION OF TRIAL PIT P10 - NORTH OF BUILDING A232	1760
3	23/8/93	P	EXCAVATION OF TRIAL PIT P10 - NORTH OF BUILDING A232	1761
4	23/8/93	P	EXCAVATION OF TRIAL PIT P10 - NORTH OF BUILDING A232	1762
5	23/8/93	P	EXCAVATION OF TRIAL PIT P10 - NORTH OF BUILDING A232	1763
6	23/8/93	P	EXCAVATION OF TRIAL PIT P10 - NORTH OF BUILDING A232	1764
7	23/8/93	P	EXCAVATION OF TRIAL PIT P10 - NORTH OF BUILDING A232	1765
8	26/8/93	B	CLEARANCE OF CONCRETE AND MASONRY FROM BURNING GROUND	1766
9	26/8/93	B	STOCKPILE MATERIAL ON BURNING GROUND	1767
10	26/8/93	P	TRIAL PIT P10 - NORTH OF BUILDING A232	1768
11	26/8/93	P	TRIAL PIT P10 - NORTH OF BUILDING A232	1769
12	26/8/93	P	TRIAL PIT P10 - NORTH OF BUILDING A232	1770
13	26/8/93	P	BUILDING A250 - BRAKING OUT OF SLAB AND FOUNDATIONS IN PROGRESS	1771
14	26/8/93	P	BUILDING A250 - PARTIAL REMAINS OF CONCRETE SLAB	1772
15	26/8/93	P	EXCAVATION OF CANAL NORTH OF BUILDINGS A230 - A234	1773
16	26/8/93	P	EXCAVATION OF CANAL NORTH OF BUILDINGS A230 - A234	1774
17	26/8/93	P	EXCAVATION OF CANAL NORTH OF BUILDINGS A230 - A234	1775
18	2/9/93	S	NEWTONS POOL - SETTING UP PUMPS PRIOR TO DE-WATERING	1776
19	2/9/93	S	NEWTONS POOL - DE-WATERING IN PROGRESS	1777
20	2/9/93	S	CANAL NORTH OF BUILDING E2, RECEIVING SCREENED WATER FROM NEWTONS POOL	1778
21	2/9/93	S	GRAVEL FILTER IN CANAL NORTH OF NEWTONS POOL	1779
22	2/9/93	S	AQUEDUCT NORTH OF BUILDING 46A	1780
23	2/9/93	S	NEWTONS POOL - VIEW LOOKING EAST	1781
24	2/9/93	S	NEWTONS POOL - SCREENING PLANT	1782
25	2/9/93	S	PUMPS SET UP ON NORTH SIDE OF NEWTONS POOL	1783
26	2/9/93	S	NEWTONS POOL - GENERAL VIEW OF PUMPS AND SCREENING PLANT	1784
27	2/9/93	S	NEWTONS POOL - CLOGGED UP PUMP STRAINER	1785
28	2/9/93	S	NEWTONS POOL - KEEPING AN EYE ON PROGRESS	1786
29	6/9/93	S	NEWTONS POOL - SHELL CASE RECOVERED	1787
30	6/9/93	S	NEWTONS POOL - SHELL CASE RECOVERED	1788
31	6/9/93	S	NEWTONS POOL - DE-WATERING IN PROGRESS	1789
32	6/9/93	S	NEWTONS POOL - GENERAL VIEW OF PUMPS AND PERSONNEL	1790
33	6/9/93	S	NEWTONS POOL - SHELL CASE REMOVED	1791
34	6/9/93	S	NEWTONS POOL - DE-WATERING IN PROGRESS	1792
35	6/9/93	S	NEWTONS POOL - SHELL CASE REMOVED	1793
36	6/9/93	S	NEWTONS POOL - SCREENING PLANT IN OPERATION	1794
36 A	6/9/93	S	NEWTONS POOL - VIEW TOWARDS GRAVEL FILTER	1795

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: 62/3714

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1			NOT USED	
2			NOT USED	
3			NOT USED	
4			NOT USED	
5	7/9/93	S	NEWTONS POOL - RETRIEVING FISH PRIOR TO DECONTAMINATION (NRA)	1796
6	7/9/93	S	NEWTONS POOL - RETRIEVING FISH PRIOR TO DECONTAMINATION (NRA)	1797
7	7/9/93	S	NEWTONS POOL - RETRIEVING FISH PRIOR TO DECONTAMINATION (NRA)	1798
8	7/9/93	S	NEWTONS POOL - RETRIEVING FISH PRIOR TO DECONTAMINATION (NRA)	1799
9	7/9/93	S	NEWTONS POOL - RETRIEVING FISH PRIOR TO DECONTAMINATION (NRA)	1800
10	7/9/93	S	NEWTONS POOL - RETRIEVING FISH PRIOR TO DECONTAMINATION (NRA)	1801
11	7/9/93	S	NEWTONS POOL - RETRIEVING FISH PRIOR TO DECONTAMINATION (NRA)	1802
12	7/9/93	S	NEWTONS POOL - RETRIEVING FISH PRIOR TO DECONTAMINATION (NRA)	1803
13	7/9/93	S	NEWTONS POOL - RETRIEVING FISH PRIOR TO DECONTAMINATION (NRA)	1804
14	7/9/93	S	NEWTONS POOL - FISH BEING EMPTIED INTO CONTAINERS (NRA)	1805
15	7/9/93	S	NEWTONS POOL - FISH BEING EMPTIED INTO CONTAINERS (NRA)	1806
16	8/9/93	P	BOREHOLE IN CANAL BANK NORTH OF BUILDINGS A230 - A234	1807
17	8/9/93	P	BOREHOLE IN CANAL BANK NORTH OF BUILDINGS A230 - A234	1808
18	8/9/93	P	BOREHOLE IN CANAL BANK NORTH OF BUILDINGS A230 - A234	1809
19	8/9/93	P	BOREHOLE IN CANAL BANK NORTH OF BUILDINGS A230 - A234	1810
20	8/9/93	P	VIEW OF CANAL NORTH OF BUILDINGS A230 - A234 - LOOKING WEST	1811
21	8/9/93	P	SCRAP METALS ACCUMULATED IN STOCKPILE	1812
22	8/9/93	S	EXCAVATION OF CANAL IN PROGRESS	1813
23	8/9/93	S	NEWTONS POOL - DECONTAMINATION WORKS	1814
24	8/9/93	H	DEMOLITION ARISINGS STOCKPILE	1815
25	8/9/93	H	DEMOLITION ARISINGS STOCKPILE	1816
26	8/9/93	H	DEMOLITION ARISINGS STOCKPILE	1817
27	8/9/93	P	CLEARANCE OF BUILDING A250 SUB STRUCTURE	1818
28	8/9/93	P	CLEARANCE OF BUILDING A250 SUB STRUCTURE	1819
29	9/9/93	H	CONTAMINATED WASTE ON H67 SAMPLING AREA	1820
30	9/9/93	P	REMOVAL OF BUILDING A250 SUB STRUCTURE	1821
31	9/9/93	P	REMOVAL OF BUILDING A250 SUB STRUCTURE	1822
32	9/9/93	T	REMEDIATION OF TETRYL FACTORY SITE (HISTORIC CRANE BASE)	1823
33	9/9/93	T	REMEDIATION OF TETRYL FACTORY SITE (HISTORIC CRANE BASE)	1824
34	9/9/93	T	EXPOSURE OF SUSPECT PIT AREA 'T', NORTH	1825
35	9/9/93	T	REMEDIATION OF TETRYL FACTORY SITE (FOUNDATIONS TO FORMER GUNPOWDER STOVE)	1826
36	9/9/93	T	REMEDIATION OF TETRYL FACTORY SITE (FOUNDATIONS TO FORMER GUNPOWDER STOVE)	1827
R	13/9/93	P	EXCAVATION ADJACENT TO BUILDINGS A230 - A234	1828

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: 63/4532

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1	15/9/93	T	CONTAMINATED MATERIAL BEING STOCKPILED	1829
2	15/9/93	T	ASBESTOS BEING BAGGED	1830
3	15/9/93	S	NEWTONS POOL - SCREENING PLANT	1831
4	15/9/93	S	NEWTONS POOL - TYPICAL SCREEN, REMOVED FOR REPAIRS	1832
5	15/9/93	S	NEWTONS POOL - EXCAVATION	1833
6	15/9/93	S	NEWTONS POOL - VIEW FROM NORTH BUILDING S34	1834
7	15/9/93	S	NEWTONS POOL - VIEW NORTH OF BUILDING S34	1835
8	15/9/93	S	NEWTONS POOL - VIEW EAST OF BUILDING S34	1836
9			NOT USED	
10	17/9/93	S	BARGE HOUSE FOUNDATIONS ON SIDE OF CANAL ADJACENT TO BUILDING E2	1837
11	17/9/93	S	BARGE HOUSE FOUNDATIONS ON SIDE OF CANAL ADJACENT TO BUILDING E2	1838
12	17/9/93	T	EXCAVATED CANAL ADJACENT TO BUILDING E2	1839
13	17/9/93	S	BARGE HOUSE TO SIDE OF EXCAVATED CANAL ADJACENT TO BUILDING E2	1840
14	18/9/93	S	NEWTONS POOL - SHINGLE DAM / FILTER - TO RETAIN SIEVED SLUDGE	1841
15	18/9/93	S	NEWTONS POOL - SCREENING PLANT FOR SIEVING SLUDGE REMOVED	1842
16	18/9/93	S	NEWTONS POOL - REMEDIATION	1843
17	20/9/93	S	NEWTONS POOL - REMEDIATION (PUMP ARRANGEMENT)	1844
18	20/9/93	S	NEWTONS POOL - REMEDIATION (LONG REACH EXCAVATOR IN USE)	1845
19	20/9/93	S	NEWTONS POOL - REMEDIATION (LONG REACH EXCAVATOR IN USE)	1846
20	20/9/93	S	NEWTONS POOL - REMEDIATION (LONG REACH EXCAVATOR IN USE)	1847
21	22/9/93	S	NEWTONS POOL - REMEDIATION (SUSPECT OBJECT REMOVED)	1848
22	22/9/93	S	NEWTONS POOL - REMEDIATION	1849
23	24/9/93	S	NEWTONS POOL - REMEDIATION	1850
24	24/9/93	S	NEWTONS POOL - REMEDIATION	1851
25	24/9/93	S	NEWTONS POOL - REMEDIATION	1852
26	24/9/93	S	NEWTONS POOL - REMEDIATION	1853
27	24/9/93	S	NEWTONS POOL - REMEDIATION	1854
28	24/9/93	S	NEWTONS POOL - REMEDIATION	1855
29	24/9/93	S	NEWTONS POOL - REMEDIATION	1856
30	24/9/93	S	NEWTONS POOL - REMEDIATION	1857
31			NOT USED	
32	25/9/93	M	NEWTONS POOL - REMEDIATION - PREPARING PRE-CAST CONCRETE MANHOLE RINGS FOR USE AS 'PUMP SUMPS'	1858
33	25/9/93	S	NEWTONS POOL - REMEDIATION	1859
34	25/9/93	S	NEWTONS POOL - REMEDIATION	1860
35	25/9/93	S	NEWTONS POOL - REMEDIATION	1861
36	25/9/93	S	NEWTONS POOL - REMEDIATION (PUMP ARRANGEMENT)	1862
37	25/9/93	S	NEWTONS POOL - REMEDIATION	1863

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: 64/4533

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1	25/9/93	S	NEWTONS POOL - REMEDIATION	1864
2	25/9/93	S	NEWTONS POOL - REMEDIATION	1865
3	25/9/93	S	NEWTONS POOL - REMEDIATION	1866
4	25/9/93	S	NEWTONS POOL - REMEDIATION	1867
5	25/9/93	M	NEWTONS POOL - REMEDIATION (CORING PRE-CAST MANHOLE RINGS TO USE AS 'PUMP SUMPS')	1868
6	25/9/93	S	NEWTONS POOL - REMEDIATION (RE-ARRANGING PUMP SUCTION LINES)	1869
7	25/9/93	S	NEWTONS POOL - REMEDIATION	1870
8	25/9/93	S	NEWTONS POOL - REMEDIATION	1871
9	25/9/93	S	NEWTONS POOL - REMEDIATION	1872
10	26/9/93	S	NEWTONS POOL - REMEDIATION	1873
11	26/9/93	S	NEWTONS POOL - REMEDIATION	1874
12	26/9/93	S	NEWTONS POOL - REMEDIATION	1875
13	26/9/93	S	NEWTONS POOL - REMEDIATION (LONG REACH EXCAVATOR IN USE)	1876
14	26/9/93	S	NEWTONS POOL - REMEDIATION	1877
15	26/9/93	S	NEWTONS POOL - REMEDIATION	1878
16	26/9/93	S	NEWTONS POOL - REMEDIATION (GROUND WATER INGRESS)	1879
17			NOT USED	
18			NOT USED	
19			NOT USED	
20			NOT USED	
21	26/9/93	S	NEWTONS POOL - REMEDIATION (GROUND WATER INGRESS)	1880
22	26/9/93	S	NEWTONS POOL - REMEDIATION	1881
23	26/9/93	S	NEWTONS POOL - REMEDIATION	1882
24	26/9/93	S	NEWTONS POOL - REMEDIATION (RE-ARRANGING PUMP SUCTION LINES)	1883
25	26/9/93	S	NEWTONS POOL - REMEDIATION (HAND CLEARANCE AT SCREENING POINT)	1884
26	26/9/93	S	NEWTONS POOL - REMEDIATION	1885
27	26/9/93	S	NEWTONS POOL - REMEDIATION	1886
28	26/9/93	S	NEWTONS POOL - REMEDIATION	1887
29	26/9/93	S	NEWTONS POOL - REMEDIATION	1888
30	26/9/93	S	NEWTONS POOL - REMEDIATION	1889
31	26/9/93	S	NEWTONS POOL - REMEDIATION	1890
32	26/9/93	S	NEWTONS POOL - REMEDIATION	1891
33	26/9/93	S	NEWTONS POOL - REMEDIATION	1892
34	26/9/93	S	NEWTONS POOL - REMEDIATION	1893
35	26/9/93	S	NEWTONS POOL - REMEDIATION	1894
36	26/9/93	S	NEWTONS POOL - REMEDIATION	1895
R	26/9/93	S	NEWTONS POOL / OLD RIVER LEA REMEDIATION	1896

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: 65/2767

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1	26/9/93	S	NEWTONS POOL - REMEDIATION	1897
2	26/9/93	S	NEWTONS POOL - REMEDIATION	1898
3	26/9/93	S	NEWTONS POOL - REMEDIATION	1899
4	26/9/93	S	NEWTONS POOL - REMEDIATION	1900
5	26/9/93	S	NEWTONS POOL - REMEDIATION	1901
6	26/9/93	S	NEWTONS POOL - REMEDIATION	1902
7	26/9/93	S	NEWTONS POOL - REMEDIATION	1903
8	26/9/93	S	NEWTONS POOL - REMEDIATION	1904
9	26/9/93	S	NEWTONS POOL - REMEDIATION	1905
10	26/9/93	S	NEWTONS POOL - REMEDIATION	1906
11	26/9/93	S	NEWTONS POOL - REMEDIATION	1907
12	26/9/93	S	NEWTONS POOL - REMEDIATION	1908
13	26/9/93	S	NEWTONS POOL - REMEDIATION	1909
14	26/9/93	S	NEWTONS POOL - REMEDIATION	1910
15	27/9/93	S	NEWTONS POOL - REMEDIATION	1911
16	27/9/93	S	NEWTONS POOL - REMEDIATION (BLUE ASBESTOS FOUND)	1912
17	28/9/93	S	NEWTONS POOL - REMEDIATION (ORIGINAL TIMBER PILE S TO SLUICE)	1913
18	28/9/93	S	NEWTONS POOL - REMEDIATION (ORIGINAL TIMBER PILE S TO SLUICE)	1914
19	28/9/93	S	NEWTONS POOL - REMEDIATION	1915
20	28/9/93	S	NEWTONS POOL - REMEDIATION	1916
21	28/9/93	S	NEWTONS POOL - REMEDIATION	1917
22	28/9/93	S	NEWTONS POOL - REMEDIATION	1918
23	28/9/93	S	NEWTONS POOL - REMEDIATION	1919
24	28/9/93	S	NEWTONS POOL - REMEDIATION	1920
25	28/9/93	S	NEWTONS POOL - REMEDIATION	1921

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: 66/2768

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1	29/9/93	P	REMEDIATION IN PROGRESS - LOOKING NORTH	1922
2	29/9/93	P	REMEDIATION IN PROGRESS - LOOKING NORTH	1923
3	29/9/93	P	REMEDIATION - LOOKING WEST	1924
4	29/9/93	P	REMEDIATION (ANCIENT FOUNDATION REVEALED)	1925
5	29/9/93	P	REMEDIATION	1926
6	29/9/93	P	REMEDIATION	1927
7	30/9/93	P	REMEDIATION (INGRESS OF WATER FROM MILLHEAD STREAM THROUGH FAULTY EMBANKMENT)	1928
8	30/9/93	P	REMEDIATION (INGRESS OF WATER FROM MILLHEAD STREAM THROUGH FAULTY EMBANKMENT)	1929
9	5/10/93	S	NEWTONS POOL - REMEDIATION (DEFLATED FOOTBALL RECOVERED)	1930
10	5/10/93	S	NEWTONS POOL - REMEDIATION (DEFLATED FOOTBALL RECOVERED)	1931
11	5/10/93	S	NEWTONS POOL - REMEDIATION (DEFLATED FOOTBALL RECOVERED)	1932
12			NOT USED	
13	7/10/93	H	VIEW FROM BUILDING A201 - LOOKING WEST TO BUILDING H10 (HOPPIT POOL BEFORE REMEDIATION)	1933
14	7/10/93	H	VIEW FROM BUILDING A201 - LOOKING WEST TO BUILDING H10 (HOPPIT POOL BEFORE REMEDIATION)	1934
15	7/10/93	H	VIEW FROM BUILDING A201 - LOOKING WEST TO BUILDING H10 (HOPPIT POOL BEFORE REMEDIATION)	1935
16	7/10/93	H	VIEW FROM BUILDING A201 - LOOKING WEST TO BUILDING H10 (HOPPIT POOL BEFORE REMEDIATION)	1936
17	7/10/93	H	VIEW FROM BUILDING A201 - LOOKING WEST TO BUILDING H10 (HOPPIT POOL BEFORE REMEDIATION)	1937
18	7/10/93	H	VIEW FROM BUILDING A201 - LOOKING WEST TO BUILDING H10 (HOPPIT POOL BEFORE REMEDIATION)	1938
19	8/10/93	M	BUILDING L157- REMEDIATION (DRIVE SHAFT IN UNDERCROFT ZONE)	1939
20	8/10/93	M	BUILDING L157- REMEDIATION (DRIVE SHAFT IN UNDERCROFT ZONE)	1940
21	8/10/93	M	BUILDING L157- REMEDIATION (DRIVE SHAFT IN UNDERCROFT ZONE)	1941
22	8/10/93	M	BUILDING L157- REMEDIATION (DRIVE SHAFT IN UNDERCROFT ZONE)	1942
23	8/10/93	M	BUILDING L157- REMEDIATION (DRIVE SHAFT IN UNDERCROFT ZONE)	1943
24	8/10/93	M	BUILDING L157- REMEDIATION (DRIVE SHAFT IN UNDERCROFT ZONE)	1944

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: 67/2769

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1			NOT USED	
2	11/10/93	P	EXCAVATED CANAL NORTH OF BUILDING A230 - A234	1945
3	11/10/93	P	EXCAVATED CANAL NORTH OF BUILDING A230 - A234	1946
4	11/10/93	P	EXCAVATED CANAL NORTH OF BUILDING A230 - A234	1947
5	11/10/93	P	REMEDIATION (REMAINS OF ANCIENT STRUCTURES EXPOSED)	1948
6	11/10/93	P	REMEDIATION (REMAINS OF ANCIENT STRUCTURES EXPOSED)	1949
7	11/10/93	P	REMEDIATION (REMAINS OF ANCIENT STRUCTURES EXPOSED)	1950
8	11/10/93	P	REMEDIATION	1951
9	11/10/93	P	REMEDIATION - LOOKING SOUTH EAST	1952
10	11/10/93	P	REMEDIATION	1953
11	11/10/93	P	REMEDIATION (SAMPLING PEGS IN POSITION - BUILDING A269 IN BACKGROUND)	1954
12	11/10/93	P	REMEDIATION (SAMPLING PEGS IN POSITION - BUILDINGS A230 - A234 IN BACKGROUND)	1955
13	11/10/93	P	REMEDIATION (SAMPLING PEGS IN POSITION - BUILDINGS A230 - A234 IN BACKGROUND)	1956
14	11/10/93	P	REMEDIATION (SAMPLING PEGS IN POSITION - BUILDINGS A230 - A234 IN BACKGROUND)	1957
15	11/10/93	P	REMEDIATION	1958
16	11/10/93	T	REMEDIATION (ROUTE OF FILLED CANAL DEFINED BY CLAYWARE AND BRICK INFILL - CONTAINING BLUE ASBESTOS)	1959
17	11/10/93	T	REMEDIATION (ROUTE OF FILLED CANAL DEFINED BY CLAYWARE AND BRICK INFILL - CONTAINING BLUE ASBESTOS)	1960
18	11/10/93	T	REMEDIATION	1961
19	11/10/93	T	REMEDIATION	1962
20	11/10/93	T	REMEDIATION (SUBSTRUCTURE OF FORMER GUNPOWDER STOVE EXPOSED YELLOW AIR MONITORING STATION AT TOP RIGHT OF PICTURE)	1963
21	11/10/93	T	REMEDIATION	1964
22	11/10/93	T	REMEDIATION (SUBSTRUCTURE OF FORMER GUNPOWDER STOVE EXPOSED)	1965
23	11/10/93	T	REMEDIATION (NOTE: YELLOW DISCOLORATION OF SURFACE WATER)	1966
24	11/10/93	T	REMEDIATION (CLEAR DEFINITION OF CANAL INFILL)	1967
25	11/10/93	P	EXCAVATION OF CANAL NORTH OF BUILDINGS A230 - A234	1968

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: 68/3118

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1	14/10/93	S	EDMONSEY SLUICE - LOOKING WEST	1969
2	14/10/93	S	EDMONSEY SLUICE - LOOKING WEST	1970
3	14/10/93	S	EDMONSEY SLUICE - LOOKING WEST	1971
4	14/10/93	S	EDMONSEY SLUICE - LOOKING WEST - IN FLOOD	1972
5	14/10/93	S	EDMONSEY SLUICE - LOOKING NORTH WEST - IN FLOOD	1973
6	14/10/93	S	EDMONSEY SLUICE - LOOKING NORTH WEST - IN FLOOD	1974
7	14/10/93	S	EDMONSEY SLUICE - LOOKING NORTH WEST - IN FLOOD	1975
8	14/10/93	S	NEWTONS POOL - TEMPORARY SHEET PILING IN PLACE	1976
9	14/10/93	S	NEWTONS POOL - VIEW LOOKING WEST	1977
10	14/10/93	S	NEWTONS POOL - VIEW LOOKING WEST	1978
11	14/10/93	S	AREA NORTH OF BUILDING S34 BEING SCRAPED	1979
12	14/10/93	T	VIEW OF HORSEMILL STREAM - LOOKING SOUTH	1980
13	14/10/93	T	VIEW OF TETRYL AREA - LOOKING SOUTH	1981
14	14/10/93	T	VIEW ACROSS HORSEMILL STREAM FROM TETRYL AREA - LOOKING WEST	1982
15	14/10/93	S	BRIDGE No. 11 LEADING TO NEW HILL	1983
16	14/10/93	S	OLD RIVER LEA IN FLOOD WEST OF NEWTONS POOL	1984
17	14/10/93	S	BUILDINGS 148 AND 149 IN 'BARREL GRAVEYARD' (OLD TIMBER STEAM MAIN SUPPORTS)	1985
18	14/10/93	S	GENERAL VIEW OF WOODED AREA	1986
19	14/10/93	S	GENERAL VIEW OF WOODED AREA	1987
20	14/10/93	S	GENERAL VIEW OF WOODED AREA	1988
21	14/10/93	S	VIEW TOWARDS BUILDING U6 IN 'BARREL GRAVEYARD'	1989
22	14/10/93	S	L.G.C. PERSONNEL PREPARING FOR SAMPLING	1990
23	14/10/93	M	BRIDGE No. 6 - LOOKING TOWARDS BUILDINGS L143 AND L134	1991
24	14/10/93	M	MILLHEAD STREAM LOOKING SOUTH EAST, ACROSS CORDITE CONTAMINATED AREA	1992
25	14/10/93	M	SCREENED CORDITE CONTAMINATED MATERIAL AWAITING SAMPLING (BUILDINGS L159 AND L151 IN BACKGROUND)	1993

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: 69/3115

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1	14/10/93	S	EDMONSEY SLUICE - LOOKING WEST (RIVER IN FLOOD)	1994
2	14/10/93	S	EDMONSEY SLUICE - LOOKING WEST (RIVER IN FLOOD)	1995
3	14/10/93	S	HORSEMILL STREAM - NORTH OF EDMONSEY SLUICE (RIVER IN FLOOD)	1996
4	14/10/93	S	EDMONSEY SLUICE - LOOKING WEST (RIVER IN FLOOD)	1997
5	14/10/93	S	EDMONSEY SLUICE - LOOKING WEST (RIVER IN FLOOD)	1998
6	14/10/93	S	HORSEMILL STREAM - SOUTH OF EDMONSEY SLUICE (RIVER IN FLOOD)	1999
7	14/10/93	S	HORSEMILL STREAM - SOUTH OF EDMONSEY SLUICE (RIVER IN FLOOD)	2000
8	14/10/93	P	EXCAVATION OF CANAL NORTH OF BUILDING A230- A234	2001
9	14/10/93	N	L.G.C. SAMPLING AT NEW HILL	2002
10	14/10/93	N	L.G.C. SAMPLING AT NEW HILL	2003
11	14/10/93	M	SCREENED CORDITE CONTAMINATED MATERIAL AWAITING SAMPLING (BUILDING L159 IN BACKGROUND)	2004
12	14/10/93	M	CORDITE SCREENED MATERIAL STOCKPILED AWAITING SAMPLING	2005
13	14/10/93	M	CORDITE SCREENED MATERIAL STOCKPILED AWAITING SAMPLING	2006
14	14/10/93	H	H16 AREA - EXCAVATED MATERIAL FROM NEWTONS POOL BEING SCRUTINISED	2007
15	14/10/93	H	H16 AREA - EXCAVATED MATERIAL FROM NEWTONS POOL BEING SCRUTINISED	2008
16	15/10/93	P	SITE VEHICLE STUCK	2009
17	15/10/93	P	SITE VEHICLE AWAITING TOW	2010
18	15/10/93	H	SHELL FOUND ON H16 AREA IN MATERIAL FROM NEWTONS POOL	2011
19	15/10/93	H	SHELL ON H16 AREA FOUND IN MATERIAL FROM NEWTONS POOL	2012
20	15/10/93	H	MARKINGS ON SHELL FOUND IN MATERIAL IN H16 AREA FROM NEWTONS POOL	2013
21			NOT USED	
22	15/10/93	H	SHELL FOUND IN MATERIAL FROM NEWTONS POOL ON H16 AREA	2014
23	18/10/93	H	BUILDING H12 - AFTER 'HEAT TREATMENT'	2015
24	18/10/93	H	BUILDING H12 - AFTER 'HEAT TREATMENT'	2016
25	18/10/93	H	BUILDING H12 - AFTER 'HEAT TREATMENT'	2017

REPORT NO. ESG 2060/94
FORMER RARDE
 WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: 70/6136

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1	27/10/93	H	LAYING OUT CONTAMINATED WASTE ON HI6 AREA FOR SAMPLING	2018
2	27/10/93	M	BUILDING L157 - BREAKING OUT CONCRETE FLOOR	2019
3	27/10/93	M	BUILDING L157 - EXTERNAL VIEW OF UNDERCROFT	2020
4	27/10/93	M	BUILDING L157 - SOUTH EAST CORNER (STRUCTURAL DEFECTS IN PARAPET BRICKWORK)	2021
5	27/10/93	M	BUILDING L157 - REMEDIATION (ARISINGS STOCKPILED OUTSIDE BUILDING)	2022
6	27/10/93	M	BUILDING L157 - SCAFFOLDING FOR PROOF WORKS	2023
7	27/10/93	S	CANAL REMEDIATION ADJACENT TO BUILDING E14	2024
8	27/10/93	S	WASTE MATERIAL BEING EXCAVATED FOR BUILDINGS 88A TO E14	2025
9	27/10/93	S	CANAL REMEDIATION NORTH OF BUILDING 88A (RED BAGS INDICATE BAGGED ASBESTOS WASTE)	2026
10	27/10/93	S	NEWTONS POOL (NEW SLUICE WORKS IN PROGRESS)	2027
11	27/10/93	S	NEWTONS POOL (NEW SLUICE WORKS IN PROGRESS)	2028
12	27/10/93	S	NEWTONS POOL - REMEDIATION	2029
13	27/10/93	S	NEWTONS POOL - REMEDIATION	2030
14	27/10/93	S	NEWTONS POOL (NEW SLUICE WORKS IN PROGRESS)	2031
15	27/10/93	M	BUILDING L157 - UNDERCROFT EXPOSED	2032
16	27/10/93	M	BUILDING L157 - UNDERCROFT EXPOSED	2033
17	27/10/93	M	BUILDING L157 - REMEDIATION (UNDERCROFT INFILL MATERIAL)	2034
18	27/10/93	M	BUILDING L157 - REMEDIATION (DRIVE SHAFT IN UNDERCROFT)	2035
19	27/10/93	M	BUILDING L157 - REMEDIATION (COLLAPSING TIMBER SHORING TO UNDERCROFT)	2036
20	27/10/93	M	BUILDING L157 - REMEDIATION (UNDERCROFT)	2037
21	27/10/93	M	BUILDING L157 - REMEDIATION (UNDERCROFT)	2038
22	27/10/93	M	BUILDING L157 - REMEDIATION (UNDERCROFT)	2039
23	27/10/93	M	BUILDING L157 - REMEDIATION (UNDERCROFT)	2040
24	27/10/93	M	BUILDING L157 - REMEDIATION (UNDERCROFT)	2041
25	28/10/93	M	BUILDING L157 - REMEDIATION (ASBESTOS LAGGED SERVICES IN CEILING VOID)	2042
26	28/10/93	M	BUILDING L157 - REMEDIATION (ASBESTOS LAGGED SERVICES IN CEILING VOID)	2043
27	28/10/93	M	BUILDING L157 - REMEDIATION (ASBESTOS LAGGED SERVICES IN CEILING VOID)	2044
28	30/10/93	B	WASTE TIMBER STACKED AS FUEL FOR 'HEAT TREATMENT'	2045
29	30/10/93	B	WASTE TIMBER FROM REMEDIATION WORKS IN INCORPORATING MILLS	2046
30	30/10/93	B	FIRING IN PROCESS	2047
31	30/10/93	B	FIRING IN PROCESS	2048
32	30/10/93	B	FIRING IN PROCESS	2049
33			NOT USED	
34	5/11/93	H	ROYAL ORDNANCE SUPERVISOR DOING PAPERWORK	2050
35	5/11/93	H	SITE ENGINEERS GETTING A POINT OVER TO SITE ARCHAEOLOGIST	2051

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: 71/6133

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1	9/11/93	S	BUILDING 27 - VIEW FROM ACROSS HORSEMILL STREAM - LOOKING EAST	2052
2	9/11/93	S	VIEW ACROSS HORSEMILL STREAM - LOOKING EAST (AREA 'S' RIVER BANK AND CANAL INTERSECTIONS 27 AND 28)	2053
3	9/11/93	T	VIEW ACROSS HORSEMILL STREAM - LOOKING EAST (AREA 'T' RIVER BANK AND CANAL INTERSECTION 27)	2054
4	9/11/93	T	VIEW ACROSS HORSEMILL STREAM - LOOKING EAST (AREA 'T' RIVER BANK AND CANAL INTERSECTION 26)	2055
5	9/11/93	T	VIEW ACROSS HORSEMILL STREAM - LOOKING EAST (AREA 'T' RIVER BANK AND CANAL INTERSECTION 25 - TO THE RIGHT)	2056
6	9/11/93	T	VIEW ACROSS HORSEMILL STREAM - LOOKING EAST	2057
7	9/11/93	T	VIEW ACROSS HORSEMILL STREAM - LOOKING EAST (AREA 'T' RIVER BANK AND CANAL INTERSECTION 26)	2058
8	9/11/93	T	VIEW ACROSS HORSEMILL STREAM - LOOKING EAST	2059
9	9/11/93	T	VIEW ACROSS HORSEMILL STREAM - LOOKING EAST (BUILDING E2 IN BACKGROUND WITH AREA 'T' RIVER BANK AND CANAL INTERSECTION 25)	2060
10	9/11/93	T	VIEW ACROSS HORSEMILL STREAM - LOOKING EAST	2061
11	9/11/93	T	VIEW ACROSS HORSEMILL STREAM - LOOKING EAST (BUILDING E2 IN BACKGROUND WITH AREA 'T' RIVER BANK)	2062
12	9/11/93	T	VIEW ACROSS HORSEMILL STREAM - LOOKING EAST	2063
13	9/11/93	T	VIEW ACROSS HORSEMILL STREAM - LOOKING EAST	2064
14	9/11/93	T	VIEW ACROSS HORSEMILL STREAM - LOOKING EAST (AREA 'T' RIVER BANK)	2065
15	9/11/93	T	VIEW ACROSS HORSEMILL STREAM - LOOKING EAST (STOCKPILE OF WASTE AND AREA 'T' RIVER BANK)	2066
16	9/11/93	T	VIEW ACROSS HORSEMILL STREAM - LOOKING EAST	2067
17	9/11/93	T	VIEW ACROSS HORSEMILL STREAM - LOOKING EAST	2068
18	9/11/93	T	VIEW ACROSS HORSEMILL STREAM - LOOKING EAST	2069
19	9/11/93	T	VIEW ACROSS HORSEMILL STREAM - LOOKING EAST	2070
20	9/11/93	T	VIEW ACROSS HORSEMILL STREAM - LOOKING EAST	2071
21	9/11/93	T	VIEW ACROSS HORSEMILL STREAM - LOOKING EAST TOWARDS BUILDING E10	2072
22	9/11/93	T	VIEW ACROSS HORSEMILL STREAM - LOOKING EAST TOWARDS BUILDING E10	2073
23	9/11/93	T	VIEW ACROSS HORSEMILL STREAM - LOOKING EAST TOWARDS BUILDING E10	2074
24	9/11/93	S	VIEW ACROSS HORSEMILL STREAM -SOUTH OF BUILDING E10 (RIVER BANK TO ACID FACTORY AND CANAL INTERSECTION 21)	2075
25	9/11/93	S	VIEW ACROSS HORSEMILL STREAM - LOOKING EAST (SITE BANK TO EDMONSEY SLUICE, SLUICE BALANCING DRAIN & CANAL IT 8)	2076
26	9/11/93	S	VIEW ACROSS HORSEMILL STREAM - LOOKING EAST (CANAL IT 18)	2077
27	9/11/93	S	VIEW ACROSS HORSEMILL STREAM - LOOKING EAST (RIVER BANK CONSTRUCTION JUST SOUTH OF EDMONSEY SLUICE)	2078
28	9/11/93	S	VIEW ACROSS HORSEMILL STREAM - LOOKING EAST	2079
29	9/11/93	S	VIEW ACROSS HORSEMILL STREAM - LOOKING EAST	2080
30	9/11/93	S	VIEW ACROSS HORSEMILL STREAM - LOOKING EAST	2081
31	9/11/93	P	EXCAVATION OF CANAL NORTH OF BUILDING A240	2082

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: 72/6897

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1	16/11/93	P	VIEW OF TREE FELLED BY HIGH WINDS	2083
2	17/11/93	S	BRIDGE No. 10 - REPAIRS IN PROGRESS	2084
3	17/11/93	S	NEWTONS POOL (CONSTRUCTION OF NEW SLUICE)	2085
4	17/11/93	S	NEWTONS POOL (CONSTRUCTION OF NEW SLUICE)	2086
5	17/11/93	S	SURVEY (TYPICAL EXAMPLE OF DECAYING ASBESTOS CLAD STEAM MAIN PIPE)	2087
6	17/11/93	S	CANAL WEST OF BUILDING 22A (ALDER GROWTH)	2088
7	17/11/93	S	CANAL WEST OF BUILDING 22A (RIVER GRAVEL INFILL & ALDER GROWTH)	2089
8	17/11/93	S	CANAL FROM BUILDING 22A TO BUILDING 16A	2090
9	17/11/93	S	CANAL FROM BUILDING 22A TO BUILDING 16A	2091
10	17/11/93	S	CANAL FROM BUILDING 22A TO BUILDING 16A (BUILDING 18A TO RIGHT)	2092
11	17/11/93	S	CANAL FROM BUILDING 22A TO BUILDING 16A	2093
12	17/11/93	S	NEWTONS POOL (CONSTRUCTION OF NEW SLUICE)	2094
13	17/11/93	S	PUMP DISCHARGE FROM NEWTONS POOL	2095
14	17/11/93	S	CANAL REMEDIATION NEAR BUILDING S30	2096
15	22/11/93	B	DECONTAMINATION OF FLOOR ASPHALT	2097
16	22/11/93	P	REMEDIATION	2098
17	22/11/93	P	REMEDIATION (FILLED CANAL LOCATED SOUTH WEST CORNER OF SITE)	2099
18			NOT USED	
19	2/12/93	M	BUILDING L157 - BAY 3 STITCH CORE DRILLING (ROYAL ORDNANCE REMOTE CONTROLLED CORE DRILLING RIG)	2100
20	2/12/93	M	BUILDING L157 - BAY 3 STITCH CORE DRILLING	2101
21	2/12/93	M	BUILDING L157 - BAY 3 STITCH CORE DRILLING	2102
22	2/12/93	M	BUILDING L157 - BAY 3 (UNDERCROFT INFILL PARTIALLY REMOVED)	2103
23	2/12/93	M	BUILDING L157 - BAY 3 (INCORPORATING PAN BEARING VISIBLE IN UNDERCROFT INFILL)	2104
24	2/12/93	M	BUILDING L157 - VOID BELOW STEEL CORRIDOR POST BAY 3 (POTENTIAL ZONE OF EXPLOSIVES DUST CONTAMINATION)	2105
25	2/12/93	M	BUILDING L157 - VOID EXTRA AIR BRICK EAST BAY 3	2106
26	2/12/93	M	BUILDING L157 - BAY 4 (UNDERFLOOR INFILL REMOVED)	2107
27	2/12/93	M	BUILDING L157 - BAY 4 WALL PAINT STRIP IN PROGRESS	2108
28	5/12/93	P	REMEDIATION (SEALANT APPLIED TO EARTH FACES AT BOUNDARY OF SITE)	2109
29	5/12/93	P	REMEDIATION	2110
30	5/12/93	P	REMEDIATION	2111
31	5/12/93	P	REMEDIATION	2112
32	5/12/93	P	REMEDIATION ('DETOX' SEALANT APPLIED TO FACES OF TREE ISLAND)	2113
33	5/12/93	P	REMEDIATION (BUILDINGS A230 - A234 IN BACKGROUND)	2114
34	5/12/93	P	REMEDIATION (BUILDING H10 CENTRE BACKGROUND)	2115
35	5/12/93	P	REMEDIATION ('DETOX' SEALANT TO PERIMETER BANKS)	2116
36	5/12/93	P	REMEDIATION ('DETOX' SEALANT TO SOUTH BOUNDARY FACES)	2117
37	5/12/93	P	REMEDIATION ('DETOX' SEALANT TO SOUTH & WEST BOUNDARY FACES)	2118

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: 73/7514

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1			NOT USED	
2	6/12/93	M	BUILDING L157 - CLEARING WASTE MATERIAL FROM UNDERCROFT (CARE AND ATTENTION WORKING AROUND DRIVE SHAFTING)	2119
3	6/12/93	M	BUILDING L157 - REMOTE CONTROLLED CORING (ROYAL ORDNANCE REMOTE CORING RIG)	2120
4	6/12/93	M	BUILDING L157 - PAINT STRIPPED WALL	2121
5	6/12/93	P	REMEDIATION	2122
6	6/12/93	P	REMEDIATION	2123
7	6/12/93	P	REMEDIATION	2124
8	6/12/93	P	REMEDIATION	2125
9	8/12/93	P	WATER CONNECTIONS ADJACENT TO BUILDING A238	2126
10	6/12/93	H	ROYAL ORDNANCE SITE MANAGER IN CHRISTMAS SPIRIT	2127
11	10/12/93	P	OUTFALL IN RIVER LEA FROM PMLH EXCAVATED CANAL (PRE-CAST CONCRETE MANHOLE RING SECTIONS USED TO BREAK FORCE OF DISCHARGE WATER)	2128
12	10/12/93	P	POWDERMILL LANE - LAYING NEW WATER MAIN (DIVERSION AROUND P SITE)	2129
13	10/12/93	P	DIVERSION OF F.W.D. FROM BUILDING A221	2130
14	15/12/93	M	BUILDING L157 - EXCAVATING UNDERFLOOR FILLING MATERIAL	2131
15	15/12/93	M	BUILDING L157 - EXCAVATING UNDERFLOOR FILLING MATERIAL (LARGE STEAM ENGINE FOUNDATIONS SHOWN)	2132
16	15/12/93	M	BUILDING L157 - EXCAVATING UNDERFLOOR FILLING MATERIAL (LARGE STEAM ENGINE FOUNDATIONS SHOWN)	2133
17	15/12/93	P	REMEDIATION	2134
18	15/12/93	P	REMEDIATION (POOR WEATHER CONDITIONS AT THIS TIME)	2135
19	15/12/93	P	REMEDIATION (POOR WEATHER CONDITIONS AT THIS TIME AND NOTE FORMER CANAL ROUTES OPENED UP)	2136
20	15/12/93	P	REMEDIATION (POOR WEATHER CONDITIONS AT THIS TIME AND NOTE FORMER CANAL ROUTES OPENED UP)	2137
21	17/12/93	H	REMOVAL OF MOUNDING TO BUILDING H12	2138
22	17/12/93	P	DEMOLITION OF BUILDINGS A230 - A234 (FRAME SHOWS NORTH ELEVATION)	2139
23	17/12/93	P	BUILDING A232 ROOFING SLATES BEING REMOVED	2140
24	17/12/93	P	BUILDING A234 ROOF DEMOLITION IN PROGRESS	2141
25	17/12/93	P	BUILDING A231 ROOF DEMOLITION IN PROGRESS	2142

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: 74/8525

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1	5/1/94	P	REMEDIATION	2143
2	9/1/94	P	REMEDIATION (FORMER CANALS OPENED UP)	2144
3	9/1/94	P	REMEDIATION (POOR WEATHER CONDITIONS AT THIS TIME)	2145
4	9/1/94	P	REMEDIATION (POOR WEATHER CONDITIONS AT THIS TIME)	2146
5	9/1/94	P	REMEDIATION (POOR WEATHER CONDITIONS AT THIS TIME)	2147
6	9/1/94	P	REMEDIATION (POOR WEATHER CONDITIONS AT THIS TIME)	2148
7	9/1/94	P	REMEDIATION (PUMP DOWN OF GROUND WATER IN PROGRESS)	2149
8	9/1/94	P	REMEDIATION	2150
9	9/1/94	P	REMEDIATION (POOR WEATHER CONDITIONS)	2151
10	9/1/94	P	REMEDIATION	2152
11	9/1/94	P	REMEDIATION (SAMPLE PEGS IN PLACE)	2153
12	9/1/94	P	REMEDIATION	2154
13	9/1/94	P	REMEDIATION	2155
14	9/1/94	P	REMEDIATION (F.W.D. IN CENTRE OF PICTURE LEFT IN PLACE. EXISTING LIVE GAS MAIN, YELLOW PIPE, LEFT IN PLACE - BOTH SERVING BUILDING A221)	2156
15	9/1/94	P	REMEDIATION (DIFFICULT CONDITIONS)	2157
16	9/1/94	P	REMEDIATION	2158
17	9/1/94	P	REMEDIATION	2159
18	9/1/94	P	REMEDIATION	2160
19	9/1/94	P	REMEDIATION	2161
20	9/1/94	P	REMEDIATION	2162
21	9/1/94	P	REMEDIATION (BUILDING A269 TO LEFT OF PICTURE)	2163
22	9/1/94	P	REMEDIATION (BUILDING A268 CENTRE RIGHT OF PICTURE)	2164
23	9/1/94	P	REMEDIATION (BUILDING A269 TO LEFT OF PICTURE)	2165
24	9/1/94	P	REMEDIATION (DIFFICULT CONDITIONS)	2166
25	9/1/94	P	REMEDIATION (DIFFICULT CONDITIONS)	2167
26	9/1/94	P	REMEDIATION	2168
27	9/1/94	P	REMEDIATION	2169
28	9/1/94	P	NEW VALVE INSTALLED TO EXISTING WATER MAIN ADJACENT TO BLDG A238	2170
29	12/1/94	M	BUILDING L157 - PULLING LARGE STONE BLOCKS FROM UNDERFLOOR CAVITY	2171
30	12/1/94	M	BUILDING L157 - PULLING LARGE STONE BLOCKS FROM UNDERFLOOR CAVITY	2172
31	12/1/94	M	BUILDING L157 - PULLING LARGE STONE BLOCKS FROM UNDERFLOOR CAVITY	2173
32	12/1/94	M	BUILDING L157 - PULLING LARGE STONE BLOCKS FROM UNDERFLOOR CAVITY	2174
33	12/1/94	M	BUILDING L157 - PULLING LARGE STONE BLOCKS FROM UNDERFLOOR CAVITY	2175
34	12/1/94	M	BUILDING L157 - PULLING LARGE STONE BLOCKS FROM UNDERFLOOR CAVITY	2176
35	12/1/94	M	BUILDING L157 - REMEDIATION (FORMER STEAM ENGINE FOUNDATIONS)	2177
36	12/1/94	M	BUILDING L157 - ENGINE HOUSE REMOVAL OF LARGE STONE BLOCKS FROM UNDERFLOOR CAVITY)	2178
37	12/1/94	M	BUILDING L157 - REMEDIATION	2179

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: 75/9190

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1	12/1/94	P	REMEDIATION	2180
2	12/1/94	P	REMEDIATION	2181
3	12/1/94	P	REMEDIATION	2182
4	12/1/94	P	REMEDIATION (DIFFICULT GROUND CONDITION)	2183
5	12/1/94	P	RETRIEVAL OF DEBRIS FROM MILLHEAD STREAM ADJACENT TO BRIDGE No. 1	2184
6	12/1/94	H	BUILDING H12 - DEMOLITION	2185
7			NOT USED	
8	25/1/94	H	ROAD REPAIRS IN PROGRESS	2186
9	25/1/94	H	DILUTING CONTAMINATED SOILS ON H19 AREA	2187
10	25/1/94	H	DEMOLITION OF BUILDING H12	2188
11	25/1/94	P	BUILDING A210 - REMOVAL OF HIGH LEVEL PROJECTIONS	2189
12	25/1/94	P	REMEDIATED AREA 'P' -SOUTH	2190
13	25/1/94	P	REMEDIATED AREA 'P' -SOUTH	2191
14	25/1/94	P	REMEDIATED AREA 'P' -SOUTH	2192
15	25/1/94	P	REMEDIATED AREA 'P' -SOUTH	2193
16	25/1/94	S	TIMBERS RECLAIMED FROM REMEDIATION WORKS TO CANALS	2194
17	27/1/94	M	BUILDING L157 - LAYING OUT EXCAVATED FILL MATERIALS FROM WITHIN BUILDING	2195
18	27/1/94	B	ROYAL ORDNANCE ASPHALT MIXING PLANT (USED FOR 'HEAT TREATMENT' OF ASPHALT TAKEN UP FROM FLOORS OF INCORPORATING MILLS)	2196
19	27/1/94	B	ROYAL ORDNANCE ASPHALT MIXING PLANT	2197
20	27/1/94	B	ROYAL ORDNANCE ASPHALT MIXING PLANT	2198
21	27/1/94	B	ROYAL ORDNANCE ASPHALT MIXING PLANT (PAPER DRUMS FOR COLLECTING 'HEAT TREATED' ASPHALT)	2199
22	27/1/94	B	ROYAL ORDNANCE ASPHALT MIXING PLANT (PAPER DRUMS FOR COLLECTING 'HEAT TREATED' ASPHALT)	2200
23	27/1/94	B	ROYAL ORDNANCE ASPHALT MIXING PLANT	2201
24	27/1/94	B	ROYAL ORDNANCE ASPHALT MIXING PLANT	2202
25	27/1/94	B	ROYAL ORDNANCE ASPHALT MIXING PLANT	2203

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: 76/9238

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1	27/1/94	B	ROYAL ORDNANCE ASPHALT MIXING PLANT FOR 'HEAT TREATING' ASPHALT REMOVED FROM PROCESS BUILDINGS	2204
2	27/1/94	B	ROYAL ORDNANCE ASPHALT MIXER - 'HEAT TREATMENT' OF ASPHALT IN PROGRESS	2205
3	27/1/94	B	CUT PRESSURE CYLINDERS STOCKPILED	2206
4	27/1/94	B	FLOOR SLAB ARISINGS FROM BUILDING L157 LAID OUT FOR 'HEAT TREATMENT'	2207
5	27/1/94	S	WIND BLOWN WILLOWS ADJACENT TO BUILDING E9	2208
6	27/1/94	H	BUILDING A203 - SQUIRREL ON HANDRAIL	2209
7	31/1/94	M	AIRSTREAM HELMET	2210
8	31/1/94	M	AIRSTREAM HELMET	2211
9	31/1/94	M	AIRSTREAM HELMET	2212
10	31/1/94	M	AIRSTREAM HELMET & DISPOSABLE SUIT (TYPICAL OUTFIT IN USE WHEN CARRYING OUT DECONTAMINATION WORKS IN BUILDINGS)	2213
11	31/1/94	M	AIRSTREAM HELMET & DISPOSABLE SUIT (TYPICAL OUTFIT IN USE WHEN CARRYING OUT DECONTAMINATION WORKS IN BUILDINGS)	2214
12	31/1/94	M	AIRSTREAM HELMET	2215
13			NOT USED	
14			NOT USED	
15			NOT USED	
16			NOT USED	
17			NOT USED	
18			NOT USED	

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: 77/9664

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1	3/2/94	S	SITE LANDROVER STUCK IN DIFFICULT CONDITIONS	2216
2	3/2/94	S	SITE LANDROVER STUCK IN DIFFICULT CONDITIONS	2217
3	10/2/94	P	TEMPORARY FENCING TO SEPARATE NORTH AND SOUTH OF 'P' AREA	2218
4	10/2/94	P	TEMPORARY FENCING TO SEPARATE NORTH AND SOUTH OF 'P' AREA - LOOKING TOWARDS BRIDGE No. 1	2219
5	10/2/94	P	MATERIALS SALVAGED FROM THE DEMOLITION OF BUILDINGS A230 - A234	2220
6	10/2/94	P	MATERIALS SALVAGED FROM THE DEMOLITION OF BUILDINGS A230 - A234	2221
7	10/2/94	P	MATERIALS SALVAGED FROM THE DEMOLITION OF BUILDINGS A230 - A234	2222
8	10/2/94	P	TRIAL TRENCH ACROSS FILLED CANAL (LOOKING NORTH)	2223
9	10/2/94	P	TRIAL TRENCH ACROSS FILLED CANAL (LOOKING SOUTH)	2224
10	10/2/94	H	WEST ELEVATION OF BUILDING H8	2225
11	10/2/94	H	SOUTH ELEVATION OF BUILDING H8	2226
12	10/2/94	H	BUILDING H8 - LOOKING SOUTH ALONG WEST ELEVATION	2227
13	10/2/94	H	NORTH ELEVATION OF BUILDING H8 (ASBESTOS CLAD CANOPY REMOVED)	2228
14	10/2/94	S	NEWTONS POOL - NEW SLUICE	2229
15	10/2/94	S	NEWTONS POOL - SLUICE HANDRAILING	2230
16	10/2/94	N	TOP SOIL STRIP IN PROGRESS	2231
17	10/2/94	S	BRIDGE No. 10 - REPAIRED BRICKWORK (EAST WALL)	2232
18	10/2/94	S	BRIDGE No. 10 - REPAIRED BRICKWORK (WEST WALL)	2233
19	10/2/94	S	LONG WALK - REMOVAL OF STREET LAMP BULBS	2234
20	10/2/94	P	NORTH OF BUILDING A219 - CAR PARK (EXPOSURE OF UNDERGROUND FUEL STORAGE TANKS)	2235
21	10/2/94	M	BUILDING L148 - EXCAVATION OF 'CROWN WHEEL' SHAFT WITHIN UNDERCROFT	2236
22	10/2/94	M	BUILDING L148 - VIEW SOUTHWARDS IN UNDERCROFT (NOTE: GROUND WATER INGRESS)	2237
23	10/2/94	M	BUILDING L148 UNDERCROFT (TYPICAL 'DUTCH' ARRANGEMENT - NOTE: UNDERCROFT FILLING BEHIND)	2238
24	10/2/94	S	RECLAIMED STOCK BRICKS FROM CANAL INFILLS	2239
25	10/2/94	M	BUILDING L148 - PAINT STRIPPING OF WALLS	2240

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: 78/0791

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1	18/2/94	P	ARCHAEOLOGISTS AT WORK (ESSEX COUNTY COUNCIL)	2241
2	18/2/94	P	ARCHAEOLOGISTS AT WORK (ESSEX COUNTY COUNCIL)	2242
3			NOT USED	
4	18/2/94	P	MOISTURE TEST METER (INVESTIGATION OF BUILDING A221 - STILL OCCUPIED BY CLIENTS TENANT)	2243
5	18/2/94	P	BUILDING A221 - SOUTH FACING BAY	2244
6	22/2/94	P	BUILDING A238 - LOCATION OF FAULT IN ROOF	2245
7	22/2/94	P	BUILDING A238 - WATER PENETRATION INSIDE	2246
8	23/2/94	P	EXPOSURE OF UNDERGROUND FUEL STORAGE TANKS	2247
9	23/2/94	P	EXPOSURE OF UNDERGROUND FUEL STORAGE TANKS	2248
10	3/3/94	H	REMEDIATION - GROUND STRIP IN ZONE OF FORMER BUILDING H25	2249
11	3/3/94	H	REMEDIATION - GROUND STRIP IN ZONE OF FORMER BUILDING H25	2250
12	3/3/94	H	EXCAVATION OF EAST - WEST CANAL (SOUTH OF BUILDINGS H25 AND H26)	2251
R	3/3/94	H	EXCAVATION OF EAST - WEST CANAL (SOUTH OF BUILDINGS H25 AND H26) (SAMPLING OF BASE)	2252

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: 79/0814

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1	3/3/94	H	EXCAVATION OF FILLED CANAL SOUTH OF BUILDINGS H25 AND H26	2253
2	3/3/94	H	EXCAVATION OF FILLED CANAL SOUTH OF BUILDINGS H25 AND H26	2254
3	3/3/94	H	EXCAVATION OF FILLED CANAL SOUTH OF BUILDINGS H25 AND H26	2255
4	3/3/94	H	EXCAVATION OF FILLED CANAL SOUTH OF BUILDINGS H25 AND H26	2256
5	3/3/94	H	EXCAVATION OF FILLED CANAL SOUTH OF BUILDINGS H25 AND H26 (HIGHBRIDGE STREET GATE IN BACKGROUND. SAMPLING PEGS IN POSITION.)	2257
6	3/3/94	H	REMEDIATION OF GROUND IN AREA OF FORMER BUILDING H25	2258
7	3/3/94	H	PUMP SUCTION LINE CROSS OVER	2259
8	3/3/94	H	PRE-CAST CONCRETE PERFORATED MANHOLE RING USED AS PUMP LINE STRAINER SUMP (REDUCTION OF GROUND WATER LEVELS)	2260
9	3/3/94	H	AREA 'H' 'SPECIAL WASTE' STOCKPILE AREA	2261
10	3/3/94	H	AREA 'H' 'SPECIAL WASTE' STOCKPILE AREA	2262
11	4/3/94	M	BUILDING L157 - SHEETED BAY (GRIT BLASTING OF STRUCTURE STEELWORK IN BAY INPROGRESS)	2263
12	4/3/94	H	REMEDIATION OF GROUND IN ZONE OF FORMER BUILDING H25 (NOTE: LINE OF DARK COLOURED SQUARE PITS CONTAINING HYDROCARBON CONTAMINANTS)	2264
13	4/3/94	H	REMEDIATION OF GROUND IN ZONE OF FORMER BUILDING H25 (NOTE: LINE OF DARK COLOURED SQUARE PITS CONTAINING HYDROCARBON CONTAMINANTS)	2265
14	4/3/94	H	'CLEAN' INFILLING OF EXCAVATED EAST - WEST CANAL SOUTH OF BUILDINGS H25 AND H26	2266
15	4/3/94	H	REMEDIATION OF GROUND IN ZONE OF FORMER BUILDING H25 (TYPICAL PIT CONTAINING HYDROCARBON CONTAMINANTS)	2267
16	4/3/94	H	REMEDIATION OF GROUND IN ZONE OF FORMER BUILDING H25 (NOTE: DARK COLOURED PIT CONTAINING HYDROCARBON CONTAMINANTS)	2268
17	4/3/94	H	REMEDIATION OF GROUND IN ZONE OF FORMER BUILDING H25 (NOTE: DARK COLOURED PIT CONTAINING HYDROCARBON CONTAMINANTS)	2269
18	4/3/94	H	REMEDIATION OF GROUND IN ZONE OF FORMER BUILDING H25 (NOTE: DARK COLOURED PIT CONTAINING HYDROCARBON CONTAMINANTS)	2270
19	4/3/94	M	BUILDING L157 - DRAINAGE IN BOILER ROOM (TYPICAL OUTLET WASTE PIPES)	2271
20	4/3/94	M	BUILDING L157 - DRAINAGE IN BOILER ROOM (TYPICAL OUTLET WASTE PIPES)	2272
21	4/3/94	M	BUILDING L157 - NORTH OFF BOILER HOUSE AREA (EXPOSURE FOR REMOVAL OF EXISTING EXTERNAL DRAINS)	2273
22	4/3/94	M	BUILDING L157 - NORTH OFF BOILER HOUSE AREA (EXPOSURE FOR REMOVAL OF EXISTING EXTERNAL DRAINS. NOTE: 'CLEAN' CUT OF PIPE EITHER SIDE OF SUSPECTED CONTAMINATED ZONE)	2274
23	4/3/94	M	BUILDING L157 - DRAINAGE REMOVAL (REMOTES OPERATED HYDRAULIC PIPE CUTTER)	2275
24	4/3/94	M	BUILDING L157 - DRAINAGE EXTERIOR VIEW LOOKING NORTH (TYPICAL EXTERNAL BACK INLET GULLEY ARRANGEMENT)	2276
R	4/3/94	M	BUILDING L157 - DRAINAGE EXTERIOR VIEW LOOKING NORTH (TYPICAL EXTERNAL BACK INLET TRAPPED GULLEY ARRANGEMENT)	2277

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: 80/1089

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1	9/3/94	M	BUILDING L157 - DRAIN REMOVAL	2278
2	9/3/94	M	BUILDING L157 - DRAIN REMOVAL	2279
3	9/3/94	M	BUILDING L157 - DRAIN REMOVAL (OPERATING HYDRAULIC PIPE CUTTER)	2280
4	9/3/94	M	BUILDING L157 - DRAIN REMOVAL	2281
5	9/3/94	M	BUILDING L157 - DRAIN REMOVAL (SETTING UP HYDRAULIC PIPE CUTTER))	2282
6	9/3/94	M	BUILDING L157 - DRAIN REMOVAL	2283
7	9/3/94	M	BUILDING L148 - INTERNAL VIEW (WALL CORING POINT CIRCLED IN YELLOW)	2284
8	9/3/94	M	BUILDING L148 - INTERNAL VIEW (WALL CORING POINT CIRCLED IN YELLOW)	2285
9	9/3/94	M	BUILDING L148 - INTERNAL VIEW (WALL CORING POINT CIRCLED IN YELLOW)	2286
10	9/3/94	M	BUILDING L148 - INTERNAL BLAST WALLS AT 'FIRING POINT'	2287
11	9/3/94	M	BUILDING L148 - INTERNAL BLAST WALLS AT 'FIRING POINT'	2288
12	9/3/94	M	BUILDING L148 - INTERNAL BLAST WALLS AT 'FIRING POINT'	2289
13	9/3/94	M	BUILDING L148 - INTERNAL BLAST WALLS AT 'FIRING POINT'	2290
14	9/3/94	M	BUILDING L148 - INTERNAL BLAST WALLS - PARTIALLY REMOVED	2291
15	9/3/94	M	BUILDING L148 - INTERNAL BLAST WALLS - PARTIALLY REMOVED	2292
16	9/3/94	M	BUILDING L148 - INTERNAL BLAST WALLS - PARTIALLY REMOVED	2293
17	9/3/94	M	BUILDING L148 - INTERNAL BLAST WALLS	2294
18	9/3/94	M	BUILDING L148 - FORMER ENGINE ROOM AREA (WALL CORING POINTS CIRCLED IN YELLOW)	2295
19	9/3/94	M	BUILDING L148 - FORMER ENGINE ROOM AREA	2296
20	9/3/94	M	BUILDING L148 - INTERNAL BLAST WALLS	2297
21	9/3/94	M	OWL FOUND IN BUILDING L148	2298
22	9/3/94	H	REMEDIATION OF SITE OF FORMER BUILDING H25 (NOTE: PITS CONTAINING HYDROCARBON CONTAMINANTS BEING REMOVED)	2299
23	9/3/94	H	REMEDIATION OF SITE OF FORMER BUILDING H25 (NOTE: PITS CONTAINING HYDROCARBON CONTAMINANTS BEING REMOVED)	2300
24	9/3/94	H	REMEDIATION OF SITE OF FORMER BUILDING H25	2301
25	9/3/94	H	REMEDIATION OF SITE OF FORMER BUILDING H25	2302
26	9/3/94	H	REMEDIATION OF SITE OF FORMER BUILDING H25	2303
27	9/3/94	H	SOUTH WALL OF EAST - WEST CANAL SOUTH OF BUILDINGS H25 & H26 - THE EDGE OF THE SCHEDULED ANCIENT MONUMENT	2304
28	9/3/94	H	EAST - WEST CANAL SOUTH OF BUILDINGS H25 & H26 - REFILLING	2305
29	9/3/94	H	EAST - WEST CANAL SOUTH OF BUILDINGS H25 & H26 - REFILLING	2306
30	9/3/94	H	H19 WASTE STOCKPILING AREA	2307
31	9/3/94	H	H19 WASTE STOCKPILING AREA	2308
32	10/3/94	H	REMEDIATION OF AREA BELOW FORMER BUILDING H25	2309
33	10/3/94	H	REMEDIATION OF AREA BELOW FORMER BUILDING H25	2310
34	10/3/94	H	REMEDIATION OF AREA BELOW FORMER BUILDING H25	2311
35	10/3/94	H	REMEDIATION OF AREA BELOW FORMER BUILDING H25	2312
36	10/3/94	H	REMEDIATION OF AREA BELOW FORMER BUILDING H25	2313
37	10/3/94	H	REMEDIATION OF AREA BELOW FORMER BUILDING H25	2314

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: 81/1086

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1	12/3/94	B	REMOTE CUTTING OF UNDERGROUND DRAINAGE PIPES FROM TETRYL FACTORY	2315
2	12/3/94	B	REMOTE CUTTING OF UNDERGROUND DRAINAGE PIPES FROM TETRYL FACTORY	2316
3	12/3/94	B	REMOTE CUTTING OF UNDERGROUND DRAINAGE PIPES FROM TETRYL FACTORY	2317
4	12/3/94	B	REMOTE CUTTING OF UNDERGROUND DRAINAGE PIPES FROM TETRYL FACTORY	2318
5	12/3/94	B	HOSING DOWN DRAINAGE PIPEWORK RETRIEVED FROM TETRYL FACTORY	2319
6	12/3/94	B	CONTAMINATED PIPEWORK CUT AND STACKED AWAITING 2ND STAGE	2320
7	12/3/94	B	CONTAMINATED PIPEWORK CUT AND STACKED AWAITING 2ND STAGE	2321
8	12/3/94	B	CONTAMINATED PIPEWORK CUT AND STACKED AWAITING 2ND STAGE	2322
9	12/3/94	B	CONTAMINATED PIPEWORK CUT AND STACKED AWAITING 2ND STAGE	2323
10	12/3/94	B	CONTAMINATED PIPEWORK CUT AND STACKED AWAITING 2ND STAGE	2324
11	12/3/94	B	CONTAMINATED PIPEWORK CUT AND STACKED AWAITING 2ND STAGE	2325
12	12/3/94	B	CONTAMINATED PIPEWORK CUT AND STACKED AWAITING 2ND STAGE	2326
13	12/3/94	B	CONTAMINATED PIPEWORK CUT AND STACKED AWAITING 2ND STAGE	2327
14	12/3/94	B	CONTAMINATED PIPEWORK CUT AND STACKED AWAITING 2ND STAGE	2328
15	12/3/94	B	CONTAMINATED PIPEWORK CUT AND STACKED AWAITING 2ND STAGE	2329
16	12/3/94	B	CONTAMINATED PIPEWORK CUT AND STACKED AWAITING 2ND STAGE	2330
17	12/3/94	B	CONTAMINATED PIPEWORK CUT AND STACKED AWAITING 2ND STAGE	2331
18	12/3/94	B	CONTAMINATED PIPEWORK CUT AND STACKED AWAITING 2ND STAGE	2332

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: 82/1767

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1	16/3/94	M	REMOVAL OF POTENTIALLY CONTAMINATED DRAINAGE AT BUILDING L157	2333
2	16/3/94	M	EXPOSED FOUL DRAIN, PRIOR TO DECONTAMINATION, ADJACENT BLDG L157	2334
3	16/3/94	M	EXPOSED FOUL DRAIN, PRIOR TO DECONTAMINATION, ADJACENT BLDG L157	2335
4	16/3/94	M	BREAKING OUT FWD MAN HOLE ADJACENT OT BUILDING L157	2336
5	16/3/94	M	FWD EXPOSED MAN HOLE ADJACENT OT BUILDING L157	2337
6	16/3/94	H	SITE OF FORMER BUILDING H25, REMOVAL OF HYDROCARBON CONTAMINATED GROUND, VIEWED FROM THE NORTH	2338
7	16/3/94	H	SITE OF FORMER BUILDING H25, REMOVAL OF HYDROCARBON CONTAMINATED GROUND, VIEWED FROM THE NORTH	2339
8	16/3/94	H	EXCAVATION OF EAST/WEST FILLED CANAL SOUTH OF BUILDING H25 AND H26	2340
9	16/3/94	H	EXCAVATION OF EAST/WEST FILLED CANAL SOUTH OF BUILDING H25 AND H26	2341
10	16/3/94	H	EXCAVATION OF EAST/WEST FILLED CANAL SOUTH OF BUILDING H25 AND H26	2342
11	16/3/94	H	H19 AREA DIFFICULTY GROUND CONDITIONS	2343
12	16/3/94	H	EXPOSING FOUNDATIONS TO BUILDING H31 (SEWER PUMPING STATION)	2344
13	16/3/94	H	EXPOSING FOUNDATIONS TO BUILDING H31 (SEWER PUMPING STATION)	2345
14	16/3/94	H	EXPOSING FOUNDATIONS TO BUILDING H31 (SEWER PUMPING STATION)	2346
15	18/3/94	H	ACOUSTIC WALL TO ABSORB PUMP NOISE	2347
16	18/3/94	H	CLEARANCE OF EAST/WEST CANAL SOUTH OF BUILDINGS H25 AND H26	2348
17	18/3/94	H	CLEARANCE OF EAST/WEST CANAL SOUTH OF BUILDINGS H25 AND H26	2349
18	18/3/94	H	HIGHBRIDGE STREET ENTRANCE - VIEW OF FIBREGLASS PETROL INTERCEPTOR UNIT	2350
19	18/3/94	H	CLEARANCE OF EAST/WEST CANAL SOUTH OF BUILDINGS H25 AND H26	2351
20	18/3/94	H	CLEARANCE OF EAST/WEST CANAL SOUTH OF BUILDINGS H25 AND H26	2352
21	18/3/94	H	EXCAVATION OF EAST/WEST FILLED CANAL SOUTH OF BLDGS H25 AND H26	2353
22	18/3/94	H	EXCAVATION OF EAST/WEST FILLED CANAL SOUTH OF BLDGS H25 AND H26	2354
23	18/3/94	H	EXCAVATION OF EAST/WEST FILLED CANAL SOUTH OF BLDGS H25 AND H26	2355
24	18/3/94	H	EXCAVATION OF EAST/WEST FILLED CANAL SOUTH OF BLDGS H25 AND H26	2356
25	18/3/94	H	EXCAVATION OF EAST/WEST FILLED CANAL SOUTH OF BLDGS H25 AND H26	2357
26	18/3/94	H	EXCAVATION OF EAST/WEST FILLED CANAL SOUTH OF BLDGS H25 AND H26	2358
27	18/3/94	H	EXCAVATION OF HYDROCARBON CONTAMINATED GROUND	2359
28	18/3/94	H	EXCAVATION OF HYDROCARBON CONTAMINATED GROUND	2360
29	19/3/94	H	EAST/WEST CANAL SOUTH OF BUILDINGS H25 AND H26 - RE-FILLING IN PROGRESS WITH IMPORTED MATERIAL VIEWED FROM THE SOUTH	2361
30	19/3/94	H	EAST/WEST CANAL SOUTH OF BUILDINGS H25 AND H26	2362
31	21/3/94	H	EAST/WEST CANAL SOUTH OF BUILDINGS H25 AND H26	2363
32	21/3/94	H	EAST/WEST CANAL SOUTH OF BUILDINGS H25 AND H26	2364
33	21/3/94	H	EAST/WEST CANAL SOUTH OF BUILDINGS H25 AND H26	2365
34	21/3/94	H	EAST/WEST CANAL SOUTH OF BUILDINGS H25 AND H26	2366
35	23/3/94	M	BUILDING L157 - GULLEY 17 MERCURY FOUND WHILST REMOVING DRAIN	2367
36	23/3/94	M	BUILDING L157 - GULLEY 17 MERCURY FOUND WHILST REMOVING DRAIN	2368
R	23/3/94	M	BUILDING L157 - GULLEY 17 MERCURY FOUND WHILST REMOVING DRAIN	2369

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: 83/1771

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1	23/3/94	M	BUILDING L157 - DRAINS REMOVAL	2370
2	23/3/94	M	BUILDING L157 - DRAINS REMOVAL	2371
3	23/3/94	M	BUILDING L157 - DRAINS REMOVAL	2372
4	23/3/94	M	BUILDING L157 - DRAINS REMOVAL	2373
5	23/3/94	M	BUILDING L157 - DRAINS REMOVAL	2374
6	23/3/94	M	BUILDING L157 - DRAINS REMOVAL	2375
7	23/3/94	B	CONTAINER LINED OUT TO RECEIVE ASBESTOS CONTAMINATED SOIL FROM DUMP SITUATED EAST OF BURNING GROUND	2376
8	25/3/94	B	LOADING ASBESTOS CONTAMINATED SOIL EAST OF BURNING GROUND	2377
9	26/3/94	N	SUSPECT PIT SOUTH OF BUILDING S43	2378
10	26/3/94	N	SUSPECT PIT SOUTH OF BUILDING S43	2379
11	26/3/94	N	SUSPECT PIT SOUTH OF BUILDING S43	2380
12	26/3/94	N	SUSPECT PITS SOUTH OF BUILDING S43	2381
13	26/3/94	N	SUSPECT PITS SOUTH OF BUILDING S43	2382
14	26/3/94	N	SUSPECT PITS SOUTH OF BUILDING S43 - SCRAP METAL RETRIEVED	2383
15	26/3/94		TOP SOIL IN AREA SOUTH OF BUILDING S13	2384
16	26/3/94	S	S30 - CANAL CLEARING - VIEW LOOKING WEST	2385
17	26/3/94	S	S30/S90 - CANAL CLEARANCE - VIEW LOOKING NORTH	2386
18	26/3/94	B	CUT PIPES FROM TETRYL FACTORY SET FOR 'HEAT TREATMENT'	2387
19	26/3/94	B	CUT PIPES FROM TETRYL FACTORY SET FOR 'HEAT TREATMENT'	2388
20	26/3/94	B	CUT PIPES FROM TETRYL FACTORY SET FOR 'HEAT TREATMENT'	2389
21	26/3/94	H	HYDROCARBON CONTAMINATED AREA - AFTER REMOVAL OF CONTAMINATED GROUND	2390
22	26/3/94	H	HYDROCARBON CONTAMINATED AREA - AFTER REMOVAL OF CONTAMINATED GROUND	2391
23	26/3/94	H	HYDROCARBON CONTAMINATED AREA - AFTER REMOVAL OF CONTAMINATED GROUND	2392
24			NOT USED	
25			NOT USED	
26	28/3/94	H	ADJACENT TO HOPPIT POOL - MALE MANDARIN DUCK	2393
27	28/3/94	H	ADJACENT TO HOPPIT POOL - MALE MANDARIN DUCK	2394
28	28/3/94	H	ADJACENT TO HOPPIT POOL - FEMALE MALLARD DUCK	2395
29	29/3/94	M	BUILDING L145 - ROOF VENT TERMINALS	2396
30	29/3/94	M	BUILDING L148 - ROOF VENT TERMINALS	2397
31	29/3/94	M	BUILDING L153 - EXTRACT VENT WALL GRILLE	2398
32	29/3/94	M	BUILDING L149 - ROOF VENT PIPE TERMINALS	2399
33	29/3/94	M	BUILDING L157 - LOUVERED VENT	2400
34	29/3/94	M	BUILDING L157 - VENT PPE TERMINALS	2401
35	29/3/94	M	BUILDING L157 - EXTRACT VENT TERMINAL AND MOTOR	2402
36	29/3/94	M	BUILDING L157 - EAST ELEVATION	2403
R	29/3/94	M	BUILDING L153 - EAST ELEVATION	2404

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: 84/2475

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1	29/3/94	H	RE-FILLING OF CLEANED OUT EAST/WEST CANAL SOUTH OF BLDGS H25 & H26	2405
2	29/3/94	H	RE-FILLING OF CLEANED OUT EAST/WEST CANAL SOUTH OF BLDGS H25 & H26	2406
3	29/3/94	H	RE-FILLING OF CLEANED OUT EAST/WEST CANAL SOUTH OF BLDGS H25 & H26	2407
4	29/3/94	H	RE-FILLING OF CLEANED OUT EAST/WEST CANAL SOUTH OF BLDGS H25 & H26	2408
5	31/3/94	H	H68 - TYPICAL RUBBLE FILLED PIT	2409
6	31/3/94	H	PETROL INTERCEPTOR - POCKETS FOR ANCHOR POINTS	2410
7	31/3/94	H	PETROL INTERCEPTOR - ANCHOR POINTS CAST IN CONCRETE	2411
8	5/4/94	P	BUILDING A221 - DAMAGE TO GARDEN LANTERN	2412
9	5/4/94	P	BUILDING A221 - DAMAGE TO GARDEN LANTERN	2413
10	7/4/94	M	BUILDING L157 - REMOVAL OF POTENTIALLY CONTAMINATED FW DRAINAGE	2414
11	7/4/94	M	BUILDING L157 - REMOVAL OF POTENTIALLY CONTAMINATED FW DRAINAGE	2415
12	7/4/94	M	BUILDING L157 - REMOVAL OF POTENTIALLY CONTAMINATED FW DRAINAGE	2416
13	7/4/94	M	BUILDING L157 - 'SINGLE SIZED STONE' IMPORTED FOR DRAIN EXCAVATION BACKFILL	2417
14	7/4/94	H	PETROL INTERCEPTOR PRIOR TO BACKFILL	2418
15	7/4/94	H	H19 AREA - ORGANISING STOCKPILED WASTE	2419
16	7/4/94	H	H16 AREA - STOCKPILING WASTE	2420
17	7/4/94	M	BLDG L157 - BACKFILLING OF TRENCHING AFTER REMOVAL OF FW DRAINAGE	2421
18	7/4/94	M	BLDG L157 - BACKFILLING OF TRENCHING AFTER REMOVAL OF FW DRAINAGE	2422
19	7/4/94	H	H16 AREA - LOADING AWAY ACCUMULATED WASTE	2423
20	7/4/94	M	BLDG L157 - BACKFILLING OF TRENCHING AFTER REMOVAL OF FW DRAINAGE	2424
21	7/4/94	H	PETROL INTERCEPTOR BACKFILLING	2425
22	7/4/94	H	PETROL INTERCEPTOR BACKFILLING	2426
23	7/4/94	H	H19 - ROYAL ORDNANCE SITE MANAGER SIZING UP WASTE STOCKPILE!	2427
24	7/4/94	M	BLDG L157 - BACKFILLING OF TRENCHING AFTER REMOVAL OF FW DRAINAGE	2428
25	7/4/94	M	BLDG L157 - BACKFILLING OF TRENCHING AFTER REMOVAL OF FW DRAINAGE	2429
26	7/4/94	H	PETROL INTERCEPTOR BACKFILLING	2430
27	12/4/94	S	BUILDING S90 - SCAFFOLD BRIDGE ACROSS CANAL FOR ACCESS TO BUILDING	2431
28	12/4/94	S	BUILDING S90 - SCAFFOLD BRIDGE ACROSS CANAL (S90 - EXTERNAL SCAFFOLD N PLACE FOR ROOF CLEARANCE AND INSPECTION)	2432
29	12/4/94	H	H16 - FLOODED AREA LOOKING NORTH (POOR WEATHER AND GROUND CONDITIONS. BUILDING H10 IN BACKGROUND)	2433
30	12/4/94	H	H16 - FLOODED AREA (DRAINAGE IN PROGRESS)	2434
31	12/4/94	H	H16 - FLOODED AREA (DIFFICULT GROUND CONDITIONS)	2435
32	12/4/94	H	H12 - FLOODED AREA (BUILDING A201/2 IN BACKGROUND)	2436
33	12/4/94	H	H12 - FLOODED AREA (BRIDGE No. 17 IN BACKGROUND)	2437
34	12/4/94	H	H16 - FLOODED AREA (SETTING OUT TEMPORARY LAND DRAINS)	2438
35	12/4/94	H	FLOODED AREA (BUILDING H17 IN BACKGROUND)	2439
36	12/4/94	H	SOIL STRIP PRIOR TO REMOVAL OF 'OLD MILLHEAD STREAM' INFILL	2440
R	12/4/94	H	SOIL STRIP PRIOR TO REMOVAL OF 'OLD MILLHEAD STREAM' INFILL	2441

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: 85/4094

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1	12/4/94	S	BLACK DUCK WITH BROKEN LEG	2442
2	12/4/94	S	BLACK DUCK WITH BROKEN LEG	2443
3	13/4/94	P	BT CABLE TRENCH EXCAVATION - POWDERMILL LANE	2444
4	13/4/94	P	BT CABLE TRENCH EXCAVATION - POWDERMILL LANE	2445
5	13/4/94	H	BURIED STRUCTURE / PIT ADJACENT WEST ABUTMENT OF BRIDGE No. 17	2446
6	13/4/94	H	BURIED STRUCTURE / PIT ADJACENT WEST ABUTMENT OF BRIDGE No. 17	2447
7	13/4/94	H	BURIED STRUCTURE / PIT ADJACENT WEST ABUTMENT OF BRIDGE No. 17	2448
8	15/4/94	S	TREE WEST OF BUILDING L190 - BLOWN OVER IN HIGH WINDS	2449
9	15/4/94	S	TREE WEST OF BUILDING L190 - BLOWN OVER IN HIGH WINDS	2450
10	15/4/94	T	VIEW OF SUSPECTED TETRYL FOUND ON FORMER TETRYL FACTORY SITE	2451
11	15/4/94	S	TREE WEST OF BUILDING L190 - BLOWN OVER IN HIGH WINDS	2452
12	15/4/94	S	EGG FOUND IN BUILDING 14 (UNUSUAL BECAUSE OF ITS LARGE SIZE)	2453
13	25/4/94	P	REMOVAL OF UNDERGROUND FUEL STORAGE TANKS ADJACENT BLDG A219	2454
14	25/4/94	P	REMOVAL OF UNDERGROUND FUEL STORAGE TANKS ADJACENT BLDG A219	2455
15	25/4/94	P	REMOVAL OF UNDERGROUND FUEL STORAGE TANKS ADJACENT BLDG A219	2456
16	25/4/94	P	REMOVAL OF UNDERGROUND FUEL STORAGE TANKS ADJACENT BLDG A219	2457
17	25/4/94	P	REMOVAL OF UNDERGROUND FUEL STORAGE TANKS ADJACENT BLDG A219	2458
18	25/4/94	P	REMOVAL OF UNDERGROUND FUEL STORAGE TANKS ADJACENT BLDG A219	2459
19	25/4/94	P	REMOVAL OF UNDERGROUND FUEL STORAGE TANKS ADJACENT BLDG A219	2460
20	26/4/94	H	H16 AREA - STOCKPILING OF 'SPECIAL WASTE'	2461
21	26/4/94	H	CANAL EXCAVATION NORTH OF BUILDING A201/2	2462
22	26/4/94	H	H16 AREA - STOCKPILING OF 'SPECIAL WASTE' AND LOADING AWAY	2463
23	27/4/94	M	BUILDING L157 - FWD REMOVAL ORIGINAL TRENCH LINE INDICATED BY SHEET PILING INDENTATIONS	2464
24	27/4/94	M	BUILDING L157 - FWD REMOVAL ORIGINAL TRENCH LINE INDICATED BY SHEET PILING INDENTATIONS	2465
25	29/4/94	H	EXCAVATION OF CANAL DISCHARGING INTO HOPPIT POOL	2466
26	29/4/94	H	EXCAVATION OF CANAL DISCHARGING INTO HOPPIT POOL	2467
27	29/4/94	H	EXCAVATION OF CANAL DISCHARGING INTO HOPPIT POOL	2468
28	29/4/94	S	SEMI PERMANENT FENCE NORTH OF BUILDING 83B AT CANAL CROSS OVER	2469
29	29/4/94	S	HARDCORED ROAD FROM NEWTONS POOL	2470
30	29/4/94	S	BUILDING S90 ROOF BEFORE STRIP OFF	2471
31	29/4/94	S	BUILDING S90 ROOF BEFORE STRIP OFF	2472
32	3/5/94	H	HYDROCARBON CONTAMINATED AREA NORTH OF FORMER BUILDING H25	2473
33	3/5/94	H	BUILDING H8 - BREAKING OUT OF ENTRANCE RETAINING WALLS IN MOUND	2474
34	3/5/94	P	FINAL CLEAR UP OF EXCAVATION FOLLOWING REMOVAL OF BURIED FUEL STORAGE TANKS ADJACENT TO FORMER BUILDING A219	2475
35	3/5/94	S	CLEARANCE OF CONTAMINATED GROUND EAST OF FORMER TETRYL FACTORY	2476
36			NOT USED	
R			NOT USED	

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: 86/4835

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1	6/5/94	H	TIMBER LINED PIT LOCATED AT FORMER SITE OF BUILDING H25	2477
2	9/5/94	T	EXPOSURE OF BURIED REMAINS TO FORMER GUNPOWDER DRYING STOVE	2478
3	9/5/94	T	LOOKING SOUTH EAST ACROSS FORMER TETRYL FACTORY SITE	2479
4	9/5/94	T	EXPOSURE OF BURIED REMAINS TO FORMER GUNPOWDER DRYING STOVE	2480
5	9/5/94	S	RESIDENT FOX	2481
6	9/5/94	S	RESIDENT FOX	2482
7	9/5/94	S	RESIDENT FOX	2483
8	9/5/94	S	RESIDENT FOX	2484
9	9/5/94	S	RE-EXCAVATED FILLED BORROW PIT WEST OF BUILDING E2	2485
10	9/5/94	M	SOUTH EAST CORNER OF BLDG L157 - BACKFILLING TO FORMER FWD TRENCH	2486
11	9/5/94	M	FWD MANHOLE NORTH OF PUMPING CHAMBER (L170) REMOVED	2487
12	9/5/94	M	BUILDING L157 - CORRIDOR PREPARATION BEFORE GRIT BLASTING	2488
13	9/5/94	M	BUILDING L157 - CORRIDOR PREPARATION BEFORE GRIT BLASTING	2489
14	9/5/94	H	PUMPING GROUND WATER INGRESS FROM HYDROCARBON CONTAMINATED AREA WEST OF BUILDING H26	2490
15	9/5/94	H	PUMPING GROUND WATER INGRESS FROM HYDROCARBON CONTAMINATED AREA WEST OF BUILDING H26	2491
16	9/5/94	H	PUMPING GROUND WATER INGRESS FROM HYDROCARBON CONTAMINATED AREA WEST OF BUILDING H26	2492
17	9/5/94	H	PUMPING GROUND WATER INGRESS FROM HYDROCARBON CONTAMINATED AREA WEST OF BUILDING H26	2493
18	9/5/94	H	FILLED CANAL EXCAVATION - HOPPIT ROAD TO H67 - LOOKING NORTH	2494
19	9/5/94	H	FILLED CANAL EXCAVATION - HOPPIT ROAD TO H67 - LOOKING NORTH	2495
20	9/5/94	H	FILLED CANAL EXCAVATION - HOPPIT ROAD TO H67 - LOOKING SOUTH	2496
21	9/5/94	H	FILLED CANAL EXCAVATION - HOPPIT ROAD TO H67 - LOOKING EAST	2497
22	9/5/94	H	FILLED CANAL EXCAVATION - HOPPIT ROAD TO H67 - LOOKING NORTH EAST	2498
23	9/5/94	H	FILLED CANAL EXCAVATION - HOPPIT ROAD TO H67 - LOOKING NORTH EAST	2499
24	13/5/94	T	ADJACENT BUILDING E2 - SUSPECTED TNT FIND (SAMPLE PEGS IN POSITION)	2500
25	13/5/94	H	REMOVAL OF BUILDING H31 - PUMPING STATION FOUNDATIONS	2501
26	13/5/94	H	REMOVAL OF BLDG H31 - PUMPING STATION FOUNDATIONS - LOOKING SOUTH	2502
27	13/5/94	H	REMOVAL OF BLDG H31 - PUMPING STATION FOUNDATIONS - LOOKING SOUTH	2503
28	13/5/94	H	HYDROCARBON CONTAMINATED AREA NORTH OF BUILDING H25 LAYING LAND DRAINAGE	2504
29	13/5/94	H	HYDROCARBON CONTAMINATED AREA NORTH OF BUILDING H25 LAYING LAND DRAINAGE - LOOKING NORTH WEST	2505
30	16/5/94	H	12 TONNE DUMP TRUCK STUCK IN DIFFICULT CONDITIONS	2506
31	16/5/94	H	12 TONNE DUMP TRUCK STUCK IN DIFFICULT CONDITIONS	2507
32	16/5/94	S	BUILDING S90 - ROOF CLEARED OF UNDERGROWTH	2508
33	16/5/94	S	BUILDING S90 - ROOF CLEARED OF UNDERGROWTH	2509
34	18/5/94	H	H31 - BACKFILLING AFTER REMOVAL OF PUMPING CHAMBER	2510
35	18/5/94	H	H31 - BACKFILLING AFTER REMOVAL OF PUMPING CHAMBER	2511
36	18/5/94	H	H31 - BACKFILLING AFTER REMOVAL OF PUMPING CHAMBER	2512

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: 87/1042

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1			NOT USED	
2	18/5/94	H	H16 AREA-GENERAL ACTIVITIES: STOCKPILING WASTE AND INFILLING H31 PIT	2513
3	18/5/94	H	H16 AREA - SURFACE SCRAPING TO REMOVE CONTAMINATED GROUND	2514
4	18/5/94	H	H16 AREA - SURFACE SCRAPING TO REMOVE CONTAMINATED GROUND	2515
5	18/5/94	M	SOUTH OF BUILDING L157 - FWD - PRESSURE GROUTING	2516
6	18/5/94	M	BLDG L157 - PAINT SPRAYING OF GRIT BLASTED STRUCTURAL STEELWORK	2517
7	18/5/94	M	SOUTH OF BUILDING L157 - FWD - PRESSURE GROUTING	2518
8	18/5/94	M	SOUTH OF BUILDING L157 - FWD - PRESSURE GROUTING	2519
9			NOT USED	
10			NOT USED	
11	25/5/94	H	SOIL STRIPPING AREA 'H' (DIFFICULT GROUND CONDITIONS)	2520
12	25/5/94	H	H13 EXCAVATION BACKFILLED	2521
13	25/5/94	H	WATER PIPE REPAIR - SOUTH OF H31	2522
14	25/5/94	H	BACKFILLING OF REMEDIATED HYDROCARBON CONTAMINATED AREA	2523
15	25/5/94	H	BACKFILLING OF REMEDIATED HYDROCARBON CONTAMINATED AREA	2524
16	25/5/94	H	BACKFILLING OF REMEDIATED HYDROCARBON CONTAMINATED AREA	2525
17	25/5/94	H	BACKFILLING OF REMEDIATED HYDROCARBON CONTAMINATED AREA	2526
18	25/5/94	P	SOIL STRIPPING AREA 'P' NORTH - LOOKING EAST	2527
19	25/5/94	P	SOIL STRIPPING AREA 'P' NORTH - LOOKING WEST	2528
20	25/5/94	P	AREA 'P' NORTH - EXCAVATION OF FILLED CANAL LOOKING TOWARDS POWDERMILL LANE SITE ENTRANCE	2529
21			NOT USED	
22	25/5/94	M	L169 - LOADING AWAY STOCKPILED WASTE	2530
23	25/5/94	M	BUILDING L157 - GRIT BLASTING OF STRUCTURAL STEELWORK	2531
24	25/5/94	M	BLDG L157- BAY PREPARED FOR GRIT BLASTING OF STRUCTURAL STEELWORK	2532
25	25/5/94	M	BUILDING L157 - REMEDIATION INTERNALLY ALMOST COMPLETE	2533
26	25/5/94	M	BUILDING L157 - INTERNAL REMEDIATION IN PROGRESS	2534
27	27/5/94	N	CLAY WINNING IN PROGRESS FOR INFILL OF EXCAVATIONS IN AREA 'H'	2535
28	27/5/94	N	CLAY WINNING IN PROGRESS FOR INFILL OF EXCAVATIONS IN AREA 'H'	2536
29	1/6/94	P	AREA 'P' NORTH - FOUNDATIONS TO FORMER BLDG, SOUTH OF BLDG A219	2537
30	1/6/94	P	AREA 'P' NORTH - FOUNDATIONS TO FORMER BLDG, SOUTH OF BLDG A219	2538
31	1/6/94	P	AREA 'P' NORTH - FOUNDATIONS TO FORMER BLDG, SOUTH OF BLDG A219	2539
32	2/6/94	M	BUILDING L157 - FWD - 'REMOTE' CUTTING OF POTENTIALLY CONTAMINATED PIPEWORK	2540
33	2/6/94	M	BUILDING L157 - FWD - 'REMOTE' CUTTING OF POTENTIALLY CONTAMINATED PIPEWORK	2541
34	2/6/94	P	BREAKING UP FOUNDATIONS TO FORMER BUILDING SOUTH OF BUILDING A219	2542
35	2/6/94	H	INFILL TO FORMER HYDROCARBON CONTAMINATED AREA NORTH BLDG H25	2543
36	2/6/94	H	INFILL TO FORMER HYDROCARBON CONTAMINATED AREA NORTH BLDG H25	2544
R	2/6/94	H	INFILL TO FORMER HYDROCARBON CONTAMINATED AREA NORTH BLDG H25	2545

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: 88/1040

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1	3/6/94	H	HYDROCARBON CONTAMINATED AREA REMEDIATED - CLAY FILLING	2546
2	3/6/94	H	HYDROCARBON CONTAMINATED AREA REMEDIATED - CLAY FILLING	2547
3	3/6/94	H	HYDROCARBON CONTAMINATED AREA REMEDIATED - CLAY FILLING	2548
4	7/6/94	H	HYDROCARBON CONTAMINATED AREA REMEDIATED - CLAY FILLING	2549
5	7/6/94	H	HYDROCARBON CONTAMINATED AREA REMEDIATED - CLAY FILLING	2550
6	7/6/94	H	HYDROCARBON CONTAMINATED AREA REMEDIATED - CLAY FILLING	2551
7			NOT USED	
8	7/6/94	H	HYDROCARBON CONTAMINATED AREA REMEDIATED - CLAY FILLING	2552
9	7/6/94	H	HYDROCARBON CONTAMINATED AREA REMEDIATED - CLAY FILLING	2553
10	7/6/94	H	HYDROCARBON CONTAMINATED AREA REMEDIATED - CLAY FILLING	2554
11	7/6/94	H	STOCKPILE OF HYDROCARBON CONTAMINATED WASTE AND BAGGED WASTE BLAST GRIT FROM BUILDING L157 / L153 WORKS	2555
12	7/6/94	H	STOCKPILE - 'SPECIAL WASTE'	2556
13	8/6/94	H	HYDROCARBON CONTAMINATED AREA REMEDIATED - CLAY FILLING	2557
14	8/6/94	H	HYDROCARBON CONTAMINATED AREA REMEDIATED - CLAY FILLING	2558
15	8/6/94	H	HYDROCARBON CONTAMINATED AREA REMEDIATED - CLAY FILLING	2559
16	8/6/94	S	CANAL EXCAVATION TO BUILDING L105 LOOKING NORTH	2560
17	8/6/94	S	CANAL EXCAVATION ADJACENT TO BUILDING L105 LOOKING SOUTH	2561
18	8/6/94	S	EAST/WEST CANAL NORTH OF BUILDING E2 - CLEARANCE IN PROGRESS LOOKING WEST	2562
19	8/6/94	S	EAST/WEST CANAL NORTH OF BUILDING E2 - CLEARANCE IN PROGRESS LOOKING EAST	2563
20	8/6/94	S	CANAL CLEARANCE WEST OF BUILDING S34 (NEWTONS POOL IN BACKGROUND)	2564
21	8/6/94	P	TEMPORARY CLAY DAM (TO HOLD BACK CONTAMINATED FILL)	2565
22	8/6/94	P	SURFACE STRIPPING TO REMOVE CONTAMINATED GROUND	2566
23	8/6/94	P	SURFACE STRIPPING TO REMOVE CONTAMINATED GROUND	2567
24	9/6/94	H	TIMBER LINED PIT EAST OF H16	2568
25	9/6/94	H	TIMBER LINED PIT EAST OF H16	2569
26			NOT USED	
27	9/6/94	H	PUDDLE CLAY PLACEMENT WEST OF BUILDING H26	2570
28	9/6/94	H	H67 - WASTE FROM CANAL NORTH OF AREA 'T'	2571
29	9/6/94	M	BLDG L153 - MERCURY AND GREEN DEPOSIT WITHIN EXTERNAL GULLY POT	2572
30			NOT USED	
31	9/6/94	M	BLDG L153 -MERCURY AND GREEN DEPOSIT ADJACENT EXTERNAL GULLY POT	2573
32	9/6/94	M	BLDG L153 -MERCURY AND GREEN DEPOSIT ADJACENT EXTERNAL GULLY POT	2574
33	9/6/94	M	BUILDING L153 - REMOVAL OF POTENTIALLY CONTAMINATED FWD'S	2575
34			NOT USED	
35	10/6/94	H	HYDROCARBON CONTAMINATED AREA REMEDIATED - CLAY FILLING	2576
36	10/6/94	H	HYDROCARBON CONTAMINATED AREA REMEDIATED - CLAY FILLING	2577

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: 89/2596

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1	13/6/94	P	BACKFILLING CLEANED EAST/WEST CANAL PARALLEL WITH FLAGSTAFF RD	2578
2	13/6/94	P	BACKFILLING CLEANED EAST/WEST CANAL PARALLEL WITH FLAGSTAFF RD	2579
3	13/6/94	P	BACKFILLING CLEANED EAST/WEST CANAL PARALLEL WITH FLAGSTAFF RD	2580
4	13/6/94	H	FILLING OF REMEDIATED HYDROCARBON CONTAMINATED AREA	2581
5	13/6/94	H	FILLING OF REMEDIATED HYDROCARBON CONTAMINATED AREA	2582
6	13/6/94	H	FILLING OF REMEDIATED HYDROCARBON CONTAMINATED AREA	2583
7	13/6/94	H	FILLING OF REMEDIATED HYDROCARBON CONTAMINATED AREA	2584
8	15/6/94	S	REMOVAL OF 'TIPPED' WASTE FROM AROUND TREES ADJACENT TO EDMONSEY SLUICE	2585
9	15/6/94	S	REMOVAL OF 'TIPPED' WASTE FROM AROUND TREES ADJACENT TO EDMONSEY SLUICE	2586
10	16/6/94	P	BRIDGE No. 31 - REMOVAL	2587
11	16/6/94	P	BRIDGE No. 31 - REMOVAL	2588
12	16/6/94	P	BRIDGE No. 31 - REMOVAL	2589
13	16/6/94	P	BRIDGE No. 31 - REMOVAL	2590
14	16/6/94	P	BRIDGE No. 31 - REMOVAL	2591
15	16/6/94	P	BRIDGE No. 31 - REMOVAL	2592
16	16/6/94	P	BRIDGE No. 11 - REMOVAL	2593
17	16/6/94	P	BRIDGE No. 11 - REMOVAL	2594
18	16/6/94	P	BRIDGE No. 11 - REMOVAL	2595
19	16/6/94	H	REMOVAL OF HYDROCARBON CONTAMINATED GROUND WEST OF BLDG H26	2596
20	16/6/94	H	REMOVAL OF HYDROCARBON CONTAMINATED GROUND WEST OF BLDG H26	2597
21	16/6/94	H	REMOVAL OF HYDROCARBON CONTAMINATED GROUND WEST OF BLDG H26	2598
22	16/6/94	H	REMOVAL OF HYDROCARBON CONTAMINATED GROUND WEST OF BLDG H26	2599
23	21/6/94	P	SHEET PILING AT BRIDGE No. 1 - CANAL INTERSECTION POINT No. 4	2600
24	21/6/94	P	SHEET PILING AT BRIDGE No. 1 - CANAL INTERSECTION POINT No. 4	2601
25	21/6/94	P	SHEET PILING AT BRIDGE No. 1 - CANAL INTERSECTION POINT No. 4	2602
26	21/6/94	P	SHEET PILING AT BRIDGE No. 1 - CANAL INTERSECTION POINT No. 4	2603
27	21/6/94	P	SHEET PILING AT BRIDGE No. 1 - CANAL INTERSECTION POINT No. 4	2604
28	21/6/94	P	SHEET PILING AT BRIDGE No. 1 - CANAL INTERSECTION POINT No. 4	2605
29	21/6/94	S	REMEDICATION OF FILLED BORROW PITS WEST OF BUILDING E2	2606
30	21/6/94	S	REMEDICATION OF FILLED BORROW PITS WEST OF BUILDING E2	2607
31	21/6/94	H	CONSTRUCTION COMMENCEMENT FOR BLOCK PAVED ROADWAY OVER REMEDIATED AREA - LOOKING SOUTH	2608
32	21/6/94	H	CONSTRUCTION COMMENCEMENT FOR BLOCK PAVED ROADWAY OVER REMEDIATED AREA - LOOKING NORTH	2609
33	22/6/94	P	SHEET PILING AT BRIDGE No. 1 - COMPLETE AND CANAL INTERSECTION No. 4	2610
34	22/6/94	P	REMOVAL OF CONTAMINATED GROUND LOOKING WEST	2611
35	22/6/94	S	DUMPED WASTE REMOVED FROM AROUND TREES ADJACENT EDMONSEY SLUICE	2612

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDICATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: 90/2598

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1			NOT USED	
2	23/6/94	H	SUB BASE CONSTRUCTION FOR BLOCK PAVED ROADWAY WEST OF BUILDING H26	2613
3	23/6/94	S	SHEET PILING ADJACENT TO BUILDING S90	2614
4	23/6/94	S	SHEET PILING BY BUILDING S90	2615
5			NOT USED	
6			NOT USED	
7			NOT USED	
8			NOT USED	
9	24/6/94	M	BUILDING L153 - REMOVAL OF FWD'S	2616
10	24/6/94	M	BUILDING L153 - REMOVAL OF FWD'S	2617
11	24/6/94	S	SHEET PILING BY BUILDING S90	2618
12	24/6/94	S	SHEET PILING BY BUILDING S90	2619
13	24/6/94	S	SHEET PILING BY BUILDING S90	2620
14			NOT USED	
15	28/6/94	P	INSPECTION OF NORTH EAST ABUTMENT TO BRIDGE No. 1	2621
16	28/6/94	H	ROAD CONSTRUCTION WEST OF BUILDING H26	2622
17	28/6/94	H	ROAD CONSTRUCTION WEST OF BUILDING H26	2623
18	28/6/94	S	EDMONSEY SLUICE - EXPOSED TREE ROOTS AFTER REMOVAL OF TIPPED WASTE	2624
19	28/6/94	T	GENERAL VIEW NORTHWARDS ACROSS AREA 'T'	2625
20	28/6/94	T	GENERAL VIEW NORTHWARDS ACROSS AREA 'T'	2626
21	28/6/94	S	CANAL CLEARANCE FROM BUILDING S34 WESTWARDS	2627
22	28/6/94	S	SHEET PILING BY BUILDING S90	2628
23			NOT USED	
24	28/6/94	P	RE-FILLING OF AREA SOUTH OF BUILDING A221	2629
25	30/6/94	H	VEHICLE WASHDOWN AREA UNDER CONSTRUCTION (LAYING OF DRAINAGE CHANNEL)	2630
26	30/6/94	H	CONSTRUCTION OF ROADWAY WEST OF BUILDING H26	2631
27	30/6/94	M	CANAL CLEARANCE IN PROGRESS VIEWED FROM BUILDING L136 NORTHWARDS	2632
28	30/6/94	M	CANAL CLEARANCE BETWEEN BUILDINGS L109 AND L108 (L108 IN SHOT)	2633
29	30/6/94	M	CANAL CLEARANCE LOOKING SOUTHWARDS TOWARDS BUILDING L136	2634
30	30/6/94	P	BUILDING A210 - CHECKING CONTINUITY OF ROOF STRUCTURE	2635
31	30/6/94	P	CANAL CLEARANCE AT INTERSECTION No. 4	2636
32	30/6/94	P	CANAL CLEARANCE AT INTERSECTION No. 4	2637
33	30/6/94	P	CANAL CLEARANCE AT INTERSECTION No. 4	2638
34	30/6/94	P	CONSTRUCTION OF NEW ENTRANCE ROAD (POWDERMILL LANE)	2639
35	30/6/94	P	CONSTRUCTION OF NEW ENTRANCE ROAD (POWDERMILL LANE)	2640
36	30/6/94	P	CANAL CLEARANCE AT INTERSECTION No. 4	2641

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: 91/3740

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1	30/6/94	S	CANAL CLEARANCE SOUTH OF THE GRAND MAGAZINE	2642
2	30/6/94	S	SHEET PILING BY BUILDING S90 COMPLETE	2643
3			NOT USED	
4	1/7/94	P	TYPICAL SAMPLING POINT IN CLEARED CANAL	2644
5	1/7/94	P	CULVERT AT EAST END OF CLEARED CANAL ADJACENT TO POWDERMILL LANE ENTRANCE	2645
6	5/7/94	T	CONSTRUCTION OF NEW TEMPORARY ROAD ACROSS REMEDIATED GROUND	2646
7	5/7/94	P	CONSTRUCTION OF NEW CAR PARK AT POWDERMILL LANE ENTRANCE	2647
8	5/7/94	H	CONSTRUCTION OF NEW ACCESS ROAD WEST OF BUILDING H26	2648
9	5/7/94	H	VEHICLE WASHDOWN AREA CONSTRUCTION OF DRAINAGE CHANNEL	2649
10	6/7/94	P	CONSTRUCTION OF NEW CAR PARK AT POWDERMILL LANE ENTRANCE	2650
11	6/7/94	H	BUILDING A203 - TABLE LAID FOR SPECIAL VISITORS ON 7/7/94	2651
12	11/7/94	P	ARTIST AT WORK	2652
13	11/7/94	P	BUILDING A210 - INSPECTION OF GUTTERING (VALLEY)	2653
14	11/7/94	H	CONSTRUCTION OF VEHICLE WASHDOWN AREA	2654
15	11/7/94	H	ROAD CONSTRUCTION WEST OF BUILDING H26	2655
16			NOT USED	
17			NOT USED	
18			NOT USED	
19			NOT USED	
20			NOT USED	
21			NOT USED	
22	12/7/94	P	ARTIST AT WORK	2656
23	13/7/94	P	BRICK CULVERT AT POWDERMILL LANE ENTRANCE - PLUGGED WITH CONCRETE	2657
24	13/7/94	H	CONCRETE MANHOLE BETWEEN H10 AND H17	2658
25	13/7/94	H	H16 SLAB - BREAKING FOR REMOVAL	2659
26	13/7/94	H	H16 SLAB - BREAKING FOR REMOVAL	2660
27	13/7/94	H	BLOCK PAVING TO ROAD WEST OF BUILDING H26	2661
28	13/7/94	H	BUILDING H10 - ASBESTOS REMOVAL IN PROGRESS	2662
29	13/7/94	S	BRIDGE No. 10 - EXCAVATED ROAD LEADING TO BRIDGE (SOUTH SIDE)	2663
30	13/7/94	S	VIEW OF EXCAVATED ROAD FROM BRIDGE No. 10 LOOKING SOUTH	2664
31	15/7/94	H	BUILDING H16 - SLAB REMOVAL	2665
32	15/7/94	H	BUILDING H16 - SLAB REMOVAL	2666

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: 92/0308

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1	19/7/94	H	NEW BLOCK PAVED ROAD WEST OF BUILDING H26	2667
2	19/7/94	H	VEHICLE WASH DOWN AREA UNDER CONSTRUCTION	2668
3	19/7/94	H	WASTE STOCKPILE - NORTH OF BUILDING H26	2669
4	19/7/94	S	REMOVAL OF ROAD WEST OF PRESS HOUSE	2670
5	19/7/94	T	NEW ACCESS ROAD FINISHED - LOOKING NORTH	2671
6	19/7/94	S	EXCAVATED CANAL WEST OF BUILDING S34	2672
7	19/7/94	P	RECONSTRUCTED ENTRANCE AND CAR PARK AT POWDERMILL LANE ENTRANCE	2673
8	19/7/94	P	BUILDING A210 - WINDOW MESH (PREVENTION OF PIGEON INGRESS) SOUTH EAST ELEVATION	2674
9	19/7/94	M	BUILDING L157 - WOOD SAMPLES FROM FLOORING AND ROOF BOARDING	2675
10	19/7/94	M	BUILDING L157 - WOOD CORE SAMPLES (EXAMPLE OF SPLIT CORE)	2676
11	19/7/94	M	BUILDING L157 - WOOD CORE SAMPLES (EXAMPLE OF SPLIT CORE)	2677
12	19/7/94	M	'LEAD IN AIR' MONITORING SAMPLES (FILTERS FORM AIR PUMPS)	2678
13	21/7/94	H	REMOVAL OF FLOOR SLAB TO BUILDING H16	2679
14	21/7/94	H	REMOVAL OF BUILDING H16 FLOOR SLABS	2680
15	21/7/94	H	GENERAL SCRAPE - NORTH AREA 'H'	2681
16	21/7/94	M	EXCAVATED CANAL NORTH OF BUILDING L136	2682
17	21/7/94	B	REMOVAL OF ACCESS ROAD FROM BRIDGE No. 10 TO BRIDGE No. 8	2683
18	21/7/94	B	REMOVAL OF ACCESS ROAD FROM BRIDGE No. 10 TO BRIDGE No. 8	2684
19	21/7/94	S	REMOVAL OF CONTAMINATED GROUND ADJACENT TO EDMONSEY SLUICE	26855
20	21/7/94	S	EXCAVATED CANAL NORTH WEST OF NEWTONS POOL	2686
21	21/7/94	S	EXCAVATED CANAL VIEWED FROM BRIDGE No. 23 NORTHWARDS	2687
22	21/7/94	S	EXCAVATION OF CONTAMINATED WASTE FROM NITRO GLYCERINE POPPING POND SOUTH OF BUILDING E2	2688
23	21/7/94	S	EXCAVATION OF CONTAMINATED WASTE FROM NITRO GLYCERINE POPPING POND SOUTH OF BUILDING E2	2689
24			NOT USED	
25	27/7/94	P	AREA 'P' NORTH - GENERAL VIEW AFTER REMOVAL OF FILLED GROUND	2690
26	27/7/94	P	AREA 'P' NORTH - GENERAL VIEW AFTER REMOVAL OF FILLED GROUND	2691
27	27/7/94	P	OIL / PETROL INTERCEPTOR ADJACENT FORMER BUILDING A220	2692
28	27/7/94	H	REMOVAL OF CONTAMINATED GROUND AT SITE OF FORMER BUILDING H16	2693
29	27/7/94	H	REMOVAL OF CONTAMINATED GROUND AT SITE OF FORMER BUILDING H16 - LOOKING SOUTH	2694
30	27/7/94	H	VEHICLE WASHDOWN CONSTRUCTION (PRIOR TO BLOCK PAVING)	2695
31	27/7/94	H	VEHICLE WASHDOWN - PETROL INTERCEPTOR ACCESS COVERS	2696
32	27/7/94	H	BLOCK PAVING TO NEW ACCESS ROAD WEST OF BUILDING H26	2697
33	27/7/94	S	CLEARED CANAL LOOKING SOUTH TOWARDS BUILDING E14 (IN BACKGROUND)	2698
34	27/7/94	T	CLEARED CANAL LOOKING TOWARDS INTERSECTION No. 26	2699
35	27/7/94	T	RECONSTRUCTED ACCESS ROAD THROUGH AREA 'T' - LOOKING SOUTH	2700
36			NOT USED	

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: 93/0753

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1	27/7/94	S	CANAL EXCAVATION AT BRIDGE No. 21	2701
2	27/7/94	S	CANAL EXCAVATION AT BRIDGE No. 21 LOOKING SOUTH TOWARDS BRIDGE No. 23	2702
3	27/7/94	S	EXCAVATED CANAL WEST OF BUILDING S34	2703
4			NOT USED	
5			NOT USED	
6	3/8/94	P	REMOVAL OF FILLED GROUND	2704
7	3/8/94	P	GENERAL VIEW ACROSS AREA 'P'	2705
8	3/8/94	P	GENERAL VIEW ACROSS AREA 'P' SHOWING EXCAVATED FILLED CANAL	2706
9	3/8/94	H	GENERAL VIEW ACROSS AREA 'H' WITH BUILDING H10 IN BACKGROUND	2707
10	3/8/94	H	GENERAL VIEW ACROSS AREA 'H' LOOKING NORTH	2708
11	3/8/94	H	GENERAL VIEW ACROSS AREA 'H'	2709
12	3/8/94	H	LOADING AWAY ACCUMULATED WASTE	2710
13	3/8/94	H	BUILDING H10 BEING DISMANTLED PRIOR TO FIRING	2711
14	3/8/94	H	BUILDING H10 DISMANTLE PRIOR TO FIRING	2712
15	3/8/94	H	BUILDING H10 DISMANTLE PRIOR TO FIRING	2713
16	3/8/94	H	BUILDING H10 DISMANTLE PRIOR TO FIRING	2714
17	3/8/94	H	BUILDING H10 DISMANTLE PRIOR TO FIRING	2715
18			NOT USED	
19	10/8/94	H	COMMENCEMENT OF EXCAVATION OF CANAL NORTH OF HOPPIT POOL	2716
20			NOT USED	
21	10/8/94	H	GENERAL VIEW LOOKING SOUTH TOWARDS ISLAND SITE - COMMENCEMENT OF CANAL RE-OPENING	2717
22	10/8/94	H	EXCAVATION OF FILLED CANAL EAST OF BUILDING H67	2718
23	13/8/94	H	BUILDING H10 - PREPARATION FOR FIRING	2719
24	13/8/94	H	BUILDING H10 - PREPARATION FOR FIRING	2720
25	13/8/94	H	BUILDING H10 - FIRING IN PROGRESS	2721
26	13/8/94	H	BUILDING H10 - FIRING IN PROGRESS	2722
27	13/8/94	H	BUILDING H10 - FIRING IN PROGRESS	2723
28			NOT USED	
29			NOT USED	
30			NOT USED	
31	16/8/94	H	EXCAVATION OF FILLED CANAL NORTH OF HOPPIT POOL - LOOKING NORTH	2724
32	16/8/94	H	EXCAVATION OF FILLED CANAL NORTH OF HOPPIT POOL - LOOKING NORTH	2725
33	16/8/94	H	CANAL CLEARANCE NORTH OF HOPPIT POOL	2726
34	16/8/94	H	CANAL CLEARANCE NORTH OF HOPPIT POOL	2727
35	16/8/94	H	CANAL CLEARANCE NORTH OF HOPPIT POOL	2728
36	16/8/94	H	BUILDING H10 READY FOR DEMOLITION AFTER FIRING	2729
37	16/8/94	H	BUILDING H71 / H10 PARTLY DEMOLISHED	2730

REPORT NO. ESG 2060/94
FORMER RARDE
 WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: 94/1031

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1	16/8/94	H	NEW ACCESS ROAD AND NEW VEHICLE WASHDOWN AREAS COMPLETE	2731
2	16/8/94	H	NEW ACCESS ROAD COMPLETE	2732
3	16/8/94	H	VIEW SOUTH - EAST OF BUILDING H26 VEGETATION CLEARED	2733
4	16/8/94	H	EAST FO BUILDING H26 - VEGETATION CLEARED VIEW NORTH	2734
5	16/8/94	H	DISMANTLING OF BUILDING H8 - LOOKING EAST	2735
6	16/8/94	H	DISMANTLING ROOF OF BUILDING H8 - LOOKING SOUTH	2736
7	16/8/94	S	TRIAL PIT No. 3 - CANAL REF.: 'Y' - NORTH OF BUILDING 22A	2737
8	16/8/94	S	TRIAL PIT No. 3 - CANAL REF.: 'Y' - NORTH OF BUILDING 22A	2738
9	16/8/94	S	TRIAL PIT No. 3 - CANAL REF.: 'Y' - NORTH OF BUILDING 22A	2739
10	16/8/94	S	TRIAL PIT No. 4 (NORTH FACE) - CANAL REF.: 'Y' - NORTH OF BUILDING 22A	2740
11	16/8/94	S	TRIAL PIT No. 4 (SOUTH FACE) - CANAL REF.: 'Y' - NORTH OF BUILDING 22A	2741
12	16/8/94	S	TRIAL PIT No. 5 (NORTH FACE) - CANAL REF.: 'Y' - NORTH OF BUILDING 22A	2742
13	16/8/94	S	TRIAL PIT No. 5 (SOUTH FACE) - CANAL REF.: 'Y' - NORTH OF BUILDING 22A	2743
14	17/8/94	S	TRIAL PIT No. 2 (NORTH FACE) - CANAL REF.: 'Y' - NORTH OF BUILDING 22A	2744
15	17/8/94	S	TRIAL PIT No. 2 (SOUTH FACE) - CANAL REF.: 'Y' - NORTH OF BUILDING 22A	2745
16	17/8/94	S	TRIAL PIT No. 1 (NORTH FACE) - CANAL REF.: 'Y' - NORTH OF BUILDING 22A	2746
17	17/8/94	S	TRIAL PIT No. 1 (SOUTH FACE) - CANAL REF.: 'Y' - NORTH OF BUILDING 22A	2747
18	17/8/94	S	TRIAL PIT No. 1 (EAST FACE) - CANAL REF.: 'Y' - NORTH OF BUILDING 22A	2748
19	17/8/94	H	DEMOLITION OF BUILDING H10 - NORTH EAST VIEW	2749
20	17/8/94	H	DEMOLITION OF BUILDING H10 - EAST VIEW	2750
21	17/8/94	H	DEMOLITION OF BUILDING H10 - EAST VIEW	2751
22	17/8/94	H	DEMOLITION OF BUILDING H10 - SOUTH EAST VIEW	2752
23	17/8/94	H	DEMOLITION OF BUILDING H10 - SOUTH VIEW	2753
24	18/8/94	H	NEARING COMPLETION OF DEMOLITION OF BUILDING H10 - NORTH WEST VIEW	2754
25	18/8/94	H	DEMOLITION OF BUILDING H10 - WEST VIEW	2755
26	18/8/94	H	BUILDING H10 - DEMOLITION IN PROGRESS	2756
27	18/8/94	H	BUILDING H10 - DEMOLITION IN PROGRESS	2757
28			NOT USED	
29			NOT USED	
30			NOT USED	
31	18/8/94	H	MILLHEAD STREAM SECURITY FENCE	2758
32	18/8/94	H	MILLHEAD STREAM SECURITY FENCE	2759
33	19/8/94	H	BREAKING UP FLOOR SLAB OF BUILDING H10	2760
34	19/8/94	H	BREAKING UP FLOOR SLAB OF BUILDING H10	2761
35	19/8/94	H	CANAL SOUTH OF H67 - REMEDIAL WORKS (EXPOSED WATER AND GAS MAINS. SEGMENTS OF MILLSTONE RECOVERED FROM CANAL EXCAVATIONS)	2762
36	19/8/94	H	CANAL SOUTH OF H67 - REMEDIAL WORKS (EXPOSED WATER AND GAS MAINS. SEGMENTS OF MILLSTONE RECOVERED FROM CANAL EXCAVATIONS)	2763
R	19/8/94	P	TEMPORARY SAFETY FENCING AT POWDERMILL LANE ENTRANCE - LOOKING SOUTH WEST	2764

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: 95/1262

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1	20/8/94	H	BUILDING H8 PREPARED FOR FIRING	2765
2	20/8/94	H	BUILDING H8 PREPARED FOR FIRING	2766
3	20/8/94	H	BUILDING H8 PREPARED FOR FIRING	2767
4	20/8/94	H	BUILDING H8 - FIRING IN PROGRESS	2768
5	22/8/94	P	BRIDGE No. 2	2769
6			NOT USED	
7	22/8/94	P	SURFACE AREA 'P' NORTH	2770
8	22/8/94	S	SECTION OF EXCAVATED CANAL AT BUILDING 16A ENTRANCE	2771
9	22/8/94	S	SECTION OF EXCAVATED CANAL AT BUILDING 16A ENTRANCE	2772
10	23/8/94	P	AERIAL VIEW OF AREA 'P' LOOKING SOUTH - BUILDING A210 IN FOREGROUND	2773
11	23/8/94	H	AERIAL VIEW OF AREA 'H' LOOKING SOUTH - BUILDING A203 AND A200 IN FOREGROUND	2774
12	23/8/94	H	AERIAL VIEW OF AREA 'H' LOOKING WEST (HOPPIT POOL IN CENTRE OF SHOT)	2775
13	23/8/94	H	AERIAL VIEW OF BUILDING H67	2776
14	23/8/94	L / M	AERIAL VIEW OF AREA 'L / M' LOOKING NORTH	2777
15	23/8/94	P	AERIAL VIEW TOWARDS WALTHAM ABBEY (BUILDING A214 IN FOREGROUND)	2778
16	23/8/94	M	AERIAL VIEW OF WEST ELEVATION OF BUILDINGS L167 / L159 / L160	2779
17	23/8/94	M	AERIAL VIEW OF THE ROOF OF BUILDING L168	2780
18	23/8/94	M	AERIAL VIEW OF THE ROOF OF BUILDING L168	2781
19	23/8/94	M	AERIAL VIEW OF BUILDINGS L167 / L177 / L180 (NORTH ELEVATION)	2782
20	23/8/94	M	VIEW OF 'BRONTO' ELEVATED AT BUILDING L168	2783
21	23/8/94	M	VIEW OF ELEVATED PLATFORM AT BUILDING L168	2784
22	23/8/94	P	BREAKING OUT FOUNDATIONS ADJACENT BUILDING A210	2785
23	23/8/94	P	LOADING AWAY WASTE FROM AREA 'P' NORTH	2786
24	23/8/94	T	AERIAL VIEW OF REMAINS OF FORMER GUNPOWDER DRYING STOVE	2787
25	23/8/94	T	AERIAL VIEW OF AREA 'T' LOOKING SOUTH	2788
26	23/8/94	S	AERIAL VIEW OF AREA 'S' - LOOKING SOUTH EAST (MOUNDED BUILDING E2 JUST VISIBLE)	2789
27	23/8/94	S	AERIAL VIEW OF AREA 'S' - LOOKING SOUTH EAST (MOUNDED BUILDING E2 JUST VISIBLE)	2790
28	23/8/94	S	AERIAL VIEW TOWARDS NEWTONS POOL	2791
29	23/8/94	S	AERIAL VIEW OF BUILDING 22A	2792
30	23/8/94	S	AERIAL VIEW OF BUILDING 22A	2793
31	23/8/94	S	AERIAL VIEW NORTHWARDS FORM AREA 'T' TO GRAND MAGAZINE	2794
32			NOT USED	
33	23/8/94	T	AERIAL VIEW OF SOUTHERN END OF AREA 'T'	2795
34	23/8/94	T	AERIAL VIEW OF HORSEMILL STREAM AT AREA 'T'	2796
35			NOT USED	
36			NOT USED	
R			NOT USED	

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: 96/1261

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1	23/8/94	T	AERIAL VIEW - REMAINS OF FORMER GUNPOWDER STOVE	2797
2	23/8/94	T	AERIAL VIEW - REMAINS OF FORMER GUNPOWDER STOVE	2798
3	23/8/94	T	AERIAL VIEW SHOWING FILLED CANAL CLEARANCE	2799
4	23/8/94	T	AERIAL VIEW, SOUTH END OF AREA 'T'	2800
5	23/8/94	T	AERIAL VIEW TO SOUTH OF BUILDING E2 (NITRO GLYCERINE 'POPPING POND')	2801
6			NOT USED	
7			NOT USED	
8	23/8/94	T	AERIAL VIEW OF BUILDING 22A	2802
9	23/8/94	T	AERIAL VIEW OF BUILDING 22A	2803
10			NOT USED	
11			NOT USED	
12	23/8/94	T	AERIAL VIEW OF SITE ARCHAEOLOGIST AND SITE LANDROVER	2804
R	23/8/94	T	AERIAL VIEW OF NORTHERN END OF AREA 'T'	2805

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: 97/1869

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1	24/8/94	H	DEMOLITION OF BUILDING H8	2806
2	24/8/94	H	DEMOLITION OF BUILDING H8	2807
3	24/8/94	H	DEMOLITION OF BUILDING H8 (STOCKPILE FROM BLDG H10 IN BACKGROUND)	2808
4	24/8/94	P	SOUTH EAST VIEW OF MILLSTONE UNCOVERED EAST OF BUILDING A203	2809
5	24/8/94	P	NORTH WEST VIEW OF MILLSTONE UNCOVERED EAST OF BUILDING A203	2810
6	24/8/94	M	BLDG L168 (MACHINE SHOP INTERNALS NORTH) - VIEW OF ROOF STRUCTURE	2811
7	24/8/94	M	BLDG L168 (MACHINE SHOP INTERNALS NORTH) - VIEW OF ROOF STRUCTURE	2812
8	24/8/94	M	BUILDING L168 (MACHINE SHOP INTERNALS) - FLOOR AREA	2813
9	25/8/94	P	BRIDGE No. 1 SOUTH EAST ABUTMENT	2814
10	25/8/94	P	BRIDGE No. 1 NORTH WEST ABUTMENT	2815
11	25/8/94	P	BRIDGE No. 1 SOUTH EAST ABUTMENT	2816
12	25/8/94	S	BUILDING L108 - CANAL EXCAVATION	2817
13	25/8/94	S	BUILDING L108 - CANAL CLEARANCE	2818
14	25/8/94	S	BRIDGE No. 27 - CANAL CLEARANCE (SWIVEL BUCKET FITTED)	2819
15	25/8/94	S	BRIDGE No. 27 - CANAL CLEARANCE (SWIVEL BUCKET FITTED)	2820
16	25/8/94	H	MICRON SITE LABORATORY - VAPORISING ACETONE ON ASBESTOS FIBRE AIR MONITORING FILTER	2821
17	25/8/94	H	MICRON SITE LABORATORY - VAPORISING ACETONE ON ASBESTOS FIBRE AIR MONITORING FILTER	2822
18	25/8/94	H	MICRON SITE LABORATORY - VAPORISING ACETONE ON ASBESTOS FIBRE AIR MONITORING FILTER	2823
19	27/8/94	P	FELLING LARGE ASH TREE AT BRIDGE No. 1	2824
20	27/8/94	M	IMPORTED PIPES FOR CANAL ROAD CROSSINGS	2825
21	27/8/94	H	PLACING PIPES AT CANAL ROAD CROSSINGS ADJACENT BUILDING H67	2826
22	27/8/94	H	PLACING PIPES AT CANAL ROAD CROSSINGS ADJACENT BUILDING H67	2827
23			NOT USED	
24			NOT USED	
25	27/8/94	S	VIEW TOWARDS BURNING GROUND - LOOKING NORTH WEST	2828
26	27/8/94	M	BUILDING L155 - STRIP OUT IN PROGRESS	2829
27	28/8/94	P	BRIDGE No. 1 ASH TREE FELLED	2830
28			NOT USED	
29	28/8/94	M	SITE DUMP TRUCK ADAPTATION (TAIL GATE FITTING)	2831
30	30/8/94	S	BLDG 18A - EXCAVATED PIT IN CANAL ZONE TO REMOVE BURIED ASBESTOS	2832
31	30/8/94	S	BLDG 18A - EXCAVATED PIT IN CANAL ZONE TO REMOVE BURIED ASBESTOS	2833
32	30/8/94	H	CANAL ROAD CROSSING CONSTRUCTED ADJACENT BUILDING H67 VIEW LOOKING SOUTH TOWARDS HOPPIT POOL	2834
33			NOT USED	
34	30/8/94	H	CANAL ROAD CROSSING EAST OF BUILDING H67	2835
35	30/8/94	P	BRIDGE No. 1 - TREE REMOVED TO ALLOW ACCESS FOR REMEDIAL WORKS	2836
36			NOT USED	
37	30/8/94	P	TREE FELLING AREA 'P' NORTH	2837

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: 98/2529

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1	31/8/94	P	REMOVAL OF ACCESS ROAD TO BRIDGE No. 2	2838
2	31/8/94	P	AREA P SOUTH - CONSTRUCTION OF ACCESS ROAD FOR RIVER REVETMENT WORKS	2839
3	31/8/94	P	AREA P SOUTH - CONSTRUCTION OF ACCESS ROAD FOR RIVER REVETMENT WORKS	2840
4	31/8/94	P	SITE ARCHAEOLOGIST INSPECTING CANALS ADJACENT BUILDING A203	2841
5	31/8/94	P	AREA P NORTH - REMOVAL OF ACCESS ROAD TO BRIDGE No. 2	2842
6			NOT USED	
7			NOT USED	
8			NOT USED	
9			NOT USED	
10	1/9/94	H	TRACING WATER MAIN ACROSS ROAD NORTH OF BUILDING H8	2843
11	1/9/94	M	'LONG REACH' EXCAVATOR DREDGING MIDDLE STREAM EAST OF BUILDING L157	2844
12	1/9/94	S	CANAL CLEARANCE NORTH OF BUILDING L136	2845
13			NOT USED	
14	2/9/94	P	BRIDGE No. 2 - LOOKING AT HANDRAIL No. 1	2846
15	2/9/94	P	BRIDGE No. 2 - LOOKING AT HANDRAIL No. 2	2847
16	2/9/94	P	BRIDGE No. 2 - FOOTWAY BOARDING CONDITION	2848
17	2/9/94	P	BRIDGE No. 2 - LOOKING NORTH	2849
18	5/9/94	P	AREA P SOUTH - CONSTRUCTION OF ACCESS ROAD FOR REVETMENT WORKS	2850
19	5/9/94	S	OTTER HOLES THROUGH EAST FENCE AT GRAND MAGAZINE	2851
20	5/9/94	S	OTTER HOLES THROUGH EAST FENCE AT GRAND MAGAZINE	2852
21	5/9/94	T	GUNPOWDER STOVE AFTER FINAL CLEAR - SAMPLING PEGS PAINTED	2853
22	5/9/94	T	GUNPOWDER STOVE AFTER FINAL CLEAR - SAMPLING PEGS PAINTED	2854
23	5/9/94	T	GUNPOWDER STOVE AFTER FINAL CLEAR - SAMPLING PEGS PAINTED	2855
24	5/9/94	T	GUNPOWDER STOVE AFTER FINAL CLEAR - SAMPLING PEGS PAINTED	2856
25	5/9/94	T	GUNPOWDER STOVE AFTER FINAL CLEAR - SAMPLING PEGS PAINTED	2857
26	5/9/94	S	TRIAL TRENCH 7 - CANAL REF.: Y NORTH OF BUILDING 22A	2858
27	5/9/94	S	TRIAL TRENCH 6 - CANAL REF.: Y NORTH OF BUILDING 22A	2859
28	6/9/94	S	TRIAL TRENCH 9 - CANAL REF.: Y NORTH OF BUILDING 22A	2860
29	6/9/94	S	TRIAL TRENCH 10 - CANAL REF.: Y NORTH OF BUILDING 22A	2861
30	6/9/94	S	DEBRIS FOUND IN TRIAL PIT 10	2862
31	6/9/94	P	STUMP GRINDING PMLH AREA SOUTH OF BRIDGE No. 1	2863
32	6/9/94	S	TRIAL TRENCH 10 - CANAL REF.: Y NORTH OF BUILDING 22A	2864
33			NOT USED	
34			NOT USED	
35	7/9/94	T	LAYING TERRAM OVER GUNPOWDER STOVES PRIOR TO COVERING	2865
36	7/9/94	P	WEST OF BUILDINGS A210 / A214 SHOWING REDUCTION OF GROUND LEVEL	2866
R	7/9/94	P	NORTH WEST VIEW OF BUILDINGS A214 / A210	2867

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: 99/2979

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1	8/9/94	M	REMOVED UNDER ROOF INSULATION MATERIAL FROM BUILDING L159	2868
2	8/9/94	M	REMOVED UNDER ROOF INSULATION MATERIAL FROM BUILDING L159	2869
3			NOT USED	
4	8/9/94	M	WATER TANK IN BUILDING L155 TO BE REMOVED	2870
5	8/9/94	M	BUILDING L151 - BAY READY FOR STRIPPING OUT	2871
6	8/9/94	M	BUILDING L149 - TYPICAL BAY MID WAY THROUGH STRIPPING OUT	2872
7			NOT USED	
8	8/9/94	M	BUILDING L149 - INTERNAL WALL DEMOLITION	2873
9	8/9/94	M	BUILDING L143 - STORAGE OF DOORS AND CARPET	2874
10	8/9/94	M	BUILDING L137 - INTERNAL WARNING SIGNS RE. PACEMAKERS	2875
11	8/9/94	M	BUILDING L145 - INTERNAL CORRIDOR WALL DEMOLISHED	2876
12	8/9/94	M	BUILDING L145 - TEMPORARY ROOF SUPPORT IN PLACE	2877
13	8/9/94	M	BUILDING L145 (WEST SIDE) - FWD DRAIN REMOVAL AND WRAPPING	2878
14	8/9/94	M	BUILDING L153 - GRIT BLASTING TEMPORARY EXTRACT DUCTWORK	2879
15	8/9/94	M	BUILDING L157 - COMPLETED GRIT BLASTING TO STRUCTURAL STEELWORK	2880
16	8/9/94	M	BUILDING L157 - TEMPORARY SUPPORT TO ROOF TRUSS BEARING	2881
17	8/9/94	M	BUILDING L153 - GRIT BLASTED ROOF TRUSS MEMBERS	2882
18	8/9/94	M	BUILDING L153 - GRIT BLASTING OPERATION - SCAFFOLD ACCESS	2883
19	8/9/94	M	BUILDING L153 - GRIT BLASTING OPERATION - TYPICAL ROOF TRUSS SUPPORT	2884
20	8/9/94	M	BUILDING L153 - GRIT BLASTING OPERATION - TEMPORARY AIR INLET	2885
21			NOT USED	
22	8/9/94	P	INSPECTION OF SUNKEN BARGE - MILLHEAD STREAM SOUTH OF BRIDGE No. 1	2886
23	8/9/94	P	INSPECTION OF SUNKEN BARGE - MILLHEAD STREAM SOUTH OF BRIDGE No. 1	2887
24	9/9/94	P	INSPECTION OF SUNKEN BARGE - MILLHEAD STREAM SOUTH OF BRIDGE No. 1	2888
25	9/9/94	P	INSPECTION OF SUNKEN BARGE - MILLHEAD STREAM SOUTH OF BRIDGE No. 1	2889
26	10/9/94	P	INSPECTION OF SUNKEN BARGE - MILLHEAD STREAM SOUTH OF BRIDGE No. 1	2890
27	10/9/94	P	INSPECTION OF SUNKEN BARGE - MILLHEAD STREAM SOUTH OF BRIDGE No. 1	2891
28	10/9/94	P	INSPECTION OF SUNKEN BARGE - MILLHEAD STREAM SOUTH OF BRIDGE No. 1	2892
29	10/9/94	P	INSPECTION OF SUNKEN BARGE - MILLHEAD STREAM SOUTH OF BRIDGE No. 1	2893
30	10/9/94	P	INSPECTION OF SUNKEN BARGE - MILLHEAD STREAM SOUTH OF BRIDGE No. 1	2894
31	10/9/94	P	CLOSER INSPECTION OF BARGE RECOVERED FROM MILLHEAD STREAM	2895
32	10/9/94	P	SUPPORTING RECOVERED BARGE FROM MILLHEAD STREAM ON DRY LAND	2896
33	12/9/94	P	FILL BEHIND SOUTH EAST BRICK ABUTMENT TO BRIDGE No. 1	2897
34	12/9/94	P	BRIDGE No. 1 - SOUTH EAST ABUTMENT - SEVERE CRACKING TO BRICKWORK	2898
35	12/9/94	P	SHEET PILING TO MILLHEAD STREAM REVETMENT SOUTH OF BRIDGE No. 1	2899
36	12/9/94	S	SAMPLING PEG POSITIONS IN EXCAVATED ROADWAY ADJACENT EDMONSEY SLUICE	2900
37	12/9/94	P	STEEL SHEET PILING WORKS TO MILLHEAD STREAM REVETMENT SOUTH OF BRIDGE No. 1	2901

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: 100/3548

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1	13/9/94	P	BARGE RECOVERED FROM MILLHEAD STREAM	2902
2	13/9/94	P	BARGE RECOVERED FROM MILLHEAD STREAM	2903
3	13/9/94	P	BARGE RECOVERED FROM MILLHEAD STREAM - LOADING	2904
4	13/9/94	P	BARGE RECOVERED FROM MILLHEAD STREAM - LOADING	2905
5	13/9/94	P	BARGE RECOVERED FROM MILLHEAD STREAM - LOADING	2906
6	13/9/94	P	BARGE RECOVERED FROM MILLHEAD STREAM - UNLOADING	2907
7	13/9/94	M	CORDITE FOUND IN CANAL ADJACENT BUILDING L145	2908
8	13/9/94	M	BARGE RECOVERED FROM MILLHEAD STREAM BEING - PLACEMENT	2909
9	13/9/94	M	BARGE RECOVERED FROM MILLHEAD STREAM BEING - PLACEMENT	2910
10	13/9/94	M	BARGE RECOVERED FROM MILLHEAD STREAM BEING - PLACEMENT	2911
11	13/9/94	M	BARGE RECOVERED FROM MILLHEAD STREAM BEING - PLACEMENT	2912
12	13/9/94	M	BUILDING L145 - PREPARATION FOR REMOVAL OF ROOF STEELWORK	2913
13	13/9/94	M	BUILDING L145 - REMOVAL OF ROOF STEELWORK	2914
14	13/9/94	M	BUILDING L145 - REMOVAL OF ROOF STEELWORK	2915
15	13/9/94	P	REMOVAL OF BRICK REVETMENT WALLING SOUTH OF BRIDGE No. 1	2916
16	13/9/94	P	SHEET PILING TO REVETMENT OF MILLHEAD STREAM	2917
17	15/9/94	P	BRIDGE NO. 1 - PREPARATION FOR BRICK ABUTMENT REPAIRS	2918
18	15/9/94	P	BRIDGE No. 1 - CLOSE UP OF DRAIN CHANNEL WITHIN BRICK ABUTMENT	2919
19			NOT USED	
20	15/9/94	P	EXCAVATION OF FILLED GROUND EAST OF BUILDING A214	2920
21	15/9/94	P	EXCAVATION OF FILLED GROUND SOUTH OF BUILDING A214	2921
22			NOT USED	
23	15/9/94	P	SERVICE TRENCH ON NORTH SIDE OF BUILDING A210	2922
24	15/9/94	P	SUMP AT NORTH FACE OF BUILDING A210	2923
25	15/9/94	P	SERVICE TRENCH NORTH OF BUILDING A210	2924
26	16/9/94	H	REMOVAL OF HYDROCARBON CONTAMINATED GROUND ADJACENT BLDG H26	2925
27	16/9/94	H	REMOVAL OF HYDROCARBON CONTAMINATED GROUND ADJACENT BLDG H26	2926
28	18/9/94	P	BRIDGE No. 1 - SOUTH EAST ABUTMENT - BRICKWORK REPAIRED	2927
29	18/9/94	P	BRIDGE No. 1 - SOUTH EAST ABUTMENT - BRICKWORK REPAIRED	2928
30	19/9/94	P	BRIDGE No. 1 - GENERAL VIEW	2929
31	19/9/94	P	BRIDGE No. 1 - GENERAL VIEW	2930
32	19/9/94	P	BRIDGE No. 1 - GENERAL VIEW	2931
33	19/9/94	P	SHEET PILING TO MILLHEAD STREAM REVETMENT SOUTH OF BRIDGE No. 1	2932
34	19/9/94	P	SHEET PILING TO MILLHEAD STREAM REVETMENT SOUTH OF BRIDGE No. 1	2933
35	20/9/94	H	MILLHEAD STREAM - WEST BANK ADJACENT BUILDING H26	2934
36			NOT USED	
37	20/9/94	H	MILLHEAD STREAM - WEST BANK ADJACENT BUILDING H26	2935

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: 101/7574

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1	20/9/94	H	VIEW OF COLLAPSED CANAL WALL EAST OF BUILDING H26	2936
2	20/9/94	H	VIEW OF COLLAPSED CANAL WALL EAST OF BUILDING H26	2937
3	20/9/94	H	VIEW OF CANAL WALL EAST OF BUILDING H26	2938
4			NOT USED	
5	21/9/94	S	CANAL INTERSECTION 27 LOOKING NORTH	2939
6	21/9/94	S	CANAL INTERSECTION 27 LOOKING SOUTH	2940
7	21/9/94	S	CANAL INTERSECTION 29 LOOKING NORTH	2941
8	21/9/94	S	CANAL INTERSECTION 29 LOOKING SOUTH	2942
9	22/9/94	P	MILLHEAD STREAM JUNCTION WITH BRIDGE No 1 SOUTH EAST ABUTMENT	2943
10			NOT USED	
11	22/9/94	P	REMOVAL OF CONTAMINATED GROUND EAST OF BUILDING A210	2944
12	22/9/94	P	REMOVAL OF CONTAMINATED GROUND EAST OF BUILDING A210	2945
13	22/9/94	T	CANAL INTERSECTION 26 LOOKING NORTH	2946
14	22/9/94	T	CANAL INTERSECTION 26 LOOKING SOUTH	2947
15	22/9/94	T	CANAL INTERSECTION 25 LOOKING NORTH	2948
16	22/9/94	T	CANAL INTERSECTION 25 LOOKING SOUTH	2949
17	23/9/94	S	CANAL INTERSECTION 22 LOOKING NORTH	2950
18	23/9/94	S	CANAL INTERSECTION 22 LOOKING SOUTH	2951
19	23/9/94	S	CANAL INTERSECTION 21 LOOKING NORTH	2952
20	23/9/94	S	CANAL INTERSECTION 21 LOOKING SOUTH	2953
21	26/9/94	P	DORMER WINDOW - BUILDING A221	2954
22			NOT USED	
23	26/9/94	P	SOUTH WEST VIEW ACROSS AREA 'P' NORTH	2955
24	26/9/94	P	AREA 'P' SOUTH - MILLHEAD STREAM EAST BANK EXCAVATED BEHIND NEW SHEET PILING	2956
25	27/9/94	S	CANAL INTERSECTION 11 LOOKING NORTH	2957
26	27/9/94	S	CANAL INTERSECTION 11 LOOKING SOUTH	2958
27	27/9/94	S	CANAL INTERSECTION 15 LOOKING NORTH	2959
28	27/9/94	S	CANAL INTERSECTION 15 LOOKING SOUTH	2960
29	27/9/94	S	CANAL INTERSECTION 17 LOOKING NORTH	2961
30	27/9/94	S	CANAL INTERSECTION 17 LOOKING SOUTH	2962
31	28/9/94	S	CANAL INTERSECTION 8 LOOKING NORTH	2963
32	28/9/94	S	CANAL INTERSECTION 8 LOOKING SOUTH	2964
33	28/9/94	S	CANAL INTERSECTION 10 LOOKING NORTH	2965
34	28/9/94	S	CANAL INTERSECTION 10 LOOKING SOUTH	2966
35	29/9/94	S	CANAL INTERSECTION 16 LOOKING EAST	2967
36	29/9/94	S	CANAL INTERSECTION 16 LOOKING WEST	2968
37	30/9/94	H	REMOVAL OF DEEP FOUNDATIONS TO BUILDING H10	2969

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: 102/7781

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1	30/9/94	H	BUILDING H8 - VIEW OF EXCAVATION AFTER REMOVAL OF FOUNDATIONS	2970
2	30/9/94	H	BUILDING H10 - VIEW OF EXCAVATION AFTER REMOVAL OF FOUNDATIONS	2971
3	30/9/94	H	STOCKPILE OF EXCAVATED MATERIAL AT BUILDING H10	2972
4	30/9/94	H	BUILDING H8 - VIEW OF EXCAVATION AFTER REMOVAL OF FOUNDATIONS	2973
5	30/9/94	H	BUILDING H8 - VIEW OF EXCAVATION AFTER REMOVAL OF FOUNDATIONS	2974
6	30/9/94	H	BUILDING H8 - VIEW OF EXCAVATION AFTER REMOVAL OF FOOTING	2975
7	30/9/94	H	FORKLIFT ON VEHICLE WASHDOWN AREA	2976
8	30/9/94	H	FORKLIFT ON VEHICLE WASHDOWN AREA	2977
9	4/10/94	H	CYLINDER RETRIEVED DURING DREDGING OPERATIONS NORTH - BRIDGE No. 3	2978
10	4/10/94	H	CYLINDER RETRIEVED DURING DREDGING OPERATIONS NORTH - BRIDGE No. 3	2979
11	4/10/94	H	CYLINDER RETRIEVED DURING DREDGING OPERATIONS NORTH - BRIDGE No. 3	2980
12	4/10/94	H	CYLINDER RETRIEVED DURING DREDGING OPERATIONS NORTH - BRIDGE No. 3	2981
13	4/10/94	H	CYLINDER RETRIEVED DURING DREDGING OPERATIONS NORTH - BRIDGE No. 3	2982
14			NOT USED	
15	5/10/94	P	CLAY PLACEMENT BEHIND MILLHEAD STREAM SHEET PILING	2983
16	5/10/94	P	CLAY PLACEMENT BEHIND MILLHEAD STREAM SHEET PILING	2984
17	5/10/94	H	BUILDING H8 - BACKFILLING EXCAVATION	2985
18	5/10/94	H	BUILDING H8 - BACKFILLING EXCAVATION	2986
19	8/10/94	H	TREE PRIOR TO FELLING, NORTH OF BRIDGE No. 3	2987
20	8/10/94	H	TREE FELLING IN PROGRESS, NORTH OF BRIDGE No. 3	2988
21	8/10/94	H	TREE FELLING COMPLETED, NORTH OF BRIDGE No. 3	2989
22	11/10/94	P	PUMPING OVER SHEET PILE WALL OF MILLHEAD STREAM	2990
23	11/10/94	P	PIPE IN PLACE FOR PUMPING OVER SHEET PILE WALL OF MILLHEAD STREAM	2991
24	11/10/94	P	VIEW OF SHEET PILE WALL TO MILLHEAD STREAM	2992
25	11/10/94	P	REMOVAL OF DRAIN RUN WEST OF BUILDING A221	2993
26	11/10/94	P	SHEET PILE WALL TO MILLHEAD STREAM	2994
27	14/10/94	S	CANAL INTERSECTION 31 LOOKING NORTH	2995
28	14/10/94	S	CANAL INTERSECTION 31 LOOKING SOUTH	2996
29	14/10/94	S	CONSTRUCTION OF NEW ROAD WEST OF BUILDING 103	2997
30	14/10/94	P	CONSTRUCTION OF NEW ROAD SOUTH OF BRIDGE No. 2	2998
31	14/10/94	P	AREA 'P' NORTH - REMEDIATION OF DITCH ADJACENT TO CONSTRUCTION OF NEW ACCESS ROAD	2999
32	14/10/94	P	AREA 'P' NORTH - REMEDIATED DITCH EAST OF ACCESS ROAD CONSTRUCTION SOUTH OF BRIDGE No. 2	3000
33	14/10/94	P	SETTING OUT OF NEW ACCESS ROAD TO BRIDGE No. 2	3001
34	14/10/94	H	BUOYANCY TANKS BEING LIFTED INTO HOPPITS POOL NORTH OF BLDG A201/2	3002
35	14/10/94	H	SETTING UP PUMP ON BUOYANCY TANKS IN HOPPITS POOL.	3003
36	14/10/94	P	NEW ACCESS ROAD UNDER CONSTRUCTION TO BRIDGE No. 2	3004
37			NOT USED	

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: 103/8702

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1			NOT USED	
2	19/10/94	T	OVERTURNED TRACTOR IN TETRYL AREA	3005
3			NOT USED	
4			NOT USED	
5	19/10/94	H	CLAY FILL WEST OF BUILDING H26	3006
6	19/10/94	H	CLAY FILL NORTH OF BUILDING H26	3007
7	19/10/94	H	CLAY FILL NORTH OF BUILDING H26	3008
8	19/10/94	P	NEW ACCESS ROAD TO BRIDGE No. 2 LOOKING SOUTH	3009
9	19/10/94	P	NEW ACCESS ROAD TO BRIDGE No. 2 LOOKING SOUTH WEST	3010
10	19/10/94	P	NEW ACCESS ROAD TO BRIDGE No. 2 LOOKING NORTH WEST	3011
11	19/10/94	M	900mm LONG PIKE FOUND OPPOSITE BUILDING L148	3012
12	19/10/94	H	DAMAGE TO SECURITY BARRIER AT HIGHBRIDGE STREET ENTRANCE	3013
13	19/10/94	H	DAMAGE TO SECURITY BARRIER AT HIGHBRIDGE STREET ENTRANCE	3014
14	20/10/94	M	SCRAP METAL STOCKPILED BY ROUNDABOUT	3015
15	20/10/94	M	SCRAP METAL STOCKPILED BY ROUNDABOUT	3016
16	20/10/94	H	DAMAGE TO SECURITY FENCE WEST OF BUILDING H8	3017
17	20/10/94	H	DAMAGE TO SECURITY FENCE WEST OF BUILDING H8	3018
18	21/10/94	T	GULLY POT CONTAINING DEPOSITS OF EXPLOSIVE IN TETRYL FACTORY	3019
19	21/10/94	T	GULLY POT EXCAVATION CONTAINING DEPOSITS OF EXPLOSIVE IN TETRYL FACTORY	3020
20			NOT USED	
21			NOT USED	
22	25/10/94	P	ROAD CONSTRUCTION WEST OF BUILDING A221	3021
23	26/10/94	P	STEEL TANKS WELDED TO SHEET PILE PRIOR TO RETRIEVING CONCRETE	3022
24	26/10/94	S	CHECKING THE DEPTH PRIOR TO THE INSTALLATION OF A PORTADAM NORTH OF BUILDING L136	3023
25	26/10/94	S	PORTADAM UNDER CONSTRUCTION NORTH OF BUILDING L136	3024
26			NOT USED	
27	26/10/94	S	PORTADAM UNDER CONSTRUCTION NORTH OF BUILDING L136	3025
28	26/10/94	S	PORTADAM UNDER CONSTRUCTION	3026
29	26/10/94	S	PORTADAM UNDER CONSTRUCTION NORTH OF BUILDING L136	3027
30	26/10/94	S	COMPLETED INSTALLATION OF PORTADAM	3028
31	27/10/94	P	NEW ACCESS ROAD TO BRIDGE No. 2 LOOKING NORTH	3029
32	27/10/94	P	NEW ACCESS ROAD FROM BRIDGE No. 2 LOOKING SOUTH	3030
33	2/11/94	H	NEW ROAD CONSTRUCTION	3032
34	2/11/94	H	DREDGING MILLHEAD STREAM	3033
35	3/11/94	P	PLACING OF LOGS TO EDGE OF NEW ROAD	3036
36	3/11/94	P	NEW ROAD CONSTRUCTION TO BUILDING A210	3034
37	3/11/94	P	REMEDIATING RIVER BANK EAST OF BUILDING A200	3035

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: 104/9710

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1	3/11/94	L	SATURATED CANAL DREDGINGS STOCKPILED IN QUEENS MEAD	3036
2	3/11/94	L	SATURATED CANAL DREDGINGS STOCKPILED IN QUEENS MEAD	3037
3	3/11/94	L	SATURATED CANAL DREDGINGS STOCKPILED IN QUEENS MEAD	3038
4	4/11/94	M	WATER OUTFALL INTO RIVER LEA EAST OF BUILDING A210	3039
5	4/11/94	M	WATER OUTFALL TO RIVER LEA	3040
6			NOT USED	
7	4/11/94	N	STAG BURIED AT NEW HILL	3041
8	4/11/94	S	CLAY BRIDGE ACROSS DRAINAGE DITCH WEST OF LONG WALK	3042
9	4/11/94	H	TEMPORARY ROAD NORTH OF H67 TOWARDS LOCK	3043
10	8/11/94	H	KOCUREK MACHINE ON MILLHEAD STREAM BANK	3044
11			NOT USED	
12	8/11/94	P	CULVERT AND DRAIN UNDER GARDEN WALL TO BUILDING A221	3045
13	8/11/94	P	WORK ON NEW ROAD LOOKING NORTH TO BRIDGE No. 2	3046
14	11/11/94	H	NEW ROAD LAYOUT UNDER CONSTRUCTION	3047
15	11/11/94	H	NEW ROAD LAYOUT UNDER CONSTRUCTION	3048
16	11/11/94	H	H10 - BREAKING OUT CONCRETE FOUNDATION SLAB	3049
17	15/11/94	P	BREAKING OUT MANHOLE AT REAR OF BUILDING A214	3050
18	15/11/94	P	DRAIN EXPOSED EAST OF BUILDING A210	3051
19	15/11/94	L	RUBBLE BENEATH UNDERGROWTH ON BANKS OF DRAINAGE DITCH WEST OF LONG WALK	3052
20	15/11/94	L	RUBBLE BENEATH UNDERGROWTH ON BANKS OF DRAINAGE DITCH WEST OF LONG WALK	3053
21	16/11/94	P	ASBESTOS IN SERVICE DUCT SOUTH OF BUILDING A210 MACHINE SHOP	3054
22	16/11/94	P	EXCAVATED ASH PIT SOUTH OF BUILDING A210	3055
23	16/11/94	P	EXCAVATED ASH PIT SOUTH OF BUILDING A210	3056
24			NOT USED	
25	17/11/94	H	CHECKING PROGRESS WEST OF HOPPIT POOL	3057
26	17/11/94	P	EXCAVATED ASH PIT SOUTH OF BUILDING A210	3058
27	17/11/94	P	DIGGING & BAGGING ASBESTOS FROM SERVICE TRENCH SOUTH BLDG A210	3059
28	17/11/94	P	REMOVAL OF ASBESTOS FORM SERVICE TRENCH SOUTH OF BUILDING A210 MACHINE SHOP	3060
29	17/11/94	P	DUCT CLEANED OUT OF ASBESTOS SOUTH OF BUILDING A210 MACHINE SHOP	3061
30	21/11/94	P	LINING EXCAVATED ASH PIT WITH CLAY SOUTH OF BUILDING A210	3062
31	21/11/94	M	VIEW OF BRIDGE No. 30 - DERELICT PEDESTRIAN SERVICE BRIDGE	3063
32	21/11/94	P	CLAY INFILL TO EXCAVATED ASH PIT SOUTH OF BUILDING A210	3064
33	21/11/94	H	CONSTRUCTION OF NEW ROAD	3065
34	22/11/94	M	GENERAL VIEW FROM ELEVATED PLATFORM- REPAIRS TO ROOF OF BLDG L168	3066
35	22/11/94	L	VIEW FROM ELEVATED PLATFORM LOOKING NORTH ACROSS QUEENS MEAD	3067
36	22/11/94	P	GENERAL VIEW FROM ELEVATED PLATFORM LOOKING SOUTH	3068
37	22/11/94	P	GENERAL VIEW FROM ELEVATED PLATFORM LOOKING SOUTH	3069

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: 105/9709

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1	22/11/94	H	GENERAL VIEW FROM ELEVATED PLATFORM LOOKING WEST	3070
2	22/11/94	P	GENERAL VIEW FROM ELEVATED PLATFORM LOOKING SOUTH WEST	3071
3	22/11/94	L / M	GENERAL VIEW FROM ELEVATED PLATFORM LOOKING NORTH EAST	3072
4	22/11/94	H	GENERAL VIEW FROM ELEVATED PLATFORM LOOKING SOUTH WEST	3073
5	22/11/94	P	GENERAL VIEW FROM ELEVATED PLATFORM LOOKING SOUTH	3074
6			NOT USED	
7	23/11/94	S	MOVING BARGE IN CANAL NORTH OF BUILDING L136	3075
8	23/11/94	S	MOVING BARGE IN CANAL NORTH OF BUILDING L136	3076
9			NOT USED	
10			NOT USED	
11	24/11/94	M	TYPICAL VIEW OF DUMP TRUCK	3077
12			NOT USED	
13			NOT USED	

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: 106/5253

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1	25/11/94	H	H17 - PUMPING OUT STORAGE CHAMBER	3078
2	25/11/94	H	FOUL WATER MANHOLE REMOVED NORTH OF H17	3079
3	25/11/94	H	FOUL WATER MANHOLE REMOVED NORTH OF H17	3080
4			NOT USED	
5	28/11/94	P	SOUTH SIDE OF BUILDING A210 - EXCAVATING PRIOR TO CLAY LINING	3081
6	28/11/94	S	BUILDING E7 - EXCAVATED BRICKWORK PAVEMENT / WALKWAY	3082
7	28/11/94	S	BUILDING E7 - EXCAVATED BRICKWORK PAVEMENT / WALKWAY	3083
8	28/11/94	S	CLEANING OUT LOCK NORTH OF BUILDING L136	3084
9	28/11/94	S	CLEANING OUT LOCK NORTH OF BUILDING L136	3085
10	28/11/94	S	FOUNDATIONS EXCAVATED BY BARGES IN CANAL EAST F BUILDING L100	3086
11	28/11/94	S	FOUNDATIONS EXCAVATED BY BARGES IN CANAL EAST F BUILDING L100	3087
12	28/11/94	S	1ST BARGE MOVED NORTH OF BUILDING L136	3088
R	28/11/94	S	BARGES WAITING TO BE MOVED IN CANAL NORTH OF BUILDING L136	3089

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: 107/6238

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1			NOT USED	
2	1/12/94	H	ROAD CROSSING UNDER CONSTRUCTION IN CANAL NORTH OF HOPPIT POOL	3090
3	1/12/94	M	ROAD CROSSING UNDER CONSTRUCTION IN CANAL NORTH OF HOPPIT POOL	3091
4	1/12/94	P	BUILDING A210 - NEW ROAD TO MACHINE SHOP	3092
5	1/12/94	P	BUILDING A210 - NEW ROAD TO MACHINE SHOP	3093
6			NOT USED	
7			NOT USED	
8			NOT USED	
9			NOT USED	
10			NOT USED	
11			NOT USED	
12	6/12/94	M	EXPLOSIVES IGNITION SYSTEM FOUND IN SPOIL ADJACENT TO BUILDING L110 (HEAT TREATED ON BURNING GROUND)	3094
13	6/12/94	M	DISCARDED BATTERY PACK FOUND IN SPOIL ADJACENT TO BUILDING L110	3095
14	13/12/94	B	CONTROLLED FIRE ON BURNING GROUND	3096
15	13/12/94	B	CONTROLLED FIRE ON BURNING GROUND	3097
16	16/12/94	S	LOCK CLEANED OUT NORTH OF BUILDING L136	3098
17	16/12/94	M	EXCAVATION AROUND BUILDING L110	3099
18	16/12/94	S	BARGES IN CANAL EAST OF BUILDING L109	3100
19	16/12/94	M	EXCAVATION OF CANAL SOUTH OF BUILDING L109	3101
20	16/12/94	S	CLEANING CAUSEWAY EAST OF BUILDING L111	3102
21	16/12/94	H	COMPLETED ROAD CROSSING OF CANAL NORTH OF HOPPIT POOL	3103

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: 108/8183

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1	4/1/95	H	EXCAVATION ADJACENT OT WEST BOUNDARY FENCE	3104
2	4/1/95	H	EXCAVATION ADJACENT OT WEST BOUNDARY FENCE	3105
3	4/1/95	H	RUBBLE INFILL FOUND IN TRENCH ADJACENT TO BOUNDARY FENCE	3106
4	4/1/95	P	ASH PIT EXCAVATION EAST OF BUILDING A210 - LOOKING EAST	3107
5	4/1/95	P	ASH PIT EXCAVATION LOOKING WEST TOWARDS BUILDING A210	3108
6	4/1/95	P	ASH PIT EXCAVATION LOOKING WEST TOWARDS BUILDING A210	3109
7	4/1/95	P	ASH PIT EXCAVATION LOOKING NORTH ADJACENT TO BUILDING A210	3110
8	4/1/95	P	ASH PIT EXCAVATION LOOKING WEST TOWARDS BUILDING A210	3111
9	4/1/95	P	EAST END OF ASH PIT LOOKING NORTH TO BUILDING A214	3112
10	4/1/95	P	ASH PIT EXCAVATION EAST OF BUILDING A210	3113
11	4/1/95	P	EXCAVATION OF DRAIN ADJACENT TO BUILDING A214	3114
12	4/1/95	S	SSSI - SOUTH WEST OF BUILDING S31 - TEMPORARY ACCESS BRIDGE FOR MATERIAL TO STEAM MAIN ROUTES	3115
13	4/1/95	S	SSSI - COVERING STEAM MAIN ROUTES	3116
14	4/1/95	S	SCRUTINY EXERCISE IN HERONRY AREA	3117
15	12/1/95	S	BUILDING E14 MOUND AFTER CLEARANCE	3118
16	12/1/95	S	BUILDING 88A MOUND AFTER CLEARANCE	3119
17	12/1/95	S	BUILDING 88A MOUND AFTER CLEARANCE	3120
18	12/1/95	S	MOUND WEST OF BUILDING S30 AFTER CLEARANCE	3121
19	12/1/95	S	ACCESS TO SSSI FOR SCRUTINY WORKS	3122
20	12/1/95	S	MOUND WEST OF BUILDING S30 AFTER CLEARANCE	3123
21	12/1/95	S	BUILDING S31 - MOUND CLEARANCE IN PROGRESS	3124
22	12/1/95	S	GENERAL VIEW SOUTHWARDS FROM BUILDING 88A	3125
23	12/1/95	S	HERONRY SCRUTINY IN PROGRESS	3126
24	12/1/95	S	BUILDING S30 MOUND AFTER CLEARANCE	3127
25	12/1/95	S	BUILDING S90 MOUND AFTER CLEARANCE	3128
26	12/1/95	S	CLEARED CANAL FROM BUILDING S90 NORTHWARDS	3129
27	20/1/95	P	BUILDING A210 EAST (BETWEEN BUILDING A210 AND BUILDING A214)	3130
28	20/1/95	P	BUILDING A210 EAST (BETWEEN BUILDING A210 AND BUILDING A214)	3131
29	20/1/95	P	BUILDING A210 EAST (BETWEEN BUILDING A210 AND BUILDING A214)	3132
30	20/1/95	P	BUILDING A210 EAST (BETWEEN BUILDING A210 AND BUILDING A214)	3133
31			NOT USED	
32			NOT USED	
33	30/1/95	H	VIEW LOOKING NORTH SHOWING FLOODING DUE TO HEAVY RAIN	3134
34	30/1/95	P	REMEDIATION NORTH EAST OF BUILDING A214	3135
35	30/1/95	P	REMEDIATION NORTH EAST OF BUILDING A214	3136
36	30/1/95	S	REMEDIATION AROUND PRESS HOUSE	3137
37	30/1/95	P	COVERING STREAM MAIN ROUTE EAST OF BUILDING 88A	3138

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: 109/9392

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1	30/1/95	S	EXCAVATION TO REMOVE TNT CONTAMINATION N/W SIDE OF BUILDING E2	3139
2	30/1/95	S	EXCAVATION TO REMOVE TNT CONTAMINATION N/W SIDE OF BUILDING E2	3140
3	7/2/95	H	CLEARANCE OF PIT CONTAINING WASTE - SOUTH WEST OF BUILDING H7	3141
4	7/2/95	H	CLEARANCE OF PIT CONTAINING WASTE - SOUTH WEST OF BUILDING H7	3142
5	7/2/95	H	CLEARANCE OF PIT CONTAINING WASTE - SOUTH WEST OF BUILDING H7	3143
6	7/2/945	H	CLEARANCE OF PIT CONTAINING WASTE - SOUTH WEST OF BUILDING H7	3144
7	7/2/95	H	CLEARANCE OF PIT CONTAINING WASTE - SOUTH WEST OF BUILDING H7	3145
8	7/2/95	H	CLEARANCE OF PIT CONTAINING WASTE - SOUTH WEST OF BUILDING H7	3146
9			NOT USED	
10	7/2/95	H	HORSEMILL STREAM BANK REINSTATEMENT (AT FENCE LINE ONLY)	3147
11	7/2/95	H	CLEARANCE OF PIT CONTAINING WASTE - SOUTH WEST OF BUILDING H7	3148
12	7/2/95	H	GENERAL VIEW LOOKING SOUTH ACROSS STRIPED AREA 'H'	3149
13	7/2/95	H	WASTE STOCKPILE NORTH OF BUILDING H7	3150
14	7/2/95	N	'CLAY PIT' DURING CLAY WINNING PROCESS (POOR WEATHER CONDITIONS)	3151
15	7/2/95	N	'CLAY PIT' DURING CLAY WINNING PROCESS (POOR WEATHER CONDITIONS)	3152
16	7/2/95	N	'CLAY PIT' DURING CLAY WINNING PROCESS (POOR WEATHER CONDITIONS)	3153
17	7/2/95	N	'CLAY PIT' DURING CLAY WINNING PROCESS (POOR WEATHER CONDITIONS)	3154
18	7/2/95	S	REMEDIATION AROUND WATER POWERED PRESS HOUSE (BUILDING 103)	3155
19	10/2/95	H	CLEARANCE OF PIT CONTAINING WASTE - SOUTH WEST OF BUILDING H7	3156
20	16/2/95	S	DISCOVERY OF EXPERIMENTAL HOUSE FOUNDATIONS EAST OF BUILDING L189	3157
21	16/2/95	S	DISCOVERY OF EXPERIMENTAL HOUSE FOUNDATIONS EAST OF BUILDING L189	3158
22	16/2/95	S	'BARREL GRAVEYARD' - STEAM MAIN ROUTE EXCAVATED	3159
23	16/2/95	S	CLEARANCE OF FORMER STEAM MAIN ROUTE	3160
24	21/2/95	S	'BARREL GRAVEYARD' - CAPPED STEAM MAIN ROUTE	3161
25	21/2/95	S	BUILDING S31 AND BRIDGE No. 10 - GENERAL VIEW SHOWING REMEDIATION TO ROAD EMBANKMENT AND BUILDING S31 TETRYL CONTAMINATED AREA	3162
26	21/2/95	S	BRIDGE No. 10 CLEARANCE WORKS LOOKING SOUTH - REMEDIATION TO ROAD EMBANKMENT	3163
27	21/2/95	S	BLDG S31 - REMEDIATION OF TETRYL CONTAMINATED AREA LOOKING WEST	3164
28	21/2/95	S	BRIDGE No. 10 NORTH EAST ROAD EMBANKMENT REMEDIAL WORK	3165
29	21/2/95	S	EAST OF BUILDING S31 - LOOKING TOWARDS BUILDING 88A	3166
30	21/2/95	S	BUILDING S31 / 95A - HEXAGONAL STRUCTURE, RODDING OUT DRAINAGE	3167
31			NOT USED	
32			NOT USED	
33	21/2/95	H	LOOKING NORTH - GROUND STRIPPING IN PROGRESS	3168
34	6/3/95	H	HOPPIT POOL - PORTADAM LTD SURVEYING DEPTH PRIOR TO INSTALLATION OF TEMPORARY DAM	3169
35	6/3/95	H	HOPPIT POOL (BRIDGE No. 17) - INSTALLATION OF TEMPORARY DAM	3170
36	6/3/95	H	HOPPIT POOL (BRIDGE No. 17) - INSTALLATION OF TEMPORARY DAM	3171

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: 110/9709

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1	7/3/95	H	TEMPORARY DAM AT HOPPIT POOL	3172
2	7/3/95	H	TEMPORARY DAM AT HOPPIT POOL	3173
3	7/3/95	H	EXCAVATION OF CANAL NORTH OF HOPPIT POOL	3174
4	7/3/95	H	LICENSED ASBESTOS CONTRACTOR CLEANING CANAL NORTH OF HOPPIT POOL	3175
5	7/3/95	H	VIEW OF DE-WATERING OF HOPPIT POOL - LOOKING SOUTH	3176
6	7/3/95	H	HOPPIT POOL LOOKING NORTH TO CANAL ENTRANCE	3177
7	8/3/95	H	NATIONAL RIVERS AUTHORITY CATCHING FISH AT HOPPIT POOL	3178
8	8/3/95	H	BRIDGE No. 17 FOUNDATIONS ON WEST SIDE	3179
9	8/3/95	H	BRIDGE No. 17 FOUNDATIONS ON EAST SIDE	3180
10	8/3/95	H	VIEW LOOKING NORTH TOWARDS BRIDGE No. 17 SHOWING TEMPORARY DAM	3181
11	9/3/95	H	EXCAVATION OF HOPPIT POOL IN PROGRESS	3182
12	9/3/95	H	HOPPIT POOL - CANAL ENTRANCE LOOKING SOUTH	3183
13	9/3/95	P	COMPLETED CLAY REMEDIATION TO SHEET PILE WALL	3184
14	9/3/95	H	HOPPIT POOL - PIPE SUCTION GUARD	3185
15	9/3/95	H	HOPPIT POOL - RAMP CONSTRUCTION IN PROGRESS	3186
16			NOT USED	
17	10/3/95	H	HOPPIT POOL - EXCAVATION IN PROGRESS	3187
18	10/3/95	M	CORDITE AREA - SCRAPE LOOKING EAST	3188
19			NOT USED	
20			NOT USED	
21			NOT USED	
22			NOT USED	
23			NOT USED	
24			NOT USED	
25			NOT USED	
26			NOT USED	
27	16/3/95	H	CLEARED CANAL LOOKING SOUTH TO HOPPIT POOL	3189
28	16/3/95	H	EXCAVATION OF CANAL LOOKING NORTH FROM HOPPIT POOL IN PROGRESS	3190
29	16/3/95	H	HOPPIT POOL - LOOKING SOUTH	3191
30	16/3/95	P	WORK IN PROGRESS WEST OF BUILDING A221 BOUNDARY WALL	3192
31	16/3/95	M	SCRAPED DITCH IN CORDITE AREA - LOOKING EAST	3193
32	16/3/95	M	SCRAPED DITCH IN CORDITE AREA - LOOKING EAST	3194
33	16/3/95	M	WEST END OF MAIN DITCH IN CORDITE AREA	3195
34	16/3/95	H	EXPLOSIVES FIND FROM HOPPIT POOL	3196
35			NOT USED	
36			NOT USED	
37			NOT USED	

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: 111/9913

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1			NOT USED	
2			NOT USED	
3			NOT USED	
4			NOT USED	
5			NOT USED	
6	17/3/95	B	BURNING GROUND - 'HEAT TREATMENT' OF EXPLOSIVELY CONTAMINATED SOILS	3197
7	17/3/95	H	HOPPIT POOL - REMEDIATION AND RECOVERY OF 'MILLSTONES'	3198
8	17/3/95	H	HOPPIT POOL - REMEDIATION AND RECOVERY OF 'MILLSTONES'	3199
9	17/3/95	S	IGNITION WIRE / GLASS FOUND BY BUILDING S90	3200
10			NOT USED	
11	20/3/95	H	HOPPIT POOL REMEDIATION - WATER JETTING EAST REVETMENT TO REMOVE CONTAMINATED SEDIMENT	3201
12	20/3/95	H	HOPPIT POOL REMEDIATION - LOOKING NORTH	3202
R	20/3/95	H	HOPPIT POOL REMEDIATION - WATER JETTING EAST REVETMENT TO REMOVE CONTAMINATED SEDIMENT	3203

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: 112/0858

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1	29/3/95	H	HOPPIT POOL REMEDIATION - EAST REVETMENT WALL	3204
2	29/3/95	H	HOPPIT POOL REMEDIATION - EAST REVETMENT WALL	3205
3	29/3/95	H	HOPPIT POOL REMEDIATION	3206
4	29/3/95	H	HOPPIT POOL REMEDIATION	3207
5	29/3/95	H	HOPPIT POOL REMEDIATION - LOOKING NORTH	3208
6	29/3/95	H	BRIDGE No 17 - VIEW OF UNDERSIDE OF THE STRUCTURE - LOOKING TOWARDS WEST ABUTMENT	3209
7			NOT USED	
8	29/3/95	H	BRIDGE No 17 - VIEW OF UNDERSIDE OF STRUCTURE LOOKING TOWARDS EAST ABUTMENT	3210
9	29/3/95	H	HOPPIT POOL REMEDIATION - VOID BENEATH BRIDGE No. 17 EAST ABUTMENT	3211
10	29/3/95	H	HOPPIT POOL REMEDIATION - VIEW OF LOCKS AT NORTHERN END	3212
11	29/3/95	H	AREA 'H' REMEDIATION / CLAY PLACEMENT OVER FORMER BLDG H10 AREA	3213
12			NOT USED	
13	29/3/95	H	BUILDING H17 - MANHOLE EXPOSED TO EAST OF BUILDING	3214
14	29/3/95	H	BRIDGE No 17 - EASTERN ABUTMENT	3215
15	29/3/95	H	BRIDGE No 17 - WESTERN ABUTMENT	3216
16	29/3/95	H	CLAY BANKING ADJACENT TO BRIDGE No. 17	3217
17	31/3/95	H	HOPPIT POOL REMEDIATION - BRIDGE No. 17	3218
18	31/3/95	H	HOPPIT POOL - GENERAL VIEW OF WORKS FROM WITHIN POOL	3219
19	31/3/95	H	REMEDIATION ADJACENT TO BLDG A221 WEST BOUNDARY - LOOKING NORTH	3220
20	31/3/95	P	DRAINAGE INTO MANHOLE ADJACENT TO BUILDING A221 WEST BOUNDARY	3221
21	31/3/95	P	BUILDING A238 POLICE LODGE - CLEARED OUT SERVICES TRENCH NORTH OF THE BUILDING - VIEW LOOKING SOUTH	3222
22	31/3/95	H	HOPPIT POOL REMEDIATION - LOOKING SOUTH TOWARDS TEMPORARY DAM	3223
23	31/3/95	S	WATER TANK BASE NORTH OF BUILDING E12	3224
24	31/3/95	S	BUILDING E2 MOUND - REMOVAL OF ASBESTOS CONTAMINATED SURFACE	3225
25	31/3/95	S	BUILDING E2 MOUND - REMOVAL OF ASBESTOS CONTAMINATED SURFACE	3226
26	31/3/95	N	LOADING CLAY FOR TRANSPORTATION TO OTHER PARTS OF THE SITE	3227
27	31/3/95	N	LOADING CLAY FOR TRANSPORTATION TO OTHER PARTS OF THE SITE	3228
28	3/4/95	H	HOPPIT POOL REMEDIATION - BRIDGE No. 17 WEST ABUTMENT	3229
29	3/4/95	H	HOPPIT POOL REMEDIATION - BRIDGE No. 17 EAST ABUTMENT	3230
30	3/4/95	H	HOPPIT POOL REMEDIATION - LOOKING SOUTH	3231
31	3/4/95	H	HOPPIT POOL REMEDIATION - LOOKING SOUTH	3232
32	5/4/95	H	HOPPIT POOL REMEDIATION	3233
33	5/4/95	H	HOPPIT POOL REMEDIATION - GENERAL VIEW LOOKING SOUTH WEST	3234
34	5/4/95	H	HOPPIT POOL REMEDIATION - NORTH EAST CORNER	3235
35	5/4/95	H	HOPPIT POOL REMEDIATION - NORTH WEST CORNER - WORKS IN PROGRESS	3236
36	5/4/95	H	HOPPIT POOL REMEDIATION - GENERAL VIEW LOOKING SOUTH	3237
37	6/4/95	H	HOPPIT POOL REMEDIATION - NORTH EAST CORNER SHOWING EXCAVATION	3238

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: 113/1871

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1	6/4/95	H	HOPPIT POOL REMEDIATION - NORTH END	3239
2	6/4/95	H	HOPPIT POOL REMEDIATION - NORTH END	3240
3	7/4/95	H	HOPPIT POOL REMEDIATION - NORTH WEST CORNER	3241
4	7/4/95	H	HOPPIT POOL REMEDIATION	3242
5	7/4/95	S	WELL NORTH OF BUILDING ARS2	3243
6	7/4/95	S	WELL NORTH OF BUILDING ARS2	3244
7	10/4/95	P	SEPTIC TANK BEING DELIVERED FOR BUILDING A221	3245
8	11/4/95	H	HOPPIT POOL REMEDIATION - NORTH WEST CORNER	3246
9	13/4/95	H	HOPPIT POOL REMEDIATION - WEST BANK	3247
10	13/4/95	H	HOPPIT POOL REMEDIATION - LOOKING NORTH WEST	3248
11	13/4/95	H	HOPPIT POOL REMEDIATION - LOOKING SOUTH (JOB NEARING COMPLETION)	3249
12	13/4/95	H	HOPPIT POOL REMEDIATION - NORTH WEST CORNER , COMPLETING LAST SECTION OF WALL	3250
13	13/4/95	H	HOPPIT POOL REMEDIATION - LOOKING NORTH	3251
14	13/4/95	H	HOPPIT POOL REMEDIATION - PROPPING OD WALLS IN SLUICE IN PROGRESS	3252
15	13/4/95	H	HOPPIT POOL REMEDIATION - DISMANTLING SUCTION PUMP PIPEWORK	3253
16			NOT USED	
17	19/4/95	S	BUILDING S33 - EAST (TETRYL DEPOSITS IN GROUND (YELLOW MATERIAL)	3254
18	19/4/95	S	BUILDING S33 - EAST (TETRYL DEPOSITS IN GROUND (YELLOW MATERIAL)	3255
19	19/4/95	S	BUILDING S33 - EAST (TETRYL DEPOSITS IN GROUND (YELLOW MATERIAL)	3256
20	19/4/95	P	AREA 'P' NORTH - REFILLING OF REDUCED GROUND SOUTH OF BUILDING A221	3257
21	19/4/95	P	AREA 'P' NORTH - GENERAL VIEW LOOKING SOUTH	3258
22			NOT USED	
23	27/4/95	H	REMOVAL OF FWD'S ADJACENT BUILDING H17 (HOPPIT POOL IN BACKGROUND)	3259
24	27/4/95	H	REMOVAL OF FWD'S ADJACENT BUILDING H17 (HOPPIT POOL IN BACKGROUND)	3260
25	27/4/95	S	SETTLING TANKS - NORTH WEST OF BUILDING 83B - CLEANING OUT TANKS	3261
26	27/4/95	S	SETTLING TANKS - NORTH WEST OF BUILDING 83B - MANHOLE ADJACENT	3262
27	27/4/95	S	SETTLING TANKS - NORTH WEST OF BUILDING 83B - FIRST CHAMBER	3263
28	27/4/95	S	CANAL INTERSECTION 26- COFFERDAM INSTALLATION PILING RIG IN POSITION	3264
29	27/4/95	S	BUILDING S31 - TETRYL CONTAMINATION - REMOVAL	3265
30	27/4/95	S	BUILDING S31 - TETRYL CONTAMINATION - REMOVAL	3266
31			NOT USED	
32			NOT USED	
33	28/4/95	H	BUILDING H17 - FWD REMOVAL	3267
34	28/4/95	S	REMOVAL OF CORDITE CONTAMINATED GROUND SOUTH OF BUILDING L189	3268
35	28/4/95	S	CANAL - PARTIAL CLEARANCE ADJACENT ACCESS ROAD - EAST OF BLDG L189	3269
36	28/4/95	T	CANAL INTERSECTION 26 - INSTALLATION OF COFFERDAM	3270
R	28/4/95	T	CANAL INTERSECTION 26 - INSTALLATION OF COFFERDAM	3271

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: 114/2412

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1			NOT USED	
2	2/5/95	S	BUILDING S90 - CLEANING OUT BRICK WELL ADJACENT S90	3272
3	2/5/95	H	H17 - FWD CAPPED OFF AT NORTH EAST CORNER	3273
4	4/5/95	T	INTERSECTION 26 - EXCAVATION AROUND BARGE	3274
5	4/5/95	T	INTERSECTION 26 - EXCAVATION AROUND BARGE	3275
6	5/5/95	T	INTERSECTION 26 - MOVING BARGE OUT OF EXCAVATION AREA	3276
7	5/5/95	T	INTERSECTION 26 - LIFTING BARGE OUT OF EXCAVATION	3277
8	5/5/95	T	INTERSECTION 26 - BARGE REMOVED FROM THE EXCAVATION	3278
9	6/5/95	T	INTERSECTION 26 - EXCAVATION OF CONTAMINATED GROUND BEHIND COFFERDAM	3279
10	6/5/95	T	INTERSECTION 26 - EXCAVATION OF CONTAMINATED GROUND BEHIND COFFERDAM	3280
11	6/5/95	T	INTERSECTION 26 - EXCAVATION OF CONTAMINATED GROUND BEHIND COFFERDAM	3281
12	6/5/95	T	INTERSECTION 26 - CLAY FILL REINSTATEMENT OF MILLHEAD STREAM BANK	3282
13	6/5/95	T	INTERSECTION 26 - CLAY FILL REINSTATEMENT OF MILLHEAD STREAM BANK	3283
14	9/5/95	T	INTERSECTION 25 - EXCAVATION OF CONTAMINATED GROUND FROM BEHIND COFFERDAM	3284
15	9/5/95	B	CORDITE RECOVERED FROM CANAL EXCAVATIONS	3285
16	9/5/95	B	CORDITE FIRING ON BURNING GROUND - COMMENCEMENT	3286
17	9/5/95	B	CORDITE FIRING ON BURNING GROUND	3287
18	9/5/95	B	CORDITE FIRING ON BURNING GROUND	3288
19	9/5/95	B	CORDITE FIRING ON BURNING GROUND	3289
20	9/5/95	B	CORDITE FIRING ON BURNING GROUND	3290
21	9/5/95	T	INTERSECTION 26-CLAY FILLING-REINSTATEMENT- HORSEMILL STREAM BANK	3291
22	9/5/95	T	INTERSECTION 26-CLAY FILLING-REINSTATEMENT- HORSEMILL STREAM BANK	3292
23	9/5/95	P	ENLARGING APPROACH ROAD TO BUILDING A210	3293
24	11/5/95	T	INTERSECTION 25 - FINISHED CLAY BANK	3294
25	11/5/95	S	INTERSECTION 21 - EXCAVATION OF CANAL BANK	3295
26	11/5/95	S	INTERSECTION 21 - REMOVAL OF CONTAMINATED GROUND	3296
27	11/5/95	M	EAST OF BUILDING L160 - CANAL EXCAVATION	3297
28	11/5/95	M	EAST OF BUILDING L160 - CANAL EXCAVATION	3298
29	11/5/95	M	EAST OF BUILDING L160 - CANAL EXCAVATION	3299
30	11/5/95	M	EAST OF BUILDING L160 - CANAL EXCAVATION	3300
31	11/5/95	M	EAST OF BUILDING L160 - CANAL EXCAVATION	3301
32	11/5/95	P	SAMPLE No. 41196	3302
33	12/5/95	S	INTERSECTION 21 - EXCAVATION AROUND BURIED BARGE	3303
34	12/5/95	S	INTERSECTION 21 - EXCAVATION AROUND BURIED BARGE	3304
35	12/5/95	M	EAST OF BUILDING L160 - CANAL EXCAVATION	3305
36	12/5/95	M	EAST OF BUILDING L160 - CANAL EXCAVATION	3306
37	12/5/95	M	EAST OF BUILDING L160 - CANAL EXCAVATION	3307

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: 115/3019

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1	12/5/95	M	CANAL EXCAVATION EAST OF BUILDING L160 - REMOVAL OF OIL / TAR	3308
2	12/5/95	M	CANAL EXCAVATION EAST OF BUILDING L160 - REMOVAL OF OIL / TAR	3309
3	12/5/95	M	CANAL EXCAVATION EAST OF BUILDING L160 - REMOVAL OF OIL / TAR	3310
4	12/5/95	M	CANAL EXCAVATION EAST OF BUILDING L160 - REMOVAL OF OIL / TAR	3311
5	12/5/95	M	CANAL EXCAVATION EAST OF BUILDING L160 - REMOVAL OF OIL / TAR	3312
6	12/5/95	M	CANAL EXCAVATION EAST OF BUILDING L160 - REMOVAL OF OIL / TAR	3313
7	12/5/95	M	CANAL EXCAVATION EAST OF BUILDING L160 - REMOVAL OF OIL / TAR	3314
8	12/5/95	S	INTERSECTION 21 - BARGE REMOVAL	3315
9	12/5/95	S	INTERSECTION 21 - BARGE REMOVAL	3316
10	12/5/95	S	INTERSECTION 21 - BARGE REMOVAL	3317
11	12/5/95	S	INTERSECTION 21 - BARGE REMOVAL	3318
12	12/5/95	S	INTERSECTION 21 - BARGE REMOVAL	3319
13	12/5/95	M	CANAL EXCAVATION EAST OF BUILDING L160 - REMOVAL OF OIL / TAR	320
14	13/5/95	S	INTERSECTION 21 - CLAY INFILLING TO REINSTATE BANK	3321
15	13/5/95	S	INTERSECTION 21 - CLAY INFILLING TO REINSTATE BANK	3322
16	16/5/95	M	BARGE FROM INTERSECTION 21 IN TRANSIT TO BUILDING L157	3323
17	16/5/95	M	BARGE FROM INTERSECTION 21 IN TRANSIT TO BUILDING L157	3324
18			NOT USED	
19	18/5/95	M	GAS WORKS SITE - EAST OF BUILDING L159	3325
20	18/5/95	M	GAS WORKS SITE - EAST OF BUILDING L159	3326
21	18/5/95	M	CANAL EXCAVATION EAST OF BUILDING L160 - REMOVAL OF OIL / TAR	3327
22	18/5/95	M	CANAL EXCAVATION EAST OF BUILDING L160 - REMOVAL OF OIL / TAR	3328
23	18/5/95	M	GAS WORKS AREA - LOOKING NORTH	3329
24	18/5/95	B	TREE PLANTING EAST OF BURNING GROUND - SOUTH OF BRIDGE No. 10	3330
25	18/5/95	S	REMEDIATION SOUTH OF BUILDING S31	3331
26	18/5/95	L	CANAL DREDGINGS - DRIED AND STOCKPILED ON QUEENS MEAD	3332
27			NOT USED	
28	18/5/95	H	AREA H SOUTH - ACCESS ROAD REINSTATEMENT FOLLOWING REMOVAL OF CONTAMINATED GROUND	3333
29	18/5/95	H	AREA H SOUTH - ACCESS ROAD REINSTATEMENT FOLLOWING REMOVAL OF CONTAMINATED GROUND	3334
30	19/5/95	M	BARGE - EX INTERSECTION 21	3335
31	19/5/95	M	BARGE - EX INTERSECTION 21	3336
32	19/5/95	M	BARGE - EX INTERSECTION 21	3337
33	19/5/95	B	BURNING GROUND REMEDIATION IN PROGRESS	3338
34	19/5/95	B	BURNING GROUND REMEDIATION IN PROGRESS	3339
35			NOT USED	
36			NOT USED	
37			NOT USED	

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: 116/4287

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1	23/5/95	M	BUILDING L160 / L159 - FWD REMOVAL	3340
2			NOT USED	
3			NOT USED	
4	24/5/95	S	WEST OF BUILDING E12 - REMOVAL OF ASBESTOS CONTAMINATED SOIL	3341
5	24/5/95	S	WEST OF BUILDING E12 - SUSPECT 'YELLOW' DEPOSITS	3342
6	24/5/95	B	EXCAVATED BURNING GROUND FILL MATERIAL LAID OUT FOR SAMPLING	3343
7	27/5/95	S	BURNT OUT BARGE AT BUILDING 88A (SUBJECT OF VANDALISM)	3344
8	27/5/95	S	BURNT OUT BARGE AT BUILDING 88A (SUBJECT OF VANDALISM)	3345
9	27/5/95	S	BURNT OUT BARGE AT BUILDING 88A (SUBJECT OF VANDALISM)	3346
10	31/5/95	H	HOPPIT ROAD/HOPPIT CANAL SHOWING UNSTABLE WALL AT ROAD CROSSING	3347
11	31/5/95	S	INTERSECTION 21 - NORTH BANK BEFORE REFILLING	3348
12	31/5/95	S	INTERSECTION 21 - NORTH BANK BEFORE REFILLING	3349
13	31/5/95	S	INTERSECTION 27 - EXCAVATION AROUND BURIED BARGE	3350
14	31/5/95	S	INTERSECTION 27 - EXCAVATION AROUND BURIED BARGE	3351
15	1/6/95	H	REMAINS OF BURIED ANIMAL CARCASSES LOCATED IN PIT N / W OF BLDG H17	3352
16	1/6/95	H	REMAINS OF BURIED ANIMAL CARCASSES LOCATED IN PIT N / W OF BLDG H17	3353
17	5/6/95	H	REINSTATEMENT OF EXCAVATED CANAL BANK LOOKING SOUTH TOWARDS HOPPITS POOL	3354
18	5/6/95	S	INTERSECTION 27-LOCATION OF 2ND BARGE IN FACE OF CANAL - LOOKING E.	3355
19	5/6/95	S	INTERSECTION 27 - LOCATION OF 1ST BARGE CLEANED OUT LOOKING WEST	3356
20	7/6/95	N	YOUNG HERON FOUND AT NEW HILL BEFORE PLACING BACK IN HERONRY	3357
21	8/6/95	S	INTERSECTION 27 - PRIOR TO BACKFILL	3358
22	8/6/95	T	INTERSECTION 26 - LOOKING SOUTH (CLAY REINSTATEMENT COMPLETE)	3359
23			NOT USED	
24			NOT USED	
25	9/6/95	H	DECONTAMINATION OF ANIMAL BONES FOUND IN PIT ADJACENT BLDG H17	3360
26	9/6/95	H	VIEW NORTH OF WESTERN HOPPIT CANAL (DECONTAMINATION OF BONES IN PROGRESS)	3361
27	9/6/95	H	DECONTAMINATION OF ANIMAL BONES FOUND IN PIT ADJACENT BLDG H17	3362
28	12/6/95	S	INTERSECTION 29 - HORSEMILL STREAM	3363
29	12/6/95	S	INTERSECTION 29 - REMOVAL OF CONTAMINATED MATERIAL FROM BEHIND HORSEMILL STREAM BANK	3364
30	12/6/95	M	REMOVAL OD OIL / TAR CONTAMINATED GROUND EAST OF BLDGS L160 / L159	3365
31	13/6/95	M	BUILDING L157 - SWAB SAMPLE LOCATION 18039	3366
32	13/6/95	M	BUILDING L157 - SWAB SAMPLE LOCATION 18040	3367
33	13/6/95	M	BUILDING L157 - SWAB SAMPLE LOCATION 18041	3368
34	13/6/95	M	BUILDING L157 - SWAB SAMPLE LOCATION 18042	3369
35	13/6/95	M	BUILDING L157 - SWAB SAMPLE LOCATION 18043	3370
36	13/6/95	M	BUILDING L157 - SWAB SAMPLE LOCATION 18044	3371
R	13/6/95	M	BUILDING L157 - SWAB SAMPLE LOCATION 18045	3372

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: 117/4631

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1	13/6/95	M	BUILDING L157 - SWAB SAMPLE LOCATION 18046	3373
2	13/6/95	M	BUILDING L157 - SWAB SAMPLE LOCATION 18047	3374
3	13/6/95	M	BUILDING L157 - SWAB SAMPLE LOCATION 18048	3375
4	13/6/95	M	BUILDING L157 - SWAB SAMPLE LOCATION 18049	3376
5	13/6/95	M	BUILDING L157 - SWAB SAMPLE LOCATION 18050	3377
6	13/6/95	M	BUILDING L157 - SWAB SAMPLE LOCATION 18051	3378
7	13/6/95	M	BUILDING L157 - SWAB SAMPLE LOCATION 18052	3379
8	13/6/95	M	BUILDING L157 - SWAB SAMPLE LOCATION 18053	3380
9			NOT USED	
10			NOT USED	
11	13/6/95	M	BUILDING L157 - SWAB SAMPLE LOCATION 18054	3381
12	13/6/95	M	BUILDING L157 - SWAB SAMPLE LOCATION 18055	3382
13	13/6/95	M	BUILDING L157 - SWAB SAMPLE LOCATION 18056	3383
14	13/6/95	M	BUILDING L157 - SWAB SAMPLE LOCATION 18057	3384
15	13/6/95	M	BUILDING L157 - SWAB SAMPLE LOCATION 18058	3385
16	13/6/95	M	BUILDING L157 - SWAB SAMPLE LOCATION 18059	3386
17	13/6/95	M	BUILDING L157 - SWAB SAMPLE LOCATION 18060	3387
18	13/6/95	M	BUILDING L157 - SWAB SAMPLE LOCATION 18061	3388
19	14/6/95	P	REMOVAL OF BRIDGE No. 2 - LOOKING SOUTH	3389
20	14/6/95	P	REMOVAL OF BRIDGE No. 2 - LOOKING SOUTH	3390
21	15/6/95	M	REMOVAL OF OIL/ TAR CONTAMINATION FROM OLD GASWORKS EXCAVATIONS	3391
22	15/6/95	M	REMOVAL OF OIL/ TAR CONTAMINATION FROM OLD GASWORKS EXCAVATIONS	3392
23	20/6/95	M	EXCAVATED CANAL IN CORDITE CONTAMINATED AREA	3393
24	20/6/95	M	DEEP EXCAVATION LOOKING EAST IN OLD GASWORKS AREA	3394
25	20/6/95	M	DEEP EXCAVATION LOOKING SOUTH IN OLD GASWORKS AREA	3395
26	26/6/95	M	DE-WATERING SUMP - LOOKING NORTH IN OLD GASWORKS AREA	3396
27	26/6/95	H	TRIAL PIT 1 - OUTSIDE SECURITY FENCE	3397
28	26/6/95	H	TRIAL PIT 1 - OUTSIDE SECURITY FENCE	3398
29	26/6/95	H	TRIAL PIT 1 - OUTSIDE SECURITY FENCE	3399
30	26/6/95	H	TRIAL PIT 2 - OUTSIDE SECURITY FENCE	3400
31	26/6/95	H	TRIAL PIT 3 - OUTSIDE SECURITY FENCE	3401
32	26/6/95	H	TRIAL PIT 4 - OUTSIDE SECURITY FENCE	3402
33	26/6/95	H	TRIAL PIT 5 - OUTSIDE SECURITY FENCE	3403
34	26/6/95	H	TRIAL PIT 6 - OUTSIDE SECURITY FENCE	3404
35	26/6/95	H	TRIAL PIT 7 - OUTSIDE SECURITY FENCE	3405

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: 118/5828

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1	27/6/95	B	'HEAT TREATMENT' OF TNT CONTAMINATED CHANNEL BLOCKS FROM EX BUILDING E2	3406
2	27/6/95	S	ACID FACTORY CLEARANCE	3407
3	27/6/95	S	ACID FACTORY CLEARANCE	3408
4	27/6/95	S	ACID FACTORY CLEARANCE	3409
5	6/7/95	H	HOPPITS PENINSULAR - TREE STUMP GRINDING MACHINE	3410
6	6/7/95	H	HOPPITS PENINSULAR - TREE STUMP GRINDING MACHINE	3411
7	6/7/95	M	VIEW LOOKING NORTH FROM BRIDGE No. 6 SHOWING EXCAVATED CANAL	3412
8	6/7/95	S	EXCAVATING CANAL NORTH FROM BRIDGE No. 6	3413
9	6/7/95	T	TETRYL FACTORY SITE - GENERAL VIEW LOOKING NORTH BEFORE CAPPING MATERIAL PLACEMENT	3414
10	6/7/95	S	EAST SIDE OF BUILDING E10 LOOKING SOUTH TOWARDS ACID FACTORY	3415
11	6/7/95	S	ACID FACTORY LOOKING SOUTH EAST	3416
12	6/7/95	S	ACID FACTORY LOOKING SOUTH	3417
13	6/7/95	S	ACID FACTORY LOOKING NORTH EAST (BUILDING E10 IN BACKGROUND)	3418
14	6/7/95	S	ACID FACTORY LOOKING NORTH	3419
15	7/7/95	B	27mm AMMUNITION FOUND IN BURNING GROUND DIG	3420
16	7/7/95	B	27mm AMMUNITION FOUND IN BURNING GROUND DIG	3421
17	7/7/95	B	27mm AMMUNITION FOUND IN BURNING GROUND DIG	3422
18	7/7/95	B	27mm AMMUNITION FOUND IN BURNING GROUND DIG	3423
19	7/7/95	H	HIGHBRIDGE STREET ENTRANCE SHOWING COMPLETED CAPPING OF ANCIENT MONUMENT	3424
20	7/7/95	H	HIGHBRIDGE STREET ENTRANCE AREA - CAPPING OF ANCIENT MONUMENT IN PROGRESS	3425
21	7/7/95	B	BUILDING L101 - VIEW OF CANAL EXCAVATION LOOKING SOUTH	3426
22	7/7/95	B	VIEW OF EXCAVATED CANAL NORTH OF BUILDING L101	3427
23	11/7/95	M	VIEW OF CANAL CLEARANCE NORTH FROM BRIDGE No. 6	3428
24	11/7/95	M	VIEW OF CANAL CLEARANCE SOUTH FROM BRIDGE No. 6	3429
25	11/7/95	M	FORMED ACCESS RAMP INTO CANAL BETWEEN BUILDINGS L135 AND L133	3430
26	11/7/95	M	EAST OF BUILDING L155 - DITCH CLEARED, CONFIRMATORY SAMPLING	3431
27	12/7/95	P	BRIDGE No. 2 IN PROCESS OF BEING ASSEMBLED	3432
28	12/7/95	P	BRIDGE No. 2 IN PROCESS OF BEING BUILT	3433
29	12/7/95	P	BRIDGE No. 2 - OLD BRIDGE DECK STRIPPED OFF	3434
30	14/7/95	P	MIDDLE STREAM NORTH OF BRIDGE No. 1 PREPARATIONS FOR 'DRAIN DOWN'	3435
31	14/7/95	P	COLLECTING FISH FROM MIDDLE STREAM DURING 'PUMP DOWN' PROCEDURE	3436
32	14/7/95	P	BUCKET OF FISH RETRIEVED FROM MIDDLE STREAM	3437
33	14/7/95	P	TYPICAL SPECIMEN OF FISH RETRIEVED FROM MIDDLE STREAM	3438
34	15/7/95	S	INTERSECTION 16 - REMOVAL OF CONTAMINATED FILL	3439
35	17/7/95	S	INTERSECTION 31 - REMOVAL OF CONTAMINATED FILL - NORTH END	3440
36	17/7/95	S	INTERSECTION 31 - REMOVAL OF CONTAMINATED FILL - SOUTH END	3441
R	17/7/95	S	INTERSECTION 16 - REMOVAL OF CONTAMINATED FILL	3442

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: 119/7185

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1	17/7/95	T	EXPLOSIVE OBJECTS FOUND - NORTH AREA 'T' AND BURNING GROUND	3443
2	17/7/95	T	EXPLOSIVE OBJECT FOUND - NORTH AREA 'T'	3444
3	17/7/95	B	EXPLOSIVE OBJECT FOUND IN BURNING GROUND	3445
4	18/7/95	P	NEW BRIDGE No. 2 IN POSITION	3446
5	18/7/95	M	REMEDIATED CANAL EAST OF BUILDING L140 - LOOKING NORTH	3447
6	18/7/95	M	REMEDIATED CANAL EAST OF BUILDING L136 - LOOKING SOUTH	3448
7	18/7/95	S	REMEDIATED CANAL LOOKING EAST FROM BUILDING L126 - TOWARDS BRIDGE No. 8	3449
8	18/7/95	P	DE-WATERING OF STREAM EAST OF BUILDING A203	3450
9	19/7/95	P	MACHINE AND DUMPER IN STREAM EAST OF BUILDING A203	3451
10	19/7/95	H	PLACING BALLAST OVERLAY ON ANCIENT MONUMENT ADJACENT MILLHEAD STREAM	3452
11	19/7/95	H	RAKING BALLAST OVERLAY ON ANCIENT MONUMENT ADJACENT MILLHEAD STREAM	3453
12			NOT USED	
13			NOT USED	
14	24/7/95	S	EXCAVATED STEEL TROUGH NORTH OF BUILDING 83B IN ACID FACTORY	3454
15	24/7/95	S	EXCAVATED TROUGH NORTH OF BUILDING 83B IN ACID FACTORY	3455
16	24/7/95	S	EXCAVATED STEEL LINED WELL BEFORE FILLING - NORTH OF BUILDING 83B	3456
17	26/7/95	B	EXPOSED FOOTINGS IN SOUTH WEST CORNER OF BURNING GROUND	3457
18	26/7/95	B	EXPOSED FOOTINGS IN SOUTH WEST CORNER OF BURNING GROUND	3458
19	26/7/95	B	EXCAVATED CANAL IN BURNING GROUND	3459
20	26/7/95	B	EXCAVATED CANAL IN BURNING GROUND NORTH OF BUILDING L101	3460
21	26/7/95	B	EXPOSED ENTRANCE TO CANAL IN BURNING GROUND	3461
22	26/7/95	T	GENERAL VIEW OF AREA 'T' LOOKING NORTH	3462
23	26/7/95	T	GENERAL VIEW OF AREA 'T' LOOKING SOUTH	3463
24	26/7/95	T	GENERAL VIEW OF AREA 'T' LOOKING SOUTH	3464
25	26/7/95	S	EXCAVATIONS AROUND BUILDING S31 LOOKING NORTH	3465
26	26/7/95	S	EXCAVATIONS AROUND BUILDING S31 LOOKING SOUTH	3466
27	26/7/95	S	EXCAVATIONS AROUND BUILDING S31 LOOKING SOUTH	3467
28			NOT USED	
29	28/7/95	H	EXCAVATED CANAL NORTH EAST OF H67 LOOKING SOUTH	3468
30	28/7/95	H	EXCAVATED CANAL NORTH OF H67 LOOKING NORTH	3469
31	28/7/95	H	EXCAVATED CANAL WEST OF BUILDING L123 LOOKING NORTH	3470
32	29/7/95	S	INTERSECTION No. 10 REDUCED LEVEL IN TRACK AREA	3471
33	29/7/95	S	INTERSECTION No. 10 VIEW OF EXCAVATED MILLHEAD STREAM	3472
34	29/7/95	S	INTERSECTION No. 10 VIEW OF EXCAVATED MILLHEAD STREAM	3473
35			NOT USED	
36			NOT USED	
37			NOT USED	

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: 120/8062

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1	9/8/95	B	BURNING GROUND - REFILLED CANAL / EAST ENTRANCE ROAD CROSSING	3474
2	9/8/95	B	BURNING GROUND - REFILLED CANAL / EAST ENTRANCE ROAD CROSSING	3475
3	9/8/95	S	BLDG S31-REFILLED AREA AFTER REMOVAL OF TETRYL CONTAMINATED GRND	3476
4	9/8/95	S	BUILDING S31 - REFILLED AREA AFTER REMOVAL OF TETRYL CONTAMINATED GROUND	3477
5	9/8/95	S	BUILDING S31 - REFILLED AREA AFTER REMOVAL OF TETRYL CONTAMINATED GROUND	3478
6	9/8/95	T	FORMER TETRYL FACTORY SITE - REMEDIATION COMPLETE	3479
7	9/8/95	T	FORMER TETRYL FACTORY SITE - REMEDIATION COMPLETE	3480
8	10/8/95	H	EXCAVATED CANAL AT INTERSECTION No. 8	3481
9	10/8/95	H	INTERSECTION No. 8 - LOOKING EAST- EXCAVATED CANAL	3482
10	10/8/95	S	BUILDING L128 EXCAVATED CANAL LOOKING SOUTH EAST	3483
11	10/8/95	M	CANAL EXCAVATION LOOKING SOUTH FROM BRIDGE No. 6	3484
12	10/8/95	M	BUILDING L143 - SURFACE SCRAPE TO REMOVE VEGETATION FROM GROUND	3485
13	10/8/95	M	SURFACE SCRAPE ADJACENT BUILDING L146	3486
14	10/8/95	S	BRIDGE No. 8 CANAL EXCAVATION LOOKING SOUTH	3487
15	10/8/95	S	BRIDGE No. 8 CANAL EXCAVATION LOOKING NORTH	3488
16	10/8/95	S	BRIDGE No. 8 - REFURBISHMENT WORK	3489
17	10/8/95	M	SURFACE SCRAPE ADJACENT BUILDING L149	3490
18	10/8/95	M	SURFACE SCRAPE ADJACENT BUILDING L151	3491
19	10/8/95	M	REMEDIATED GAS WORKS AREA (PART) ADJACENT BUILDING L155	3492
20	10/8/95	M	REMEDIATED GAS WORKS AREA ADJACENT BUILDING L160	3493
21	10/8/95	M	MIDDLE STREAM CANAL DREDGING BRIDGE No. 4 TO BRIDGE No. 6 - LOOKING NORTH (NOTE: RECOVERED BARGES PLACED HERE FOR PRESERVATION)	3494
22	10/8/95	M	MIDDLE STREAM CANAL DREDGING BY BRIDGE No. 5 LOOKING NORTH	3495
23	10/8/95	M	MIDDLE STREAM CANAL DREDGING BY BRIDGE No. 5 LOOKING SOUTH	3496
24	10/8/95	M	MIDDLE STREAM CANAL DREDGING BY BRIDGE No. 4 LOOKING SOUTH	3497
25	10/8/95	M	MIDDLE STREAM CANAL DREDGING BY BRIDGE No. 4 LOOKING NORTH	3498
26	10/8/95	M	MIDDLE STREAM CANAL DREDGING LOOKING WEST TOWARDS BRIDGE No. 2	3499
27	11/8/95	S	CORDITE RECOVERED FROM CANAL AT BRIDGE No. 8	3500
28	11/8/95	S	CORDITE RECOVERED FROM CANAL AT BRIDGE No. 8	3501
29	11/8/95	S	CORDITE IN CANAL SOUTH OF BRIDGE No. 8	3502
30	11/8/95	S	BURIED BARGE IN CANAL BY BRIDGE No. 8	3503
31	11/8/95	S	ACID FACTORY - CAPPING LAYERS BEING PLACED	3504
32	11/8/95	S	ACID FACTORY - CAPPING LAYERS BEING PLACED	3505
33	11/8/95	S	ACID FACTORY - CAPPING LAYERS BEING PLACED	3506
34	11/8/95	S	ACID FACTORY - CAPPING LAYERS BEING PLACED	3507
35	22/8/95	H	MILLHEAD STREAM LOCK - SITUATED NORTH OF FORMER BUILDING H67	3508
36	22/8/95	H	MILLHEAD STREAM LOCK - SITUATED NORTH OF FORMER BUILDING H67	3509
R	22/8/95	S	BRIDGE No. 8 LOOKING EAST	3510

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG



REMEDIATION RECORD

NEGATIVE REFERENCE: 121/9359

FRAME:	DATE:	AREA:	SUBJECT MATTER:	LOG PAGE NUMBER:
1			NOT USED	
2			NOT USED	
3	24/8/95	S	NEW ROAD OF BRIDGE No. 11 - BETWEEN BUILDING S27 AND BRIDGE No. 36	3511
4	4/9/95	N	SUSPECT 4" SHELL BASE FOUND 65m N/W OF THE CENTRE OF BUILDING S16	3512
5	4/9/95	N	SUSPECT 4" SHELL BASE FOUND 65m N/W OF THE CENTRE OF BUILDING S16	3513
6	4/9/95	N	SUSPECT 4" SHELL BASE FOUND 65m N/W OF THE CENTRE OF BUILDING S16	3514
7	4/9/95	N	CONCRETE BASE FOUND 60m NORTH WEST OF CENTRE OF BUILDING S16	3515
8	4/9/95	N	'PROPELLANT' FOUND IN PIT WITHIN BUILDING S16	3516
9			NOT USED	
10	7/9/95	M	WHEEL SHOT FOR SMEATONS MILL - EAST OF MILLHEAD STREAM LOOKING NORTH (SHUTTLE PLATE FOR MILL IN FOREGROUND)	3517
11	7/9/95	M	WHEEL SHOT FOR SMEATONS MILL - EAST OF MILLHEAD STREAM LOOKING SOUTH (SHUTTLE PLATE FOR MILL IN FOREGROUND)	3518
12	7/9/95	M	WHEEL SHOT FOR SMEATONS MILL - EAST OF MILLHEAD STREAM LOOKING EAST (SHUTTLE PLATE FOR MILL IN FOREGROUND)	3519
13	8/9/95	H	GENERAL VIEW OF HOPPIT POOL LOOKING NORTH FROM BRIDGE No. 17	3520
14	8/9/95	H	GENERAL VIEW OF AREA 'H' TAKEN FROM HIGHBRIDGE STREET ENTRANCE	3521
15	9/9/95	H	GENERAL VIEW NORTH EAST ACROSS THE SITE OF FORMER BUILDING H67	3522
16	9/9/95	S	GENERAL VIEW NORTH OVER FORMER POWER HOUSE AREA	3523
17	9/9/95	S	GENERAL VIEW SOUTH OVER FORMER POWER HOUSE AREA	3524
18	9/9/95	S	GENERAL VIEW NORTH OVER FORMER ACID FACTORY AREA	3525
19	9/9/95	S	GENERAL VIEW NORTH OVER FORMER ACID FACTORY AREA	3526
20	9/9/95	S	GENERAL VIEW S/W ACROSS FROM 83B OVER ADJACENT FOUNDATION SLABS	3527
21	9/9/95	S	GENERAL VIEW SOUTH OF REMEDIATION STEAM MAIN ROUTE SOUTH OF 83B	3528
22	9/9/95	S	GENERAL VIEW NORTH WEST OF BURNING GROUND	3529
23	9/9/95	S	GENERAL VIEW NORTH SHOWING REMEDIATED AREA AROUND BUILDING S31	3530
24	9/9/95	N	GENERAL VIEW SOUTH SHOWING REMEDIATED STEAM MAIN ROUTE OF S16	3531
25	9/9/95	N	GENERAL VIEW EAST SHOWING REMEDIATED STEAM ROUTE EAST OF S5	3532
26	9/9/95	N	VIEW NORTH ACROSS CLAY WINNING PIT	3533
27	9/9/95	N	PROPELLANT FOUND IN VICINITY OF BUILDING S16 & SUSPICIOUS OBJECT WITH WHITE MATERIAL IN END - FOUND BY BUILDING S16	3534
28	9/9/95	L	GENERAL VIEW OF QUEENS MEAD LOOKING NORTH	3535
29	9/9/95	L	GENERAL VIEW OF NORTH END OF QUEENS MEAD AND STEAM MAIN ROUTES	3536
30	9/9/95	H	GENERAL VIEW SOUTH EAST FROM FORMER BUILDING H67 TO THE ROUNDABOUT ON LONG WALK	3537
31	9/9/95	M / S	GENERAL VIEW TO THE WORKS TO THE SOUTH OF BRIDGE No. 8	3538
32	9/9/95	S	GENERAL VIEW LOOKING NORTH WEST TOWARDS BUILDING S33	3539
33	9/9/95	S	GENERAL VIEW OF FORMER BUILDING 63 AFTER REMEDIATION	3540
34	9/9/95	S	GENERAL VIEW OF CANAL AFTER REMEDIATION LOOKING NORTH TO 22A	3541
35	9/9/95	S	VIEW OF REMEDIATED CANAL WEST OF BUILDING 22A	3542
36	9/9/95	S	VIEW OF EAST BANK OF MIDDLE STREAM AFTER REMEDIATION	3543
37	9/9/95	S	WEST ELEVATION OF BUILDING A200	3544

REPORT NO. ESG 2060/94
FORMER RARDE
WALTHAM ABBEY NORTH SITE
REMEDIATION PROJECT
PHOTOGRAPHIC LOG

