

REPORT NO. ESG 2060/94

FORMER RARDE

WALTHAM ABBEY (NORTH SITE)

REMEDICATION PROJECT

PHOTOGRAPHIC LOG

INDEX FOR
PHOTOGRAPHIC RECORD

Environmental Services Group
Property Services Department
Royal Ordnance plc
Westcott
Aylesbury
Bucks. HP18 0NZ

DATE: September 1995 (Issue A)



BRITISH AEROSPACE
DEFENCE

ROYAL ORDNANCE
ENVIRONMENTAL SERVICES GROUP

WAI-1224 Photo Envelopes List

1	63
2	64
3	65
4	66 missing
5	67 missing
6	68 missing
7	69 missing
8	70 missing
9	71 missing
10	72 missing
11	73 missing
12	74 missing
13	75 missing
14	76 missing
15	77 missing
16	78 missing
17	79 missing
18	80 missing
19 missing	81 missing
20	82
21	83 missing
22	84 missing
23	85 missing
24	86 missing
25	87 missing
26	88 missing
27	89 missing
28	90 missing
29	91 missing
30	92 missing
31	93 missing
32	94 missing
33	95 missing
34	96 missing
35	97 missing
36	98 missing
37 missing	99 missing
38	100 missing
39 missing	101 missing
40 missing	102 missing
41	103 missing
42 missing	104 missing
43 missing	105 missing
44 missing	106
45	107 missing
46 missing	108 missing
47 missing	109 missing
48	110 missing
49	111 missing
50 missing	112 missing
51 missing	113 missing
52 missing	114 missing
53 missing	115 missing
54	116 missing
55 missing	117 missing
56 missing	118 missing
57	119 missing
58 missing	120 missing
59 missing	121 missing



BRITISH AEROSPACE
DEFENCE
ROYAL ORDNANCE
ENVIRONMENTAL SERVICES GROUP

**NEGATIVE
REFERENCE:**

1/5192

**REPORT NO.: ESG 2060/94
FORMER RARDE
WALTHAM ABBEY
NORTH SITE
REMEDIATION PROJECT**

**SPARE
PHOTOGRAPHS**

**IF YOU REMOVE PHOTOGRAPHS FROM
THIS ENVELOPE
PLEASE FILL IN THE**

SPARE PHOTOGRAPHS REGISTER'

ESG:1/5192

Missing

FRAME:	DATE:	AREA:	SUBJECT MATTER:
1			void
2			void
3			void
4			void
5	OCT '92	T	TETRYL FACTORY - BREAKING OUT CONCRETE FOUNDATION BASES
6	OCT '92	T	TETRYL FACTORY - BREAKING OUT CONCRETE FOUNDATION BASES
7	OCT '92	P	MOBILE LAB. FOR 'ASBESTOS IN AIR' MONITORING WITHIN BUILDINGS
8	OCT '92	P	INTERIOR VIEW OF BUILDING A210 - SAMPLING (AIR MONITORING PUMP)
9	OCT '92	P	INTERIOR VIEW OF BUILDING A210 - SAMPLING (AIR MONITORING PUMP)
10	OCT '92	P	INTERIOR VIEW OF BUILDING A210 - SAMPLING (AIR MONITORING PUMP)
11	OCT '92	P	INTERIOR VIEW OF BUILDING A210 - SAMPLING (AIR MONITORING PUMP)
12	OCT '92	P	PERSONNEL DECONTAMINATION UNIT
13	OCT '92	P	PIPE CLAD IN ASBESTOS LAGGING, WRAPPED PRIOR TO DISPOSAL
14	OCT '92	T	HEAVY CONCRETE FOUNDATION BASE BROKEN UP, FOR DISPOSAL
15	OCT '92	P	LINK BETWEEN BUILDING A235 & BUILDING A238 - NORTH ELEVATION
16	OCT '92	P	EAST ELEVATION OF BUILDING A266 - TIMBER & ASBESTOS CONSTRUCTION
17	OCT '92	P	N/W ELEVATION OF BUILDING A288 (TOILET EXTENSION TO BLDG. A269)
18	OCT '92	P	NORTH ELEVATION OF BUILDING A289 - ASBESTOS ROOF SHEETS
19	OCT '92	P	NORTH EAST ELEVATION OF BUILDING A289 - ASBESTOS ROOF SHEETS
20	OCT '92	P	EAST ELEVATION OF BUILDING A271 - OVERGROWN WITH TREES & SHRUBS
21	OCT '92	P	EAST ELEVATION OF BUILDING A271 - OVERGROWN WITH TREES & SHRUBS
22	OCT '92	P	EAST ELEVATION OF BUILDING A273 - ASBESTOS ROOFING & GABLE CLAD.
23	OCT '92	P	WEST ELEVATION OF BUILDING A273 - ASBESTOS ROOF SHEETING
24	OCT '92	P	SOUTH WEST ELEVATION OF BUILDING A272 - ASPHALT FLAT ROOF
25	OCT '92	P	EAST ELEVATION OF BUILDING A282 - ASBESTOS WALL & ROOF CLADDING
26	OCT '92	P	EAST ELEVATION OF BUILDING A284 - ASBESTOS ROOF & GABLE CLADDING
27	OCT '92	P	EAST ELEVATION OF BUILDING A284 - ASBESTOS ROOF & GABLE SHEETING
28	OCT '92	P	VIEW FROM BLDG. A269 (UPSTAIRS) - BLDG'S A266, A230 & A288 IN PICTURE
29	OCT '92	P	VIEW WEST SHOWING ROOF OF BUILDING A273 IN THE FOREGROUND
30	OCT '92	P	VIEW S/W SHOWING ROOF OF BUILDING A272 - ASBESTOS ROOF SHEETS
31	OCT '92	P	WEST ELEVATION OF POWDERMILL LANE GATES BETWEEN A269 & A238
32	OCT '92	P	WEST ELEVATION OF POWDERMILL LANE GATES - CANON BALL BOLLARDS
33	OCT '92	S	REMOVAL OF ASBESTOS FROM TETRYL DRYING STOVES - ASBESTOS POOR
34	OCT '92	M	INTERNAL VIEW OF BUILDING L162
35	OCT '92	M	INTERNAL VIEW OF BUILDING L162 - ASBESTOS ROOF SHEETING
36	OCT '92	S	ASBESTOS COLLECTION FROM TETRYL DRYING STOVES - BAD TERRAIN
37	OCT '92	S	ASBESTOS COLLECTION FROM TETRYL DRYING STOVES - BAD TERRAIN



BRITISH AEROSPACE
DEFENCE
ROYAL ORDNANCE
ENVIRONMENTAL SERVICES GROUP

**NEGATIVE
REFERENCE:**

2/5193

**REPORT NO.: ESG 2060/94
FORMER RARDE
WALTHAM ABBEY
NORTH SITE
REMEDICATION PROJECT**

**SPARE
PHOTOGRAPHS**

**IF YOU REMOVE PHOTOGRAPHS FROM
THIS ENVELOPE
PLEASE FILL IN THE**

'SPARE PHOTOGRAPHS REGISTER'

ESG:2/5193

Missing

FRAME:	DATE:	AREA:	SUBJECT MATTER:
	1 OCT '92	S	SURFACE WATER EARTHENW ARE DRAIN
	2 OCT '92	S	ASBESTOS SHEETING AS FOUND -GENERAL POOR CONDITON OF SHEETS
	3 OCT '92	S	ASBESTOS SHEETING AS FOUND -GENERAL POOR CONDITON OF SHEETS
	4 OCT '92	S	ASBESTOS SHEETING AS FOUND -GENERAL POOR CONDITON OF SHEETS
	5 OCT '92	S	COLLECTING LABORATORY GLASSWARE AND BOTTLED CHEMICALS
	6 OCT '92	S	SITE CLEARANCE PLANT TO ENABLE ACCESS FOR GENERAL CLEARANCE
	7 OCT '92	M	SOUTH EAST ELEVATION OF BUILDING L113 -GENERAL POOR CONDITON
	8 OCT '92	M	NORTH WEST ELEVATION OF BUILDING L113
	9 OCT '92	M	SOUTH WEST ELEVATION OF BUILDING L112 -ASBESTOS SHEET ROOFING
	10 OCT '92	M	NORTH EAST ELEVATION OF BUILDING L112 -SOLVENT STORAGE PLACE
	11 OCT '92	M	WEST ELEVATION OF BUILDING L197 -ASBESTOS END PANELS
	12 OCT '92	M	EAST ELEVATION OF BUILDING L197 -ASBESTOS END PANELS
	13 OCT '92	M	EAST ELEVATION OF BUILDING L161 -GARAGE/STORE
	14 OCT '92	M	WEST ELEVATION OF BUILDING L161 -GARAGE / STORE
	15 OCT '92	M	NORTH ELEVATION OF BUILDING L161 -GARAGE/STORE (POOR STATE)
	16 OCT '92	M	NORTH ELEVATION OF BUILDING L162 -GENERAL POOR CONDITON
	17 OCT '92	M	SOUTH ELEVATION OF BUILDING L162 -GENERAL POOR CONDITON
	18 OCT '92	M	EAST ELEVATION OF BUILDING L163 -OVERGROWN WITH VEGETATION
	19 OCT '92	M	NORTH EAST ELEVATION OF BUILDING L163 -OVERGROWN WITH TREES
	20 OCT '92	M	NORTH ELEVATION OF BUILDING L127-GARAGE WITH VEHICLE HOIST
	21 OCT '92	M	SOUTH WEST ELEVATION OF BUILDING L127 -GARAGE
	22 OCT '92	M	NORTH WEST ELEVATION OF No.1 GREENHOUSE -POOR CONDITON
	23 OCT '92	M	ELEVATION OF No.2 GREENHOUSE -GENERAL POOR CONDITON
	24 OCT '92	M	NORTH ELEVATION OF BUILDING L169 -ASBESTOS SHEET ROOFING
	25 OCT '92	M	EAST ELEVATION OF BUILDING L169 -ASBESTOS SHEET ROOFING
	26 OCT '92	M	SOUTH WEST ELEVATION OF BUILDING L169 -ASBESTOS SHEET ROOFING
	27 OCT '92	M	EAST ELEVATION OF BUILDING L173 -GENERAL POOR CONDITON
	28 OCT '92	M	NORTH ELEVATION OF BUILDING L173 -GENERAL POOR CONDITON
	29 OCT '92	P	EAST ELEVATION OF BUILDING A210 (D) -WELDING SHOP (FOREGROUND)
	30 OCT '92	P	NORTH ELEVATION OF BUILDING A210 (D)-WELDING SHOP
	31 OCT '92	P	EAST ELEVATION OF BUILDING A211 -ASBESTOS ROOF SHEETING
	32 OCT '92	P	SOUTH WEST ELEVATION OF BUILDING A211-ASBESTOS ROOF SHEETING
	33 OCT '92	P	NORTH ELEVATION OF BUILDING A212-ASBESTOS ROOF SHEETING
	34 OCT '92	P	EAST ELEVATION OF BUILDING A212 -ASBESTOS ROOF SHEETING
	35 OCT '92	P	NORTH EAST ELEVATION OF BUILDING A219 -TRANSPORT OFFICES
	36 OCT '92	P	SOUTH EAST ELEVATION OF BUILDING A219 -TRANSPORT OFFICES
	37 OCT '92	P	SOUTH WEST ELEVATION OF BUILDING A219 -TRANSPORT OFFICES



BRITISH AEROSPACE
DEFENCE
ROYAL ORDNANCE
ENVIRONMENTAL SERVICES GROUP

NEGATIVE
REFERENCE:

3/5903

REPORT NO.: ESG 2060/94
FORMER RARDE
WALTHAM ABBEY
NORTH SITE
REMEDIATION PROJECT

**SPARE
PHOTOGRAPHS**

IF YOU REMOVE PHOTOGRAPHS FROM
THIS ENVELOPE
PLEASE FILL IN THE
SPARE PHOTOGRAPHS REGISTER'

ESG:3/5903

Missing

FRAME:	DATE:	AREA:	SUBJECT MATTER:
	1 OCT '92	P	SOUTH ELEVATION OF BUILDING A21 0 (B) - SOUTH CONCRETE BUNKER
	2 OCT '92	P	WEST ELEVATION OF BUILDING A21 0 (B) - SOUTH CONCRETE BUNKER
	3 OCT '92	P	WEST ELEVATION OF BUILDING A210 (A) - NORTH CONCRETE BUNKER
	4 OCT '92	P	EAST ELEVATION OF BUILDING A210 (A) - NORTH CONCRETE BUNKER
	5 OCT '92	P	PHASE 1 DEMOLISHED IN PROGRESS - ASBESTOS ROOFING ETC. REMOVED
	6 OCT '92	P	PHASE 1 DEMOLISHED IN PROGRESS
	7 OCT '92	P	PHASE 1 DEMOLISHED IN PROGRESS
	8 OCT '92	S	PIPE WRAPPED WITH BLUE ASBESTOS BRAID
	9 OCT '92	S	FALLEN TELEGRAPH POLE
	10 OCT '92	S	CLEARANCE OF BUILDING 92 (A) - GENERALLY OVERGROWN WITH TREES
	11 OCT '92	S	CLEARANCE OF BUILDING 92 (A)
	12 OCT '92	S	CLEARED RAIL WAY ROUTE ADJACENT TO BUILDINGS 93A AND 96A
	13 OCT '92	S	CLEARED RAIL WAY ROUTE ADJACENT TO BUILDINGS 93A AND 96A
	14 OCT '92	S	TYPICAL STEAM MAIN THROUGH WOODS - GENERAL POOR CONDITON
	15 OCT '92	S	LONG WALK LOOKING NORM - BUILDINGS 107 AND 108 ON LEFT
	16 OCT '92	B/S	BURNING GROUND - TEMPORARY ACCESS ROAD
	17 OCT '92	B/S	BURNING GROUND - TEMPORARY ACCESS ROAD
	18 OCT '92	S	ELEVATION OF WALL (BASE) OF BUILDING S46 - ASBESTOS LAGGED PIPES
	19 OCT '92	S	ELEVATION OF BUILDING S48 - BASE OF EXTERNAL WALL
	20 OCT '92	S	SITE CLEARANCE WORKS BY BUILDING 18 - TREE FELLING
	21 OCT '92		WALL PLAQUE - RE ENFIELD SITE (LOANED)
	22 OCT '92		WALL PLAQUE - RE ENFIELD SITE (LOANED)
	23 OCT '92		WALL PLAQUE - RE ENFIELD SITE (LOANED)
	24 OCT '92		WALL PLAQUE - RE ENFIELD SITE (LOANED)
	25 OCT '92		WALL PLAQUE - RE ENFIELD SITE (LOANED)



BRITISH AEROSPACE
DEFENCE
ROYAL ORDNANCE
ENVIRONMENTAL SERVICES GROUP

**NEGATIVE
REFERENCE:**

4/5904

**REPORT NO.: ESG 2060/94
FORMER RARDE
WALTHAM ABBEY
NORTH SITE
REMEDIAATION PROJECT**

**SPARE
PHOTOGRAPHS**

**IF YOU REMOVE PHOTOGRAPHS FROM
THIS ENVELOPE
PLEASE FILL IN THE**

SPARE PHOTOGRAPHS REGISTER'

ESG:4/5904

Missing

FRAME:	DATE:	AREA:	SUBJECT MATTER:
	1 OCT '92	B	CONSTRUCTION OF ACCESS ROAD TO WEST SIDE OF BURNING GROUND
	2 OCT '92	B	CONSTRUCTION OF ACCESS ROAD TO WEST SIDE OF BURNING GROUND
	3 OCT '92	B	CONSTRUCTION OF ACCESS ROAD TO WEST SIDE OF BURNING GROUND
	4 OCT '92	H	NORTH EAST ELEVATION OF BUILDING H67 -GENERAL POOR CONDITON
	5 OCT '92	H	NORTH ELEVATION OF BUILDING H67-GENERAL POOR CONDITON
	6 OCT '92	H	NORTH EAST ELEVATION OF BUILDING H67
	7 OCT '92	H	SOUTH ELEVATION OF ENTRANCE TO BUILDING H67 -POOR CONDITON
	8 OCT '92	H	SOUTH EAST ELEVATION OF BUILDING H68 -GENERAL POOR CONDITON
	9 OCT '92	H	WEST ELEVATION OF BUILDING H68 -GENERAL POOR CONDITON
	10 OCT '92	H	SOUTH ELEVATION OF STRUCTURE H68a -FIRING TUNNEL/PCC PIPE
	11 OCT '92	H	SOUTH EAST ELEVATION OF BUILDING H7 -MAGAZINE
	12 OCT '92	H	NORTH ELEVATION OF BUILDING H7 -MAGAZINE
	13 OCT '92	H	SOUTH ELEVATION OF BUILDING H17 -SEWER PUMPING STATION
	14 OCT '92	H	NORTH ELEVATION OF BUILDING H17 -SEWER PUMPING STATION
	15 OCT '92	H	ACTIVE SEWER PUMPING STATION
	16 OCT '92	H	NORTH WEST ELEVATION OF BUILDING H66 -ASBESTOS ROOF SHEETS
	17 OCT '92	H	SOUTH EAST ELEVATION OF BUILDING H66-ASBESTOS ROOF SHEETS
	18 OCT '92	H	EAST ELEVATION OF BUILDING H72 -OVERGROWN WITH VEGETATION
	19 OCT '92	H	WEST ELEVATION OF BUILDING H72 -SOL VENT AND CHEMICAL STORE
	20 OCT '92	H	SOUTH WEST ELEVATION OF BUILDING H72
	21 OCT '92	H	NORTH WEST ELEVATION OF BUILDING H72
	22 OCT '92	H	SOUTH WEST ELEVATION OF BUILDING H72(A)
	23 OCT '92	H	SOUTH WEST ELEVATION OF BUILDING H69
	24 OCT '92	H	NORTH ELEVATION OF BUILDING H69 -MAGAZINE (pOOR CONDITON)
	25 OCT '92	H	SOUTH WEST ELEVATION OF BUILDING H70 -GENERAL POOR CONDITON
	26 OCT '92	H	NORTH EAST ELEVATION OF BUILDING H70 -BLDGH67IN BACKGROUND
	27 OCT '92	L	NORTH WEST ELEVATION OF BUILDING L165(AFTER LEAN-TO REMOVAL)
	28 OCT '92	L	NORTH WEST ELEVATION OF BUILDING L165(AFTER LEAN-TO REMOVAL)
	29 OCT '92	H	NORTH ELEVATION OF BUILDING H65 -LOCKER MAGAZINE
	30 OCT '92	H	SOUTH ELEVATION OF BUILDING H65 -LOCKER MAGAZINE
	31 OCT '92	H	SOUTH EAST ELEVATION OF BUILDING H13 -GENERAL POOR CONDITON
	32 OCT '92	H	NORTH WEST ELEVATION OF BUILDING H13
	33 OCT '92	H	NORTH WEST ELEVATION OF BUILDING H12 -GENERAL POOR CONDITON
	34 OCT '92	H	INTERNAL ELEVATION OF BUILDING H12 -GENERAL POOR CONDITON
	35 OCT '92	H	INTERNAL ELEVATION OF BUILDING H12 -GENERAL POOR CONDITON
	36 OCT '92	H	SOUTH WEST ELEVATION OF BUILDING H14 -GENERAL POOR CONDITON
	37 OCT '92	H	NORTH EAST ELEVATION OF BUILDING H14 -STORE SHED/MAGAZINE



BRITISH AEROSPACE
DEFENCE
ROYAL ORDNANCE
ENVIRONMENTAL SERVICES GROUP

**NEGATIVE
REFERENCE:**

5/6285

REPORT NO.: ESC 2060/94
FORMER RARDE
WALTHAM ABBEY
NORTH SITE
REMEDIATION PROJECT

**SPARE
PHOTOGRAPHS**

IF YOU REMOVE PHOTOGRAPHS FROM
THIS ENVELOPE
PLEASE FILL IN THE

SPARE PHOTOGRAPHS REGISTER'

ESG: 5/6285

Missing

FRAME:	DATE:	AREA:	SUBJECT MATTER:
	1 NOV '92	H	SOUTH WEST ELEVATION OF BUILDING H15 -CONCRETE AIR RAID SHELTER
	2 NOV '92	H	SOUTH WEST ELEVATION OF BUILDING H15 -CONCRETE AIR RAID SHELTER
	3 NOV '92	H	SOUTH WEST ELEVATION OF BUILDING H24 -SEWAGE PUMP HOUSE
	4 NOV '92	H	NORTH EAST ELEVATION OF BUILDING H24 -SEWAGE PUMP HOUSE
	5 NOV '92	H	EAST ELEVATION OF BUILDING H23 -STORAGE SHED
	6 NOV '92	H	SOUTH WEST ELEVATION OF BUILDING H23 -STORAGE SHED
	7 NOV '92	H	SOUTH ELEVATION OF BLDG H23 -SHED OVERGROWN WITH VEGETATION
	8 NOV '92	H	EAST ELEVATION OF BUILDING H25 -SURGERY / WOMENS HOSPITAL / FLATS
	9 NOV '92	H	WEST ELEVATION OF BUILDING H25 -SURGERY / WOMENS HOSPITAL / FLATS
	10 NOV '92	H	WEST ELEVATION OF BUILDING H25 (A) -GENERAL POOR CONDITON
	11 NOV '92	H	SOUTH ELEVATION OF BUILDING H26 -GENERAL POOR CONDITON
	12 NOV '92	H	EAST ELEVATION OF BUILDING H26 -SANDHURST RESIDENTIAL HOSPITAL
	13 NOV '92	H	NORTH WEST ELEVATION OF BUILDING H26 -SANDHURST HOSPITAL
	14 NOV '92	H	SOUTH WEST ELEVATION OF BUILDING H26 -SANDHURST HOSPITAL
	15 NOV '92	P	EAST ELEVATION OF BUILDING A235
	16 NOV '92	P	NORTH ELEVATION OF LINK BETWEENBLDG A238 AND BLDG A234
	17 NOV '92	P	NORTH ELEVATION OF LINK BETWEEN BLDG A238 AND BLDG A234
	18 NOV '92	S	ELEVATION OF BUILDING ARS 1 -GENERAL POOR CONDITON
	19 NOV '92	S	ELEVATION OF BUILDING ARS 1 -GENERAL POOR CONDITON
	20		void
	21 NOV '92	N	SQUIRREL EATING AN APPLE
	22 NOV '92	N	SITE WASTE TRANSFER STATION
	23 NOV '92	N	SITE WASTE TRANSFER STATION
	24 NOV '92	S	MINI EXCAVATOR EN-ROUTE TO NEXT TASK
	25 NOV '92	S	R.O. SUPERVISOR CO ORDINATING SITE WORK WITH TREE FELLING GANG
	26 NOV '92	S	SOUTH WEST ELEVATION OF BUILDING S34 BLAST WALL
	27 NOV '92	S	NEWTON'S POOLSOUTH WEST ELEVATION OF BUILDING S34 BLAST WALL
	28 NOV '92	S	NEWTON'S POOL -OVER WATER CABLEWAY EQUIP ..VIEWED FROM WEST
	29 NOV '92	S	VIEW LOOKING NORTH EAST -BUILDING S34 (DEBRIS IN FOREGROUND)
	30 NOV '92	S	SOUTH WEST ELEVATION OF NEWTON'S POOL WEIR -POOR CONDITON
	31 NOV '92	S	NORTH ELEVATION OF BUILDING 46A -NEWTON'S POOL IN FOREGROUND
	32 NOV '92	S	ELEVATION OF AIR RAID SHELTER ADJACENT TO BUILDING 14
	33 NOV '92	S	No.1 BORE HOLE NORTH OF SSSI
	34 NOV '92	S	EAST PERIMETER ROAD LOOKING SOUTH WEST
	35 NOV '92	S	VESSEL FOUND ADJACENT TO BUILDING 14
	36 NOV '92	S	WEST PERIMETER FENCE -DISTRESSED ROOK RESCUED
	37 NOV '92	S	R.O.SUPERVISOR WITH ROOK -ALONG THE WEST PERIMETER FENCE



BRITISH AEROSPACE
DEFENCE
ROYAL ORDNANCE
ENVIRONMENTAL SERVICES GROUP

**NEGATIVE
REFERENCE:**

6/6286

**REPORT NO.: ESG 2060/94
FORMER RARDE
WALTHAM ABBEY
NORTH SITE
REMEDICATION PROJECT**

**SPARE
PHOTOGRAPHS**

**IF YOU REMOVE PHOTOGRAPHS FROM
THIS ENVELOPE
PLEASE FILL IN THE**

'SPARE PHOTOGRAPHS REGISTER'

ESG: 6/6286

Missing

FRAME:	DATE:	AREA:	SUBJECT MATTER:
	1 NOV '92	M	VIEW SHOWING JCB KNOCKING ROOF IN OF BUILDING L117
	2 NOV '92	P	SOUTHERN ASPECT OF BLDG A210-DEMOLISHED OF CONCRETE BUNKER
	3 NOV '92	P	SOUTHERN ASPECT OF BLDG A210 SHOWING 'PULVERISER' ON 360 MACHINE
	4 NOV '92	S	DAMPING DOWN BUILDING 22A AFTER FIRING OF EXTERNAL AIR DUCTING
	5 NOV '92	S	DAMPING DOWN BUILDING 22A AFTER FIRING OF EXTERNAL AIR DUCTING
	6 NOV '92	P	INTERNAL VIEW OF R.O. PROJECT OFFICE
	7 NOV '92	P	INTERNAL VIEW OF R.O. PROJECT OFFICE
	8 NOV '92	S	EAST ELEVATION OF BUILDING 22A-QUINAN STOVE/DERELICT
	9 NOV '92	S	NORTH ELEVATION OF BUILDING 22A-QUINAN STOVE/DERELICT
	10 NOV '92	S	SOUTH WEST ELEVATION OF BUILDING 22A SHOWING FRONT DUCTING
	11 NOV '92	S	PART NORTH ELEVATION OF BUILDING 22A-BLASTWALL TO RIGHT
	12 NOV '92	S	SOUTH ELEVATION OF BUILDING E10
	13 NOV '92	S	EAST ELEVATION OF BUILDING E10 -SAFETY STORE
	14 NOV '92	S	WEST ELEVATION OF BUILDING E6 -CONTROL ROOM
	15 NOV '92	S	NORTH EAST ELEVATION OF BUILDING E6-CONTROL ROOM
	16 NOV '92	S	SOUTH WEST ELEVATION SHOWING ENTRANCE TO BUILDING E15
	17 NOV '92	S	NORTH EAST ELEVATION OF BUILDING E15 -GENERATOR ROOM
	18 NOV '92	S	NORTH WEST ELEVATION OF BUILDING E9 -REFRIGERATION HOUSE
	19 NOV '92	S	SOUTH WEST ELEVATION OF BUILDING E9 -REFRIGERATION HOUSE
	20 NOV '92	S	WEST ELEVATION OF BUILDING E2-NITRATION PLANT
	21 NOV '92	S	SOUTH WEST ELEVATION OF BUILDING E2 -NITRATION PLANT
	22 NOV '92	S	INTERNAL ELEVATION OF BUILDING E2 -NITRATION PLANT
	23 NOV '92	S	INTERNAL VIEW OF BUILDING E2 -NITRATION PLANT
	24 NOV '92	S	SOUTHWEST ELEVATION OF ENTRANCE TO BUILDING E2
	25 NOV '92	S	ELEVATION OF BLDG U6 -SMALL STORAGE HUT OVERGROWN BY TREES
	26 NOV '92	S	ELEVATION OF BLDG U6-SMALL STORAGE HUT OVERGROWN BY TREES
	27 NOV '92	S	SOUTH ELEVATION OF BUILDING S31
	28 NOV '92	S	NORTH EAST INTERNAL ELEVATION OF BUILDING S31
	29 NOV '92	S	SOUTH EAST ELEVATION OF BUILDING S90-DERELICT BOILER HOUSE
	30 NOV '92	S	NORTH WEST ELEVATION OF BUILDING S90 -DERELICT BOILERHOUSE
	31 NOV '92	S	SOUTH EAST ELEVATION OF BLDG S90-OVERGROWN WITH VEGETATION
	32 NOV '92	S	NORTH ELEVATION OF BUILDING S90-OVERGROWN WITH VEGETATION
	33 NOV '92	S	WEST INTERNAL ELEVATION OF BUILDING S30 -BLAST WALLS ONLY
	34 NOV '92	S	SOUTH WEST ELEVATION OF BUILDING S29
	35 NOV '92	S	NORTH EAST ELEVATION OF BUILDING S29
	36 NOV '92	S	NORTH EAST ELEVATION OF BUILDING S29A
	37 NOV '92	S	NORTHWEST ELEVATION OF BUILDING S29A



BRITISH AEROSPACE
DEFENCE
ROYAL ORDNANCE
ENVIRONMENTAL SERVICES GROUP

**NEGATIVE
REFERENCE:**

7/6287

**REPORT NO.: ESG 2060/94
FORMER FARDE
WALTHAM ABBEY
NORTH SITE
REMEDICATION PROJECT**

**SPARE
PHOTOGRAPHS**

**IF YOU REMOVE PHOTOGRAPHS FROM
THIS ENVELOPE
PLEASE FILL IN THE**

'SPARE PHOTOGRAPHS REGISTER'

ESG:7/6287

Missing

FRAME:	DATE:	AREA:	SUBJECT MATTER:
	1 NOV '92		ROAD SWEEPER - SITE ROAD NETWORK SWEEP ON A REGULAR BASIS
	2 NOV '92	P	ESSEX FIRE & RESCUE SERVICE VEHICLE - POWDERMILL LANE ENTRANCE
	3 NOV '92	HVS	NORTH EAST ELEVATION OF BUILDING A201/2 - ASBESTOS CLAD BIKESHED
	4 NOV '92	HVS	NORTH ELEVATION OF BUILDING A201/2 - ASBESTOS CLAD BIKESHED
	5 NOV '92	HVS	EAST ELEVATION OF BUILDING A291
	6 NOV '92	HVS	NORTH EAST ELEVATION OF BUILDING A291
	7 NOV '92	HVS	SOUTH EAST ELEVATION OF BUILDING A292
	8 NOV '92	HVS	WEST FACT OF BUILDING A292 - FENCE GUARDING SETTLEMENT PIT
	9 NOV '92	H	NORTHEAST ELEVATION OF BUILDING HI- PREFABRICATED STRUCTURE
	10 NOV '92	H	WEST ELEVATION OF BUILDING H1 - PREFABRICATED STRUCTURE
	11 NOV '92	H	EAST ELEVATION OF BUILDING H2 - PREFABRICATED STRUCTURE
	12 NOV '92	H	WEST ELEVATION OF BUILDING H2 - PREFABRICATED STRUCTURE
	13 NOV '92	H	SOUTH ELEVATION OF BUILDING H3 - PREFABRICATED STRUCTURE
	14 NOV '92	H	NORTH ELEVATION OF BUILDING H3 - PREFABRICATED STRUCTURE
	15 NOV '92	M	WEST ELEVATION OF BUILDING L183
	16 NOV '92	M	NORTH EAST ELEVATION OF BUILDING L183
	17 NOV '92	M	SOUTH EAST ELEVATION OF BUILDING L158 - GENERAL POOR CONDITON
	18 NOV '92	M	NORTH ELEVATION OF BUILDING L158
	19 NOV '92	M	SOUTH EAST ELEVATION OF BUILDING L187
	20 NOV '92	M	NORTH EAST ELEVATION OF BUILDING L187
	21 NOV '92	M	SOUTH EAST ELEVATION OF BUILDING L156 - GENERAL POOR CONDITON
	22 NOV '92	M	WEST ELEVATION OF BUILDING L156
	23 NOV '92	H	EAST ELEVATION OF BUILDING H23 - GENERAL POOR CONDITON
	24 NOV '92	H	SOUTH ELEVATION OF BUILDING H23 - OVERGROWN WITH VEGETATION
	25 NOV '92	H	WEST ELEVATION OF BUILDING H23 - OVERGROWN WITH VEGETATION
	26 NOV '92	M	INTERNAL VIEW OF BUILDING L183 - GENERAL POOR CONDITON
	27 NOV '92	M	INTERNAL VIEW OF BUILDING L183 - GENERAL POOR CONDITON
	28 NOV '92	M	NORTH ELEVATION OF BUILDING L117
	29 NOV '92	M	NORTH EAST ELEVATION OF BUILDING L117
	30 NOV '92	H	SOUTH ELEVATION OF BUILDING H21
	31 NOV '92	H	NORTH WEST ELEVATION OF BUILDING H21
	32 NOV '92	S	WEST ELEVATION OF BUILDING 22A - PREPARATION FOR FIRING DUCTING
	33 NOV '92	S	WEST ELEVATION OF BUILDING 22A - EXTERNAL DUCTWORK BEING FIRED
	34 NOV '92	S	ELEVATION OF BUILDING 22A - EXTERNAL DUCTWORK BEING FIRED
	35 NOV '92	M	REMOVAL OF STEAM MAIN SUPPORT STEELWORK
	36 NOV '92	M	ELEVATION OF BUILDING L117 BUILDING BEING PREPARED FOR FIRING
	37 NOV '92	M	SOUTH EAST ELEVATION OF BUILDING L117



BRITISH AEROSPACE
DEFENCE
ROYAL ORDNANCE
ENVIRONMENTAL SERVICES GROUP

**NEGATIVE
REFERENCE:**

8/6340

**REPORT NO.: ESG 2060/94
FORMER RARDE
WALTHAM ABBEY
NORTH SITE
REMEDIAION PROJECT**

**SPARE
PHOTOGRAPHS**

**IF YOU REMOVE PHOTOGRAPHS FROM
THIS ENVELOPE
PLEASE FILL IN THE**

'SPARE PHOTOGRAPHS REGISTER'

WA1
1224

ESG:8/6340

Missing

FRAME:	DATE:	AREA:	SUBJECT MATTER:
			void 1-15
16 NOV '92	S		BAGGED ASBESTOS IN GUNCOTTON STOVES - AWAITING DISPOSAL
17 NOV '92	S		BAGGED ASBESTOS IN GUNCOTTON STOVES - AWAITING DISPOSAL
18 NOV '92	S		BAGGED ASBESTOS IN GUNCOTTON STOVES - AWAITING DISPOSAL
19 NOV '92	S		ASBESTOS BOARD DEBRIS, AS FOUND, ADJACENT TO GUNCOTTON STOVES
20 NOV '92	S		INITIAL 'PICK UP' OF DEBRIS LYING AROUND SSSI AREA
21 NOV '92	S		INITIAL 'PICK UP' OF DEBRIS LYING AROUND SSSI AREA
22 NOV '92	S		BAGGED ASBESTOS NEAR GUNCOTTON STOVES
23 NOV '92	S		SHEET ASBESTOS PRIOR TO BAGGING - ASBESTOS DEBRIS 'AS FOUND'
24 NOV '92	S		SHEET ASBESTOS AT GUNCOTTON STOVES - ASBESTOS DEBRIS 'AS FOUND'
25 NOV '92	S		SHEET ASBESTOS PRIOR TO BAGGING - ASBESTOS BOARDING 'AS FOUND'
26 NOV '92	S		SHEET ASBESTOS AT GUNCOTTON STOVES - SHEET ASBESTOS 'AS FOUND'
27 NOV '92	S		SHEET ASBESTOS - COLLECTED AND BAGGED A WAITING DISPOSAL
28 NOV '92	S		ASBESTOS AT GUNCOTTON STOVE - BAGGING OF ASBESTOS DEBRIS
29 NOV '92	M		NORTH ELEVATION OF BUILDING L127 - ASBESTOS CLAD BUILDING
30 NOV '92	M		WEST ELEVATION OF BUILDING L161- GENERAL POOR CONDITON
31 NOV '92	M		SOUTH WEST ELEVATION OF BUILDING L112
32 NOV '92	M		SOUTH WEST ELEVATION OF BUILDING L113
33 NOV '92	M		NORTH ELEVATION OF BUILDING L117
34			void
35			void
36 NOV '92	M		INTERNAL VIEW OF BUILDING L117 (LOCKER MAGAZINE)
37 NOV '92	M		NORTH ELEVATION OF BUILDING L117 - TIMBER IMPORTED FOR FIRING



BRITISH AEROSPACE
DEFENCE
ROYAL ORDNANCE
ENVIRONMENTAL SERVICES GROUP

**NEGATIVE
REFERENCE:**

9/8224

**REPORT NO.: ESG 2060/94
FORMER RARDE
WALTHAM ABBEY
NORTH SITE
REMEDIAION PROJECT**

**SPARE
PHOTOGRAPHS**

**IF YOU REMOVE PHOTOGRAPHS FROM
THIS ENVELOPE
PLEASE FILL IN THE**

'SPARE PHOTOGRAPHS REGISTER'

ESG:9/8824

Missing

FRAME:	DATE:	AREA:	SUBJECT MATTER:
			void 1-7
	8 NOV '92	T	TETRYL FACTORY SITE - CORE DRILLING / BURSTING
	9 NOV '92	T	TETRYL FACTORY SITE - CORE DRILLING / BURSTING
			void 10-15
	16 NOV '92	T	CORE DRILLING FOUNDATION BASES
	17 NOV '92	B	L.G C SAMPLING GROUND WATER FROM SITE BORE HOLES
	18 NOV '92	S	COPPER LIGHTNING CONDUCTORS FROM ROOFS OF MAGAZINES
	19 NOV '92	N	COPPER LIGHTNING CONDUCTORS - ACCUMULATION FOR SALVAGE
	20 NOV '92	M	COPPER LIGHTNING CONDUCTORS - ACCUMULATION FOR SALVAGE
	21 NOV '92	T	TETRYL FACTORY SITE - BURSTING OF FOUNDATION CONCRETE
	22 NOV '92	T	TETRYL FACTORY SITE - BURSTING OF FOUNDATION CONCRETE
	23 NOV '92	P	WEST ELEVATION OF BUILDING A210 - SERVICES PIPEWORK, SOME LAGGED
	24 NOV '92	P	NORTH ELEVATION OF BUILDING A210 - ASBESTOS LAGGED PIPES WRAPPED
	25 NOV '92	P	NORTH ELEVATION OF BUILDING A212 - ASBESTOS LAGGED PIPES WRAPPED
	26 NOV '92	M	NORTH EAST ELEVATION OF BUILDINGL113 - ASBESTOS LAGGED PIPES
	27 NOV '92	M	PIPES NEAR BUILDINGL153 WRAPPED FOR REMOVAL
	28 NOV '92	P	PERSONNEL DECONTAMINATION UNIT
	29 NOV '92	S	STEAM MAIN PIPE IN SSSI AREA - ASBESTOS LAGGED PIPE WRAPPED
	30 NOV '92	S	STEAM MAIN PIPE NEAR BUILDING 88A - ASBESTOS LAGGED PIPE WRAPPED
	31 NOV '92	N	NORTH EAST VIEW OF GATE IN AREA N - HOLE CUT IN GATE BY INTRUDERS



BRITISH AEROSPACE
DEFENCE
ROYAL ORDNANCE
ENVIRONMENTAL SERVICES GROUP

NEGATIVE
REFERENCE:

10/6853

REPORT NO.: ESG 2060/94
FORMER RARDE
WALTHAM ABBEY
NORTH SITE
REMEDIAION PROJECT

**SPARE
PHOTOGRAPHS**

**IF YOU REMOVE PHOTOGRAPHS FROM
THIS ENVELOPE
PLEASE FILL IN THE**

SPARE PHOTOGRAPHS REGISTER'

ESG:10/6853

Missing

FRAME:	DATE:	AREA:	SUBJECT MATTER:
			void 1-11
12 NOV '92	H		INTERNAL VIEW OF BUILDING H12 - REMOTE CORING OF BRICK WALLS
13 NOV '92	H		INTERNAL VIEW OF BUILDING H12 - REMOTE CORING OF BRICK WALLS
14 NOV '92	H		INTERNAL VIEW OF BUILDING H12 - REMOTE CORING OF BRICK WALLS
15 NOV '92	H		INTERNAL VIEW OF BUILDING H12 - REMOTE CORING OF BRICK WALLS
16 NOV '92	H		INTERNAL VIEW OF BUILDING H12 - REMOTE CORING OF BRICK WALLS
17 NOV '92	H		INTERNAL VIEW OF BUILDING H12 - REMOTE CORING OF BRICK WALLS
18 NOV '92	H		INTERNAL VIEW OF BUILDING H12 - REMOTE CORING OF BRICK WALLS
19 NOV '92	H		MAN HOLE BETWEEN BUILDING H10 & H71
20 NOV '92	S		INTERNAL VIEW OF BUILDING L190 - REMOTE FLOOR CORING IN PROGRESS
21			void
22 NOV '92	S		BARGE IN CANAL WEST OF BUILDING 107/108 - GENERAL POOR CONDITON
23 NOV '92	S		BARGE IN CANAL WEST OF BUILDING 107/108 - GENERAL POOR CONDITON
24 NOV '92	S		POWDER BARGE IN CANAL AT 88A
25 NOV '92	S		POWDER BARGE IN CANAL AT 88A



BRITISH AEROSPACE
DEFENCE
ROYAL ORDNANCE
ENVIRONMENTAL SERVICES GROUP

**NEGATIVE
REFERENCE:**

11/6956

**REPORT NO.: ESG 2060/94
FORMER RARDE
WALTHAM ABBEY
NORTH SITE
REMEDIAION PROJECT**

**SPARE
PHOTOGRAPHS**

**IF YOU REMOVE PHOTOGRAPHS FROM
THIS ENVELOPE
PLEASE FILL IN THE**

'SPARE PHOTOGRAPHS REGISTER'

ESG:11/6956

Missing

FRAME:	DATE:	AREA:	SUBJECT MATTER:
	1 NOV '92	H	MAN HOLE COVER BETWEEN BUILDINGS H10 & H71 (NORTH SIDE)
	2 NOV '92	H	MAN HOLE COVER BETWEEN BUILDINGS H10 & H71 (NORTH SIDE)
	3 NOV '92	S	GENERAL VIEW OF TRACK SOUTH OF BLDG U4 -HEAVY USE BY VEHICLES
	4 NOV '92	S	VIEW SOUTH SHOWING GENERAL CLEARANCE AROUND BUILDING U4
	5 NOV '92	S	GENERAL VIEW OF WASTE MATERIAL SOUTH OF U4
	6 NOV '92	S	OUTSIDE BUILDING U4 -COPPER EARTHING STRIP, RETRIEVAL FOR SALVAGE
	7 NOV '92	S	CLEARING WASTE FROM AREA SOUTH OF BUILDING U4
	8 NOV '92	S	SETTLEMENT TANK NORTH WEST OF BUILDING 83B
	9 NOV '92	S	GENERAL VIEW OF WASTE NORTH OF BUILDING U4 -VIEW LOOKING NORTH
	10 NOV '92	S	OLD TELEGRAPH POLES STOCKPILED
	11 NOV '92	S	VIEW OF TYPICAL TRACK WITHIN WOODED AREAS OF SSSI
	12 NOV '92		MAP READING BY ROYAL ORDNANCE -ON SITE CO ORDINATION
	13 NOV '92	S	TRIAL TRENCHING OF TRAVERSE (TYPICAL) -DIFFICULT ACCESS
	14 NOV '92	M	DISMANTLING GREENHOUSE No.1
	15 NOV '92	M	DEMOLISHED OF BUILDINGS
	16 NOV '92	S	VIEW OF WASTE MATERIAL IN WASTE DUMP SOUTH OF BUILDING U4
	17 NOV '92	S	VIEW OF WASTE MATERIAL IN WASTE DUMP SOUTH OF BUILDING U4
	18 NOV '92	S	ASBESTOS UNCOVERED IN WASTE DUMP SOUTH OF BUILDING U4
	19 NOV '92	S	WASTE DUMP REMOVAL SOUTH OF BUILDING U4
	20 NOV '92	S	ASBESTOS IN WASTE DUMP SOUTH OF BUILDING U4
	21 NOV '92	S	ASBESTOS IN WASTE DUMP SOUTH OF BUILDING U4
	22 NOV '92	S	BAGGED ASBESTOS AT BUILDING 23
	23 NOV '92	S	ASBESTOS WASTE IN BUILDING 23-CONDITON PRIOR TO CLEAN UP
	24 NOV '92	S	REMOVING WASTE FROM TIP
	25 NOV '92	S	VIEW LOOKING NORTH TO E10 -FENCE GUARDING PITS
	26 NOV '92	S	WEST ELEVATION OF BUILDING E12
	27 NOV '92	S	sournELEVATION OF BUILDING E10
	28 NOV '92	S	REMOVAL OF WASTE BY LORRY -NORTH OF BUILDING 83B
	29 NOV '92	L	ELEVATION OF BUILDING L191 -CORE SAMPLING
	30 NOV '92	S	WEST ELEVATION OF BUILDING 22A -AFTERMATH OF FIRED DUCTWORK
	31 NOV '92	S	TREE CLEARANCE -LOGGING
	32 NOV '92	S	TREE CLEARANCE -CHIPPING
	33 NOV '92	N	DEMONSTRATION ON DIFFICULT TERRAIN OF TRACKED DUMPER
	34 NOV '92	N	DEMONSTRATION ON DIFFICULT TERRAIN OF TRACKED DUMPER
	35 NOV '92	N	DEMONSTRATION ON DIFFICULT TERRAIN OF TRACKED DUMPER
	36 NOV '92	N	DEMONSTRATION ON DIFFICULT TERRAIN OF TRACKED DUMPER
	37 NOV '92	N	DEMONSTRATION ON DIFFICULT TERRAIN OF TRACKED DUMPER



BRITISH AEROSPACE
DEFENCE
ROYAL ORDNANCE
ENVIRONMENTAL SERVICES GROUP

**NEGATIVE
REFERENCE:**

12/7113

**REPORT NO.: ESG 2060/94
FORMER RARDE
WALTHAM ABBEY
NORTH SITE
REMEDIAION PROJECT**

**SPARE
PHOTOGRAPHS**

**IF YOU REMOVE PHOTOGRAPHS FROM
THIS ENVELOPE
PLEASE FILL IN THE**

SPARE PHOTOGRAPHS REGISTER'

ESG:12/7113

Missing

FRAME:	DATE:	AREA:	SUBJECT MATTER:
	1 NOV '92	H	TYPICAL STEAM MAINSUPPORT-SOUTH OF BUILDING H17
	2 NOV '92	H	TYPICAL STEAM PIPE SUPPORT BASE
	3 NOV '92	H	STEAM PIPE SUPPORT SOUTH OF BUILDING H12(UNUSUAL-ALL CONCRETE)
	4 NOV '92	S	PALLETING RECLAIMED 'STOCK' (BRICKS) FOR FUTURE USE (SOUTH OF U4)
	5 NOV '92	S	R.O. SUPERVISING THE RECLAMATION OF BRICKS SOUTH OF BUILDING U4
	6 NOV '92	S	WASTE TIP REFERENCE 11013 -VIEW LOOKING SOUTH
	7 NOV '92	S	COMMENCEMENT OF BREAKING OUT SURFACE SLABS WEST OF BLDG 83B
	8 NOV '92	S	GENERAL CLEARANCE OF TIMBER FROM WASTE TIP REFERENCE 11013
	9 NOV '92	B	TIMBER STACKED IN BURNING GROUND AS FUEL FOR 'HEAT TREATMENT'
	10 NOV '92	S	GENERAL VIEW -TIMBER CLEARANCE FOR ACCESS
	11 NOV '92	S	GUNPOWDER PRESS HOUSE,EAST OF BURNING GROUND VIEWED FROM WEST
	12 NOV '92	S	GENERAL VIEW -WASTE TIP REF.:11036 ADJACENT TO G.P. PRESS HOUSE
	13 NOV '92	S	GENERAL VIEW OF WASTE TIP REF.: 11036 -GUNPOWDER PRESS HOUSE
	14 NOV '92	S	VIEW OF WASTE TIP REF.:11036-ADJACENT GUNPOWDER PRESS HOUSE
	15 NOV '92	S	VIEW OF WASTE TIP REF.:11036 -ADJACENT GUNPOWDER PRESS HOUSE
	16 NOV '92	S	VIEW OF WASTE TIP REF.: 11036-ADJACENT GUNPOWDER PRESS HOUSE
	17 NOV '92	S	VIEW OF WASTE TIP REF.:11036 -ADJACENT GUNPOWDER PRESS HOUSE
	18 NOV '92	S	VIEW OF WASTE TIP REF.:11036-ADJACENT GUNPOWDER PRESS HOUSE
	19 NOV '92	S	VIEW OF BRIDGE 10 LOOKING NORTH (PRESS HOUSE S31 IN BACKGROUND)
	20 NOV '92	S	ELEVATION OF BUILDING X16 (BUILDING NORTH WEST OF BRIDGE 10)
	21 NOV '92	B	WASTETIP REF.:11038 SITUATED NORTH OF THE BURNING GROUND
	22 NOV '92	N	GENERAL CLEARANCE
	23 NOV '92	M	REMOTE CONTROLLED CORING IN BUILDING L149 -REMOTE OPERATOR
	24 NOV '92	M	REMOTE CONTROLLED CORING OF CONCRETE FLOOR IN BUILDING L149
	25 NOV '92	N	CLEARED PATHWAYS
	26 NOV '92	N	STEEL PLATES IN BUILDING S19
	27 NOV '92	N	CLEARING PATHWAYS TO BUILDINGS
	28 NOV '92	N	CLEARED PATHWAY
	29 NOV '92	N	CLEARED ROADS AT BUILDING S21-NARROW GAUGE TRACK VISIBLE
	30 NOV '92	N	SOUTH ELEVATION OF BUILDING S22
	31 NOV '92	N	NORTH ELEVATION OF BUILDING S25
	32 NOV '92	N	SOUTH ELEVATION OF BUILDING S25
	33 NOV '92	N	TYPICAL OVERGROWN PATHWAY-OVERGROWN BY TREES AND SHRUBS
	34 NOV '92	N	INTERNAL VIEW OF BUILDING S25
	35 NOV '92	N	TYPICAL OVERGROWN DRAINAGE CHANNEL FROM BUILDING S16
	36 NOV '92	N	CLEARING DRAINAGE CHANNEL FROM BUILDING S16
	37 NOV '92	N	DRAINAGE CHANNEL RUNNING SOUTHWARD FROM BUILDING S16



BRITISH AEROSPACE
DEFENCE
ROYAL ORDNANCE
ENVIRONMENTAL SERVICES GROUP

**NEGATIVE
REFERENCE:**

13/7562

**REPORT NO.: ESG 2060/94
FORMER RARDE
WALTHAM ABBEY
NORTH SITE
REMEDICATION PROJECT**

**SPARE
PHOTOGRAPHS**

**IF YOU REMOVE PHOTOGRAPHS FROM
THIS ENVELOPE
PLEASE FILL IN THE**

'SPARE PHOTOGRAPHS REGISTER'

ESG:13/7562

Missing

FRAME:	DATE:	AREA:	SUBJECT MATTER:
	1 NOV '92	M	WEST ELEVATION OF BUILDING L167
	2 NOV '92	M	SOUTH WEST ELEVATION OF BUILDING L167
	3 NOV '92	M	SOUTH ELEVATION OF BUILDING L157
	4 NOV '92	M	WEST ELEVATION OF BUILDING L157
	5 NOV '92	M	WEST ELEVATION OF BUILDING L148/L153
	6 NOV '92	M	PART EAST AND NORTH ELEVATIONS OF BUILDING L157
	7 NOV '92	M	LOOKING SOUTH -BUILDING L157 IN FOREGROUND
	8 NOV '92	M	PART EAST ELEVATION OF BUILDING L153
	9 NOV '92	M	WEST ELEVATION OF BUILDING L149
	10 NOV '92	M	PART NORTH AND EAST ELEVATIONS OF BUILDING L153
	11 NOV '92	M	EAST ELEVATION OF BUILDING L148
	12 NOV '92	M	PART EAST ELEVATION OF BUILDING L148
	13 NOV '92	M	SOUTH EASTERN ASPECT OF BUILDING L145
	14 NOV '92	M	NORTH EASTERN ASPECT OF BUILDING L149
	15 NOV '92	M	NORTH EASTERN ASPECT OF BUILDING L149
	16 NOV '92	M	NORTH EASTERN ASPECT OF BUILDING L145
	17 NOV '92	M	SOUTH ELEVATION OF BUILDING L136
	18 NOV '92	M	SOUTH WESTERN ASPECT OF BUILDING L136
	19 NOV '92	L	NORTH WESTERN ASPECT OF BUILDING L122
	20 NOV '92	B	WEST ELEVATION OF BUILDING L102 -FILLED CANAL IN FOREGROUND
	21 NOV '92	B	NORTH ELEVATION OF BUILDING L103
	22 NOV '92	B	EAST ELEVATION OF BUILDINGS L102 /L103
	23 NOV '92	B	NORTHEASTERN ASPECT OF BUILDING L101



BRITISH AEROSPACE
DEFENCE
ROYAL ORDNANCE
ENVIRONMENTAL SERVICES GROUP

**NEGATIVE
REFERENCE:**

14/7575

**REPORT NO.: ESG 2060/94
FORMER RARDE
WALTHAM ABBEY
NORTH SITE
REMEDIAION PROJECT**

**SPARE
PHOTOGRAPHS**

**IF YOU REMOVE PHOTOGRAPHS FROM
THIS ENVELOPE
PLEASE FILL IN THE**

'SPARE PHOTOGRAPHS REGISTER'

ESG:14/7575

Missing

FRAME:	DATE:	AREA:	SUBJECT MATTER:
	1 NOV '92	N	WEST ELEVATION OF BUILDING X3-BUNKER TYPE
	2 NOV '92	N	SOUTH ELEVATION OF BUILDING X3
	3 NOV '92	B	PREPARATION OF FIRE IN BURNING GROUND FOR 'HEATTREATMENT'
	4 NOV '92	B	PREPARATION OF FIRE IN BURNING GROUND FOR 'HEATTREATMENT'
	5 NOV '92	B	PREPARATION OF FIRE IN BURNING GROUND FOR 'HEATTREATMENT'
	6 NOV '92	B	PREPARATION OF FIRE IN BURNING GROUND FOR 'HEATTREATMENT'
	7 NOV '92	B	HEAT TREATMENT OF MATERIALS AT BURNING GROUND (INPROGRESS)
	8 NOV '92	T	REMEDICATION OF TETRYL FACTORY SITE
	9 NOV '92	T	REMEDICATION OF TETRYL FACTORY SITE
	10 NOV '92	T	EXPOSURE OF SUSPECT PIT AT NORTH END OF TETRYL FACTORY SITE
	11 NOV '92	T	EXPOSURE OF SUSPECT PIT AT NORTH END OF TETRYL FACTORY SITE
	12 NOV '92	T	EXPOSURE OF SUSPECT PIT AT NORTH END OF TETRYL FACTORY SITE
	13 NOV '92	T	REMEDICATION OF TETRYL FACTORY SITE VIEWED SOUTHERLY
	14 NOV '92	T	REMEDICATION OF TETRYL FACTORY SITE VIEWED SOUTHERLY
	15 NOV '92	T	EXPOSUREOF SUSPECT PIT AT NORTH END OF TETRYL FACTORY SITE
	16 NOV '92	T	EAST SIDE OF TETRYL FACTORY SITE -WASTE DUMP
	17 NOV '92	T	REMEDICATION OF TETRYL FACTORY SITE
	18 NOV '92	T	REMEDICATION OF TETRYL FACTORY SITE
	19 NOV '92	T	REMEDICATION OF TETRYL FACTORY SITE
	20 NOV '92	T	YELLOW' DISCOLOURATION OF FOUNDATIONS TO TETRYL FACTORY SITE
	21 NOV '92	T	BREAKING OF CONCRETE FOUNDATIONS OF FORMER TETRYL FACTORY
	22 NOV '92	T	EXPOSURE OF DRAINS TO FORMER TETRYL FACTORY SITE
	23 NOV '92	T	BROKEN FOUNDATIONS OF FORMER TETRYL FACTORY
	24 NOV '92	T	REMEDICATION OF TETRYL FACTORY SITE
	25 NOV '92	S	TRACKED DUMPER BY BUILDING E12 REMOVING WASTE FROM CANAL
	26 NOV '92	S	TRACKED DUMPER TIPPING WASTE BY BUILDING E12
	27 NOV '92	H I/S	SOUTH ELEVATION OF BUILDING A203
	28 NOV '92	H I/S	NORTH ELEVATION OF BUILDING A200
	29 NOV '92	H I/S	EAST ELEVATION OF BUILDING A201 /2
	30 NOV '92	H I/S	CLOSE UP OF FRACTURED PIER TO NORTH EAST CORNER OF BUILDING A201/2
	31 NOV '92	H I/S	WEST ELEVATION OF BUILDING A200
	32 NOV '92	P	NORTH WESTERN ASPECT OF BUILDING A210
	33 NOV '92	P	WEST ELEVATION OF BUILDING A210
	34 NOV '92	P	NORTH EASTERN ASPECT OF BUILDING A2I4 (BLDG A210 IN BACKGROUND)
	35 NOV '92	M	SOUTH ELEVATION OF BUILDING L176 -BRIDGE No.2 IN FOREGROUND
	36 NOV '92	M	NORTH WESTERN ASPECT OF BUILDING L176
	37 NOV '92	M	NORTHELEVATION OF BUILDING L168



BRITISH AEROSPACE
DEFENCE
ROYAL ORDNANCE
ENVIRONMENTAL SERVICES GROUP

**NEGATIVE
REFERENCE:**

15/7600

REPORT NO.: ESG 2060/94
FORMER RARDE
WALTHAM ABBEY
NORTH SITE
REMEDICATION PROJECT

**SPARE
PHOTOGRAPHS**

IF YOU REMOVE PHOTOGRAPHS FROM
THIS ENVELOPE
PLEASE FILL IN THE

SPARE PHOTOGRAPHS REGISTER'

ESG:15/7600

Missing

FRAME:	DATE:	AREA:	SUBJECT MATTER:
	1 NOV '92	S	KUBOTA EXCAVATOR ACCIDENT IN SOFT GROUND
	2 NOV '92	S	KUBOTA EXCAVATOR ACCIDENT IN SOFT GROUND
	3 NOV '92	S	FALLOW DEER IN SSSI
	4 NOV '92	S	FALLOW DEER IN SSSI
	5 NOV '92	S	NARROW GAUGE RAIL WAY UNCOVERED IN SSSI,BETWEEN BLDG'S 22&23
	6 NOV '92	S	NARROW GAUGE RAIL WAY UNCOVERED IN SSSI,BETWEEN BLDG'S 22&23
	7 NOV '92	P	FITTING OUT SITE ADMINISTRATION OFFICES -BUILDING A320
	8 NOV '92	H I/S	WEST ELEVATION OF BUILDING A200
	9 NOV '92	H I/S	NORTH ELEVATION OF BUILDING A200
	10 NOV '92	H I/S	EAST ELEVATION OF BUILDING A201/2
	11 NOV '92	H I/S	VIEW OF FRACTURED PIER TO NORTH EAST CORNER OF BUILDING A201/2
	12 NOV '92	P	SOUTH ELEVATION OF BUILDING A210 (BOILER HOUSE)
	13 NOV '92	P	NORTH ELEVATION OF BUILDING A210 (BOILER HOUSE)
	14 NOV '92	M	SOUTH ELEVATION OF BUILDING L182
	15 NOV '92	M	NORTH WEST ASPECT OF BUILDING L176
	16 NOV '92	M	SOUTH ELEVATION OF BUILDING L176
	17 NOV '92	M	WEST ELEVATION OF BUILDING L167
	18 NOV '92	M	EAST AND NORTH ELEVATIONS OF BUILDING L167
	19 NOV '92	M	WEST ELEVATION OF BUILDING L157
	20 NOV '92	M	NORTH EAST ELEVATION OF BUILDING L157
	21 NOV '92	M	WEST ELEVATION OF BUILDING L148/L153
	22 NOV '92	M	NORTH EAST ELEVATION OF BUILDING L153
	23 NOV '92	M	NORTH EAST ELEVATION OF BUILDING L149
	24 NOV '92	M	SOUTH ELEVATION OF BUILDING L149
	25 NOV '92	M	ELEVATION OF BUILDING L148
	26 NOV '92	M	NORTH EAST ELEVATION OF BUILDING L145
	27 NOV '92	M	SOUTH ELEVATION OF BUILDING L136
	28 NOV '92	M	SOUTH AND WEST ELEVATIONS OF BUILDING L136
	29 NOV '92	L	SOUTH AND WEST ELEVATIONS OF BUILDING L122
	30 NOV '92	S	VIEW OF TYPICAL WASTE DUMP -MIXED WASTE
	31 NOV '92	S	TYPICAL WASTE DUMP REF.:11036
	32 NOV '92	S	TYPICAL WASTE DUMPREF.:11036 -CONTAINS ASBESTOS
	33 NOV '92	S	DEPICTS A DATED TELEGRAPH POLE FOUND IN SSSI
	34 NOV '92	S	WASTE DUMP REF.:11038, SITUATED NORTH OF THE BURNING GROUND
	35 NOV '92	P	NORTH ELEVATION OF BUILDING A238
	36 NOV '92	P	SOUTH ELEVATION OF BUILDING A221 -DIRECTORS HOUSE(OCCUPIED)
	37 NOV '92	P	(R) EAST ELEVATION OF BUILDING A200(WALTON HOUSE)



BRITISH AEROSPACE
DEFENCE
ROYAL ORDNANCE
ENVIRONMENTAL SERVICES GROUP

**NEGATIVE
REFERENCE:**

16/7809

**REPORT NO.: ESG 2060/94
FORMER RARDE
WALTHAM ABBEY
NORTH SITE
REMEDICATION PROJECT**

**SPARE
PHOTOGRAPHS**

**IF YOU REMOVE PHOTOGRAPHS FROM
THIS ENVELOPE
PLEASE FILL IN THE**

SPARE PHOTOGRAPHS REGISTER'

ESG:16/7809

Missing

FRAME:	DATE:	AREA:	SUBJECT MATTER:
	1		void
	2 NOV '92	P	NORTH ELEVATION OF BUILDING A230
	3 NOV '92	P	NORTH ELEVATION OF BUILDING A231
	4 NOV '92	P	NORTH ELEVATION OF BUILDINGS A232 - A234
	5 NOV '92	P	SOUTH ELEVATION OF BUILDING A221 (MRS BELLAMY'S HOUSE)
	6 NOV '92	P	NORTH ELEVATION OF BUILDING A238
	7 NOV '92	H	NORTH ELEVATION OF BUILDING H25
	8 NOV '92	H	SOUTH ELEVATION OF BUILDING H26
	9 NOV '92	H	WEST ELEVATION OF BUILDING H8
	10 NOV '92	H	EAST ELEVATION OF BUILDING H8
	11 NOV '92	M	WEST ELEVATION OF BUILDING L157
	12 NOV '92	M	WEST ELEVATION OF BUILDING L153 / L148
	13 NOV '92	L	WEST ELEVATION OF BUILDING L185
	14 NOV '92	L	SOUTH ELEVATION OF BUILDING L122
	15 NOV '92	M	EAST ELEVATION OF BUILDING L107
	16 NOV '92	M	SOUTH ELEVATION OF BUILDING L138
	17		void
	18 NOV '92	M	WEST ELEVATION OF BUILDING L133
	19 NOV '92	M	NORTH ELEVATION OF BUILDING L143
	20 NOV '92	S	SOUTH ASPECT OF 'WATERMAN'S COTTAGE'
	21 NOV '92	S	SOUTH ELEVATION OF BUILDING 103 - PRESS HOUSE
	22 NOV '92	S	BUILDING 103 PRESS HOUSE BLAST WALL
	23 NOV '92	S	SOUTH ELEVATION OF BUILDING S31
	24 NOV '92	S	ELEVATION OF BUILDING 890
	25 NOV '92	S	BUILDING S90



BRITISH AEROSPACE
DEFENCE
ROYAL ORDNANCE
ENVIRONMENTAL SERVICES GROUP

**NEGATIVE
REFERENCE:**

17/7810

**REPORT NO.: ESG 2060/94
FORMER RARDE
WALTHAM ABBEY
NORTH SITE
REMEDICATION PROJECT**

**SPARE
PHOTOGRAPHS**

**IF YOU REMOVE PHOTOGRAPHS FROM
THIS ENVELOPE
PLEASE FILL IN THE**

SPARE PHOTOGRAPHS REGISTER'

ESG:17/7810

Missing

FRAME:	DATE:	AREA:	SUBJECT MATTER:
	1 NOV '92	S	ASBESTOS FOUND IN UNDERGROWTH
	2 NOV '92	S	ASBESTOS FOUND IN UNDERGROWTH
	3 NOV '92	T	CONCRETE FOUNDATION EXPOSED IN FORMER TETRYL FACTORY
	4 NOV '92	P	EXPOSED GAS PIPE TO BUILDING A221
	5 NOV '92	B	GENERAL VIEW OF BURNING GROUND
	6 NOV '92	S	RUBBISH COLLECTION BY BUILDING 88A
	7 NOV '92	S	VIEW FROM TOW PATH OPPOSITE BUILDING 88A
	8 NOV '92	S	TYPICAL STEAM MAIN ROUTE THROUGH UNDERGROWTH
	9 NOV '92	S	TRANSPORTATION OF BAGGED ASBESTOS ONSITE
	10 NOV '92	S	DIGGING OUT ASBESTOS FROM STEAM MAIN ROUTE ADJACENT TO BLDG 88A
	11 NOV '92	S	DIGGING OUT ASBESTOS FROM STEAM MAIN ROUTE ADJACENT TO BLDG 88A
	12 NOV '92	S	CANAL SOUTH OF BUILDING 88A -LOOKING EAST
	13 NOV '92	S	CANAL SOUTH OF BUILDING 88A -LOOKING EAST
	14 NOV '92	S	INTERNAL VIEW OF BUILDING 88A -WESTWALL
	15 NOV '92	S	INTERNAL VIEW OF BUILDING 88A -EAST AND NORTH WALLS
	16 NOV '92	S	CANAL SOUTH OF BUILDING 88A
	17 NOV '92	S	STEAM MAIN SUPPORTS
	18 NOV '92	S	STEAM MAIN SUPPORTS
	19 NOV '92	S	STEAM MAIN SUPPORTS
	20 NOV '92	S	STEAM MAIN SUPPORTS
	21 NOV '92	S	SOUTH OF BUILDING 88A -STEAM MAIN ROUTES
	22 NOV '92	S	CANAL SOUTH OF BUILDING 88A
	23 NOV '92	S	SOUTH ELEVATION OF BUILDING 88B
	24 NOV '92	S	STEAM MAIN IN SSSI
	25 NOV '92	S	SOUTH OF BUILDING 88A
	26 NOV '92	S	SOUTH OF BUILDING 88A
	27 NOV '92	S	DIGGING OUT WASTE FROM CANAL ADJACENT TO BUILDING 62
	28 NOV '92	S	EXCAVATION AND BAGGING OF ASBESTOS FOUND IN WASTE DUMP
	29 NOV '92	S	WASTE DUG FROM CANAL ADJACENT TO BUILDING 62
	30 NOV '92	S	CANAL WEST OF BUILDING 62 -LOOKING SOUTH
	31 NOV '92	S	CANAL CLEARANCE WEST OF BUILDING 76
	32 NOV '92	S	NORTH WEST ELEVATION OF BUILDING E14
	33 NOV '92	S	WEST ELEVATION OF BUILDING 76
	34 NOV '92	S	SOUTH WEST ELEVATION OF BUILDING E14
	35 NOV '92	S	SOUTH ELEVATION OF BLDG 76 VIEWED FROM TOP OF BLDG E14 TRAVERSE
	36 NOV '92	S	CANAL NORTH OF BUILDING E14 LOOKING TOWARDS BUILDING 88A
	37 NOV '92	S	VIEW OF BUILDING 88A FROM ROOF OF BUILDING E14



**BRITISH AEROSPACE
DEFENCE**

ROYAL ORDNANCE
ENVIRONMENTAL SERVICES GROUP

**NEGATIVE
REFERENCE:**

18/7998

**REPORT NO.: ESG 2060/94
FORMER RARDE
WALTHAM ABBEY
NORTH SITE
REMEDICATION PROJECT**

**SPARE
PHOTOGRAPHS**

**IF YOU REMOVE PHOTOGRAPHS FROM
THIS ENVELOPE
PLEASE FILL IN THE**

'SPARE PHOTOGRAPHS REGISTER'

ESG:18/7998

Missing

FRAME:	DATE:	AREA:	SUBJECT MATTER:
	1 DEC '92	H	SOUTH ELEVATION OF BUILDING H26
	2 DEC '92	H	SOUTH WEST ELEVATION OF BUILDING H26
	3 DEC '92	H	NORTH WEST ELEVATION OF BUILDING A203 (BRIDGE 17 IN FOREGROUND)
	4 DEC '92	H	NORTH AND EAST ELEVATIONS OF BUILDING H7
	5 DEC '92	L	NORTH AND WEST ELEVATIONS OF BUILDING L122
	6 DEC '92	M	NORTH AND WEST ELEVATIONS OF BUILDING L145
	7 DEC '92	M	WEST ELEVATION OF BUILDING L148
	8 DEC '92	S	SOUTH WEST ELEVATION OF 'WATERMAN'S COTTAGE'
	9 DEC '92	S	NORTH ELEVATION OF 'WATERMAN'S COTTAGE'
	10 DEC '92	H	EAST ELEVATION OF BUILDING A203
	11 DEC '92	P	EAST ELEVATION OF BUILDING A268
	12 DEC '92	P	EAST ELEVATION OF BUILDING A26
	13 DEC '92	P	NORTH ELEVATION OF BUILDING A238 (MAIN GATE TO SITE)
	14 DEC '92	P	SOUTH ELEVATION OF BUILDING A221
	15 DEC '92	P	EAST ELEVATION OF BUILDING A221
	16 DEC '92	P	WEST ELEVATION OF BUILDING A268
	17 DEC '92	P	NORTH AND WEST ELEVATIONS OF BUILDING A269
	18 DEC '92	M	NORTH EAST ELEVATION OF BUILDING L177
	19 DEC '92	M	SOUTH EAST ELEVATION OF BUILDING L177
	20 DEC '92	M	NORTH ELEVATION OF BUILDING L168
	21 DEC '92	L	NORTH EAST ELEVATION OF BUILDING L165
	22 DEC '92	L	WEST ELEVATION OF BUILDING L165
	23 DEC '92	M	SOUTH AND WEST ELEVATIONS OF BUILDING L168



BRITISH AEROSPACE
DEFENCE

ROYAL ORDNANCE
ENVIRONMENTAL SERVICES GROUP

**NEGATIVE
REFERENCE:**

20/9355

**REPORT NO.: ESG 2060/94
FORMER RARDE
WALTHAM ABBEY
NORTH SITE
REMEDICATION PROJECT**

**SPARE
PHOTOGRAPHS**

**IF YOU REMOVE PHOTOGRAPHS FROM
THIS ENVELOPE
PLEASE FILL IN THE**

SPARE PHOTOGRAPHS REGISTER'

ESG:20/9355

Missing

FRAME:	DATE:	AREA:	SUBJECTMATTER:
	1 JAN '93	S	FLOODED CANAL WEST OF LONG WALK -LOOKING NORTH AT BRIDGE 7
	2 JAN '93	S	FLOODED CANAL WEST OF LONG WALK -LOOKING NORTH AT BRIDGE 7
	3 JAN '93	S	AREA EAST OF BUILDING L128-SHOWING FLOODING
	4 JAN '93	S	NORTH WEST ACCESS BRIDGE TO BUILDING L128 -BRIDGE No.7
	5 JAN '93	S	FLOODING IN OLD MILLHEAD STREAM VIEWED FROM WEST SIDE OF BUILDING L128 -LOOKING SOUTH
	6 JAN '93	S	FLOODING IN CANAL SOUTH OF BUILDING 107 AND 108
	7 JAN '93	S	FLOODING WEST OF LONG WALK
	8 JAN '93	S	FLOODING IN CANAL WEST OF BUILDING S30 -LOOKING SOUTH
	9 JAN '93	S	VIEW SOUTH OF BUILDING S28 (WEST)
	10 JAN '93	S	FLOODING IN CANAL WEST OF BUILDING S30 (WEST)
	11 JAN '93	S	ASBESTOS MATERIAL STACKED FOR DISPOSAL
	12 JAN '93	S	ASBESTOS MATERIAL STACKED FOR DISPOSAL
	13 JAN '93	S	FLOODED POND NORTH OF BUILDING E2
	14 JAN '93	S	ARTEFACT FOUND NEAR POND NORTH OF BUILDING E2
	15 JAN '93	S	FLOODED CONTAMINATED POND NORTH OF BUILDING E2
	16 JAN '93	S	FLOODED CONTAMINATED POND NORTH OF BUILDING E2
	17 JAN '93	S	FLOODED POND NORTH WEST OF BUILDING E2
	18 JAN '93	M	NOTICE ON DOOR IN BUILDING L145 PRIOR TO STRIPPING OUT BUILDING L148
	19 JAN '93	S	CRACKED WILLOW DAMAGED IN GATE
	20 JAN '93	B	BUILDING 96-COLLAPSING THE ROOF TO MAKE IT SAFE
	21 JAN '93	B	GENERAL VIEW OF BUILDING 96
	22 JAN '93	B	GAS CYLINDER ADJACENT TO BUILDING L103
	23 JAN '93	S	FLOODED AREA OF SSSI
	24 JAN '93	S	REMOVAL OF CONCRETE AND MASONRY WEST OF BUILDING 103
	25 JAN '93	S	CONTAMINATION ON AREA WEST OF BUILDING 103
	26 JAN '93	S	ROAD SWEEPER (KEEPING SITE ACCESS ROUTES CLEAN)
	27 JAN '93	M	SOUTH EAST CORNER OF AREA 'M' -REMOVAL OF CORDITE CONTAMINATED SOIL
	28 JAN '93	M	SOUTH EAST CORNER OF AREA 'M' -REMOVAL OF CORDITE CONTAMINATED SOIL
	29 JAN '93	M	SOUTH EAST CORNER OF AREA 'M' -REMOVAL OF CORDITE CONTAMINATED SOIL
	30 JAN '93	M	SCREENING CORDITE CONTAMINATED SOIL
	31 JAN '93	M	SCREENING CORDITE CONTAMINATED SOIL
	32 JAN '93	M	SCREENING CORDITE CONTAMINATED SOIL
	33 JAN '93	M	SCREENING CORDITE CONTAMINATED SOIL
	34 JAN '93	M	SCREENING CORDITE CONTAMINATED SOIL
	35 JAN '93	M	SCREENING CORDITE CONTAMINATED SOIL
	36 JAN '93	M	SCREENING CORDITE CONTAMINATED SOIL
	37 JAN '93	M	SCREENING CORDITE CONTAMINATED SOIL



BRITISH AEROSPACE
DEFENCE
ROYAL ORDNANCE
ENVIRONMENTAL SERVICES GROUP

**NEGATIVE
REFERENCE:**

21/9361

**REPORT NO.: ESG 2060/94
FORMER RARDE
WALTHAM ABBEY
NORTH SITE
REMEDICATION PROJECT**

**SPARE
PHOTOGRAPHS**

**IF YOU REMOVE PHOTOGRAPHS FROM
THIS ENVELOPE
PLEASE FILL IN THE**

'SPARE PHOTOGRAPHS REGISTER'

ESG:21/9361

Missing

FRAME:	DATE:	AREA:	SUBJECT MATTER:
	1 JAN '93	B	CLEARANCE OF CANAL WEST OF BUILDING L103
	2 JAN '93	B	GAS CYLINDERS REMOVED FROM WASTE FILLED CANAL WEST -BLDG L103
	3 JAN '93	H	EXCAVATED MATERIAL FROM FILLED CANALS BEING TIPPED ON H16 SAMPLING SLAB
	4 JAN '93	H	MACHINE TRACKING BETWEEN BAYS OF CONTAMINATED MATERIAL ON H16 SLAB
	5 JAN '93	H	SAMPLING IN PROGRESS -CONTAMINATED WASTE (H16 SAMPLING AREA)
	6 JAN '93	H	SAMPLING IN PROGRESS -CONTAMINATED WASTE (H16 SAMPLING AREA)
	7 JAN '93	B	FURTHER EXCAVATION OF CONTAMINATED WASTE WEST OF BLDG. L103
	8 JAN '93	B	GAS CYLINDERS REMOVED FROM WASTE FILLED CANAL WEST -BLDG L103
	9 JAN '93	B	INSPECTION OF GAS CYLINDERS FROM FILLED CANAL WESTBLDG L103
	10 JAN '93	H	VIEW OF CONTAMINATED WASTE SAMPLING AREA ON H16
	11 JAN '93	H	CONTAMINATED WASTE STORED ON H16 SAMPLING AREA
	12 JAN '93	B	GAS CYLINDERS REMOVED FROM WASTE FILLED CANAL WEST -BLDG L103
	13 JAN '93	B	GAS CYLINDERS REMOVED FROM WASTE FILLED CANAL WEST -BLDG L103
	14 JAN '93	B	GAS CYLINDERS REMOVED FROM WASTE FILLED CANAL WEST -BLDG L103
	15 JAN '93	B	EXCAVATION OF WASTE FILLED CANAL WEST OF BUILDING L103
	16 JAN '93	B	GAS CYLINDERS REMOVED FROM WASTE FILLED CANALS
	17 JAN '93	B	EXCAVATION OF WASTE FILLED CANAL IN PROGRESS -WEST OF BLDG L103
	18 JAN '93	B	VIEW OF CANOPY TO BUILDING L103 ON CANAL SIDE
	19 JAN '93	B	CONTAMINATED WASTE IN CANAL WEST OF BLDG L103(ADJACENT TO BLDG ENTRANCE)
	20 JAN '93	B	SOUTH VIEW SHOWING EXCAVATION OF WASTE FILLED CANAL WEST OF BLDG L103
	21 JAN '93	B	CONTAMINATED WASTE IN CANAL WEST OF BUILDING L103
	22 JAN '93	S	CONTAMINATED WASTE TIP SOUTH EAST OF BUILDINGS 107 AND 108
	23 JAN '93	S	PIPE BRIDGES OVER WASTE FILLED CANALS, WEST OF BURNING GROUND
	24 JAN '93	H	H16 SAMPLING AREA
	25 JAN '93	H	H16 SAMPLING AREA
	26 JAN '93	H	CONTAMINATED BOTTLES FROM WASTE ON H16 SAMPLING ARE
	27 JAN '93	B	FUSE RECOVERED FROM NORTH END OF BURNING GROUND
	28 JAN '93	B	FUSE RECOVERED FROM NORTH END OF BURNING GROUND
	29 JAN '93	L	FLOODED AREA WEST OF INCORPORATING MILLS (QUEENS MEAD)
	30 JAN '93	B	FLOODED CANAL WEST OF BUILDING L103
	31 JAN '93	S	FLOODED CANAL WEST OF BUILDING 76
	32 JAN '93	S	FLOODED AREA AROUND MACHINE (LOOKING NORTH TOWARDS BLDG 62)
	33 JAN '93	S	FLOODED CANAL WEST OF BUILDING 76
	34 JAN '93	S	FLOODED CANAL -BUILDING E14 RIGHT OF PICTURE
	35 JAN '93	T	FLOODED TETRYL AREA, VIEW TOWARDS HORSEMILL STREAM
	36 JAN '93	S	FLOODED PONDS NORTH OF BUILDINGS E2
	37 JAN '93	S	EXTENT OF EROSION DUE TO FLOOD WEST OF BUILDING E12



BRITISH AEROSPACE
DEFENCE
ROYAL ORDNANCE
ENVIRONMENTAL SERVICES GROUP

NEGATIVE
REFERENCE:

22/9590

REPORT NO.: ESG 2060/94
FORMER RARDE
WALTHAM ABBEY
NORTH SITE
REMEDIAATION PROJECT

**SPARE
PHOTOGRAPHS**

IF YOU REMOVE PHOTOGRAPHS FROM
THIS ENVELOPE
PLEASE FILL IN THE

'SPARE PHOTOGRAPHS REGISTER'

ESG:22/9590

Missing

FRAME:	DATE:	AREA:	SUBJECT MATTER:
	1 JAN '93	M	EAST ELEVATION OF BUILDING L148
	2 JAN '93	M	EAST ELEVATION OF BUILDING L148
	3 JAN '93	M	VIEW ALONG EAST ELEVATION OF BUILDING L148
	4 JAN '93	M	VIEW ALONG EAST ELEVATION OF BUILDING L148
	5 JAN '93	M	EXTERNAL VIEW OF BUILDING L148
	6 JAN '93	M	WEST ELEVATION OF BUILDING L148
	7 JAN '93	M	INTERNAL VIEW OF BUILDING L148
	8 JAN '93	M	INTERNAL VIEW OF BUILDING L148
	9 JAN '93	M	INTERNAL VIEW OF BUILDING L148
	10 JAN '93	M	INTERNAL VIEW OF BUILDING L148
	11 JAN '93	M	INTERNAL VIEW OF BUILDING L148
	12 JAN '93	M	INTERNAL VIEW OF BUILDING L148
	13 JAN '93	M	INTERNAL VIEW OF BUILDING L148
	14 JAN '93	M	INTERNAL VIEW OF BUILDING L148
	15 JAN '93	M	INTERNAL VIEW OF UNDER FLOOR VOID IN BUILDING L148
	16 JAN '93	M	INTERNAL VIEW OF UNDER FLOOR VOID IN BUILDING L148
	17 JAN '93	M	INTERNAL VIEW OF UNDER FLOOR VOID IN BUILDING L148
	18 JAN '93	M	INTERNAL VIEW OF UNDER FLOOR VOID IN BUILDING L148
	19 JAN '93	M	INTERNAL VIEW OF UNDER FLOOR VOID IN BUILDING L148
	20 JAN '93	M	INTERNAL VIEW OF UNDER FLOOR VOID IN BUILDING L148
	21 JAN '93	M	INTERNAL VIEW OF UNDER FLOOR VOID IN BUILDING L148
	22 JAN '93	M	INTERNAL VIEW OF UNDER FLOOR VOID IN BUILDING L148
	23 JAN '93	M	INTERNAL VIEW OF UNDER FLOOR VOID IN BUILDING L148
	24 JAN '93	M	INTERNAL VIEW OF UNDER FLOOR VOID IN BUILDING L148
	25 JAN '93	M	INTERNAL VIEW OF UNDER FLOOR VOID IN BUILDING L148
	26 JAN '93	M	INTERNAL VIEW OF UNDER FLOOR VOID IN BUILDING L148
	27 JAN '93	M	INTERNAL VIEW OF UNDER FLOOR VOID IN BUILDING L148
	28 JAN '93	M	INTERNAL VIEW OF UNDER FLOOR VOID IN BUILDING L148
	29 JAN '93	M	INTERNAL VIEW OF UNDER FLOOR VOID IN BUILDING L148
	30 JAN '93	M	INTERNAL VIEW OF UNDER FLOOR VOID IN BUILDING L148
	31 JAN '93	M	INTERNAL VIEW OF UNDER FLOOR VOID IN BUILDING L148
	32 JAN '93	M	INTERNAL VIEW OF UNDER FLOOR VOID IN BUILDING L148
	33 JAN '93	M	INTERNAL VIEW OF UNDER FLOOR VOID IN BUILDING L148
	34 JAN '93	M	INTERNAL VIEW OF UNDER FLOOR VOID IN BUILDING L148
	35 JAN '93	M	INTERNAL VIEW OF UNDER FLOOR VOID IN BUILDING L148
	36 JAN '93	M	INTERNAL VIEW OF UNDER FLOOR VOID IN BUILDING L148
	37 JAN '93	M	VIEW DOWN UNDER FLOOR VOID IN BUILDING L148



BRITISH AEROSPACE
DEFENCE
ROYAL ORDNANCE
ENVIRONMENTAL SERVICES GROUP

**NEGATIVE
REFERENCE:**

23/9591

**REPORT NO.: ESG 2060/94
FORMER RARDE
WALTHAM ABBEY
NORTH SITE
REMEDICATION PROJECT**

**SPARE
PHOTOGRAPHS**

**IF YOU REMOVE PHOTOGRAPHS FROM
THIS ENVELOPE
PLEASE FILL IN THE**

SPARE PHOTOGRAPHS REGISTER'

ESG:23/9591

Missing

FRAME:	DATE:	AREA:	SUBJECT MATTER:
	1 JAN '93	S	TIP SITE 11036 (DISCOVERING BURIED ASBESTOS)
	2 JAN '93	S	TIP SITE 11036 (DISCOVERING BURIED ASBESTOS)
	3 JAN '93	S	TIP SITE 11036 (TREES GROWING OUT OF TIP)
	4 JAN '93	S	TIP SITE11036(DISCOVERY OF ASBESTOS AND CHEMICALS)
	5 JAN '93	S	TIP SITE 11036(DISCOVERYOF CHEMICALS)
	6 JAN '93	S	TIP SITE 11036 (DISCOVERY OF ASBESTOS)
	7 JAN '93	S	TIP SITE 11036 (DISCOVERY OF ASBESTOS)
	8 JAN '93	S	TIP SITE 11036 (DISCOVERY OF ASBESTOS ANDVEHICLEBATTERY)
	9 JAN '93	S	TIP SITE 11036 (DISCOVERY OF ASBESTOS AND VEHICLE BATTERY)
	10 JAN '93	S	TIP SITE 11036 (DISCOVERY OF ASBESTOS AND METALS)
	11 JAN '93	S	TIP SITE 11036 (DISCOVERY OF ASBESTOS AND METALS)
	12 JAN '93	S	TIP SITE 11036 (REMAINS OF DEMOLISHED STRUCTURES WITHIN RUBBISH DUMP)
	13 JAN '93	M	CORDITEREMOVAL
	14 JAN '93	M	CORDITE REMOVAL
	15 JAN '93	M	CORDITE REMOVAL
	16 JAN '93	M	INTERNAL VIEW OF UNDERCROFT IN BUILDING L153
	17 JAN '93	M	INTERNAL VIEW OF UNDERCROFT IN BUILDING L153
	18 JAN '93	M	INTERNAL VIEW OF BUILDING L153 (ENTRANCE TO UNDERCROFT)
	19 JAN '93	S	TIP SITE 11036 (ASBESTOS WITHIN RUBBISH DUMP)
	20 JAN '93	S	TIP SITE 11036 (ASBESTOS WITHIN RUBBISH DUMP)
	21 JAN '93	S	TIP SITE 11036 (TREES GROWING IN WASTE)
	22 JAN '93	S	PIT LOCATED ADJACENT TO BUILDING S31
	23 JAN '93	S	EXCAVATION NORTH EAST OF BUILDING S29
	24 JAN '93	S	HERONRY DEMARCATION TAPE
	25 JAN '93	M	REMOVAL OF CORDITE
	26 JAN '93	M	REMOVAL OF CORDITE
	27 JAN '93	M	REMOVAL OF CORDITE
	28 JAN '93	M	CORDITE REMOVAL (CORDITE VISIBLE IN STICK FORM)
	29 JAN '93	M	CORDITE REMOVAL
	30 JAN '93	S	TIP SITE 11036 (ASBESTOS REMOVAL)
	31 JAN '93	S	TIP SITE 11036 (CHEMICAL GLASSWARE)
	32 JAN '93	S	TIP SITE 11036 (ASBESTOS REMOVAL)
	33 JAN '93	S	TIP SITE 11036 (ASBESTOS REMOVAL)
	34 JAN '93	S	TIP SITE 11036 (ASBESTOS REMOVAL)
	35 JAN '93	M	HOLDING AREA FOR REMOVED CONCRETE FOUNDATIONS
	36 JAN '93	M	HOLDING AREA FOR REMOVED CONCRETE FOUNDATIONS
	37 JAN '93	M	HOLDING AREA FOR REMOVED CONCRETE FOUNDATIONS



BRITISH AEROSPACE
DEFENCE
ROYAL ORDNANCE
ENVIRONMENTAL SERVICES GROUP

NEGATIVE
REFERENCE:

24/9990

REPORT NO.: ESG 2060/94
FORMER RARDE
WALTHAM ABBEY
NORTH SITE
REMEDIATION PROJECT

**SPARE
PHOTOGRAPHS**

**IF YOU REMOVE PHOTOGRAPHS FROM
THIS ENVELOPE
PLEASE FILL IN THE**

SPARE PHOTOGRAPHS REGISTER'

ESG:24/9990

Missing

FRAME:	DATE:	AREA:	SUBJECT MATTER:
	1 JAN '93	H	INTERNAL VIEW OF BUILDING H10
	2 JAN '93	H	INTERNAL VIEW OF BUILDING H10
	3 JAN '93	H	INTERNAL VIEW OF BUILDING H10
	4 JAN '93	H	INTERNAL VIEW OF BUILDING H10
	5 JAN '93	H	INTERNAL VIEW OF BUILDING H10
	6 JAN '93	H	INTERNAL VIEW OF BUILDING H10
	7 JAN '93	M	CORDITE AREA EXCAVATION -LOOKING NORTH
	8 JAN '93	M	CORDITE AREA EXCAVATION -LOOKING NORTH
	9 JAN '93	M	CORDITE AREA EXCAVATION -LOOKING NORTH
	10 JAN '93	M	CORDITE AREA EXCAVATION -LOOKING NORTH
	11 JAN '93	M	CORDITE AREA EXCAVATION-LOOKING NORTH
	12 JAN '93	M	CORDITE AREA EXCAVATION -LOOKING SOUTH WEST
	13 JAN '93	M	CORDITE AREA EXCAVATION
	14 JAN '93	M	CORDITE AREA EXCAVATION -LOOKING WEST
	15 JAN '93	M	CORDITE AREA EXCAVATION (ASBESTOS WASTE)
	16 JAN '93	M	CORDITE AREA EXCAVATION (SCREENING PLANT)
	17 JAN '93	M	CORDITE AREA EXCAVATION (SCREENING PLANT)
	18 JAN '93	M	CORDITE AREA EXCAVATION (SCREENING WASTE)
	19 JAN '93	M	CORDITE AREA EXCAVATION(SCREENINGPLANT)
	20 JAN '93	S	TAKING OUR STEAM MAIN FOUNDATIONS NORTH OF BUILDING L136
	21 JAN '93	S	WEST ELEVATION OF BUILDING L135
	22 JAN '93	M	EAST ELEVATION OF BUILDING L148
	23 JAN '93	B	EXPOSED FUSE ADJACENT TO BUILDING 96
	24 JAN '93	B	EXPOSED FUSE ADJACENT TO BUILDING 96
	25 JAN '93	B	INSPECTION OF GAS CYLINDERS BY ROYAL ORDNANCE ADJACENT TO BLDG L175



BRITISH AEROSPACE
DEFENCE
ROYAL ORDNANCE
ENVIRONMENTAL SERVICES GROUP

**NEGATIVE
REFERENCE:**

25/0129

**REPORT NO.: ESG 2060/94
FORMER RARDE
WALTHAM ABBEY
NORTH SITE
REMEDICATION PROJECT**

**SPARE
PHOTOGRAPHS**

**IF YOU REMOVE PHOTOGRAPHS FROM
THIS ENVELOPE
PLEASE FILL IN THE**

'SPARE PHOTOGRAPHS REGISTER'

ESG:25/0129

Missing

FRAME:	DATE:	AREA:	SUBJECT MATTER:
	0 JAN '93	S	POWDER BARGE (RCHME REF.: 104)
	1 JAN '93	S	POWDER BARGE (RCHME REF.: 104)
	2 JAN '93	S	VIEW THROUGH EAST SECURITY FENCE
	3 JAN '93	S	POWDER BARGE WEST OF BLDG 76 - LOOKING NORTH EAST (RCHME REF.: 101)
	4 JAN '93	S	POWDER BARGE WEST OF BUILDING 76 - LOOKING EAST (RCHME REF.: 101)
	5 JAN '93	S	POWDER BARGE WEST OF BLDG 76 - LOOKING SOUTH (RCHME REF.: 101)
	6 JAN '93	S	POWDER BARGE WEST OF BLDG 76 - LOOKING NORTH (RCHME REF.: 101)
	7 JAN '93	S	POWDER BARGE WEST OF BLDG 76 - LOOKING NORTH EAST (RCHME REF.: 101)
	8 JAN '93	S	LOCK GATES (RCHME REF.: 225)
	9 JAN '93	S	VIEW LOOKING WEST ON BUILDING L109
	10 JAN '93	S	POWDER BARGE (RCHME RE.: 157)
	11 JAN '93	S	POWDER BARGES (RCHME 157-160)
	12 JAN '93	S	POWDER BARGES (RCHME 157-160)
	13 JAN '93	S	POWDER BARGES (RCHME 157-160)
	14 JAN '93	S	SITE OPERATIVES (TEMPORARY SAFETY FENCING)
	15 JAN '93	M	INTERNAL VIEW OF BUILDING L148 (STRIPPING OUT)
	16 JAN '93	M	INTERNAL VIEW OF BUILDING L148 (STRIPPING OUT)
	17 JAN '93	M	INTERNAL VIEW OF BUILDING L148 (STRIPPING OUT)
	18 JAN '93	M	INTERNAL VIEW OF BUILDING L148 (STRIPPING OUT)
	19 JAN '93	M	INTERNAL VIEW OF BUILDING L148 (STRIPPING OUT)
	20 JAN '93	M	SOUTH EAST ELEVATION OF BUILDING L148
	21 JAN '93	M	INTERNAL VIEW OF BUILDING L148 (STRIPPING OUT)
	22 JAN '93	M	INTERNAL VIEW OF BUILDING L148 (STRIPPING OUT)
	23 JAN '93	M	INTERNAL VIEW OF BUILDING L148 (STRIPPING OUT)
	24 JAN '93	M	INTERNAL VIEW OF BUILDING L148 (STRIPPING OUT)
	25 JAN '93	M	INTERNAL VIEW OF BUILDING L148 (STRIPPING OUT)
	26 JAN '93	M	INTERNAL VIEW OF BUILDING L148 (STRIPPING OUT)
	27 JAN '93	M	INTERNAL VIEW OF BUILDING L148 (STRIPPING OUT)
	28 JAN '93	M	INTERNAL VIEW OF BUILDING L148 (STRIPPING OUT)
	29 JAN '93	M	INTERNAL VIEW OF BUILDING L148 (STRIPPING OUT)
	30 JAN '93	P	WEST ELEVATION OF BUILDING A269
	31 JAN '93	P	NORTH ELEVATION OF BUILDING A269
	32 JAN '93	M	INTERNAL VIEW OF BUILDING L148 (ASPHALT FLOOR SURFACE REMOVAL)
	33 JAN '93	M	INTERNAL VIEW OF BUILDING L148 (STRIPPING OUT)
	34 JAN '93	M	INTERNAL VIEW OF BUILDING L148 (VACUUMING INTERNAL SURFACES)
	35 JAN '93	M	INTERNAL VIEW OF BUILDING L148 (ASPHALT FLOOR SURFACE REMOVAL)
	36 JAN '93	P	WEST ELEVATION OF BUILDING A269
	37 JAN '93	P	WEST ELEVATION OF BUILDING A269



BRITISH AEROSPACE
DEFENCE
ROYAL ORDNANCE
ENVIRONMENTAL SERVICES GROUP

**NEGATIVE
REFERENCE:**

26/0130

**REPORT NO.: ESG 2060/94
FORMER RARDE
WALTHAM ABBEY
NORTH SITE
REMEDIAION PROJECT**

**SPARE
PHOTOGRAPHS**

**IF YOU REMOVE PHOTOGRAPHS FROM
THIS ENVELOPE
PLEASE FILL IN THE**

SPARE PHOTOGRAPHS REGISTER'

ESG:26/0130

Missing

FRAME:	DATE:	AREA:	SUBJECT MATTER:
	1 JAN '93	B	EMBLEM IN BUILDING L102 (ROYAL GUNPOWDER FACTORY DEPICTED)
	2 JAN '93	B	EMBLEM IN BUILDING L102 (ROYAL GUNPOWDER FACTORY DEPICTED)
	3 JAN '93	B	EMBLEM ON BRIDGE No. 16 -EAST OF BUILDING 96
	4 JAN '93	B	EMBLEM ON SIDE OF AQUEDUCT -BRIDGE No.14 (NORTH EAST OF BLDG 96)
	5 JAN '93	S	EMBLEM ON BRIDGE No.16
	6 JAN '93	S	CLOSE UP VIEW OF EMBLEM ON BRIDGE No.16
	7 JAN '93	S	EMBLEM ON BRIDGE No. 16
	8 JAN '93	B	EMBLEM ON SIDE OF AQUEDUCT -BRIDGE No. 14 (NORTH EAST OF BLDG 96)
	9 JAN '93	B	BRIDGE No. 16 -SOUTH ELEVATION
	10 JAN '93	B	BRIDGE No. 19 -CARRYING BRIDGE TO BUILDING 96
	11 JAN '93	B	BRIDGE No. 16 -SOUTH ELEVATION
	12 JAN '93	B	BRIDGE No. 16 -SOUTH ELEVATION
	13 JAN '93	B	SOUTH EAST VIEW OF BURNING GROUND



BRITISH AEROSPACE
DEFENCE
ROYAL ORDNANCE
ENVIRONMENTAL SERVICES GROUP

**NEGATIVE
REFERENCE:**

27/0536

**REPORT NO.: ESG 2060/94
FORMER RARDE
WALTHAM ABBEY
NORTH SITE
REMEDICATION PROJECT**

**SPARE
PHOTOGRAPHS**

**IF YOU REMOVE PHOTOGRAPHS FROM
THIS ENVELOPE
PLEASE FILL IN THE**

'SPARE PHOTOGRAPHS REGISTER'

ESG:27/0536

Missing

FRAME:	DATE:	AREA:	SUBJECT MATTER:
	1		void
	2		void
	3 FEB '93	M	CORDITE EXPOSED IN CORDITE AREA
	4 FEB '93	M	CORDITE EXPOSED IN CORDITE AREA
	5 FEB '93	M	CORDITE EXPOSED IN CORDITE AREA
	6 FEB '93	M	CORDITE EXPOSED IN CORDITE AREA
	7		void
	8		void
	9 FEB '93	B	INVESTIGATING CONTAMINATED MATERIAL FROM TIP No. 11038 - BURNING GROUND NORTH
	10 FEB '93	B	LOOKING THROUGH TIP No. 11038 NORTH BURNING GROUND
	11 FEB '93	M	CONCRETE BASE OF BUILDING L169 (SET OUT FOR SAMPLING OF WASTE)
	12 FEB '93	M	CONCRETE BASE OF BUILDING L169 (SET OUT FOR SAMPLING OF WASTE)
	13 FEB '93	M	CONCRETE BASE OF BUILDING L169 (SET OUT FOR SAMPLING OF WASTE)
	14 FEB '93	L	VIEW LOOKING NORTH FROM BUILDING L169 ACROSS 'QUEENS MEAD'
	15 FEB '93	M	WASTE BEGIN DELIVERED TO SAMPLING SLAB AT L169
	16 FEB '93	M	EXCAVATION IN CORDITE AREA (BUILDING L160 IN TOP RIGHT)
	17 FEB '93	M	EXCAVATION IN CORDITE AREA (BUILDING L160 IN TOP RIGHT)
	18 FEB '93	M	EXCAVATION IN CORDITE AREA (BUILDING L160 IN TOP RIGHT)
	19 FEB '93	M	EXCAVATION IN CORDITE AREA
	20 FEB '93	M	EXCAVATION IN CORDITE AREA
	21 FEB '93	M	CORDITE FOUND
	22 FEB '93	M	CORDITE FOUND
	23 FEB '93	M	SOUTH ELEVATION OF BUILDING L148
	24 FEB '93	M	STOCKPILE OF ASBESTOS CONTAMINATED SOIL
	25 FEB '93	M	ASBESTOS CONTAMINATED SOIL, STRIPPED ALONG WEST ELEVATION OF BUILDING L157
	26 FEB '93	L	ASBESTOS CONTAMINATED SOIL, STRIPPED ALONG WEST ELEVATION OF BUILDING L157
	27 FEB '93	M	WASTE SAMPLING AT L169 SAMPLING AREA (P.P.E.)
	28 FEB '93	P	JUNCTION OF POWDERMILL LANE AND FLAGSTAFF ROAD LOOKING SOUTH
	29 FEB '93	M	BUILDING L157 UNDERCROFT
	30 FEB '93	S	FALLEN TREE WEST SSSI
	31 FEB '93	S	FALLEN TREE WEST SSSI
	32 FEB '93	S	FALLEN TREE WEST SSSI
	33 FEB '93	S	STEAM PIPE ROUTE NORTH OF BUILDING 76
	34 FEB '93	S	STEAM PIPE ROUTE NORTH OF BUILDING 76 (ASBESTOS CONTAMINATION)
	35 FEB '93	S	STEAM PIPE ROUTE NORTH OF BUILDING 76 (ASBESTOS CONTAMINATION)
	36 FEB '93	S	GROUND UNDER STEAM PIPE ROUTE NORTH BUILDING 76 (ASBESTOS CONTAMINATION)
	37 FEB '93	S	STEAM PIPE ROUTE NORTH OF BUILDING 76 (ASBESTOS CONTAMINATION)



BRITISH AEROSPACE
DEFENCE
ROYAL ORDNANCE
ENVIRONMENTAL SERVICES GROUP

**NEGATIVE
REFERENCE:**

28/1012

**REPORT NO.: ESG 2060/94
FORMER RARDE
WALTHAM ABBEY
NORTH SITE
REMEDICATION PROJECT**

**SPARE
PHOTOGRAPHS**

**IF YOU REMOVE PHOTOGRAPHS FROM
THIS ENVELOPE
PLEASE FILL IN THE**

SPARE PHOTOGRAPHS REGISTER'

ESG:28/1012

Missing

FRAME:	DATE:	AREA:	SUBJECT MATTER:
	1 FEB '93	S	WASTE TIP SOUTH OF BUILDING S32 (ASBESTOS)
	2 FEB '93	S	WASTE TIP SOUTH OF BUILDING S32 (ASBESTOS)
	3 FEB '93	S	WASTE TIP SOUTH OF BUILDING S32 (ASBESTOS)
	4 FEB '93	M	MILLSTONE FOUND WHILST SCRAPPING
	5 FEB '93	M	INTERNAL VIEW OF BUILDING L157-1ST STAGE DECONTAMINATION
	6 FEB '93	M	INTERNAL VIEW OF BUILDING L157-1ST STAGE DECONTAMINATION
	7 FEB '93	M	INTERNAL VIEW OF BUILDING L157 -1ST STAGE DECONTAMINATION
	8 FEB '93	M	INTERNAL VIEW OF BUILDING L157 -1ST STAGE DECONTAMINATION
	9 FEB '93	M	INTERNAL VIEW OF BUILDING L157 (PRIOR TO DECONTAMINATION)
	10 FEB '93	M	INTERNAL VIEW OF BUILDING L157 (PRIOR TO DECONTAMINATION)
	11 FEB '93	M	INTERNAL VIEW OF BUILDING L157 (BAGGED ASBESTOS)
	12 FEB '93	M	INTERNAL VIEW OF BUILDING L157 (CONTAMINATED STEELWORK STACKED)
	13 FEB '93	M	INTERNAL VIEW OF BUILDING L157 (BAGGED CONTAMINATED MATERIAL)
	14 FEB '93	M	INTERNAL VIEW OF BUILDING L157 (BAGGED CONTAMINATED MATERIAL)
	15 FEB '93	M	INTERNAL VIEW OF BUILDING L157 (BAGGED CONTAMINATED MATERIAL)
	16 FEB '93	M	INTERNAL VIEW OF BUILDING L157 (PRIOR TO DECONTAMINATION)
	17 FEB '93	M	INTERNAL VIEW OF BUILDING L157 (BAGGED CONTAMINATED MATERIAL AND TIMBER)
	18 FEB '93	M	INTERNAL VIEW OF BUILDING L157-DECONTAMINATION OPERATIVES
	19 FEB '93	M	INTERNAL VIEW OF BUILDING L157 -DECONTAMINATION OPERATIVES
	20 FEB '93	M	INTERNAL VIEW OF BUILDING L157-DECONTAMINATION OPERATIVE
	21 FEB '93	M	INTERNAL VIEW OF BUILDING L157(ASBESTOS REMOVAL CONTRACTOR'S NEGATIVE AIR TENT)
	22 FEB '93	M	BUILDING L157 -EXTERNAL SAVEALL DRAIN
	23 FEB '93	M	CORDITE SCREENING PLANT
	24 FEB '93	M	GRADED ARISINGS FROM CORDITE CONTAMINATED AREAS
	25 FEB '93	M	STOCKPILING SCREENED CORDITE ARISINGS
	26 FEB '93	M	STOCKPILING OF ARISINGS FROM CORDITE CONTAMINATED AREA
	27 FEB '93	M	SCREENED ARISINGS FROM CORDITE CONTAMINATED AREA
	28 FEB '93	M	CLOSE UP OF GRADED ARISINGS FROM CORDITE CONTAMINATED AREA
	29 FEB '93	M	GRADED ARISINGS FROM CORDITE CONTAMINATED AREA
	30 FEB '93	M	CLOSE UP OF GRADED ARISINGS FROM CORDITE CONTAMINATED AREA
	31 FEB '93	M	COARSE SCREENED ARISINGS FROM CORDITE CONTAMINATED AREA
	32 FEB '93	M	CLOSEUP OF GRADED ARISINGS FROM CORDITE CONTAMINATED AREA
	33 FEB '93	M	MILLSTONE EXCAVATED FROM CORDITE AREA
	34 FEB '93	M	MILLSTONE EXCAVATED FROM CORDITE AREA
	35 FEB '93	M	MILLSTONES EXCAVATED FROM CORDITE AREA



BRITISH AEROSPACE
DEFENCE
ROYAL ORDNANCE
ENVIRONMENTAL SERVICES GROUP

**NEGATIVE
REFERENCE:**

29/1013

**REPORT NO.: ESG 2060/94
FORMER RARDE
WALTHAM ABBEY
NORTH SITE
REMEDICATION PROJECT**

**SPARE
PHOTOGRAPHS**

**IF YOU REMOVE PHOTOGRAPHS FROM
THIS ENVELOPE
PLEASE FILL IN THE**

'SPARE PHOTOGRAPHS REGISTER'

ESG:29/1013

Missing

FRAME:	DATE:	AREA:	SUBJECT MATTER:
	1 FEB '93	M	REMOVAL OF CORDITE CONTAMINATED GROUND
	2 FEB '93	M	REMOVAL OF CORDITE CONTAMINATED GROUND
	3 FEB '93	M	REMOVAL OF CORDITE CONTAMINATED GROUND
	4 FEB '93	S	ONE OF THE OLDEST EXAMPLES OF HORSE CHESTNUT TREE
	5 FEB '93	S	ONE OF THE OLDEST EXAMPLES OF HORSE CHESTNUT TREE
	6 FEB '93	S	ROYAL ORDNANCE SUPERVISOR CHECKING TREE TAGS PRIOR TO FELLING
	7 FEB '93	H	TREES GROWING OUT OF BUILDING H72
	8 FEB '93	N	VIEW OF SUSPECT PIT AT NEW HILL -LOOKING SOUTH
	9 FEB '93	N	VIEW LOOKING NORTH AT NEW HILL ALONG LINE OF SUSPECT PITS
	10 FEB '93	N	SUSPECT PIT AT NEW HILL NEAR TO EAST ACCESS GATE
	11 FEB '93	N	SUSPECT PIT AT NEWHILL NEAR TO EAST ACCESS GATE
	12 FEB '93	N	SUSPECT PIT AT NEW HILL NEAR TO EAST ACCESS GATE
	13 FEB '93	N	SUSPECT PIT AT NEW HILL NEAR TO EAST ACCESS GATE
	14 FEB '93	S	BAGGED ASBESTOS A W AITING COLLECTION FROM WASTE TIPS
	15 FEB '93	S	VIEW OF WASTE TIP, DENSE ASBESTOS CONTAMINANTS REMOVED BY SPECIALIST CONTRACTORS
	16 FEB '93	M	VIEW OF CANAL 'OPENED UP' IN THE CORDITE CONTAMINATED AREA (BUILDING L159 IN THE BACKGROUND) (BAGGED ASBESTOS)
	17 FEB '93	M	VIEW OF CANAL 'OPENED UP' IN THE CORDITE CONTAMINATED AREA
	18 FEB '93	M	VIEW OF CANAL 'OPENED UP' IN THE CORDITE CONTAMINATED AREA
	19 FEB '93	M	VIEW OF CANAL 'OPENED UP' IN THE CORDITE CONTAMINATED AREA
	20 FEB '93	M	ASBESTOS BEING REMOVED FROM FILLED CANAL IN CORDITE CONTAMINATED AREA (ASBESTOS CONTAMINANTS)
	21 FEB '93	M	LICENSED ASBESTOS CONTRACTOR BAGGING ASBESTOS IN CORDITE CONTAMINATED AREA BUILDING A214 TOWER IN BACKGROU
	22 FEB '93	H	SERVICE TRENCH BETWEEN BUILDING A203 AND BRIDGE No.17
	23 FEB '93	H	SERVICE TRENCH BETWEEN BUILDING A203 AND BRIDGE No.17
	24 FEB '93	H	SERVICE TRENCH BETWEEN BUILDING A203 AND BRIDGE No. 17
	25 FEB '93	H	WEST SIDE OF BUILDING LOOKING NORTH (HOPPIT POOL TO THE LEFT)
	26 FEB '93	H	SERVICE TRENCH TO BUILDING A200 FROM BUILDING A201/2
	27 FEB '93	H	SERVICE TRENCH TO BUILDING A200
	28 FEB '93	H	SERVICE TRENCH TO BUILDING A200
	29 FEB '93	H	SERVICE TRENCH UNDER ROAD NORTH OF BUILDING A203
	30 FEB '93	H	SERVICE TRENCH NORTH OF BUILDING A203 (ENTRY TO A203 PLANT ROOM)
	31 FEB '93	H	TRENCH NORTH OF BUILDING A203
	32 FEB '93	H	SERVICE TRENCH BETWEEN BUILDING A203 AND BRIDGE No. 17
	33 FEB '93	H	STOCKPILING CLEAN CONCRETE WASTE EAST OF H8
	34 FEB '93	H	VIEW OF FELLED TREES -LOOKING EAST FROM H8
	35 FEB '93	H	STOCKPILING OF CONCRETE WASTE EAST OF H8
	36 FEB '93	H	STOCKPILING OF CONCRETE WASTE EAST OF H8
	37 FEB '93	M	WASTE MATERIAL LAID OUT ON L169 PRIOR TO SAMPLING



BRITISH AEROSPACE
DEFENCE
ROYAL ORDNANCE
ENVIRONMENTAL SERVICES GROUP

**NEGATIVE
REFERENCE:**

30/1014

**REPORT NO.: ESG 2060/94
FORMER RARDE
WALTHAM ABBEY
NORTH SITE
REMEDICATION PROJECT**

**SPARE
PHOTOGRAPHS**

**IF YOU REMOVE PHOTOGRAPHS FROM
THIS ENVELOPE
PLEASE FILL IN THE**

'SPARE PHOTOGRAPHS REGISTER'

ESG:30/1014

Missing

FRAME:	DATE:	AREA:	SUBJECT MATTER:
	1 FEB '93	H	SOUTH EAST VIEW OF STOCKPILING 'SPECIAL WASTE' ON H19 AREA
	2 FEB '93	H	NORTH VIEW OF STOCKPILED 'SPECIAL WASTE' ON H19 AREA
	3 FEB '93	H	NEW WATER VALVE INSTALLATION NORTH OF BUILDING A203
	4 FEB '93	H	NEW WATER VALVE INSTALLATION NORTH OF BUILDING A203
	5 FEB '93	M	GENERAL VIEW OF SOIL REMOVAL IN CORDITE CONTAMINATED AREA
	6 FEB '93	M	GENERAL VIEW OF SOIL REMOVAL IN CORDITE CONTAMINATED AREA
	7 FEB '93	M	REMOVAL OF CORDITE CONTAMINATED SOIL (CORDITE STICKS)
	8 FEB '93	M	REMOVAL OF CORDITE CONTAMINATED SOIL (CORDITE STICKS)
	9 FEB '93	M	REMOVAL OF CORDITE CONTAMINATED GROUND
	10 FEB '93	M	REMOVAL OF CORDITE CONTAMINATED GROUND (CORDITE STICKS)
	11 FEB '93	M	REMOVAL OF CORDITE CONTAMINATED GROUND
	12 FEB '93	P	TRACKING SERVICES WITH 'CAT SOUTH OF BUILDING A231
	13 FEB '93	M	INTERNAL VIEW OF BUILDING L153 (CEILING REMOVED - 1ST STAGE DECONTAMINATION)
	14		void
	15 FEB '93	M	INTERNAL VIEW OF BUILDING L153 (CORE HOLES IN WALL)
	16 FEB '93	M	INTERNAL VIEW OF BUILDING L153 - 1ST STAGE DECONTAMINATION
	17 FEB '93	M	INTERNAL VIEW OF BUILDING L153 - STRIPPING OUT (VACUUMING TIMBER PARTITIONS)
	18 FEB '93	M	INTERNAL VIEW OF BUILDING L153 - STRIPPING OUT (VACUUMING TIMBER PARTITIONS)
	19 FEB '93	M	BUILDINGL153 - CARTING AWAY WASTE
	20 FEB '93	M	BUILDINGL153 - STRIPPING OUT (CONTAMINATED TIMBER STORE)
	21 FEB '93	M	BUILDINGL153 - STRIPPING OUT (CONTAMINATED TIMBER STORE)
	22 FEB '93	M	BUILDINGL153 - STRIPPING OUT (CONTAMINATED TIMBER STORE)
	23 FEB '93	H	BLANKED OFF HYDRANT NEAR HIGHBRIDGE STREET (WEST)
	24 FEB '93	H	BLANKED OFF HYDRANT NEAR HIGHBRIDGE STREET (NORTH EAST)
	25 FEB '93	H	BLANKING OFF A HYDRANT NEAR HIGHBRIDGE STREET (NORTH EAST)
	26 FEB '93	M	EXCAVATION OF CORDITE CONTAMINATED GROUND - SCREENING PLANT BEYOND
	27 FEB '93	M	OPENING UP OF FILLED CANAL BRANCH IN CORDITE CONTAMINATED AREA
	28 FEB '93	M	REMOVAL OF CORDITE CONTAMINATED GROUND
	29 FEB '93	M	REMOVAL OF CORDITE CONTAMINATED GROUND
	30 FEB '93	M	REMOVAL OF CORDITE CONTAMINATED GROUND
	31 FEB '93	M	OPENING UP OF FILLED CANAL IN CORDITE CONTAMINATED AREA
	32 FEB '93	M	OPENING UP OF FILLED CANAL IN CORDITE CONTAMINATED AREA
	33 FEB '93	M	OPENING UP OF FILLED CANAL IN CORDITE CONTAMINATED AREA
	34 FEB '93	M	OPENING UP OF FILLED CANAL IN CORDITE CONTAMINATED AREA (TIMBER PILES DELINEATED CANAL EDGES)
	35 FEB '93	M	OPENING UP OF FILLED CANAL IN CORDITE CONTAMINATED AREA (BUILDING L159 - CENTRE)
	36 FEB '93	M	OPENING UP OF FILLED CANAL IN CORDITE CONTAMINATED AREA



BRITISH AEROSPACE
DEFENCE
ROYAL ORDNANCE
ENVIRONMENTAL SERVICES GROUP

**NEGATIVE
REFERENCE:**

31/1373

**REPORT NO.: ESG 2060/94
FORMER RARDE
WALTHAM ABBEY
NORTH SITE
REMEDICATION PROJECT**

**SPARE
PHOTOGRAPHS**

**IF YOU REMOVE PHOTOGRAPHS FROM
THIS ENVELOPE
PLEASE FILL IN THE**

'SPARE PHOTOGRAPHS REGISTER'

ESG:31/1373

Missing

FRAME:	DATE:	AREA:	SUBJECT MATTER:
	1 MAR '93	M	OPENING UP OF FILLED CANAL IN CORDITE CONTAMINATED AREA
	2 MAR '93	M	OPENING UP OF FILLED CANAL IN CORDITE CONTAMINATED AREA
	3 MAR '93	M	OPENING UPOF FILLED CANAL IN CORDITE CONTAMINATED AREA
	4 MAR '93	M	OPENING UP OF FILLED CANAL IN CORDITE CONTAMINATED AREA
	5 MAR '93	M	OPENING UP OF FILLED CANAL IN CORDITE CONTAMINATED AREA
	6 MAR '93	M	OPENING UP OF FILLED CANAL IN CORDITE CONTAMINATED AREA
	7 MAR '93	M	OPENING UP OF FILLED CANAL IN CORDITE CONTAMINATED AREA
	8 MAR '93	M	OPENING UP OF FILLED CANAL IN CORDITE CONTAMINATED AREA
	9 MAR '93	M	OPENING UP OF FILLED CANAL IN CORDITE CONTAMINATED AREA
	10 MAR '93	H	SERVICE TRENCH ADJACENT TO BUILDING H26
	11 MAR '93	H	SERVICE TRENCH NORTH OF HIGHBRIDGE STREET GATE
	12 MAR '93	P	INTERNAL VIEW OF BUILDING A210 (CORDITE CONTAMINATED MATERIAL STOCKPILED FOR DRYING OUT)
	13 MAR '93	M	INTERNAL VIEW OF BUILDING L168
	14 MAR '93	M	INTERNAL VIEW OF BUILDING L168
	15 MAR '93	M	REMOVAL OF CORDITE CONTAMINATED GROUND
	16 MAR '93	M	REMOVAL OF CORDITE CONTAMINATED GROUND
	17 MAR '93	H	REMOVAL OF CORDITE CONTAMINATED GROUND
	18 MAR '93	H	EXCAVATED FOUND IN USE AS A FOUNDATION
	19 MAR '93	H	EXCAVATION OF SERVICES ADJACENT TO BUILDING H26 (MILLSTONE FOUND IN USE AS A FOUNDATION)
	20 MAR '93	H	EXCAVATION FOR SERVICES SOUTH OF BUILDING H26
	21 MAR '93	H	EXCAVATION FORSERVICESSOUTHOF BUILDING H26
	22 MAR '93	H	EXCAVATION FOR SERVICES SOUTH OF BUILDING H26
	23 MAR '93	H	EXPOSED TIE ROD FOR MILLHEAD STREAM CONCRETE PILED REVETMENT
	24 MAR '93	M	INTERNAL VIEW OF BUILDING L157 (HOLES THROUGH FLOOR HAVE BEEN SEALED TO PREVENT ESCAPE OF ASBESTOS FIBRES)
	25 MAR '93	M	INTERNAL VIEW OF BUILDING L157 -ASBESTOS REMOVAL
	26 MAR '93	M	INTERNAL VIEW OF BUILDING L157 -ASBESTOS REMOVAL
	27 MAR '93	M	INTERNAL VIEW OF BUILDING L157 -INITIAL STRIP OUT
	28 MAR '93	M	INTERNAL VIEW OF BUILDING L157 -ASBESTOS REMOVAL
	29 MAR '93	M	INTERNAL VIEW OF BUILDING L157 (REMOVAL OF ASPHALT FROM CORRIDOR FLOOR)
	30 MAR '93	M	INTERNAL VIEW OF BUILDING L157
	31 MAR '93	M	INTERNAL VIEW OF BUILDING L157
	32 MAR '93	M	INTERNAL VIEW OF BUILDING L157
	33 MAR '93	H	SERVICES TRENCH FROM BLDG A203-A200 (NEW SERVICES BEING INSTALLED)
	34 MAR '93	H	SERVICES TRENCH TO BUILDING A200
	35 MAR '93	H	SERVICES TRENCH TO BUILDING A200
	36 MAR '93	H	STOCKPILING OF 'SPECIAL WASTE' ON H19 AREA
	37 MAR '93	H	EXCAVATION FOR SERVICES EAST OF BUILDING H26



BRITISH AEROSPACE
DEFENCE
ROYAL ORDNANCE
ENVIRONMENTAL SERVICES GROUP

NEGATIVE
REFERENCE:

32/1374

REPORT NO.: ESG 2060/94
FORMER RARDE
WALTHAM ABBEY
NORTH SITE
REMEDICATION PROJECT

**SPARE
PHOTOGRAPHS**

IF YOU REMOVE PHOTOGRAPHS FROM
THIS ENVELOPE
PLEASE FILL IN THE

'SPARE PHOTOGRAPHS REGISTER'

ESG:32/1374

Missing

FRAME:	DATE:	AREA:	SUBJECT MATTER:
	1		void
	2 MAR '93	H	SERVICE TRENCH EAST OF BUILDING H26
	3 MAR '93	H	SERVICE TRENCH EXCAVATION
	4 MAR '93	H	SPECIAL WASTE' STOCKPILED WEST OF BUILDING H23
	5 MAR '93	H	SPECIAL WASTE' STOCKPILED ON H19 AREA
	6 MAR '93	M	BUILDING L148 - TIDYING UP EXTERNALLY
	7 MAR '93	M	BUILDING L153 - TIDYING UP EXTERNALLY
	8 MAR '93	M	INTERNAL VIEW OF BUILDING L148 (BAGGING ASPHALT FROM CORRIDOR FLOOR)
	9 MAR '93	M	INTERNAL VIEW OF BUILDING L148 (REMOVAL OF ASPHALT FROM CORRIDOR FLOOR)
	10 MAR '93	M	INTERNAL VIEW OF BUILDING L148 (BAGGING ASPHALT FROM CORRIDOR FLOOR)
	11 MAR '93	M	INTERNAL VIEW OF BUILDING L148 (VACUUMING ROOF)
	12 MAR '93	M	INTERNAL VIEW OF BUILDING L148 (VACUUMING ROOF & WALLS - TYPE 'H' VACUUM IN USE)
	13 MAR '93	M	INTERNAL VIEW OF BUILDING L148 (GENERAL VIEW OF VACUUMING - TYPE 'H' VACUUM IN USE)



BRITISH AEROSPACE
DEFENCE
ROYAL ORDNANCE
ENVIRONMENTAL SERVICES GROUP

NEGATIVE
REFERENCE:

33/1575

REPORT NO.: ESG 2060/94
FORMER RARDE
WALTHAM ABBEY
NORTH SITE
REMEDIAION PROJECT

SPARE
PHOTOGRAPHS

IF YOU REMOVE PHOTOGRAPHS FROM
THIS ENVELOPE
PLEASE FILL IN THE
'SPARE PHOTOGRAPHS REGISTER'

ESG:33/1575

Missing

FRAME:	DATE:	AREA:	SUBJECT MATTER:
	1 MAR '93	S	BAGGED ASBESTOS STOCKPILED AWAITING MOVE TO HOLDING/SAMPLING AREA
	2 MAR '93	S	BAGGED ASBESTOS STOCKPILED AWAITING MOVE TO HOLDING/SAMPLING AREA
	3 MAR '93	S	ASBESTOS REMOVAL IN PROGRESS FORM WASTE DUMP
	4 MAR '93	B	FILLED CANAL -EXCAVATION OF WASTE (BURNING GROUND NORTH)
	5 MAR '93	S	FILLED CANAL -EXCAVATION OF WASTE (BURNING GROUND NORTH)
	6 MAR '93	B	VARIOUS PRESSURE CYLINDERS FOUND IN WASTE FROM CANAL EXCAVATION (BURNING GROUND NORTH)
	7 MAR '93	B	EXCAVATION OF FILLED CANAL (BURNING GROUND NORTH)
	8 MAR '93	B	TRACKED DUMPER TRANSPORTING WASTE MATERIAL
	9 MAR '93	B	PRESSURE CYLINDER FOUND IN CANAL WASTE
	10 MAR '93	B	3600 MACHINE CLEARING FILLED CANAL (BRIDGE No.16 IN BACKGROUND)
	11 MAR '93	B	WASTE DUMP EAST OF BURNING GROUND (REF.: 11038)
	12 MAR '93	B	TREE CLEARANCE OVER WASTE TIP (BRIDGE No. 10 IN BACKGROUND)
	13 MAR '93	M	CORDITE RECOVERED FROM AREA 'M'
	14 MAR '93	M	CORDITE RECOVERED FROM AREA 'M'
	15 MAR '93	M	CORDITE RECOVERED FROM AREA 'M'
	16 MAR '93	M	CORDITE RECOVERED FROM AREA 'M'
	17 MAR '93	M	CORDITE RECOVERED FROM AREA 'M'
	18 MAR '93	H	SERVICE TRENCH WEST BANK OF MILLHEAD STREAM (INSTALLATION OF ISLAND SITE SERVICES)
	19 MAR '93	H	SERVICE TRENCH WEST BANK OF MILLHEAD STREAM
	20 MAR '93	H	SERVICE TRENCH WEST BANK OF MILLHEAD STREAM
	21 MAR '93	H	SERVICE TRENCH WEST BANK OF MILLHEAD STREAM
	22 MAR '93	H	SERVICE TRENCH WEST BANK OF MILLHEAD STREAM
	23 MAR '93	H	NEW SERVICES TRENCH -EXISTING TIMBER BOARDING
	24 MAR '93	H	SERVICE TRENCH WEST BANK OF MILLHEAD STREAM
	25 MAR '93	H	TRIAL PIT AT CORNER OF BUILDING A200
	26 MAR '93	H	TRIAL PIT AT CORNER OF BUILDING A200
	27 MAR '93	H	TRIAL PIT AT CORNER OF BUILDING A200
	28 MAR '93	H	TRIAL PIT AT CORNER OF BUILDING A200
	29 MAR '93	H	TRIAL PIT AT CORNER OF BUILDING A200
	30 MAR '93	H	TRIAL PIT AT CORNER OF BUILDING A200
	31 MAR '93	H	EXCAVATION OF TRIAL PIT AT BUILDING A200
	32 MAR '93	H	TRIAL PIT AT CORNER OF BUILDING A200
	33 MAR '93	H	BUILDING A203 -DUCT IN SERVICE TRENCH
	34 MAR '93	H	BUILDING A203 -DUCT IN SERVICE TRENCH
	35 MAR '93	H	BUILDING A202 -TELEPHONE DRAW PIT WEST SIDE OF BUILDING
	36 MAR '93	H	SERVICE TRENCH ON WEST SIDE OF BUILDINGS A202 AND A203
	37 MAR '93	H	SERVICE TRENCH AT BRIDGE No.17



BRITISH AEROSPACE
DEFENCE
ROYAL ORDNANCE
ENVIRONMENTAL SERVICES GROUP

**NEGATIVE
REFERENCE:**

34/2032

**REPORT NO.: ESG 2060/94
FORMER RARDE
WALTHAM ABBEY
NORTH SITE
REMEDIAATION PROJECT**

**SPARE
PHOTOGRAPHS**

**IF YOU REMOVE PHOTOGRAPHS FROM
THIS ENVELOPE
PLEASE FILL IN THE**

'SPARE PHOTOGRAPHS REGISTER'

1924

ESG:34/2032

Missing

FRAME:	DATE:	AREA:	SUBJECT MATTER:
1	10/03/1993	H	VIEW ACROSS MILLHEAD STREAM SHOWING SERVICE TRENCH ON WEST BANK (LOOKING SOUTH WEST)
2	10/03/1993	S	EXCAVATION OF WASTE TIP REF.:11034 LOOKING SOUTH
3	10/03/1993	H	VIEW OF ROOF OF BUILDING A201 / 2 (DILAPIDATION OF ROOF)
4	10/03/1993	H	BUILDING A201 AND A202 - FLAT ROOF LOOKING WEST (POOR CONDITION)
5	10/03/1993	H	BUILDING A201 AND A202 - FLAT ROOF LOOKING EAST (POOR CONDITION)
6	10/03/1993	H	VIEW FROM A201 FLAT ROOF TOWARDS AREA 'H'
7	10/03/1993	H	BUILDING A201 - VALLEY GUTTER SHOWING DAMAGED SLATES (WEST)
8	10/03/1993	H	BUILDING A201 - VALLEY GUTTER SHOWING DAMAGED SLATES (EAST)
9	10/03/1993	H	BUILDING A201 - VALLEY GUTTER SHOWING DAMAGED SLATES (EAST)
10	10/03/1993	H	BUILDING A201 - VALLEY GUTTER SHOWING DAMAGED HIP SLATES
11	10/03/1993	H	BUILDING A201 - SHOWING DAMAGED HIP SLATES
12	10/03/1993	H	BUILDING A201 - ROOF SHOWING PATCH TO HIP END (POOR CONDITION)



BRITISH AEROSPACE
DEFENCE
ROYAL ORDNANCE
ENVIRONMENTAL SERVICES GROUP

**NEGATIVE
REFERENCE:**

35/2033

**REPORT NO.: ESG 2060/94
FORMER FARDE
WALTHAM ABBEY
NORTH SITE
REMEDIAION PROJECT**

**SPARE
PHOTOGRAPHS**

**IF YOU REMOVE PHOTOGRAPHS FROM
THIS ENVELOPE
PLEASE FILL IN THE**

'SPARE PHOTOGRAPHS REGISTER'

FRAME:	DATE:	AREA:	SUBJECT MATTER:
1	11/03/1993	H	'SPECIAL WASTE' STOCKPILE AT H19 AREA
2	11/03/1993	H	'SPECIALWASTE' STOCKPILE AT H19 AREA (LOADING OFF SITE TRANSPORT)
3	11/03/1993	H	SPECIAL WASTE' STOCKPILE AT H19 AREA (LOADING OFF SITE TRANSPORT)
4	11/03/1993	H	AIR MONITOR AT H19 'SPECIAL WASTE' STOCKPILE
5	11/03/1993	H	AIR MONITOR AT H19 'SPECIAL WASTE' STOCKPILE
6	11/03/1993	H	AIR MONITOR AT H19 'SPECIAL WASTE' STOCKPILE
7	11/03/1993	H	AIR MONITOR AT H19 'SPECIAL WASTE' STOCKPILE
8	11/03/1993	H	AIR MONITORING AT H24 LOCATION NEAR 'SPECIAL WASTE' STOCKPILE
9	11/03/1993	H	AIR MONITORING AT H24 LOCATION NEAR 'SPECIAL WASTE' STOCKPILE
10	11/03/1993	H	AIR MONITORING AT H19
11	11/03/1993	H	SPECIAL WASTE' REMOVAL -LORRY CLEANING (PRESSURE WASHER)
12	11/03/1993	H	SPECIAL WASTE' REMOVAL -LORRY CLEANING (PRESSURE WASHER)
13	11/03/1993	H	VIEW OF H16 WASTE SAMPLING AREA (DAMPENING DOWN WASTE TO CONTROL DUST)
14	12/03/1993	B	BURIED STRUCTURE EAST OF BURNING GROUND
15	12/03/1993	B	BURIED STRUCTURE EAST OF BURNING GROUND
16	12/03/1993	B	BURIED STRUCTURE EAST OF BURNING GROUND
17	12/03/1993	B	ASBESTOS DUMP EAST OF BURNING GROUND TIP REF.: 11038
18	12/03/1993	B	ASBESTOS DUMP EAST OF BURNING GROUND TIP REF.: 11038
19	12/03/1993	B	ASBESTOS DUMP EAST OF BURNING GROUND TIP REF.: 11038
20	12/03/1993	B	ASBESTOS DUMP EAST OF BURNING GROUND TIP REF.: 11038
21	12/03/1993	B	ASBESTOS DUMP EAST OF BURNING GROUND TIP REF.: 11038
22	12/03/1993	B	WASTE TIP REF.: 11038 -NORTH BURNING GROUND -REMOVAL
23	12/03/1993	B	WASTE TIP REF.:11038 -NORTH BURNING GROUND -AFTER REMOVAL
24	12/03/1993	B	WASTE TIP REF.:11038 -NORTH BURNING GROUND (WHITE DEPOSITS IN GRAVEL'S)
25	12/03/1993	B	WASTE TIP REF.: 11038 -NORTH BURNING GROUND
26	12/03/1993	B	WASTE TIP REF.:11038 -NORTH BURNING GROUND
27	12/03/1993	B	ASBESTOS DUMP SOUTH EAST OF BURNING GROUND
28	12/03/1993	P	WASTE FROM AROUND THE SITE BEING SORTED OUT TO RETRIEVE SCRAP METALS
29	12/03/1993	H	MOBILE SITELABORATORY -AIR MONITORING
30	12/03/1993	H	MOBILE SITE LABORATORY -AIR MONITORING
31	12/03/1993	H	MOBILE SITELABORATORY-AIR MONITORING
32	12/03/1993	H	TRIAL PIT AT H19 -LOOKING N/E TO DETERMINE DEPTH OF FILLED GROUND
33	12/03/1993	H	TRIAL PIT AT H19 -CLOSE UP OF FILLED IN LEVELS
34	12/03/1993	H	TRIAL PIT AT H19-LOOKING NIE TO DETERMINE DEPTH OF FILLED GROUND
35	12/03/1993	P	BUILDING A238 -REFURBISHMENT OF ROOF



BRITISH AEROSPACE
DEFENCE
ROYAL ORDNANCE
ENVIRONMENTAL SERVICES GROUP

**NEGATIVE
REFERENCE:**

36/2034

**REPORT NO.: ESG 2060/94
FORMER RARDE
WALTHAM ABBEY
NORTH SITE
REMEDIAATION PROJECT**

**SPARE
PHOTOGRAPHS**

**IF YOU REMOVE PHOTOGRAPHS FROM
THIS ENVELOPE
PLEASE FILL IN THE**

'SPARE PHOTOGRAPHS REGISTER'

ESG:36/2034

Missing

FRAME:	DATE:	AREA:	SUBJECT MATTER:
1	08/03/1993	H	'SPECIAL WASTE' LORRIES LEAVING HIGHBRIDGE STREET
2	08/03/1993	H	'SPECIAL WASTE' LORRIES LEAVING HIGHBRIDGE STREET
3	08/03/1993	H	LOADING 'SPECIAL WASTE' LORRIES ON H19 AREA
4	08/03/1993	H	LOADING 'SPECIAL WASTE' LORRIES ON H19 AREA
5	09/03/1993	H	SERVICE TRENCH WEST BANK MILLHEAD STREAM
6	09/03/1993	H	SERVICE TRENCH SHOWING EXISTING SERVICES
7	09/03/1993	H	SERVICE TRENCH SHOWING EXISTING SERVICES
8	09/03/1993	H	SERVICE TRENCH SHOWING REVETMENT TIE RODS
9	09/03/1993	H	SERVICE TRENCH SHOWING EXISTING SERVICES
10	09/03/1993	H	SERVICE TRENCH SHOWING EXISTING SERVICES
11	09/03/1993	H	SERVICE TRENCH (WATER ONLY) SOUTH OF H10
12	09/03/1993	H	SERVICE TRENCH (ELECTRICITY ONLY) EAST OF H10
13	09/03/1993	H	SERVICE TRENCH (WATER ONLY) SOUTH OF H6 AND H5
14	09/03/1993	H	SERVICE TRENCH (WATER ONLY) SOUTH OF H10
15	09/03/1993	H	SERVICE TRENCH (ELECTRICITY ONLY) NORTH OF H10-H17
16	09/03/1993	H	SERVICE TRENCH (ELECTRICITY ONLY) NORTH OF H10-H17
17	09/03/1993	H	SERVICE TRENCH (ELECTRICITY ONLY) NORTH OF H10-H17
18	09/03/1993	H	SERVICE TRENCH (ELECTRICITY ONLY) H17 -H8
19	10/03/1993	B	EXCAVATION OF WASTE TIP REF.: 11032
20	10/03/1993	B	WASTE TIP REF.: 11032
21	10/03/1993	B	EXCAVATION OF WASTE TIP REF.:11032
22	10/03/1993	S	RCHME SURVEYING (GRAND MAGAZINE)
23	10/03/1993	S	RCHME SURVEYING (GRAND MAGAZINE)
24	10/03/1993	S	GRAND MAGAZINE
25	10/03/1993	S	GRAND MAGAZINE
26	10/03/1993	S	GRAND MAGAZINE
27	10/03/1993	S	GRAND MAGAZINE (TREE MARKED FOR FELLING)
28	10/03/1993	S	TREES ADJACENT TO GRAND MAGAZINE MARKED FOR FELLING
29	10/03/1993	S	GRAND MAGAZINE
30	10/03/1993	S	RCHME PLANE TABLE
31	10/03/1993	S	GRAND MAGAZINE
32	10/03/1993	S	RCHME PLANE TABLE
33	10/03/1993	S	RCHME SURVEYING (ASBESTOS IN FOREGROUND)
34	10/03/1993	H	SERVICE TRENCH (ELECTRICITY ONLY) H8-H17
35	10/03/1993	H	SERVICE TRENCH (ELECTRICITY ONLY) AT ENTRANCE TO BUILDING H8
36	10/03/1993	H	SERVICE TRENCH BETWEEN BUILDING A203 AND A202 (BRIDGE No. 17 ACCESS)
37	10/03/1993	H	'SPECIAL WASTE' ON H19 SAMPLING AREA



BRITISH AEROSPACE
DEFENCE
ROYAL ORDNANCE
ENVIRONMENTAL SERVICES GROUP

**NEGATIVE
REFERENCE:**

38/2756

**REPORT NO.: ESG 2060/94
FORMER RARDE
WALTHAM ABBEY
NORTH SITE
REMEDICATION PROJECT**

**SPARE
PHOTOGRAPHS**

**IF YOU REMOVE PHOTOGRAPHS FROM
THIS ENVELOPE
PLEASE FILL IN THE**

'SPARE PHOTOGRAPHS REGISTER'

ESG:38/2756

Missing

FRAME:	DATE:	AREA:	SUBJECT MATTER:
	1 MAR '93	M	BUILDING L148-DRILLING FOR TIMBER SAMPLES
	2 MAR '93	M	BUILDING L148-DRILLING FOR TIMBER SAMPLES
	3 MAR '93	M	BUILDING L148 -DRILLING FOR TIMBER SAMPLES
	4 MAR '93	M	BUILDING L148 -DRILLING FOR TIMBER SAMPLES
	5 MAR '93	M	BUILDING L148-DRILLING FOR TIMBER SAMPLES
	6 MAR '93	M	BUILDING L148 -DRILLING FOR TIMBER SAMPLES
	7 MAR '93	M	BUILDING L148 -DRILLING FOR TIMBER SAMPLES
	8 MAR '93	M	BUILDING L145 -WOOD SHAVING SAMPLES
	9 MAR '93	M	BUILDING L148 -PAINTED NOTICE ON CORRIDOR FLOOR
	10 MAR '93	M	BUILDING L148 -BAGGED ASBESTOS WASTE AWAITING DISPOSAL
	11 MAR '93	M	BUILDING L148 -CONTAMINATED METAL AWAITING TREATMENT AND DISPOSAL
	12 MAR '93	M	BUILDING L148 -BAGGEDWASTEAND OTIIER WASTEAWAITINGDISPOSAL
	13 MAR '93	M	BUILDING L148 -BAGGEDWASTE AWAITINGDISPOSAL
	14 MAR '93	M	BUILDING L148 -CONTAMINATED TIMBER AWAITING DISPOSAL
	15 MAR '93	M	BUILDING L148 -BAGGED ASBESTOS WASTE AWAITING DISPOSAL
	16 MAR '93	M	BUILDING L148-CONTAMINATED TIMBER AWAITING DISPOSAL
	17 MAR '93	M	BUILDING L148 -CONTAMINATED RUBBLE AWAITING DISPOSAL
	18 MAR '93	M	BUILDING L148 -CONTAMINATEDMETAL AWAITING TREATMENT AND DISPOSAL



BRITISH AEROSPACE
DEFENCE
ROYAL ORDNANCE
ENVIRONMENTAL SERVICES GROUP

**NEGATIVE
REFERENCE:**

41/3130

**REPORT NO.: ESG 2060/94
FORMER RARDE
WALTHAM ABBEY
NORTH SITE
REMEDIAION PROJECT**

**SPARE
PHOTOGRAPHS**

**IF YOU REMOVE PHOTOGRAPHS FROM
THIS ENVELOPE
PLEASE FILL IN THE**

'SPARE PHOTOGRAPHS REGISTER'

ESG:41/3130

Missing

FRAME:	DATE:	AREA:	SUBJECT MATTER:
1	07/04/1993	S	BAGGED ASBESTOS AND SOIL WASTE LAID OUT ON SAMPLING SLAB
2	07/04/1993	S	BAGGED ASBESTOS AND SOIL WASTE LAID OUT ON SAMPLING SLAB
3	07/04/1993	S	BAGGED ASBESTOS AND SOIL WASTE STOCKPILED WEST OF BUILDING 83B
4	07/04/1993	S	NEWTON'S POOL SLUICE VIEWED FROM WEST
5	07/04/1993	S	NEWTON'S POOL LOOKING TOWARDS BUILDING S34
6	07/04/1993	S	NEWTON'S POOL SLUICE VIEWED FROM WEST
7	07/04/1993	S	NEWTON'S POOL SLUICE VIEWED FROM WEST
8	07/04/1993	S	NEWTON'S POOL DISCHARGE INTO OLD RIVER LEA
9	07/04/1993	S	NEWTON'S POOL DISCHARGE INTO OLD RIVER LEA
10	07/04/1993	S	VIEW OF BUILDING S34 AND CAR PARK -LOOKING EAST
11	07/04/1993	S	NEWTON'S POOL LOOKING NORTH (BUILDING S34 IN BACKGROUND)
12	07/04/1993	S	NEWTON'S POOL LOOKING WEST TOWARDS OLD RIVER LEA
13	07/04/1993	S	VIEW OF BUILDING S34 AND CAR PARK - LOOKING WEST



BRITISH AEROSPACE
DEFENCE
ROYAL ORDNANCE
ENVIRONMENTAL SERVICES GROUP

**NEGATIVE
REFERENCE:**

45/4945

**REPORT NO.: ESG 2060/94
FORMER RARDE
WALTHAM ABBEY
NORTH SITE
REMEDIAION PROJECT**

**SPARE
PHOTOGRAPHS**

**IF YOU REMOVE PHOTOGRAPHS FROM
THIS ENVELOPE
PLEASE FILL IN THE**

'SPARE PHOTOGRAPHS REGISTER'

ESG:45/4945

Missing

FRAME:	DATE:	AREA:	SUBJECT MATTER:
1			void
2	MAY '93	M	RECONSTRUCTION OF RIVER WALL USING STONE FILLED GABIONS
3	MAY '93	M	RECONSTRUCTION OF RIVER WALL USING STONE FILLED GABIONS
4	MAY '93	M	RECONSTRUCTION OF RIVER WALL USING STONE FILLED GABIONS
5	MAY '93	M	RECONSTRUCTION OF RIVER WALL USING STONE FILLED GABIONS
6			void
7			void
8			void
9			void
10	MAY '93	H	WEST ELEVATION OF BUILDING A200 - WALTON HOUSE
11	MAY '93	P	BOREHOLE RIG
12	MAY '93	P	TRIAL PIT EXCAVATION IN PROGRESS PRIOR TO SAMPLING
13	MAY '93	M	BLUE ASBESTOS IN SIDE OF RIVER BANK EXCAVATION



BRITISH AEROSPACE
DEFENCE
ROYAL ORDNANCE
ENVIRONMENTAL SERVICES GROUP

**NEGATIVE
REFERENCE:**

48/5898

**REPORT NO.: ESG 2060/94
FORMER RARDE
WALTHAM ABBEY
NORTH SITE
REMEDIAATION PROJECT**

**SPARE
PHOTOGRAPHS**

**IF YOU REMOVE PHOTOGRAPHS FROM
THIS ENVELOPE
PLEASE FILL IN THE
'SPARE PHOTOGRAPHS REGISTER'**

ESG:48/5898

Missing

FRAME: DATE: AREA: SUBJECT MATTER:

FRAME:	DATE:	AREA:	SUBJECT MATTER:
1	24/05/1993	M	CANAL TRIAL PIT 4 IN CORDITE CONTAMINATED AREA
2	25/05/1993	M	EXCAVATION OF CANAL IN CORDITE CONTAMINATED AREA
3	25/05/1993	M	EXCAVATION OF CANAL IN CORDITE CONTAMINATED AREA
4	25/05/1993	M	TREE STUMP REMOVED FROM CANAL IN CORDITE CONTAMINATED AREA
5	25/05/1993	M	TREE STUMP REMOVED FROM CANAL IN CORDITE CONTAMINATED AREA
6	25/05/1993	M	TREE STUMP REMOVED FROM CANAL IN CORDITE CONTAMINATED AREA
7	25/05/1993	P	BUILDING A250 - LOOKING SOUTH WEST
8	25/05/1993	P	BUILDING A250 - LOOKING SOUTH EAST
9	25/05/1993	P	EAST ELEVATION OF BUILDING A230 - TENNIS HUT
10	25/05/1993	P	WEST ELEVATION OF BUILDING A230 - TENNIS HUT
11	25/05/1993	P	BASE SLAB OF BUILDING A213
12	25/05/1993	P	NORTH ELEVATION OF BUILDING A234
13	25/05/1993	P	NORTH ELEVATION OF BUILDING A232
14	25/05/1993	P	NORTH ELEVATION OF BUILDING A231
15	25/05/1993	P	NORTH ELEVATION OF BUILDING A231
16	25/05/1993	P	NORTH ELEVATION OF BUILDING A230
17			void
18	25/05/1993	H	SUSPECT CONTAMINATED PIPEWORK FROM BUILDING H67 - (RETURNED TO BUILDING FOR 'HEAT TREATMENT')
19			void
20	27/05/1993	H	EXCAVATION FOR NEW DRAIN NORTH OF BUILDING A200
21	27/05/1993	H	TRAP DOOR IN FLOOR OF BUILDING A201
22	27/05/1993	N	BUILDING S16 - EXCAVATION OF TRIAL TRENCH IN MOUND IN PROGRESS
23	27/05/1993	S	EXPOSED FOUNDATIONS OF BUILDING 63
24	27/05/1993	S	EXPOSED FOUNDATIONS OF BUILDING 63
25	27/05/1993	N	BUILDING S16 - VIEW OF TRIAL TRENCH IN MOUND
26	27/05/1993	N	BUILDING S16 - EXCAVATION OF TRIAL TRENCH IN PROGRESS
27	27/05/1993	N	BUILDING S16 - WASTE TIP ADJACENT EAST SIDE OF MOUND
28	27/05/1993	N	BUILDING S16 - EXCAVATION OF TRIAL TRENCH IN NORTH FACE OF MOUND IN PROGRESS
29	27/05/1993	N	BUILDING S16 - EXCAVATION OF TRIAL TRENCH IN PROGRESS ON NORTH SIDE OF MOUND
30	27/05/1993	S	REMAINS OF BUILDING 46 FOUNDATIONS
31	27/05/1993	S	REMAINS OF BUILDING 46 FOUNDATIONS
32	27/05/1993	H	DRAIN LAYING IN PROGRESS OF BUILDING A200
33	27/05/1993	P	BUILDING A222 LOOKING NORTH WEST
34	27/05/1993	P	SOUTH ELEVATION OF BUILDING A234
35	27/05/1993	P	SOUTH ELEVATION OF BUILDING A231
36	27/05/1993	P	SOUTH ELEVATION OF BUILDING A232
37	27/05/1993	P	SOUTH ELEVATION OF BUILDING A230



BRITISH AEROSPACE
DEFENCE
ROYAL ORDNANCE
ENVIRONMENTAL SERVICES GROUP

**NEGATIVE
REFERENCE:**

49/5897

**REPORT NO.: ESG 2060/94
FORMER RARDE
WALTHAM ABBEY
NORTH SITE
REMEDIAATION PROJECT**

**SPARE
PHOTOGRAPHS**

**IF YOU REMOVE PHOTOGRAPHS FROM
THIS ENVELOPE
PLEASE FILL IN THE
'SPARE PHOTOGRAPHS REGISTER'**

ESG:49/5897

Missing

FRAME:	DATE:	AREA:	SUBJECT MATTER:
1	28/05/1993	S	BUILDING S36 AT NEWTON'S POOL
2	28/05/1993	S	BUILDING S36 AT NEWTON'S POOL
3	28/05/1993	S	BUILDING S50 AT NEWTON'S POOL
4	28/05/1993	S	BUILDING S50 AT NEWTON'S POOL
5	28/05/1993	S	VIEW LOOKING TOWARDS TRAVERSE AT NEWTON'S POOL
6	28/05/1993	S	VIEW LOOKING TOWARDS MAIN ENTRANCE TO BUILDING S34
7	28/05/1993	S	VIEW LOOKING TOWARDS BUILDING S38 AT NEWTON'S POOL
8	28/05/1993	S	VIEW LOOKING TOWARDS BUILDING S38 AT NEWTON'S POOL
9	28/05/1993	S	EAST ELEVATION OF BUILDING S34
10	28/05/1993	S	BUILDING S34 LOOKING WEST AT NEWTON'S POOL
11	28/05/1993	S	BUILDING S34 LOOKING WEST FROM WALL AT NEWTON'S POOL
12	28/05/1993	H	WEST ELEVATION OF BUILDING H71
13	28/05/1993	H	BUILDING H71 IN FOREGROUND WITH BUILDING H10 BEYOND
14	28/05/1993	H	EAST ELEVATION OF BUILDING H10
15	28/05/1993	H	NORTH ELEVATION OF BUILDING H10
16	28/05/1993	H	NORTH ELEVATION OF BUILDING H10
17	28/05/1993	H	BUILDING H12 LOOKING FROM TOP OF MOUND
18	28/05/1993	H	BUILDING H12 LOOKING NORTH WEST FROM TOP OF MOUND
19	28/05/1993	H	BUILDING H12 -LOOKING WEST
20	28/05/1993	H	BUILDING H12 -LOOKING SOUTH AT MAIN ENTRANCE
21	28/05/1993	N	WASTE TIP REF.: 11050 -EAST SIDE OF BUILDING S16
22	28/05/1993	N	WASTE TIP REF.: 11050 -EAST SIDE OF BUILDING S16
23	28/05/1993	N	WASTE TIP REF.: 11050 -EAST SIDE OF BUILDING S16
24	28/05/1993	N	WASTE TIP REF.: 11050 -EAST SIDE OF BUILDING S16
25	28/05/1993	N	WASTE TIP REF.: 11050 -EAST SIDE OF BUILDING S16
26	28/05/1993	M	BUILDING L147
27	28/05/1993	M	EAST ELEVATION OF BUILDING L157 (COVERED ASBESTOS SKIP IN FOREGROUND)
28	28/05/1993	M	EAST ELEVATION OF BUILDING L145 AND BUILDING L148
29	28/05/1993	M	BUILDING L140 AMENITIES BLOCK
30	28/05/1993	M	SOUTH ELEVATION OF BUILDING L140
31	28/05/1993	M	DETERIORATION OF FLAT ROOF TO BUILDING L145
32	28/05/1993	M	DETERIORATION OF FLAT ROOF TO BUILDING L145
33	28/05/1993	M	DETERIORATION OF FLAT ROOF TO BUILDING L145
34	28/05/1993	M	DETERIORATION OF FLAT ROOF TO BUILDING L145
35	28/05/1993	M	DETERIORATION OF FLAT ROOF TO BUILDING L145
36	28/05/1993	M	NORTH ELEVATION OF BUILDING L145 EXTENSION
37	28/05/1993	M	SCREENING PLANT IN CORDITE CONTAMINATED AREA



BRITISH AEROSPACE
DEFENCE
ROYAL ORDNANCE
ENVIRONMENTAL SERVICES GROUP

**NEGATIVE
REFERENCE:**

54/9804

**REPORT NO.: ESG 2060/94
FORMER RARDE
WALTHAM ABBEY
NORTH SITE
REMEDICATION PROJECT**

**SPARE
PHOTOGRAPHS**

**IF YOU REMOVE PHOTOGRAPHS FROM
THIS ENVELOPE
PLEASE FILL IN THE**

'SPARE PHOTOGRAPHS REGISTER'

ESG:54/9804

Missing

FRAME:	DATE:	AREA:	SUBJECT MATTER:
1	02/07/1993	M	WEST END OF EXCAVATED CANAL IN CORDITE CONTAMINATED AREA
2	02/07/1993	M	EXCAVATION OF CANAL IN PROGRESS IN CORDITE CONTAMINATED AREA
3	02/07/1993	M	EXCAVATION OF CANAL IN PROGRESS IN CORDITE CONTAMINATED AREA
4			void
5	02/07/1993	S	BAGGING ASBESTOS ON EAST TIP RE.: 11 032
6	02/07/1993	S	BAGGING ASBESTOS ON EAST TIP RE.: 11 032
7	02/07/1993	S	BAGGING ASBESTOS ON EAST TIP RE.: 11 032
8	03/07/1993	H	EXCAVATION IN PROGRESS IN FOR NEW ROAD NORTH OF BUILDING A203
9	05/07/1993	M	ASBESTOS UNCOVERED IN SOIL IN CORDITE CONTAMINATED AREA
10	05/07/1993	M	ASBESTOS UNCOVERED IN SOIL IN CORDITE CONTAMINATED AREA
11	05/07/1993	M	ASBESTOS UNCOVERED IN SOIL IN CORDITE CONTAMINATED AREA
12	05/07/1993	M	ASBESTOS UNCOVERED IN SOIL IN CORDITE CONTAMINATED AREA
13	05/07/1993	M	ASBESTOS UNCOVERED IN SOIL IN CORDITE CONTAMINATED AREA
14	05/07/1993	M	COMPLETED EXCAVATION OF CANAL IN CORDITE CONTAMINATED AREA
15	05/07/1993	M	COMPLETED EXCAVATION OF CANAL IN CORDITE CONTAMINATED AREA LOOKING EAST
16	05/07/1993	M	GENERAL EXCAVATION IN CORDITE CONTAMINATED AREA
17	05/07/1993	M	EXCAVATED MATERIAL LOADED INTO VOLVO DUMP TRUCK IN CORDITE CONTAMINATED AREA
18	05/07/1993	M	EXCAVATED CANAL IN CORDITE CONTAMINATED AREA - LOOKING WEST
19	05/07/1993	M	GENERAL VIEW OF CANAL AWAITING SURVEYING IN CORDITE CONTAMINATED AREA
20	05/07/1993	M	MANOEUVRING BOAT TO TAKE LEVELS AND SAMPLES IN CANAL - CORDITE CONTAMINATED AREA
21	05/07/1993	M	SORTING OUT SAMPLE JARS PRIOR TO SAMPLING CANAL IN CORDITE CONTAMINATED AREA
22	05/07/1993	M	LOCATING BOAT PRIOR TO LEVELLING OF CANAL IN CORDITE CONTAMINATED AREA
23	05/07/1993	M	PUMP USED FOR 'DE-WATERING' OF CANAL IN CORDITE CONTAMINATED AREA
24	05/07/1993	M	PUMP USED FOR 'DE-WATERING' OF CANAL IN CORDITE CONTAMINATED AREA
25	05/07/1993	M	SURVEYING OF CANAL IN PROGRESS IN CORDITE CONTAMINATED AREA
26	05/07/1993	M	SAMPLING OF CANAL IN PROGRESS IN CORDITE CONTAMINATED AREA
27	05/07/1993	M	SAMPLING OF CANAL IN PROGRESS IN CORDITE CONTAMINATED AREA
28	06/07/1993	M	BOAT MOORED IN CANAL IN CORDITE CONTAMINATED AREA
29	06/07/1993	M	SAMPLING OF CANAL IN PROGRESS IN CORDITE CONTAMINATED AREA
30	07/07/1993	H	VIEW OF BUILDING H37 FOUNDATION SLAB



BRITISH AEROSPACE
DEFENCE
ROYAL ORDNANCE
ENVIRONMENTAL SERVICES GROUP

**NEGATIVE
REFERENCE:**

57/0095

**REPORT NO.: ESG 2060/94
FORMER RARDE
WALTHAM ABBEY
NORTH SITE
REMEDIAION PROJECT**

**SPARE
PHOTOGRAPHS**

**IF YOU REMOVE PHOTOGRAPHS FROM
THIS ENVELOPE
PLEASE FILL IN THE**

SPARE PHOTOGRAPHS REGISTER'

ESG:57/0095

Missing

FRAME:	DATE:	AREA:	SUBJECT MATTER:
1	23/07/1993	H	TORRENTIAL RAIN STORM (BUILDING A200)
2	23/07/1993	H	TORRENTIAL RAIN STORM (BUILDING A200)
3			void
4			void
5	27/07/1993	S	SOUTH ELEVATION OF BUILDING 103 (GUNPOWDER PRESS HOUSE)
6	27/07/1993	S	SOUTH ELEVATION OF BUILDING 103 (WATERWHEEL GUNPOWDER PRESS HOUSE)
7	27/07/1993	S	SOUTH ELEVATION OF BUILDING 103 (GUNPOWDER PRESS HOUSE)
8	27/07/1993	S	SOUTH ELEVATION OF BUILDING 103 (GUNPOWDER PRESS HOUSE)
9	27/07/1993	S	SOUTH ELEVATION OF BUILDING 103 (GUNPOWDER PRESS HOUSE)
10	27/07/1993	S	SOUTH EASTERN ASPECT OF BUILDING 103 (GUNPOWDER PRESS HOUSE)
11	27/07/1993	S	PART OF EAST ELEVATION OF BUILDING 103 (GUNPOWDER PRESS HOUSE)
12	27/07/1993	S	EAST ELEVATION OF BUILDING 103 (GUNPOWDER PRESS HOUSE)
13	27/07/1993	S	EAST ELEVATION OF BUILDING 103 (GUNPOWDER PRESS HOUSE)
14	27/07/1993	S	PART OF WEST ELEVATION OF BUILDING 103 (GUNPOWDER PRESS HOUSE)
15	27/07/1993	S	WEST ELEVATION OF BUILDING 103 (GUNPOWDER PRESS HOUSE)
16	27/07/1993	S	SOUTH WESTERN ASPECT OF BUILDING 103 (GUNPOWDER PRESS HOUSE)
17	27/07/1993	S	SOUTH WESTERN ASPECT OF BUILDING 103 (GUNPOWDER PRESS HOUSE)
18	27/07/1993	S	WEST ELEVATION OF BUILDING 103 (GUNPOWDER PRESS HOUSE)
19	27/07/1993	S	SOUTH WESTERN ASPECT OF BUILDING 103 (GUNPOWDER PRESS HOUSE)
20	27/07/1993	S	SOUTH WESTERN ASPECT OF BUILDING 103 (GUNPOWDER PRESS HOUSE)
21	27/07/1993	S	SOUTH ELEVATION OF BUILDING 103 (GUNPOWDER PRESS HOUSE)
22	27/07/1993	S	BUILDING 103 (WATERWHEEL OF GUNPOWDER PRESS HOUSE)
23			void
24	27/07/1993	S	BUILDING 103 (WATERWHEEL OF GUNPOWDER PRESS HOUSE)
25	27/07/1993	P	WATER MAIN REPAIR NORTH OF BUILDING A250 ('VIKING JOHNSON COUPLING')
26	27/07/1993	P	WATER MAIN REPAIR NORTH OF BUILDING A250
27	27/07/1993	P	WATER MAIN REPAIR NORTH OF BUILDING A250
28	27/07/1993	P	WATER MAIN REPAIR NORTH OF BUILDING A250
29	27/07/1993	P	WATER MAIN REPAIR NORTH OF BUILDING A250
30	27/07/1993	P	WATER MAIN REPAIR NORTH OF BUILDING A250
31	27/07/1993	P	BUILDING A238 - GATE HOUSE (SECURITY CHECK IN PROGRESS)
32	27/07/1993	P	VIEW NORTH FROM POWDERMILL LANE
33	27/07/1993	P	VIEW NORTH FROM POWDERMILL LANE
34	27/07/1993	P	VIEW WEST FROM POWDERMILL LANE
35	27/07/1993	P	VIEW NORTH FROM POWDERMILL LANE
36	27/07/1993	P	VIEW NORTH FROM POWDERMILL LANE
37	27/07/1993	P	VIEW WEST FROM POWDERMILL LANE



BRITISH AEROSPACE
DEFENCE
ROYAL ORDNANCE
ENVIRONMENTAL SERVICES GROUP

**NEGATIVE
REFERENCE:**

63/4532

**REPORT NO.: ESG 2060/94
FORMER RARDE
WALTHAM ABBEY
NORTH SITE
REMEDICATION PROJECT**

**SPARE
PHOTOGRAPHS**

**IF YOU REMOVE PHOTOGRAPHS FROM
THIS ENVELOPE
PLEASE FILL IN THE**

'SPARE PHOTOGRAPHS REGISTER'

ESG:63/4532

Missing

FRAME:	DATE:	AREA:	SUBJECT MATTER:
1	15/09/1993	T	CONTAMINATED MATERIAL BEING STOCKPILED
2	15/09/1993	T	ASBESTOS BEING BAGGED
3	15/09/1993	S	NEWTONS POOL - SCREENING PLANT
4	15/09/1993	S	NEWTONS POOL - TYPICAL SCREEN, REMOVED FOR REPAIRS
5	15/09/1993	S	NEWTONSPOOL-EXCAVATION
6	15/09/1993	S	NEWTONS POOL - VIEW FROM NORTH BUILDING S34
7	15/09/1993	S	NEWTONS POOL - VIEW NORTH OF BUILDING S34
8	15/09/1993	S	NEWTONS POOL - VIEW EAST OF BUILDING S34
9			void
10	17/09/1993	S	BARGE HOUSE FOUNDATIONS ON SIDE OF CANAL ADJACENT TO BUILDING E2
11	17/09/1993	S	BARGE HOUSE FOUNDATIONS ON SIDE OF CANAL ADJACENT TO BUILDING E2
12	17/09/1993	T	EXCAVATED CANAL ADJACENT TO BUILDING E2
13	17/09/1993	S	BARGE HOUSE TO SIDE OF EXCAVATED CANAL ADJACENT TO BUILDING E2
14	18/09/1993	S	NEWTONS POOL - SHINGLE DAM / FILTER - TO RETAIN SIEVED SLUDGE
15	18/09/1993	S	NEWTONS POOL - SCREENING PLANT FOR SIEVING SLUDGE REMOVED
16	18/09/1993	S	NEWTONS POOL - REMEDIATION
17	20/09/1993	S	NEWTONS POOL - REMEDIATION (pUMP ARRANGEMENT)
18	20/09/1993	S	NEWTONS POOL - REMEDIATION (LONG REACH EXCAVATOR IN USE)
19	20/09/1993	S	NEWTONS POOL - REMEDIATION (LONG REACH EXCAVATOR IN USE)
20	20/09/1993	S	NEWTONS POOL - REMEDIATION (LONG REACH EXCAVATOR IN USE)
21	22/09/1993	S	NEWTONS POOL - REMEDIATION (SUSPECT OBJECT REMOVED)
22	22/09/1993	S	NEWTONS POOL - REMEDIATION
23	24/09/1993	S	NEWTONS POOL - REMEDIATION
24	24/09/1993	S	NEWTONS POOL - REMEDIATION
25	24/09/1993	S	NEWTONS POOL - REMEDIATION
26	24/09/1993	S	NEWTONS POOL - REMEDIATION
27	24/09/1993	S	NEWTONS POOL - REMEDIATION
28	24/09/1993	S	NEWTONS POOL - REMEDIATION
29	24/09/1993	S	NEWTONS POOL - REMEDIATION
30	24/09/1993	S	NEWTONS POOL - REMEDIATION
31			void
32	25/09/1993	M	NEWTONS POOL - REMEDIATION - PREPARING PRE-CAST CONCRETE MANHOLE RINGS FOR USE AS 'PUMP SUMPS'
33	25/09/1993	S	NEWTONS POOL - REMEDIATION
34	25/09/1993	S	NEWTONS POOL - REMEDIATION
35	25/09/1993	S	NEWTONS POOL - REMEDIATION
36	25/09/1993	S	NEWTONS POOL - REMEDIATION (PUMP ARRANGEMENT)
37	25/09/1993	S	NEWTONS POOL - REMEDIATION



BRITISH AEROSPACE
DEFENCE
ROYAL ORDNANCE
ENVIRONMENTAL SERVICES GROUP

NEGATIVE
REFERENCE:

64/4533

REPORT NO.: ESG 2060/94
FORMER RARDE
WALTHAM ABBEY
NORTH SITE
REMEDIAION PROJECT

**SPARE
PHOTOGRAPHS**

IF YOU REMOVE PHOTOGRAPHS FROM
THIS ENVELOPE
PLEASE FILL IN THE

'SPARE PHOTOGRAPHS REGISTER'

ESG:64/4533

Missing

FRAME:	DATE:	AREA:	SUBJECT MATTER:
1	25/09/1993	S	NEWTONS POOL - REMEDIATION
2	25/09/1993	S	NEWTONS POOL - REMEDIATION
3	25/09/1993	S	NEWTONS POOL - REMEDIATION
4	25/09/1993	S	NEWTONS POOL - REMEDIATION
5	25/09/1993	M	NEWTONS POOL - REMEDIATION (CORING PRE-CAST MANHOLE RINGS TO USE AS 'PUMP SUMPS')
6	25/09/1993	S	NEWTONS POOL - REMEDIATION (RE-ARRANGING PUMP SUCTION LINES)
7	25/09/1993	S	NEWTONS POOL - REMEDIATION
8	25/09/1993	S	NEWTONS POOL - REMEDIATION
9	25/09/1993	S	NEWTONS POOL - REMEDIATION
10	26/09/1993	S	NEWTONS POOL - REMEDIATION
11	26/09/1993	S	NEWTONS POOL - REMEDIATION
12	26/09/1993	S	NEWTONS POOL - REMEDIATION
13	26/09/1993	S	NEWTONS POOL - REMEDIATION (LONG REACH EXCAVATOR IN USE)
14	26/09/1993	S	NEWTONS POOL - REMEDIATION
15	26/09/1993	S	NEWTONS POOL - REMEDIATION
16	26/09/1993	S	NEWTONS POOL - REMEDIATION (GROUND WATER INGRESS)
17			void
18			void
19			void
20			void
21	26/09/1993	S	NEWTONS POOL - REMEDIATION (GROUND WATER INGRESS)
22	26/09/1993	S	NEWTONS POOL - REMEDIATION
23	26/09/1993	S	NEWTONS POOL - REMEDIATION
24	26/09/1993	S	NEWTONS POOL - REMEDIATION (RE-ARRANGING PUMP SUCTION LINES)
25	26/09/1993	S	NEWTONS POOL - REMEDIATION (HAND CLEARANCE AT SCREENING POINT)
26	26/09/1993	S	NEWTONS POOL - REMEDIATION
27	26/09/1993	S	NEWTONS POOL - REMEDIATION
28	26/09/1993	S	NEWTONS POOL - REMEDIATION
29	26/09/1993	S	NEWTONS POOL - REMEDIATION
30	26/09/1993	S	NEWTONS POOL - REMEDIATION
31	26/09/1993	S	NEWTONS POOL - REMEDIATION
32	26/09/1993	S	NEWTONS POOL - REMEDIATION
33	26/09/1993	S	NEWTONS POOL - REMEDIATION
34	26/09/1993	S	NEWTONS POOL - REMEDIATION
35	26/09/1993	S	NEWTONS POOL - REMEDIATION
36	26/09/1993	S	NEWTONS POOL - REMEDIATION
37	26/09/1993	S	NEWTONS POOL / OLD RIVER LEA REMEDIATION



BRITISH AEROSPACE
DEFENCE
ROYAL ORDNANCE
ENVIRONMENTAL SERVICES GROUP

**NEGATIVE
REFERENCE:**

65/2767

**REPORT NO.: ESG 2060/94
FORMER RARDE
WALTHAM ABBEY
NORTH SITE
REMEDICATION PROJECT**

**SPARE
PHOTOGRAPHS**

**IF YOU REMOVE PHOTOGRAPHS FROM
THIS ENVELOPE
PLEASE FILL IN THE**

'SPARE PHOTOGRAPHS REGISTER'

ESG:65/2767

Missing

FRAME:	DATE:	AREA:	SUBJECT MATTER:
1	26/09/1993	S	NEWTONS POOL - REMEDIATION
2	26/09/1993	S	NEWTONS POOL - REMEDIATION
3	26/09/1993	S	NEWTONS POOL - REMEDIATION
4	26/09/1993	S	NEWTONS POOL - REMEDIATION
5	26/09/1993	S	NEWTONS POOL - REMEDIATION
6	26/09/1993	S	NEWTONS POOL - REMEDIATION
7	26/09/1993	S	NEWTONS POOL - REMEDIATION
8	26/09/1993	S	NEWTONS POOL - REMEDIATION
9	26/09/1993	S	NEWTONS POOL - REMEDIATION
10	26/09/1993	S	NEWTONS POOL - REMEDIATION
11	26/09/1993	S	NEWTONS POOL - REMEDIATION
12	26/09/1993	S	NEWTONS POOL - REMEDIATION
13	26/09/1993	S	NEWTONS POOL - REMEDIATION
14	26/09/1993	S	NEWTONS POOL - REMEDIATION
15	27/09/1993	S	NEWTONS POOL - REMEDIATION
16	27/09/1993	S	NEWTONS POOL - REMEDIATION (BLUE ASBESTOS FOUND)
17	28/09/1993	S	NEWTONS POOL - REMEDIATION (ORIGINAL TIMBER PILES TO SLUICE)
18	28/09/1993	S	NEWTONS POOL - REMEDIATION (ORIGINAL TIMBER PILES TO SLUICE)
19	28/09/1993	S	NEWTONS POOL - REMEDIATION
20	28/09/1993	S	NEWTONS POOL - REMEDIATION
21	28/09/1993	S	NEWTONS POOL - REMEDIATION
22	28/09/1993	S	NEWTONS POOL - REMEDIATION
23	28/09/1993	S	NEWTONS POOL - REMEDIATION
24	28/09/1993	S	NEWTONS POOL - REMEDIATION
25	28/09/1993	S	NEWTONS POOL - REMEDIATION



BRITISH AEROSPACE
DEFENCE
ROYAL ORDNANCE
ENVIRONMENTAL SERVICES GROUP

**NEGATIVE
REFERENCE:**

82/1767

**REPORT NO.: ESG 2060/94
FORMER RARDE
WALTHAM ABBEY
NORTH SITE
REMEDICATION PROJECT**

**SPARE
PHOTOGRAPHS**

**IF YOU REMOVE PHOTOGRAPHS FROM
THIS ENVELOPE
PLEASE FILL IN THE**

SPARE PHOTOGRAPHS REGISTER'

ESG:82/1767

Missing

FRAME:	DATE:	AREA:	SUBJECT MATTER:
1	16/03/1994	M	REMOVAL OF POTENTIALLY CONTAMINATED DRAINAGE AT BUILDING L157
2	16/03/1994	M	EXPOSED FOUL DRAIN, PRIOR TO DECONTAMINATION, ADJACENT BLDG L157
3	16/03/1994	M	EXPOSED FOUL DRAIN, PRIOR TO DECONTAMINATION, ADJACENT BLDG L157
4	16/03/1994	M	BREAKING OUT FWD MAN HOLE ADJACENT OT BUILDING L157
5	16/03/1994	M	FWD EXPOSED MAN HOLE ADJACENT TO BUILDING L157
6	16/03/1994	H	SITE OF FORMER BUILDING H25, REMOVAL OF HYDROCARBON CONTAMINATED GROUND, VIEWED FROM THE NORTH
7	16/03/1994	H	SITE OF FORMER BUILDING H25, REMOVAL OF HYDROCARBON CONTAMINATED GROUND, VIEWED FROM THE NORTH
8	16/03/1994	H	EXCAVATION OF EASTIWEST FILLED CANAL SOUTH OF BUILDING H25 AND H26
9	16/03/1994	H	EXCAVATION OF EASTIWEST FILLED CANAL SOUTH OF BUILDING H25 AND H26
10	16/03/1994	H	EXCAVATION OF EASTIWEST FILLED CANAL SOUTH OF BUILDING H25 AND H26
11	16/03/1994	H	H19 AREA DIFFICULTY GROUND CONDITONS
12	16/03/1994	H	EXPOSING FOUNDATIONS TO BUILDING H31 (SEWER PUMPING STATION)
13	16/03/1994	H	EXPOSING FOUNDATIONS TO BUILDING H31 (SEWER PUMPING STATION)
14	16/03/1994	H	EXPOSING FOUNDATIONS TO BUILDING H31 (SEWER PUMPING STATION)
15	18/03/1994	H	ACOUSTIC WALL TO ABSORB PUMP NOISE
16	18/03/1994	H	CLEARANCE OF EAST/WEST CANAL SOUTH OF BUILDINGS H25 AND H26
17	18/03/1994	H	CLEARANCE OF EAST/WEST CANAL SOUTH OF BUILDINGS H25 AND H27
18	18/03/1994	H	HIGHBRIDGE STREET ENTRANCE -VIEW OF FIBREGLASS PETROL INTERCEPTOR UNIT
19	18/03/1994	H	CLEARANCE OF EAST/WEST CANAL SOUTH OF BUILDINGS H25 AND H26
20	18/03/1994	H	CLEARANCE OF EAST/WEST CANAL SOUTH OF BUILDINGS H25 AND H26
21	18/03/1994	H	EXCAVATION OF EAST/WEST FILLED CANAL SOUTH OF BLDGS H25 AND H26
22	18/03/1994	H	EXCAVATION OF EAST/WEST FILLED CANAL SOUTH OF BLDGS H25 AND H27
23	18/03/1994	H	EXCAVATION OF EAST/WEST FILLED CANAL SOUTH OF BLDGS H25 AND H28
24	18/03/1994	H	EXCAVATION OF EAST/WEST FILLED CANAL SOUTH OF BLDGS H25 AND H29
25	18/03/1994	H	EXCAVATION OF EAST/WEST FILLED CANAL SOUTH OF BLDGS H25 AND H30
26	18/03/1994	H	EXCAVATION OF EAST/WEST FILLED CANAL SOUTH OF BLDGS H25 AND H31
27	18/03/1994	H	EXCAVATION OF HYDROCARBON CONTAMINATED GROUND
28	18/03/1994	H	EXCAVATION OF HYDROCARBON CONTAMINATED GROUND
29	19/03/1994	H	E/W CANAL SOUTH OF BUILDINGS H25 & H26 -RE-FILLING IN PROGRESS WITH IMPORTED MATERIAL VIEWED FROM THE SOUTH
30	19/03/1994	H	EAST/WEST CANAL SOUTH OF BUILDINGS H25 AND H26
31	21/03/1994	H	EAST/WEST CANAL SOUTH OF BUILDINGS H25 AND H27
32	21/03/1994	H	EAST/WEST CANAL SOUTH OF BUILDINGS H25 AND H28
33	21/03/1994	H	EAST/WEST CANAL SOUTH OF BUILDINGS H25 AND H29
34	21/03/1994	H	EAST/WEST CANAL SOUTH OF BUILDINGS H25 AND H30
35	23/03/1994	M	BUILDING L157 -GULLEY 17 MERCURY FOUND WHILST REMOVING DRAIN
36	23/03/1994	M	BUILDING L157 -GULLEY 17 MERCURY FOUND WHILST REMOVING DRAIN
37	23/03/1994	M	BUILDING L157 -GULLEY 17 MERCURY FOUND WHILST REMOVING DRAIN



BRITISH AEROSPACE
DEFENCE
ROYAL ORDNANCE
ENVIRONMENTAL SERVICES GROUP

**NEGATIVE
REFERENCE:**

106/5253

**REPORT NO.: ESG 2060/94
FORMER RARDE
WALTHAM ABBEY
NORTH SITE
REMEDICATION PROJECT**

**SPARE
PHOTOGRAPHS**

**IF YOU REMOVE PHOTOGRAPHS FROM
THIS ENVELOPE
PLEASE FILL IN THE**

'SPARE PHOTOGRAPHS REGISTER'

ESG:106/5253

Missing

FRAME:	DATE:	AREA:	SUBJECT MATTER:
1	25/11/1994	H	H17 - PUMPING OUT STORAGE CHAMBER
2	25/11/1994	H	FOUL WATER MANHOLE REMOVED NORTH OF H17
3	25/11/1994	H	FOUL WATER MANHOLE REMOVED NORTH OF H17
4			void
5	28/11/1994	P	SOUTH SIDE OF BUILDING A210 - EXCAVATING PRIOR TO CLAY LINING
6	28/11/1994	S	BUILDING E7 - EXCAVATED BRICKWORK PAVEMENT / WALKWAY
7	28/11/1994	S	BUILDING E7 - EXCAVATED BRICKWORK PAVEMENT / WALKWAY
8	28/11/1994	S	CLEANING OUT LOCK NORTH OF BUILDING L136
9	28/11/1994	S	CLEANING OUT LOCK NORTH OF BUILDING L136
10	28/11/1994	S	FOUNDATIONS EXCAVATED BY BARGES IN CANAL EAST OF BUILDING L100
11	28/11/1994	S	FOUNDATIONS EXCAVATED BY BARGES IN CANAL EAST OF BUILDING L100
12	28/11/1994	S	1ST BARGE MOVED NORTH OF BUILDING L136
13	28/11/1994	S	BARGES WAITING TO BE MOVED IN CANAL NORTH OF BUILDING L136