


WASC 1977

Cotton Waste

Test Book

1943



COTTON WASTE

TEST BOOK

FROM CONS — 3640.
— 269.

COTTON WASTE

TEST BO

Wt 10409 3 Bks/4/42 W. STRAKER LTD.

Consign ^t No.	LABEL ON SAMPLE.	Date of Receipt in Laboratory.		General Characteristics:		Oil, per cent.	Moisture, per cent.	Soluble in 3% Na O.H.	
				Bale	Shier				
3640	60 Bales from bottom cellulose. C659.	May	17	12852-63. 3504, 12996-13007. 3513 & 3515, 13044-13079. 3517 & 3519.		.20	4.8	2.5	
269	150 Bales from M of S. Samples from the following C811 417598, 417658, 417607, 417553, 417549, 417573, 417550, 417577.	May	26	417509-58 8131 417559-608 8132 417609-658 8133		.04	5.7	2.2	
270	50 Bales from M of S. (Globe Hill) C852.	May	31	11889 11835 11831	} 711-14	.15	6.4	1.7	
3641	94 Bales from Lancil Ltd. C721	May	26	13335 2689 13287 2687 13292 2687 13325 2689 13297 2689		.27	6.0	1.9	
3642	100 Bales from Lancil Ltd C753	May	27	13613 2700 13592 2699 13614 2730 13545 2696 13443 2693		.24	5.8	1.8	
271	50 Bales from M of S. (Rockdale) C937	May	30	12133 727 12138 728 12135 730		.13	6.97	1.46	
272	144 Bales from M of S (Mount Sion) C940.	June.	1	419967 419976 8176 419897 419969 8180 418852 419885 8181. 419866		.22	6.06	2.13	
273	50 Bales from M of S. (Rockdale). C941	June	1	422080 714 422086 422088 715 422087 716 422099 422021 717.		.13	6.7	2.6	
274	144 Bales from M of S. (Mt. Sion) C1013 Dispatched to R.O.F. Warrham 9.9.43	June	8	11880 8224 11918 8225 11906 8227.		.33	5.2	2.7	

COTTON WASTE

TEST BO

Wt 10409 3 Bks/4/42 W. STRAKER LTD.

Consign ^t No.	LABEL ON SAMPLE.	Date of Receipt in Laboratory.	General Characteristics.		Oil. per cent.	Moisture, per cent.	Soluble in 3% Na O.H.	
			Bale	Sliver				
3643	100 Bales from Lancil Ltd. 7/6. C1012	June 10	2683	13179	1.09	6.7	2.4	
			2682 }	13166				
			2680	13155				
			2683	13188				
3644					14	5.4	1.8	
Sl. 1202	50 Bales from Mrs Lancil Ltd	JUNE 14	Bales 2704, 2706, 2708 & 2709					
245	50 Bales from Mr Supply, Glouches	" 14	Batch 1067, 1068 & 1069		14	6.0	2.3	
Sl 1195	Reckdale							
246	144 Bales from Mr Supply Mount Zion	" 20	Bales 8266, 8267 & 8268		33	6.1	2.6	
Sl 1251								
244	50 Bales from Mr Supply Glouches	" 28	Batch 434 & 438		32	6.1	2.0	
Sl 1361	Reckdale							
248	144 Bales from Mr Supply Mount Zion	" 28	Batch 8353 & 8357		10	6.8	2.6	
Sl 1362	Disputed to R.O.F. Wrexham 13.9.13.							
249	50 Bales from Mr Supply Glouches	" 28	Batch 1060-1062		10	6.4	2.1	
Sl 1393	Reckdale							
3645	90 Bales from Mess Lancil Ltd	" 22	Batch 2709-2714		28	6.0	1.9	
Sl 1254			Bales 13870, 13811, 13803, 13838, 13879					
3646	45 Bales from Mess Lancil Ltd	" 28	Batch 2716-2719		25	5.9	1.6	
Sl 1257			Bales 13943, 13959, 13950, 13932					
3647	60 Bales from Mess Lancil Ltd	" 29	Batch 2721-2724		23	6.4	2.7	
Sl 1400			Bales 14041, 14043, 14017					

COTTON WASTE

TEST BO

Wt 10409 3 Bks/4/42 W. STRAKER LTD.

Consign- No.	LABEL ON SAMPLE.	Date of Receipt in Laboratory.	General Characteristics.	Oil. per cent.	Moisture, per cent.	Soluble in 3% Na O.H.
280	50 Bales from M. of S. (Globe Mill) C1596	July 24	Bakt Bale 1157-1160 3618- 3667	16	6.9	1.3
281	144 Bales from M. of S. (Mount Sion) C1636.	July 26	8311 426231-78 8312 278-326 8313 327-374	40	6.5	3.0
282	50 Bales from M. of S. (Mount Globe Mill) C1729	July 26	1164/5 3718 1162/3 -3767	12	6.9	2.3
283	50 Bales from M. of S. M. of S. (Globe Mill) C1750	July 26	1056-1060 1893- 1942	07	6.3	1.6
284	50 Bales from M. of S. (Mt. Sion) C1817	July 28	8421 - 431511-53 8423 - 431607-67 8424 - 431655-702	19	6.2	2.2
285	144 Bales from M. of S. (Mt. Sion) C1818.	July 28	8389 - 429975-022 8390 - 430023-070 8392 - 430119-166	20	6.4	2.8
	Despatched to R. O. F. Warrham 13.9.43.					
3648	70 Bales (Hard) from Lonsil C1734	July 28	2724 - 14075- 2727 14144	20	6.5	1.6
3649.	81 Bales (Hard) from Lonsil. C1828	July 28	2731 - 14220- 2735 14300	11	5.2	1.1

WASTE

TEST BOOK.

Characteristics.	Oil. per cent.	Moisture, per cent.	Soluble in 3% Na O.H.	Starch %	Ash %	Dyeing.	Viscosity.	Congo Red Test.	Woven Material	General Appearance	Sentence.		
											Fit or Unfit.	Initials.	Date.
Bale 618- 3667	.16	6.9	1.3	NIL	.17	good	1.0	Satis	Trace	good	dit	SH	4/8/1943
6331-78 8-326 1-374	.40	6.5	3.0	NIL	.29	good	1.7	Satis	Trace	good	dit	SH	4/8/1943
3718 3767	.12	6.9	2.3	NIL	.28	good	1.3	Satis	Trace	good	dit	SH	4/8/43
893- 1942	.07	6.3	1.6	NIL	.24	good	1.0	Satis	Trace	good	dit	SH	4/8/43
1511-53 57-64 55-702	.19	6.2	2.2	NIL	.21	good	3.8	Satis	Trace	good	dit	SH	4/8/43
9475-022 023-090 19-166	.20	6.4	2.8	NIL	.43	good	1.3	Satis	Trace	good	dit	SH	4/8/43
14045- 14144	.20	6.5	1.6	NIL	.47	good	1.0	Satis	Trace	good	dit	SH	4/8/43
14220- 14300	.11	5.2	1.1	NIL	.56	good	1.5	Satis	Trace	good	dit	SH	4.8.43