

On Her Majesty's Service

WASC1401

Patterns of Various Articles to be brought in the Vessel from Faversham to the Tower (if not already sent) for a guide to the Contractors to make others by, the same to be Tally'd. No. For the.

Copper Watering Pots	{ Large - - - - - 1 Small - with only 2/3 ^d of the Rose Punched - - - - - 1	} Stove.
Copper Pot for Oil	1	
Small Copper Ladle	1	
Copper Hammer	1	
Signum Vita Runner for Cornung Powder	1	
Stove Barrel	1	} Cornung House
Proof Pan of Copper	1	
Punch for Parchment Skins	1	
Separating Sieves	{ N ^o 1 - - - - - 1 2 - - - - - 1 3 for taking out Dust - - - - - 1	
	Composition Sieve	1
	Wooden Scuppit	Small - - - - - 1
Mill Brush with long Handle	1	
Copper Scraper with wooden Handle	1	} Mills.
Copper Shovels for Composition	1	
Charge Tubs	{ Whole - - - - - 1 Half - - - - - 1	} Mixing House
	Charge Wheelbarrow with Painted cover	
Brass Wire for Charcoal Bunting Engine - a small Piece	1	} Charcoal & Sulphur Mill.
D: for - Sulphur Bunting Engine - a small Piece	1	
Copper	{ Plates for Proofing Powder - - - - - 1 Funnel for D: - - - - - 1 Shimble for D: - - - - - 1 Spoon - for D: - - - - - 1	} Proof House.