

WASC-1829

GAS MASK

LF

Packing of Respirator.

The Respirator should be placed in box with heavy end (container) standing on bottom of box. The Transparent Eyepiece should lie evenly on the top of the container and at full length without any deformation.

When Respirator is required for use.

1. Hold Respirator by the straps.
2. Put on by first putting chin into the Facepiece and then draw the straps over the head. Adjust straps to obtain close but comfortable fit.
3. Take off by pulling the straps over the head from the back.

DO NOT TAKE RESPIRATOR OFF BY PULLING THE CONTAINER UPWARDS OVER THE FACE.

P. E. P.



WASC 1829

TOP