

C.E. SECTION.

Recommendations for the Prevention of Dermatitis.

1. Ointment is supplied by the Factory. It will be rubbed well into the skin before starting work, and again at the end of the shift after bathing.
Always wash both face and hands to get rid of C.E. before rubbing on ointment.
2. The tips of the collar of the Danger Building Jacket will be sewn down and a soft collar stitched over it so as to prevent chafing at the neck.
The soft collar will be removed and washed frequently.
3. Do not scratch the face and neck, either during or out of working hours.
If the skin feels dry and inflamed after leaving work, relief will generally be afforded by the application of a little Lanoline mixed with a little castor oil.
4. If a man thinks he has developed dermatitis, he will report through his Chargeman to the Assistant Foreman. The latter will, if he considers it necessary, send the man to the hospital.

P.G. Knapman,

Waltham Abbey.

Superintendent,

4th October, 1939.

Royal Gunpowder Factory.

C.E. SECTION.

Recommendations for the Prevention of Dermatitis.

1. Ointment is supplied by the Factory. It will be rubbed well into the skin before starting work, and again at the end of the shift after bathing.
Always wash both face and hands to get rid of C.E. before rubbing on ointment.
2. The tips of the collar of the Danger Building Jacket will be sewn down and a soft collar stitched over it so as to prevent chafing at the neck.
The soft collar will be removed and washed frequently.
3. Do not scratch the face and neck, either during or out of working hours.
If the skin feels dry and inflamed after leaving work, relief will generally be afforded by the application of a little Lanoline mixed with a little castor oil.
4. If a man thinks he has developed dermatitis, he will report through his Chargeman to the Assistant Foreman. The latter will, if he considers it necessary, send the man to the hospital.

P.G. Knapman,

Waltham Abbey.

Superintendent,

4th October, 1939.

Royal Gunpowder Factory.