

WASC 1333

WAI 0343

5.10.1940

Royal Gunpowder Factory Waltham Abbey b/w photographs. Enemy bomb. /1-7

- 1 No 15 Cordite Stove from NE
- 2 No 15 Cordite Stove from SW
- 3 No 15 Cordite Stove, (remaining crater) after demolition by enemy action, looking NE
- 4 No 15 Cordite Stove, (remaining crater) after demolition by enemy action, looking SW
- 5 Crater caused by enemy action, 20 yards from N 15 Cordite Blending House, Looking E
- 6 Crater caused by enemy action, 20 yards from N 15 Cordite Blending House, Looking S
- 7 Crater caused by enemy action, 20 yards from N 15 Cordite Blending House, Looking S













