WASS 96

The Royal Gunpowder Factory

South Site

Area Old Series 405 - 662

References: Photographic Cartographic Documents

Concord... 5 014108 711992 Made in Great Britain

405

Number/ SS Number	405	Old Series:		NGR:	TQ37599974
Name/Function:					Condition
Name / Fundame	ction	Start Date:	End Date:		Good
Cordite wharf		1892	by 1923		Fair
					Demolished
					Unknown
Contact Prints	_ '				
Photography					
Cartographic depiction:					
Date: Cartograp	hic Depiction:	_			
1908 WASC 900/6	2A				
1923 WASC 900/8	4				
Documentary Reference	s:				
	ocumentary F	Reference:	Year:		
Sandhurst WASC 1508			1894 1910	-	
Historical Photographs:					
Relationship with other I	vionuments:				
Artefacts					
General Description:					
Length: 0	Breadth:	O Hei	ght: 0		
Shape in Plan					
Number of Storeys:					
Building Material:					
Bonding Type:					
Form of Roof:					
Roofing Material:					
Roof Features		· · · · · · · · · · · · · · · · · · ·			
Power Source					
Traverse:					
Entrance To:					
Elevation North:					
Elevation East:					
Elevation South:					
Elevation West:					

ROYAL GUNPOWDER FACTORY SOUTH SITE

Number/ SS Number	405B	Old Series:		NGR:	TQ37788977
Name/Function:					Condition
Name / Fund		Start Date:	End Date:		Good
Dry gun cotton yarn sto Demolished	ve	1918 by 1976	still present in 1923		Fair
Demonstred		by 1970			Demolished
					Unknown
Contact Prints					
Photography					
Cartographic depiction:					
	hic Depiction:				
1923 WASC 900/8					
1976 WASC 900/1					
Documentary Reference			V		
WASC 1508	ocumentary Ref	rerence:	Year: 1910	-	
Historical Photographs:					
Relationship with other I	Monuments:				
Artefacts					
General Description:					
Length: 0	Dua a dála	0 110	inha.		
	Breadth:	O Hei	ight: 0		
Shape in Plan					
Number of Storeys:					
Building Material:					
Bonding Type:					
Form of Roof:					
Roofing Material:					
Roof Features					
Power Source			*		
Traverse:					
Entrance To:					
Elevation North:					
Elevation East:					
Elevation South:					
Elevation West:					

405C

Number/ SS Number	405C	Old Series:			NGR:	TQ37929977
Name/Function:						Condition
Name / Funct	tion	Start Da	te:	End Date:		Good
Chimney						Fair Demolished Unknown
Contact Prints						
Photography						
Cartographic depiction:						
Date:Cartographi1923WASC 900/84	c Depiction:					
Documentary References:						
Historical Photographs:						
Relationship with other M	onuments:					
Artefacts						
General Description:						
Length: 0	Breadth:	0	Height:	0		
Shape in Plan						
Number of Storeys:						
Building Material:						
Bonding Type:						
Form of Roof:						
Roofing Material:						
Roof Features						
Power Source						
Traverse:						
Entrance To:						
Elevation North:						
Elevation East:						
Elevation South:						
Elevation West:						
Overall Internal Descriptio						
Interpretation of phasing						

405D

ROYAL GUNPOWDER FACTORY SOUTH SITE

Number/ SS Number	405D	Old Series:		NGR:	TQ37939977
Name/Function:					Condition
Name / Func	tion	Start Date:	End Date:		Good
Boiler House No.6					Fair Demolished Unknown
Contact Prints					
Photography					
Cartographic depiction:					
Date: Cartograph 1923 WASC 900/84	ic Depiction:				
Documentary References					
Historical Photographs:					
Relationship with other M	lonuments:				
Artefacts					
General Description:					
Length: 0	Breadth:	0 Heigh	nt: 0		
Shape in Plan					
Number of Storeys:					
Building Material:					
Bonding Type:					
Form of Roof:					
Roofing Material:					
Roof Features					
Power Source					
Traverse:					
Entrance To:					
Elevation North:					
Elevation East:					
Elevation South:					
Elevation West:					
Overall Internal Description	ı				

Interpretation of phasing

406

ROYAL GUNPOWDER FACTORY SOUTH SITE

Number/ SS Number	406	Old Series:			NGR:	TQ37869977
Name/Function:						Condition
Name / Func	tion	Start Da	te:	End Date:		Good
Carpentry Shop and Office		1905		1923		
						Fair Demolished Unknown
Contact Prints						
Photography						
Cartographic depiction:						
	ic Depiction:	Т				
1908 WASC 900/62		-				
1923 WASC 900/84						
Documentary References						
	cumentary Ref	erence:		Year:		
WASC 1508				1910		
Historical Photographs: Relationship with other M Artefacts	onuments:					
General Description:						
Length: 0	Breadth:	0	Height:	0		
Shape in Plan						
Number of Storeys:						
Building Material:						
Bonding Type:						
Form of Roof:						
Roofing Material:						
Roof Features						
Power Source						
Traverse:						
Entrance To:						
Entrance 10.						
Elevation North:						
Elevation East:						
Elevation South:						
Elevation West:						

407

ROYAL GUNPOWDER FACTORY SOUTH SITE

Name/Function: Name / Function Start Date: End Date: Good Fair Demolished Unknown Demolished Unknown Unkn
Name / Function Start Date: End Date: Good Fair Demolished Demolished Unknown Demolished Unknown Demolished Unknown Date: Cartographic depiction: Documentary References: Year: WASC 900/62A 1923 WASC 900/84 Documentary References: Year: WASC 1508 1910 Historical Photographs: Relationship with other Monuments: Artefacts General Description: Length: O
E.W. Dept.Store 1897 by 1923 Fair Demolished Unknown Unkno
Contact Prints Photography Cartographic depiction: Date: Cartographic Depiction: 1908 WASC 900/62A 1923 WASC 900/84 Documentary Reference: Year: WASC 1508 1910 Historical Photographs: Relationship with other Monuments: Artefacts General Description: Length: 0 Breadth: 0 Height: 0 Shape in Plan Number of Storeys:
Contact Prints Photography Cartographic depiction: Date: Cartographic Depiction: 1908 WASC 900/62A 1923 WASC 900/84 Documentary References: Documentary Reference: Year: WASC 1508 1910 Historical Photographs: Relationship with other Monuments: Artefacts General Description: Length: 0 Breadth: 0 Height: 0 Shape in Plan Number of Storeys:
Photography Cartographic depiction: Date: Cartographic Depiction: 1908 WASC 900/62A 1923 WASC 900/84 Documentary References: Documentary Reference: Year: WASC 1508 1910 Historical Photographs: Relationship with other Monuments: Artefacts General Description: Length: 0 Breadth: 0 Height: 0 Shape in Plan Number of Storeys:
Photography Cartographic depiction: Date: Cartographic Depiction: 1908 WASC 900/62A 1923 WASC 900/84 Documentary References: Documentary Reference: Year: WASC 1508 1910 Historical Photographs: Relationship with other Monuments: Artefacts General Description: Length: 0 Breadth: 0 Height: 0 Shape in Plan Number of Storeys:
Cartographic depiction: Date: Cartographic Depiction: 1908
Cartographic depiction: Date: Cartographic Depiction: 1908 WASC 900/62A 1923 WASC 900/84
Date: Cartographic Depiction: 1908
1908 WASC 900/62A 1923 WASC 900/84 Documentary References: Documentary Reference: Year:
Documentary References: Documentary Reference: Year:
Documentary Reference: Year: WASC 1508 1910 Historical Photographs: Relationship with other Monuments: Artefacts General Description: Length: 0 Breadth: 0 Height: 0 Shape in Plan Number of Storeys:
WASC 1508 1910 Historical Photographs: Relationship with other Monuments: Artefacts General Description: Length: 0 Breadth: 0 Height: 0 Shape in Plan Number of Storeys:
Historical Photographs: Relationship with other Monuments: Artefacts General Description: Length: 0
Relationship with other Monuments: Artefacts General Description: Length: 0
Artefacts General Description: Length: 0 Breadth: 0 Height: 0 Shape in Plan Number of Storeys:
General Description: Length: 0 Breadth: 0 Height: 0 Shape in Plan Number of Storeys:
Length: 0 Breadth: 0 Height: 0 Shape in Plan Number of Storeys:
Shape in Plan Number of Storeys:
Shape in Plan Number of Storeys:
Number of Storeys:
Control of the Contro
Bonding Type:
Form of Roof:
Roofing Material:
Roof Features
Power Source
Traverse:
Entrance To:
Elevation North:
Elevation East:
Elevation East: Elevation South:

408

ROYAL GUNPOWDER FACTORY SOUTH SITE

Number/ SS Number	408	Old Series:		NGR:	TQ37959980
Name/Function:					Condition
Name / Fun	ction	Start Date:	End Date:		Good
B.W. Dept. Store		1897 by 1923	by 1076		☐ Fair
Dining Room		by 1923	by 1976		Demolished
					Unknown
Contact Prints					
Contact Prints	_				
Photography					
Cartographic depiction:					
	hic Depiction:				
1923 WASC 900/8	34				
1976 WASC 900/1	13				
Documentary Reference					
WASC 1508	ocumentary Re	ference:	Year: 1910	-	
			1010		
Historical Photographs:					
Relationship with other	Monuments:				
Artefacts					
General Description:					
Length: 0	Breadth:	O Heig	ght: 0		
Shape in Plan]		
Number of Storeys:					
Building Material:					
Bonding Type:					
Form of Roof:					
Roofing Material:					
Roof Features					
Power Source					
Traverse:					
Entrance To:					
Elevation North:					
Elevation East:					
Elevation South:					
Elevation West:					

408A

ROYAL GUNPOWDER FACTORY SOUTH SITE

Number/ SS Number	408A	Old Series:			NGR:	TQ3795	59980
Name/Function:		,				Conditi	on
Name / Fund	etion	Start Da		End Date:			Good
Guard House		1915	by	1976			Fair
						\boxtimes	Demolished
							Unknown
Contact Prints	_						
Photography							
Cartographic depiction:							
	nic Depiction:						
1923 WASC 900/8							
1976 WASC 900/1							
Documentary References		f		Vacan			
WASC 1508 (sup)	ocumentary Re	rerence:		Year: 1910			
Historical Photographs:							
Relationship with other N	/lonuments:						
Artefacts							
General Description:							
Length: 0	Breadth:	0	Height:	0			
	breautii.	U	Height.	U			
Shape in Plan							
Number of Storeys:							
Building Material:							
Bonding Type:							
Form of Roof:							
Roofing Material:							
Roof Features							
Power Source							
Traverse:							
Entrance To:							
Elevation North:							
Elevation East:							
Elevation South:							
Elevation West:							

409

Number/ SS Number	409	Old Series:			NGR:	TQ37959978
Name/Function:		ī				Condition
Name / Func	tion	Start Dat		End Date:		Good
Earth Closet		1903	by	1976		Fair
						□ Demolished
						Unknown
Contact Prints						
Photography						
Cartographic depiction:						
	ic Depiction:					
1908 WASC 900/62 1923 WASC 900/84		_				
1976 WASC 900/11						
Documentary References	:					
	ocumentary Re	ference:		Year:		
WASC 1508				1910		
Historical Photographs:						
Relationship with other M	/lonuments:					
Artefacts						
General Description:						
Length: 0	Breadth:	0	Height:	0		
Shape in Plan						
Number of Storeys:						
Building Material:						
Bonding Type:						
Form of Roof:						
Roofing Material:						
Roof Features						
Power Source						
Traverse:						
Entrance To:						
Elevation North:						
Elevation East:						
Elevation South:						
Elevation West:						

411

Name/Function: Name / Function Start Date: End Date: Good Fair Demolished Unknown
Name / Function 1904 by 1976 Fair Demolished Unknown
Contact Prints Photography Cartographic depiction: Date:
Contact Prints Photography Cartographic depiction: Date: Cartographic Depiction: 1908 WASC 900/62A 1923 WASC 900/84 1976 WASC 900/113 Documentary References:
Contact Prints Photography Cartographic depiction: Date: Cartographic Depiction: 1908 WASC 900/62A 1923 WASC 900/84 1976 WASC 900/113 Documentary References:
Photography Cartographic depiction: Date: Cartographic Depiction: 1908 WASC 900/62A 1923 WASC 900/84 1976 WASC 900/113 Documentary References:
Cartographic depiction: Date: Cartographic Depiction: 1908 WASC 900/62A 1923 WASC 900/84 1976 WASC 900/113 Documentary References:
Cartographic depiction: Date: Cartographic Depiction: 1908 WASC 900/62A 1923 WASC 900/84 1976 WASC 900/113 Documentary References:
Cartographic depiction: Date: Cartographic Depiction: 1908 WASC 900/62A 1923 WASC 900/84 1976 WASC 900/113 Documentary References:
Cartographic depiction: Date: Cartographic Depiction: 1908 WASC 900/62A 1923 WASC 900/84 1976 WASC 900/113 Documentary References:
Cartographic depiction: Date: Cartographic Depiction: 1908 WASC 900/62A 1923 WASC 900/84 1976 WASC 900/113 Documentary References:
Cartographic depiction: Date: Cartographic Depiction: 1908 WASC 900/62A 1923 WASC 900/84 1976 WASC 900/113 Documentary References:
Cartographic depiction: Date: Cartographic Depiction: 1908 WASC 900/62A 1923 WASC 900/84 1976 WASC 900/113 Documentary References:
Cartographic depiction: Date: Cartographic Depiction: 1908 WASC 900/62A 1923 WASC 900/84 1976 WASC 900/113 Documentary References:
Date: Cartographic Depiction: 1908 WASC 900/62A 1923 WASC 900/84 1976 WASC 900/113 Documentary References:
1908 WASC 900/62A 1923 WASC 900/84 1976 WASC 900/113 Documentary References:
1923 WASC 900/84 1976 WASC 900/113 Documentary References:
1976 WASC 900/113 Documentary References:
Documentary Reference: Year:
WASC 1508 1910
Historical Photographs:
Relationship with other Monuments:
Artefacts
General Description:
Length: 0 Breadth: 0 Height: 0
Shape in Plan
Shape in Plan Number of Storeys:
Shape in Plan Number of Storeys: Building Material:
Shape in Plan Number of Storeys: Building Material: Bonding Type:
Shape in Plan Number of Storeys: Building Material: Bonding Type: Form of Roof:
Shape in Plan Number of Storeys: Building Material: Bonding Type: Form of Roof: Roofing Material:
Shape in Plan Number of Storeys: Building Material: Bonding Type: Form of Roof: Roofing Material: Roof Features
Shape in Plan Number of Storeys: Building Material: Bonding Type: Form of Roof: Roofing Material: Roof Features Power Source
Shape in Plan Number of Storeys: Building Material: Bonding Type: Form of Roof: Roofing Material: Roof Features
Shape in Plan Number of Storeys: Building Material: Bonding Type: Form of Roof: Roofing Material: Roof Features Power Source
Shape in Plan Number of Storeys: Building Material: Bonding Type: Form of Roof: Roofing Material: Roof Features Power Source Traverse: Entrance To:
Shape in Plan Number of Storeys: Building Material: Bonding Type: Form of Roof: Roofing Material: Roof Features Power Source Traverse: Entrance To: Elevation North:
Shape in Plan Number of Storeys: Building Material: Bonding Type: Form of Roof: Roofing Material: Roof Features Power Source Traverse: Entrance To:

412

Number/ SS Number	412	Old Series:			NGR:	TQ37959976
Name/Function:						Condition
Name / Functi	ion	Start Dat	e:	End Date:		Good
Fan House		1903	by	1976		Fair
						Demolished
						Unknown
Contact Prints				-		
Photography						
Cartographic depiction:						
Date: Cartographic						
1908 WASC 900/62A 1923 WASC 900/84	4	-				
1976 WASC 900/113	3					
Documentary References:						
	cumentary Ref	ference:		Year:		
WASC 1508				1910		
Historical Photographs:						
Relationship with other Mo	onuments:					
Artefacts						
General Description:						
Length: 0	Breadth:	0	Height:	0		
Shape in Plan						
Number of Storeys:						
Building Material:						
Bonding Type:						
Form of Roof:						
Roofing Material:						
Roof Features						
Power Source						
Traverse:						
Entrance To:						
Flavorian North						
Elevation North:						
Elevation East:						
Elevation South:						
Elevation West:						

412A

Number/ SS Num	ber	412A	Old Series:			NGR:	TQ37959975
Name/Function:			_				Condition
	e / Func	tion	Start Date		End Date:		Good
Stokers Shifting	Room		1915	by 197	6		Fair
							□ Demolished
							Unknown
Contact Prints							
-	_						
Photography							
Cartographic dep	iction:						
		ic Depiction:					
	900/84		-				
Documentary Ref		cumentary R	eference:		Year:		
WASC 1508		ourneritary 10	0101011001		1910		
Historical Photogr	raphs:						
Relationship with	other M	lonuments:					
Artefacts							
General Descripti	on:						
Length: 0		Breadth:	0	Height: 0			
Shape in Plan							
Number of Storey	/s:						
Building Material:							
Bonding Type:							
Form of Roof:							
Roofing Material:							
Roof Features							
Power Source							
Traverse:							
Entrance To:							
Elevation North:							
Elevation East:							
Elevation South:							
Elevation West:							
Overall Internal D	escriptio						

414

Number/ SS Number	414	Old Series:			NGR:	TQ37969978
Name/Function:						Condition
Name / Func	tion	Start Dat	e: Er	nd Date:		Good
Office (re-erected on Sou	ıth Site)	1886 1892	by 1976		-	☐ Fair
						Demolished
						Unknown
Contact Prints						
_						
Photography						
Cartographic depiction:						
	ic Depiction:	\Box				
1908 WASC 900/62	2A					
1923 WASC 900/84 1976 WASC 900/11						
Documentary References	: ocumentary Re	ference:		Year:		
WASC 1508	oumontary no	101011001		1910		
Historical Photographs:						
Relationship with other M	Ionuments:					
Artefacts						
General Description:						
Length: 0	Breadth:	0	Height: 0			
Shape in Plan						
Number of Storeys:						
Building Material:						
Bonding Type:						
Form of Roof:						
Roofing Material:						
Roof Features						
Power Source						
Traverse:						
Entrance To:						
Elevation North:						
Elevation East:						
Elevation South:						
Elevation West:						

415

Number/ SS Number	415	Old Series:			NGR:	TQ3801	9982
Name/Function:						Conditi	on
Name / Func	tion	Start Date		End Date:			Good
Coal Elevator		1903	by	1976			Fair Demolished Unknown
Contact Prints	-		_				
Photography							
Cartographic depiction:							
	ic Depiction:						
1908 WASC 900/62 1923 WASC 900/84		-					
1976 WASC 900/11							
Documentary References	:						
	cumentary Re	ference:		Year:			
WASC 1508				1910			
Historical Photographs:	lanumanta.						
Relationship with other M	ionuments:						
Artefacts							
General Description:							
Length: 0	Breadth:	0 H	leight:	0			
Shape in Plan							
Number of Storeys:							
Building Material:							
Bonding Type:							
Form of Roof:							
Roofing Material:							
Roof Features							
Power Source							
Traverse:							
Entrance To:							
Elevation North:							
Elevation East:							
Elevation South:							
Elevation West:							

416

Number/ SS Number	416	Old Series:		NGR:	TQ38049977
Name/Function:					Condition
Name / Func	tion	Start Date	End Da	te:	Good
Chimney		1902-3	by 1976	, i	Fair
					Demolished
					Unknown
Contact Prints					
Photography					
Cartographic depiction:					
	ic Depiction:				
1908 WASC 900/62 1923 WASC 900/84		-			
1976 WASC 900/11					
Documentary References	:				
	cumentary Ref	erence:	Y	ear:	
WASC 1508			1910)	
Historical Photographs:					
Relationship with other M	Ionuments:				
Artefacts					
General Description:					
Length: 0	Breadth:	0 H	eight: 0		
Shape in Plan					
Number of Storeys:					
Building Material:					
Bonding Type:		***			
Form of Roof:					
Roofing Material:					
Roof Features					
Power Source					
Traverse:					
Entrance To:					
Elevation North:					
Elevation East:					
Elevation South:					
Elevation West:					

417

ROYAL GUNPOWDER FACTORY SOUTH SITE

Number/ SS Number	417	Old Series:			NGR:	TQ38049979
Name/Function:		J				Condition
Name / Fund	ction	Start Dat	e:	End Date:		Good
Economiser Chamber		1902-3		1976		Fair
						Demolished Unknown
Contact Prints						onknown
_	_					
Photography						
Cartographic depiction:						
	hic Depiction:					
1908 WASC 900/6 1923 WASC 900/8		_				
1976 WASC 900/1						
Documentary References	s:					
D	ocumentary Re	ference:		Year:		
WASC 1508				1910		
Historical Photographs:						
Relationship with other M	√lonuments:					
Artefacts						
General Description:						
Length: 0	Breadth:	0	Height:	0		
Shape in Plan						
Number of Storeys:						
Building Material:						
Bonding Type:						
Form of Roof:						
Roofing Material:						
Roof Features						
Power Source						
Traverse:						
Entrance To:						
Elevation North:						
Elevation East:						
Elevation South:						

Elevation West:

418

Number/ SS Number	418	Old Series:			NGR:	TQ3804	49975
Name/Function:		_				Conditi	on
Name / Fund	ction	Start Da		End Date:			Good
Economiser Chamber		1902-3	by	y 1976			Fair
						\boxtimes	Demolished
							Unknown
Contact Prints	-						
Photography							
Cartographic depiction:							
	nic Depiction:						
1908 WASC 900/6 1923 WASC 900/8		-					
1976 WASC 900/1							
Documentary References	s:						
	ocumentary Re	eference:		Yea	ır:		
WASC 1508				1910			
Historical Photographs:							
Relationship with other I	Vlonuments:						
Artefacts							
General Description:							
Length: 0	Breadth:	0	Height:	0			
	breautii.	0	rieigiit.	U			
Shape in Plan							
Number of Storeys:							
Building Material:							
Bonding Type:							
Form of Roof:							
Roofing Material:							
Roof Features							
Power Source							
Traverse:							
Entrance To:							
Elevation North:							
Elevation East:							
Elevation South:							
Elevation West:							

419

Number/ SS Number	419	Old Series:			NGR:	TQ38029978
Name/Function:		J				Condition
Name / Func	tion	Start Dat	e:	End Date:		Good
Boiler House No.7		1902-3	by	1976		Fair
						Demolished
						Unknown
Contact Prints						,
Photography						
Cartographic depiction:						
	ic Depiction:					
1908 WASC 900/62 1923 WASC 900/84		-				
1976 WASC 900/11						
Documentary References	:					
	cumentary Re	ference:		Year:		
WASC 1508				1910		
Historical Photographs:						
Relationship with other M	lonuments:					
Artefacts						
General Description:						
Length: 0	Breadth:	0	Height:	0		
Shape in Plan						
Number of Storeys:						
Building Material:						
Bonding Type:						
Form of Roof:						
Roofing Material:						
Roof Features						
Power Source						
Traverse:						
Entrance To:						
Elevation North:						
Elevation East:						
Elevation South:						
Elevation West:						

419A

ROYAL GUNPOWDER FACTORY SOUTH SITE

Number/ SS Number	419A	Old Series:			NGR:	TQ3802	9978
Name/Function:						Conditio	n
Name / Func	tion	Start Da	te:	End Date:			Good
Pump House						\boxtimes	Fair Demolished Unknown
Contact Prints							
Photography							
Cartographic depiction:							
Date: Cartograph 1923 WASC 900/62 1976 WASC 900/11							
Documentary References							
WASC 1508 (sup)	cumentary Ref	ference:		Year: 1910	+		
				1.0.0			
Historical Photographs: Relationship with other M	lonuments:						
Artefacts							
General Description:							
Length: 0	Breadth:	0	Height:	0			
	breauth:	U	neight.	O			
Shape in Plan			100				
Number of Storeys:							
Building Material:							
Bonding Type:							
Form of Roof:							
Roofing Material:							
Roof Features							
Power Source							
Traverse:							
Entrance To:							
Elevation North:							
Elevation East:							
Elevation South:							
Elevation West:							

420

Number/ SS Number	420	Old Series:			NGR:	TQ3802	29974
Name/Function:						Conditi	on
Name / Func	tion	Start Date		End Date:			Good
Coal Elevator		1903	by	1973			Fair Demolished Unknown
Contact Prints							
Photography							
Cartographic depiction:							
	ic Depiction:						
1908 WASC 900/62 1923 WASC 900/84		-					
1976 WASC 900/11							
Documentary References	:						
WASC 1508	cumentary Ref	erence:		Year: 1910			
Historical Photographs:							
Relationship with other M	lonuments:						
Artefacts							
General Description:							
Length: 0	Breadth:	0	Height:	0			
Shape in Plan							
Number of Storeys:							
Building Material:							
Bonding Type:							
Form of Roof:							
Roofing Material:							
Roof Features							
Power Source							
Traverse:							
Entrance To:							
Elevation North:							
Elevation East:							
Elevation South:							
Elevation West:							

421A

ROYAL GUNPOWDER FACTORY SOUTH SITE

Number/ SS Number	421A	Old Series:			NGR:	TQ3805	59977
Name/Function:						Conditi	on
Name / Func	tion	Start Da		End Date:			Good
Vat House		1916		by 1976			Fair
							Demolished
							Unknown
Contact Prints							
	-				-		
Photography							
Cartographic depiction:							
Date: Cartograph	ic Depiction:						
1923 WASC 900/84 1976 WASC 900/11							
Documentary References							
	cumentary Ref	erence:		Year	r:		
WASC 1508				1910			
Historical Photographs:							
Relationship with other M	lonuments:						
Artefacts							
General Description:							
Length: 0	Breadth:	0	Heigh	:: 0			
Shape in Plan							
Number of Storeys:							
Building Material:							
Bonding Type:							
Form of Roof:							
Roofing Material:							
Roof Features							
Power Source							
Traverse:							
Entrance To:							
2.1001100 101							
Elevation North:							
Elevation East:							
Elevation South:							
Elevation West:							

421B

ROYAL GUNPOWDER FACTORY SOUTH SITE

Number/ SS Number	421B	Old Series:			NGR:	TQ38059977
Name/Function:						Condition
Name / Fund	tion	Start Da		End Date:		Good
Press House	*	1916	by	1976		Fair Demolished Unknown
Contact Prints	_					
Photography						
Cartographic depiction:						
Documentary References						
WASC 1508	ocumentary Re	ference:		Year: 1910	-	
Historical Photographs:						
Relationship with other N	/lonuments:					
Artefacts						
General Description:						
Length: 0	Breadth:	0	Height:	0		
Shape in Plan						
Number of Storeys:						
Building Material:						
Bonding Type:						
Form of Roof:						
Roofing Material:						
Roof Features						
Power Source						
Traverse:						
Entrance To:						
Elevation North:						
Elevation East:						
Elevation South:						
Elevation West:						

422

Number/ SS Number	422	Old Series:			NGR:	TQ38179983
Name/Function:						Condition
Name / Func	tion	Start Da	te:	End Date:		Good
Vat House		1889				Fair
						Demolished
						Unknown
Contact Prints						
Photography						
Cartographic depiction:						
	ic Depiction:					
1923 WASC 900/84 1907 WASC 900/62						
1897 OS map	A (vat nouse)					
1888 WASC 900/38	· Soaking Tan	k				
Documentary References		K.				
	cumentary Re	ference:		Year:		
WASC 1508				1910		
Sandhurst SUPP/5/327				1894	-	
Historical Photographs:						
Relationship with other M	lonuments:					
Artefacts						
General Description:						
Length: 0	Breadth:	0	Height:	0		
Shape in Plan						
Number of Storeys:						
Building Material:						
Bonding Type:						
Form of Roof:						
Roofing Material:						
Roof Features						
Power Source						
Traverse:						
Entrance To:						
Florest November						
Elevation North:						
Elevation East:						

422A

Number/ SS Number	422A	Old Series:		NGR:	TQ38189983
Name/Function:					Condition
Name / Func	tion	Start Date:	End Date:		Good
A.C. Store Vat House		1888 1916			☐ Fair
vat riouse		1010			Demolished
					Unknown
Contact Prints					
	-				
Photography					
Cartographic depiction:					
	ic Depiction:				
1897 OS map	A /				
1907 WASC 900/62 1923 WASC 900/84		3			
1888 WASC 900/38					
Documentary References:	1				
	cumentary Re	ference:	Year:		
Sandhurst WASC 1508 (sup)			1894 1910	_	
			1310		
Historical Photographs:					
Relationship with other M	onuments:				
Artefacts					
General Description:					
Length: 0	Breadth:	0 Height	: O		
Shape in Plan					
Number of Storeys:					
Building Material:					
Bonding Type:					
Form of Roof:					
Roofing Material:					
Roof Features					
Power Source					
Traverse:					
Entrance To:					
Elevation North:					
Elevation East:					
Elevation South:					
Elevation West:					

423

Number/ SS Number	423	Old Series:			NGR:	TQ38199983
Name/Function:		_				Condition
Name / Fund	tion	Start Dat	te:	End Date:		Good
Acid Separation House Nitrate of Soda Store		1888 by 1907				☐ Fair
Mitrate of Soda Store		by 1907				Demolished
						Unknown
-						
Contact Prints						
Photography						
Cartographic depiction:						
Date: Cartograph 1923 WASC 900/84	ic Depiction:					
1907 WASC 900/62						
1897 OS map						
1888 WASC 900/38	3;Acid Stores					
Documentary References						
WASC 1508	ocumentary Re	eference:		Year: 1910	\perp	
Sandhurst (acid separation	n house)			1894		
SUPP/5/327						
Historical Photographs:						
Relationship with other N	/lonuments:					
Artefacts						
General Description:						
			4			
Length: 0	Breadth:	0	Height:	0		
Shape in Plan						
Number of Storeys:						
Building Material:						
Bonding Type:						
Form of Roof:						
Roofing Material:						
Roof Features						
Power Source						
Traverse:						
Entrance To:						
Elevation North:						
Elevation East:						
Elevation South:						

423A

ROYAL GUNPOWDER FACTORY SOUTH SITE

Number/ SS Number	423A	Old Series:			NGR:	TQ3819	9983
Name/Function:						Conditi	on
Name / Fund	etion	Start Da	te:	End Date:			Good
Cotton Waste Store		1913					Fair Demolished Unknown
Contact Prints							
Photography							
Cartographic depiction:							
Date: Cartograph 1923 WASC 900/8	nic Depiction: 4 (cotton waste						
Documentary References							
	ocumentary Ref	erence:		Year:	-		
WASC 1508 (sup)				1910			
Historical Photographs:							
Relationship with other N Artefacts	vionuments:						
General Description:							
	D 1/1		11-2-1-2				
	Breadth:	0	Height:	0			
Shape in Plan							
Number of Storeys:							
Building Material:							
Bonding Type:							
Form of Roof:							
Roofing Material:							
Roof Features							
Power Source							
Traverse:							
Entrance To:							
Elevation North:							
Elevation East:							
Elevation South:							
Elevation West:							

424

ROYAL GUNPOWDER FACTORY SOUTH SITE

Number/ SS Number	424	Old Series:		NGR:	TQ38199982
Name/Function:					Condition
Name / Fund	etion	Start Date:	End Date:		Good
Acid Separating House Egg House and Store		1892 by 1907			☐ Fair
Egg Flouse and Otore		Dy 1007			Demolished
					Unknown
Contact Prints					
DI .					
Photography					
Cartographic depiction: Date: Cartograph	nia Daniation:				
1923 WASC 900/8					
1907 WASC 900/6	2A				
1897 OS map					
Documentary References	s: ocumentary R	eference:	Year:		
WASC 1508	ocumentary n	ererence.	1910		
Sandhurst (acid separation	ng house)		1897		
Historical Photographs:					
Relationship with other	Vlonuments:	Subsumed into G431			
Artefacts					
General Description:					
Length: 0	Breadth:	O Height:	0		
	Diodutiii				
Shape in Plan					
Number of Storeys:					
Building Material:					
Bonding Type:					
Form of Roof:					
Roofing Material:					
Roof Features					
Power Source					
Traverse:					
Entrance To:					
Claustian Narth					
Elevation North:					
Elevation East:					
Elevation South:					

Elevation West:

424A

ROYAL GUNPOWDER FACTORY SOUTH SITE

Number/ SS Number	424A	Old Series:			NGR:	TQ38219982
Name/Function:		1				Condition
Name / Fund	tion	Start D	ate:	End Date:		Good
Cotton Waste Store No.	3	1913				☐ Fair
						Demolished
						Unknown
Contact Prints						
- —				-		
Photography						
Cartographic depiction:						
	ic Depiction:					
1923 WASC 900/84	4 (cotton wast	е				
Documentary References	::					
	ocumentary Re	ference:		Year:		
WASC 1508 (sup)				1910		
Historical Photographs:						
Relationship with other N	flonuments:	Subsumed in	to G431			
Artefacts						
General Description:						
Length: 0	Breadth:	0	Height:	0		
Shape in Plan						
Number of Storeys:						
Building Material:						
Bonding Type:				311 - 1 - 333 - 3 - 3 - 3 - 3 - 3 - 3 -		
Form of Roof:						
Roofing Material:						
Roof Features						
Power Source						
Traverse:						
Entrance To:						
Elevation North:						
Elevation East:						
Elevation South:						
Elevation West:						
LICYULION WYGGL						

425

Number/ SS Number	425	Old Series:		NGR:	TQ38229983				
Name/Function:					Condition				
Name / Func	tion	Start Date:	End Date:		Good				
Denitrating House		by 1897-8			Fair				
Nitric Acid Factory		by 1907	4000						
Picric Acid Factory		1914	post 1923						
					Unknown				
Contact Prints		_							
Photography Cartographic depiction:									
	ic Depiction:	\Box							
Date: Cartograph 1923 WASC 900/84									
1908 WASC 900/62									
1897 OS map (denit	rating house)								
Documentary References	:								
	cumentary Ref	erence:	Year:						
WASC 1508 1910 Historical Photographs:									
Relationship with other M	Ionuments:								
Artefacts									
General Description:									
Length: 0	Breadth:	0 Hei	ght: 0						
Shape in Plan]						
Number of Storeys:									
Building Material:									
Bonding Type:									
Form of Roof:									
Roofing Material:									
Roof Features									
Power Source									
Traverse:									
Entrance To:									
Elevation North:									
Elevation East:									
Elevation South:									
Elevation West:									

425A

Number/ SS Number	425A	Old Series:			NGR:	TQ38229983
Name/Function:		J				Condition
						Good
						☐ Fair
						Demolished
						Unknown
Contact Prints	_					
Photography						
Cartographic depiction:						
Documentary Reference	s:					
Historical Photographs:						
Relationship with other	Monuments:					
Artefacts						
General Description:						
Length: 0	Breadth:	0	Height:	0		
Shape in Plan						
Number of Storeys:						
Building Material:						
Bonding Type:						
Form of Roof:						
Roofing Material:						
Roof Features						
Power Source						
Traverse:						
Entrance To:						
Elevation North:						
Elevation East:						
Elevation South:						
Elevation West:						
Overall Internal Descript	io					
Overall Internal Descript Interpretation of phasing						

425B

ROYAL GUNPOWDER FACTORY SOUTH SITE

Number/ SS Number	425B	Old Series:			NGR:	TQ38229983
Name/Function:						Condition
Name / Funct		Start Da	te:	End Date:		Good
Extension to Picric Facto	ry (building 42	by 1922				Fair
						Demolished
						Unknown
Contact Prints						
	-					-
Photography						
Cartographic depiction:						
	ic Depiction:					
1923 WASC 900/84						
Documentary References	•					
Historical Photographs:						
Relationship with other M	lonuments:					
Artefacts						
General Description:						
Length: 0	Breadth:	0	Height:	0		
Shape in Plan						
Number of Storeys:						
Building Material:						
Bonding Type:						
Form of Roof:						
Roofing Material:						
Roof Features						4
Power Source						
Traverse:						
Entrance To:						
Elevation North:						
Elevation East:						
Elevation South:						
Elevation West:						
Overall Internal Descriptio						

Interpretation of phasing

426

ROYAL GUNPOWDER FACTORY SOUTH SITE

Number/ SS Number	426	Old Series:			NGR:	TQ3823	39982
Name/Function:						Conditi	on
Name / Fund	etion	Start Da	te:	End Date:			Good
Chimney		1898-9					Fair
							Demolished
							Unknown
Contact Prints							
Photography							
Cartographic depiction:							
Date: Cartograph 1923 WASC 900/8	nic Depiction:						
1907 WASC 900/6							
Documentary References	s:						
WASC 1508	ocumentary Re	ference:		Year: 1910	-		
Historical Photographs:				1010			
Relationship with other N	Monuments:						
Artefacts							
General Description:							
Length: 0	Breadth:	0	Height:	0			
Shape in Plan							
Number of Storeys:				×			
Building Material:							
Bonding Type:							
Form of Roof:							
Roofing Material:							
Roof Features							
Power Source							
Traverse:							
Entrance To:							
Elevation North:							
Elevation East:							
Elevation South:							
Elevation West:							
Annual Contraction (Contraction Contraction Contractio							

427A

ROYAL GUNPOWDER FACTORY SOUTH SITE

Number/ SS Number	427A	Old Series:		NGR:	TQ38089978
Name/Function:					Condition
Name / Func	tion	Start Date:	End Date:		Good
Guncotton Press Drilling	Houses	by 1923			Fair Demolished Unknown
Contact Prints					
Photography					
Cartographic depiction:					
		dr			
Documentary References	:				
Historical Photographs:					
Relationship with other N	fonuments:				
Artefacts					
General Description:					
Length: 0	Breadth:	O Heigh	t: 0		
Shape in Plan					
Number of Storeys:					
Building Material:					
Bonding Type:					
Form of Roof:					
Roofing Material:					
Roof Features					
Power Source					
Traverse:					
Entrance To:					
Elevation North:					
Elevation East:					
Elevation South:					
Elevation West:					
Overall Internal Description)				

Interpretation of phasing

428

ROYAL GUNPOWDER FACTORY SOUTH SITE

Number/ SS Number	428	Old Series:			NGR:	TQ3812	9979
Name/Function:						Condition	on
Name / Fund	tion	Start Da	ate:	End Date:			Good
Chimney		1888 1907					Fair
							Demolished
							Unknown
Contact Prints		_					
Photography							
Cartographic depiction:							
	ic Depiction:						
Documentary References	s: ocumentary Ref	erence:		Year:			
WASC 1508	Journal y 110			1910			
Historical Photographs:							
Relationship with other N	/lonuments:						
Artefacts							
General Description:							
Length: 0	Breadth:	0	Height:	0			
Shape in Plan							
Number of Storeys:							
Building Material:							
Bonding Type:							
Form of Roof:							
Roofing Material:							
Roof Features							
Power Source							
Traverse:							
Entrance To:							
Elevation North:							
Elevation East:							
Elevation South:							
Elevation West:							

429

Number/ SS Number	429	Old Series:		NGR:	TQ38189980
Name/Function:					Condition
	Name / Function		End Date:		Good
Nitrating Room		1888			Fair
					□ Demolished
					Unknown
0					
Contact Prints	_				
Photography					
Cartographic depiction:	ia Daniations	$\overline{}$			
Date: Cartograph 1923 WASC 900/84	ic Depiction: Initrating roo	,			
1907 WASC 900/62					
1897 OS map					
Documentary References					
WASC 1508	cumentary Re	eference:	Year: 1910	-	
Sandhurst (guncotton wo	rks)		1894		
Historical Photographs:					
Relationship with other N	lonumenter				
	ionuments.				
Artefacts					
General Description:					
Length: 0	Breadth:	0 Heigh	t: 0		
Shape in Plan					
Number of Storeys:					
Building Material:					
Bonding Type:					
Form of Roof:					
Roofing Material:					
Roof Features					
Power Source					
Traverse:					
Entrance To:					
Elevation North:					
Elevation East:					
Elevation South:					

429A

Number/ SS Number	429A	Old Series:			NGR:	TQ38179980
Name/Function:		_				Condition
Name / Fund	tion	Start Dat	te:	End Date:		Good
Cooling Room		by 1894 by 1907				☐ Fair
Cooming Mooni		D) 1007				Demolished
						Unknown
Contact Prints						
_	-			-		
Photography						
Cartographic depiction:						
	ic Depiction:					
1923 WASC 900/84 1907 WASC 900/62						
1897 OS map						
1888 WASC 900/38		C				
Documentary References						
Sandhurst (guncotton wo	ocumentary R	eterence:		1894	\dashv	
Historical Photographs:						
	,					
Relationship with other N	nonuments:					
Artefacts						
General Description:						
Length: 0	Breadth:	0	Height:	0		
Shape in Plan						
Number of Storeys:						
Building Material:						
Bonding Type:						
Form of Roof:						
Roofing Material:						
Roof Features						
Power Source						
Traverse:						
Entrance To:						
Entrance 10.						
Elevation North:						
Elevation East:						
Elevation South:						
Elevation West:						

429B

Number/ SS Number	429B	Old Series:		NGR:	TQ38189980
Name/Function:		_			Condition
Name / Fun	ction	Start Date:	End Date:		Good
		1888			☐ Fair
Drying Room		1907			Demolished
					Unknown
0					
Contact Prints					
Di- 4					
Photography					
Cartographic depiction:	Li D. I.d.				
	hic Depiction: 34 (drying roon				
1907 WASC 900/6	32A (nitrating l				
1897 OS map 1888 WASC 900/3	88; Drying and				
Documentary Reference			V		
WASC 1508	ocumentary R	eterence:	1910		
Sandhurst (guncotton w	orks)		1894		
Historical Photographs:					
Relationship with other	Monuments:	Subsumed into G431			
Artefacts		Gustamou into G161			
General Description:					
Length: 0	Breadth:	O Height:	0		
Shape in Plan					
Number of Storeys:					
Building Material:					
Bonding Type:					
Form of Roof:					
Roofing Material:					
Roof Features					
Power Source					
Traverse:					
Entrance To:					
Elevation North:					
Elevation East:					
Elevation South:					
Elevation West:					

429C

Number/ SS Number	429C	Old Series:		NGR:	TQ38209980
Name/Function:					Condition
Name / Fund	etion	Start Date:	End Date:		Good
Teasing Room		1888 by 1907			⊠ Fair
reading readin		by 1007		*	Demolished
					Unknown
Contact Prints					
	-				
Photography					
Cartographic depiction:					
	nic Depiction:				
1923 WASC 900/84 1907 WASC 900/63					
1897 OS map					
Documentary References	3:				
	ocumentary R	Reference:	Year:		
WASC 1508 SUPP/5/466 p32, (new p	ulning machi	ne)	1910 11/1894		
Sandhurst	Julping muoni	110)	1894		
Historical Photographs:					
		Historical Photographs:			
BB92/ 16740 RCHME					
Relationship with other N	/lonuments:	Subsumed into G431			
Artefacts					
General Description:					
Length: 0	Breadth:	O Height:	0		
Shape in Plan					
Number of Storeys:					
Building Material:					
Bonding Type:					
Form of Roof:					
Roofing Material:					
Roof Features					
Power Source					
Traverse:					
Entrance To:					
Elevation North:					
Elevation East:					

430

Number/ SS Number	430	Old Series:		NGR:	TQ38219980
Name/Function:					Condition
Name / Fun	ction	Start Date:	End Date:		Good
Cotton Waste Store					Fair Demolished Unknown
Contact Prints					
Photography					
Cartographic depiction:					
	hic Depiction:	\Box			
1923 WASC 900/8 1907 WASC 900/6	34 (cotton waste 32A	3			
Documentary Reference					
	ocumentary Re	ference:	Year: 1910	_	
WASC 1508 SUPP/5/327			1910		
Historical Photographs:					
Relationship with other	Monuments:	Subsumed into G431			
Artefacts					
General Description:					
Length: 0	Breadth:	O Height:	0		
Shape in Plan					
Number of Storeys:					
Building Material:					
Bonding Type:					
Form of Roof:					
Roofing Material:					
Roof Features					
Power Source					
Traverse:					
Entrance To:					
Elevation North:					
Elevation East:					
Elevation South:					
Elevation West:					

430A

Number/ SS Number	430A	Old Series:			NGR:	TQ38209981
Name/Function:						Condition
Name / Func		Start Da	te:	End Date:		Good
Electric Tractor Charging	House	1917				Fair
						Demolished
						Unknown
Contact Prints	_					
Photography						
Cartographic depiction:						
Date: Cartograph 1923 WASC 900/84	ic Depiction:	\Box				
Documentary References						
	cumentary Re	ference:		Year:		
WASC 1508 (sup) Historical Photographs:				1910		
Relationship with other M	lonuments:					
Artefacts						
General Description:						
Length: 0	Breadth:	0	Height:	0		
Shape in Plan						
Number of Storeys:						
Building Material:						
Bonding Type:						
Form of Roof:						
Roofing Material:						
Roof Features						
Power Source						
Traverse:						
Entrance To:						
Elevation North:						
Elevation East:						
Elevation South:						
Elevation West:						
Overall Internal Description						

431

Number/ SS Number	431	Old Series:		NGR:	TQ38209980
Name/Function:					Condition
Name / Fund	tion	Start Date:	End Date:		Good
Paint Store		1888 1923			⊠ Fair
raint Store		1020			Demolished
					Unknown
Contact Prints					
	_				
Photography					
Cartographic depiction:	ia Daniatiana	\neg			
Date: Cartograph 1923 WASC 900/84	ic Depiction: 4 (paint store)	-			
1907 WASC 900/62	2A				
1888 WASC 900/38	3				
Documentary References	: :				
	ocumentary Re	ference:	Year: 1910		
WASC 1508			1910		
Historical Photographs:					
Relationship with other N	Monuments:	Subsumed into G431			
Artefacts					
General Description:					
Length: 0	Breadth:	O Height:	0		
Shape in Plan					
Number of Storeys:					
Building Material:					
Bonding Type:					
Form of Roof:					
Roofing Material:					
Roof Features					
Power Source					
Traverse:					
Entrance To:					
Elevation North:					
Elevation East:					
Elevation South:					
Elevation West:					

431A

ROYAL GUNPOWDER FACTORY SOUTH SITE

Number/ SS Number	431A	Old Series:			NGR:	TQ3820	09980
Name/Function:						Conditi	on
Name / Func	tion	Start D	ate:	End Date:			Good
G.C. Foreman's Office		1923					Fair
							Demolished
						\boxtimes	Unknown
Contact Prints							
Photography							
Cartographic depiction:							
	ic Depiction:						
1923 WASC 900/84		in					
1888 WASC 900/38							
Documentary References		farancai		Voor			
SUPP/5/327	cumentary Re	rerence:		Year:			
Historical Photographs:							
Relationship with other M	Ionuments:						
Artefacts							
General Description:							
Length: 0	Breadth:	0	Height:	0			
Shape in Plan	Didutiii						
Number of Storeys:							
Building Material:							
Bonding Type:							
Form of Roof:							
Roofing Material:							
Roof Features							
Power Source							
Traverse:							
Entrance To:							
Elevation North:							
Elevation East:							
Elevation South:							
Elevation West:							

Interpretation of phasing

Rooms Detail:

Other:

432

Number/ SS Number	432	Old Series:			NGR:	TQ3824	19984
Name/Function:		,				Conditi	on
Name / Fund	ction	Start Da	te:	End Date:			Good
Cover for Nitre Cake		1905					Fair
							Demolished
							Unknown
Contact Prints							
Photography							
Cartographic depiction:							
Date: Cartograph 1923 WASC 900/8	hic Depiction:						
1907 WASC 900/6							
Documentary Reference	s:						
	ocumentary Re	ference:		Year:			
WASC 1508 N-B 50				1910 1938			
Historical Photographs:							
Relationship with other I	Monuments:						
Artefacts							
General Description:							
Length: 0	Breadth:	0	Height:	0			
	Dieautii.	0	Tieight.	O			
Shape in Plan							
Number of Storeys:					-		
Building Material:							
Bonding Type:							
Form of Roof:							
Roofing Material:							
Roof Features							
Power Source							
Traverse:							
Entrance To:							
Elevation North:							
Elevation East:							
Elevation South:							
Elevation West:							

433

Number/ SS Number	433	Old Series:		NGR:	TQ38329985
Name/Function:					Condition
Name / Fund	etion	Start Date:	End Date:		Good
Boiler/ pump house Demolished		1904 by 1976	still present 1923		Fair
Demonstred		by 1970			Demolished
					Unknown
Contact Prints					
Photography					
Cartographic depiction:					
	nic Depiction:				
1908 WASC 900/62 1923 WASC 900/84					
1976 WASC 900/1					
Documentary References):				
	ocumentary Ref	erence:	Year:		
WASC 1508			1910		
Historical Photographs:					
Relationship with other N	/lonuments:				
Artefacts					
General Description:					
Length: 0	Breadth:	O Hei	ght: 0		
	Dioddin				
Shape in Plan					
Number of Storeys:					
Building Material:					
Bonding Type:					
Form of Roof:					
Roofing Material:					
Roof Features					
Power Source					
Traverse:					
Entrance To:					
Elevation North:					
Elevation East:					
Elevation South:					
Elevation West:					

434

Number/ SS Number	434	Old Series:			NGR:	TQ38309984
Name/Function:		1				Condition
Name / Func		Start Dat	e:	End Date:		Good
Chimney (overlain by G4	40)	1904				Fair
						Demolished
						Unknown
Contact Prints						
Photography						
Cartographic depiction:						
	ic Depiction:					
1923 WASC 900/84 1907 WASC 900/62		_				
Documentary References	: cumentary Re	farancai		Year:		
WASC 1508	cumentary Re	rerence:		1910		
N-B 50				1938		
Historical Photographs:						
Relationship with other M	lonuments:					
Artefacts						
General Description:						
Length: 0	Breadth:	0	Height:	0		
Shape in Plan						
Number of Storeys:						
Building Material:						
Bonding Type:						
Form of Roof:						
Roofing Material:						
Roof Features						
Power Source						
Traverse:						
Entrance To:						
Elevation North:						
Elevation East:						
Elevation South:						

434A

ROYAL GUNPOWDER FACTORY SOUTH SITE

Number/ SS Number	434A	Old Series:			NGR:	TQ3827	9982
Name/Function:						Condition	on
Name / Func	tion	Start Da	te:	End Date:			Good
Motor House		1918					Fair Demolished Unknown
Contact Prints							
Photography							
Cartographic depiction:							
	ic Depiction: 1 (motorhouse)						
Documentary References	:						
	ocumentary Re	ference:		Year: 1910			
WASC 1508 (sup) N-B 50				1938			
Historical Photographs:							
Relationship with other N	flonuments:						
Artefacts							
General Description:							
Length: 0	Breadth:	0	Height:	0			
Shape in Plan							
Number of Storeys:							
Building Material:							
Bonding Type:							
Form of Roof:							
Roofing Material:							
Roof Features							
Power Source							
Traverse:							
Entrance To:							
Elevation North:							
Elevation East:							
Elevation South:							
Elevation West:							

434B

ROYAL GUNPOWDER FACTORY SOUTH SITE

Number/ SS Number	434B	Old Series:			NGR:	TQ38279982
Name/Function:		_				Condition
Name / Funct		Start Da	te:	End Date:		Good
Nitre Cake Crusher (Plant	:)					Fair Demolished Unknown
Contact Prints	_					
Photography						
Cartographic depiction:						
Date: Cartograph 1923 WASC 900/84	ic Depiction: - (nitre cake c	:r				
Documentary References	:					
	cumentary R	eference:		Year:		
WASC 1508 NB-50				1910 1938		
Historical Photographs:						
Relationship with other M	lonuments:					
Artefacts						
General Description:						
Length: 0	Breadth:	0	Height:	0		
Shape in Plan						
Number of Storeys:						
Building Material:						
Bonding Type:						
Form of Roof:						
Roofing Material:						
Roof Features						
Power Source						
Traverse:						
Entrance To:						
Elevation North:						
Elevation East:						
Elevation South:						
Elevation West:						
Overall Internal Description)					

- - -

435

Number/ SS Number	435	Old Series:			NGR:	TQ38359987
Name/Function:						Condition
Name / Fund	tion	Start Dat	te:	End Date:		Good
Sulphuric Acid Concentr	ation	1904-5				☐ Fair
						Demolished
						Unknown
Contact Prints						
_	-			-		
Photography						
Cartographic depiction:						
	ic Depiction:					
1923 WASC 900/84 1907 WASC 900/63						
Documentary References		foronooi		Year:		
WASC 1508	ocumentary Re	rerence:		1910		
N-B 50				1938		
Historical Photographs:						
Relationship with other N	/lonuments:					
Artefacts						
General Description:						
Length: 0	Breadth:	0	Height:	0		
Shape in Plan						
Number of Storeys:						
Building Material:						
Bonding Type:						
Form of Roof:						
Roofing Material:						
Roof Features						
Power Source						
Traverse:						
Entrance To:						
Elevation North:						
Elevation East:						
Elevation South:						
Elevation West:						

Number/ SS Number	435A	Old Series:			NGR:	TQ38359987
Name/Function:		1				Condition
Name / Funct	tion	Start Dat	te:	End Date:		Good
Drum shed		1903-4				Fair Demolished Unknown
Contact Prints						
Photography						
Cartographic depiction:						
Date:Cartographi1923WASC 900/84	c Depiction: (Drum Shed)					
Documentary References						
	cumentary Re	ference:		Year:	_	
WASC 1508 N-B 50				1910 1938	-	
Historical Photographs:						
Relationship with other M	onuments:					
Artefacts						
General Description:						
Length: 0	Breadth:	0	Height:	0		
Shape in Plan						
Number of Storeys:						
Building Material:						
Bonding Type:						
Form of Roof:						
Roofing Material:						
Roof Features				e .		
Power Source						
Traverse:						
Entrance To:						
Elevation North:						
Elevation East:						
Elevation South:						
Flevation West:						

436

Number/ SS Number	436	Old Series:			NGR:	TQ38339984
Name/Function:						Condition
Name / Func		Start Date:	End	d Date:		Good
Nitric Acid Concentration	1	1904-5				☐ Fair
						Demolished
						Unknown
Contact Prints						
	-					
Photography						
Cartographic depiction:						
	ic Depiction:					
1922 WASC 900/84 1907 WASC 900/62						
Documentary References						
	ocumentary Re	eference:		Year:		
WASC 1508				1910		
N-B 50				1938	-	
Lileterie el Direte manha						
Historical Photographs:						
Relationship with other M	lonuments:					
Artefacts						
General Description:						
Length: 0	Breadth:	0 He	eight: 0			
Shape in Plan						
Number of Storeys:						
Building Material:						
-						
Bonding Type:						
Form of Roof:						
Roofing Material:						
Roof Features						
Power Source						
Traverse:						
Entrance To:						
Elevation North:						
Elevation East:						
Elevation South:						
Flevation West:						

436A

Number/ SS Number	436A	Old Series:		NGR:	TQ38369984
Name/Function:		_			Condition
Name / Fur		Start Date:	End Date:		Good
Nitric Acid Concentration	on	1915	1940 (demolished)		Fair Demolished Unknown
Contact Prints					
Photography					
Cartographic depiction:					
	ohic Depiction: 34 (nitric acid c	00			
Documentary Reference	es:				
	Documentary R	eference:	Year:		
WASC 1508 (sup) N-B 50 RGPF RDX Quin	ton Hill, note:'	Demolished'	1938		
Historical Photographs:					
Relationship with other	Monuments:				
Artefacts					
General Description:					
Length: 0	Breadth:	O Hei	ight: 0		
Shape in Plan					
Number of Storeys:					
Building Material:					
Bonding Type:					
Form of Roof:					
Roofing Material:					
Roof Features					
Power Source					
Traverse:					
Entrance To:					
Elevation North:					
Elevation East:					
Elevation South:					
Elevation West:					

437

Number/ SS Number	437	Old Series:		NGR:	TQ38349983
Name/Function:					Condition
Name / Func	tion	Start Date:	End Date:	•	Good
Contact Prints		1904-5			Fair Demolished Unknown
Photography					
Cartographic depiction:					
Date: Cartograph 1923 WASC 900/84	ic Depiction:				
1907 WASC 900/62					
Documentary References	:				
Do	cumentary R	eference:	Year:		
WASC 1508			1910 1938	_	
N-B 50			1938		
Historical Photographs:					
Relationship with other M	ionuments:				
Artefacts					
General Description:					
Length: 0	Breadth:	0 Heigh	t: 0		
Shape in Plan					
Number of Storeys:					
Building Material:					
Bonding Type:					
Form of Roof:					
Roofing Material:					
Roof Features					
Power Source					
Traverse:					
Entrance To:					
Elevation North:					
Elevation East:					
Elevation South:					
Flevation West:					

437A

Number/ SS Number	437A	Old Series:		N	IGR:	TQ38369984
Name/Function:						Condition
Name / Fur	nction	Start Date		End Date:		Good
Acid Tower		1918	by 197:	3		Fair Demolished
						Unknown
Contact Prints						
		10				
Photography						
Cartographic depiction:						
	hic Depiction: 84 (acid tower	(d				
Documentary Reference	es:					
	Documentary R	eference:		Year:		
WASC 1508 (sup) N-B 50				1910 1938		
Historical Photographs:						
Relationship with other	Monuments:					
Artefacts						
General Description:						
Length: 0	Breadth:	0	Height: 0			
Shape in Plan						
Number of Storeys:						
Building Material:						
Bonding Type:						
Form of Roof:						
Roofing Material:						
Roof Features						
Power Source						
Traverse:						
Entrance To:						
Elevation North:						
Elevation East:						
Elevation South:						
Elevation West:						

437B

ROYAL GUNPOWDER FACTORY SOUTH SITE

Number/ SS Number	437B	Old Series:			NGR:	TQ43789984
Name/Function:		1				Condition
Name / Fund	tion	Start Date:		nd Date:		Good
Acid Tower		1910 (not finis	ne by 1917			Fair Demolished Unknown
Contact Prints						
Photography						
Cartographic depiction:						
	nic Depiction: 4 (acid tower (d				
Documentary References	»:					
WASC 1508	ocumentary Re	ference:		Year: 1910	+	
WA3C 1908				1310		
Historical Photographs:						
Relationship with other N	/lonuments:					
Artefacts						
General Description:						
Length: 0	Breadth:	0 He	eight: 0			
Shape in Plan						
Number of Storeys:						
Building Material:						
Bonding Type:						
Form of Roof:						
Roofing Material:						
Roof Features						
Power Source						
Traverse:						
Entrance To:						
Elevation North:						
Elevation East:						
Elevation South:						
Elevation West:						

438

ROYAL GUNPOWDER FACTORY SOUTH SITE

Number/ SS Number	438	Old Series:			NGR:	TQ38499987
Name/Function:		ı				Condition
Name / Func	tion	Start Da	te:	End Date:		Good
Cycle Shed		1905		1938		Fair
						Demolished
						=
						Unknown
Contact Prints						
Photography		ja .				
Cartographic depiction:						
	ic Depiction:					
1923 WASC 900/84						
Documentary References	:					
	cumentary Re	ference:		Year	:	
WASC 1508				1910		
N-B 50 RGPF RDX Quinto	n Hill			1938		
Historical Photographs:						
Relationship with other M	lonuments:					
Artefacts						
General Description:						
Length: 0	Breadth:	0	Height:	0		
Shape in Plan						
Number of Storeys:						
Building Material:						
Bonding Type:						
Form of Roof:						
Roofing Material:						
Roof Features						
Power Source						
Traverse:						
Entrance To:						
Littrance 10.						
Elevation North:						
Elevation East:						
Elevation South:						
Elevation West:						

438A

Number/ SS Number	438A	Old Series:			NGR:	TQ38519987
Name/Function:		1				Condition
Name / Func	tion	Start Date	e:	End Date:		Good
Cycle shed		1915	by	1938		☐ Fair
						Demolished
						Unknown
Contact Prints						
Photography						
Cartographic depiction:						
	ic Depiction:					
1923 WASC 900/84						
1907 WASC 900/62	.A					
Documentary References						
WASC 1508 (sup)	cumentary Re	ference:		Year: 1910	-	
N-B 50 RGPF RDX, Quint	on Hill, 1938			1938		
Historical Photographs:						
Relationship with other M	lonuments:					
Artefacts						
General Description:						
Length: 0	Breadth:	0	Height:	0		
	Dicadii.		Tioighti	U		
Shape in Plan						
Number of Storeys:						
Building Material:						
Bonding Type:						
Form of Roof:						
Roofing Material:						
Roof Features						
Power Source						
Traverse:						
Entrance To:						
17						
Elevation North:						
Elevation East:						
Elevation South:						
Elevation West:						

438B

ROYAL GUNPOWDER FACTORY SOUTH SITE

Number/ SS Number	438B	Old Series:			NGR:	TQ3853	39987
Name/Function:						Conditi	on
Name / Fun	ction	Start Dat		End Date:			Good
Ticket Station		1916	192	23-4			Fair
						\boxtimes	Demolished
							Unknown
Contact Prints							
_							
Photography							
Cartographic depiction: Date: Cartograp	hic Depiction:	П					
	4 (ticket station	n					
Documentary Reference	s:						
	ocumentary Re	ference:		Year	:		
WASC 1508				1910			
Historical Photographs:							
Relationship with other	Monuments:						
Artefacts							
General Description:							
Length: 0	Breadth:	0	Height:	0			
Shape in Plan							
Number of Storeys:							
Building Material:							
Bonding Type:							
Form of Roof:		(
Roofing Material:							
Roof Features							
Power Source							
Traverse:							
Entrance To:							
Elevation North:							
Elevation East:							
Elevation South:							
Elevation West:							

439

Number/ SS Number	439	Old Series:		NGR:	TQ38549987
Name/Function:					Condition
Name / Fund	ction	Start Date:	End Date:		Good
Police Hut		1889 (re-erected			☐ Fair
					Demolished
					Unknown
Contact Prints					
Photography					
Cartographic depiction:					
	nic Depiction:				
1923 WASC 900/8 1907 WASC 900/6					
Documentary References	s: ocumentary F	Reference:	Year:		
WASC 1508	ocumentary r	tererence.	1910		
N-B 50 RGPF RDX Quint	on Hill		1938		
Historical Photographs:					
Relationship with other M	Monuments:				
Artefacts					
General Description:					
Length: 0	Breadth:	0 Height	: 0		
Shape in Plan					
Number of Storeys:					
Building Material:					
Bonding Type:					
Form of Roof:					
Roofing Material:					
Roof Features					
Power Source					
Traverse:					
Entrance To:					
Elevation North:					
Elevation East:					
Elevation South:					
Flevation West:					

439A

ROYAL GUNPOWDER FACTORY SOUTH SITE

Number/ SS Number	439A	Old Series:			NGR:	TQ38549986
Name/Function:						Condition
Name / Func	tion	Start Dat	te:	End Date:		Good
Gas Meter House		1907-8				Fair Demolished Unknown
Contact Prints						
Photography						
Cartographic depiction:						
Documentary References	:					
	cumentary Re	ference:		Year:		
WASC 1508	un Liill			1910	-	
N-B 50 RGPF RDX Quinto	on mili			1938		
Historical Photographs:						
Relationship with other M	lonuments:					
Artefacts						
General Description:						
Length: 0	Breadth:	0	Height:	0		
Shape in Plan	Diodatiii		Tiolgilli			
Number of Storeys:						
Building Material:						
Bonding Type:						
Form of Roof:						
Roofing Material:						
Roof Features						
Power Source						
Traverse:						
Entrance To:						
Littratice 10.						
Elevation North:						
Elevation East:						
Elevation South:						
Elevation West:						

439B

Number/ SS Number	439B	Old Series:			NGR:	TQ38539986
Name/Function:						Condition
Name / Fund	tion	Start Date:	En	d Date:		Good
Time Keepers Office		1916	1923-4			Fair Demolished Unknown
Contact Prints						
Photography						
Cartographic depiction:						
Documentary References		· ·				
WASC 1508 (sup)	ocumentary Re	eference:		Year: 1910	\dashv	
N-B 50 RGPF RDX Quint	on Hill			1938		
Historical Photographs:						
Relationship with other N	lonuments:					
Artefacts						
General Description:						
Length: 0	Breadth:	О Н	eight: 0			
Shape in Plan						
Number of Storeys:						
Building Material:						
Bonding Type:						
Form of Roof:						
Roofing Material:						
Roof Features						
Power Source						
Traverse:						
Entrance To:						
Elevation North:						
Elevation East:						
Elevation South:						
Elevation West:						
Overall Internal Description)					

439C

ROYAL GUNPOWDER FACTORY SOUTH SITE

Number/ SS Number	439C	Old Series:		NGR:	TQ38539988
Name/Function:					Condition
Name / Func	tion	Start Date			Good
Shelter		1917	1923-4		☐ Fair
					Demolished
					Unknown
Contact Prints					
_	-		-		
Photography					
Cartographic depiction:					
	ic Depiction:	\Box			
	(shelter (dem				
Documentary References					
WASC 1508 (sup)	cumentary Ref	erence:	Year: 1910	-	
N-B 50, RGPF, RDX, Quir	nton Hill		1938		
Historical Photographs:					
Relationship with other M	lonuments:				
Artefacts					
General Description:					
Length: 0	Breadth:	0 H	leight: 0		
Shape in Plan					
Number of Storeys:					
Building Material:					
Bonding Type:					
Form of Roof:					
Roofing Material:					
Roof Features					
Power Source					
Traverse:					
Entrance To:					
Elevation North:					
Elevation East:					
Elevation South:					
Elevation West:					

440

Number/ SS Number	440	Old Series:			NGR:	TQ38469986	7
Name/Function:		J				Condition	_
Name / Fund	tion	Start Da	ite:	End Date:		Good	
Petrol Shed		1914				Fair Demolished Unknown	
Contact Prints	-						
							·
Photography							
1923 WASC 900/84 Documentary References	nic Depiction: 4 (petrol shed) s: ocumentary Re	ference		Year:			
WASC 1508 (sup)	Jeumentary Re	referice.		Tear.			
Historical Photographs:							
Relationship with other N	/lonuments:	Number also	used for OI	d Farmhouse [SS	131]		
Artefacts							
General Description:							
Length: 0	Breadth:	0	Height:	0			
Shape in Plan							
Number of Storeys:							
Building Material:							
Bonding Type:							
Form of Roof:							
Roofing Material:							
Roof Features							
Power Source							
Traverse:							
Entrance To:							
Elevation North:							
Elevation East:							
Elevation South:							
Elevation West:							
Overall Internal Description)						

440B

ROYAL GUNPOWDER FACTORY SOUTH SITE

Number/ SS Number	440B	Old Series:			NGR:	TQ38449983
Name/Function:						Condition
Name / Funct	tion	Start Date	:	End Date:		Good
Cotton Waste Store		by 1923	den	nolished c1940		Fair
						Demolished
						Unknown
Contact Prints						
		_				
Photography						
Cartographic depiction:						
Date: Cartographi	c Depiction:	П				
1923 WASC 900/84						
Documentary References:	9					
	cumentary Ref	erence:		Year: 1910		
WASC 1680 N- B50				1910		
Historical Photographs:						
Relationship with other M	onumente					
	onuments.					
Artefacts						
General Description:						
Length: 0	Breadth:	0 H	leight:	0		
Shape in Plan						
Number of Storeys:						
Building Material:					-	
Bonding Type:						
Form of Roof:						
Roofing Material:						
Roof Features						
Power Source						
Traverse:						
Entrance To:						
Littratice 10.						
Elevation North:						
Elevation East:						
Elevation South:						
Elevation West:						

ROYAL GUNPOWDER FACTORY SOUTH SITE

Number/ SS Number	440C	Old Series:			NGR:	TQ3836	9981
Name/Function:						Condition	on
Name / Func	tion	Start Da	ite:	End Date:			Good
Nitrate of Soda Store		1918					Fair Demolished Unknown
Contact Prints							
Photography							
Cartographic depiction:							
Date: Cartograph 1923 WASC 900/84	ic Depiction:						
Documentary References	:						
	cumentary Re	ference:		Year:			
WASC 1680 (nitrate of s	oda store)			1910			
Historical Photographs:							
Relationship with other N	lonuments:						
Artefacts							
General Description:							
Length: 0	Breadth:	0	Height:	0			
Shape in Plan							
Number of Storeys:							
Building Material:							
Bonding Type:							
Form of Roof:							
Roofing Material:							
Roof Features							
Power Source							
Traverse:							
Entrance To:							
Elevation North:							
Elevation East:							
Elevation South:							
Elevation West:							

442

Number/ SS Number	442	Old Series:		NGR:	TQ38259978
Name/Function:					Condition
Name / Fund	ction	Start Date:	End Date:		☐ Good
Washing House		1888			☐ Fair
Guncotton Shifting Room	n	by 1897			Demolished
[extended]		1904			Unknown
Contact Prints	_				
Photography					
Cartographic depiction:					
	nic Depiction	<u>ı:</u>			
1897 OS map (shift					
1907 WASC 900/63 1923 WASC 900/84					
1888 WASC 900/3					
Documentary References					
	ocumentary	Reference:	Year:		
Sandhurst (shifting room			1894		
WASC 1680 (shifting roo	om)		1910	_	
WASC 1508 N-B 50			1910 1938	-	
SUPP/5/327			1936		
Historical Photographs:					
Relationship with other N	/lonuments:				
Artefacts	nonuments.				
General Description:					
ength: 0	Breadth	n: 0 Height	t: 0		
Shape in Plan					
Number of Storeys:					
Building Material:					
Bonding Type:					
Form of Roof:					
Roofing Material:					
Roof Features					
Power Source					
Traverse:					
Entrance To:					
Elevation North:					
Hovation Fast:					

443

Number/ SS Number	443	Old Series:			NGR:	TQ38239977
Name/Function:						Condition
Name / Func	tion	Start Dat	e: Ei	nd Date:		Good
Guncotton Dining Room (extended)		1888 1903				☐ Fair
(extended)		1000				Demolished
						Unknown
Contact Prints						
	_					
Photography						•
Cartographic depiction:						
	ic Depiction:					
1923 WASC 900/84	dining room					
1907 WASC 900/62		om				
1897 OS map (dining						
Documentary References						
Sandhurst (dining room)	cumentary R	ererence:		Year: 1894	-	
WASC 1508 (dining room				1910		
WASC 1680 (dining room N-B 50	1)			1910 1938	+	
SUPP/5/327				,,,,,,		
Historical Photographs:						
Relationship with other M	Ionuments:					
Artefacts						
General Description:						
Length: 0	Breadth:	0	Height: 0			
Shape in Plan						
Number of Storeys:						
Building Material:						
Bonding Type:						
Form of Roof:						
Roofing Material:						
Roof Features						
Power Source						
Traverse:		,				
Entrance To:						
Elevation North:						
Elevation East:						

443A

ROYAL GUNPOWDER FACTORY SOUTH SITE

Number/ SS Number	443A	Old Series:			NGR:	TQ38239977
Name/Function:						Condition
Name / Func	tion	Start Da	ate:	End Date:		Good
Dining Room, Guncotton,		1915				Fair
						Demolished
						Unknown
Contact Prints						
	-			-		
Photography						
Cartographic depiction:						
	ic Depiction:					
1923 WASC 900/84	(Dining Room	1)				
Documentary References:	:					
	cumentary Re			Year:		
WASC 1680, Supp (dining N-B 50	g room G.C. e	xtension)		1910 1938	-	
Historical Photographs:				1,000		
Relationship with other M	onumenter					
	onuments.					
Artefacts						
General Description:						
Length: 0	Breadth:	0	Height:	0		
Shape in Plan						
Number of Storeys:						
Building Material:						
Bonding Type:						
Form of Roof:						
Roofing Material:						
Roof Features						
Power Source						
Traverse:						
Entrance To:						
Elevation North:						
Elevation East:						
Elevation South:						
Elevation West:						

444B

Number/ SS Number	444B	Old Series:		NGR:	TQ38249984
Name/Function:					Condition
Name / Fun	ction	Start Date:	End Date:		Good
Smiths shop Office		post-1910, by 19 1961?		-	
					Demolished
					Unknown
Contact Prints					
					-
Photography					
Cartographic depiction:					
	hic Depiction:				
	4 (smiths sho	0)			
Documentary Reference	s:				
	ocumentary R	eference:	Year: 1961		
G432 B.05, conversion	piaris		1901		
Historical Photographs:					
Relationship with other l	Monuments:	subsumed into G432			
Artefacts					
General Description:					
Length: 0	Breadth:	O Height:	0		
Shape in Plan					
Number of Storeys:					
Building Material:					
Bonding Type:					
Form of Roof:					
Roofing Material:					
Roof Features					
Power Source					
Traverse:					
Entrance To:					
Elevation North:					
Elevation East:					
Elevation South:					
Elevation West:					
Overall Internal Description	0				

444C

ROYAL GUNPOWDER FACTORY SOUTH SITE

Number/ SS Number	444C	Old Series:			NGR:	TQ38239979
Name/Function:						Condition
Name / Func	tion	Start Da	ite:	End Date:		Good
Ticket Station		1923				Fair
		part 1910				☐ Demolished
Contact Prints						Unknown
	-					
Photography						
Cartographic depiction:						
	ic Depiction:	П				
	1 (ticket station	n				
Documentary References	::					
Historical Photographs:						
Relationship with other N	fonuments:					
Artefacts						
General Description:						
Length: 0	Breadth:	0	Height:	0		
Shape in Plan						
Number of Storeys:						*
Building Material:						
Bonding Type:						
Form of Roof:						
Roofing Material:						
Roof Features						
Power Source						
Traverse:						
Entrance To:						
Elevation North:						
Elevation East:						
Elevation South:						
Elevation West:						
Overall Internal Description						

Interpretation of phasing

445

Number/ 33 Number	445	Old Series:		NGR:	TQ38189975
Name/Function:					Condition
Name / Fur	nction	Start Date:	End Date:		Good
Lavatory		1888			Fair
					Demolished
					Unknown
Contact Prints					
			-		
Photography					
Cartographic depiction:					
	hic Depiction				
1923 WASC 900/8 1907 WASC 900/8					
1897 OS map (E.C					
Documentary Reference	es:				
	Ocumentary I	Reference:	Year:		
WASC 1680 (E.C.) WASC 1508			1910 1910	-	
Relationship with other Artefacts	Monuments:				
General Description:					
Length: 0	Breadth	. O Heimbe	. 0		
	breadin	: 0 Height	: 0		
Shape in Plan					
Number of Storeys:					
Building Material:					
Bonding Type:					
Form of Roof:					
Roofing Material:					
Roof Features					
Power Source					
Traverse:					
Entrance To:					
Elevation North:					
Elevation East:					
Elevation South:					
Elevation West:					

448

Number/ SS Number	448	Old Series:		NGR:	TQ38179976
Name/Function:					Condition
Name / Func	tion	Start Date:	End Date:		Good
Hose House		1902			☐ Fair
Electric Spares Store		by 1923			Demolished
					Unknown
Contact Prints					
Photography					
Cartographic depiction:					
	ic Depiction:				
1907 WASC 900/62 1923 WASC 900/84					
Documentary References		 L.1			
	cumentary Re	ference:	Year:		
WASC 1680 WASC 1508			1910 1910	-	
Historical Photographs:					
Relationship with other M	onuments:	Attached to G424 [44	7]		
Artefacts					
General Description:					
Length: 0	Breadth:	O Height:	0		
Shape in Plan					
Number of Storeys:					
Building Material:					
Bonding Type:					
Form of Roof:					
Roofing Material:					
Roof Features					
Power Source					
Traverse:					
Entrance To:					
Elevation North:					
Elevation East:					
Elevation South:					
Flevation West					

449

ROYAL GUNPOWDER FACTORY SOUTH SITE

Number/ SS Number	449	Old Series:			NGR:	TQ38139974
Name/Function:						Condition
Name / Func	tion	Start Dat	e:	End Date:		Good
Lavatory		by 1907				Fair
						Demolished
						Unknown
Contact Prints						
Photography						
Cartographic depiction:						
	nic Depiction:					
1907 WASC 900/62 1923 WASC 900/84		-				
Documentary References						
Historical Photographs:						
Relationship with other N	/lonuments:					
Artefacts						
General Description:						
Length: 0	Breadth:	0	Height:	0		
Shape in Plan						
Number of Storeys:						
Building Material:						
Bonding Type:						
Form of Roof:						
Roofing Material:						
Roof Features						
Power Source						
Traverse:						
Entrance To:						
Elevation North:						
Elevation East:						
Elevation South:						
Elevation West:						
Overall Internal Description	o					

Interpretation of phasing

449A

Number/ SS Number	449A	Old Series:			NGR:	TQ38119975
Name/Function:						Condition
Name / Fund	tion	Start Da	ite:	End Date:		Good
Box House		1915				☐ Fair
						Demolished
						Unknown
Contact Prints						
	-					
Photography						
Cartographic depiction:						
	ic Depiction:					
1923 WASC 900/84	1 (box house)					
Documentary References						
WASC 1680, SUPP. (box	chouse)	terence:		Year: 1910		
Historical Photographs:						
Relationship with other M	lonuments:					
Artefacts						
General Description:						
Length: 0	Breadth:	0	Height:	0		
Shape in Plan						
Number of Storeys:						
Building Material:						
Bonding Type:						
Form of Roof:						
Roofing Material:						
Roof Features						
Power Source						
Traverse:						
Entrance To:						
Elevation North:						
Elevation East:						
Elevation South:						
Elevation West:						
Overall Internal Description)					

450

Number/ SS Number	450	Old Series:			NGR:	TQ38099976
Name/Function:						Condition
Name / Func	tion	Start Dat	te:	End Date:		Good
Wet Guncotton Packing		1902				Fair
						☐ Demolished
						Unknown
Contact Prints						
Photography						
Cartographic depiction:						
	ic Depiction:					
1923 WASC 900/84	1 (wet guncott					
1907 WASC 900/62	2A (packing ho					
Documentary References						
WASC 1680 (packing ho	ocumentary Re	ference:		Year: 1910		
WASC 1680 (packing no	use)			1910		
Historical Photographs:						
Relationship with other M	fonuments:					
Artefacts						
General Description:						
Length: 0	Breadth:	0	Height:	0		
Shape in Plan						
Number of Storeys:						
Building Material:						
Bonding Type:						
Form of Roof:						
Roofing Material:						
Roof Features						
Power Source						
Traverse:						
Entrance To:						
Elevation North:						
Elevation East:						
Elevation South:						
Flevation West:						

450A

Number/ SS Number	450A	Old Series:			NGR:	TQ38109977	
Name/Function:						Condition	
Name / Funct	tion	Start Da	ite:	End Date:		Good	
Guncotton Press House		1915				Fair Demolished Unknown	ĺ
Contact Prints							
Photography							
Cartographic depiction: Date: Cartographi 1923 WASC 900/84 Documentary References:		7					
	cumentary Ref	ference:		Year:			
WASC 1680, Supp. (gund				1910			
Historical Photographs:							
Relationship with other M	onuments:						
Artefacts							
General Description:							
Length: 0	Breadth:	0	Height:	0			
Shape in Plan							
Number of Storeys:							
Building Material:							
Bonding Type:							
Form of Roof:							
Roofing Material:							
Roof Features							7
Power Source							_
Traverse:							
Entrance To:							
Elevation North:							
Elevation East:							
Elevation South:							
Elevation West:							
Overall Internal Descriptio							

451

Number/ SS Number	451	Old Series:			NGR:	TQ3809	99975
Name/Function:						Conditi	on
Name / Func	tion	Start Date	:	End Date:			Good
Soldering House		1902					Fair
							Demolished
						Ш	Unknown
Contact Prints							
	_						
Photography							
Cartographic depiction:							
	ic Depiction:	П					
1908 WASC 900/62	.A						
1923 WASC 900/84							
Documentary References		.					
WASC 1680 (soldering ho	cumentary Re	rerence:		Year: 1910	\dashv		
WASC 1508				1910			
Historical Photographs:							
Relationship with other M	lonuments:						
Artefacts							
General Description:							
Length: 0	Breadth:	0 F	leight: 0				
			_				
Shape in Plan							
Shape in Plan Number of Storeys:							
Shape in Plan Number of Storeys: Building Material:							
Shape in Plan Number of Storeys: Building Material: Bonding Type:							
Shape in Plan Number of Storeys: Building Material: Bonding Type: Form of Roof:							
Shape in Plan Number of Storeys: Building Material: Bonding Type: Form of Roof: Roofing Material:							
Shape in Plan Number of Storeys: Building Material: Bonding Type: Form of Roof: Roofing Material: Roof Features							
Shape in Plan Number of Storeys: Building Material: Bonding Type: Form of Roof: Roofing Material: Roof Features Power Source							
Shape in Plan Number of Storeys: Building Material: Bonding Type: Form of Roof: Roofing Material: Roof Features Power Source Traverse:							
Shape in Plan Number of Storeys: Building Material: Bonding Type: Form of Roof: Roofing Material: Roof Features Power Source							
Shape in Plan Number of Storeys: Building Material: Bonding Type: Form of Roof: Roofing Material: Roof Features Power Source Traverse:							
Shape in Plan Number of Storeys: Building Material: Bonding Type: Form of Roof: Roofing Material: Roof Features Power Source Traverse: Entrance To: Elevation North:							
Shape in Plan Number of Storeys: Building Material: Bonding Type: Form of Roof: Roofing Material: Roof Features Power Source Traverse: Entrance To:							

451A

ROYAL GUNPOWDER FACTORY SOUTH SITE

Number/ SS Number	451A	Old Series:			NGR:	TQ38079976
Name/Function:						Condition
Name / Funct		Start Dat	e: E	nd Date:		Good
Fire Engine and Hose Hou	Jse	1915				Fair Demolished Unknown
Contact Prints						
Photography						
Cartographic depiction:						
Date: Cartographi 1923 WASC 900/84	c Depiction:	n				
Documentary References:						
	cumentary Re			Year:		
WASC 1680, Supp. (fire 6) WASC 1508	engine and ho	se house)		1910 1910		
Historical Photographs:						
Relationship with other M	onuments:					
Artefacts						
General Description:						
Length: 0	Breadth:	0	Height: 0			
Shape in Plan						
Number of Storeys:						
Building Material:						
Bonding Type:						
Form of Roof:						
Roofing Material:						
Roof Features						
Power Source						
Traverse:						
Entrance To:						
Elevation North:						
Elevation East:						
Elevation South:						
Elevation West:						

453

Number/ SS Number	453	Old Series:			NGR:	TQ38109973
Name/Function:		_				Condition
Name / Func	tion	Start Da		End Date:		Good
Cycle Shed		1904	by	1923		☐ Fair
						Demolished
						Unknown
Contact Prints						
	. –					
Photography						
Cartographic depiction:						
	ic Depiction:					
1908 WASC 900/62	?A					
1923 WASC 900/84						
Documentary References						
WASC 1680 (cycle shed)	cumentary R	eference:		Year: 1910		
WASC 1660 (cycle siled) WASC 1508				1910		
Historical Photographs:						
Relationship with other M	lonuments:					
	ionamonto					
Artefacts						
General Description:						
Length: 0	Breadth:	0	Height:	0		
Shape in Plan						
Number of Storeys:						
Building Material:						
Bonding Type:						
Form of Roof:						
Roofing Material:						
Roof Features						
Power Source						
Traverse:						
Entrance To:						
Elevation North:						
Elevation East:						
Elevation South:						
Elevation West:						

Number/ SS Number	453A	Old Series:	was 453	3	NGR:	TQ3810	09973
Name/Function:						Conditi	on
Name / Fui		Start D	ate:	End Date:			Good
Foreman's Dining Roor	n	by 1908					Fair
							Demolished
						Ш	Unknown
Contact Prints							
Photography							
Cartographic depiction:							
	ohic Depiction:						
1908 WASC 900/ 1923 WASC 900/	62A; No. 453 84						
Documentary Reference							
Historical Photographs:							
Relationship with other	Monuments:						
Artefacts							
General Description:							
Length: 0	Breadth:	0	Height:	0			
Shape in Plan							
Number of Storeys:							
Building Material:							
Bonding Type:							
Form of Roof:							
Roofing Material:							
Roof Features							
Power Source							
Traverse:							
Entrance To:							
Elevation North:							
Elevation East:							
Elevation South:							
Elevation West:							
Overall Internal Descrip	tio						
	pest						

Interpretation of phasing

454

ROYAL GUNPOWDER FACTORY SOUTH SITE

Number/ SS Number	454	Old Series:			NGR:	TQ38109973
Name/Function:		_				Condition
Name / Fun	ction	Start Dat	e:	End Date:		Good
Office and Laboratory		1904				Fair
						Demolished
						Unknown
Contact Prints						
Contact Prints				-		
Photography						
Cartographic depiction:						
	hic Depiction	:]				
1907 WASC 900/6						
1923 WASC 900/8						
Documentary Reference						
WASC 1680	Documentary I	Reference:		Year: 1910	-	
				1,01,0		
Historical Photographs:						
Relationship with other	Monuments:					
Artefacts						
General Description:						
Length: 0	Breadth	: 0	Height:	0		
Shape in Plan						
Number of Storeys:						
Building Material:						
Bonding Type:						
Form of Roof:						
Roofing Material:						
Roof Features						
Power Source						
Traverse:						
Entrance To:						
Elevation North:						
Elevation East:						
Elevation South:						
Elevation West:						

Number/ SS Number	455	Old Series:			NGR:	TQ38139973
Name/Function:						Condition
Name / Funct	ion	Start Dat	te:	End Date:		Good
Contact Prints						Fair Demolished Unknown
Photography						
Cartographic depiction:	B 1.11					
Date: Cartographi 1907 WASC 900/62	c Depiction:	-				
1923 WASC 900/84						
Documentary References:						
	cumentary Re	ference:		Year:		
WASC 1680 WASC 1764				1910 1910	-	
Historical Photographs:						
Relationship with other M	onumenter					
Artefacts	onuments.					
General Description:	*.					
Length: 0	Breadth:	0	Height:	0		x .
Shape in Plan						
Number of Storeys:						
Building Material:						
Bonding Type:						
Form of Roof:						
Roofing Material:						
Roof Features						
Power Source						
Traverse:						
Entrance To:						
2						
Elevation North:						
Elevation East:						
Elevation South:						
Elevation West:						

455A

Number/ SS Number	455A	Old Series:			NGR:	TQ38129972
Name/Function:						Condition
Name / Fund	tion	Start Dat	te:	End Date:		Good
Drying Room		1916				Fair Demolished Unknown
Contact Prints	_					
Photography						
Cartographic depiction:						
	nic Depiction:					
Documentary References						
WASC 1680	ocumentary Re	ference:		Year: 1910		
Historical Photographs:						
Relationship with other M	/lonuments:					
Artefacts						
General Description:						
Length: 0	Breadth:	0	Height:	0		
Shape in Plan						
Number of Storeys:						
Building Material:						
Bonding Type:						
Form of Roof:						El .
Roofing Material:						
Roof Features						
Power Source						
Traverse:						
Entrance To:						
Elevation North:						
Elevation East:						
Elevation South:						
Elevation West:						
Overall Internal Description)					

455B

ROYAL GUNPOWDER FACTORY SOUTH SITE

Number/ SS Number	455B	Old Series:			NGR:	TQ38129972
Name/Function:		,				Condition
Name / Fund	ction	Start Da	ate:	End Date:		Good
Cloak Drying Room		1916				Fair
B.W.D Office				***		Demolished
						Unknown
Contact Prints						
	_					
Photography						
Cartographic depiction:						
	hic Depiction:					
1923 WASC 900/8	4					
Documentary References	s:					
	ocumentary Re	ference:		Year:		
WASC 1680				1910		
Historical Photographs:						
Relationship with other N	Vionuments:					
Artefacts						
General Description:						
Length: 0	Breadth:	0	Height:	0		
Shape in Plan						
Number of Storeys:						
Building Material:						
Bonding Type:						
Form of Roof:						
Roofing Material:						
Roof Features						
Power Source						
Traverse:						
Entrance To:						
Elevation North:						
Elevation East:						
Elevation South:						
Elevation West:						

455G

ROYAL GUNPOWDER FACTORY SOUTH SITE

Number/ SS Number	455G	Old Series:			NGR:	TQ38259974
Name/Function:						Condition
Name / Func	tion	Start Da	ite:	End Date:		Good
B.W.D Workshop		1917				Fair Demolished Unknown
Contact Prints						
Photography						
Cartographic depiction:						
	ic Depiction:					
Documentary References		•		. Varia		
WASC 1680	cumentary Re	rerence:		Year: 1910	-	
Historical Photographs:				'		
Relationship with other N	lonuments:					
Artefacts						
General Description:						
Length: 0	Breadth:	0	Height:	0		
Shape in Plan						
Number of Storeys:						
Building Material:						
Bonding Type:						
Form of Roof:						
Roofing Material:						
Roof Features						
Power Source						
Traverse:						
Entrance To:						
Elevation North:						
Elevation East:						
Elevation South:						
Elevation West:						

455H

ROYAL GUNPOWDER FACTORY SOUTH SITE

Number/ SS Number	455H	Old Series:			NGR:	TQ38259974
Name/Function:						Condition
Name / Func	tion	Start Da	ite:	End Date:		Good
B.W.D Office		1917				Fair
						□ Demolished
						Unknown
Contact Prints						
Photography						
Cartographic depiction:						
Date: Cartographi 1923 WASC 900/84	ic Depiction:	-				
Documentary References						
Do	cumentary Re	ference:		Year:		
WASC 1680				1910		
Historical Photographs:						
Relationship with other M	lonuments:					
Artefacts						
General Description:						
Length: 0	Breadth:	0	Height:	0		
Shape in Plan						
Number of Storeys:						
Building Material:						
Bonding Type:						
Form of Roof:						
Roofing Material:						
Roof Features						
Power Source						
Traverse:						
Entrance To:						
Elevation North:						
Elevation East:						
Elevation South:						
Elevation West:						

Interpretation of phasing

Rooms Detail:

Other:

456

ROYAL GUNPOWDER FACTORY SOUTH SITE

Number/ SS Number	456	Old Series:		NGR:	TQ38149973
Name/Function:		,			Condition
Name / Fund	tion	Start Date	: End Date	:	Good
Shed		1904	1905-6		Fair Demolished Unknown
Contact Prints					
Photography					
Cartographic depiction:					
Documentary References					
WASC 1704 (shed)	ocumentary Re	ference:	1910	ar:	
WASC 1704 (shed)			1910		
WASC 1508			1910		
Historical Photographs:					
Relationship with other N	Monuments:				
Artefacts					
General Description:					
Length: 0	Breadth:	0	Height: 0		
Shape in Plan					
Number of Storeys:					
Building Material:					
Bonding Type:					
Form of Roof:					
Roofing Material:					
Roof Features					
Power Source					
Traverse:					
Entrance To:					
Elevation North:					
Elevation East:					
Elevation South:					
Elevation West:					

458

ROYAL GUNPOWDER FACTORY SOUTH SITE

Number/ SS Number	458	Old Series:		NGR:	TQ38099969
Name/Function:					Condition
Name / Func	tion	Start Date:	End Date:		Good
Earth Closet		1904	by 1976		☐ Fair
					Demolished
					Unknown
Contact Prints					
_					
Photography					
Cartographic depiction:					
Date: Cartograph 1923 WASC 900/84	ic Depiction:	_			
1976 WASC 900/11					
Documentary References					
	cumentary Re	ference:	Year:		
WASC 1508	ournormary mo	101011001	1910		
Historical Photographs:					
Relationship with other N	ionuments:				
Artefacts					
General Description:					
Length: 0	Breadth:	O Hei	ght: 0		
Shape in Plan]		
Number of Storeys:					
Building Material:					
Bonding Type:					
Form of Roof:					
Roofing Material:					
Roof Features					
Power Source					
Traverse:					
Entrance To:					
Entrance 10.					
Elevation North:					
Elevation East:					
Liovation Last.					
Elevation South:					
Elevation West:					

Number/ SS Number	459	Old Series:		NGR:	TQ38079968
Name/Function:					Condition
Name / Fun	ction	Start Date:	End Date:		Good
Gun cotton stove (expe		1888	by 1908		Fair
Gun cotton store		by 1908	still present 1923		Demolished
Demolished		by 1976			Unknown
Contact Prints					
Photography					
Cartographic depiction:					
	hic Depiction:	_			
1897 OS 1908 WASC 900/6	32A; Guncotton				
	34; Guncotton S				
1976 WASC 900/1	13				
Documentary Reference	s:				
	ocumentary Re	eference:	Year:		
WASC 1508 Sandhurst; Drying House			1910 1894		
Historical Photographs:	2		1004		
Relationship with other	Monuments:				
Artefacts					
General Description:					
Length: 0	Breadth:	O Heig	ght: 0		
Shape in Plan					
Number of Storeys:					
Building Material:					
Bonding Type:					
Form of Roof:					
Roofing Material:					
Roof Features					
Power Source					
Traverse:					
Entrance To:					
Elevation North:					
Elevation East:					
Elevation South:					
Elevation West:					

Number/ SS Number	460A	Old Series:		NGR:	ΤΩ37879967
Name/Function:					Condition
Name / Funct		Start Dat			Good
Dry guncotton yarn store Demolished		1917 by 1976	still present 1923		Fair
Demonstred		by 1370			Demolished
					Unknown
Contact Prints					
Contact Prints				-	
Photography					
Cartographic depiction: Date: Cartographi	c Depiction:	П			
1923 WASC 900/84					
1976 WASC 900/11	3				
Documentary References:					
	cumentary Ref	erence:	Year:		
WASC 1508			1910		
Historical Photographs:					
Relationship with other M	onuments:				
Artefacts					
General Description:					
Length: 0	Breadth:	0	Height: 0		
Shape in Plan					
Number of Storeys:					
Building Material:					
Bonding Type:					
Form of Roof:					
Roofing Material:					
Roof Features					
Power Source					
Traverse:					
Entrance To:					
Elevation North:					
Elevation East:					
Elevation South:					
Elevation West:					

461

ROYAL GUNPOWDER FACTORY SOUTH SITE

Number/ SS Number	461	Old Series:			NGR:	TQ37809969
Name/Function:						Condition
Name / Func	tion	Start Da	te:	End Date:		Good
Guncotton Stove No.3 Guncotton Stove No.16		pre 1908 by 1908		post 1923		☐ Fair
Contact Prints		lov 1000		post 1920		☑ Demolished☑ Unknown
Photography						
Cartographic depiction:						
Documentary References	:					
Historical Photographs:						
Relationship with other M	lonuments:					
Artefacts						
General Description:						
Length: 0	Breadth:	0	Heigh	t: 0		
Shape in Plan						
Number of Storeys:						
Building Material:						
Bonding Type:						
Form of Roof:						
Roofing Material:						
Roof Features						
Power Source						
Traverse:						
Entrance To:						
Elevation North:						
Elevation East:						
Elevation South:						
Elevation West:						
Overall Internal Descriptio						

Interpretation of phasing

Number 33 Number	462	Old Series:		NGR:	TQ37799969
Name/Function:					Condition
Name / Fund		Start Date:	End Date:		Good
Engine House to Guncot	ton Stove No.3	1894/5	by 1976		Fair Demolished Unknown
Contact Prints			-		<u></u>
Photography					
Cartographic depiction:		-			
	nic Depiction:				
1897 O/S Map 1908 WASC 900/6	2A				
1923 WASC 900/8	4				
1976 WASC 900/1	13				
Documentary References					
Sandhurst De	ocumentary Ref	erence:	Yea 1894	r:	
Historical Photographs:					
Relationship with other N	/lonuments:				
Artefacts					
General Description:					
Length: 0	Breadth:	O Heig	ght: 0		
Shape in Plan					
Number of Storeys:					
Building Material:					
Bonding Type:					
Form of Roof:					
Roofing Material:					
Roof Features					
Power Source					
Traverse:					
Entrance To:					
Elevation North:					
Elevation East:					
Elevation South:					
Flevation West:					

Number/ SS Number	462A	Old Series:			NGR:	TQ37709972
Name/Function:		J				Condition
Name / Func	tion	Start Da	ite:	End Date:		Good
Well		by 1923		present		Fair Demolished Unknown
Contact Prints						
Photography	Tune	Cubinet	Direction	Evn No.		
Film Number: Film none	туре	Subject:	Direction	n Exp No:		
Cartographic depiction:						
Date: Cartograph 1923 WASC 900/84 1976 WASC 900/11						
Documentary References	:					
Historical Photographs:						
Relationship with other M	fonuments:	462A is locat	ed to the no	orth of M317		
Artefacts						
General Description:		circular, brick			d half in	concrete and half in
Length: 32	Breadth:	3.2	Height:			
Shape in Plan	circular					
Number of Storeys:						
Building Material:	red brick					
Bonding Type:	?					
Form of Roof:	N/A					
Roofing Material:						
Roof Features						
Power Source	Water					
Traverse:	none					
Entrance To:						
Elevation North:						
Elevation East:						
Elevation South:						
Elevation West:						

Number/ SS Number	463	Old Series:		NGR:	TQ37969965
Name/Function:					Condition
Name / Fun	oction	Start Date:	End Date:		Good
Engine House		1894	still present 1923		☐ Fair
Demolished		1971			☐ Demolished
					Unknown
Contact Prints	_		_		
Photography					
Cartographic depiction:					
	hic Depiction	:			
1897 O/S Map 1908 WASC 900/6	62A				
1923 WASC 900/8	34				
1976 WASC 900/1	113				
Documentary Reference					
	Documentary	Reference:	Year:		
WASC 1508 Sandhurst			1910 1894		
C 1988 BPB012			1988		
Historical Photographs:					
Relationship with other	Monuments:				
Artefacts					
General Description:					
Length: 0	Breadth	: O He	eight: 0		
Shape in Plan					
Number of Storeys:					
Building Material:					
Bonding Type:					
Form of Roof:					
Roofing Material:					
Roof Features					
Power Source					
Traverse:					
Entrance To:					
Elevation North:					
Elevation East:					
Elevation South:					

Number/ SS Number	464A	Old Series:		NGR:	TQ37979967
Name/Function:					Condition
Name / Fund	etion	Start Date:	End Date:		Good
Reservoir/cooling tray Demolished		1912 by 1963	by 1963		Fair
Demonshed		by 1903			Demolished
					Unknown
Contact Prints					
Photography					
Cartographic depiction:					
	nic Depiction:				
1923 WASC 900/8	4				
1976 WASC 900/1					
Documentary References			V		
WASC 1508	ocumentary Re	rerence:	Year: 1910		
Historical Photographs:					
Relationship with other M	Monuments:				
Artefacts					
General Description:					
Length: 0	Breadth:	0 He	ight: 0		
Shape in Plan]		
Number of Storeys:					
Building Material:					
Bonding Type:					
Form of Roof:					
Roofing Material:					
Roof Features					
Power Source					
Traverse:					
Entrance To:					
Elevation North:					
Elevation East:					
Elevation South:					
Elevation West:					
cievation west:					

Shape in Plan Number of Storeys: Building Material: Bonding Type: Form of Roof: Roofing Material: Roof Features Power Source Traverse: Entrance To: Elevation North: Elevation South:	Number/ SS Number	464B	Old Series:			NGR:	TQ37969967
Name / Function	Name/Function:						Condition
Demolished by 1976		ction					
Contact Prints Photography Cartographic depiction: Date: Cartographic Depiction: 1923 WASC 900/84 1976 WASC 900/113 Documentary References: Documentary References: WASC 1506/1 1972 Historical Photographs: Relationship with other Monuments: Artefacts General Description: Length: O Breadth: O Height: O Shape in Plan Number of Storeys: Bullding Material: Bonding Type: Form of Roof: Roofing Material: Roof Features Power Source Traverse: Entrance To: Elevation North: Elevation North: Elevation South:			- AASSO 1 15	by1	976		☐ Fair
Contact Prints Photography Cartographic depiction: Date: Cartographic Depiction: 1923 WASC 900/84 1976 WASC 900/113 Documentary References: Year: WASC 1506/1 1972 Historical Photographs: Relationship with other Monuments: Artefacts General Description: Length: O Breadth: O Height: O Shape in Plan Number of Storeys: Building Material: Bonding Type: Form of Roof: Roofing Material: Roof Features Power Source Traverse: Elevation North: Elevation South:	Demonshed		by 1970				Demolished
Photography Cartographic depiction: Date: Cartographic Depiction: 1923 WASC 900/84 1976 WASC 900/13 Documentary References: Documentary Reference: Year: WASC 1506/1 1972 Historical Photographs: Relationship with other Monuments: Artefacts General Description: Length: O Breadth: O Height: O Shape in Plan Number of Storeys: Building Material: Bonding Type: Form of Roof: Roofing Material: Roof Features Power Source Traverse: Elevation North: Elevation North: Elevation East: Elevation South:							Unknown
Photography Cartographic depiction: Date: Cartographic Depiction: 1923 WASC 900/84 1976 WASC 900/13 Documentary References: Documentary Reference: Year: WASC 1506/1 1972 Historical Photographs: Relationship with other Monuments: Artefacts General Description: Length: O Breadth: O Height: O Shape in Plan Number of Storeys: Building Material: Bonding Type: Form of Roof: Roofing Material: Roof Features Power Source Traverse: Elevation North: Elevation North: Elevation East: Elevation South:	Contact Prints						
Cartographic depiction: Date: Cartographic Depiction: 1923							
Cartographic depiction: Date: Cartographic Depiction: 1923							
Cartographic depiction: Date: Cartographic Depiction: 1923							
Cartographic depiction: Date: Cartographic Depiction: 1923							
Cartographic depiction: Date: Cartographic Depiction: 1923							
Cartographic depiction: Date: Cartographic Depiction: 1923							
Cartographic depiction: Date: Cartographic Depiction: 1923							
Date:	Photography						
Date:	Cartographic depiction:						
1976 WASC 900/113 Documentary References: Documentary Reference: Year:		nic Depiction:					
Documentary References: Documentary Reference: Year:	1923 WASC 900/8	4					
Documentary Reference: Year: WASC 1506/1 1972 Historical Photographs: Relationship with other Monuments: Artefacts General Description: Length: O Breadth: O Height: O Shape in Plan Number of Storeys: Building Material: Bonding Type: Form of Roof: Roofing Material: Roof Features Power Source Traverse: Entrance To: Elevation North: Elevation South:	1976 WASC 900/1	13					
WASC 1506/1 1972 Historical Photographs: Relationship with other Monuments: Artefacts General Description: Length: O Breadth: O Height: O Shape in Plan Number of Storeys: Building Material: Bonding Type: Form of Roof: Roofing Material: Roof Features Power Source Traverse: Entrance To: Elevation North: Elevation South:							
Historical Photographs: Relationship with other Monuments: Artefacts General Description: Length: O Breadth: O Height: O Shape in Plan Number of Storeys: Building Material: Bonding Type: Form of Roof: Roofing Material: Roof Features Power Source Traverse: Entrance To: Elevation North: Elevation South:		ocumentary Re	ference:			-	
Relationship with other Monuments: Artefacts General Description: Length: O Breadth: O Height: O Shape in Plan Number of Storeys: Building Material: Bonding Type: Form of Roof: Roofing Material: Roof Features Power Source Traverse: Entrance To: Elevation North: Elevation South:							
Artefacts General Description: Length: O Breadth: O Height: O Shape in Plan Number of Storeys: Building Material: Bonding Type: Form of Roof: Roofing Material: Roof Features Power Source Traverse: Entrance To: Elevation North: Elevation South:							
General Description: Length: O Breadth: O Height: O Shape in Plan Number of Storeys: Building Material: Bonding Type: Form of Roof: Roofing Material: Roof Features Power Source Traverse: Entrance To: Elevation North: Elevation South:		vionuments:					
Length: 0 Breadth: 0 Height: 0 Shape in Plan Number of Storeys: Building Material: Bonding Type: Form of Roof: Roofing Material: Roof Features Power Source Traverse: Entrance To: Elevation North: Elevation South:							
Shape in Plan Number of Storeys: Building Material: Bonding Type: Form of Roof: Roofing Material: Roof Features Power Source Traverse: Entrance To: Elevation North: Elevation South:	General Description:						
Number of Storeys: Building Material: Bonding Type: Form of Roof: Roofing Material: Roof Features Power Source Traverse: Entrance To: Elevation North: Elevation South:	Length: 0	Breadth:	0	Height:	0		
Building Material: Bonding Type: Form of Roof: Roofing Material: Roof Features Power Source Traverse: Entrance To: Elevation North: Elevation South:	Shape in Plan						
Bonding Type: Form of Roof: Roofing Material: Roof Features Power Source Traverse: Entrance To: Elevation North: Elevation East: Elevation South:	Number of Storeys:						
Bonding Type: Form of Roof: Roofing Material: Roof Features Power Source Traverse: Entrance To: Elevation North: Elevation East: Elevation South:	Building Material:						
Form of Roof: Roofing Material: Roof Features Power Source Traverse: Entrance To: Elevation North: Elevation East: Elevation South:	Bondina Type:						
Roofing Material: Roof Features Power Source Traverse: Entrance To: Elevation North: Elevation East: Elevation South:							
Roof Features Power Source Traverse: Entrance To: Elevation North: Elevation East: Elevation South:							
Power Source Traverse: Entrance To: Elevation North: Elevation East: Elevation South:							
Traverse: Entrance To: Elevation North: Elevation East: Elevation South:							
Entrance To: Elevation North: Elevation East: Elevation South:							
Elevation North: Elevation East: Elevation South:							
Elevation East: Elevation South:	Entrance To:						
Elevation South:	Elevation North:						
	Elevation East:						
	Elevation South:						
Elevation vvest:	Elevation West:						

466

Number/ SS Number	466	Old Series:		NGR:	TQ37879960
Name/Function:					Condition
Name / Fun	ction	Start Date:	End Date:		Good
Dry Guncotton Packing	House	c1895 (not prese	still present 1923		☐ Fair
Demolished		by 1976			Demolished
					Unknown
Contact Prints					
Photography					
Cartographic depiction:					
	hic Depiction	. 🗇			
Date: Cartograp 1897 O/S Map	nic Depiction	•			
1908 WASC 900/6	62A				
1923 WASC 900/8					
1976 WASC 900/1	13				
Documentary Reference					
	ocumentary	Reference:	Year:		
WASC 1508			1910		
Historical Photographs:					
Relationship with other	Monuments:				
Artefacts					
General Description:					
Length: 0	Breadth	: 0 Heig	ht: 0		
Shape in Plan					
Number of Storeys:					
Building Material:					
Bonding Type:					
Form of Roof:					
Roofing Material:					
Roof Features					
Power Source					
Traverse:					
Entrance To:					
Elevation North:					
Elevation East:					
Elevation South:					
Elevation West:					

Number/ SS Number	468	Old Series:		NGR:	TQ37949962
Name/Function:					Condition
Name / Funct	tion	Start Date:	End Date:		Good
Store Dry Guncotton Stencilling	n House	1887/8 by 1923	by 1923 by 1976		☐ Fair
Dry Gancotton Stenening	g House	by 1925	by 1970		Demolished
					Unknown
O					
Contact Prints	_				
Photography					
Cartographic depiction:					
	c Depiction:	_			
1888 WASC 900/38 1897 O/S Map					
1908 WASC 900/62	Α				
1923 WASC 900/84					
1976 WASC 900/11					
Documentary References:					
	cumentary Re	ference:	Year: 1894	-	
Sandhurst WASC 1508			1910		
Historical Photographs:					
Relationship with other M	onuments:				
Artefacts					
General Description:					
Length: 0	Breadth:	O He	ight: 0		
Shape in Plan					
Number of Storeys:			_		
Building Material:					
Bonding Type:					
Form of Roof:					
Roofing Material:					
Roof Features				-	
Power Source					
Traverse:					
Entrance To:					
Elevation North:					
Elevation East:					
Elevation South:					

468A

ROYAL GUNPOWDER FACTORY SOUTH SITE

Number/ SS Number	468A	Old Series:			NGR:	TQ37959962
Name/Function:						Condition
Name / Func	tion	Start Da		End Date:		Good
Earth Closet, womens'.		by 1897?		by 1976		Fair
						Demolished Unknown
Contact Prints						
Photography						
Cartographic depiction:						
	ic Depiction:	\Box				
1923 WASC 900/84 Documentary References						
Historical Photographs:	•					
Relationship with other M	lonuments:					
Artefacts	ionamonto.					
General Description:						
Length: 0	Breadth:	0	Height	: 0		
Shape in Plan						
Number of Storeys:						
Building Material:						
Bonding Type:						
Form of Roof:						
Roofing Material:						
Roof Features						
Power Source						
Traverse:						
Entrance To:						
Elevation North:						
Elevation East:						
Elevation South:						
Elevation West:						
Overall Internal Descriptio						

Interpretation of phasing

471

Number/ SS Number	471	Old Series:		NGR:	TQ37939961
Name/Function:					Condition
Name / Fun	ction	Start Date:	End Date:		Good
Gun Shed		1887/8	by 1923		
Guncotton water proofi	ing shed	by 1923			Fair
Demolished		1970			Demolished
Contact Prints					Unknown
Photography					
Cartographic depiction:					
	hic Depiction:				
1888 WASC 900/3 1897 O/S Map	88; Gun shed				
1908 WASC 900/6	32A				
1923 WASC 900/8					
Documentary Reference	s:				
	ocumentary F	Reference:	Year:		
Sandhurst			1894		•
M346 B01-B02 WASC 1680			1887 1910		
Historical Photographs:			110.0		
Relationship with other	Manumantai				
Artefacts	wonuments.				
General Description:					
Length: 0	Breadth:	O Hei	ight: 0		
Shape in Plan					
Number of Storeys:					
Building Material:					
Bonding Type:					
Form of Roof:					
Roofing Material:					
Roof Features					
Power Source					
Traverse:					
Entrance To:					
Elevation North:					
Elevation East:					
Elevation South:					

Number/ SS Number	471A	Old Series:		NGR:	TQ37919961?
Name/Function:					Condition
Name / Fun	ction	Start Date:	: End Date:		Good
Store to north of 471.		by 1894	by 1897		Fair
Magazine Demolished		by 1897 by 1908	by 1908		Demolished
Demolished		by 1908			Unknown
Contact Prints					
Photography					
Cartographic depiction:					
	hic Depiction:				
1897 O/S Map					
1908 WASC 900/6	52A				
Documentary Reference	s:				
	ocumentary Ro	eference:	Year:		
Sandhurst			1894		
Historical Photographs:					
Relationship with other	Monuments:				
Artefacts					
General Description:					
Length: 0	Breadth:	О Н	leight: 0		
Shape in Plan					
Number of Storeys:			_		
Building Material:					
Bonding Type:					
Form of Roof:					
Roofing Material:					
Roof Features					
Power Source					
Traverse:					
Entrance To:					
Elevation North:					
Elevation East:					
Elevation South:					
Elevation West:					

472

Number/ SS Number	472	Old Series:		NGR:	TQ37979960
Name/Function:					Condition
Name / F	unction	Start Date:	End Date:		Good
Cell		1887/8	Disused but still pre	sent	☐ Fair
					Demolished
					Unknown
0					
Contact Prints					
Photography					
Cartographic depiction	on:				
	raphic Depiction	:			
1888 WASC 90	0/38; Cell				
1897 O/S Map 1908 WASC 90	0/62A				
1923 WASC 90					
Documentary Referen	nces:				
	Documentary I	Reference:	Year:		
Sandhurst WASC 1680			1894 1910		
			1,010		
Historical Photograph					
Relationship with oth	er Monuments:				
Artefacts					
General Description:					
Length: 0	Breadth	: 0 He	ight: 0		
Shape in Plan					
Number of Storeys:					
Building Material:					
Bonding Type:					
Form of Roof:					
Roofing Material:					
Roof Features					
Power Source					
Traverse:					
Entrance To:					
Elevation North:					
Elevation East:					
Elevation South:					
Elevation South:					
cievation west:					

472A

ROYAL GUNPOWDER FACTORY SOUTH SITE

Number/ SS Number	472A	Old Series:		NGR:	TQ38039960
Name/Function:					Condition
Name / Fun	ction	Start Date:	End Date:		Good
Guncotton Yarn Drying	Stove	1916/7	still present 1923		☐ Fair
Demolished		by 1976			☐ Demolished
					Unknown
Contact Prints					
Photography					
Cartographic depiction:					
Date: Cartograp 1923 WASC 900/8	hic Depiction:				
1976 WASC 900/1					
Documentary Reference	es:				
	ocumentary R	eference:	Year:		
WASC 1508			1910		
Historical Photographs:					
Relationship with other	Monuments:				
Artefacts					
General Description:					
Length: 0	Breadth:	O Heig	ght: 0		
	breautii.	O Heij	giit. O		
Shape in Plan					
Number of Storeys:					
Building Material:					
Bonding Type:					
Form of Roof:					
Roofing Material:					
Roof Features					
Power Source					
Traverse:					
Entrance To:					
zmianos roi					
Elevation North:					
Elevation East:					
Elevation South:					
Elevation West:					
Lievation West:					

472B

ROYAL GUNPOWDER FACTORY SOUTH SITE

Number/ SS Number	472B	Old Series:		NGR:	TQ38039960
Name/Function:					Condition
Name / Fun		Start Date:	End Date:		Good
Guncotton yarn drying s Demolished	stove	1916/7 by 1976	still present 1923		Fair
Demonstred		ру 1370			Demolished
					Unknown
Contact Prints					
Photography					
Cartographic depiction:					
	hic Depiction:				
1926 WASC 900/8 1976 WASC 900/1					
Documentary Reference					
D	ocumentary Re	ference:	Year:		
WASC 1508			1910		
Historical Photographs:					
Relationship with other l	Monuments:				
Artefacts					
General Description:					
Length: 0	Breadth:	0 He	eight: 0		
Shape in Plan					
Number of Storeys:					
Building Material:					
Bonding Type:					
Form of Roof:					
Roofing Material:					
Roof Features					
Power Source					
Traverse:					
Entrance To:					
Elevation North:					
Elevation East:					
Elevation South:					
Elevation West:					

472C

ROYAL GUNPOWDER FACTORY SOUTH SITE

Number/ SS Number	472C	Old Series:		NGR:	TQ38039960			
Name/Function:					Condition			
Name / Fund		Start Date:	End Date:		Good			
Guncotton yarn drying s Demolished	tove	1916/7	still present 1923		Fair			
Demonstred		by 1976			Demolished			
					Unknown			
Contact Prints								
	_							
Photography								
Cartographic depiction:								
	nic Depiction:	\Box						
1923 WASC 900/8	4							
1976 WASC 900/6	2A							
Documentary References								
WASC 1508	ocumentary Re	ference:	Year: 1910	-				
Historical Photographs:								
Relationship with other M	Monuments:							
Artefacts								
General Description:								
Length: 0	Breadth:	0 Heig	ht: 0					
Shape in Plan								
Number of Storeys:								
Building Material:								
Bonding Type:								
Form of Roof:								
Roofing Material:								
Roof Features								
Power Source								
Traverse:								
Entrance To:								
Elevation North:								
Elevation East:								
Elevation South:								
Elevation West:								

472D

ROYAL GUNPOWDER FACTORY SOUTH SITE

Number/ SS Number	472D	Old Series:			NGR:	TQ38039960
Name/Function:						11. Sec. 201. Co. C.
Name / Func	tion	Start Dat	·	End Date:		Condition
Guncotton yarn drying s		1916/7		present 1923		Good
Demolished		by 1976				☐ Fair
						Demolished
						Unknown
Contact Prints						
_	_					
		×				
Photography						
Cartographic depiction:						
	nic Depiction:					
1923 WASC 900/84 1976 WASC 900/1						
Documentary References						
WASC 1508	ocumentary R	eference:		1910	-	
Historical Photographs:						
Relationship with other N	flonuments:					
Artefacts						
General Description:						
	B 10					
Length: 0	Breadth:	0	Height:	0		
Shape in Plan						
Number of Storeys:						
Building Material:						
Bonding Type:						
Form of Roof:						
Roofing Material:						
Roof Features						
Power Source						
Traverse:						
Entrance To:						
Entrance 10.						
Elevation North:						
Elevation East:						
Elevation South:						
Elevation West:						

Interpretation of phasing

Rooms Detail:

Other:

Number/ SS Number	472E	Old Series:		NGR:	TQ38039960
Name/Function:					Condition
Name / Fun		Start Date:	End Date:		Good
Guncotton yarn drying s	stove	1916/7	still present 1923		Fair
Demollished		by 1976			Demolished
					Unknown
Contact Prints					
	_				
Photography					
Cartographic depiction:					
	hic Depiction:				
1923 WASC 900/8	4				
1976 WASC 900/1	13				
Documentary Reference	s:				
	ocumentary Re	eference:	Year: 1910		
WASC 1508			1910		
Historical Photographs:					
Relationship with other I	Vionuments:				
Artefacts					
General Description:					
Length: 0	Breadth:	0 Hei	ght: 0		
Shape in Plan					
Number of Storeys:					
Building Material:					
Bonding Type:					
Form of Roof:					
Roofing Material:					
Roof Features					
Power Source					
Traverse:					
Entrance To:					
Elevation North:					
Elevation East:					
Elevation South:					
Elevation West:					

472É

ROYAL GUNPOWDER FACTORY SOUTH SITE

Number/ SS Number	472F	Old Series:		NGR:	TQ38039960
Name/Function:					Condition
Name / Funct	ion	Start Date:	End Date:		Good
Guncotton yarn drying st	ove	1916/7	still present 1923		☐ Fair
Demolished		by 1976			□ Demolished
					Unknown
Contact Prints					
Photography					
Cartographic depiction:					
Date: Cartographi 1923 WASC 900/84 1976 WASC 900/11					
Documentary References:					
	cumentary Ref	erence:	Year:		
WASC 1508			1910		
Historical Photographs:					
Relationship with other M	onuments:				
Artefacts					
General Description:					
Length: 0	Breadth:	0 Hei	ght: 0		
Shape in Plan					
Number of Storeys:					
Building Material:					
Bonding Type:					
Form of Roof:					
Roofing Material:					
Roof Features					
Power Source					
Traverse:					
Entrance To:					
Elevation North:					
Elevation East:					
Elevation South:					
Elevation West:					
Liovation woot.					

472G

ROYAL GUNPOWDER FACTORY SOUTH SITE

Number/ SS Number	472G	Old Series:		NGR:	TQ38039960
Name/Function:					Condition
Name / Func	tion	Start Date:	End Date:		Good
Guncotton yarn drying st	ove	1916/7	still present 1923		☐ Fair
Demolished		by 1976			Demolished
Contact Prints	_				Unknown
Photography					
Cartographic depiction:					
	ic Depiction:				
1923 WASC 900/84	•				
1976 WASC 900/11	3				
Documentary References	:				
Do	cumentary Re	ference:	Year:		
WASC 1508			1910		
Historical Photographs:					
Relationship with other M	lonuments:				
Artefacts					
General Description:					
Length: 0	Breadth:	0 Hei	ght: 0		
Shape in Plan]		
Number of Storeys:			_		
Building Material:					
Bonding Type:					
Form of Roof:					
Roofing Material:					
Roof Features					
Power Source					
Traverse:					
Entrance To:					
Elevation North:					
Elevation East:					
Elevation South:					
Elevation West:					

473

ROYAL GUNPOWDER FACTORY SOUTH SITE

Number/ SS Number	473	Old Series:			NGR:	TQ37939954
, L	170					
Name/Function: Name / Funct	ion	Stort Do	to.	End Date:		Condition
Shed	.1011	Start Da 1890		End Date: 1923		Good
						Fair Demolished
						Unknown
						OHRHOWN
Contact Prints						
Photography						
Cartographic depiction:						
	c Depiction:					
1897 O/S Map 1908 WASC 900/62	A	-				
1923 WASC 900/84						
Documentary References:						
WASC 1508	cumentary Ref	ference:		Year: 1910	+	
Historical Photographs:				11313		
Relationship with other M	onuments:					
Artefacts						
General Description:						
Length: 0	Breadth:	0	Height:	0		
Shape in Plan						
Number of Storeys:						
Building Material:						
Bonding Type:						
Form of Roof:						
Roofing Material:						
Roof Features						
Power Source						
Traverse:						
Entrance To:						
Elevation North:						
Elevation East:						
Elevation South:						

Elevation West:

Name / Function Start Date: End Date: Good	Number/ SS Number	475	Old Series:		NGR:	TQ38319965
After Separating House 1891 1903 Fair Demolished Unknown Demolished Demolished Unknown Demolished Demolished Unknown Demolished Dem	Name/Function:					Condition
Contact Prints Gemol. 1907-8 Pair Demolished Demolished Unknown		tion				Good
Contact Prints Chotography Cartographic depiction: Date: Cartographic Depiction: 1897	After Separating House		1891			Fair
Contact Prints Cartography Cartographic depiction: Date: Cartographic Depiction: Date: Os Mop 1907 WASC 900/62A Documentary Reference: Year: Sandhurst 1894 WASC 1680 1910 Surprise Photographs: Historical Photographs: PRO Supply 5/861 176-177 (1903) Relationship with other Monuments: Artefacts General Description: Length: O Breadth: O Height: O Shape in Plan Sumber of Storeys: Suiding Material: Bonding Type: Form of Roof: Roofing Material: Bonding Type: Form of Roof: Bonding Type: Form of				demoi. 1907-8		Demolished
Photography Cartographic depiction: Date: Cartographic Depiction: 1897						Unknown
Photography Cartographic depiction: Date: Cartographic Depiction: 1897						
Cartographic depiction: Date: Cartographic Depiction: 1897	Contact Prints					
Cartographic depiction: Date: Cartographic Depiction: 1897						
Cartographic depiction: Date: Cartographic Depiction: 1897						
Cartographic depiction: Date: Cartographic Depiction: 1897						
Cartographic depiction: Date: Cartographic Depiction: 1897						
Cartographic depiction: Date: Cartographic Depiction: 1897						
Cartographic depiction: Date: Cartographic Depiction: 1897						
Cartographic depiction: Date: Cartographic Depiction: 1897						
Date: Cartographic Depiction: 1897 0.5 Map 1907 WASC 900/62A Documentary References: Year: Sandhurst 1894 WASC 1680 1910 SUPP/5/327 Historical Photographs: Historical Photographs: PRO Supply 5/861 176-177 (1903) Relationship with other Monuments: Artefacts General Description: Gen	Photography			×		
1997	Cartographic depiction:					
Documentary References: Documentary References: Year:		ic Depiction:				
Documentary References: Documentary References: Year:						
Documentary Reference: Year:	1907 WASC 900/62	!A				
Sandhurst WASC 1680 WASC 1						
WASC 1680 SUPP/5/327 distorical Photographs: Historical Photographs: PRO Supply 5/861 176-177 (1903) Relationship with other Monuments: Artefacts General Description: Length: O Breadth: O Height: O Shape in Plan Sumber of Storeys: Building Material: Bonding Type: Form of Roof: Roofing Material: Roof Features Power Source Fraverse: Entrance To: Elevation North: Elevation East:		cumentary Ref	erence:			
SUPP/5/327 distorical Photographs: Historical Photographs: PRO Supply 5/861 176-177 (1903) Relationship with other Monuments: Artefacts General Description: Length: 0 Breadth: 0 Height: 0 Shape in Plan Shape						
Historical Photographs: PRO Supply 5/861 176-177 (1903) Relationship with other Monuments: Artefacts General Description: Length: O Breadth: O Height: O Shape in Plan Sumber of Storeys: Suilding Material: Bonding Type: Form of Roof: Roofing Material: Roof Features Power Source Traverse: Entrance To: Elevation North: Elevation East:	SUPP/5/327			1010		
Historical Photographs: PRO Supply 5/861 176-177 (1903) Relationship with other Monuments: Artefacts General Description: Length: O Breadth: O Height: O Shape in Plan Sumber of Storeys: Suilding Material: Bonding Type: Form of Roof: Roofing Material: Roof Features Power Source Traverse: Entrance To: Elevation North: Elevation East:	Historical Photographs:					
Relationship with other Monuments: Artefacts General Description: Length: 0		Н	istorical Photograp	phs:		
Artefacts General Description: Length: O	PRO Supply 5/861 176-1	77 (1903)				
General Description: Length: O	Relationship with other M	lonuments:				
Rength: 0 Breadth: 0 Height: 0 Shape in Plan Number of Storeys: Building Material: Bonding Type: Form of Roof: Roofing Material: Roof Features Power Source Traverse: Entrance To: Slevation North: Slevation East:	Artefacts					
Breadth: 0 Height: 0 Shape in Plan Number of Storeys: Building Material: Bonding Type: Form of Roof: Roofing Material: Roof Features Power Source Traverse: Entrance To: Slevation North: Slevation East:	General Description:					
Shape in Plan Number of Storeys: Building Material: Bonding Type: Form of Roof: Broofing Material: Broof Features Power Source Fraverse: Entrance To: Elevation North: Elevation East:	Length: 0	Breadth:	O Heio	aht: 0		
Number of Storeys: Building Material: Bonding Type: Form of Roof: Roofing Material: Roof Features Power Source Traverse: Entrance To: Elevation North:		D. Gudum		5		
Building Material: Bonding Type: Form of Roof: Boofing Material: Broof Features Power Source Fraverse: Entrance To: Elevation North: Elevation East:]		
Bonding Type: Form of Roof: Roofing Material: Roof Features Power Source Traverse: Entrance To: Elevation North: Elevation East:	Number of Storeys:					
Form of Roof: Roofing Material: Roof Features Power Source Traverse: Entrance To: Elevation North:	Building Material:					
Roofing Material: Roof Features Power Source Traverse: Entrance To: Elevation North:	Bonding Type:					
Roofing Material: Roof Features Power Source Traverse: Entrance To: Elevation North:	Form of Roof:					
Power Source Traverse: Entrance To: Elevation North: Elevation East:	Roofing Material:					
Power Source Traverse: Entrance To: Elevation North: Elevation East:	Roof Features					
Traverse: Entrance To: Elevation North: Elevation East:						
Entrance To: Elevation North: Elevation East:						
Elevation North:						
Elevation East:	Entrance To:					
	Elevation North:					
	Elevation East:					
nevation pourts	Elevation South:					

Number/ SS Number	476	Old Series:			NGR:	
Name/Function:		ı				Condition
Name / Func	tion	Start Da	te:	End Date:		Good
Nitrating House No.1		1891	1903			☐ Fair
Nitrating House No.2		1903	1904			Demolished
						Unknown
Occident Drints						
Contact Prints						
Photography						
Cartographic depiction:						
	ic Depiction:					
1897 OS; No.1 Nitra	ating House					
	2A; No.2 Nitra					
	; Nitrating Ho	u				
Documentary References		•				
Sandhurst; Nitrating House	ocumentary Re se No.1	terence:		Year: 1894	\dashv	
PRO Supply 5/						
Historical Photographs:						
Relationship with other M	lonuments:					
Artefacts						
General Description:						
Length: 0	Breadth:	0	Height:)		
Shape in Plan						
Number of Storeys:						
Building Material:						
Bonding Type:						
Form of Roof:						
Roofing Material:						
Roof Features						
Power Source						
Traverse:						
Entrance To:						
Elevation North:						
Elevation East:						
Elevation South:						
Elevation West:						

Number/ SS Number	477	Old Series:		NGR:	TQ38329963
Name/Function:					Condition
Name / Func	tion	Start Date:	End Date:		Good
Nitrating House No.2		1891	1903		Fair
Nitrating House No.3		1903	1903		Demolished
			demol. 1907-8		Unknown
Contact Prints					
	-				
Photography					
Cartographic depiction:					
	ic Depiction:				
1897 O.S; No.2 Nitr	ating House				
1907 WASC 900/62	2A; No.3 Nitr	ati			
Documentary References	:				
	cumentary F	leference:	Year:		
Sandhurst; Nitrating House WASC 1680; Nitrating House		shed 1907-8	1894 1910		
SUPP/5/327	ouse, demon	31104 1007 0	1010		
Historical Photographs:					
Thotorious Friotographics		Historical Photograp	ohs:		
PRO Supply 5/861- 163;		ng House			
PRO Supply 5/861- 174;		ng House			
Relationship with other M	lonuments:				
Artefacts					
General Description:					
Length: 0	Breadth:	O Heig	ght: 0		
Shape in Plan]		
Number of Storeys:			J		
Building Material:					
Bonding Type:					
Form of Roof:					
Roofing Material:					
Roof Features			· · · · · · · · · · · · · · · · · · ·		
Power Source					
Traverse:					
Entrance To:					
Elevation North:					
Elevation East:					

481

Number/ SS Number	481	Old Series:			NGR:	TQ38539958
Name/Function:						Condition
Name / Fur Acetone Store	nction	Start Date: 1892	Er	nd Date:		Good
Acetone Store		1032				Fair Demolished Unknown
Contact Prints						
Photography						
Date: Cartographic depiction: 1897 O.S Map 1907 WASC 900/8 1923 WASC 900/8 Documentary Reference	ohic Depiction: 62A 84					
	Documentary F	Reference:	-	Year:		
Sandhurst WASC 1680 WASC 1764 SUPP/5/327				1894 1910 1910		
Historical Photographs:						
Relationship with other	Monuments:					
Artefacts						
General Description:						
Length: 0	Breadth:	0 He	ight: 0			
Shape in Plan						
Number of Storeys:						
Building Material:						
Bonding Type:						
Form of Roof:						
Roofing Material:						
Roof Features						
Power Source						
Traverse:						
Entrance To:						
Elevation North:						
Elevation East:						
Elevation South:						

482

Number/ SS Number	482	Old Series:			NGR:	TQ38579958
Name/Function:		,				Condition
Name / Func	tion	Start Da		End Date:		Good
Contact Prints		1892	demo	lished by 1970		Fair Demolished Unknown
Photography						
Cartographic depiction:						
Date: Cartograph	ic Depiction:	-				
1907 WASC 900/62	A					
1923 WASC 900/84						
Documentary References	:					
	cumentary Re	ference:		Year:		
Sandhurst WASC 1680				1894 1910	-	
WASC 1680				1910		
SUPP/5/327						
Historical Photographs:						
Relationship with other M	lonuments:					
Artefacts						
General Description:						
Length: 0	Breadth:	0	Height:	0		
Shape in Plan						
Number of Storeys:						
Building Material:						
Bonding Type:						
Form of Roof:						
Roofing Material:						
Roof Features						
Power Source						
Traverse:						
Entrance To:						
Elevation North:						
Elevation East:						
Elevation South:						

484

Number/ SS Number	484	Old Series:			NGR:	TQ38319957
Name/Function:						Condition
Name / Funct	tion	Start Dat	e: En	d Date:		Good
Junction House, Covered		1894	derelict by			
,						☐ Fair
						Demolished
						Unknown
Contact Prints						
Photography						
Cartographic depiction:						
	c Depiction:	\Box				
1897 O.S Map	c Depiction.	-				
1907 WASC 900/62	A					
1923 WASC 900/84						
Documentary References:	:					
Do	cumentary Ref	ference:		Year:		
WASC 1680				1910		
WASC 1764 WASC 901/331				1910 1891		
WASC 901/331				1908		
F.						
Historical Photographs:		listorical Photo	graphs:			
PRO Supply 5/861 (1903)		notorioui i rioto	grupiioi			
PRO Supply 5/861 (1903)						
Relationship with other M	onuments:					
Artefacts						
General Description:						
Length: 0	Breadth:	0	Height: 0			
Shape in Plan						
Number of Storeys:						
Building Material:						
Bonding Type: Form of Roof:						
Roofing Material:						
Roof Features						
Power Source						
Traverse:						
Entrance To:						
Elevation North:						

490

Number/ SS Number	490	Old Series:			NGR:	TQ3814	19953
Name/Function:						Conditi	on
Name / Fund	tion	Start Da	te:	End Date:		Conditi	Good
Lavatory		1893-4					Fair Demolished Unknown
Contact Prints							
Photography							
Cartographic depiction: Date: Cartograph 1907 WASC 900/62 1923 WASC 900/84							
Documentary References	:						
	cumentary Re	ference:		Year:			
Sandhurst WASC 1680				1894 1910			
WASC 1764				1910			
Historical Photographs:							
Relationship with other N	fonuments:						
Artefacts							
General Description:							
Length: 0	Breadth:	0	Height:	0			
Shape in Plan							
Number of Storeys:							
Building Material:							
Bonding Type:							
Form of Roof:							
Roofing Material:							
Roof Features							
Power Source							
Traverse:							
Entrance To:							
Elevation North:							
Elevation East:							
Elevation South:							
Elevation West:							

495

ROYAL GUNPOWDER FACTORY SOUTH SITE

Number/ SS Number 4	95	Old Series:		NGR:	TQ37899947
Name/Function:					Condition
Name / Functio	n	Start Date:	End Date	e:	Good
Engine House		1892	still present 192	23	☐ Fair
Demolished		by 1976			Demolished
					Unknown
Contact Prints					
Photography					
Cartographic depiction:					
Date: Cartographic	Depiction:				
1897 O/S Map					
1908 WASC 900/62A 1923 WASC 900/84		-			
1976 WASC 900/113					
Documentary References:					
	mentary Ref	erence:		ear:	
WASC 1508			1910		
Historical Photographs:					
Relationship with other Mor	numents:	Served M351			
Artefacts Fan machinery (c	orroded)				
General Description:		nery set on a conci	rete and brick plint	th. No roof o	r walls survive.
Length: 3	Breadth:	3 Heig	ght: 0		
			1		
Shape in Plan	Rectangular				
Number of Storeys:					
Building Material:	Concrete, w	vith brickwork surr	round		
Bonding Type:					
Form of Roof:	None surviv	ing			
Roofing Material:					
Roof Features					
Power Source	Electric?				
Traverse:					
Entrance To:					
Littratice to.					
Elevation North:					
Elevation East:					
Elevation South:					

Elevation West:

Overall Internal Descriptio

Interpretation of phasing

Rooms Detail:

Other:

497

Number/ SS Number	497	Old Series:		NGR:	TQ37669948
Name/Function:					Condition
Name / Funct	tion	Start Date:	End Date:		Good
Earth Closet		1903	still present 1923		Fair
Demolished		by 1976			
					Demolished
					Unkňown
Contact Prints					
Photography					
Cartographic depiction:					
	ic Depiction:	\Box			
1908 WASC 900/62	A				
1923 WASC 900/84					
1976 WASC 900/11	3				
Documentary References					
	cumentary Ref	erence:	Year: 1910		
WASC 1508 Historical Photographs:			1910		
Relationship with other M	lonuments:				
Artefacts					
General Description:					
Length: 0	Breadth:	O Hei	ght: 0		
Shape in Plan]		
Number of Storeys:			_		
Building Material:					
Bonding Type:					
Form of Roof:					
Roofing Material:					
Roof Features					
Power Source					
Traverse:					
Entrance To:					
Elevation North:					
Elevation East:					
Elevation South:					
Elevation West:					

498

Number/ SS Number	498	Old Series:		NGR:	TQ37669948
Name/Function:		1			Condition
Name / Funct	tion	Start Date:	End Date:		Good
Switchboard House		1903	by 1908		=
Dynamo House		by 1908	still present 1923		Fair
Demolished		by 1976			Demolished
					Unknown
Contact Prints	_				
Photography					
Cartographic depiction:					
Date: Cartographi	c Depiction:				
1908 WASC 900/62					
1923 WASC 900/84		_			
1976 WASC 900/11	3				
Documentary References:					
	cumentary Re	ference:	Year:		
WASC 1508			1910		
Historical Photographs:					
Relationship with other M	onuments:				
Artefacts					
General Description:					
Length: 0	Breadth:	O Heiç	ght: O		
Shape in Plan					
Number of Storeys:					
Building Material:					
Bonding Type:					
Form of Roof:					
Roofing Material:					
Roof Features					
Power Source					
Traverse:					
Entrance To:					
Entrance 10:					
Elevation North:					
Elevation East:					
Elevation South:					
Elevation West:					
LICVATION VVCSL.					

498A

ROYAL GUNPOWDER FACTORY SOUTH SITE

Number/ SS Number	498A	Old Series:		NGR:	TQ37669948
Name/Function:					Condition
Name / Func	tion	Start Date:	End Date:		Good
Dining Room		1917	still present 1923		Fair
Demolished		by 1976			Demolished
					Unknown
Contact Prints					
		_			
Photography					
Cartographic depiction:					
Date: Cartograph	ic Depiction:				
1976 WASC 900/11		, x			
Documentary References	:				
	cumentary Ref	erence:	Year:		
WASC 1508-sup			1910		
Historical Photographs:					
Relationship with other M	Ionuments:				
Artefacts					
General Description:					
Length: 0	Breadth:	O He	ight: 0		
Shape in Plan					
Number of Storeys:					
Building Material:					
Bonding Type:					
Form of Roof:					
Roofing Material:					
Roof Features					
Power Source					
Traverse:					
Entrance To:					
Elevation North					
Elevation North:					
Elevation East:					
Elevation South:					
Elevation West:					

Number/ SS Number	499	Old Series:			NGR:	TQ37669948
Name/Function:		_				Condition
Name / Fund	tion	Start Da	te:	End Date:		Good
Boiler House		1903	still	present 1923		Fair
Demolished		by 1976				Demolished
						Unknown
Contact Prints						
Photography						
Cartographic depiction:						
Date: Cartograph	nic Depiction:					
1908 WASC 900/6						
1923 WASC 900/8- 1976 WASC 900/1						
Documentary References	s: ocumentary Re	foronoo		Year:		
WASC 1508	ocumentary ne	referice.		1910		
Historical Photographs:						
Relationship with other N	nonuments:					
Artefacts						
General Description:						
Length: 0	Breadth:	0	Height:	0		
Shape in Plan						
Number of Storeys:						
Building Material:						
Bonding Type:						
Form of Roof:						
Roofing Material:						
Roof Features						
Power Source						
Traverse:						
Entrance To:						
Elevation North:						
Elevation East:						
Elevation South:						
Elevation West:						

500

ROYAL GUNPOWDER FACTORY SOUTH SITE

Number/ SS Number	500	Old Series:		NGR:	TQ37669947
Name/Function:					Condition
Name / Fund	tion	Start Date:	End Date:		Good
Economiser and cover Demolished		1903 1976	still present 1923		☐ Fair
		1,5,5			□ Demolished
					Unknown
Contact Prints					
-	_		-		
Photography					
Cartographic depiction:		\Box			
Date: Cartograph	nic Depiction: 2A	-			
1923 WASC 900/84					
1976 WASC 900/1					
Documentary References	s: ocumentary Ref	oronoo	Year:		
WASC 1508	ocumentary nei	erence.	1910		
Historical Photographs:					
Relationship with other N	/lonuments:				
Artefacts					
General Description:					
Length: 0	Breadth:	O Usi	-14.		
	Breadtn:	O Heig	ght: O		
Shape in Plan					
Number of Storeys:					
Building Material:					
Bonding Type:					
Form of Roof:					
Roofing Material:					
Roof Features					
Power Source					
Traverse:					
Entrance To:					
Elevation North:					
Elevation East:					
Elevation South:					

Elevation West:

501

Number/ SS Number	501	Old Series:			NGR:	TQ3766	39947
Name/Function:						Conditi	on
Name / Fun	ction	Start Dat		End Date:			Good
Chimney Demolished		1903 by 1976	sti	II present 1923			Fair
Demonstred		БУ 1370				\boxtimes	Demolished
							Unknown
Contact Prints							
Photography							
Cartographic depiction:							
	hic Depiction:	П					
1908 WASC 900/6	2A						
1923 WASC 900/8 1976 WASC 900/1		-					
Documentary Reference	s: ocumentary Re	forence:		Year:			
WASC 1508	ocumentary ne	referice.		1910			
Historical Photographs:							
Relationship with other I	Monumenter						
	vioriuments.						
Artefacts							
General Description:							
Length: 0	Breadth:	0	Height:	0			
Shape in Plan							
Number of Storeys:							
Building Material:							
Bonding Type:							
Form of Roof:							
Roofing Material:							
Roof Features							
Power Source							
Traverse:							
Entrance To:							
Flourities North							
Elevation North:							
Elevation East:							
Elevation South:						,	
Elevation West:							

Overall Internal Descriptio

Interpretation of phasing

Rooms Detail:

Ofher:

503

Number/ SS Number	503	Old Series:			NGR:	TQ38139945
Name/Function:						Condition
Name / Func	tion	Start Da		End Date:		Good
Weighing House		1894	de	molished 1908-9		Fair
						Demolished
						Unknown
Contact Prints						
Photography						
Cartographic depiction:						
	ic Depiction:					
1897 O.S Map 1907 WASC 900/62	PA	-				
Documentary References						
	cumentary Re	ference:		Year:		
WASC 1680				1910		
WASC 1764				1910		
Historical Photographs:						
Relationship with other M	lonuments:					
Artefacts						
General Description:						
Length: 0	Breadth:	0	Height:	0		
Shape in Plan						
Number of Storeys:						
Building Material:				· · · · · · · · · · · · · · · · · · ·		
Bonding Type:						
Form of Roof:						
Roofing Material:		7				
Roof Features						
Power Source						
Traverse:						
Entrance To:						
Entrance 10.						
Elevation North:						
Elevation East:						
Elevation South:						
Elevation West:						

505

Number/ SS Number	505	Old Series:			NGR:	TQ38239943
Name/Function:						Condition
Name / Func	tion	Start Dat	e:	End Date:		Good
Store, solvent and genera	ni	1892				Fair
Acetone and M.S store		by 1897				
Store		by 1907	de	molished 1908-9		2.5
Contact Prints						Unknown
Photography						
Cartographic depiction:						
Date: Cartograph 1897 O.S Map	ic Depiction	<u>ı:</u>				
1907 WASC 900/62	2A					
Documentary References						
	cumentary	Reference:		Year:	<u> </u>	
WASC 1680	oumontary	Troitorion or		1910		
WASC 1764				1910		
SUPP/5/327						
Historical Photographs:						
Relationship with other M	lonuments:					
Artefacts						
General Description:						
Length: 0	Breadth	ı: 0	Height:	0		
Shape in Plan						
Number of Storeys:						
Building Material:						
Bonding Type:						
Form of Roof:						
Roofing Material:						
Roof Features						
Power Source						
Traverse:						
Entrance To:						
Elevation North:						
Elevation East:						
Elevation South:						
Elevation West:						

506

Number/ SS Number	506	Old Series:		NGR:	TQ38309943
Name/Function:					Condition
Name / Fund	tion	Start Date:	End Date:		Good
Mud Washing Shed		1891	demolished 1908-9		Fair Demolished Unknown
Contact Prints	_				
Photography					
Cartographic depiction:					
Date: Cartograph 1897 O.S Map	ic Depiction:				
1907 WASC 900/62	2A				
Documentary References	:				
	ocumentary Re	ference:	Year:		
Sandhurst WASC 1680			1894 1910	-	
WASC 1764			1910		
SUPP/5/327					
Historical Photographs:					
PRO Supply 5/861 170-1		listorical Photogr	aphs:		
Relationship with other M					
Artefacts					
General Description:					
Length: 0	Breadth:	0 H	eight: 0		
Shape in Plan					
Number of Storeys:					
Building Material:					
Bonding Type:					
Form of Roof:					
Roofing Material:					
Roof Features				1	
Power Source					
Traverse:	1				
Entrance To:					
Elevation North:					
Elevation East:					

509

Number/ SS Number	509	Old Series:		NGR:	TQ38369942
Name/Function:	1				Condition
Name / Fun	ction	Start Date:	End Date:		Good
Blank Cutting House Experimental House		1892 by 1907			☐ Fair
Experimental House		by 1907			Demolished
					Unknown
Contact Prints					
Photography					
Cartographic depiction:					
	hic Depiction:				
1897 O.S Map					
1907 WASC 900/6 1923 WASC 900/8		-			
Documentary Reference					
	ocumentary Ref	ference:	Year:		
Sandhurst			1894		
WASC 1680 WASC 1764			1910	-	
Plan and elevations: N57	6; SUPP/5/327	7	1310		
Historical Photographs:					
Relationship with other I	Vlonuments:				
Artefacts					
General Description:					
Length: 0	Breadth:	O Heigh	it: 0		
Shape in Plan					
Number of Storeys:					
Building Material:					
Bonding Type:					
Form of Roof:					
Roofing Material:					
Roof Features					
Power Source					
Traverse:					
Entrance To:					
Elevation North:					
Elevation East:					
Elevation South:					

510A

ROYAL GUNPOWDER FACTORY SOUTH SITE

Number/ SS Number	510A	Old Series:			NGR:	TQ38399947
Name/Function:						Condition
Name / Func	tion	Start Dat	e:	End Date:		Good
Tractor Charging House		1917				Fair Demolished Unknown
Contact Prints		_				
Photography						
Cartographic depiction:						
Date:Cartograph1923WASC 900/84	ic Depiction:					
Documentary References						
	cumentary Re	ference:		Year: 1910	-	
WASC 1680				1910		
Historical Photographs:						
Relationship with other M Artefacts	Ionuments:					
General Description:						
Length: 0	Breadth:	0	Height:	0		
Shape in Plan						
Number of Storeys:						
Building Material:						
Bonding Type:						
Form of Roof:						
Roofing Material:						
Roof Features						
Power Source						
Traverse:						
Entrance To:						
Elevation North:						
Elevation East:						
Elevation South:						
Elevation West:						

Number/	SS Number	511	Old Series:		NGR:	TQ38389944
Name/Fu	unction:					Condition
	Name / Fund	ction	Start Date:	End Date:		Good
Incorpora	ating House		1891 by 1907	post 1910		☐ Fair
Crushing			by 1923	demolished?		□ Demolished
						Unknown
_						
Contact	Prints			-:		
	•					
Photograp						
	phic depiction:					
Date: 1907	WASC 900/6	nic Depiction:				
1897	O.S.Map	2/1				
1923	WASC 900/8	4				
Documen	ntary References	3:				
	Do	ocumentary R	eference:	Year:		
Sandhurs				1894		
WASC 17				1910		
SUPP/5/3				1010		
Historical	Photographs:					
	hip with other N	vionuments:				
Artefacts	•					
General D	Description:					
Length:	0	Breadth:	O Heig	ght: 0		
Shape in	Plan]		
	of Storeys:					
Building N	Material:					
Bonding 7	Гуре:					
Form of F	Roof:					
Roofing N	/laterial:					
Roof Fea	tures					
Power So						
Traverse:						
Entrance	То:					
Elevation	North:					
Elevation	East:					
Elevation	South:					

513

Number/ SS Number	513	Old Series:			NGR:		
Name/Function:		Ĭ				Conditi	on
Name / Funct	tion	Start Da	ite:	End Date:			Good
Hydrant Hose House		1895			4		Fair Demolished Unknown
Contact Prints							
Photography							
Cartographic depiction:							
Date:Cartographi1907WASC 900/62	c Depiction:						
Documentary References:	:						
	cumentary Re	ference:		Year:			
WASC 1680 WASC 1764				1910 1910			
Sandhurst				1894			
Historical Photographs: Relationship with other M	onuments:						
Artefacts							
General Description:							
Length: 0	Breadth:	0	Height:	0			
Shape in Plan							
Number of Storeys:							
Building Material:							
Bonding Type:							
Form of Roof:							
Roofing Material:							
Roof Features							
Power Source							
Traverse:							
Entrance To:							
Elevation North:							
Elevation East:							
Elevation South:							
Elevation West:							

Number/ SS Number	514	Old Series:		NGR:	TQ38429948
Name/Function:					Condition
Name / Fun	ction	Start Date:	End Date:		Good
Press House No 2		1893			Fair
Acetone Store Press House		by 1907 by 1923			Demolished
1 1ess 1 louse		by 1323			Unknown
Contact Prints					
Photography					
Cartographic depiction:					
	hic Depiction	<u>1:</u>			
1907 WASC 900/6 1897 O.S.Map	52A				
1923 WASC 900/8	34				
Documentary Reference	ocumentary	Reference:	Year:		
Sandhurst	ocumentary	nererence.	1894		
WASC 1680			1910		
N566 unnumbered plans SUPP/5/327	and elevation	ons	1892	_	
Historical Photographs:					
Relationship with other	Monuments:	Underlies N566			
Artefacts					
General Description:					
Length: 0	Breadtl	n: 0 Height	: 0		
Shape in Plan					
Number of Storeys:					
Building Material:					
Bonding Type:					
Form of Roof:					
Roofing Material:					
Roof Features					
Power Source					
Traverse:					
Entrance To:					
Elevation North:					
			,		
Elevation East:					
Elevation South:					

517B

ROYAL GUNPOWDER FACTORY SOUTH SITE

Number/ SS Number 5	17B	Old Series:			NGR:	TQ38509946
Name/Function:						Condition
Name / Functio	n	Start Dat	e:	End Date:		Good
Womens Lavatory		1917				Fair Demolished Unknown
Contact Prints						
Photography						
Cartographic depiction:						
Date:Cartographic1923WASC 900/84	Depiction:					
Documentary References:						
WASC 1680	mentary Ref	erence:		Year: 1910	-	
				1910		
Historical Photographs: Relationship with other Mor	umenter					
Artefacts	iumontoi					
General Description:						
Length: 0	Breadth:	0	Height:	0		
Shape in Plan						
Number of Storeys:						
Building Material:						
Bonding Type:						
Form of Roof:						
Roofing Material:						
Roof Features						
Power Source						
Traverse:						
Entrance To:						
Elevation North:						
Elevation East:						
Elevation South:						
Elevation West:						

519

Number/ SS Number	519	Old Series:			NGR:	TQ38589947			
Name/Function:	Name/Function: Condition								
Name / Funct	ion	Start Dat	e:	End Date:		Good			
Contact Prints		1892				Fair Demolished Unknown			
Photography									
1907 WASC 900/62 1897 O.S Map 1923 WASC 900/84									
Documentary References:				V					
WASC 1680	cumentary Ref	rerence:		Year: 1910					
Historical Photographs:									
Relationship with other M	onuments:								
Artefacts									
General Description:									
Length: 0	Breadth:	0	Height:	0					
Shape in Plan									
Number of Storeys:									
Building Material:									
Bonding Type:									
Form of Roof:									
Roofing Material:									
Roof Features									
Power Source									
Traverse:									
Entrance To:									
Elevation North:									
Elevation East:									
Elevation South:									
Elevation West:									

520

ROYAL GUNPOWDER FACTORY SOUTH SITE

Number/ SS Number	520	Old Series:		NGR:	TQ38559947		
Name/Function:				Condition			
Name / Fun	ction	Start Date:	End Date:		Good		
Police Search Hut		1902	by1923		Fair		
Warders Hut		by 1910	demolished by c19	20	Demolished		
					Unknown		
Contact Prints							
Photography							
Cartographic depiction:							
	hic Depiction:						
1907 WASC 900/6							
Documentary Reference							
WASC 1680	ocumentary Re	ference:	Year: 1910				
			1310				
Historical Photographs:							
Relationship with other	Monuments:						
Artefacts							
General Description:							
Length: 0	Duo a déb.	0 He	inht.				
Length: 0	Breadth:	О	ight: 0				
Shape in Plan							
Number of Storeys:							
Building Material:							
Bonding Type:							
Form of Roof:							
Roofing Material:							
Roof Features							
Power Source							
Traverse:							
Entrance To:							
Elevation North:							
Elevation East:							
Elevation South:							
Elevation West:							

522

Number/ SS Number	522	Old Series:			NGR:	TQ38529943
Name/Function:						Condition
Name / Func	Start Da	te:	End Date:		Good	
Lavatory		by 1894				Fair Demolished Unknown
Contact Prints						
Photography						
Cartographic depiction:						
	c Depiction:					
1907 WASC 900/62 1897 O.S Map	A					
1923 WASC 900/84						
Documentary References:						
	cumentary Re	ference:		Year:		
Sandhurst				1894		
Historical Photographs:						
Relationship with other M	onuments:					
Artefacts						
General Description:						
Length: 0	Breadth:	0	Height:	0		
Shape in Plan						
Number of Storeys:						
Building Material:						
Bonding Type:						
Form of Roof:						
Roofing Material:						
Roof Features						
Power Source						
Traverse:						
Entrance To:						
Littlation 101						
Elevation North:						
Elevation North:						

523

ROYAL GUNPOWDER FACTORY SOUTH SITE

Number/ SS Number	523	Old Series:			NGR:		
Name/Function:						Conditi	
Name / Fund	ction	Start Date:	En	d Date:			Good
Shed		c1893	demolishe				Fair Demolished Unknown
Contact Prints							
		T.					
Photography							
Cartographic depiction:							
	hic Depiction:						
1907 WASC 900/6	2A						
Documentary Reference	s:						
	ocumentary R			Year:			
WASC 1680; Shed, dem	olished 1908-	.9		1910 1894	-		
Sandhurst Historical Photographs:				1034			
Relationship with other I	Vlonuments:						
Artefacts							
General Description:							
Length: 0	Breadth:	O He	eight: 0				
Shape in Plan							
Number of Storeys:							
Building Material:							
Bonding Type:							
Form of Roof:							
Roofing Material:							
Roof Features							
Power Source							
Traverse:							
Entrance To:							
Elevation North:							
Elevation East:							
Elevation South:							
Elevation West:							

524

Number/ SS Number	524	Old Series:			NGR:	TQ38479943	
Name/Function:						Condition	
Name / Fund	ction	Start Da		End Date:		Good	
Dynamo House		1894-1907				☐ Fair	
						Demolished	
						Unknown	
Contact Prints	_						
Photography							
Cartographic depiction:							
	nic Depiction:	\Box					
	2A; Dynamo H	0					
Documentary References							
Sandhurst; Dynamo Hous	ocumentary Re se	rerence:		Year: 1894			
Historical Photographs:				•			
Relationship with other M	/lonuments:						
Artefacts							
General Description:							
Length: 0	Breadth:	0	Height:	0			
Shape in Plan							
Number of Storeys:							
Building Material:							7
Bonding Type:							7
Form of Roof:							7
Roofing Material:							7
Roof Features							7
Power Source							_
Traverse:							
Entrance To:							
Elevation North:							
Elevation East:							
Elevation South:							
Elevation West:							
Overall Internal Description)						

525

ROYAL GUNPOWDER FACTORY SOUTH SITE

Number/ SS Number	525	Old Series:		NGR:	TQ38479943
Name/Function:					Condition
Name / Funct	ion	Start Date			Good
Chimney		1891	demolished 190	8-9	☐ Fair
					Demolished
					Unknown
Contact Prints					
_	-	1		-	-
Photography					
Cartographic depiction:		\neg			
Date: Cartographi 1897 O.S.Map	c Depiction:	-			
1907 WASC 900/62	A				
Documentary References:					
	cumentary Ref	erence:	Yea	ar:	
Sandhurst WASC 1680			1894 1910		
Historical Photographs:					
Relationship with other Me	onuments:				
Artefacts	ondinonts.				
General Description:					
Length: 0	Breadth:	0	Height: 0		
Shape in Plan					
Number of Storeys:					
Building Material:					
Bonding Type:					
Form of Roof:					
Roofing Material:					
Roof Features					
Power Source					
Traverse:					
Entrance To:					
Elevation North:					
Elevation East:					
Elevation South:					
Elevation West:					

526

ROYAL GUNPOWDER FACTORY SOUTH SITE

Number/ SS Number	526	Old Series:			NGR:	TQ38479943
Name/Function:		1				Condition
Name / Func	tion	Start Dat	e:	End Date:		Good
Switchboard House		1896 by 1907				☐ Fair
						Demolished
						Unknown
Contact Prints						
Photography				1		
Cartographic depiction:						
	c Depiction:					
1907 WASC 900/62	A					
1923 WASC 900/84						
Documentary References						
WASC 1680	cumentary Re	eterence:		Year: 1910	\dashv	
Sandhurst	0 1/ /	7 14/41		1894		
Uncatalogued plan at P.R.	O Kew store	drawer / WA)		1916		
Historical Photographs:						
Relationship with other M	onuments:					
Artefacts						
General Description:						
Length: 0	Breadth:	0	Height:	0		
Shape in Plan						
Number of Storeys:						
Building Material:						
Bonding Type:						
Form of Roof:						
Roofing Material:						
Roof Features						
Power Source						
Traverse:						
Entrance To:						
Elevation North:						
Elevation East:						
Elevation South:						
Elevation West:						

ROYAL GUNPOWDER FACTORY SOUTH SITE

Number/ SS Number	527A	Old Series:			NGR:	TQ38459943	
Name/Function:						Condition	
Name / Func	tion	Start Da	ite:	End Date:		Good	
Hose House		1917				Fair	
						□ Demolisher	d
						Unknown	
Contact Prints							
Photography							
Cartographic depiction:							
Date: Cartograph 1923 WASC 900/84	ic Depiction:						
Documentary References							
WASC 1680SUPP	cumentary Re	ference:		Year: 1910	\dashv		
				1310			
Historical Photographs:							
Relationship with other N	Ionuments:						
Artefacts							
General Description:							
Length: 0	Breadth:	0	Height:	0			
Shape in Plan							
Number of Storeys:							
Building Material:							
Bonding Type:							
Form of Roof:							
Roofing Material:							
Roof Features							
Power Source							
Traverse:							
Entrance To:							
Elevation North:							
Elevation East:							
Elevation South:							
Elevation West:							

527B

ROYAL GUNPOWDER FACTORY SOUTH SITE

Number/ SS Number	527B	Old Series:			NGR:	TQ38489940
Name/Function:						
Name / Func	tion	Start Da	ate:	End Date:		Condition Good
Circular Filter Bed		1917				Fair
						□ Demolished
						Unknown
Contact Prints						
Photography						
Cartographic depiction:						
Documentary References						
WASC 1680	ocumentary Re	ference:		Year: 1910	-	
"Filter Bed" Uncatalogue	d Plan of Drain	age at		1916		
P.R.O Kew Store(WA Dra						
Historical Photographs:						
Relationship with other M	fonuments:					
Artefacts						
General Description:						
Length: 0	Breadth:	0	Height:	0		
Shape in Plan						
Number of Storeys:						
Building Material:						
Bonding Type:						
Form of Roof:						
Roofing Material:						
Roof Features						
Power Source						
Traverse:						
Entrance To:						
Entrance To.						
Elevation North:						
Elevation East:						
Elevation South:						
Elevation West:						
LIGVATION VVCSL.						
Overall Internal Description)					

527C

ROYAL GUNPOWDER FACTORY SOUTH SITE

Number/ SS Number	527C	Old Series:		NGR:	TQ38459943
Name/Function:					Condition
Name / Fun		Start Date:	End Date:		Good
Acetone + M.S. Store		by 1910 1892			☐ Fair
		1692			Demolished
					Unknown
Contact Prints					
			.18		
Photography					
Cartographic depiction:	L' B. J.d.				
Date: Cartograp 1923 WASC 900/8	hic Depiction:	_			
Documentary Reference					
	Ocumentary R	eference:	Year:		
WASC 1680			1910		
Historical Photographs:					
Relationship with other	Monuments:				
Artefacts					
General Description:					
Length: 0	Breadth:	O Height:	0		
Shape in Plan					
Number of Storeys:					
Building Material:					
Bonding Type:					
Form of Roof:					
Roofing Material:					
Roof Features					
Power Source					
Traverse:					
Entrance To:					
Elevation North:					
Elevation East:					
Elevation South:					
Elevation West:					
LIGVATION VVEST:					

527D

ROYAL GUNPOWDER FACTORY SOUTH SITE

Number/ SS Number	527D	Old Series:		NGR:	TQ38489941
Name/Function:					Condition
Name / Fund		Start Date:	End Date:		Good
Septic Tank and Valve F	Pit	by 1923			Fair Demolished Unknown
Contact Prints	×				
Photography					
Cartographic depiction:					
Date: Cartograph 1923 WASC 900/8	nic Depiction: 4				
Documentary References	s:				
	ocumentary Re	ference:	Year:		
WASC 1680			1910		
Historical Photographs:					
Relationship with other M	Monuments:				
Artefacts					
General Description:					
Length: 0	Breadth:	0 Heig	ht: 0		
Shape in Plan					
Number of Storeys:					
Building Material:					
Bonding Type:					
Form of Roof:					
Roofing Material:					
Roof Features					
Power Source					
Traverse:					
Entrance To:					
Elevation North:					
Elevation East:					
Elevation South:					
Elevation West:					

528

ROYAL GUNPOWDER FACTORY SOUTH SITE

Number/ SS Number	528	Old Series:			NGR:		7
Name/Function:						Condition	
Name / Func	tion	Start Da		End Date:		Good	
Barrel Shed		1893	∫d€	emolished 1905-6	6	Fair Demolished Unknown	
Contact Prints	_						
Photography							
Cartographic depiction:							
Documentary References	:						
WASC 1680	cumentary Ref	ference:		Year : 1910			
Historical Photographs:				1310			
Relationship with other M	lonumente:						
Artefacts	ionuments.						
General Description:							
Length: 0	Breadth:	0	Height:	0			
Shape in Plan							
Number of Storeys:							
Building Material:							7
Bonding Type:							٦
Form of Roof:							7
Roofing Material:							
Roof Features							٦
Power Source							
Traverse:							
Entrance To:							
Elevation North:							
Elevation East:							
Elevation South:							
Elevation West:							
Overall Internal Descriptio							

529

ROYAL GUNPOWDER FACTORY SOUTH SITE

Number/ SS Number	529	Old Series:			NGR:	TQ3830	9940
Name/Function:						Conditi	on
Name / Func	tion	Start Da	ate:	End Date:			Good
Landing Stage		1904					Fair Demolished Unknown
Contact Prints							
Photography							
Cartographic depiction:							
Date: Cartograph 1907 WASC 900/62 1923 WASC 900/84 Documentary References							
	cumentary Ref	erence:		Year:			
WASC 1680				1910			
Historical Photographs:							
Relationship with other M	lonuments:						
Artefacts							
General Description:							
Length: 0	Breadth:	0	Height:	0			
Shape in Plan							
Number of Storeys:							
Building Material:							
Bonding Type:							,
Form of Roof:							
Roofing Material:							
Roof Features							
Power Source							
Traverse:							
Entrance To:							
Elevation North:							
Elevation East:							
Elevation South:							
Elevation West:							

529C

ROYAL GUNPOWDER FACTORY SOUTH SITE

Number/ SS Number	529C	Old Series:			NGR:	TQ38279926
Name/Function:						Condition
Name / Func	tion	Start Da	te:	End Date:		Good
Toilet		by 1923				Fair Demolished Unknown
Contact Prints						
Photography						
Cartographic depiction:						
Date: Cartograph 1923 WASC 900/84	ic Depiction:					
Documentary References	:					
Historical Photographs:						
Relationship with other M	lonuments:					
Artefacts						
General Description:						
Length: 0	Breadth:	0	Height:	0		
Shape in Plan						
Number of Storeys:						
Building Material:						
Bonding Type:						
Form of Roof:						
Roofing Material:						
Roof Features						
Power Source						
Traverse:						
Entrance To:						
Elevation North:						
Elevation East:						
Elevation South:						
Elevation West:						
Overall Internal Description						

536A

ROYAL GUNPOWDER FACTORY SOUTH SITE

Number/ SS Number	536A	Old Series:			NGR:	TQ37759939
Name/Function:						Condition
Name / Fund	tion	Start Da	te:	End Date:		Good
Cordite Drying Plant (No	rm Air)	by 1923		/ 1976		Fair Demolished Unknown
Contact Prints						
Photography						
Cartographic depiction:						
	ic Depiction:					
1923 WASC 900/84 1976 WASC 900/1						
Documentary References		_ L				
Historical Photographs:						
Relationship with other N	fonuments:					
Artefacts						
General Description:						
Length: 0	Breadth:	0	Height:	0		
Shape in Plan						
Number of Storeys:						
Building Material:						
Bonding Type:						
Form of Roof:						
Roofing Material:						
Roof Features						
Power Source						
Traverse:						
Entrance To:						
Elevation North:						
Elevation East:						
Elevation South:						
Elevation West:						
Overall Internal Description)					

537

ROYAL GUNPOWDER FACTORY SOUTH SITE

Number/ SS Number	537	Old Series:			NGR:	TQ37809938
Name/Function:						Condition
Name / Func	tion	Start Da		End Date:		Good
Hose House		by 1908	b	y1976		Fair Demolished Unknown
Contact Prints				-		
Photography						
Cartographic depiction:						
Date: Cartograph 1908 WASC 900/62	ic Depiction:	-				
1923 WASC 900/84						
1976 WASC 900/11						
Documentary References	•					
Historical Photographs:						
Relationship with other M	lonuments:					
Artefacts						
General Description:						
Length: 0	Breadth:	0	Height:	0		
Shape in Plan						
Number of Storeys:						
Building Material:						
Bonding Type:						
Form of Roof:						
Roofing Material:						
Roof Features						
Power Source						
Traverse:						
Entrance To:						
Elevation North:						
Elevation East:						
Elevation South:						
Elevation West:						

544

ROYAL GUNPOWDER FACTORY SOUTH SITE

Number/ SS Number	544	Old Series:			NGR:	TQ38199939
Name/Function:						Condition
Name / Fur	nction	Start Date	e:	End Date:		Good
Lavatory		1905				Fair Demolished Unknown
Contact Prints						
Photography						
Cartographic depiction:						
	hic Depiction:					
1923 WASC 900/8 1908 WASC 900/8						
Documentary Reference						
WASC 1680; E.C.	Documentary Re	eference:		Year: 1910	-	
Historical Photographs:						
Relationship with other	Monuments:					
Artefacts						
General Description:						
Length: 0	Breadth:	0 H	Height:	0		
Shape in Plan						
Number of Storeys:						
Building Material:						
Bonding Type:						
Form of Roof:						
Roofing Material:						
Roof Features						
Power Source						
Traverse:						
Entrance To:						
Elevation North:						
Elevation East:						
Elevation South:						
Elevation West:						

545B

ROYAL GUNPOWDER FACTORY SOUTH SITE

Number/ SS Number	545B	Old Series:			NGR:	TQ38169936	
Name/Function:						Condition	
Name / Funct	tion	Start Da		End Dat	e:	Good	
Motor House		1903	de	emol.		Fair Demol	
Contact Prints							
Photography							
Cartographic depiction:							
Date: Cartographi 1923 WASC 900/84	c Depiction:						
Documentary References:				*			
Historical Photographs:							
Relationship with other M	onuments:						
Artefacts							
General Description:			*				
Length: 0	Breadth:	0	Height:	0			
Shape in Plan							
Number of Storeys:							
Building Material:							
Bonding Type:							
Form of Roof:							
Roofing Material:							
Roof Features							
Power Source							
Traverse:							
Entrance To:							
Elevation North:							
Elevation East:							
Elevation South:							
Elevation West:							
Overall Internal Descriptio							

545C

ROYAL GUNPOWDER FACTORY SOUTH SITE

Number/ SS Number	545C	Old Series:			NGR:	TQ38169935
Name/Function:						0
Name / Func	tion	Start Da	ite:	End Date:		Condition Good
Lavatory		1903				Fair
						Demolished
						Unknown
Contact Prints						
Photography						
Cartographic depiction:						
	ic Depiction:					
1923 WASC 900/84						
Documentary References	:					
Historical Photographs:						
Relationship with other M	Ionuments:					
Artefacts						
General Description:						
Length: 0	D 141	0	Halaha.			
Length.	Breadth:	0	Height:	0		
Shape in Plan						
Number of Storeys:						
Building Material:						
Bonding Type:						
Form of Roof:						
Roofing Material:						
Roof Features						
Power Source						
Traverse:						
Entrance To:						
Elevation North:						
Elevation East:						
Elevation South:						
Elevation West:						
Overall Internal Description)					
Interpretation of phasing						

ROYAL GUNPOWDER FACTORY SOUTH SITE

Number/ SS Number	546A	Old Series:		NGR:	TQ38079936
Name/Function:		1			Condition
Name / Func	tion	Start Dat		Date:	Good
Motor House		by 1923	by 1976		Fair Demolished Unknown
Contact Prints	_				
Photography					
Cartographic depiction:					
Documentary References	::				
Historical Photographs:					
Relationship with other N	lonuments:				
Artefacts					
General Description:					
Length: 0	Breadth:	0	Height: 0		
Shape in Plan					
Number of Storeys:					
Building Material:					
Bonding Type:					
Form of Roof:					
Roofing Material:					
Roof Features					
Power Source Traverse:					
Entrance To:					
Elevation North:					
Elevation East:					
Elevation South:					
Elevation West:					
Overall Internal Description	o				
Interpretation of phasing					
Rooms Detail:					

Other:

546B

ROYAL GUNPOWDER FACTORY SOUTH SITE

Number/ SS Number	546B	Old Series:		NGR:	TQ38079935
Name/Function:					Condition
Name / Fund	tion	Start Date:			Good
Earth Closet		by 1923	by 1976		Fair Demolished Unknown
Contact Prints					
Photography					
Cartographic depiction:					
Documentary References	:				
Historical Photographs:					
Relationship with other N	lonuments:				
Artefacts					
General Description:					
Length: 0	Breadth:	0 F	leight: 0		
Shape in Plan					
Number of Storeys:					
Building Material:					
Bonding Type:					
Form of Roof:					
Roofing Material:					
Roof Features					
Power Source					
Traverse:					
Entrance To:					
Elevation North:					
Elevation East:					
Elevation South:					
Elevation West:					
Overall Internal Description					
Interpretation of phasing					
Rooms Detail:					

Other:

547

ROYAL GUNPOWDER FACTORY SOUTH SITE

Number/ SS Number	547	Old Series:			NGR:	TQ3784	49933
Name/Function:		1				Conditi	on
Name / Func	tion	Start Da		End Date:			Good
Earth Closet		by 1908	by	1976			Fair
							Demolished
						Ш	Unknown
Contact Prints							
	_					_	
Photography							
Cartographic depiction:							
Date: Cartograph	ic Depiction:						
1908 WASC 900/62 1923 WASC 900/84		_					
1976 WASC 900/11							
Documentary References	:						
Historical Photographs:							
Relationship with other N	lonuments:						
Artefacts							
General Description:							
Length: 0	Breadth:	0	Height:	0			
Shape in Plan							
Number of Storeys:							
Building Material:							
Bonding Type:							
Form of Roof:							
Roofing Material:							
Roof Features		1					
Power Source							
Traverse:							
Entrance To:							
Elevation North:							
Elevation East:							
Elevation South:							
Elevation West:							

561

ROYAL GUNPOWDER FACTORY SOUTH SITE

Number/ SS Number	561	Old Series:			NGR:	TQ38039922
Name/Function:						Condition
Name / Func	tion	Start Da	ite:	End Date:		Good
Hose House		by 1908				Fair Demolished Unknown
Contact Prints						
Photography						
Cartographic depiction:						
Documentary References	:					
Historical Photographs:						
Relationship with other M	lonuments:					
Artefacts						
General Description:						
Length: 0	Breadth:	0	Height:	0		
Shape in Plan						
Number of Storeys:						
Building Material:				76		
Bonding Type:						
Form of Roof:						
Roofing Material:						
Roof Features						
Power Source						
Traverse:						
Entrance To:						
Elevation North:						
Elevation East:						
Elevation South:						
Elevation West:						
Overall Internal Descriptio						

ROYAL GUNPOWDER FACTORY SOUTH SITE

Number/ SS Number	567	Old Series:			NGR:	TQ37919917
Name/Function:		_				Condition
Name / Funct	tion	Start Date		d Date:		Good
Cordite Tray Stove Destroyed by fire		1902 1917	1917			☐ Fair
Destroyed by fire		1917				Demolished
						Unknown
Contact Prints	_					
Photography						
Cartographic depiction:						
	c Depiction:					
1908 WASC 900/62 1923 WASC 900/84						
Documentary References				Vasau		
WASC 1508	cumentary Re	eterence:		Year: 1910	+	
WASC 1680				1910		
P.R.O. Supl 5, 801, 332-	334.					
Historical Photographs:						
Relationship with other M	onuments:					
Artefacts						
General Description:						
Length: 0	Breadth:	0	Height: 0			
Shape in Plan						
Number of Storeys:						
Building Material:						
Bonding Type:						
Form of Roof:						
Roofing Material:						
Roof Features						
Power Source						
Traverse:						
Entrance To:						
Entrance 10:						
Elevation North:						
Elevation East:						
Elevation South:						
Elevation West:						

570A

ROYAL GUNPOWDER FACTORY SOUTH SITE

Number/ SS Number	570A	Old Series:			NGR:	TQ37719917
Name/Function:		J				Condition
Name / Func	tion	Start Da	ate:	End Date:		Good
Hose House		by 1923	by	1976		Fair Demolished Unknown
Contact Prints						
Photography						
Cartographic depiction:						
	ic Depiction:					
1923 WASC 900/84	-					
1976 WASC 900/11						
Documentary References	:					
Historical Photographs:						
Relationship with other N	lonuments:					
Artefacts						
General Description:						
Length: 0	Breadth:	0	Height:	0		
Shape in Plan						
Number of Storeys:						
Building Material:						
Bonding Type:						
Form of Roof:						
Roofing Material:						
Roof Features						
Power Source						
Traverse:						
Entrance To:						
Elevation North:						
Elevation East:						
Elevation South:						
Elevation West:						
Overall Internal Descriptio	ı					

571

ROYAL GUNPOWDER FACTORY SOUTH SITE

Number/ SS Number	571	Old Series:			NGR:	TQ37609917
Name/Function:		Į.				Condition
Name / Fund	tion	Start Da		End Date:		Good
Acetone Recovery Plant		1904	by	1976		Fair
Contact Prints	_					☐ Demolished☐ Unknown
Photography						
Cartographic depiction:						
Date: Cartograph 1908 WASC 900/63 1923 WASC 900/84 1976 WASC 900/1	4					
Documentary References	::					
Historical Photographs:						
Relationship with other N	/lonuments:					
Artefacts						
General Description:						
Length: 0	Breadth:	0	Height:	0		
Shape in Plan						
Number of Storeys:						
Building Material:						
Bonding Type:						
Form of Roof:						
Roofing Material:						
Roof Features						
Power Source						
Traverse:						
Entrance To:						
Elevation North:						
Elevation East:						
Elevation South:						
Elevation West:						

571A

ROYAL GUNPOWDER FACTORY SOUTH SITE

Number/ SS Number	571A	Old Series:			NGR:	TQ37599917
Name/Function:						Condition
Name / Func	tion	Start Da	ite:	End Date	e:	Good
Caustic Soda Store Contact Prints		by 1908		by 1976		Fair Demolished Unknown
Photography Cartographic depiction: Date: Cartograph 1908 WASC 900/62 1923 WASC 900/84 1976 WASC 900/11 Documentary References	3					
Historical Photographs: Relationship with other M Artefacts General Description: Length: 0	lonuments: Breadth:	0	Height	: 0		
Shape in Plan	Dioddini					
Number of Storeys:						
Building Material:						
Bonding Type:						
Form of Roof:						
Roofing Material:						
Roof Features						
Power Source						
Traverse:						
Entrance To:						
Elevation North:						
Elevation East:						
Elevation South:						
Elevation West:						

571B

ROYAL GUNPOWDER FACTORY SOUTH SITE

Number/ SS Number	571B	Old Series:			NGR:	TQ37609920
Name/Function:						0 11:1
Name / Function.	on	Start Da	ite:	End Date:		Condition Good
Crane		by 1908		y 1923		Fair Demolished Unknown
Contact Prints —	_					
Photography						
Cartographic depiction:						
Documentary References:						
Historical Photographs:						
Relationship with other Mo	numents:	North of 571	on old c	ourse of River Le	e.	
Artefacts						
General Description:						
Length: 0	Breadth:	0	Height	: 0		
Shape in Plan						
Number of Storeys:						
Building Material:						
Bonding Type:						
Form of Roof:						
Roofing Material:						
Roof Features						
Power Source						
Traverse:						
Entrance To:						
Elevation North:						
Elevation East:						
Elevation South:						
Elevation West:						
Overall Internal Descriptio						
Interpretation of phasing						
Rooms Detail:						

Other:

578

ROYAL GUNPOWDER FACTORY SOUTH SITE

Number/ SS Number	578	Old Series:			NGR:	TQ37879908
Name/Function:						Condition
Name / Func	tion	Start Da		End Date:		Good
Earrth Closet	4	by 1908	by	1976		Fair Demolished Unknown
Contact Prints						
Photography						
Cartographic depiction:						
Date: Cartograph 1908 WASC 900/62 1923 WASC 900/84 1976 WASC 900/11						
Documentary References	:					
Historical Photographs:						
Relationship with other M	lonuments:					
Artefacts						
General Description:						
Length: 0	Breadth:	0	Height:	0		
Shape in Plan						
Number of Storeys:						
Building Material:						
Bonding Type: Form of Roof:						
Roofing Material:						
Roof Features						
Power Source						
Traverse:						
Entrance To:						
Elevation North:						
Elevation East:						
Elevation South:						
Elevation West:						

584

ROYAL GUNPOWDER FACTORY SOUTH SITE

Number/ SS Number	584	Old Series:			NGR:	TQ37879901
Name/Function:						Condition
Name / Func	tion	Start Da	te:	End Date:		Good
Hose House		by 1908	by	1976		Fair
						Demolished
						Unknown
Contact Prints						
_		_				
Photography						
Cartographic depiction:						
1750 Oct.	ic Depiction:					
1908 WASC 900/62	2A					
1923 WASC 900/84 1976 WASC 900/11						
Documentary References						
Historical Photographs:						
Relationship with other N	lonuments:					
Artefacts						
General Description:						
Length: 0	Breadth:	0	Height:	0		
Shape in Plan						
Number of Storeys:						
Building Material:						
Bonding Type:						
Form of Roof:						
Roofing Material:						
Roof Features						
Power Source						
Traverse:						
Entrance To:						
E.Manoo To.						
Elevation North:						
Elevation East:						
Elevation South:						
Elevation West:						

585

ROYAL GUNPOWDER FACTORY SOUTH SITE

Number/ SS Number	585	Old Series:			NGR:	TQ37629916
Name/Function:						Condition
Name / Func	tion	Start Da		End Date:		Good
Earth Closet Contact Prints		by 1908	I	by 1976		Fair Demolished Unknown
		_				
Photography						
Cartographic depiction:						
Date: Cartograph 1908 WASC 900/62 1923 WASC 900/84 1976 WASC 900/11			,			
Documentary References	:					
Historical Photographs:						
Relationship with other M	lonuments:					
Artefacts						
General Description:						
Length: 0	Breadth:	0	Height	: 0		
Shape in Plan						
Number of Storeys:						
Building Material:						
Bonding Type:						
Form of Roof:						
Roofing Material:						
Roof Features						
Power Source						
Traverse:						
Entrance To:						
Elevation North:						
Elevation East:						
Elevation South:						
Elevation West:						

587

ROYAL GUNPOWDER FACTORY SOUTH SITE

Number/ SS Number	587	Old Series:			NGR:	
Name/Function:						
Name / Func	tion	Start Da	te:	End Date:		Condition Good
Landing Stage (from cana		by 1923		y 1976		Fair
						Demolished
						Unknown
Contact Prints						
	_					
Photography						
Cartographic depiction: Date: Cartograph	ic Depiction:	\Box				
1923 WASC 900/62	A.					
1976 WASC 900/11	3					
Documentary References	:					
Historical Photographs:						
Relationship with other M	lonuments:					
Artefacts						
General Description:						
Length: 0	Breadth:	0	Height:	0		
Shape in Plan						
Number of Storeys:						
Building Material:						
Bonding Type:						
Form of Roof:						
Roofing Material:						
Roof Features						
Power Source						
Traverse:						
Entrance To:						
Elevation North:						
Elevation East:						
Elevation South:						
Elevation West:						
Overall Internal Description)					

592

ROYAL GUNPOWDER FACTORY SOUTH SITE

Number/ SS Number	592	Old Series:			NGR:	
Name/Function:		Į.				Condition
Name / Func	tion	Start Da	te:	End Date:		Good
Landing Stage (canal to r	ailway)	by 1923	by	1976		Fair Demolished Unknown
Contact Prints						
Photography						
Cartographic depiction:	3					
Historical Photographs:						
Relationship with other N	ionuments:					
Artefacts General Description:						
Length: 0	Breadth:	0	Height:	0		
Shape in Plan						
Number of Storeys:						
Building Material:						
Bonding Type:						
Form of Roof:						
Roofing Material:						
Roof Features						
Power Source						
Traverse:						
Entrance To:						
Elevation North:						
Elevation East:						
Elevation South:						
Elevation West:						
Overall Internal Descriptio						

598

ROYAL GUNPOWDER FACTORY SOUTH SITE

Number/ SS Number	598	Old Series:			NGR:	
Name/Function:						Condition
Name / Func	tion	Start Da	ite:	End Date:		Good
Earth Closet		by 1923	by 1	976		☐ Fair
						Demolished
						Unknown
Contact Prints						
Photography						
Cartographic depiction:	ia Daniation.	П				
Date: Cartograph	ic Depiction:	-				
1976 WASC 900/11	3					
Documentary References	:					
Historical Photographs:						
Relationship with other M	lonuments:					
Artefacts						
General Description:						
Length: 0	Breadth:	0	I I a l'arlado			
	breauth:	0	Height:	0		
Shape in Plan						
Number of Storeys:						#
Building Material:						
Bonding Type:						
Form of Roof:						
Roofing Material:						
Roof Features						
Power Source						
Traverse:						
Entrance To:						
Elevation North:						
Elevation East:						
Elevation South:						
Elevation West:						
Overall Internal Descriptio						

599

ROYAL GUNPOWDER FACTORY SOUTH SITE

Number/ SS Number	599	Old Series:			NGR:		
Name/Function:						Condition	
Name / Func	tion	Start Da	te:	End Date:		Good	
Hose House		by 1923	by	1976		Fair Demolishe Unknown	:d
Contact Prints		_					
Photography							
Cartographic depiction:							
Date: Cartograph 1923 WASC 900/84 1976 WASC 900/11							
Documentary References	:						
Historical Photographs:							
Relationship with other M	lonuments:						
Artefacts							
General Description:							
Length: 0	Breadth:	0	Height:	0			
Shape in Plan							
Number of Storeys:							
Building Material:							
Bonding Type:							
Form of Roof:							
Roofing Material:							
Roof Features							
Power Source							
Traverse:							
Entrance To:							
Elevation North:							
Elevation East:							
Elevation South:							
Elevation West:							
Overall Internal Descriptio							

606

ROYAL GUNPOWDER FACTORY SOUTH SITE

Number/ SS Number	606	Old Series:			NGR:	TQ38589943
Name/Function:						Condition
Name / Func	tion	Start Da	te:	End Date:		Good
Police Hut		by 1923		· · · · · · · · · · · · · · · · · · ·		Fair Demolished Unknown
Contact Prints						
Photography						
Cartographic depiction:						
Date:Cartograph1923WASC 900/84	ic Depiction:					
Documentary References	:					
Historical Photographs:						
Relationship with other N	Ionuments:					
Artefacts						
General Description:						
Length: 0	` Breadth:	0	Height:	0		
Shape in Plan				*		
Number of Storeys:						
Building Material:						
Bonding Type:						
Form of Roof:						
Roofing Material:						
Roof Features						
Power Source						
Traverse:						
Entrance To:						
Elevation North:						
Elevation East:						
Elevation South:						
Elevation West:						
Overall Internal Description						

606A

ROYAL GUNPOWDER FACTORY SOUTH SITE

Number/ SS Number	606A	Old Series:			NGR:	TQ38599943
Name/Function:						
Name / Functi	ion	Start Da	te:	End Date:		Condition Good
Cycle Shed		by 1923				Fair
						Demolished
						Unknown
Contact Prints						
- —						
Photography						
Cartographic depiction:						
Date: Cartographic 1923 WASC 900/84	c Depiction:					
Documentary References:						
Historical Photographs:						
Relationship with other M	onuments:					
Artefacts						
General Description:						
Length: 0	Breadth:	0	Height:	0		
Shape in Plan						
Number of Storeys:						
Building Material:						
Bonding Type:						
Form of Roof:						
Roofing Material:						
Roof Features						
Power Source						
Traverse:						
Entrance To:						
Elevation North:						
Elevation East:						
Elevation South:						
Elevation West:						
Overall Internal Descriptio						

607

ROYAL GUNPOWDER FACTORY SOUTH SITE

Number/ SS Number	607	Old Series:			NGR:	TQ38579938
Name/Function:						Condition
Name / Func		Start Dat	te:	End Date:		Good
Womens Shifting and Dir	ning Room	by 1916				Fair Demolished Unknown
Contact Prints	-					
Photography Cartographic depiction: Date: Cartograph 1923 WASC 900/84	ic Depiction:					
Documentary References	:					
Do	cumentary R			Year:		
Uncatalogued plan in P.R.	O Kew Store	es (Waltham		1993		
Abbey Drawer No.7)				1993	-	
Historical Photographs:				,		
Historical Photographs.		Historical Photo	graphs:			
G5493/3			3			
Relationship with other M	lonuments:					
Artefacts						
General Description:						
Length: 0	Breadth:	0	Height:	0		
Shape in Plan						
Number of Storeys:						
Building Material:						
Bonding Type:						
Form of Roof:						
Roofing Material:						
Roof Features						
Power Source						
Traverse:						
Entrance To:						
Elevation North:						
Elevation East:						
Elevation South:						
Elevation West:						

607A

ROYAL GUNPOWDER FACTORY SOUTH SITE

Number/ SS Number	607A	Old Series:			NGR:	TQ38579938
Name/Function:						Condition
Name / Func		Start Da	ate:	End Date:		Good
Wheel Stretcher's House		1918				☐ Fair
						Demolished
						Unknown
Contact Prints						
Photography						
Cartographic depiction:						
	ic Depiction:					
1923 WASC 900/84						
Documentary References				Vacre		
WASC 1680	cumentary Ref	rerence:		Year: 1910	\dashv	
Historical Photographs:				-		
Relationship with other N	Ionuments:					
Artefacts						
General Description:						
Length: 0	Breadth:	0	Height:	0		
Shape in Plan						
Number of Storeys:						
Building Material:						
Bonding Type:						
Form of Roof:						
Roofing Material:						
Roof Features						
Power Source						
Traverse:						
Entrance To:						
Elevation North:						
Elevation East:						
Elevation South:						
Elevation West:						

611

ROYAL GUNPOWDER FACTORY SOUTH SITE

Number/ SS Number	611	Old Series:			NGR:	TQ38349934
Name/Function:						Condition
Name / Funct	ion	Start Da	ite:	End Date:		Good
Womens Lavatory		1918				Fair
						Demolished
						Unknown
O-read District						
Contact Prints						
Photography						
Cartographic depiction:		$\overline{}$				
Date: Cartographic 1923 WASC 900/84		-				
Documentary References:				Vaan		
WASC 1680	cumentary Ref	erence:		Year: 1910	$\dashv \bot$	
Historical Photographs:				1		
Relationship with other Me	onuments:					
Artefacts						
General Description:						
Length: 0	Breadth:	0	Height:	0		
Shape in Plan						
Number of Storeys:						
Building Material:						
Bonding Type:						
Form of Roof:						
Roofing Material:						
Roof Features						
Power Source						
Traverse:						
Entrance To:						
Elevation North:						
Elevation East:						
Elevation South:						
Elevation West:						

613A

ROYAL GUNPOWDER FACTORY SOUTH SITE

Number/ SS Number	613A	Old Series:			NGR:	TQ38279930
Name/Function:						Condition
Name / Funct	tion	Start Da	te:	End Date:		Good
Lavatory		1916				Fair Demolished Unknown
Contact Prints	_					
Photography						
Cartographic depiction:						
Date:Cartograph1923WASC 900/84	ic Depiction:					
Documentary References	:					
Historical Photographs:						
Relationship with other M	lonuments:					
Artefacts						
General Description:						
Length: 0	Breadth:	0	Height:	0		
Shape in Plan						
Number of Storeys:						
Building Material:						
Bonding Type:						
Form of Roof:						
Roofing Material:						
Roof Features						
Power Source Traverse:						
Entrance To:						
Elevation North:						
Elevation East:						
Elevation South:						
Elevation West:						
Overall Internal Description						

621

ROYAL GUNPOWDER FACTORY SOUTH SITE

Number/ SS Number	621	Old Series:			NGR:	TQ38479914			
Name/Function: Condition									
Name / Func	tion	Start Da	te:	End Date:		Good			
Hose House		by 1923				Fair Demolished Unknown			
Contact Prints									
Photography									
Cartographic depiction:									
Date: Cartograph 1923 WASC 900/84	ic Depiction:								
Documentary References	:								
Historical Photographs:									
Relationship with other Monuments:									
Artefacts									
General Description:									
Length: 0	Breadth:	0	Height:	0					
Shape in Plan									
Number of Storeys:									
Building Material:									
Bonding Type:									
Form of Roof:									
Roofing Material:									
Roof Features									
Power Source									
Traverse:									
Entrance To:									
Elevation North:									
Elevation East:									
Elevation South:									
Elevation West:									
Overall Internal Description)								

622

ROYAL GUNPOWDER FACTORY SOUTH SITE

Number/ SS Number	622	Old Series:		NGR:						
Name/Function:					Condition					
Name / Funct	ion	Start Dat		d Date:	Good					
Boiler House No. 10		1904	by 1976		Fair Demolished					
					Unknown					
Contact Prints										
-										
Photography										
Cartographic depiction:										
Date: Cartographi	c Depiction:									
1923 WASC 900/84 1976 WASC 900/11										
Documentary References:										
1910 WASC 1508; Boiler	House No. 10			Year:						
Historical Photographs:	110000 110110		L							
Relationship with other Monuments:										
Artefacts										
General Description:										
Length: 0	Breadth:	0	Height: 0							
Shape in Plan										
Number of Storeys:										
Building Material:										
Bonding Type:										
Form of Roof:										
Roofing Material:										
Roof Features										
Power Source										
Traverse:										
Entrance To:										
Elevation North:										
Elevation East:										
Elevation South:										
Elevation West:										