

FORMER  
RARDE  
WALTHAM  
ABBEY  
(NORTH SITE)  
REMEDATION PROJECT  
PHOTOGRAPHIC LOG  
REMEDATION RECORD  
DISK 1



FORMER  
RARDE  
WALTHAM  
ABBEY  
(NORTH SITE)  
REMEDATION PROJECT  
PHOTOGRAPHIC LOG  
REMEDATION RECORD  
DISK 2



FORMER  
RARDE  
WALTHAM  
ABBEY  
(NORTH SITE)  
REMEDATION PROJECT  
PHOTOGRAPHIC LOG  
REMEDATION RECORD  
DISK 3



MFD-2HD  
HIGH DENSITY  
1.44MB  
PS/2 & compatibles  
FORMATTED for IBM  
SONY

1.44 MB  
Formatted - Formatee  
IBM  
Haute densite  
High Density  
3M

1.44 MB  
Formatted - Formatee  
IBM  
Haute densite  
High Density  
3M

FORMER  
RARDE  
WALTHAM  
ABBEY  
(NORTH SITE)  
REMEDATION PROJECT  
PHOTOGRAPHIC LOG  
REMEDATION RECORD  
DISK 4



FORMER  
RARDE  
WALTHAM  
ABBEY  
(NORTH SITE)  
REMEDATION PROJECT  
PHOTOGRAPHIC LOG  
REMEDATION RECORD  
DISK 5



FORMER  
RARDE  
WALTHAM  
ABBEY  
(NORTH SITE)  
REMEDATION PROJECT  
PHOTOGRAPHIC LOG  
REMEDATION RECORD  
DISK 6



1.44 MB  
Formatted - Formatee  
IBM  
Haute densite  
High Density  
3M

1.44 MB  
Formatted - Formatee  
IBM  
Haute densite  
High Density  
3M

1.44 MB  
Formatted - Formatee  
IBM  
Haute densite  
High Density  
3M

3M ENHANCED PERFORMANCE DISKETTES

FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDATION PROJECT  
SPARE PHOTO'S LOG  
REMEDATION RECORD  
SPAREPH 1, 2 & 3  
REMREC 5, 6

DISK 7

3M ENHANCED PERFORMANCE DISKETTES

FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDATION PROJECT  
SPARE PHOTO'S LOG  
REMEDATION RECORD  
SPAREPH 4, 5 & 6

DISK 8

3M ENHANCED PERFORMANCE DISKETTES

FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDATION PROJECT  
SPARE PHOTO'S LOG  
REMEDATION RECORD  
DEMREC 1, 2, 3 & 4

DISK 9

MFD-2HD  
HIGH DENSITY  
1.44MB  
PS/2 & compatibles  
FORMATTED for IBM  
SONY

1.44 MB  
Formatted - Formatee  
IBM  
Haute densite  
High Density  
3M

MFD-2HD  
HIGH DENSITY  
1.44MB  
PS/2 & compatibles  
FORMATTED for IBM  
SONY

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDICATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	1/5192	5

LOCATION:	AREA T
-----------	--------

ACTIVITY:

TETRYL FACTORY - BREAKING OUT HEAVY CONCRETE FOUNDATION BASES. FOLLOW UP WORK AFTER CORING AND SPLITTING.

SPECIAL FEATURES:

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDICATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	1/5192	6

LOCATION:	AREA T
-----------	--------

ACTIVITY:


TETRYL FACTORY - BREAKING OUT HEAVY CONCRETE FOUNDATION BASES. FOLLOW UP WORK AFTER CORING AND SPLITTING.

SPECIAL FEATURES:


LARGE DIAMETER TUBED HOLDING DOWN BOLTS.

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	1/5192	7
LOCATION:	AREA P	
ACTIVITY:		
MOBILE LABORATORY FOR "ASBESTOS IN AIR" MONITORING WITHIN BUILDINGS.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	1/5192	8
LOCATION:	AREA P	
ACTIVITY:		
INTERIOR VIEW OF BUILDING A210.		
SPECIAL FEATURES:		
SAMPLING - AIR MONITORING PUMP.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	1/5192	9
LOCATION:	AREA P	
ACTIVITY:		
INTERIOR VIEW OF BUILDING A210.		
SPECIAL FEATURES:		
SAMPLING - AIR MONITORING PUMP.		



<b>FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD</b>		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	1/5192	10
LOCATION:	AREA P	
ACTIVITY:		
INTERIOR VIEW OF BUILDING A210.		
SPECIAL FEATURES:		
SAMPLING - AIR MONITORING PUMP.		



<b>FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD</b>		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	1/5192	11
LOCATION:	AREA P	
ACTIVITY:		
INTERIOR VIEW OF BUILDING A210.		
SPECIAL FEATURES:		
SAMPLING - AIR MONITORING PUMP.		




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	1/5192	12
LOCATION:	AREA P	
ACTIVITY:		
PERSONNEL DECONTAMINATION UNIT.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	1/5192	13
LOCATION:	AREA P	
ACTIVITY:		
PIPE CLAD IN ASBESTOS LAGGING, WRAPPED PRIOR TO DISPOSAL.		

SPECIAL FEATURES:
ENCAPSULATION OF HAZARD.

<b>FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD</b>		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	1/5192	14
LOCATION:	AREA T	
ACTIVITY:		

HEAVY CONCRETE FOUNDATION BASE BROKEN UP, FOR DISPOSAL.

SPECIAL FEATURES:

LARGE DIAMETER HOLDING DOWN BOLTS.

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	1/5192	15

LOCATION:	AREA P	
ACTIVITY:		
LINK BETWEEN BUILDING A235 AND BUILDING A238. NORTH ELEVATION.		
SPECIAL FEATURES:		
MARKED READY FOR DEMOLITION TO ALLOW ACCESS INTO POWDERMILL LANE HOUSING SITE AREA.		

<b>FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD</b>		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:

OCT '92	1/5192	16
LOCATION:	AREA P	
ACTIVITY:		
EAST ELEVATION OF BUILDING A266.		
SPECIAL FEATURES:		
TIMBER AND ASBESTOS CONSTRUCTION.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	1/5192	17
LOCATION:	AREA P	
ACTIVITY:		
NORTH WEST ELEVATION OF BUILDING A288 - (TOILET EXTENSION TO BUILDING A269).		
SPECIAL FEATURES:		
ASBESTOS ROOFING SHEETS.		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	1/5192	18

LOCATION:	AREA P
-----------	--------


ACTIVITY:  
NORTH ELEVATION OF BUILDING A289.

SPECIAL FEATURES:  
ASBESTOS ROOFING SHEETS.




--


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	1/5192	19
LOCATION:	AREA P	
ACTIVITY:		
NORTH EAST ELEVATION OF BUILDING A289.		
SPECIAL FEATURES:		
ASBESTOS ROOFING SHEETS.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	1/5192	20
LOCATION:	AREA P	
ACTIVITY:		
EAST ELEVATION OF BUILDING A271.		
SPECIAL FEATURES:		
OVERGROWN WITH TREES AND SHRUBS. ASBESTOS ROOFING SHEETS.		




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	1/5192	21
LOCATION:	AREA P	
ACTIVITY:		
EAST ELEVATION OF BUILDING A271.		
SPECIAL FEATURES:		
OVERGROWN WITH TREES AND SHRUBS. ASBESTOS ROOFING SHEETS.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	1/5192	22
LOCATION:	AREA P	
ACTIVITY:		
EAST ELEVATION OF BUILDING A273.		
SPECIAL FEATURES:		
ASBESTOS ROOFING AND GABLE CLADDING.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	1/5192	23
LOCATION:	AREA P	
ACTIVITY:		
WEST ELEVATION OF BUILDING A273.		
SPECIAL FEATURES:		
ASBESTOS ROOF SHEETING.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	1/5192	24
LOCATION:	AREA P	
ACTIVITY:		
SOUTH WEST ELEVATION OF BUILDING A272.		
SPECIAL FEATURES:		

ASPHALTED FLAT ROOF.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	1/5192	25
LOCATION:	AREA P	
ACTIVITY:		
EAST ELEVATION OF BUILDING A282.		

SPECIAL FEATURES:
ASBESTOS WALL AND ROOF CLADDING.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	1/5192	26
LOCATION:	AREA P	
ACTIVITY:		




EAST ELEVATION OF BUILDING A284.

SPECIAL FEATURES:

ASBESTOS ROOF AND GABLE CLADDING SHEETS.  
OVERGROWN WITH TREES AND SHRUBS.

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	1/5192	27

LOCATION:	AREA P	
ACTIVITY:		
EAST ELEVATION OF BUILDING A284.		
SPECIAL FEATURES:		
ASBESTOS ROOF AND GABLE SHEETING. OVERGROWN WITH TREES AND SHRUBS.		
		

<b>FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD</b>		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:

OCT '92	1/5192	28
LOCATION:	AREA P	
ACTIVITY:		
VIEW FROM BUILDING A269 (UPSTAIRS) - LOOKING WEST AT: BUILDING A266 (CENTRE OF PICTURE) BUILDING A230 (TOP RIGHT OF PICTURE) BUILDING A288 (BOTTOM LEFT OF PICTURE)		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	1/5192	29
LOCATION:	AREA P	
ACTIVITY:		
VIEW (LOOKING WEST) SHOWING THE ROOF OF BUILDING A273 IN THE FOREGROUND.		
SPECIAL FEATURES:		
GENERAL USE OF ASBESTOS CLADDING TO ROOFS.		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	1/5192	30

LOCATION:	AREA P
-----------	--------

ACTIVITY:


VIEW (LOOKING SOUTH WEST) SHOWING THE ROOF OF BUILDING A272.

SPECIAL FEATURES:


ASBESTOS ROOFING SHEETS.  
OVERGROWN TREES AND SHRUBS.

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	1/5192	31
LOCATION:	AREA P	
ACTIVITY:		
WEST ELEVATION OF POWDERMILL LANE GATES (WOODEN) (GATES BETWEEN A269 AND A238)		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	1/5192	32
LOCATION:	AREA P	
ACTIVITY:		
WEST ELEVATION OF POWDERMILL LANE GATES LEADING OFF POWDERMILL LANE.		
SPECIAL FEATURES:		
CANON AND CANON BALL BOLLARDS.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	1/5192	33
LOCATION:	AREA S	
ACTIVITY:		
REMOVAL OF ASBESTOS FROM TETRYL DRYING STOVES.		
SPECIAL FEATURES:		
GENERAL CONDITION OF ASBESTOS VERY POOR.		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	1/5192	34
LOCATION:	AREA M	
ACTIVITY:		
INTERNAL VIEW OF BUILDING L162.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	1/5192	35
LOCATION:	AREA M	
ACTIVITY:		
INTERNAL VIEW OF BUILDING L162.		
SPECIAL FEATURES:		
ASBESTOS ROOF SHEETING, ASBESTOS PIPE LAGGING.		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	1/5192	36
LOCATION:	AREA S	
ACTIVITY:		
ASBESTOS COLLECTION FROM TETRYL DRYING STOVES.		
SPECIAL FEATURES:		

DIFFICULT, OVERGROWN AND BOGGY, TERRAIN.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	1/5192	37
LOCATION:	AREA S	
ACTIVITY:		
ASBESTOS COLLECTION FROM TETRYL DRYING STOVES.		

SPECIAL FEATURES:
DIFFICULT, OVERGROWN AND BOGGY, TERRAIN.

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	2/5193	1

LOCATION:	AREA S - NORTH EAST OF WATERMAN'S COTTAGE
-----------	---

ACTIVITY:
SURFACE WATER EARTHENWARE DRAIN.

SPECIAL FEATURES:

--

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDICATION RECORD**


DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	2/5193	2

LOCATION:	AREA S - ADJACENT TO BUILDING 96A
-----------	-----------------------------------

ACTIVITY:
ASBESTOS SHEETING AS FOUND.


SPECIAL FEATURES:
GENERAL POOR CONDITION OF SHEETS, FRAGMENTED AND RELEASING FIBRES.

--




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	2/5193	3
LOCATION:	AREA S - BUILDING 96A	
ACTIVITY:		
ASBESTOS SHEETING AS FOUND.		
SPECIAL FEATURES:		
GENERAL POOR CONDITION OF SHEETS, FRAGMENTED AND RELEASING FIBRES.		







FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	2/5193	4
LOCATION:	AREA S - ADJACENT TO BUILDING 98A	
ACTIVITY:		
ASBESTOS SHEETING AS FOUND.		
SPECIAL FEATURES:		
GENERAL POOR CONDITION OF SHEETS, FRAGMENTED AND RELEASING FIBRES.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	2/5193	5
LOCATION:	AREA S - TETRYL STOVES	
ACTIVITY:		
COLLECTING LABORATORY GLASSWARE AND BOTTLED CHEMICALS.		
SPECIAL FEATURES:		
MOST BOTTLES MISSING THEIR I.D. LABELLING.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	2/5193	6
LOCATION:	AREA S	
ACTIVITY:		
SITE CLEARANCE PLANT TO ENABLE ACCESS FOR GENERAL CLEARANCE WORKS.		
SPECIAL FEATURES:		
DIFFICULT ACCESS.		



<b>FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD</b>		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	2/5193	7
LOCATION:	AREA M	
ACTIVITY:		
SOUTH EAST ELEVATION OF BUILDING L113.		
SPECIAL FEATURES:		
GENERAL POOR CONDITION.		



<b>FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD</b>		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	2/5193	8
LOCATION:	AREA M	
ACTIVITY:		
NORTH WEST ELEVATION OF BUILDING L113.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	2/5193	9
LOCATION:	AREA M	
ACTIVITY:		
SOUTH WEST ELEVATION OF BUILDING L112.		
SPECIAL FEATURES:		

SOLVENT STORAGE FACILITY.  
ASBESTOS SHEET ROOFING.

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	2/5193	10
LOCATION:	AREA M	
ACTIVITY:		
NORTH EAST ELEVATION OF BUILDING L112.		

SPECIAL FEATURES:
SOLVENT STORAGE FACILITY.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	2/5193	11
LOCATION:	AREA M	
ACTIVITY:		



WEST ELEVATION OF BUILDING L197.

SPECIAL FEATURES:

AIR RAID SHELTER.  
ASBESTOS END PANELS.



**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	2/5193	12

LOCATION:	AREA M	
ACTIVITY:		
EAST ELEVATION OF BUILDING L197.		
SPECIAL FEATURES:		
AIR RAID SHELTER. ASBESTOS END PANELS.		

<b>FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD</b>		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	2/5193	14
LOCATION:	AREA M	
ACTIVITY:		
WEST ELEVATION OF BUILDING L161.		
SPECIAL FEATURES:		
GARAGE / STORE.		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	2/5193	15

LOCATION:	AREA M
-----------	--------

ACTIVITY:


NORTH ELEVATION OF BUILDING L161.

SPECIAL FEATURES:


GARAGE / STORE.  
GENERAL POOR CONDITION.

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	2/5193	16
LOCATION:	AREA M	
ACTIVITY:		
NORTH ELEVATION OF BUILDING L162.		
SPECIAL FEATURES:		
LABOUR POOL / STORE. GENERAL POOR CONDITION.		




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	2/5193	17
LOCATION:	AREA M	
ACTIVITY:		
SOUTH ELEVATION OF BUILDING L162.		
SPECIAL FEATURES:		
GREENHOUSE AT REAR OF BUILDING L162. GENERAL POOR CONDITION.		




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	2/5193	18
LOCATION:	AREA M	
ACTIVITY:		
EAST ELEVATION OF BUILDING L163.		
SPECIAL FEATURES:		
AIR RAID SHELTER. OVERGROWN WITH VEGETATION.		






FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	2/5193	19
LOCATION:	AREA M	
ACTIVITY:		
NORTH EAST ELEVATION OF BUILDING L163.		
SPECIAL FEATURES:		
OVERGROWN WITH VEGETATION.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	2/5193	20
LOCATION:	AREA M	
ACTIVITY:		
NORTH ELEVATION OF BUILDING L127.		
SPECIAL FEATURES:		
GARAGE WITH VEHICLE HOIST WITHIN ASBESTOS CLADDING.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	2/5193	21
LOCATION:	AREA M	
ACTIVITY:		
SOUTH WEST ELEVATION OF BUILDING L127.		
SPECIAL FEATURES:		

GARAGE.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	2/5193	22
LOCATION:	AREA M	
ACTIVITY:		
NORTH WEST ELEVATION OF No. 1 GREENHOUSE.		

SPECIAL FEATURES:
GENERAL POOR CONDITION.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	2/5193	23
LOCATION:	AREA M	
ACTIVITY:		

ELEVATION OF No. 2 GREENHOUSE.
SPECIAL FEATURES:
GENERAL POOR CONDITION.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	2/5193	24

LOCATION:	AREA M	
ACTIVITY:		
NORTH ELEVATION OF BUILDING L169.		
SPECIAL FEATURES:		
FORMER PRESS HOUSE LOCATION, LATER, WORKSHOP FACILITY. ASBESTOS ROOF SHEETING.		

<b>FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD</b>		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	2/5193	26
LOCATION:	AREA M	
ACTIVITY:		
SOUTH WEST ELEVATION OF BUILDING L169.		
SPECIAL FEATURES:		
FORMER PRESS HOUSE LOCATION, LATER - WORKSHOP FACILITY. ASBESTOS ROOF SHEETING.		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	2/5193	27

LOCATION:	AREA M
-----------	--------

ACTIVITY:


EAST ELEVATION OF BUILDING L173.

SPECIAL FEATURES:


TELEPHONE EXCHANGE.  
GENERAL POOR CONDITION.

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	2/5193	28
LOCATION:	AREA M	
ACTIVITY:		
NORTH ELEVATION OF BUILDING L173.		
SPECIAL FEATURES:		
TELEPHONE EXCHANGE. GENERAL POOR CONDITION.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	2/5193	29
LOCATION:	AREA P	
ACTIVITY:		
EAST ELEVATION OF BUILDING A210(D).		
SPECIAL FEATURES:		
WELDING SHOP (FOREGROUND). BUILDING A210 - MACHINE SHOP IN BACKGROUND.		




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	2/5193	30
LOCATION:	AREA P	
ACTIVITY:		
NORTH ELEVATION OF BUILDING A210(D).		
SPECIAL FEATURES:		
WELDING SHOP.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	2/5193	31
LOCATION:	AREA P	
ACTIVITY:		
EAST ELEVATION OF BUILDING A211.		
SPECIAL FEATURES:		
CONTROL ROOM. ASBESTOS ROOF SHEETING.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	2/5193	32
LOCATION:	AREA P	
ACTIVITY:		
SOUTH WEST ELEVATION OF BUILDING A211.		
SPECIAL FEATURES:		
CONTROL ROOM. ASBESTOS SHEET ROOFING.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	2/5193	33
LOCATION:	AREA P	
ACTIVITY:		
NORTH ELEVATION OF BUILDING A212.		
SPECIAL FEATURES:		



WATER SOFTENING PLANT FACILITY.  
ASBESTOS ROOF SHEETING.

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	2/5193	34
LOCATION:	AREA P	
ACTIVITY:	EAST ELEVATION OF BUILDING A212.	

SPECIAL FEATURES:
<p>WATER SOFTENING PLANT FACILITY.          ASBESTOS ROOF SHEETING.          (BUILDING A210 IN BACKGROUND).</p>

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	2/5193	35
LOCATION:	AREA P	
ACTIVITY:		

NORTH EAST ELEVATION OF BUILDING A219.

SPECIAL FEATURES:

TRANSPORT OFFICES.



**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	2/5193	36

LOCATION:	AREA P	
ACTIVITY:		
SOUTH EAST ELEVATION OF BUILDING A219.		
SPECIAL FEATURES:		
TRANSPORT OFFICES.		

<b>FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD</b>		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:

OCT '92	2/5193	37
LOCATION:	AREA P	
ACTIVITY:		
SOUTH WEST ELEVATION OF BUILDING A219.		
SPECIAL FEATURES:		
TRANSPORT OFFICES.		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	3/5903	1

LOCATION:	AREA P
-----------	--------

ACTIVITY:

SOUTH ELEVATION OF BUILDING A210(B) - SOUTH CONCRETE BUNKER.

SPECIAL FEATURES:

CONCRETE BUNKER.  
GENERAL POOR CONDITION.

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**


DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	3/5903	2

LOCATION:	AREA P
-----------	--------

ACTIVITY:
WEST ELEVATION OF BUILDING A210(B) SOUTH CONCRETE BUNKER.


SPECIAL FEATURES:
WEST ELEVATION OF CONCRETE BUNKER. GENERAL POOR CONDITION.

--




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	3/5903	3
LOCATION:	AREA P	
ACTIVITY:		
WEST ELEVATION OF BUILDING A210(A) - NORTH CONCRETE BUNKER.		
SPECIAL FEATURES:		
GENERAL POOR CONDITION.		






FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	3/5903	4
LOCATION:	AREA P	
ACTIVITY:		
EAST ELEVATION OF BUILDING A210(A) - NORTH CONCRETE BUNKER.		
SPECIAL FEATURES:		
GENERAL POOR CONDITION.		



<b>FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD</b>		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	3/5903	5
LOCATION:	AREA P	
ACTIVITY:		
PHASE 1 DEMOLITION IN PROGRESS.		
SPECIAL FEATURES:		
ASBESTOS ROOFING AND TIMBERS REMOVED PRIOR TO MAIN DEMOLITION.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	3/5903	6
LOCATION:	AREA P	
ACTIVITY:		
PHASE 1 DEMOLITION IN PROGRESS.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	3/5903	7
LOCATION:	AREA P	
ACTIVITY:		
PHASE 1 DEMOLITION IN PROGRESS.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	3/5903	8
LOCATION:	AREA S	
ACTIVITY:		
PIPE WRAPPED WITH BLUE ASBESTOS BRAID.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	3/5903	9
LOCATION:	AREA S	
ACTIVITY:		
FALLEN TELEGRAPH POLE.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	3/5903	10
LOCATION:	AREA S	
ACTIVITY:		

CLEARANCE OF BUILDING 92(A).

SPECIAL FEATURES:

GENERALLY OVERGROWN WITH VEGETATION.



**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	3/5903	11



LOCATION:	AREA S	
ACTIVITY:		
CLEARANCE OF BUILDING 92(A).		
SPECIAL FEATURES:		

<b>FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD</b>		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:

OCT '92	3/5903	12
LOCATION:	AREA S	
ACTIVITY:		
CLEARED RAILWAY ROUTE ADJACENT TO BUILDINGS 93A AND 96A.		
SPECIAL FEATURES:		
CLEARANCE OF THIS ROUTE CARRIED OUT TO ENABLE ACCESS TO TETRYL DRYING STOVE BUILDINGS.		

**FORMER RARDE WALTHAM ABBEY NORTH SITE**

REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	3/5903	13
LOCATION:	AREA S	
ACTIVITY:		
CLEARED RAILWAY ROUTE ADJACENT TO BUILDINGS 93A AND 96A.		
SPECIAL FEATURES:		
CLEARANCE OF THIS ROUTE CARRIED OUT TO ENABLE ACCESS TO TETRYL DRYING STOVES.		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	3/5903	14

LOCATION:	AREA S (SSSI)
-----------	---------------

ACTIVITY:

TYPICAL STEAM MAIN THROUGH WOODS.

SPECIAL FEATURES:


GENERAL POOR CONDITION AND DIFFICULT ACCESS.

--


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	3/5903	15
LOCATION:	AREA S	
ACTIVITY:		
LONG WALK LOOKING NORTH (BUILDINGS 107 AND 108 ON LEFT)		
SPECIAL FEATURES:		
BLAST WALLS OF FORMER PRESS HOUSE 107 AND 108. GENERAL OVERGROWTH OF VEGETATION.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	3/5903	16
LOCATION:	AREA B / S	
ACTIVITY:		
BURNING GROUND - TEMPORARY ACCESS ROAD.		
SPECIAL FEATURES:		
PIPE BRIDGES OVER FORMER CANAL.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	3/5903	17
LOCATION:	AREA B / S	
ACTIVITY:		
BURNING GROUND - TEMPORARY ACCESS ROAD.		
SPECIAL FEATURES:		
PIPE BRIDGES OVER FORMER CANALS.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	3/5903	18
LOCATION:	AREA S	
ACTIVITY:		
ELEVATION OF WALL (BASE) OF BUILDING S46.		
SPECIAL FEATURES:		
ASBESTOS LAGGED STEAM PIPES WHICH FED DRYING RACKS. DRAIN EXIT PIPEWORK IN WALL.		





<b>FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD</b>		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	3/5903	19
LOCATION:	AREA S	
ACTIVITY:		
ELEVATION OF BUILDING S48 - BASE OF EXTERNAL WALL.		
SPECIAL FEATURES:		
ASBESTOS LAGGED STEAM PIPES.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	3/5903	20
LOCATION:	AREA S	
ACTIVITY:		
SITE CLEARANCE WORKS BY BUILDING 18.		
SPECIAL FEATURES:		
TREE FELLING.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	3/5903	21
LOCATION:	NOT NORTH SITE	
ACTIVITY:		
WALL PLAQUE - RE ENFIELD SITE (LOANED)		

SPECIAL FEATURES:
WOOD CARVING.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	3/5903	22
LOCATION:	NOT NORTH SITE	
ACTIVITY:		
WALL PLAQUE RE ENFIELD SITE (LOANED)		

SPECIAL FEATURES:
WOOD CARVING.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	3/5903	23
LOCATION:	NOT NORTH SITE	
ACTIVITY:		

WALL PLAQUE RE ENFIELD SITE (LOANED)

SPECIAL FEATURES:

WOOD CARVING.

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDICATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	3/5903	24

LOCATION:	NOT NORTH SITE	
ACTIVITY:		
WALL PLAQUE RE ENFIELD SITE (LOANED).		
SPECIAL FEATURES:		
WOOD CARVING.		

<b>FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD</b>		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:

OCT '92	3/5903	25
LOCATION:	NOT NORTH SITE	
ACTIVITY:		
WALL PLAQUE RE ENFIELD SITE (LOANED).		
SPECIAL FEATURES:		
WOOD CARVING.		



**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	4/5904	1

LOCATION:	AREA B
-----------	--------

ACTIVITY:

CONSTRUCTION OF ACCESS ROAD TO WEST SIDE OF BURNING GROUND.

SPECIAL FEATURES:

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**


DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	4/5904	2

LOCATION:	AREA B
-----------	--------


ACTIVITY:
CONSTRUCTION OF ACCESS ROAD TO WEST SIDE OF BURNING GROUND.

SPECIAL FEATURES:


--



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	4/5904	3
LOCATION:	AREA B	
ACTIVITY:		
CONSTRUCTION OF ACCESS ROAD TO WEST SIDE OF BURNING GROUND.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	4/5904	4
LOCATION:	AREA H	
ACTIVITY:		
NORTH EAST ELEVATION OF BUILDING H67.		
SPECIAL FEATURES:		
BUILDING USED FOR MECHANICAL TESTING. GENERAL POOR CONDITION.		



<b>FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD</b>		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	4/5904	5
LOCATION:	AREA H	
ACTIVITY:		
NORTH ELEVATION OF BUILDING H67.		
SPECIAL FEATURES:		
BUILDING USED FOR MECHANICAL TESTING. GENERAL POOR CONDITION.		



<b>FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD</b>		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	4/5904	6
LOCATION:	AREA H	
ACTIVITY:		
NORTH EAST ELEVATION OF BUILDING H67.		
SPECIAL FEATURES:		
BUILDING USED FOR MECHANICAL TESTING.		




<b>FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD</b>		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	4/5904	7
LOCATION:	AREA H	
ACTIVITY:		
SOUTH ELEVATION OF ENTRANCE TO BUILDING H67.		
SPECIAL FEATURES:		
BUILDING USED FOR MECHANICAL TESTING. GENERAL POOR CONDITION.		



<b>FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD</b>		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	4/5904	8
LOCATION:	AREA H	
ACTIVITY:		
SOUTH EAST ELEVATION OF BUILDING H68.		
SPECIAL FEATURES:		



BUILDING USED AS A TEST BED.  
GENERAL POOR CONDITION.



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	4/5904	9
LOCATION:	AREA H	
ACTIVITY:		
WEST ELEVATION OF BUILDING H68.		

SPECIAL FEATURES:
BUILDING USED AS A TEST BED. GENERAL POOR CONDITION.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	4/5904	10
LOCATION:	AREA H (NORTH OF BUILDING H68)	
ACTIVITY:		

SOUTH ELEVATION OF STRUCTURE H68A.
SPECIAL FEATURES:
FIRING TUNNEL / PCC PIPE.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	4/5904	11

LOCATION:	AREA H	
ACTIVITY:		
SOUTH EAST ELEVATION OF BUILDING H7.		
SPECIAL FEATURES:		
MAGAZINE.		

<b>FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD</b>		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:

OCT '92	4/5904	12
LOCATION:	AREA H	
ACTIVITY:		
NORTH ELEVATION OF BUILDING H7.		
SPECIAL FEATURES:		
MAGAZINE.		

FORMER RARDE WALTHAM ABBEY NORTH SITE

REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	4/5904	13
LOCATION:	AREA H	
ACTIVITY:		
SOUTH ELEVATION OF BUILDING H17.		
SPECIAL FEATURES:		
SEWER PUMPING STATION.		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	4/5904	14

LOCATION:	AREA H
-----------	--------


ACTIVITY:  
NORTH ELEVATION OF BUILDING H17.

SPECIAL FEATURES:  
SEWER PUMPING STATION.  
REMAINS IN USE SERVING BUILDINGS A203 / A201/2 / A200.


--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	4/5904	15
LOCATION:	AREA H	
ACTIVITY:		
SPECIAL FEATURES:		
ACTIVE SEWER PUMPING STATION.		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	4/5904	16
LOCATION:	AREA H	
ACTIVITY:		
NORTH WEST ELEVATION OF BUILDING H66.		
SPECIAL FEATURES:		
ASBESTOS ROOFING SHEETS. GENERAL POOR CONDITION. LOCKER MAGAZINE.		




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	4/5904	17
LOCATION:	AREA H	
ACTIVITY:		
SOUTH EAST ELEVATION OF BUILDING H66.		
SPECIAL FEATURES:		
ASBESTOS ROOFING SHEETS.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	4/5904	18
LOCATION:	AREA H	
ACTIVITY:		
EAST ELEVATION OF BUILDING H11.		
SPECIAL FEATURES:		
SOLVENT AND CHEMICAL STORE. OVERGROWN WITH TREES AND SHRUBS.		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	4/5904	19
LOCATION:	AREA H	
ACTIVITY:		
WEST ELEVATION OF BUILDING H11.		
SPECIAL FEATURES:		
SOLVENT AND CHEMICAL STORE.		



<b>FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD</b>		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	4/5904	20
LOCATION:	AREA H	
ACTIVITY:		
SOUTH WEST ELEVATION OF BUILDING H72.		
SPECIAL FEATURES:		
COMPRESSOR HOUSE FOR BUILDING H67.		

GENERAL POOR CONDITION.  
OVERGROWN WITH VEGETATION.



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	4/5904	21
LOCATION:	AREA H	
ACTIVITY:		
NORTH WEST ELEVATION OF BUILDING H72.		

SPECIAL FEATURES:		
COMPRESSOR HOUSE FOR BUILDING H67.		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	4/5904	22
LOCATION:	AREA H	
ACTIVITY:		
SOUTH WEST ELEVATION OF BUILDING H72(A).		

SPECIAL FEATURES:
BIKE SHED. CORROGATED STEEL SHEETING.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	4/5904	23
LOCATION:	AREA H	



ACTIVITY:	
SOUTH WEST ELEVATION OF BUILDING H69.	
SPECIAL FEATURES:	
MAGAZINE. GENERAL POOR CONDITION.	

<b>FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD</b>		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:

OCT '92	4/5904	24
LOCATION:	AREA H	
ACTIVITY:		
NORTH ELEVATION OF BUILDING H69.		
SPECIAL FEATURES:		
MAGAZINE. GENERAL POOR CONDITION.		

FORMER RARDE WALTHAM ABBEY NORTH SITE

REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	4/5904	25
LOCATION:	AREA H	
ACTIVITY:		
SOUTH WEST ELEVATION OF BUILDING H70.		
SPECIAL FEATURES:		
SOLVENT STORE. GENERAL POOR CONDITION.		


**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	4/5904	26

LOCATION:	AREA H
-----------	--------


ACTIVITY:  
NORTH EAST ELEVATION OF BUILDING H70.

SPECIAL FEATURES:  
SOLVENT STORE.  
BUILDING H67 IN BACKGROUND.




--


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	4/5904	27
LOCATION:	AREA L	
ACTIVITY:		
SOUTH WEST ELEVATION OF BUILDING L165.		
SPECIAL FEATURES:		
ASBESTOS SHEET CANOPY AND LEANTO HAS BEEN REMOVED.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	4/5904	28
LOCATION:	AREA L	
ACTIVITY:		
NORTH WEST ELEVATION OF BUILDING L165.		
SPECIAL FEATURES:		
ASBESTOS SHEET CANOPY AND LEANTO HAS BEEN REMOVED.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	4/5904	29
LOCATION:	AREA H	
ACTIVITY:		
NORTH ELEVATION OF BUILDING H65.		
SPECIAL FEATURES:		
LOCKER MAGAZINE. GENERAL POOR CONDITION.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	4/5904	30
LOCATION:	AREA H	
ACTIVITY:		
SOUTH ELEVATION OF BUILDING H65.		
SPECIAL FEATURES:		
LOCKER MAGAZINE. GENERAL POOR CONDITION.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	4/5904	31
LOCATION:	AREA H	
ACTIVITY:		
SOUTH EAST ELEVATION OF BUILDING H13.		
SPECIAL FEATURES:		
ENGINE SHET / METAL STORE. GENERAL POOR CONDITION / STRUCTURAL FAILURE TO LINTEL OVER MAIN DOORS.		



**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	4/5904	32

LOCATION:	AREA H
-----------	--------

ACTIVITY:  
NORTH WEST ELEVATION OF BUILDING H13.

SPECIAL FEATURES:  
ENGINE SHET / METAL STORE.

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**


DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	4/5904	33

LOCATION:	AREA H
-----------	--------


ACTIVITY:
NORTH WEST ELEVATION OF BUILDING H12.

SPECIAL FEATURES:
REEL MAGAZINE / FIRING POINT. GENERAL POOR CONDITION.


--



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	4/5904	34
LOCATION:	AREA H	
ACTIVITY:		
INTERNAL ELEVATION OF BUILDING H12.		
SPECIAL FEATURES:		
REEL MAGAZINE / FIRING POINT. GENERAL POOR CONDITION.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	4/5904	35
LOCATION:	AREA H	
ACTIVITY:		
INTERNAL ELEVATION OF BUILDING H12.		
SPECIAL FEATURES:		
REEL MAGAZINE / FIRING POINT. GENERAL POOR CONDITION.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	4/5904	36
LOCATION:	AREA H	
ACTIVITY:		
SOUTH WEST ELEVATION OF BUILDING H14.		
SPECIAL FEATURES:		
STORE SHED / MAGAZINE. GENERAL POOR CONDITION.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	4/5904	37
LOCATION:	AREA H	
ACTIVITY:		
NORTH EAST ELEVATION OF BUILDING H14.		
SPECIAL FEATURES:		
STORE SHED / MAGAZINE.		





**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	5/6285	1

LOCATION:	AREA H
-----------	--------

ACTIVITY:  
SOUTH WEST ELEVATION OF BUILDING H15.

SPECIAL FEATURES:  
CONCRETE AIR RAID SHELTER.

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**


DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	5/6285	2

LOCATION:	AREA H
-----------	--------


ACTIVITY:
SOUTH WEST ELEVATION OF BUILDING H15.

SPECIAL FEATURES:
CONCRETE AIR RAID SHELTER.


--



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	5/6285	3
LOCATION:	AREA H	
ACTIVITY:		
SOUTH WEST ELEVATION OF BUILDING H24.		
SPECIAL FEATURES:		
SEWAGE PUMP HOUSE.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	5/6285	4
LOCATION:	AREA H	
ACTIVITY:		
NORTH EAST ELEVATION OF BUILDING H24.		
SPECIAL FEATURES:		
SEWAGE PUMP HOUSE.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	5/6285	5
LOCATION:	AREA H	
ACTIVITY:		
EAST ELEVATION OF BUILDING H23.		
SPECIAL FEATURES:		
STORAGE SHED.		




<b>FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD</b>		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	5/6285	6
LOCATION:	AREA H	
ACTIVITY:		
SOUTH WEST ELEVATION OF BUILDING H23.		
SPECIAL FEATURES:		
STORAGE SHED OVERGROWN WITH VEGETATION.		



<b>FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD</b>		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	5/6285	7
LOCATION:	AREA H	
ACTIVITY:		
SOUTH ELEVATION OF BUILDING H23.		
SPECIAL FEATURES:		
STORAGE SHED OVERGROWN WITH VEGETATION.		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	5/6285	8
LOCATION:	AREA H	
ACTIVITY:		
EAST ELEVATION OF BUILDING H25.		
SPECIAL FEATURES:		

SURGERY / WOMENS HOSPITAL / FLATS.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	5/6285	9
LOCATION:	AREA H	
ACTIVITY:		
WEST ELEVATION OF BUILDING H25.		

SPECIAL FEATURES:
SURGERY / WOMENS HOSPITAL / FLATS.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	5/6285	10
LOCATION:	AREA H	
ACTIVITY:		

WEST ELEVATION OF BUILDING H25(A).

SPECIAL FEATURES:

GENERAL POOR CONDITION.



**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	5/6285	11

LOCATION:	AREA H	
ACTIVITY:		
SOUTH ELEVATION OF BUILDING H26.		
SPECIAL FEATURES:		
SANDHURST RESIDENTIAL HOSPITAL. GENERAL POOR CONDITION.		

<b>FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD</b>		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:

NOV '92	5/6285	12
LOCATION:	AREA H	
ACTIVITY:		
EAST ELEVATION OF BUILDING H26.		
SPECIAL FEATURES:		
SANDHURST RESIDENTIAL HOSPITAL.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	5/6285	13
LOCATION:	AREA H	
ACTIVITY:		
NORTH WEST ELEVATION OF BUILDING H26.		
SPECIAL FEATURES:		
SANDHURST RESIDENTIAL HOSPITAL. GENERAL POOR CONDITION.		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	5/6285	14

LOCATION:	AREA H
-----------	--------


ACTIVITY:  
SOUTH WEST ELEVATION OF BUILDING H26.

SPECIAL FEATURES:  
SANDHURST RESIDENTIAL HOSPITAL.  
GENERAL POOR CONDITION.




--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	5/6285	15
LOCATION:	AREA P	
ACTIVITY:		
EAST ELEVATION OF BUILDING A235.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	5/6285	16
LOCATION:	AREA P	
ACTIVITY:		
NORTH ELEVATION OF LINK BETWEEN BUILDING A238 AND A234.		
SPECIAL FEATURES:		
SHOWING DEMOLITION.		




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	5/6285	17
LOCATION:	AREA P	
ACTIVITY:		
NORTH ELEVATION OF LINK BETWEEN BUILDING A238 AND A234.		
SPECIAL FEATURES:		
SHOWING DEMOLITION.		




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	5/6285	18
LOCATION:	AREA S	
ACTIVITY:		
ELEVATION OF BUILDING ARS 1		
SPECIAL FEATURES:		
(AIR RAID SHELTER) GENERAL POOR CONDITION AND OVERGROWN WITH VEGETATION.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	5/6285	19
LOCATION:	AREA S	
ACTIVITY:		
ELEVATION OF BUILDING ARS 1.		
SPECIAL FEATURES:		
(AIR RAID SHELTER) GENERAL POOR CONDITION AND OVERGROWN WITH VEGETATION.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	5/6285	21
LOCATION:	AREA N	
ACTIVITY:		
SQUIRREL EATING AN APPLE.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	5/6285	22
LOCATION:	AREA N	
ACTIVITY:		
SITE WASTE TRANSFER STATION.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	5/6285	23
LOCATION:	AREA N	
ACTIVITY:		



SITE WASTE TRANSFER STATION.

SPECIAL FEATURES:

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	5/6285	24

LOCATION:	AREA S	
ACTIVITY:		
MINI EXCAVATOR EN-ROUTE TO NEXT TASK.		
SPECIAL FEATURES:		

<b>FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD</b>		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:

NOV '92	5/6285	25
LOCATION:	AREA S	
ACTIVITY:		
R.O. SUPERVISOR CO-ORDINATING SITE WORK WITH TREE FELLING GANG.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	5/6285	26
LOCATION:	AREA S	
ACTIVITY:		
SOUTH WEST ELEVATION OF BUILDING S34 BLAST WALL.		
SPECIAL FEATURES:		
OVERGROWN WITH VEGETATION AND TREES.		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDICATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	5/6285	27


LOCATION:	AREA S
-----------	--------

ACTIVITY:


NEWTONS POOL / SOUTH WEST ELEVATION OF BUILDING S34 BLAST WALL.

SPECIAL FEATURES:


NEWTONS POOL - OVERWATER CABLEWAY GANTRY IN FOREGROUND.



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	5/6285	28
LOCATION:	AREA S	
ACTIVITY:		
NEWTONS POOL - OVERWATER CABLEWAY EQUIPMENT VIEWED FROM THE WEST.		
SPECIAL FEATURES:		
GENERAL POOR CONDITION. NEWTONS POOL IN BACKGROUND.		




<b>FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD</b>		
<b>DATE:</b>	<b>NEGATIVE REFERENCE:</b>	<b>FRAME REFERENCE:</b>
NOV '92	5/6285	29
<b>LOCATION:</b>	<b>AREA S</b>	
<b>ACTIVITY:</b>		
VIEW LOOKING NORTH EAST - BUILDING S34.		
<b>SPECIAL FEATURES:</b>		
DEPOSITED DEBRIS IN FOREGROUND.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	5/6285	30
LOCATION:	AREA S	
ACTIVITY:		
SOUTH WEST ELEVATION OF NEWTONS POOL WEIR.		
SPECIAL FEATURES:		
GENERAL POOR CONDITION.		






FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	5/6285	31
LOCATION:	AREA S	
ACTIVITY:		
NORTH ELEVATION OF BUILDING 46A.		
SPECIAL FEATURES:		
NEWTONS POOL IN FOREGROUND.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	5/6285	32
LOCATION:	AREA S	
ACTIVITY:		
ELEVATION OF AIR RAID SHELTER ADJACENT TO BUILDING 14.		
SPECIAL FEATURES:		
(BUILDING 14 - GUNCOTTON STOVE / BURNT OUT)		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	5/6285	33
LOCATION:	AREA S	
ACTIVITY:		
No. 1 BORE HOLE NORTH OF SSSI.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	5/6285	34
LOCATION:	AREA S	
ACTIVITY:		
EAST PERIMETER ROAD LOOKING SOUTH WEST.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	5/6285	35
LOCATION:	AREA S	
ACTIVITY:		

VESSEL FOUND ADJACENT TO BUILDING 14.

SPECIAL FEATURES:

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	5/6285	36

LOCATION:	AREA S	
ACTIVITY:		
WEST PERIMETER FENCE - DISTRESSED ROOK RESCUED.		
SPECIAL FEATURES:		

<b>FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD</b>		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:

NOV '92	5/6285	37
LOCATION:	AREA S	
ACTIVITY:		
R.O. SUPERVISOR WITH ROOK - ALONG THE WEST PERIMETER FENCE.		
SPECIAL FEATURES:		



**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	6/6286	1

LOCATION:	AREA M
-----------	--------

ACTIVITY:  
VIEW SHOWING JCB KNOCKING ROOF IN OF BUILDING L117.

SPECIAL FEATURES:  
PREPARATION FOR FIRING.

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**


DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	6/6286	2

LOCATION:	AREA P
-----------	--------


ACTIVITY:
SOUTHERN ASPECT OF BUILDING A210 - DEMOLITION OF CONCRETE BUNKER IN PROGRESS.

SPECIAL FEATURES:
MACHINE IS ABLE TO SEPARATE REINFORCEMENT FROM THE CONCRETE.


--



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	6/6286	3
LOCATION:	AREA P	
ACTIVITY:		
SOUTHERN ASPECT OF BUILDING A210 SHOWING 'PULVERISOR' FITTED TO 360 EXCAVATOR.		
SPECIAL FEATURES:		
MACHINE USED FOR 'CRUNCHING' CONCRETE DURING DEMOLITION.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	6/6286	4
LOCATION:	AREA S	
ACTIVITY:		
DAMPING DOWN BUILDING 22A AFTER FIRING OF EXTERNAL AIR DUCTWORK.		
SPECIAL FEATURES:		
2 MAN FIRE HOSE.		



<b>FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD</b>		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	6/6286	5
LOCATION:	AREA S	
ACTIVITY:		
DAMPING DOWN BUILDING 22A AFTER FIRING OF EXTERNAL AIR DUCTWORK.		
SPECIAL FEATURES:		



<b>FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD</b>		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	6/6286	6
LOCATION:	AREA P (BUILDING A230)	
ACTIVITY:		
INTERNAL VIEW OF R.O. PROJECT OFFICE.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	6/6286	7
LOCATION:	AREA P (BUILDING A230)	
ACTIVITY:		
INTERNAL VIEW OF R.O. PROJECT OFFICE.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	6/6286	8
LOCATION:	AREA S	
ACTIVITY:		
EAST ELEVATION OF BUILDING 22A.		
SPECIAL FEATURES:		



QUINAN STOVE / DERELICT



**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	6/6286	9
LOCATION:	AREA S	
ACTIVITY:	NORTH ELEVATION OF BUILDING 22A.	

SPECIAL FEATURES:
QUINAN STOVE (DERELICT)

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	6/6286	10
LOCATION:	AREA S	
ACTIVITY:		

SOUTH WEST ELEVATION OF BUILDING 22A SHOWING FRONT DUCTING.

SPECIAL FEATURES:

DUCTWORK AFTER FIRING.



**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	6/6286	11

LOCATION:	AREA S	
ACTIVITY:		
PART NORTH ELEVATION OF BUILDING 22A.		
SPECIAL FEATURES:		
QUINAN STOVE (DERELICT). BLAST WALL TO THE RIGHT.		

<b>FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD</b>		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:

NOV '92	6/6286	12
LOCATION:	AREA S	
ACTIVITY:		
SOUTH ELEVATION OF BUILDING E10.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	6/6286	13
LOCATION:	AREA S	
ACTIVITY:		
EAST ELEVATION OF BUILDING E10.		
SPECIAL FEATURES:		
SAFETY STORE.		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	6/6286	14

LOCATION:	AREA S
-----------	--------


ACTIVITY:  
WEST ELEVATION OF BUILDING E6.

SPECIAL FEATURES:  
CONTROL ROOM.


--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	6/6286	15
LOCATION:	AREA S	
ACTIVITY:		
NORTH EAST ELEVATION OF BUILDING E6.		
SPECIAL FEATURES:		
CONTROL ROOM.		






FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	6/6286	16
LOCATION:	AREA S	
ACTIVITY:		
SOUTH WEST ELEVATION SHOWING ENTRANCE TO BUILDING E15.		
SPECIAL FEATURES:		
GENERATOR ROOM.		




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	6/6286	17
LOCATION:	AREA S	
ACTIVITY:		
NORTH EAST ELEVATION OF BUILDING E15.		
SPECIAL FEATURES:		
GENERATOR ROOM.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	6/6286	18
LOCATION:	AREA S	
ACTIVITY:		
NORTH WEST ELEVATION OF BUILDING E9.		
SPECIAL FEATURES:		
REFRIGERATION HOUSE.		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	6/6286	19
LOCATION:	AREA S	
ACTIVITY:		
SOUTH WEST ELEVATION OF BUILDING E9.		
SPECIAL FEATURES:		
REFRIGERATION HOUSE.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	6/6286	20
LOCATION:	AREA S	
ACTIVITY:		
WEST ELEVATION OF BUILDING E2.		
SPECIAL FEATURES:		
NITRATION PLANT.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	6/6286	21
LOCATION:	AREA S	
ACTIVITY:		
SOUTH WEST ELEVATION OF BUILDING E2.		

SPECIAL FEATURES:	
NITRATION PLANT.	

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	6/6286	22
LOCATION:	AREA S	
ACTIVITY:		
INTERNAL ELEVATION OF BUILDING E2.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	6/6286	23
LOCATION:	AREA S	
ACTIVITY:		



INTERNAL VIEW OF BUILDING E2.

SPECIAL FEATURES:

NITRATION PLANT.

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDICATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	6/6286	24

LOCATION:	AREA S	
ACTIVITY:		
SOUTH WEST ELEVATION OF ENTRANCE TO BUILDING E2.		
SPECIAL FEATURES:		
NITRATION PLANT.		

<b>FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD</b>		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:

NOV '92	6/6286	25
LOCATION:	AREA S	
ACTIVITY:		
ELEVATION OF BUILDING U6.		
SPECIAL FEATURES:		
SMALL STORAGE HUT OVERGROWN BY TREES.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	6/6286	26
LOCATION:	AREA S	
ACTIVITY:		
ELEVATION OF BUILDING U6.		
SPECIAL FEATURES:		
SMALL STORAGE HUT OVERGROWN BY TREES.		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	6/6286	27


LOCATION:	AREA S
-----------	--------

ACTIVITY:  
SOUTH ELEVATION OF BUILDING S31.


SPECIAL FEATURES:

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	6/6286	28
LOCATION:	AREA S	
ACTIVITY:		
NORTH EAST INTERNAL ELEVATION OF BUILDING S31.		
SPECIAL FEATURES:		
BLAST WALLS ONLY REMAIN, VIEWED FROM DRY CANAL.		




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	6/6286	29
LOCATION:	AREA S	
ACTIVITY:		
SOUTH EAST ELEVATION OF BUILDING S90.		
SPECIAL FEATURES:		
DERELICT BOILER HOUSE.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	6/6286	30
LOCATION:	AREA S	
ACTIVITY:		
NORTH WEST ELEVATION OF BUILDING S90.		
SPECIAL FEATURES:		
DERELICT BOILER HOUSE.		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	6/6286	31
LOCATION:	AREA S	
ACTIVITY:		
SOUTH EAST ELEVATION OF BUILDING S90.		
SPECIAL FEATURES:		
OVERGROWN WITH VEGETATION, DECAYING MASONRY.		



<b>FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD</b>		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	6/6286	32
LOCATION:	AREA S	
ACTIVITY:		
NORTH ELEVATION OF BUILDING S90.		
SPECIAL FEATURES:		
OVERGROWN WITH VEGETATION, DECAYING MASONRY.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	6/6286	33
LOCATION:	AREA S	
ACTIVITY:		
WEST INTERNAL ELEVATION OF BUILDING S30.		
SPECIAL FEATURES:		
BLAST WALLS ONLY REMAIN, VIEWED FROM DRY CANAL.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	6/6286	34
LOCATION:	AREA S	
ACTIVITY:		
SOUTH WEST ELEVATION OF BUILDING S29.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	6/6286	35
LOCATION:	AREA S	
ACTIVITY:		
NORTH EAST ELEVATION OF BUILDING S29.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	6/6286	36
LOCATION:	AREA S	
ACTIVITY:		

NORTH EAST ELEVATION OF BUILDING S29A.

SPECIAL FEATURES:

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDICATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	6/6286	37

LOCATION:	AREA S
ACTIVITY:	
NORTH WEST ELEVATION OF BUILDING S29A.	
SPECIAL FEATURES:	




**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	7/6287	1
LOCATION:	GENERAL	
ACTIVITY:		
ROAD SWEEPER.		
SPECIAL FEATURES:		
SITE ROAD NETWORK SWEEPED ON A REGULAR BASIS - ARISINGS KEPT ON SITE FOR CORRECT DISPOSAL.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	7/6287	2
LOCATION:	AREA P - SITE ENTRANCE (POWDERMILL LANE)	
ACTIVITY:		
ESSEX FIRE & RESCUE SERVICE VEHICLE.		
SPECIAL FEATURES:		
VISIT BY LOCAL FIRE BRIGADE TO FAMILIARISE THEMSELVES WITH SITE ACCESS ETC.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	7/6287	3
LOCATION:	AREA H - ISLAND SITE	
ACTIVITY:		
NORTH EAST ELEVATION OF BUILDING A201 / 202.		
SPECIAL FEATURES:		
ASBESTOS CLAD BIKESHED.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	7/6287	4
LOCATION:	AREA H - ISLAND SITE	
ACTIVITY:		
NORTH ELEVATION OF BUILDING A201 / 202.		
SPECIAL FEATURES:		

ASBESTOS CLAD BIKESHED.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	7/6287	5
LOCATION:	AREA H - ISLAND SITE	
ACTIVITY:		
EAST ELEVATION OF BUILDING A291.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	7/6287	6


LOCATION:	AREA H - ISLAND SITE	
ACTIVITY:		
NORTH EAST ELEVATION OF BUILDING A291.		
SPECIAL FEATURES:		
OVERGROWTH OF VEGETATION.		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	7/6287	7
LOCATION:	AREA H - ISLAND SITE	
ACTIVITY:		
SOUTH EAST ELEVATION OF BUILDING A292.		
SPECIAL FEATURES:		



--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	7/6287	8
LOCATION:	AREA H - ISLAND SITE	
ACTIVITY:		
WEST FACE OF BUILDING A292.		
SPECIAL FEATURES:		
FENCE GUARDING SETTLEMENT PIT.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	7/6287	9
LOCATION:	AREA H	
ACTIVITY:		
NORTH EAST ELEVATION OF BUILDING H1.		
SPECIAL FEATURES:		
PREFABRICATED STRUCTURE.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	7/6287	10
LOCATION:	AREA H	
ACTIVITY:		
WEST ELEVATION OF BUILDING H1.		
SPECIAL FEATURES:		

PREFABRICATED STRUCTURE.



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	7/6287	11
LOCATION:	AREA H	
ACTIVITY:		
EAST ELEVATION OF BUILDING H2.		

SPECIAL FEATURES:
PREFABRICATED STRUCTURE.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	7/6287	12

LOCATION:	AREA H	
ACTIVITY:		
WEST ELEVATION OF BUILDING H2.		
SPECIAL FEATURES:		
PREFABRICATED STRUCTURE.		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	7/6287	13
LOCATION:	AREA H	
ACTIVITY:		
SOUTH ELEVATION OF BUILDING H3.		
SPECIAL FEATURES:		
PREFABRICATED STRUCTURE.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	7/6287	14
LOCATION:	AREA H	
ACTIVITY:		
NORTH ELEVATION OF BUILDING H3.		
SPECIAL FEATURES:		
PREFABRICATED STRUCTURE.		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	7/6287	15
LOCATION:	AREA M	
ACTIVITY:		
WEST ELEVATION OF BUILDING L183.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	7/6287	16
LOCATION:	AREA M	
ACTIVITY:		
NORTH EAST ELEVATION OF BUILDING L183.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	7/6287	17
LOCATION:	AREA M	
ACTIVITY:		
SOUTH EAST ELEVATION OF BUILDING L158.		

SPECIAL FEATURES:
GENERAL POOR CONDITION.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	7/6287	18

LOCATION:	AREA M	
ACTIVITY:		
NORTH ELEVATION OF BUILDING L158.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	7/6287	19
LOCATION:	AREA M	
ACTIVITY:		
SOUTH EAST ELEVATION OF BUILDING L187.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	7/6287	20
LOCATION:	AREA M	
ACTIVITY:		
NORTH EAST ELEVATION OF BUILDING L187.		
SPECIAL FEATURES:		




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	7/6287	21
LOCATION:	AREA M	
ACTIVITY:		
SOUTH EAST ELEVATION OF BUILDING L156.		
SPECIAL FEATURES:		
GENERAL POOR CONDITION.		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	7/6287	22
LOCATION:	AREA M	
ACTIVITY:		
WEST ELEVATION OF BUILDING L156.		
SPECIAL FEATURES:		

GENERAL POOR CONDITION.



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	7/6287	23
LOCATION:	AREA H	
ACTIVITY:		
EAST ELEVATION OF BUILDING H23.		

SPECIAL FEATURES:
GENERAL POOR CONDITION. OVERGROWTH OF TREES AND VEGETATION.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	7/6287	24

LOCATION:	AREA H	
ACTIVITY:		
SOUTH ELEVATION OF BUILDING H23.		
SPECIAL FEATURES:		
GENERAL POOR CONDITION. OVERGROWTH OF TREES AND VEGETATION.		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	7/6287	25
LOCATION:	AREA H	
ACTIVITY:		
WEST ELEVATION OF BUILDING H23.		
SPECIAL FEATURES:		
OVERGROWN WITH TREES AND SHRUBS.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	7/6287	26
LOCATION:	AREA M	
ACTIVITY:		
INTERNAL VIEW OF BUILDING L183.		
SPECIAL FEATURES:		
GENERAL POOR CONDITION.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	7/6287	27
LOCATION:	AREA M	
ACTIVITY:		
INTERNAL VIEW OF BUILDING L183.		
SPECIAL FEATURES:		
GENERAL POOR CONDITION.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	7/6287	28
LOCATION:	AREA M	
ACTIVITY:		
NORTH ELEVATION OF BUILDING L117.		
SPECIAL FEATURES:		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	7/6287	29
LOCATION:	AREA M	
ACTIVITY:		
NORTH EAST ELEVATION OF BUILDING L117.		

SPECIAL FEATURES:


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	7/6287	30

LOCATION:	AREA H	
ACTIVITY:		
SOUTH ELEVATION OF BUILDING H21.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	7/6287	31
LOCATION:	AREA H	
ACTIVITY:		
NORTH WEST ELEVATION OF BUILDING H21.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	7/6287	32
LOCATION:	AREA S	
ACTIVITY:		
WEST ELEVATION OF BUILDING 22A.		
SPECIAL FEATURES:		
PREPARATION FOR FIRING EXTERNAL DUCTWORK.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	7/6287	33
LOCATION:	AREA S	
ACTIVITY:		
WEST ELEVATION OF BUILDING 22A.		
SPECIAL FEATURES:		
EXTERNAL DUCTWORK BEING FIRED.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	7/6287	34
LOCATION:	AREA S	
ACTIVITY:		
ELEVATION OF BUILDING 22A.		
SPECIAL FEATURES:		

EXTERNAL DUCTWORK FIRING.

Empty rectangular box for notes or details.

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	7/6287	35
LOCATION:	AREA M	
ACTIVITY:		
REMOVAL OF STEAM MAIN SUPPORT STEELWORK.		



SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	7/6287	36
LOCATION:	AREA M	

ACTIVITY:	
ELEVATION OF BUILDING L117.	
SPECIAL FEATURES:	
BUILDING BEING PREPARED FOR FIRING.	

FORMER RARDE WALTHAM ABBEY NORTH SITE


REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	7/6287	37
LOCATION:	AREA M	
ACTIVITY:		
SOUTH EAST ELEVATION OF BUILDING L117.		
SPECIAL FEATURES:		
BUILDING PREPARATION FOR FIRING.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	8/6340	16
LOCATION:	AREA S	
ACTIVITY:		
BAGGED ASBESTOS IN GUNCOTTON STOVES.		
SPECIAL FEATURES:		
ASBESTOS DEBRIS BAGGED UP AWAITING DISPOSAL.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	8/6340	17
LOCATION:	AREA S	
ACTIVITY:		
BAGGED ASBESTOS IN GUNCOTTON STOVES.		
SPECIAL FEATURES:		
ASBESTOS DEBRIS BAGGED UP AWAITING DISPOSAL.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	8/6340	18
LOCATION:	AREA S	
ACTIVITY:		
BAGGED ASBESTOS IN GUNCOTTON STOVES.		
SPECIAL FEATURES:		
ASBESTOS DEBRIS BAGGED UP AWAITING DISPOSAL.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	8/6340	19
LOCATION:	AREA S	
ACTIVITY:		
ASBESTOS BOARD DEBRIS, AS FOUND, ADJACENT TO GUNCOTTON STOVES.		
SPECIAL FEATURES:		
GENERAL CONDITION.		




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	8/6340	20
LOCATION:	AREA S	
ACTIVITY:		
INITIAL 'PICK UP' OF DEBRIS LYING AROUND SSSI AREA.		

SPECIAL FEATURES:


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	8/6340	21

LOCATION:	AREA S
ACTIVITY:	
INITIAL 'PICK UP' OF DEBRIS LYING AROUND SSSI AREA.	
SPECIAL FEATURES:	

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	8/6340	22
LOCATION:	AREA S	
ACTIVITY:		
BAGGED ASBESTOS NEAR GUNCOTTON STOVES.		
SPECIAL FEATURES:		
ASBESTOS DEBRIS COLLECTED TOGETHER, BAGGED AND AWAITING DISPOSAL.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	8/6340	23
LOCATION:	AREA S	
ACTIVITY:		
SHEET ASBESTOS PRIOR TO BAGGING.		
SPECIAL FEATURES:		
ASBESTOS DEBRIS 'AS FOUND' ADJACENT TO GUNCOTTON STOVES.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	8/6340	24
LOCATION:	AREA S	
ACTIVITY:		
SHEET ASBESTOS AT THE GUNCOTTON STOVES.		
SPECIAL FEATURES:		
ASBESTOS DEBRIS 'AS FOUND' ADJACENT TO GUNCOTTON STOVES.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	8/6340	25
LOCATION:	AREA S	
ACTIVITY:		
SHEET ASBESTOS PRIOR TO BAGGING.		
SPECIAL FEATURES:		

ASBESTOS BOARDING 'AS FOUND'.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	8/6340	26
LOCATION:	AREAS	
ACTIVITY:		
SHEET ASBESTOS AT GUNCOTTON STOVE.		



SPECIAL FEATURES:
ASBESTOS BOARDING 'AS FOUND'.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	8/6340	27

LOCATION:	AREAS	
ACTIVITY:		
SHEET ASBESTOS.		
SPECIAL FEATURES:		
COLLECTED AND BAGGED AWAITING DISPOSAL.		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	8/6340	28
LOCATION:	AREA S	
ACTIVITY:		
ASBESTOS AT GUNCOTTON STOVE.		
SPECIAL FEATURES:		
BAGGING OF ASBESTOS DEBRIS IN PROGRESS.		

--


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	8/6340	29
LOCATION:	AREA M	
ACTIVITY:		
NORTH ELEVATION OF BUILDING L127.		
SPECIAL FEATURES:		
ASBESTOS CLAD BUILDING.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	8/6340	30
LOCATION:	AREA M	
ACTIVITY:		
WEST ELEVATION OF BUILDING L161.		
SPECIAL FEATURES:		
GENERAL POOR CONDITION.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	8/6340	31
LOCATION:	AREA M	
ACTIVITY:		
SOUTH WEST ELEVATION OF BUILDING L112.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	8/6340	32
LOCATION:	AREA M	
ACTIVITY:		
SOUTH WEST ELEVATION OF BUILDING L113.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	8/6340	33




LOCATION:	AREA M	
ACTIVITY:		
NORTH ELEVATION OF BUILDING L117.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	8/6340	36
LOCATION:	AREA M	
ACTIVITY:		
INTERNAL VIEW OF BUILDING L117 (LOCKER MAGAZINE).		
SPECIAL FEATURES:		
STRIPPING OUT PRIOR TO FIRING.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	8/6340	37
LOCATION:	AREA M	
ACTIVITY:		
NORTH ELEVATION OF BUILDING L117.		
SPECIAL FEATURES:		
TIMBER IMPORTED TO USE AS FIRING FUEL.		




FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDICATION RECORD


DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	9/8224	8
LOCATION:	AREA T	
ACTIVITY:		
TETRYL FACTORY SITE - CORE DRILLING / BURSTING.		
SPECIAL FEATURES:		
CORE DRILLING EQUIPMENT.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	9/8224	9
LOCATION:	AREA T	
ACTIVITY:		
TETRYL FACTORY SITE - CORE DRILLING / BURSTING.		
SPECIAL FEATURES:		
CORE DRILLING EQUIPMENT.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	9/8224	16
LOCATION:	AREA T	
ACTIVITY:		
CORE DRILLING FOUNDATION BASES.		
SPECIAL FEATURES:		
CORE DRILLING EQUIPMENT.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	9/8224	17
LOCATION:	AREA B	
ACTIVITY:		
LABORATORY OF GOVERNMENT CHEMIST SAMPLING GROUND WATER FROM SITE BOREHOLES.		
SPECIAL FEATURES:		



AMOUNT OF EQUIPMENT REQUIRED.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	9/8224	18
LOCATION:	AREAS	
ACTIVITY:		
EXAMPLE OF COPPER LIGHTENING CONDUCTORS ORIGINATING FROM		

ROOFS OF MAGAZINES.
SPECIAL FEATURES:


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	9/8224	19

LOCATION:	AREA N	
ACTIVITY:		
COPPER LIGHTENING CONDUCTORS.		
SPECIAL FEATURES:		
ACCUMULATION FOR SALVAGE.		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	9/8224	20
LOCATION:	AREA M	
ACTIVITY:		
COPPER LIGHTENING CONDUCTORS.		
SPECIAL FEATURES:		
ACCUMULATED FOR SALVAGE.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	9/8224	21
LOCATION:	AREA T	
ACTIVITY:		
TETRYL FACTORY SITE - BURSTING OF FOUNDATION CONCRETE.		
SPECIAL FEATURES:		
BURSTING EQUIPMENT (REMOTE ACTIVATION).		




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	9/8224	22
LOCATION:	AREA T	
ACTIVITY:		
TETRYL FACTORY SITE BURSTING OF CONCRETE FOUNDATIONS.		
SPECIAL FEATURES:		
BURSTING EQUIPMENT (REMOTE ACTIVATION).		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	9/8224	23
LOCATION:	AREA P	
ACTIVITY:		
WEST ELEVATION OF BUILDING A210.		
SPECIAL FEATURES:		

SERVICES PIPEWORK, SOME LAGGED WITH ASBESTOS AND WRAPPED  
PRIOR TO REMOVAL TO AVOID ESCAPE OF ASBESTOS FIBRES.



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	9/8224	24
LOCATION:	AREA P	
ACTIVITY:		
NORTH ELEVATION OF BUILDING A210.		



SPECIAL FEATURES:
ASBESTOS LAGGED PIPES WRAPPED FOR REMOVAL.


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	9/8224	25

LOCATION:	AREA P	
ACTIVITY:		
NORTH ELEVATION OF BUILDING A212.		
SPECIAL FEATURES:		
ASBESTOS LAGGED PIPES WRAPPED FOR REMOVAL.		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	9/8224	26
LOCATION:	AREA M	
ACTIVITY:		
NORTH EAST ELEVATION OF BUILDING L113.		
SPECIAL FEATURES:		
ASBESTOS LAGGED PIPES WRAPPED FOR REMOVAL.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	9/8224	27
LOCATION:	AREA M	
ACTIVITY:		
PIPES NEAR BUILDING L153 WRAPPED FOR REMOVAL.		
SPECIAL FEATURES:		




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	9/8224	28
LOCATION:	AREA P	
ACTIVITY:		
PERSONNEL DECONTAMINATION UNIT.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	9/8224	29
LOCATION:	AREA S	
ACTIVITY:		
STEAM MAIN PIPE IN SSSI AREA.		
SPECIAL FEATURES:		

ASBESTOS LAGGED PIPE WRAPPED FOR REMOVAL.



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	9/8224	30
LOCATION:	AREA S	
ACTIVITY:		
STEAM MAIN PIPE NEAR BUILDING 88A.		

SPECIAL FEATURES:
ASBESTOS LAGGED PIPE WRAPPED FOR REMOVAL.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	9/8224	31




LOCATION:	AREA N	
ACTIVITY:		
NORTH EAST VIEW OF GATE IN AREA N.		
SPECIAL FEATURES:		
HOLE CUT IN GATE BY INTRUDERS.		

FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	10/6853	12
LOCATION:	AREA H	
ACTIVITY:		
INTERNAL VIEW OF BUILDING H12.		
SPECIAL FEATURES:		
REMOTE CORING OF BRICK WALLS.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	10/6853	13
LOCATION:	AREA H	
ACTIVITY:		
INTERNAL VIEW OF BUILDING H12.		
SPECIAL FEATURES:		
REMOTE CORING OF BRICK WALLS.		




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	10/6853	14
LOCATION:	AREA H	
ACTIVITY:		
INTERNAL VIEW OF BUILDING H12.		
SPECIAL FEATURES:		
REMOTE CORING OF BRICK WALLS.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	10/6853	15
LOCATION:	AREA H	
ACTIVITY:		
INTERNAL VIEW OF BUILDING H12.		
SPECIAL FEATURES:		

REMOTE CORING OF BRICK WALLS.



**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	10/6853	16
LOCATION:	AREA H	
ACTIVITY:		
INTERNAL VIEW OF BUILDING H12.		

SPECIAL FEATURES:
REMOTE CORING OF BRICK WALLS.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	10/6853	17

LOCATION:	AREA H	
ACTIVITY:		
INTERNAL VIEW OF BUILDING H12.		
SPECIAL FEATURES:		
REMOTE CORING OF BRICK WALLS.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	10/6853	18
LOCATION:	AREA H	
ACTIVITY:		
INTERNAL VIEW OF BUILDING H12.		
SPECIAL FEATURES:		
REMOTE CORING OF BRICK WALLS.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	10/6853	19
LOCATION:	AREA H	
ACTIVITY:		
MAN HOLE BETWEEN BUILDING H10 & H71.		
SPECIAL FEATURES:		




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	10/6853	20
LOCATION:	AREA S	
ACTIVITY:		
INTERNAL VIEW OF BUILDING L190.		
SPECIAL FEATURES:		
REMOTE FLOOR CORING IN PROGRESS.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	10/6853	22
LOCATION:	AREA S	
ACTIVITY:		
BARGE IN CANAL WEST OF BUILDING 107 / 108.		
SPECIAL FEATURES:		

GENERAL POOR CONDITION.



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	10/6853	23
LOCATION:	AREA S	
ACTIVITY:		
BARGE IN CANAL WEST OF BUILDING 107 / 108.		

SPECIAL FEATURES:
GENERAL POOR CONDITION.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	10/6853	24

LOCATION:	AREAS	
ACTIVITY:		
POWDER BARGE IN CANAL AT 88A.		
SPECIAL FEATURES:		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDICATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	10/6853	25
LOCATION:	AREA S	
ACTIVITY:		
POWDER BARGE IN CANAL AT 88A.		
SPECIAL FEATURES:		






FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	11/6956	1
LOCATION:	AREA H	
ACTIVITY:		
MAN HOLE COVER BETWEEN BUILDINGS H10 & H71(NORTH SIDE).		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	11/6956	2
LOCATION:	AREA H	
ACTIVITY:		
MAN HOLE COVER BETWEEN BUILDING H10 & H71 (NORTH SIDE).		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	11/6956	3
LOCATION:	AREA S	
ACTIVITY:		
GENERAL VIEW OF TRACK SOUTH OF BUILDING U4.		
SPECIAL FEATURES:		
HEAVY USE BY SITE VEHICLES.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	11/6956	4
LOCATION:	AREA S	
ACTIVITY:		
VIEW SOUTH SHOWING GENERAL CLEARANCE AROUND BUILDING U4.		
SPECIAL FEATURES:		

GENERAL OVERGROWTH OF TREES AND VEGETATION.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	11/6956	5
LOCATION:	AREA S	
ACTIVITY:		
GENERAL VIEW OF WASTE MATERIAL SOUTH OF U4.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	11/6956	6

LOCATION:	AREAS	
ACTIVITY:		
OUTSIDE BUILDING U4.		
SPECIAL FEATURES:		
COPPER EARTHING STRIP, RETRIEVAL FOR SALVAGE.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	11/6956	7
LOCATION:	AREA S	
ACTIVITY:		
CLEARING WASTE FROM AREA SOUTH OF BUILDING U4.		
SPECIAL FEATURES:		
GENERAL SITE CLEARANCE OF WASTE DUMPS.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	11/6956	8
LOCATION:	AREA S	
ACTIVITY:		
SETTLEMENT TANK NORTH WEST OF BUILDING 83B.		
SPECIAL FEATURES:		
GENERAL POOR CONDITION & OVERGROWTH.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	11/6956	9
LOCATION:	AREA S	
ACTIVITY:		
GENERAL VIEW OF WASTE NORTH OF BUILDING U4. (VIEW LOOKING NORTH)		
SPECIAL FEATURES:		
TYPICAL WASTE DUMP.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	11/6956	10
LOCATION:	AREA S	
ACTIVITY:		
OLD TELEGRAPH POLES STOCKPILED.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	11/6956	11
LOCATION:	AREA S	
ACTIVITY:		
VIEW OF TYPICAL TRACK WITHIN WOODED AREAS OF SSSI.		

SPECIAL FEATURES:
SHOWS DIFFICULT CONDITIONS FOR SITE VEHICLES AND PLANT.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	11/6956	12

LOCATION:	AREA	
ACTIVITY:		
MAP READING BY ROYAL ORDNANCE.		
SPECIAL FEATURES:		
ON SITE CO-ORDINATION IN PROGRESS.		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	11/6956	13
LOCATION:	AREA S	
ACTIVITY:		
TRIAL TRENCHING OF TRAVERSE. (TYPICAL)		
SPECIAL FEATURES:		
DIFFICULT ACCESS.		



--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	11/6956	14
LOCATION:	AREA M	
ACTIVITY:		
DISMANTLING GREENHOUSE No. 1.		
SPECIAL FEATURES:		
PART OF DEMOLITION CONTRACT.		




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	11/6956	15
LOCATION:	AREA M	
ACTIVITY:		
DEMOLITION OF BUILDINGS.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	11/6956	16
LOCATION:	AREA S	
ACTIVITY:		
VIEW OF WASTE MATERIAL IN WASTE DUMP SOUTH OF BUILDING U4.		
SPECIAL FEATURES:		

WASTE INCLUDES ASBESTOS.



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	11/6956	17
LOCATION:	AREA S	
ACTIVITY:		
VIEW OF WASTE MATERIAL IN WASTE DUMP SOUTH OF BUILDING U4.		

SPECIAL FEATURES:
WASTE INCLUDES ASBESTOS AND CHEMICAL GLASSWARE.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	11/6956	18

LOCATION:	AREAS	
ACTIVITY:		
ASBESTOS UNCOVERED IN WASTE DUMP SOUTH OF BUILDING U4.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	11/6956	19
LOCATION:	AREA S	
ACTIVITY:		
WASTE DUMP REMOVAL SOUTH OF BUILDING U4.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	11/6956	20
LOCATION:	AREA S	
ACTIVITY:		
ASBESTOS IN WASTE DUMP SOUTH OF BUILDING U4.		
SPECIAL FEATURES:		




--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	11/6956	21
LOCATION:	AREA S	
ACTIVITY:		
ASBESTOS IN WASTE DUMP SOUTH OF BUILDING U4.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	11/6956	22
LOCATION:	AREA S	
ACTIVITY:		
BAGGED ASBESTOS AT BUILDING 23.		
SPECIAL FEATURES:		

THESE ARE BAGGED ASBESTOS FOUND DUMPED IN DITCH ADJACENT TO THIS BUILDING.



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	11/6956	23
LOCATION:	AREA S	
ACTIVITY:		
ASBESTOS WASTE IN BUILDING 23.		

SPECIAL FEATURES:
CONDITION PRIOR TO CLEAN UP:


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	11/6956	24

LOCATION:	AREAS	
ACTIVITY:		
REMOVING WASTE FROM TIP.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	11/6956	25
LOCATION:	AREA S	
ACTIVITY:		
VIEW LOOKING NORTH TO E10.		
SPECIAL FEATURES:		
FENCING GUARDING PITS.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	11/6956	26
LOCATION:	AREA S	
ACTIVITY:		
WEST ELEVATION OF BUILDING E12.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	11/6956	27
LOCATION:	AREA S	
ACTIVITY:		
SOUTH ELEVATION OF BUILDING E10.		
SPECIAL FEATURES:		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	11/6956	28
LOCATION:	AREA S	
ACTIVITY:		
REMOVAL OF WASTE BY LORRY - NORTH OF BUILDING 83B.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	11/6956	29
LOCATION:	AREA L	
ACTIVITY:		
ELEVATION OF BUILDING L191 - CORE SAMPLING.		

SPECIAL FEATURES:
REMOTE CORING EQUIPMENT IN USE EXTERNALLY.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	11/6956	30


LOCATION:	AREAS	
ACTIVITY:		
WEST ELEVATION OF BUILDING 22A.		
SPECIAL FEATURES:		
AFTERMATH OF 'FIRED' EXTERNAL DUCTWORK.		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	11/6956	31
LOCATION:	AREA S	
ACTIVITY:		
TREE CLEARANCE - LOGGING.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	11/6956	32
LOCATION:	AREA S	
ACTIVITY:		
TREE CLEARANCE - CHIPPING.		
SPECIAL FEATURES:		
WOOD CHIPPING MACHINERY.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	11/6956	33
LOCATION:	AREA N	
ACTIVITY:		
TRACKED DUMPER AT NEW HILL.		
SPECIAL FEATURES:		
DEMONSTRATION OF TRACKED 2.5 TONNE TIPPING CARRIER ON DIFFICULT TERRAIN.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	11/6956	34
LOCATION:	AREA N	
ACTIVITY:		
TRACKED DUMPER AT NEW HILL.		
SPECIAL FEATURES:		



DEMONSTRATION OF TRACKED 2.5 TONNE TIPPING CARRIER ON  
DIFFICULT TERRAIN.



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	11/6956	35
LOCATION:	AREA N	
ACTIVITY:		
TRACKED DUMPER.		

SPECIAL FEATURES:
DEMONSTRATION OF TRACKED 2.5 TONNE TIPPING CARRIER ON DIFFICULT TERRAIN.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	11/6956	36

LOCATION:	AREA N	
ACTIVITY:		
TRACKED DUMPER.		
SPECIAL FEATURES:		
DEMONSTRATION OF TRACKED 2.5 TONNE TIPPING CARRIER ON DIFFICULT TERRAIN.		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	11/6956	37
LOCATION:	AREA N	
ACTIVITY:		
TRACKED DUMPER.		
SPECIAL FEATURES:		
DEMONSTRATION OF TRACKED 2.5 TONNE TIPPING CARRIER ON DIFFICULT TERRAIN.		




**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	12/7113	1
LOCATION:	AREA H	
ACTIVITY:		
TYPICAL STEAM PIPE SUPPORT - SOUTH OF BUILDING H17.		
SPECIAL FEATURES:		
OVERGROWN WITH TREES AND SHRUBS.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	12/7113	2
LOCATION:	AREA H	
ACTIVITY:		
TYPICAL STEAM PIPE SUPPORT BASE.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	12/7113	3
LOCATION:	AREA H	
ACTIVITY:		
STEAM PIPE SUPPORT - SOUTH OF BUILDING H12.		
SPECIAL FEATURES:		
UNUSUAL 'ALL CONCRETE' CONSTRUCTION.		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	12/7113	4
LOCATION:	AREA S	
ACTIVITY:		
PALLETING RECLAIMED 'STOCK' (BRICKS) FOR FUTURE USE - SOUTH OF BUILDING U4.  GRID REFERENCE: 201 900 N		
SPECIAL FEATURES:		

FALLEN CHIMNEY STACK ON SITE OF FORMER POWER HOUSE.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	12/7113	5
LOCATION:	AREAS	
ACTIVITY:		
ROYAL ORDNANCE SUPERVISING THE RECLAMATION OF BRICKS SOUTH		

OF BUILDING U4.
SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	12/7113	6

LOCATION:	AREA S	
ACTIVITY:		
WASTE TIP REF.: 11013.		
GRID REFERENCE : 201 900 N          537 400 E		
SPECIAL FEATURES:		
VIEW LOOKING SOUTH.		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	12/7113	7
LOCATION:	AREA S	
ACTIVITY:		
<p>COMMENCEMENT OF BREAKING OUT SURFACE SLABS WEST OF BUILDING 83B IN THE AREA OF WASTE TIP REF.:11013.</p>		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	12/7113	8
LOCATION:	AREA S	
ACTIVITY:		
GENERAL CLEARANCE OF TIMBER FROM WASTE TIP REF.:11013.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	12/7113	9
LOCATION:	AREA B	
ACTIVITY:		
TIMBER STACKED IN BURNING GROUND.		
SPECIAL FEATURES:		
WASTE TIMBER FOR USE AS FUEL IN 'HEAT TREATMENT' PROCESS.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	12/7113	10
LOCATION:	AREAS	
ACTIVITY:		
GENERAL VIEW.		
SPECIAL FEATURES:		



TIMBER CLEARANCE FOR ACCESS.



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	12/7113	11
LOCATION:	AREA S	
ACTIVITY:		
GUNPOWDER PRESS HOUSE, EAST OF BURNING GROUND, VIEWED FROM		

THE WEST.
SPECIAL FEATURES:
OVERGROWN WITH VEGETATION.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	12/7113	12

LOCATION:	AREAS	
ACTIVITY:		
GENERAL VIEW - WASTE TIP REF.: 11036 ADJACENT TO GUNPOWDER PRESS HOUSE.		
SPECIAL FEATURES:		
OVERGROWN WITH VEGETATION.		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	12/7113	13
LOCATION:	AREAS	
ACTIVITY:		
GENERAL VIEW OF WASTE TIP REF.: 11036 GUNPOWDER PRESS HOUSE.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	12/7113	14
LOCATION:	AREA S	
ACTIVITY:		
VIEW OF WASTE TIP REF.: 11036. ADJACENT GUNPOWDER PRESS HOUSE.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	12/7113	15
LOCATION:	AREA S	
ACTIVITY:		
VIEW OF WASTE TIP REF.:11036 - ADJACENT GUNPOWDER PRESS HOUSE		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	12/7113	16
LOCATION:	AREA S	
ACTIVITY:		
WASTE TIP REF.:11036 ADJACENT GUNPOWDER PRESS HOUSE.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	12/7113	17
LOCATION:	AREA S	
ACTIVITY:		
WASTE TIP REF.:11036 BASE OF BLAST WALL ADJACENT GUNPOWDER		



PRESS HOUSE.
SPECIAL FEATURES:


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	12/7113	18

LOCATION:	AREAS	
ACTIVITY:		
VIEW OF WASTE TIP REF.: 11036 ADJACENT GUNPOWDER PRESS HOUSE.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	12/7113	19
LOCATION:	AREA S	
ACTIVITY:		
VIEW OF BRIDGE 10 LOOKING NORTH.		
SPECIAL FEATURES:		
PRESS HOUSE S31 IN BACKGROUND.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	12/7113	20
LOCATION:	AREA S	
ACTIVITY:		
ELEVATION OF BUILDING X16. (BUILDING NORTH WEST OF BRIDGE 10)		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	12/7113	21
LOCATION:	AREA B	
ACTIVITY:		
WASTE DUMP REF.: 11038 SITUATED NORTH OF THE BURNING GROUND.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	12/7113	22
LOCATION:	AREA N	
ACTIVITY:		
GENERAL CLEARANCE.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	12/7113	23
LOCATION:	AREA M	
ACTIVITY:		
REMOTE CONTROLLED CORING IN BUILDING L149.		

SPECIAL FEATURES:
REMOTE OPERATOR.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	12/7113	24



LOCATION:	AREA M	
ACTIVITY:		
REMOTE CONTROLLED CORING OF CONCRETE FLOOR IN BUILDING L149.		
SPECIAL FEATURES:		
PORTABLE CORING.		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	12/7113	25
LOCATION:	AREA N	
ACTIVITY:		
CLEARED PATHWAYS.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	12/7113	26
LOCATION:	AREA N	
ACTIVITY:		
STEEL PLATES IN BUILDING S19.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	12/7113	27
LOCATION:	AREA N	
ACTIVITY:		
CLEARING PATHWAYS TO BUILDINGS.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	12/7113	28
LOCATION:	AREA N	
ACTIVITY:		
CLEARED PATHWAY.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	12/7113	29
LOCATION:	AREA N	
ACTIVITY:		
CLEARED ROADS AT BUILDING S21.		

SPECIAL FEATURES:
NARROW GAUGE RAIL TRACK VISIBLE.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	12/7113	30


LOCATION:	AREA N	
ACTIVITY:		
SOUTH ELEVATION OF BUILDING S22.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	12/7113	31
LOCATION:	AREA N	
ACTIVITY:		
NORTH ELEVATION OF BUILDING S25.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	12/7113	32
LOCATION:	AREA N	
ACTIVITY:		
SOUTH ELEVATION OF BUILDING S25.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	12/7113	33
LOCATION:	AREA N	
ACTIVITY:		
TYPICAL OVERGROWN PATHWAY.		
SPECIAL FEATURES:		
OVERGROWN WITH TREES AND SHRUBS.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	12/7113	34
LOCATION:	AREA N	
ACTIVITY:		
INTERNAL VIEW OF BUILDING S25.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	12/7113	35
LOCATION:	AREA N	
ACTIVITY:		
TYPICAL OVERGROWN DRAINAGE CHANNEL FROM S16.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	12/7113	36

LOCATION:	AREA N	
ACTIVITY:		
CLEARING DRAINAGE CHANNEL FROM BUILDING S16.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	12/7113	37
LOCATION:	AREA N	
ACTIVITY:		
DRAINAGE CHANNEL RUNNING SOUTHWARD FROM BUILDING S16.		
SPECIAL FEATURES:		
OVERGROWN WITH TREES AND SHRUBS.		






FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	13/7562	1
LOCATION:	AREA M	
ACTIVITY:		
WEST ELEVATION OF BUILDING L167.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	13/7562	2
LOCATION:	AREA M	
ACTIVITY:		
SOUTH WEST ELEVATION OF BUILDING L167.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	13/7562	3
LOCATION:	AREA M	
ACTIVITY:		
SOUTH ELEVATION OF BUILDING L157.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	13/7562	4
LOCATION:	AREA M	
ACTIVITY:		
WEST ELEVATION OF BUILDING L157.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	13/7562	5
LOCATION:	AREA M	
ACTIVITY:		
WEST ELEVATION OF BUILDING L148 / L153.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	13/7562	6

LOCATION:	AREA M	
ACTIVITY:		
PART EAST & NORTH ELEVATIONS OF BUILDING L157.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	13/7562	7
LOCATION:	AREA M	
ACTIVITY:		
LOOKING SOUTH - BUILDING L157 IN FOREGROUND.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	13/7562	8
LOCATION:	AREA M	
ACTIVITY:		
PART EAST ELEVATION OF BUILDING L153.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	13/7562	9
LOCATION:	AREA M	
ACTIVITY:		
WEST ELEVATION OF BUILDING L149.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	13/7562	10
LOCATION:	AREA M	
ACTIVITY:		
PART NORTH & EAST ELEVATIONS OF BUILDING L153.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	13/7562	11
LOCATION:	AREA M	
ACTIVITY:		
EAST ELEVATION OF BUILDING L148.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	13/7562	12


LOCATION:	AREA M	
ACTIVITY:		
PART EAST ELEVATION OF BUILDING L148.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	13/7562	13
LOCATION:	AREA M	
ACTIVITY:		
SOUTH EASTERN ASPECT OF BUILDING L145.		
SPECIAL FEATURES:		



--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	13/7562	14
LOCATION:	AREA M	
ACTIVITY:		
NORTH EASTERN ASPECT OF BUILDING L149.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	13/7562	15
LOCATION:	AREA M	
ACTIVITY:		
NORTH EASTERN ASPECT OF BUILDING L149.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	13/7562	16
LOCATION:	AREA M	
ACTIVITY:		
NORTH EASTERN ASPECT OF BUILDING L145.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	13/7562	17
LOCATION:	AREA M	
ACTIVITY:		
SOUTH ELEVATION OF BUILDING L136.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	13/7562	18

LOCATION:	AREA M	
ACTIVITY:		
SOUTH WESTERN ASPECT OF BUILDING L136.		
SPECIAL FEATURES:		
STEAM MAIN SUPPORTS IN FOREGROUND.		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	13/7562	19
LOCATION:	AREA L	
ACTIVITY:		
NORTH WESTERN ASPECT OF BUILDING L122.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	13/7562	20
LOCATION:	AREA B	
ACTIVITY:		
WEST ELEVATION OF BUILDING L102.		
SPECIAL FEATURES:		
FILLED CANAL IN FOREGROUND.		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	13/7562	21
LOCATION:	AREA B	
ACTIVITY:		
NORTH ELEVATION OF BUILDING L103.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	13/7562	22
LOCATION:	AREA B	
ACTIVITY:		
EAST ELEVATION OF BUILDINGS L102 / L103.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	13/7562	23
LOCATION:	AREA B	
ACTIVITY:		
NORTH EASTERN ASPECT OF BUILDING L101.		

SPECIAL FEATURES:



--







FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	14/7575	1
LOCATION:	AREA N	
ACTIVITY:		
WEST ELEVATION OF BUILDING X3.		
SPECIAL FEATURES:		
BUNKER TYPE CONSTRUCTED OF SANDBAGS.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	14/7575	2
LOCATION:	AREA N	
ACTIVITY:		
SOUTH ELEVATION OF BUILDING X3.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	14/7575	3
LOCATION:	AREA B	
ACTIVITY:		
PREPARATION OF FIRE IN BURNING GROUND FOR HEAT TREATMENT OF MATERIALS.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	14/7575	4
LOCATION:	AREA B	
ACTIVITY:		
PREPARATION OF FIRE ON BURNING GROUND FOR HEAT TREATMENT OF MATERIALS.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	14/7575	5
LOCATION:	AREA B	
ACTIVITY:		
PREPARATION OF FIRE ON BURNING GROUND FOR HEAT TREATMENT OF		

MATERIALS.
SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	14/7575	6

LOCATION:	AREA B	
ACTIVITY:		
PREPARATION OF FIRE ON BURNING GROUND FOR HEAT TREATMENT OF MATERIALS.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	14/7575	7
LOCATION:	AREA B	
ACTIVITY:		
HEAT TREATMENT OF MATERIALS AT BURNING GROUND - IN PROGRESS.		
SPECIAL FEATURES:		



--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	14/7575	8
LOCATION:	AREA T	
ACTIVITY:		
REMEDICATION OF TETRYL FACTORY SITE.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	14/7575	9
LOCATION:	AREA T	
ACTIVITY:		
REMEDICATION OF TETRYL FACTORY SITE VIEWED IN SOUTHERLY DIRECTION.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	14/7575	10
LOCATION:	AREA T	
ACTIVITY:		
EXPOSURE OF SUSPECT PIT AT NORTH END OF TETRYL FACTORY SITE.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	14/7575	11
LOCATION:	AREA T	
ACTIVITY:		
EXPOSURE OF SUSPECT PIT AT NORTH END OF TETRYL FACTORY SITE.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	14/7575	12

LOCATION:	AREA T	
ACTIVITY:		
EXPOSURE OF SUSPECT PIT AT NORTH END OF TETRYL FACTORY SITE.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	14/7575	13
LOCATION:	AREA T	
ACTIVITY:		
REMEDATION OF TETRYL FACTORY SITE VIEWED IN SOUTHERLY DIRECTION.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	14/7575	14
LOCATION:	AREA T	
ACTIVITY:		
REMEDIATION OF TETRYL FACTORY SITE VIEWED IN SOUTHERLY DIRECTION.		
SPECIAL FEATURES:		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	14/7575	15
LOCATION:	AREA T	
ACTIVITY:		
EXPOSURE OF SUSPECT PIT AT NORTH END OF TETRYL FACTORY SITE.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	14/7575	16
LOCATION:	AREA T	
ACTIVITY:		
EAST SIDE OF TETRYL FACTORY SITE - WASTE DUMP.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	14/7575	17
LOCATION:	AREA T	
ACTIVITY:		
REMEDICATION OF TETRYL FACTORY SITE.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	14/7575	18

LOCATION:	AREA T	
ACTIVITY:		
REMEDICATION OF TETRYL FACTORY SITE.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	14/7575	19
LOCATION:	AREA T	
ACTIVITY:		
REMEDICATION OF TETRYL FACTORY SITE.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	14/7575	20
LOCATION:	AREA T	
ACTIVITY:		
"YELLOW" DISCOLOURATION OF FOUNDATIONS TO FORMER TETRYL FACTORY.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	14/7575	21
LOCATION:	AREA T	
ACTIVITY:		
BREAKING OF CONCRETE FOUNDATIONS OF FORMER TETRYL FACTORY.		
SPECIAL FEATURES:		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	14/7575	22
LOCATION:	AREA T	
ACTIVITY:		
EXPOSURE OF DRAINS TO FORMER TETRYL FACTORY SITE.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	14/7575	23
LOCATION:	AREA T	
ACTIVITY:		
BROKEN FOUNDATIONS OF FORMER TETRYL FACTORY.		

SPECIAL FEATURES:


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	14/7575	24

LOCATION:	AREA T	
ACTIVITY:		
REMEDICATION OF TETRYL FACTORY SITE.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	14/7575	25
LOCATION:	AREA S	
ACTIVITY:		
TRACKED DUMPER BY BUILDING E12 REMOVING WASTE FROM FORMER CANAL.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	14/7575	26
LOCATION:	AREA S	
ACTIVITY:		
TRACKED DUMPER TIPPING WASTE BY BUILDING E12.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	14/7575	27
LOCATION:	AREA H - ISLAND SITE	
ACTIVITY:		
SOUTH ELEVATION OF BUILDING A203.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	14/7575	28
LOCATION:	AREA H - ISLAND SITE	
ACTIVITY:		
NORTH ELEVATION OF BUILDING A200.		
SPECIAL FEATURES:		




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	14/7575	29
LOCATION:	AREA H - ISLAND SITE	
ACTIVITY:		
EAST ELEVATION OF BUILDING A201/2		

SPECIAL FEATURES:


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	14/7575	30

LOCATION:	AREA H - ISLAND SITE	
ACTIVITY:		
CLOSE UP OF FRACTURED PIER TO NORTH EAST CORNER OF BUILDING A201/2.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	14/7575	31
LOCATION:	AREA H - ISLAND SITE	
ACTIVITY:		
WEST ELEVATION OF BUILDING A200.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	14/7575	32
LOCATION:	AREA P	
ACTIVITY:		
NORTH WESTERN ASPECT OF BUILDING A210.		
SPECIAL FEATURES:		




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	14/7575	33
LOCATION:	AREA P	
ACTIVITY:		
WEST ELEVATION OF BUILDING A210.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	14/7575	34
LOCATION:	AREA P	
ACTIVITY:		
NORTH EASTERN ASPECT OF BUILDING A214.		
SPECIAL FEATURES:		

BUILDING A210 IN BACKGROUND.



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	14/7575	35
LOCATION:	AREA M	
ACTIVITY:		
SOUTH ELEVATION OF BUILDING L176.		



SPECIAL FEATURES:
BRIDGE No. 2 IN FOREGROUND.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	14/7575	36

LOCATION:	AREA M	
ACTIVITY:		
NORTH WESTERN ASPECT OF BUILDING L176.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	14/7575	37
LOCATION:	AREA M	
ACTIVITY:		
NORTH ELEVATION OF BUILDING L168.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	15/7600	1
LOCATION:	AREA S	
ACTIVITY:		
KUBOTA EXCAVATOR ACCIDENT IN SOFT GROUND.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	15/7600	2
LOCATION:	AREA S	
ACTIVITY:		
KUBOTA EXCAVATOR ACCIDENT IN SOFT GROUND.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	15/7600	3
LOCATION:	AREA S	
ACTIVITY:		
FALLOW DEER IN SSSI.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	15/7600	4
LOCATION:	AREA S	
ACTIVITY:		
FALLOW DEER IN SSSI.		
SPECIAL FEATURES:		




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	15/7600	5
LOCATION:	AREAS	
ACTIVITY:		
NARROW GAUGE RAILWAY UNCOVERED IN SSSI, BETWEEN BUILDINGS		

22 AND 23.
SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	15/7600	6

LOCATION:	AREAS	
ACTIVITY:		
NARROW GAUGE RAILWAY UNCOVERED IN SSSI, BETWEEN BUILDINGS 22 AND 23.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	15/7600	7
LOCATION:	AREA P	
ACTIVITY:		
FITTING OUT SITE ADMINISTRATION OFFICES - BUILDING A230.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	15/7600	8
LOCATION:	AREA H - ISLAND SITE	
ACTIVITY:		
WEST ELEVATION OF BUILDING A200.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	15/7600	9
LOCATION:	AREA H - ISLAND SITE	
ACTIVITY:		
NORTH ELEVATION OF BUILDING A200.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	15/7600	10
LOCATION:	AREA H - ISLAND SITE	
ACTIVITY:		
EAST ELEVATION OF BUILDING A201/2.		
SPECIAL FEATURES:		



<b>FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD</b>		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	15/7600	11
LOCATION:	AREA H - ISLAND SITE	
ACTIVITY:		
VIEW OF FRACTURED PIER TO NORTH EAST CORNER OF BUILDING		



A201/2.
SPECIAL FEATURES:


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	15/7600	12

LOCATION:	AREA P	
ACTIVITY:		
SOUTH ELEVATION OF BUILDING A210 (BOILER HOUSE).		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	15/7600	13
LOCATION:	AREA P	
ACTIVITY:		
NORTH ELEVATION OF BUILDING A210 (BOILER HOUSE).		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	15/7600	14
LOCATION:	AREA M	
ACTIVITY:		
SOUTH ELEVATION OF BUILDING L182.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	15/7600	15
LOCATION:	AREA M	
ACTIVITY:		
NORTH WEST ASPECT OF BUILDING L176.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	15/7600	16
LOCATION:	AREA M	
ACTIVITY:		
SOUTH ELEVATION OF BUILDING L176.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	15/7600	17
LOCATION:	AREA M	
ACTIVITY:		
WEST ELEVATION OF BUILDING L167.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	15/7600	18



LOCATION:	AREA M	
ACTIVITY:		
EAST & NORTH ELEVATIONS OF BUILDING L167.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	15/7600	19
LOCATION:	AREA M	
ACTIVITY:		
WEST ELEVATION OF BUILDING L157.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	15/7600	20
LOCATION:	AREA M	
ACTIVITY:		
NORTH EAST ELEVATION OF BUILDING L157.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	15/7600	21
LOCATION:	AREA M	
ACTIVITY:		
WEST ELEVATION OF BUILDING L148/L153.		
SPECIAL FEATURES:		
BUILDING L148 TO THE RIGHT.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	15/7600	22
LOCATION:	AREA M	
ACTIVITY:		
NORTH EAST ELEVATION OF BUILDING L153.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	15/7600	23
LOCATION:	AREA M	
ACTIVITY:		
NORTH EAST ELEVATION OF BUILDING L149.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	15/7600	24


LOCATION:	AREA M	
ACTIVITY:		
SOUTH ELEVATION OF BUILDING L149.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	15/7600	25
LOCATION:	AREA M	
ACTIVITY:		
ELEVATION OF BUILDING L148.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	15/7600	26
LOCATION:	AREA M	
ACTIVITY:		
NORTH EAST ELEVATION OF BUILDING L145.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	15/7600	27
LOCATION:	AREA M	
ACTIVITY:		
SOUTH ELEVATION OF BUILDING L136.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	15/7600	28
LOCATION:	AREA M	
ACTIVITY:		
SOUTH & WEST ELEVATIONS OF BUILDING L136.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	15/7600	29
LOCATION:	AREA L	
ACTIVITY:		
SOUTH & WEST ELEVATIONS OF BUILDING L122.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	15/7600	30

LOCATION:	AREAS	
ACTIVITY:		
VIEW OF TYPICAL WASTE DUMP.		
SPECIAL FEATURES:		
MIXED NATURE OF THE WASTE.		


**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	15/7600	31
LOCATION:	AREA S	
ACTIVITY:		
TYPICAL WASTE DUMP - REF.: 11036.		
SPECIAL FEATURES:		



--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	15/7600	32
LOCATION:	AREA S	
ACTIVITY:		
TYPICAL WASTE DUMP - REF.: 11036.		
SPECIAL FEATURES:		
CONTAINS ASBESTOS IN VARIOUS FORMS.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	15/7600	33
LOCATION:	AREA S	
ACTIVITY:		
DEPICTS A DATED TELEGRAPH POLE FOUND IN SSSI.		
SPECIAL FEATURES:		
DATE APPLIED USING 'COPPER' WIRE.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	15/7600	34
LOCATION:	AREA S	
ACTIVITY:		
WASTE DUMP REF.: 11038, SITUATED NORTH OF THE BURNING GROUND.		
SPECIAL FEATURES:		

MIXED NATURE OF WASTE.




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	15/7600	35
LOCATION:	AREA P	
ACTIVITY:		
NORTH ELEVATION OF BUILDING A238.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	15/7600	36

LOCATION:	AREA P	
ACTIVITY:		
SOUTH ELEVATION OF BUILDING A221 - DIRECTORS HOUSE (OCCUPIED).		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	15/7600	R
LOCATION:	AREA P	
ACTIVITY:		
EAST ELEVATION OF BUILDING A200 (WALTON HOUSE).		
SPECIAL FEATURES:		






**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	16/7809	2
LOCATION:	AREA P	
ACTIVITY:		
NORTH ELEVATION OF BUILDING A230.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	16/7809	3
LOCATION:	AREA P	
ACTIVITY:		
NORTH ELEVATION OF BUILDING A231.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	16/7809	4
LOCATION:	AREA P	
ACTIVITY:		
NORTH ELEVATION OF BUILDING A232/A234.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	16/7809	5
LOCATION:	AREA P	
ACTIVITY:		
SOUTH ELEVATION OF BUILDING A221 (MRS BELLAMY'S HOUSE).		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	16/7809	6
LOCATION:	AREA P	
ACTIVITY:		
NORTH ELEVATION OF BUILDING A238.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	16/7809	7

LOCATION:	AREA H	
ACTIVITY:		
NORTH ELEVATION OF BUILDING H25.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	16/7809	8
LOCATION:	AREA H	
ACTIVITY:		
SOUTH ELEVATION OF BUILDING H26.		
SPECIAL FEATURES:		



--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	16/7809	9
LOCATION:	AREA H	
ACTIVITY:		
WEST ELEVATION OF BUILDING H8.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	16/7809	10
LOCATION:	AREA H	
ACTIVITY:		
EAST ELEVATION OF BUILDING H8.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	16/7809	11
LOCATION:	AREA M	
ACTIVITY:		
WEST ELEVATION OF BUILDING L157.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	16/7809	12
LOCATION:	AREA M	
ACTIVITY:		
WEST ELEVATION OF BUILDING L153/L148.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	16/7809	13

LOCATION:	AREA L	
ACTIVITY:		
WEST ELEVATION OF BUILDING L185.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	16/7809	14
LOCATION:	AREA L	
ACTIVITY:		
SOUTH ELEVATION OF BUILDING L122.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	16/7809	15
LOCATION:	AREA M	
ACTIVITY:		
EAST ELEVATION OF BUILDING L107.		
SPECIAL FEATURES:		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	16/7809	16
LOCATION:	AREA M	
ACTIVITY:		
SOUTH ELEVATION OF BUILDING L138.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	16/7809	18
LOCATION:	AREA M	
ACTIVITY:		
WEST ELEVATION OF BUILDING L133.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	16/7809	19
LOCATION:	AREA M	
ACTIVITY:		
NORTH ELEVATION OF BUILDING L143.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	16/7809	20

LOCATION:	AREAS	
ACTIVITY:		
SOUTH WEST ASPECT OF 'WATERMANS COTTAGE'.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	16/7809	21
LOCATION:	AREA S	
ACTIVITY:		
SOUTH ELEVATION OF BUILDING 103 - PRESS HOUSE.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	16/7809	22
LOCATION:	AREA S	
ACTIVITY:		
BUILDING 103 PRESS HOUSE BLAST WALL.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	16/7809	23
LOCATION:	AREA S	
ACTIVITY:		
SOUTH ELEVATION OF BUILDING S31.		
SPECIAL FEATURES:		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	16/7809	24
LOCATION:	AREA S	
ACTIVITY:		
ELEVATION OF BUILDING S90.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	16/7809	25
LOCATION:	AREA S	
ACTIVITY:		
BUILDING S90.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	17/7810	1
LOCATION:	AREA S	
ACTIVITY:		
ASBESTOS FOUND IN UNDERGROWTH.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	17/7810	2
LOCATION:	AREA S	
ACTIVITY:		
ASBESTOS FOUND IN UNDERGROWTH.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	17/7810	3
LOCATION:	AREA T	
ACTIVITY:		
CONCRETE FOUNDATION EXPOSED IN FORMER TETRYL FACTORY.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	17/7810	4
LOCATION:	AREA P	
ACTIVITY:		
EXPOSED GAS PIPE FEED TO BUILDING A221.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	17/7810	5
LOCATION:	AREA B	
ACTIVITY:		
GENERAL VIEW OF BURNING GROUND.		



SPECIAL FEATURES:


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	17/7810	6

LOCATION:	AREAS	
ACTIVITY:		
RUBBISH COLLECTION BY BUILDING 88A.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	17/7810	7
LOCATION:	AREA S	
ACTIVITY:		
VIEW FROM TOW PATH OPPOSITE BUILDING 88A.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	17/7810	8
LOCATION:	AREA S	
ACTIVITY:		
TYPICAL STEAM MAIN ROUTE THROUGH UNDERGROWTH.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	17/7810	9
LOCATION:	AREA S	
ACTIVITY:		
TRANSPORTATION OF BAGGED ASBESTOS ON SITE.		
SPECIAL FEATURES:		
SEALED ASBESTOS CONTAINER IN BACKGROUND.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	17/7810	10
LOCATION:	AREA S	
ACTIVITY:		
DIGGING OUT ASBESTOS FROM STEAM MAIN ROUTE ADJACENT TO BUILDING 88A.		
SPECIAL FEATURES:		

WORK IN PROGRESS BY LICENSED ASBESTOS CONTRACTOR.

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	17/7810	11
LOCATION:	AREA S	
ACTIVITY:		
DIGGING OUT ASBESTOS FROM STEAM MAIN ROUTE ADJACENT TO		

BUILDING 88A.
SPECIAL FEATURES:
WORK IN PROGRESS BY LICENSED ASBESTOS CONTRACTOR.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	17/7810	12



LOCATION:	AREAS	
ACTIVITY:		
CANAL SOUTH OF BUILDING 88A - LOOKING EAST.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	17/7810	13
LOCATION:	AREA S	
ACTIVITY:		
CANAL SOUTH OF BUILDING 88A - LOOKING EAST.		
SPECIAL FEATURES:		
WORK IN PROGRESS BY LICENSED ASBESTOS CONTRACTOR REMOVING ASBESTOS CONTAMINATED SOILS FROM STEAM MAIN ROUTES.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	17/7810	14
LOCATION:	AREA S	
ACTIVITY:		
INTERNAL VIEW OF BUILDING 88A - WEST WALL.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	17/7810	15
LOCATION:	AREA S	
ACTIVITY:		
INTERNAL VIEW OF BUILDING 88A - EAST AND NORTH WALLS.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	17/7810	16
LOCATION:	AREA S	
ACTIVITY:		
CANAL SOUTH OF BUILDING 88A.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	17/7810	17
LOCATION:	AREA S	
ACTIVITY:		
STEAM MAIN SUPPORTS.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	17/7810	18


LOCATION:	AREAS	
ACTIVITY:		
STEAM MAIN SUPPORTS.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	17/7810	19
LOCATION:	AREA S	
ACTIVITY:		
STEAM MAIN SUPPORTS.		
SPECIAL FEATURES:		
CANAL CLEARANCE IN PROGRESS.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	17/7810	20
LOCATION:	AREA S	
ACTIVITY:		
STEAM MAIN ROUTES.		
SPECIAL FEATURES:		
WORK IN PROGRESS BY LICENSED ASBESTOS CONTRACTORS REMOVING ASBESTOS CONTAMINATED SOIL FROM STEAM MAIN ROUTES.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	17/7810	21
LOCATION:	AREA S	
ACTIVITY:		
SOUTH OF BUILDING 88A - STEAM MAIN ROUTES.		
SPECIAL FEATURES:		
WORK IN PROGRESS BY LICENSED ASBESTOS CONTRACTORS.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	17/7810	22
LOCATION:	AREA S	
ACTIVITY:		
CANAL SOUTH OF BUILDING 88A.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	17/7810	23
LOCATION:	AREA S	
ACTIVITY:		
SOUTH ELEVATION OF BUILDING 88B.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	17/7810	24

LOCATION:	AREA S	
ACTIVITY:		
STEAM MAIN IN SSSI.		
SPECIAL FEATURES:		
PIPEWORK CLAD WITH ASBESTOS IN DEGRADED STATE.		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	17/7810	25
LOCATION:	AREA S	
ACTIVITY:		
SOUTH OF BUILDING 88A.		
SPECIAL FEATURES:		
ASBESTOS CONTAMINATED SOIL CLEARANCE.		



--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	17/7810	26
LOCATION:	AREA S	
ACTIVITY:		
SOUTH OF BUILDING 88A.		
SPECIAL FEATURES:		
WORK IN PROGRESS BY LICENSED ASBESTOS CONTRACTOR, CLEARANCE OF ASBESTOS CONTAMINATED SOIL ON STEAM MAIN ROUTES.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	17/7810	27
LOCATION:	AREA S	
ACTIVITY:		
DIGGING OUT WASTE FROM CANAL ADJACENT TO BUILDING 62.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	17/7810	28
LOCATION:	AREA S	
ACTIVITY:		
EXCAVATION AND BAGGING OF ASBESTOS FOUND IN WASTE DUMP.		
SPECIAL FEATURES:		

WORK IN PROGRESS BY LICENSED ASBESTOS CONTRACTOR.

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	17/7810	29
LOCATION:	AREA S	
ACTIVITY:		
WASTE DUG OUT FROM CANAL ADJACENT TO BUILDING 62.		

SPECIAL FEATURES:
CANAL CLEARANCE IN PROGRESS - ASBESTOS DUMP LOCATED, WEST OF BUILDING 62'S ENTRANCE.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	17/7810	30

LOCATION:	AREAS	
ACTIVITY:		
CANAL WEST OF BUILDING 62 -LOOKING SOUTH.		
SPECIAL FEATURES:		
CANAL CLEARANCE IN PROGRESS, NOTE REVETMENT DESTROYED BY SYCAMORE TREES.		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	17/7810	31
LOCATION:	AREA S	
ACTIVITY:		
CANAL CLEARANCE WEST OF BUILDING 76.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	17/7810	32
LOCATION:	AREA S	
ACTIVITY:		
NORTH WEST ELEVATION OF BUILDING E14.		
SPECIAL FEATURES:		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	17/7810	33
LOCATION:	AREA S	
ACTIVITY:		
WEST ELEVATION OF BUILDIING 76.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	17/7810	34
LOCATION:	AREA S	
ACTIVITY:		
SOUTH WEST ELEVATION OF BUILDING E14.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	17/7810	35
LOCATION:	AREA S	
ACTIVITY:		
SOUTH ELEVATION OF BUILDING 76 VIEWED FROM TOP OF BUILDING E14		

TRAVERSE.
SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	17/7810	36

LOCATION:	AREAS	
ACTIVITY:		
CANAL NORTH OF BUILDING E14 LOOKING TOWARDS BUILDING 88A.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
NOV '92	17/7810	37
LOCATION:	AREA S	
ACTIVITY:		
VIEW OF BUILDING 88A FROM ROOF OF BUILDING E14.		
SPECIAL FEATURES:		




FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
DEC '92	18/7998	1
LOCATION:	AREA H	
ACTIVITY:		
SOUTH ELEVATION OF BUILDING H26.		
SPECIAL FEATURES:		



--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
DEC '92	18/7998	2
LOCATION:	AREA H	
ACTIVITY:		
SOUTH WEST ELEVATION OF BUILDING H26.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
DEC '92	18/7998	3
LOCATION:	AREA H	
ACTIVITY:		
NORTH WEST ELEVATION OF BUILDING A203.		
SPECIAL FEATURES:		
BRIDGE 17 IN FOREGROUND.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
DEC '92	18/7998	4
LOCATION:	AREA H	
ACTIVITY:		
NORTH AND EAST ELEVATIONS OF BUILDING H7.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
DEC '92	18/7998	5
LOCATION:	AREA L	
ACTIVITY:		
NORTH AND WEST ELEVATIONS OF BUILDING L122.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
DEC '92	18/7998	6


LOCATION:	AREA M	
ACTIVITY:		
NORTH AND WEST ELEVATIONS OF BUILDING L145.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
DEC '92	18/7998	7
LOCATION:	AREA M	
ACTIVITY:		
WEST ELEVATION OF BUILDING L148.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
DEC '92	18/7998	8
LOCATION:	AREA S	
ACTIVITY:		
SOUTH WEST ELEVATION OF 'WATERMANS COTTAGE'.		
SPECIAL FEATURES:		






FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
DEC '92	18/7998	9
LOCATION:	AREA S	
ACTIVITY:		
NORTH ELEVATION OF 'WATERMANS COTTAGE'.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
DEC '92	18/7998	10
LOCATION:	AREA H	
ACTIVITY:		
EAST ELEVATION OF BUILDING A203.		
SPECIAL FEATURES:		

BRIDGE No. 1 TO THE LEFT OF FOREGROUND.



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
DEC '92	18/7998	11
LOCATION:	AREA P	
ACTIVITY:		
EAST ELEVATION OF BUILDING A268.		

SPECIAL FEATURES:
NOTE 'CANNON BARREL' BOLLARD AND 'POWDERMILL LANE' IN FOREGROUND.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
DEC '92	18/7998	12

LOCATION:	AREA P	
ACTIVITY:		
EAST ELEVATION OF BUILDING A269.		
SPECIAL FEATURES:		
'POWDERMILL LANE' IN FOREGROUND.		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
DEC '92	18/7998	13
LOCATION:	AREA P	
ACTIVITY:		
NORTH ELEVATION OF BUILDING A238.		
SPECIAL FEATURES:		
'MAIN GATE' TO SITE.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
DEC '92	18/7998	14
LOCATION:	AREA P	
ACTIVITY:		
SOUTH ELEVATION OF BUILDING A221.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
DEC '92	18/7998	15
LOCATION:	AREA P	
ACTIVITY:		
EAST ELEVATION OF BUILDING A221.		
SPECIAL FEATURES:		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
DEC '92	18/7998	16
LOCATION:	AREA P	
ACTIVITY:		
WEST ELEVATION OF BUILDING A268.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
DEC '92	18/7998	17
LOCATION:	AREA P	
ACTIVITY:		
NORTH AND WEST ELEVATIONS OF BUILDING A269.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
DEC '92	18/7998	18


LOCATION:	AREA M	
ACTIVITY:		
NORTH EAST ELEVATION OF BUILDING L177.		
SPECIAL FEATURES:		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
DEC '92	18/7998	19
LOCATION:	AREA M	
ACTIVITY:		
SOUTH EAST ELEVATION OF BUILDING L177.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
DEC '92	18/7998	20
LOCATION:	AREA M	
ACTIVITY:		
NORTH ELEVATION OF BUILDING L168.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
DEC '92	18/7998	21
LOCATION:	AREA L	
ACTIVITY:		
NORTH EAST ELEVATION OF BUILDING L165.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
DEC '92	18/7998	22
LOCATION:	AREA L	
ACTIVITY:		
WEST ELEVATION OF BUILDING L165.		
SPECIAL FEATURES:		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
DEC '92	18/7998	23
LOCATION:	AREA M	
ACTIVITY:		
SOUTH AND WEST ELEVATIONS OF BUILDING L168.		


SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
DEC '92	19/8812	1
LOCATION:	AREA P	
ACTIVITY:		
ROYAL ORDNANCE OFFICE CHRISTMAS TREE.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
DEC '92	19/8812	2
LOCATION:	AREA S	
ACTIVITY:		
RECOVERED TETRYL DEPOSIT FROM CANAL BED NORTH OF BUILDING S31.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
DEC '92	19/8812	3
LOCATION:	AREA S	
ACTIVITY:		
RECOVERED TETRYL DEPOSIT FROM CANAL BED NORTH OF BUILDING S31.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
DEC '92	19/8812	4
LOCATION:	AREA S	
ACTIVITY:		
CLEARING OUT BUILDING E2.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
DEC '92	19/8812	5
LOCATION:	AREAS	
ACTIVITY:		
CLEARING OUT BUILDING E2.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
DEC '92	19/8812	6




LOCATION:	AREA H	
ACTIVITY:		
SOIL STRIP OF STEAM MAIN ROUTES IN AREA 'H'		
SPECIAL FEATURES:		
SOIL CONTAMINATED BY ASBESTOS. BRIDGE 17 AT RIGHT BACKGROUND.		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
DEC '92	19/8812	7
LOCATION:	AREA S	
ACTIVITY:		
REMOVAL OF CONTAMINATED SOIL ALONG FORMER STEAM MAIN ROUTES.		
SPECIAL FEATURES:		
WORK IN PROGRESS BY LICENSED ASBESTOS CONTRACTOR.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
DEC '92	19/8812	8
LOCATION:	AREA S	
ACTIVITY:		
CLEARING OUT BUILDING E3.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
DEC '92	19/8812	9
LOCATION:	AREA S	
ACTIVITY:		
TREE FELLING AT BUILDING 103 'PRESS HOUSE'.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
DEC '92	19/8812	10
LOCATION:	AREA S	
ACTIVITY:		
TREE FELLING AT BUILDING 103 'PRESS HOUSE'.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
DEC '92	19/8812	11
LOCATION:	AREA S	
ACTIVITY:		
STOCKPILED WOOD CHIPPINGS FROM TREE FELLING.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
DEC '92	19/8812	12

LOCATION:	AREAS	
ACTIVITY:		
WEST ELEVATION OF BUILDING 103 'PRESS HOUSE'.		
SPECIAL FEATURES:		



**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
DEC '92	19/8812	13
LOCATION:	AREA S	
ACTIVITY:		
TREE FELLING AT WASTE TIP ADJACENT TO BUILDING 103.		
SPECIAL FEATURES:		
BUILDING 103 TO LEFT OF THE PICTURE.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
DEC '92	19/8812	14
LOCATION:	AREA S	
ACTIVITY:		
TREE FELLING AT WASTE TIP ADJACENT TO BUILDING 103.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
DEC '92	19/8812	15
LOCATION:	AREA S	
ACTIVITY:		
TREE FELLING AT BUILDING S30 - VIEW LOOKING WEST.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
DEC '92	19/8812	16
LOCATION:	AREA S	
ACTIVITY:		
INVESTIGATING EXISTING SERVICE ROUTES.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
DEC '92	19/8812	17
LOCATION:	AREA S	
ACTIVITY:		
INVESTIGATING EXISTING SERVICE ROUTES.		

SPECIAL FEATURES:


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
DEC '92	19/8812	18

LOCATION:	AREAS	
ACTIVITY:		
INVESTIGATING EXISTING SERVICE ROUTES.		
SPECIAL FEATURES:		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
DEC '92	19/8812	19
LOCATION:	AREA P	
ACTIVITY:		
NORTH EAST ELEVATION OF BUILDING A214.		
SPECIAL FEATURES:		
BUILDING A210 IN BACKGROUND.		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
DEC '92	19/8812	20
LOCATION:	AREA P	
ACTIVITY:		
NORTH EAST ELEVATION OF BUILDING A214.		
SPECIAL FEATURES:		
BUILDING A210 IN BACKGROUND.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
DEC '92	19/8812	21
LOCATION:	AREA P	
ACTIVITY:		
NORTH EAST ELEVATION OF BUILDING A214.		
SPECIAL FEATURES:		
BUILDING A210 IN BACKGROUND.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
DEC '92	19/8812	22
LOCATION:	AREA P	
ACTIVITY:		
NORTH EAST ELEVATION OF BUILDING A214.		
SPECIAL FEATURES:		

BUILDING A210 IN BACKGROUND.




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
DEC '92	19/8812	23
LOCATION:	AREA P	
ACTIVITY:		
NORTH EAST ELEVATION OF BUILDING A214.		

SPECIAL FEATURES:
BUILDING A210 IN BACKGROUND.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
DEC '92	19/8812	24

LOCATION:	AREA P	
ACTIVITY:		
NORTH EAST ELEVATION OF BUILDING A214.		
SPECIAL FEATURES:		
BUILDING A210 IN BACKGROUND.		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
DEC '92	19/8812	25
LOCATION:	AREA P	
ACTIVITY:		
NORTH EAST ELEVATION OF BUILDING A214.		
SPECIAL FEATURES:		
BUILDING A210 IN BACKGROUND.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
DEC '92	19/8812	26
LOCATION:	AREA P	
ACTIVITY:		
NORTH EAST ELEVATION OF BUILDING A214.		
SPECIAL FEATURES:		
BUILDING A210 IN BACKGROUND.		






FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
DEC '92	19/8812	27
LOCATION:	AREA P	
ACTIVITY:		
NORTH EAST ELEVATION OF BUILDING A214.		
SPECIAL FEATURES:		
BUILDING A210 IN BACKGROUND.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
DEC '92	19/8812	28
LOCATION:	AREA P	
ACTIVITY:		
NORTH EAST ELEVATION OF BUILDING A214.		
SPECIAL FEATURES:		

BUILDING A210 IN BACKGROUND.



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
DEC '92	19/8812	29
LOCATION:	AREA P	
ACTIVITY:		
NORTH EAST ELEVATION OF BUILDING A214.		

SPECIAL FEATURES:
BUILDING A210 IN BACKGROUND.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
DEC '92	19/8812	30

LOCATION:	AREA P	
ACTIVITY:		
NORTH EAST ELEVATION OF BUILDING A214.		
SPECIAL FEATURES:		
BUILDING A210 IN BACKGROUND.		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
DEC '92	19/8812	31
LOCATION:	AREA P	
ACTIVITY:		
NORTH EAST ELEVATION OF BUILDING A214.		
SPECIAL FEATURES:		
BUILDING A210 IN BACKGROUND.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
DEC '92	19/8812	32
LOCATION:	AREA H	
ACTIVITY:		
H16 SAMPLING SLAB PREPARATION.		
SPECIAL FEATURES:		




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
DEC '92	19/8812	33
LOCATION:	AREA H	
ACTIVITY:		
H16 SAMPLING SLAB PREPARATION.		
SPECIAL FEATURES:		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
DEC '92	19/8812	34
LOCATION:	AREA H	
ACTIVITY:		
H16 SAMPLING SLAB PREPARATION.		
SPECIAL FEATURES:		

BUILDING A250 IN BACKGROUND.



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
DEC '92	19/8812	35
LOCATION:	AREA H	
ACTIVITY:		
H16 SAMPLING SLAB PREPARATION.		


SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
DEC '92	19/8812	36

LOCATION:	AREA H	
ACTIVITY:		
H16 SAMPLING SLAB PREPARATION.		
SPECIAL FEATURES:		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
DEC '92	19/8812	R
LOCATION:	AREA H	
ACTIVITY:		
H16 SAMPLING SLAB PREPARATION.		
SPECIAL FEATURES:		




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	20/9355	1
LOCATION:	AREA S	
ACTIVITY:		
FLOODED CANAL WEST OF LONG WALK - LOOKING NORTH AT BRIDGE No. 7.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	20/9355	2
LOCATION:	AREA S	
ACTIVITY:		
FLOODED CANAL WEST OF LONG WALK - LOOKING SOUTH AT BRIDGE No. 7.		
SPECIAL FEATURES:		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	20/9355	3
LOCATION:	AREA S	
ACTIVITY:		
AREA EAST OF BUILDING L128 - SHOWING FLOODING.		
SPECIAL FEATURES:		
'MILL WHEELS' IN FOREGROUND.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	20/9355	4
LOCATION:	AREA S	
ACTIVITY:		
NORTH WEST ACCESS BRIDGE TO BUILDING L128 - BRIDGE No. 7.		
SPECIAL FEATURES:		

RECOVERED STONWORK.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	20/9355	5
LOCATION:	AREA S	
ACTIVITY:		
FLOODING IN OLD MILLHEAD STREAM VIEWED FROM WEST SIDE OF		

BUILDING L128 - LOOKING SOUTH.
SPECIAL FEATURES:


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	20/9355	6

LOCATION:	AREAS	
ACTIVITY:		
FLOODING IN CANAL SOUTH OF BUILDING 107 AND 108.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	20/9355	7
LOCATION:	AREA S	
ACTIVITY:		
FLOODING WEST OF LONG WALK.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	20/9355	8
LOCATION:	AREA S	
ACTIVITY:		
FLOODING IN CANAL WEST OF BUILDING S30 - LOOKING SOUTH.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	20/9355	9
LOCATION:	AREA S	
ACTIVITY:		
VIEW SOUTH OF BUILDING S28 (WEST).		
SPECIAL FEATURES:		
LICENSED ASBESTOS CONTRACTORS PROGRESSING WITH ASBESTOS CONTAMINATED SOIL CLEARANCE FROM STEAM MAIN ROUTES.		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	20/9355	10
LOCATION:	AREA S	
ACTIVITY:		
FLOODING IN CANAL WEST OF BUILDING S30 (WEST).		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	20/9355	11
LOCATION:	AREA S	
ACTIVITY:		
ASBESTOS MATERIAL STACKED FOR DISPOSAL.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	20/9355	12

LOCATION:	AREAS	
ACTIVITY:		
ASBESTOS MATERIAL STACKED FOR DISPOSAL.		
SPECIAL FEATURES:		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	20/9355	13
LOCATION:	AREA S	
ACTIVITY:		
FLOODED POND NORTH OF BUILDING E2.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	20/9355	14
LOCATION:	AREA S	
ACTIVITY:		
ARTIFACT FOUND NEAR POND NORTH OF BUILDING E2.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	20/9355	15
LOCATION:	AREA S	
ACTIVITY:		
FLOODED CONTAMINATED POND NORTH OF BUILDING E2.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	20/9355	16
LOCATION:	AREA S	
ACTIVITY:		
FLOODED CONTAMINATED POND NORTH OF BUILDING E2.		
SPECIAL FEATURES:		




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	20/9355	17
LOCATION:	AREA S	
ACTIVITY:		
FLOODED POND NORTH WEST OF BUILDING E2.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	20/9355	18

LOCATION:	AREA M	
ACTIVITY:		
NOTICE ON DOOR IN BUILDING L145 PRIOR TO STRIPPING OUT BUILDING L148.		
SPECIAL FEATURES:		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDICATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	20/9355	19
LOCATION:	AREA S	
ACTIVITY:		
CRACKED WILLOW DAMAGED IN GALE.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	20/9355	20
LOCATION:	AREA B	
ACTIVITY:		
BUILDING 96.		
SPECIAL FEATURES:		
COLLAPSING THE ROOF TO MAKE IT SAFE.		




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	20/9355	21
LOCATION:	AREA B	
ACTIVITY:		
GENERAL VIEW OF BUILDING 96.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	20/9355	22
LOCATION:	AREA B	
ACTIVITY:		
GAS CYLINDERS ADJACENT TO BUILDING L103.		
SPECIAL FEATURES:		

SOME OF THE GAS CYLINDERS RECOVERED FROM FILLED AREAS  
ADJACENT TO THE BURNING GROUND.



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	20/9355	23
LOCATION:	AREA S	
ACTIVITY:		
FLOODED AREA OF SSSI.		



SPECIAL FEATURES:


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	20/9355	24

LOCATION:	AREAS	
ACTIVITY:		
REMOVAL OF CONCRETE & MASONRY WEST OF BUILDING 103.		
SPECIAL FEATURES:		
ATTEMPT AT REMOVING TIPPED WASTE BEFORE AGREED TREE REMOVAL TOOK PLACE.		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	20/9355	25
LOCATION:	AREA S	
ACTIVITY:		
CONTAMINATION IN AREA WEST OF BUILDING 103.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	20/9355	26
LOCATION:	AREA S	
ACTIVITY:		
ROAD SWEEPER.		
SPECIAL FEATURES:		
KEEPING SITE ACCESS ROUTES CLEAN.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	20/9355	27
LOCATION:	AREA M	
ACTIVITY:		
SOUTH EAST CORNER OF AREA M, REMOVAL OF CORDITE CONTAMINATED SOIL.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	20/9355	28
LOCATION:	AREA M	
ACTIVITY:		
SOUTH EAST CORNER OF AREA M, REMOVAL OF CORDITE CONTAMINATED SOIL.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	20/9355	29
LOCATION:	AREA M	
ACTIVITY:		
SOUTH EAST CORNER OF AREA M, REMOVAL OF CORDITE		

CONTAMINATED SOIL.
SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	20/9355	30



LOCATION:	AREA M	
ACTIVITY:		
SCREENING CORDITE CONTAMINATED SOIL.		
SPECIAL FEATURES:		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	20/9355	31
LOCATION:	AREA M	
ACTIVITY:		
SCREENING CORDITE CONTAMINATED SOIL.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	20/9355	32
LOCATION:	AREA M	
ACTIVITY:		
SCREENING CORDITE CONTAMINATED SOIL.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	20/9355	33
LOCATION:	AREA M	
ACTIVITY:		
SCREENING CORDITE CONTAMINATED SOIL.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	20/9355	34
LOCATION:	AREA M	
ACTIVITY:		
SCREENED CORDITE CONTAMINATED SOIL.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	20/9355	35
LOCATION:	AREA M	
ACTIVITY:		
SCREENING CORDITE CONTAMINATED SOIL.		

SPECIAL FEATURES:


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	20/9355	36

LOCATION:	AREA M	
ACTIVITY:		
SCREENING CORDITE CONTAMINATED SOIL.		
SPECIAL FEATURES:		



**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	20/9355	36 a
LOCATION:	AREA M	
ACTIVITY:		
SCREENING CORDITE CONTAMINATED SOIL.		
SPECIAL FEATURES:		
HAND SORTING FOR CORDITE AFTER SCREENING.		



**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	21/9361	1
LOCATION:	AREA B	
ACTIVITY:		
CLEARANCE OF CANAL WEST OF BUILDING L103.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	21/9361	2
LOCATION:	AREA B	
ACTIVITY:		
GAS CYLINDERS REMOVED FROM WASTE FILLED CANAL WEST OF BUILDING L103.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	21/9361	3
LOCATION:	AREA H	
ACTIVITY:		
EXCAVATED MATERIAL FROM FILLED CANALS BEING TIPPED ON H16 SAMPLING SLAB.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	21/9361	4
LOCATION:	AREA H	
ACTIVITY:		
MACHINE TRACKING BETWEEN BAYS OF CONTAMINATED MATERIAL ON H16 SAMPLING SLAB.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	21/9361	5
LOCATION:	AREA H	
ACTIVITY:		
SAMPLING IN PROGRESS ON CONTAMINATED WASTE (H16 SAMPLING)		

AREA).
SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	21/9361	6




LOCATION:	AREA H	
ACTIVITY:		
SAMPLING IN PROGRESS ON CONTAMINATED WASTE (H16 SAMPLING AREA).		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	21/9361	7
LOCATION:	AREA B	
ACTIVITY:		
FURTHER EXCAVATION OF CONTAMINATED WASTE WEST OF BUILDING L103.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	21/9361	8
LOCATION:	AREA B	
ACTIVITY:		
GAS CYLINDERS REMOVED FROM WASTE FILLED CANAL WEST OF BUILDING L103.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	21/9361	9
LOCATION:	AREA B	
ACTIVITY:		
INSPECTION OF GAS CYLINDERS REMOVED FROM WASTE FILLED CANAL WEST OF BUILDING L103.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	21/9361	10
LOCATION:	AREA H	
ACTIVITY:		
VIEW OF CONTAMINATED WASTE SAMPLING AREA ON H16.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	21/9361	11
LOCATION:	AREA H	
ACTIVITY:		
CONTAMINATED WASTE STORED ON H16 SAMPLING AREA.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	21/9361	12


LOCATION:	AREA B	
ACTIVITY:		
GAS CYLINDERS REMOVED FROM WASTE FILLED CANAL WEST OF BUILDING L103.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	21/9361	13
LOCATION:	AREA B	
ACTIVITY:		
GAS CYLINDERS REMOVED FROM WASTE FILLED CANAL WEST OF BUILDING L103.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	21/9361	14
LOCATION:	AREA B	
ACTIVITY:		
VIEW OF GAS CYLINDERS REMOVED FROM WASTE FILLED CANAL WEST OF BUILDING L103.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	21/9361	15
LOCATION:	AREA B	
ACTIVITY:		
EXCAVATION OF WASTE FILLED CANAL WEST OF BUILDING L103.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	21/9361	16
LOCATION:	AREA B	
ACTIVITY:		
GAS CYLINDERS REMOVED FROM WASTE FILLED CANALS.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	21/9361	17
LOCATION:	AREA B	
ACTIVITY:		
EXCAVATION OF WASTE FILLED CANAL IN PROGRESS - WEST OF		

BUILDING L103.
SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	21/9361	18

LOCATION:	AREA B	
ACTIVITY:		
VIEW OF CANOPY TO BUILDING L103 ON CANAL SIDE.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	21/9361	19
LOCATION:	AREA B	
ACTIVITY:		
CONTAMINATED WASTE IN CANAL WEST OF BUILDING L103 (ADJACENT TO BUILDING ENTRANCE).		
SPECIAL FEATURES:		



--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	21/9361	20
LOCATION:	AREA B	
ACTIVITY:		
SOUTH VIEW SHOWING EXCAVATION OF WASTE FILLED CANAL WEST OF BUILDING L103.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	21/9361	21
LOCATION:	AREA B	
ACTIVITY:		
CONTAMINATED WASTE IN CANAL WEST OF BUILDING L103.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	21/9361	22
LOCATION:	AREA S	
ACTIVITY:		
CONTAMINATED WASTE TIP SOUTH EAST OF BUILDINGS 107 & 108.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	21/9361	23
LOCATION:	AREA S	
ACTIVITY:		
PIPE BRIDGES OVER WASTE FILLED CANALS, WEST ENTRANCE OF		

BURNING GROUND.
SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	21/9361	24

LOCATION:	AREA H	
ACTIVITY:		
H16 SAMPLING AREA.		
SPECIAL FEATURES:		


**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	21/9361	25
LOCATION:	AREA H	
ACTIVITY:		
H16 SAMPLING AREA.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	21/9361	26
LOCATION:	AREA H	
ACTIVITY:		
CONTAMINATED BOTTLES FROM WASTE ON H16 SAMPLING AREA.		
SPECIAL FEATURES:		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	21/9361	27
LOCATION:	AREA B	
ACTIVITY:		
FUZE RECOVERED FROM NORTH END OF BURNING GROUND.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	21/9361	28
LOCATION:	AREA B	
ACTIVITY:		
FUZE RECOVERED FROM NORTH END OF BURNING GROUND.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	21/9361	29
LOCATION:	AREA L	
ACTIVITY:		
FLOODED AREA WEST OF INCORPORATING MILLS (QUEENS MEAD).		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	21/9361	30


LOCATION:	AREA B	
ACTIVITY:		
FLOODED CANAL WEST OF BUILDING L103.		
SPECIAL FEATURES:		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	21/9361	31
LOCATION:	AREA S	
ACTIVITY:		
FLOODED CANAL WEST OF BUILDING 76.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	21/9361	32
LOCATION:	AREA S	
ACTIVITY:		
FLOODED AREA AROUND MACHINE (LOOKING NORTH TOWARDS BUILDING 62).		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	21/9361	33
LOCATION:	AREA S	
ACTIVITY:		
FLOODED CANAL WEST OF BUILDING 76.		
SPECIAL FEATURES:		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	21/9361	34
LOCATION:	AREA S	
ACTIVITY:		
FLOODED CANAL - BUILDING E14 AT RIGHT OF PICTURE.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	21/9361	35
LOCATION:	AREA T	
ACTIVITY:		
FLOODED TETRYL AREA, VIEWED TOWARDS HORSEMILL STREAM.		


SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	21/9361	36

LOCATION:	AREAS	
ACTIVITY:		
FLOODED PONDS NORTH OF BUILDING E2.		
SPECIAL FEATURES:		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	21/9361	37
LOCATION:	AREA S	
ACTIVITY:		
EXTENT OF EROSION DUE TO FLOOD WEST OF BUILDING E12.		
SPECIAL FEATURES:		




**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	22/9590	1
LOCATION:	AREA M	
ACTIVITY:		
EAST ELEVATION OF BUILDING L148.		
SPECIAL FEATURES:		
SEALING EXTERNAL OPENINGS FOR ASBESTOS REMOVAL.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	22/9590	2
LOCATION:	AREA M	
ACTIVITY:		
VIEW OF EAST ELEVATION OF BUILDING L148.		
SPECIAL FEATURES:		
RUBBISH FROM UNDERFLOOR VOID.		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	22/9590	3
LOCATION:	AREA M	
ACTIVITY:		
VIEW ALONG EAST ELEVATION OF BUILDING L148.		
SPECIAL FEATURES:		
RUBBISH EXTRACTED FROM UNDERFLOOR VOID.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	22/9590	4
LOCATION:	AREA M	
ACTIVITY:		
VIEW ALONG EAST ELEVATION OF BUILDING L148.		
SPECIAL FEATURES:		

RUBBISH EXTRACTED FROM UNDERFLOOR VOID.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	22/9590	5
LOCATION:	AREA M	
ACTIVITY:		
EXTERNAL VIEW OF BUILDING L148.		


SPECIAL FEATURES:
RUBBISH EXTRACTED FROM UNDERFLOOR VOID.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	22/9590	6

LOCATION:	AREA M	
ACTIVITY:		
WEST ELEVATION OF BUILDING L148.		
SPECIAL FEATURES:		
SEALING EXTERNAL OPENINGS FOR ASBESTOS REMOVAL.		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	22/9590	7
LOCATION:	AREA M	
ACTIVITY:		
INTERNAL VIEW OF BUILDING L148.		
SPECIAL FEATURES:		
ASBESTOS REMOVAL - NEGATIVE AIR TENT IN PLACE.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	22/9590	8
LOCATION:	AREA M	
ACTIVITY:		
INTERNAL VIEW OF BUILDING L148.		
SPECIAL FEATURES:		
TYPE 'H' VACUUM IN USE.		




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	22/9590	9
LOCATION:	AREA M	
ACTIVITY:		
INTERNAL VIEW OF BUILDING L148.		
SPECIAL FEATURES:		
INTERNAL STRIP OUT.		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	22/9590	10
LOCATION:	AREA M	
ACTIVITY:		
INTERNAL VIEW OF BUILDING L148.		
SPECIAL FEATURES:		

INTERNAL STRIP OUT.



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	22/9590	11
LOCATION:	AREA M	
ACTIVITY:		
INTERNAL VIEW OF BUILDING L148.		


SPECIAL FEATURES:
INTERNAL STRIP OUT.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	22/9590	12


LOCATION:	AREA M	
ACTIVITY:		
INTERNAL VIEW OF BUILDING L148.		
SPECIAL FEATURES:		
INTERNAL STRIP OUT.		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	22/9590	13
LOCATION:	AREA M	
ACTIVITY:		
INTERNAL VIEW OF BUILDING L148.		
SPECIAL FEATURES:		
FLOOR SEALED AGAINST MIGRATION OF ASBESTOS FIBRE.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	22/9590	14
LOCATION:	AREA M	
ACTIVITY:		
INTERNAL VIEW OF BUILDING L148.		
SPECIAL FEATURES:		
PERSONNEL CHANGING ROOM.		




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	22/9590	15
LOCATION:	AREA M	
ACTIVITY:		
INTERNAL VIEW OF UNDERFLOOR VOID IN BUILDING L148.		
SPECIAL FEATURES:		
ASBESTOS LAGGING TO SERVICE PIPEWORK.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	22/9590	16
LOCATION:	AREA M	
ACTIVITY:		
INTERNAL VIEW OF UNDERFLOOR VOID IN BUILDING L148.		
SPECIAL FEATURES:		



ASBESTOS LAGGING TO SERVICE PIPEWORK.



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	22/9590	17
LOCATION:	AREA M	
ACTIVITY:		
INTERNAL VIEW OF UNDERFLOOR VOID IN BUILDING L148.		

SPECIAL FEATURES:
ASBESTOS LAGGING TO SERVICE PIPEWORK.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	22/9590	18


LOCATION:	AREA M	
ACTIVITY:		
INTERNAL VIEW OF UNDERFLOOR VOID IN BUILDING L148.		
SPECIAL FEATURES:		
ASBESTOS DEBRIS PRESENT.		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	22/9590	19
LOCATION:	AREA M	
ACTIVITY:		
INTERNAL VIEW OF UNDERFLOOR VOID IN BUILDING L148.		
SPECIAL FEATURES:		
ASBESTOS DEBRIS PRESENT.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	22/9590	20
LOCATION:	AREA M	
ACTIVITY:		
INTERNAL VIEW OF UNDERFLOOR VOID IN BUILDING L148.		
SPECIAL FEATURES:		
ASBESTOS DEBRIS PRESENT.		




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	22/9590	21
LOCATION:	AREA M	
ACTIVITY:		
INTERNAL VIEW OF UNDERFLOOR VOID IN BUILDING L148.		
SPECIAL FEATURES:		
ASBESTOS LAGGED SERVICE PIPEWORK.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	22/9590	22
LOCATION:	AREA M	
ACTIVITY:		
INTERNAL VIEW OF UNDERFLOOR VOID IN BUILDING L148.		
SPECIAL FEATURES:		

ASBESTOS LAGGED SERVICE PIPEWORK.



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	22/9590	23
LOCATION:	AREA M	
ACTIVITY:		
INTERNAL VIEW OF UNDERFLOOR VOID IN BUILDING L148.		



SPECIAL FEATURES:
ASBESTOS LAGGED SERVICE PIPEWORK.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	22/9590	24


LOCATION:	AREA M	
ACTIVITY:		
INTERNAL VIEW OF UNDERFLOOR VOID IN BUILDING L148.		
SPECIAL FEATURES:		
ASBESTOS LAGGED SERVICE PIPEWORK.		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	22/9590	25
LOCATION:	AREA M	
ACTIVITY:		
INTERNAL VIEW OF UNDERFLOOR VOID IN BUILDING L148.		
SPECIAL FEATURES:		
ASBESTOS & OTHER DEBRIS PRESENT.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	22/9590	26
LOCATION:	AREA M	
ACTIVITY:		
INTERNAL VIEW OF UNDERFLOOR VOID IN BUILDING L148.		
SPECIAL FEATURES:		
ASBESTOS LAGGED SERVICE PIPEWORK.		




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	22/9590	27
LOCATION:	AREA M	
ACTIVITY:		
INTERNAL VIEW OF UNDERFLOOR VOID IN BUILDING L148.		
SPECIAL FEATURES:		
ASBESTOS LAGGED SERVICE PIPEWORK.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	22/9590	28
LOCATION:	AREA M	
ACTIVITY:		
INTERNAL VIEW OF UNDERFLOOR VOID IN BUILDING L148.		
SPECIAL FEATURES:		

ASBESTOS LAGGED SERVICE PIPEWORK.



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	22/9590	29
LOCATION:	AREA M	
ACTIVITY:		
INTERNAL VIEW OF UNDERFLOOR VOID IN BUILDING L148.		

SPECIAL FEATURES:
ASBESTOS AND OTHER DEBRIS PRESENT.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	22/9590	30




LOCATION:	AREA M	
ACTIVITY:		
INTERNAL VIEW OF UNDERFLOOR VOID IN BUILDING L148.		
SPECIAL FEATURES:		
ASBESTOS AND OTHER DEBRIS PRESENT.		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	22/9590	31
LOCATION:	AREA M	
ACTIVITY:		
INTERNAL VIEW OF UNDERFLOOR VOID IN BUILDING L148.		
SPECIAL FEATURES:		
ASBESTOS AND OTHER DEBRIS PRESENT.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	22/9590	32
LOCATION:	AREA M	
ACTIVITY:		
INTERNAL VIEW OF UNDERFLOOR VOID IN BUILDING L148.		
SPECIAL FEATURES:		
ASBESTOS AND OTHER DEBRIS PRESENT.		




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	22/9590	33
LOCATION:	AREA M	
ACTIVITY:		
INTERNAL VIEW OF UNDERFLOOR VOID IN BUILDING L148.		
SPECIAL FEATURES:		
ASBESTOS LAGGED SERVICE PIPEWORK.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	22/9590	34
LOCATION:	AREA M	
ACTIVITY:		
INTERNAL VIEW OF UNDERFLOOR VOID IN BUILDING L148.		
SPECIAL FEATURES:		

ASBESTOS AND OTHER DEBRIS PRESENT.



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	22/9590	35
LOCATION:	AREA M	
ACTIVITY:		
INTERNAL VIEW OF UNDERFLOOR VOID IN BUILDING L148.		


SPECIAL FEATURES:
ASBESTOS AND OTHER DEBRIS PRESENT.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	22/9590	36

LOCATION:	AREA M	
ACTIVITY:		
INTERNAL VIEW OF UNDERFLOOR VOID IN BUILDING L148.		
SPECIAL FEATURES:		
ASBESTOS AND OTHER DEBRIS PRESENT.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	22/9590	37
LOCATION:	AREA M	
ACTIVITY:		
VIEW DOWN UNDERFLOOR VOID IN BUILDING L148.		
SPECIAL FEATURES:		
ASBESTOS AND OTHER DEBRIS PRESENT.		




FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	23/9591	1
LOCATION:	AREA S	
ACTIVITY:		
TIP SITE 11036.		
SPECIAL FEATURES:		
DISCOVERING BURIED ASBESTOS.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	23/9591	2
LOCATION:	AREA S	
ACTIVITY:		
TIP SITE 11036.		
SPECIAL FEATURES:		
DISCOVERING BURIED ASBESTOS.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	23/9591	3
LOCATION:	AREA S	
ACTIVITY:		
TIP SITE 11036.		
SPECIAL FEATURES:		
TREES GROWING OUT OF TIP.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	23/9591	4
LOCATION:	AREA S	
ACTIVITY:		
TIP SITE 11036.		
SPECIAL FEATURES:		

DISCOVERY OF ASBESTOS AND CHEMICALS.

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	23/9591	5
LOCATION:	AREAS	
ACTIVITY:		
TIP SITE 11036.		

SPECIAL FEATURES:
DISCOVERY OF CHEMICALS.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	23/9591	6



LOCATION:	AREAS	
ACTIVITY:		
TIP SITE 11036.		
SPECIAL FEATURES:		
DISCOVERY OF ASBESTOS.		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	23/9591	7
LOCATION:	AREA S	
ACTIVITY:		
TIP SITE 11036.		
SPECIAL FEATURES:		
DISCOVERY OF ASBESTOS.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	23/9591	8
LOCATION:	AREA S	
ACTIVITY:		
TIP SITE 11036.		
SPECIAL FEATURES:		
DISCOVERY OF ASBESTOS AND VEHICLE BATTERY.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	23/9591	9
LOCATION:	AREA S	
ACTIVITY:		
TIP SITE 11036.		
SPECIAL FEATURES:		
DISCOVERY OF ASBESTOS AND VEHICLE BATTERY.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	23/9591	10
LOCATION:	AREA S	
ACTIVITY:		
TIP SITE 11036.		
SPECIAL FEATURES:		

DISCOVERY OF ASBESTOS AND METALS.

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	23/9591	11
LOCATION:	AREA S	
ACTIVITY:		
TIP SITE 11036.		

SPECIAL FEATURES:
DISCOVERY OF ASBESTOS AND METALS.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	23/9591	12

LOCATION:	AREAS	
ACTIVITY:		
TIP SITE 11036.		
SPECIAL FEATURES:		
REMAINS OF DEMOLISHED STRUCTURES WITHIN RUBBISH DUMP.		



**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	23/9591	13
LOCATION:	AREA M	
ACTIVITY:		
CORDITE REMOVAL.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	23/9591	14
LOCATION:	AREA M	
ACTIVITY:		
CORDITE REMOVAL.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	23/9591	15
LOCATION:	AREA M	
ACTIVITY:		
CORDITE REMOVAL.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	23/9591	16
LOCATION:	AREA M	
ACTIVITY:		
INTERNAL VIEW OF UNDERCROFT IN BUILDING L153.		
SPECIAL FEATURES:		

DRIVE SHAFT MECHANISM.



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	23/9591	17
LOCATION:	AREA M	
ACTIVITY:		
INTERNAL VIEW OF UNDERCROFT IN BUILDING L153.		

SPECIAL FEATURES:
DRIVE SHAFT CROWN WHEEL.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	23/9591	18

LOCATION:	AREA M	
ACTIVITY:		
INTERNAL VIEW OF BUILDING L153.		
SPECIAL FEATURES:		
ENTRANCE TO UNDERCROFT.		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	23/9591	19
LOCATION:	AREA S	
ACTIVITY:		
TIP SITE 11036.		
SPECIAL FEATURES:		
ASBESTOS WITHIN RUBBISH DUMP.		



--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	23/9591	20
LOCATION:	AREA S	
ACTIVITY:		
TIP SITE 11036.		
SPECIAL FEATURES:		
ASBESTOS WITHIN RUBBISH DUMP.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	23/9591	21
LOCATION:	AREA S	
ACTIVITY:		
TIP SITE 11036.		
SPECIAL FEATURES:		
TREES GROWING IN WASTE.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	23/9591	22
LOCATION:	AREA S	
ACTIVITY:		
PIT LOCATED ADJACENT TO BUILDING S31.		
SPECIAL FEATURES:		

'CAULDRON' SHAPE.



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	23/9591	23
LOCATION:	AREA S	
ACTIVITY:		
EXCAVATION NORTH EAST OF BUILDING S29.		

SPECIAL FEATURES:
TO LOCATE BURST WATER MAIN.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	23/9591	24

LOCATION:	AREAS	
ACTIVITY:		
HERONRY DEMARCATION TAPE.		
SPECIAL FEATURES:		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	23/9591	25
LOCATION:	AREA M	
ACTIVITY:		
REMOVAL OF CORDITE.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	23/9591	26
LOCATION:	AREA M	
ACTIVITY:		
REMOVAL OF CORDITE.		
SPECIAL FEATURES:		




--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	23/9591	27
LOCATION:	AREA M	
ACTIVITY:		
REMOVAL OF CORDITE.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	23/9591	28
LOCATION:	AREA M	
ACTIVITY:		
CORDITE REMOVAL.		
SPECIAL FEATURES:		

CORDITE VISIBLE IN STICK FORM.



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	23/9591	29
LOCATION:	AREA M	
ACTIVITY:		
CORDITE REMOVAL.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	23/9591	30


LOCATION:	AREAS	
ACTIVITY:		
TIP SITE 11036.		
SPECIAL FEATURES:		
ASBESTOS REMOVAL.		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	23/9591	31
LOCATION:	AREA S	
ACTIVITY:		
TIP SITE 11036.		
SPECIAL FEATURES:		
CHEMICAL GLASSWARE.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	23/9591	32
LOCATION:	AREA S	
ACTIVITY:		
TIP SITE 11036.		
SPECIAL FEATURES:		
ASBESTOS REMOVAL.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	23/9591	33
LOCATION:	AREA S	
ACTIVITY:		
TIP SITE 11036.		
SPECIAL FEATURES:		
ASBESTOS REMOVAL.		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	23/9591	34
LOCATION:	AREA S	
ACTIVITY:		
TIP SITE 11036.		
SPECIAL FEATURES:		

ASBESTOS REMOVAL.

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	23/9591	35
LOCATION:	AREA M	
ACTIVITY:		
HOLDING AREA FOR REMOVED CONCRETE FOUNDATIONS.		


SPECIAL FEATURES:
BUILDING L168 IN BACKGROUND.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	23/9591	36

LOCATION:	AREA M	
ACTIVITY:		
HOLDING AREA FOR REMOVED CONCRETE FOUNDATIONS.		
SPECIAL FEATURES:		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	23/9591	37
LOCATION:	AREA M	
ACTIVITY:		
HOLDING AREA FOR REMOVED CONCRETE FOUNDATIONS.		
SPECIAL FEATURES:		




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	24/9990	1
LOCATION:	AREA H	
ACTIVITY:		
INTERNAL VIEW OF BUILDING H10.		
SPECIAL FEATURES:		
REFURBISHMENT OF LABORATORY BENCHING FOR SITE EXPLOSIVES TESTING.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	24/9990	2
LOCATION:	AREA H	
ACTIVITY:		
INTERNAL VIEW OF BUILDING H10.		
SPECIAL FEATURES:		
REFURBISHMENT OF LABORATORY BENCHING FOR USE AS SITE TESTING LABORATORY.		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	24/9990	3
LOCATION:	AREA H	
ACTIVITY:		
INTERNAL VIEW OF BUILDING H10.		
SPECIAL FEATURES:		
REFURBISHMENT OF FUME CUPBOARD IN LABORATORY No. 1 FOR USE AS SITE TESTING LABORATORY.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	24/9990	4
LOCATION:	AREA H	
ACTIVITY:		
INTERNAL VIEW OF BUILDING H10.		
SPECIAL FEATURES:		



SPECIAL FEATURES:
REFURBISHMENT OF LABORATORY No. 2 BENCHING FOR USE AS SITE TESTING LABORATORY.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	24/9990	6

LOCATION:	AREA H	
ACTIVITY:		
INTERNAL VIEW OF BUILDING H10.		
SPECIAL FEATURES:		
REFURBISHMENT OF BENCHING IN LABORATORY No. 2 FOR USE AS SITE TESTING LABORATORY.		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	24/9990	7
LOCATION:	AREA M	
ACTIVITY:		
CORDITE AREA EXCAVATION - LOOKING NORTH.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	24/9990	8
LOCATION:	AREA M	
ACTIVITY:		
CORDITE EXCAVATION LOOKING NORTH.		
SPECIAL FEATURES:		
BUILDING L160 TO RIGHT OF BACKGROUND.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	24/9990	9
LOCATION:	AREA M	
ACTIVITY:		
CORDITE AREA EXCAVATION - LOOKING NORTH.		
SPECIAL FEATURES:		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	24/9990	10
LOCATION:	AREA M	
ACTIVITY:		
CORDITE AREA EXCAVATION - LOOKING NORTH.		
SPECIAL FEATURES:		




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	24/9990	11
LOCATION:	AREA M	
ACTIVITY:		
CORDITE AREA EXCAVATION - LOOKING NORTH.		

SPECIAL FEATURES:
BUILDING L160 IN CENTRE BACKGROUND.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	24/9990	12

LOCATION:	AREA M	
ACTIVITY:		
CORDITE EXCAVATION - LOOKING SOUTH WEST.		
SPECIAL FEATURES:		
RETRIEVING ASBESTOS - BRIDGE No. 30 IN BACKGROUND.		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	24/9990	13
LOCATION:	AREA M	
ACTIVITY:		
CORDITE AREA EXCAVATION.		
SPECIAL FEATURES:		
RETRIEVING ASBESTOS.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	24/9990	14
LOCATION:	AREA M	
ACTIVITY:		
CORDITE AREA EXCAVATION LOOKING WEST.		
SPECIAL FEATURES:		
BRIDGE No. 4 AT RIGHT BACKGROUND.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	24/9990	15
LOCATION:	AREA M	
ACTIVITY:		
CORDITE AREA EXCAVATION.		
SPECIAL FEATURES:		
ASBESTOS WASTE.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	24/9990	16
LOCATION:	AREA M	
ACTIVITY:		
CORDITE AREA EXCAVATION.		
SPECIAL FEATURES:		



SCREENING PLANT.

Empty rectangular box for additional information or notes.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	24/9990	17
LOCATION:	AREA M	
ACTIVITY:		
CORDITE AREA EXCAVATION.		

SPECIAL FEATURES:
SCREENING PLANT.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	24/9990	18

LOCATION:	AREA M	
ACTIVITY:		
CORDITE AREA EXCAVATION.		
SPECIAL FEATURES:		
SCREENED WASTE.		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	24/9990	19
LOCATION:	AREA M	
ACTIVITY:		
CORDITE AREA EXCAVATION.		
SPECIAL FEATURES:		
SCREENING PLANT.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	24/9990	20
LOCATION:	AREA S	
ACTIVITY:		
TAKING OUT STEAM MAIN FOUNDATIONS NORTH OF BUILDING L136.		
SPECIAL FEATURES:		




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	24/9990	21
LOCATION:	AREA S	
ACTIVITY:		
WEST ELEVATION OF BUILDING L135.		
SPECIAL FEATURES:		
RCHME PHOTOGRAPHER - PHOTOGRAPHING BUILDING L139.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	24/9990	22
LOCATION:	AREA M	
ACTIVITY:		
EAST ELEVATION OF BUILDING L148.		
SPECIAL FEATURES:		

STEAM MAIN FOUNDATION IN FOREGROUND.



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	24/9990	23
LOCATION:	AREA B	
ACTIVITY:		
EXPOSED FUZE ADJACENT TO BUILDING 96.		



SPECIAL FEATURES:
FUZE SUSPECTED TO BE LIVE.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	24/9990	24

LOCATION:	AREA B	
ACTIVITY:		
EXPOSED FUZE ADJACENT TO BUILDING 96.		
SPECIAL FEATURES:		
FUZE SUSPECTED TO BE LIVE.		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	24/9990	25
LOCATION:	AREA B	
ACTIVITY:		
INSPECTION OF GAS CYLINDERS BY ROYAL ORDNANCE ADJACENT TO BUILDING L175.		
SPECIAL FEATURES:		
CYLINDERS RETRIEVED FROM FILLED CANALS.		




**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	25/0129	1
LOCATION:	AREA S	
ACTIVITY:		
POWDER BARGE.		
SPECIAL FEATURES:		
RCHME REF.: 104.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	25/0129	2
LOCATION:	AREA S	
ACTIVITY:		
VIEW THROUGH EAST SECURITY FENCE.		
SPECIAL FEATURES:		




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	25/0129	3
LOCATION:	AREA S	
ACTIVITY:		
POWDER BARGE WEST OF BUILDING 76 - LOOKING NORTH EAST.		
SPECIAL FEATURES:		
RCHME REF.: 101.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	25/0129	4
LOCATION:	AREA S	
ACTIVITY:		
POWDER BARGE WEST OF BUILDING 76 - LOOKING EAST.		
SPECIAL FEATURES:		



RCHME REF.: 101.



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	25/0129	5
LOCATION:	AREA S	
ACTIVITY:		
POWDER BARGE WEST OF BUILDING 76 - LOOKING SOUTH.		

SPECIAL FEATURES:
RCHME REF.: 101.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	25/0129	6

LOCATION:	AREAS	
ACTIVITY:		
POWDER BARGE WEST OF BUILDING 76 - LOOKING NORTH.		
SPECIAL FEATURES:		
RCHME REF.: 101.		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	25/0129	7
LOCATION:	AREA S	
ACTIVITY:		
POWDER BARGE WEST OF BUILDING 76 - LOOKING NORTH EAST.		
SPECIAL FEATURES:		
RCHME REF.: 101.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	25/0129	8
LOCATION:	AREA S	
ACTIVITY:		
LOCK GATES.		
SPECIAL FEATURES:		
RCHME REF.: 225.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	25/0129	9
LOCATION:	AREA S	
ACTIVITY:		
VIEW LOOKING WEST ON BUILDING L109.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	25/0129	10
LOCATION:	AREA S	
ACTIVITY:		
POWDER BARGE.		
SPECIAL FEATURES:		

RCHME REF.: 157.



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	25/0129	11
LOCATION:	AREA S	
ACTIVITY:		
POWDER BARGES.		



SPECIAL FEATURES:
RCHME REFS.: 157 - 160.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	25/0129	12


LOCATION:	AREAS	
ACTIVITY:		
POWDER BARGES.		
SPECIAL FEATURES:		
RCHME REFS.: 157 - 160.		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	25/0129	13
LOCATION:	AREA S	
ACTIVITY:		
RCHME REFS.: 157 - 160.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	25/0129	14
LOCATION:	AREA S	
ACTIVITY:		
SITE OPERATIVES.		
SPECIAL FEATURES:		
TEMPORARY SAFETY FENCING.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	25/0129	15
LOCATION:	AREA M	
ACTIVITY:		
INTERNAL VIEW OF BUILDING L148.		
SPECIAL FEATURES:		
STRIPPING OUT.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	25/0129	16
LOCATION:	AREA M	
ACTIVITY:		
INTERNAL VIEW OF BUILDING L148.		
SPECIAL FEATURES:		

STRIPPING OUT.



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	25/0129	17
LOCATION:	AREA M	
ACTIVITY:		
INTERNAL VIEW OF BUILDING L148.		

SPECIAL FEATURES:
STRIPPING OUT.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	25/0129	18



LOCATION:	AREA M	
ACTIVITY:		
INTERNAL VIEW OF BUILDING L148.		
SPECIAL FEATURES:		
STRIPPING OUT.		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	25/0129	19
LOCATION:	AREA M	
ACTIVITY:		
INTERNAL VIEW OF BUILDING L148.		
SPECIAL FEATURES:		
STRIPPING OUT.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	25/0129	20
LOCATION:	AREA M	
ACTIVITY:		
SOUTH EAST ELEVATION OF BUILDING L148.		
SPECIAL FEATURES:		




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	25/0129	21
LOCATION:	AREA M	
ACTIVITY:		
INTERNAL VIEW OF BUILDING L148.		
SPECIAL FEATURES:		
STRIP OUT IN PROGRESS.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	25/0129	22
LOCATION:	AREA M	
ACTIVITY:		
INTERNAL VIEW OF BUILDING L148.		
SPECIAL FEATURES:		

STRIP OUT IN PROGRESS.



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	25/0129	23
LOCATION:	AREA M	
ACTIVITY:		
INTERNAL VIEW OF BUILDING L148.		

SPECIAL FEATURES:
STRIP OUT IN PROGRESS.


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	25/0129	24

LOCATION:	AREA M	
ACTIVITY:		
INTERNAL VIEW OF BUILDING L148.		
SPECIAL FEATURES:		
STRIP OUT IN PROGRESS.		




**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	25/0129	25
LOCATION:	AREA M	
ACTIVITY:		
INTERNAL VIEW OF BUILDING L148.		
SPECIAL FEATURES:		
STRIP OUT IN PROGRESS.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	25/0129	26
LOCATION:	AREA M	
ACTIVITY:		
INTERNAL VIEW OF BUILDING L148.		
SPECIAL FEATURES:		
STRIP OUT IN PROGRESS.		




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	25/0129	27
LOCATION:	AREA M	
ACTIVITY:		
INTERNAL VIEW OF BUILDING L148.		
SPECIAL FEATURES:		
STRIP OUT IN PROGRESS.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	25/0129	28
LOCATION:	AREA M	
ACTIVITY:		
INTERNAL VIEW OF BUILDING L148.		
SPECIAL FEATURES:		

STRIP OUT IN PROGRESS.



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	25/0129	29
LOCATION:	AREA M	
ACTIVITY:		
INTERNAL VIEW OF CORRIDOR IN BUILDING L148.		


SPECIAL FEATURES:
STRIP OUT IN PROGRESS.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	25/0129	30


LOCATION:	AREA P	
ACTIVITY:		
WEST ELEVATION OF BUILDING A269.		
SPECIAL FEATURES:		
ROOF REFURBISHMENT - SCAFFOLD ERECTION.		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	25/0129	31
LOCATION:	AREA P	
ACTIVITY:		
NORTH ELEVATION OF BUILDING A269.		
SPECIAL FEATURES:		
SCAFFOLDING ERECTION FOR ROOF REFURBISHMENT.		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	25/0129	32
LOCATION:	AREA M	
ACTIVITY:		
INTERNAL VIEW OF BUILDING L148.		
SPECIAL FEATURES:		
ASPHALT FLOOR SURFACE REMOVAL.		




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	25/0129	33
LOCATION:	AREA M	
ACTIVITY:		
INTERNAL VIEW OF BUILDING L148.		
SPECIAL FEATURES:		
STRIP OUT IN PROGRESS.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	25/0129	34
LOCATION:	AREA M	
ACTIVITY:		
INTERNAL VIEW OF BUILDING L148.		
SPECIAL FEATURES:		

VACUUMING INTERNAL SURFACES.



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	25/0129	35
LOCATION:	AREA M	
ACTIVITY:		
INTERNAL VIEW OF BUILDING L148.		

SPECIAL FEATURES:
ASPHALT FLOOR SURFACE REMOVAL.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	25/0129	36


LOCATION:	AREA P	
ACTIVITY:		
WEST ELEVATION OF BUILDING A269.		
SPECIAL FEATURES:		
ROOF REFURBISHMENT - SCAFFOLD ERECTION.		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	25/0129	37
LOCATION:	AREA P	
ACTIVITY:		
WEST ELEVATION OF BUILDING A269.		
SPECIAL FEATURES:		
ROOF REFURBISHMENT - SCAFFOLD ERECTION.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	25/0129	0
LOCATION:	AREA S	
ACTIVITY:		
POWDER BARGE.		
SPECIAL FEATURES:		
RCHME REF.: 104.		






FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	26/0130	1
LOCATION:	AREA B	
ACTIVITY:		
EMBLEM IN BUILDING L102.		
SPECIAL FEATURES:		
ROYAL GUNPOWDER FACTORY DEPICTED.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	26/0130	2
LOCATION:	AREA B	
ACTIVITY:		
EMBLEM IN BUILDING L102.		
SPECIAL FEATURES:		
ROYAL GUNPOWDER FACTORY DEPICTED.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	26/0130	3
LOCATION:	AREA B	
ACTIVITY:		
EMBLEM ON BRIDGE No. 16 - EAST OF BUILDING 96.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	26/0130	4
LOCATION:	AREA B	
ACTIVITY:		
EMBLEM ON SIDE OF AQUEDUCT - BRIDGE No. 14 (NORTH EAST OF BUILDING 96).		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	26/0130	5
LOCATION:	AREAS	
ACTIVITY:		
EMBLEM ON BRIDGE No. 16.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	26/0130	6

LOCATION:	AREAS	
ACTIVITY:		
CLOSE UP VIEW OF EMBLEM ON BRIDGE No. 16.		
SPECIAL FEATURES:		




**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	26/0130	7
LOCATION:	AREA S	
ACTIVITY:		
EMBLEM ON BRIDGE No. 16.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	26/0130	8
LOCATION:	AREA B	
ACTIVITY:		
EMBLEM ON SIDE OF AQUEDUCT - BRIDGE No. 14 (NORTH EAST OF BUILDING 96).		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	26/0130	9
LOCATION:	AREA B	
ACTIVITY:		
BRIDGE No. 16 - SOUTH ELEVATION.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	26/0130	10
LOCATION:	AREA B	
ACTIVITY:		
BRIDGE NO. 19 - CARRYING ROAD TO BUILDING 96.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	26/0130	11
LOCATION:	AREA B	
ACTIVITY:		
BRIDGE No. 16 - SOUTH ELEVATION.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	26/0130	12

LOCATION:	AREA B	
ACTIVITY:		
BRIDGE No. 16 - SOUTH ELEVATION.		
SPECIAL FEATURES:		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
JAN '93	26/0130	12 R
LOCATION:	AREA B	
ACTIVITY:		
SOUTH EAST VIEW OF BURNING GROUND.		
SPECIAL FEATURES:		






**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	27/0536	1
LOCATION:	AREA	
ACTIVITY:		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	27/0536	2
LOCATION:	AREA	
ACTIVITY:		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	27/0536	3
LOCATION:	AREA M	
ACTIVITY:		
CORDITE EXPOSED IN CORDITE AREA.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	27/0536	4
LOCATION:	AREA M	
ACTIVITY:		
CORDITE EXPOSED IN CORDITE AREA.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	27/0536	5
LOCATION:	AREA M	
ACTIVITY:		
CORDITE EXPOSED IN CORDITE AREA.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	27/0536	6

LOCATION:	AREA M	
ACTIVITY:		
CORDITE EXPOSED IN CORDITE AREA.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	27/0536	9
LOCATION:	AREA B	
ACTIVITY:		
INVESTIGATING CONTAMINATED METAL FROM TIP 11038 - BURNING GROUND NORTH.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	27/0536	10
LOCATION:	AREA B	
ACTIVITY:		
LOOKING THROUGH TIP No. 11038 NORTH BURNING GROUND.		
SPECIAL FEATURES:		


--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	27/0536	11
LOCATION:	AREA M	
ACTIVITY:		
CONCRETE BASE OF BUILDING L169.		
SPECIAL FEATURES:		
SET OUT FOR SAMPLING OF WASTE.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	27/0536	12
LOCATION:	AREA M	
ACTIVITY:		
CONCRETE BASE OF BUILDING L169.		
SPECIAL FEATURES:		

SET OUT FOR SAMPLING OF WASTE.



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	27/0536	13
LOCATION:	AREA M	
ACTIVITY:		
CONCRETE BASE OF BUILDING L169.		

SPECIAL FEATURES:
SET OUT FOR SAMPLING OF WASTE.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	27/0536	14

LOCATION:	AREA L	
ACTIVITY:		
VIEW LOOKING NORTH FROM BUILDING L169 ACROSS 'QUEENS MEAD'.		
SPECIAL FEATURES:		
BUILDING L157 IN RIGHT OF PICTURE.		


**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	27/0536	15
LOCATION:	AREA M	
ACTIVITY:		
WASTE BEING DELIVERED TO SAMPLING SLAB AT L169.		
SPECIAL FEATURES:		



--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	27/0536	16
LOCATION:	AREA M	
ACTIVITY:		
EXCAVATION IN CORDITE AREA.		
SPECIAL FEATURES:		
BUILDING L160 IN TOP RIGHT.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	27/0536	17
LOCATION:	AREA M	
ACTIVITY:		
EXCAVATION IN CORDITE AREA.		
SPECIAL FEATURES:		
BUILDING L160 IN TOP LEFT.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	27/0536	18
LOCATION:	AREA M	
ACTIVITY:		
EXCAVATION IN CORDITE AREA.		
SPECIAL FEATURES:		

BUILDING L160 IN TOP LEFT.



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	27/0536	19
LOCATION:	AREA M	
ACTIVITY:		
EXCAVATION IN CORDITE AREA.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	27/0536	20

LOCATION:	AREA M	
ACTIVITY:		
EXCAVATION IN CORDITE AREA.		
SPECIAL FEATURES:		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDICATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	27/0536	21
LOCATION:	AREA M	
ACTIVITY:		
CORDITE FOUND.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	27/0536	22
LOCATION:	AREA M	
ACTIVITY:		
CORDITE FOUND.		
SPECIAL FEATURES:		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	27/0536	23
LOCATION:	AREA M	
ACTIVITY:		
SOUTH ELEVATION OF BUILDING L148.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	27/0536	24
LOCATION:	AREA M	
ACTIVITY:		
STOCKPILE OF ASBESTOS CONTAMINATED SOIL.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	27/0536	25
LOCATION:	AREA M	
ACTIVITY:		
ASBESTOS CONTAMINATED SOIL STRIPPED ALONG WEST ELEVATION OF		

BUILDING L157.
SPECIAL FEATURES:
BUILDING A210 IN BACKGROUND.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	27/0536	26

LOCATION:	AREA L	
ACTIVITY:		
ASBESTOS CONTAMINATED SOIL STRIPPED ALONG WEST ELEVATION OF BUILDING L157.		
SPECIAL FEATURES:		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	27/0536	27
LOCATION:	AREA M	
ACTIVITY:		
WASTE SAMPLING AT L169 SAMPLING AREA.		
SPECIAL FEATURES:		
PERSONAL PROTECTION EQUIPMENT.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	27/0536	28
LOCATION:	AREA P	
ACTIVITY:		
JUNCTION OF POWDERMILL LANE AND FLAGSTAFF ROAD LOOKING SOUTH.		
SPECIAL FEATURES:		
BUILDING A269 ROOF REFURBISHMENT IN PROGRESS (BACKGROUND).		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	27/0536	29
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 UNDERCROFT.		
SPECIAL FEATURES:		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	27/0536	30
LOCATION:	AREA S	
ACTIVITY:		
FALLEN TREE WEST SSSI.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	27/0536	31
LOCATION:	AREA S	
ACTIVITY:		
FALLEN TREE WEST SSSI.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	27/0536	32

LOCATION:	AREAS	
ACTIVITY:		
FALLEN TREE WEST SSSI.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	27/0536	33
LOCATION:	AREA S	
ACTIVITY:		
STEAM PIPE ROUTE NORTH OF BUILDING 76.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	27/0536	34
LOCATION:	AREA S	
ACTIVITY:		
STEAM PIPE ROUTE NORTH OF BUILDING 76.		
SPECIAL FEATURES:		
ASBESTOS CONTAMINATION.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	27/0536	35
LOCATION:	AREA S	
ACTIVITY:		
STEAM PIPE ROUTE NORTH OF BUILDING 76.		
SPECIAL FEATURES:		
ASBESTOS CONTAMINATION.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	27/0536	36
LOCATION:	AREA S	
ACTIVITY:		
GROUND UNDER STEAM PIPE ROUTE NORTH OF BUILDING 76.		
SPECIAL FEATURES:		



ASBESTOS CONTAMINATION.

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	27/0536	36 A
LOCATION:	AREA S	
ACTIVITY:		
STEAM PIPE ROUTE NORTH OF BUILDING 76.		

--

SPECIAL FEATURES:

ASBESTOS CONTAMINATION.

--

FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD

DATE:

NEGATIVE REFERENCE:

FRAME REFERENCE:

FEB '93

28/1012

1

LOCATION:

AREA S

ACTIVITY:


WASTE TIP SOUTH OF BUILDING S32.

SPECIAL FEATURES:

ASBESTOS.

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	28/1012	2
LOCATION:	AREA S	
ACTIVITY:		
WASTE TIP SOUTH OF BUILDING S32.		
SPECIAL FEATURES:		
ASBESTOS.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	28/1012	3
LOCATION:	AREA S	
ACTIVITY:		
WASTE TIP SOUTH OF BUILDING S32.		
SPECIAL FEATURES:		
ASBESTOS.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	28/1012	4
LOCATION:	AREA M	
ACTIVITY:		
MILLSTONE FOUND WHILST SCRAPING.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	28/1012	5
LOCATION:	AREA M	
ACTIVITY:		
INTERNAL VIEW OF BUILDING L157 - 1ST STAGE DECONTAMINATION.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	28/1012	6



LOCATION:	AREA M	
ACTIVITY:		
INTERNAL VIEW OF BUILDING L157 - 1ST STAGE DECONTAMINATION.		
SPECIAL FEATURES:		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	28/1012	7
LOCATION:	AREA M	
ACTIVITY:		
INTERNAL VIEW OF BUILDING L157 - 1ST STAGE DECONTAMINATION.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	28/1012	8
LOCATION:	AREA M	
ACTIVITY:		
INTERNAL VIEW OF BUILDING L157 - 1ST STAGE DECONTAMINATION.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	28/1012	25
LOCATION:	AREA M	
ACTIVITY:		
STOCKPILING SCREENED CORDITE ARISINGS.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	28/1012	26
LOCATION:	AREA M	
ACTIVITY:		
STOCKPILING OF ARISINGS FROM CORDITE CONTAMINATED AREA.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	28/1012	27
LOCATION:	AREA M	
ACTIVITY:		
SCREENED ARISING FROM CORDITE CONTAMINATED AREA.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	28/1012	28

LOCATION:	AREA M	
ACTIVITY:		
CLOSE UP OF GRADED ARISINGS FROM CORDITE CONTAMINATED AREA.		
SPECIAL FEATURES:		



**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	28/1012	29
LOCATION:	AREA M	
ACTIVITY:		
GRADED ARISINGS FROM CORDITE CONTAMINATED AREA.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	28/1012	30
LOCATION:	AREA M	
ACTIVITY:		
CLOSE UP OF GRADED ARISINGS FROM CORDITE CONTAMINATED AREA.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	28/1012	31
LOCATION:	AREA M	
ACTIVITY:		
COARSE SCREENED ARISINGS FROM CORDITE CONTAMINATED AREA.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	28/1012	32
LOCATION:	AREA M	
ACTIVITY:		
CLOSE UP OF GRADED ARISINGS FROM CORDITE CONTAMINATED AREA.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	28/1012	33
LOCATION:	AREA M	
ACTIVITY:		
MILLSTONE EXCAVATED FOR CORDITE AREA.		

SPECIAL FEATURES:


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	28/1012	34

LOCATION:	AREA M	
ACTIVITY:		
MILLSTONE EXCAVATED FROM CORDITE AREA.		
SPECIAL FEATURES:		


**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	28/1012	35
LOCATION:	AREA M	
ACTIVITY:		
MILLSTONES EXCAVATED FROM CORDITE AREA.		
SPECIAL FEATURES:		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	28/1012	9
LOCATION:	AREA M	
ACTIVITY:		
INTERNAL VIEW OF BUILDING L157.		
SPECIAL FEATURES:		
PRIOR TO DECONTAMINATION.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	28/1012	10
LOCATION:	AREA M	
ACTIVITY:		
INTERNAL VIEW OF BUILDING L157.		
SPECIAL FEATURES:		
PRIOR TO DECONTAMINATION.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	28/1012	11
LOCATION:	AREA M	
ACTIVITY:		
INTERNAL VIEW OF BUILDING L157.		
SPECIAL FEATURES:		

BAGGED ASBESTOS.



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	28/1012	12
LOCATION:	AREA M	
ACTIVITY:		
INTERNAL VIEW OF BUILDING L157.		

SPECIAL FEATURES:
CONTAMINATED STEELWORK STACKED.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	28/1012	13

LOCATION:	AREA M	
ACTIVITY:		
INTERNAL VIEW OF BUILDING L157.		
SPECIAL FEATURES:		
BAGGED CONTAMINATED MATERIAL.		


**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	28/1012	14
LOCATION:	AREA M	
ACTIVITY:		
INTERNAL VIEW OF BUILDING L157.		
SPECIAL FEATURES:		
BAGGED CONTAMINATED MATERIAL.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	28/1012	15
LOCATION:	AREA M	
ACTIVITY:		
INTERNAL VIEW OF BUILDING L157.		
SPECIAL FEATURES:		
BAGGED CONTAMINATED MATERIAL.		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	28/1012	16
LOCATION:	AREA M	
ACTIVITY:		
INTERNAL VIEW OF BUILDING L157.		
SPECIAL FEATURES:		
PRIOR TO DECONTAMINATION.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	28/1012	17
LOCATION:	AREA M	
ACTIVITY:		
INTERNAL VIEW OF BUILDING L157.		
SPECIAL FEATURES:		

BAGGED CONTAMINATED MATERIAL AND TIMBER.



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	28/1012	18
LOCATION:	AREA M	
ACTIVITY:		
INTERNAL VIEW OF BUILDING L157.		

SPECIAL FEATURES:
DECONTAMINATION OPERATIVE.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	28/1012	19

LOCATION:	AREA M	
ACTIVITY:		
INTERNAL VIEW OF BUILDING L157.		
SPECIAL FEATURES:		
DECONTAMINATION OPERATIVES.		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	28/1012	20
LOCATION:	AREA M	
ACTIVITY:		
INTERNAL VIEW OF BUILDING L157.		
SPECIAL FEATURES:		
DECONTAMINATION OPERATIVE.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	28/1012	21
LOCATION:	AREA M	
ACTIVITY:		
INTERNAL VIEW OF BUILDING L157.		
SPECIAL FEATURES:		
ASBESTOS REMOVAL CONTRACTOR'S NEGATIVE AIR TENT.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	28/1012	22
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - EXTERNAL SAVE ALL DRAIN.		
SPECIAL FEATURES:		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	28/1012	23
LOCATION:	AREA M	
ACTIVITY:		
CORDITE SCREENING PLANT.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	28/1012	24
LOCATION:	AREA M	
ACTIVITY:		
GRADED ARISINGS FROM CORDITE CONTAMINATED AREAS.		


SPECIAL FEATURES:

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	29/1013	1
LOCATION:	AREA M	
ACTIVITY:		
REMOVAL OF CORDITE CONTAMINATED GROUND.		
SPECIAL FEATURES:		
ASBESTOS CONTAMINATION ALSO PRESENT.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	29/1013	2
LOCATION:	AREA M	
ACTIVITY:		
REMOVAL OF CORDITE CONTAMINATED GROUND.		
SPECIAL FEATURES:		
ASBESTOS CONTAMINATION ALSO PRESENT.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	29/1013	3
LOCATION:	AREA M	
ACTIVITY:		
REMOVAL OF CORDITE CONTAMINATED GROUND.		
SPECIAL FEATURES:		
ASBESTOS CONTAMINATION ALSO PRESENT.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	29/1013	4
LOCATION:	AREA S	
ACTIVITY:		
ONE OF THE OLDEST EXAMPLES OF A HORSE CHESTNUT TREE.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	29/1013	5
LOCATION:	AREA S	
ACTIVITY:		
ONE OF THE OLDEST EXAMPLES OF A HORSE CHESTNUT TREE.		




SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	29/1013	6

LOCATION:	AREAS	
ACTIVITY:		
ROYAL ORDNANCE SUPERVISOR CHECKING TREE TAGS PRIOR TO FELLING.		
SPECIAL FEATURES:		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	29/1013	7
LOCATION:	AREA H	
ACTIVITY:		
TREES GROWING OUT OF BUILDING H72.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	29/1013	8
LOCATION:	AREA N	
ACTIVITY:		
VIEW OF SUSPECT PIT AT NEW HILL - LOOKING SOUTH. (EAST FENCE LINE SHOWN AT LEFT OF PICTURE).		
SPECIAL FEATURES:		




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	29/1013	9
LOCATION:	AREA N	
ACTIVITY:		
VIEW LOOKING NORTH AT NEW HILL ALONG LINE OF SUSPECT PITS. (BUILDING S9 ON RIGHT OF PICTURE).		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	29/1013	10
LOCATION:	AREA N	
ACTIVITY:		
SUSPECT PIT AT NEW HILL NEAR TO EAST ACCESS GATE.		
SPECIAL FEATURES:		

OVERGROWN - LOCATED BY ACCIDENT.



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	29/1013	11
LOCATION:	AREA N	
ACTIVITY:		
SUSPECT PIT AT NEW HILL NEAR TO EAST ACCESS GATE.		

SPECIAL FEATURES:
OVERGROWN - LOCATED BY ACCIDENT.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	29/1013	12




LOCATION:	AREA N	
ACTIVITY:		
SUSPECT PIT AT NEW HILL NEAR TO EAST ACCESS GATE (IN CENTRE FOREGROUND OF PICTURE).		
SPECIAL FEATURES:		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	29/1013	13
LOCATION:	AREA N	
ACTIVITY:		
SUSPECT PIT AT NEW HILL NEAR TO EAST ACCESS GATE.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	29/1013	14
LOCATION:	AREA S	
ACTIVITY:		
BAGGED ASBESTOS AWAITING COLLECTION FROM WASTE TIPS.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	29/1013	15
LOCATION:	AREA S	
ACTIVITY:		
VIEW OF WASTE TIP, DENSE ASBESTOS CONTAMINANTS REMOVED BY SPECIALIST CONTRACTORS.		
SPECIAL FEATURES:		
BAGGED ASBESTOS AWAITING COLLECTION.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	29/1013	16
LOCATION:	AREA M	
ACTIVITY:		
VIEW OF CANAL 'OPENED UP' IN THE CORDITE CONTAMINATED AREA. (BUILDING L159 IN BACKGROUND)		
SPECIAL FEATURES:		

BAGGED ASBESTOS.




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	29/1013	17
LOCATION:	AREA M	
ACTIVITY:		
VIEW OF CANAL 'OPENED UP' IN CORDITE CONTAMINATED AREA.		

(BRIDGE No. 4 TO LEFT OF PICTURE)

SPECIAL FEATURES:

BAGGING ASBESTOS FOUND DUMPED IN FILLED CANAL.



**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	29/1013	18

LOCATION:	AREA M	
ACTIVITY:		
VIEW OF CANAL 'OPENED UP' IN CORDITE CONTAMINATED AREA.		
SPECIAL FEATURES:		
ASBESTOS LOCATED IN EXCAVATION.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	29/1013	19
LOCATION:	AREA M	
ACTIVITY:		
VIEW OF CANAL 'OPENED UP' IN CORDITE CONTAMINATED AREA.		
SPECIAL FEATURES:		
ASBESTOS LOCATED IN EXCAVATION.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	29/1013	20
LOCATION:	AREA M	
ACTIVITY:		
ASBESTOS BEING REMOVED FROM FILLED CANAL IN CORDITE CONTAMINATED AREA.		
SPECIAL FEATURES:		
ASBESTOS CONTAMINANTS.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	29/1013	21
LOCATION:	AREA M	
ACTIVITY:		
LICENSED ASBESTOS CONTRACTOR BAGGING ASBESTOS, IN CORDITE CONTAMINATED AREA (BUILDING A214 TOWER IN BACKGROUND).		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	29/1013	22
LOCATION:	AREA H	
ACTIVITY:		
SERVICE TRENCH BETWEEN BUILDING A203 AND BRIDGE No. 17.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	29/1013	23
LOCATION:	AREA H	
ACTIVITY:		
SERVICE TRENCH BETWEEN BUILDING A203 AND BRIDGE No. 17.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	29/1013	24

LOCATION:	AREA H	
ACTIVITY:		
SERVICE TRENCH BETWEEN BUILDING A203 AND BRIDGE No. 17.		
SPECIAL FEATURES:		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	29/1013	25
LOCATION:	AREA H	
ACTIVITY:		
WEST SIDE OF BUILDING A202 LOOKING NORTH (HOPPIT POOL TO THE LEFT).		
SPECIAL FEATURES:		
NOTE STEAM MAIN SUPPORTS.		



--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	29/1013	26
LOCATION:	AREA H	
ACTIVITY:		
SERVICE TRENCH TO BUILDING A200 FROM BUILDING A201/2.		
SPECIAL FEATURES:		
INSTALLATION OF PERMANENT WATER, TELECOM AND ELECTRIC SERVICES TO BUILDING A200.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	29/1013	27
LOCATION:	AREA H	
ACTIVITY:		
SERVICE TRENCH TO BUILDING A200.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	29/1013	28
LOCATION:	AREA H	
ACTIVITY:		
SERVICE TRENCH TO BUILDING A200.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	29/1013	29
LOCATION:	AREA H	
ACTIVITY:		
SERVICE TRENCH UNDER ROAD NORTH OF BUILDING A203.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	29/1013	30

LOCATION:	AREA H	
ACTIVITY:		
SERVICE TRENCH NORTH OF BUILDING A203 (ENTRY TO A203 PLANT ROOM).		
SPECIAL FEATURES:		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	29/1013	31
LOCATION:	AREA H	
ACTIVITY:		
TRENCH NORTH OF BUILDING A203.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	29/1013	32
LOCATION:	AREA H	
ACTIVITY:		
SERVICE TRENCH BETWEEN BUILDING A203 AND BRIDGE No. 17.		
SPECIAL FEATURES:		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	29/1013	33
LOCATION:	AREA H	
ACTIVITY:		
STOCKPILING CLEAN CONCRETE WASTE EAST OF H8.		
SPECIAL FEATURES:		
PREPARATION FOR DISPOSAL OFF SITE.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	29/1013	34
LOCATION:	AREA H	
ACTIVITY:		
VIEW OF FELLED TREES - LOOKING EAST FROM H8 (BUILDING L168 TO RIGHT OF PICTURE).		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	29/1013	35
LOCATION:	AREA H	
ACTIVITY:		
STOCKPILING OF CONCRETE WASTE EAST OF H8.		

SPECIAL FEATURES:
PREPARATION FOR DISPOSAL OFF SITE.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	29/1013	36

LOCATION:	AREA H	
ACTIVITY:		
STOCKPILING CONCRETE WASTE EAST OF H8.		
SPECIAL FEATURES:		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	29/1013	37
LOCATION:	AREA M	
ACTIVITY:		
WASTE MATERIAL LAID OUT ON L169 PRIOR TO SAMPLING.		
SPECIAL FEATURES:		
NOTE THE INHOMOGENEITY OF THE MATERIAL.		




FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	30/1014	1
LOCATION:	AREA H	
ACTIVITY:		
SOUTH EAST VIEW OF STOCKPILING 'SPECIAL WASTE' ON H19 AREA.		
SPECIAL FEATURES:		



--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	30/1014	2
LOCATION:	AREA H	
ACTIVITY:		
NORTH VIEW OF STOCKPILED 'SPECIAL WASTE' ON H19 AREA.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	30/1014	3
LOCATION:	AREA H	
ACTIVITY:		
NEW WATER VALVE INSTALLATION NORTH OF BUILDING A203.		
SPECIAL FEATURES:		
MAINTENANCE OF SITE INFRASTRUCTURE.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	30/1014	4
LOCATION:	AREA H	
ACTIVITY:		
NEW WATER VALVE INSTALLATION NORTH OF BUILDING A203.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	30/1014	5
LOCATION:	AREA M	
ACTIVITY:		
GENERAL VIEW OF SOIL REMOVAL IN CORDITE CONTAMINATED AREA.		

SPECIAL FEATURES:
CANAL EDGE TIMBERS AND PUDDLE CLAY STRIP VISIBLE.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	30/1014	6


LOCATION:	AREA M	
ACTIVITY:		
GENERAL VIEW OF SOIL REMOVAL IN CORDITE CONTAMINATED AREA. (BUILDING L160 CENTRE BACKGROUND).		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	30/1014	7
LOCATION:	AREA M	
ACTIVITY:		
REMOVAL OF CORDITE CONTAMINATED SOIL.		
SPECIAL FEATURES:		
CORDITE 'STICKS'.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	30/1014	8
LOCATION:	AREA M	
ACTIVITY:		
REMOVAL OF CORDITE CONTAMINATED SOIL.		
SPECIAL FEATURES:		
CORDITE 'STICKS'.		






FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	30/1014	9
LOCATION:	AREA M	
ACTIVITY:		
REMOVAL OF CORDITE CONTAMINATED GROUND (BUILDING L160 TO RIGHT OF PICTURE).		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	30/1014	10
LOCATION:	AREA M	
ACTIVITY:		
REMOVAL OF CORDITE CONTAMINATED GROUND.		
SPECIAL FEATURES:		

CORDITE 'STICKS':



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	30/1014	11
LOCATION:	AREA M	
ACTIVITY:		
REMOVAL OF CORDITE CONTAMINATED GROUND.		

SPECIAL FEATURES:
SOIL SCREENING PLANT IN BACKGROUND.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	30/1014	12

LOCATION:	AREA P	
ACTIVITY:		
TRACKING SERVICES WITH 'CAT' SOUTH OF BUILDING A231.		
SPECIAL FEATURES:		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	30/1014	13
LOCATION:	AREA M	
ACTIVITY:		
INTERNAL VIEW OF BUILDING L153.		
SPECIAL FEATURES:		
CEILING REMOVED - 1ST STAGE DECONTAMINATION.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	30/1014	15
LOCATION:	AREA M	
ACTIVITY:		
INTERNAL VIEW OF BUILDING L153 - 1ST STAGE DECONTAMINATION.		
SPECIAL FEATURES:		
CORE HOLES IN WALL.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	30/1014	16
LOCATION:	AREA M	
ACTIVITY:		
INTERNAL VIEW OF BUILDING L153 - 1ST STAGE DECONTAMINATION.		
SPECIAL FEATURES:		
CORE HOLES IN WALL.		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	30/1014	17
LOCATION:	AREA M	
ACTIVITY:		
INTERNAL VIEW OF BUILDING L153 - STRIPPING OUT.		
SPECIAL FEATURES:		

VACUUMING TIMBER PARTITIONS.



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	30/1014	18
LOCATION:	AREA M	
ACTIVITY:		
INTERNAL VIEW OF BUILDING L153 - STRIPPING OUT.		

SPECIAL FEATURES:
VACUUMING TIMBER PARTITIONS.


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	30/1014	19

LOCATION:	AREA M	
ACTIVITY:		
BUILDING L153 - CARTING AWAY WASTE.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	30/1014	20
LOCATION:	AREA M	
ACTIVITY:		
INTERNAL VIEW OF BUILDING L153 - STRIPPING OUT.		
SPECIAL FEATURES:		
CONTAMINATED TIMBER STORE.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	30/1014	21
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L153 - STRIPPING OUT.		
SPECIAL FEATURES:		
CONTAMINATED TIMBER STORE.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	30/1014	22
LOCATION:	AREA M	
ACTIVITY:		
INTERNAL VIEW OF BUILDING L153 - STRIPPING OUT.		
SPECIAL FEATURES:		
CONTAMINATED TIMBER STORE.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	30/1014	23
LOCATION:	AREA H	
ACTIVITY:		
BLANKED OFF HYDRANT NEAR HIGHBRIDGE STREET (WEST).		
SPECIAL FEATURES:		



RATIONALISATION OF SITE INFRASTRUCTURE.



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	30/1014	24
LOCATION:	AREA H	
ACTIVITY:		
BLANKED OFF HYDRANT NEAR HIGHBRIDGE STREET (NORTH EAST).		

SPECIAL FEATURES:
RATIONALISATION OF SITE INFRASTRUCTURE.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	30/1014	25

LOCATION:	AREA H	
ACTIVITY:		
BLANKING OFF A HYDRANT NEAR HIGHBRIDGE STREET (NORTH EAST).		
SPECIAL FEATURES:		
RATIONALISATION OF SITE INFRASTRUCTURE.		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	30/1014	26
LOCATION:	AREA M	
ACTIVITY:		
EXCAVATION OF CORDITE CONTAMINATED GROUND - SCREENING PLANT BEYOND.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	30/1014	27
LOCATION:	AREA M	
ACTIVITY:		
OPENING UP OF FILLED CANAL BRANCH IN CORDITE CONTAMINATED AREA.		
SPECIAL FEATURES:		
BUILDING L160 TO THE LEFT AND SOIL SCREENING PLANT CENTRE RIGHT.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	30/1014	28
LOCATION:	AREA M	
ACTIVITY:		
REMOVAL OF CORDITE CONTAMINATED GROUND.		
SPECIAL FEATURES:		
CORDITE INTERTWINED WITH TREE ROOT SYSTEM.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	30/1014	29
LOCATION:	AREA M	
ACTIVITY:		
REMOVAL OF CORDITE CONTAMINATED GROUND.		
SPECIAL FEATURES:		

CORDITE INTERTWINED WITH TREE ROOT SYSTEM.



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	30/1014	30
LOCATION:	AREA M	
ACTIVITY:		
REMOVAL OF CORDITE CONTAMINATED GROUND.		



SPECIAL FEATURES:
CORDITE INTERTWINED WITH TREE ROOT SYSTEM.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	30/1014	31

LOCATION:	AREA M	
ACTIVITY:		
OPENING UP OF FILLED CANAL IN CORDITE CONTAMINATED AREA.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	30/1014	32
LOCATION:	AREA M	
ACTIVITY:		
OPENING UP OF FILLED CANAL IN CORDITE CONTAMINATED AREA.		
SPECIAL FEATURES:		
TIMBER PILES DELINEATE CANAL EDGES.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	30/1014	33
LOCATION:	AREA M	
ACTIVITY:		
OPENING UP OF FILLED CANAL IN CORDITE CONTAMINATED AREA.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	30/1014	34
LOCATION:	AREA M	
ACTIVITY:		
OPENING UP OF FILLED CANAL IN CORDITE CONTAMINATED AREA.		
SPECIAL FEATURES:		
TIMBER PILES DELINEATED CANAL EDGES.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	30/1014	35
LOCATION:	AREA M	
ACTIVITY:		
OPENING UP OF FILLED CANAL IN CORDITE CONTAMINATED AREA (BUILDING L159 - CENTRE).		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
FEB '93	30/1014	36
LOCATION:	AREA M	
ACTIVITY:		
OPENING UP OF FILLED CANAL IN CORDITE CONTAMINATED AREA.		

SPECIAL FEATURES:




FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAR '93	31/1373	1
LOCATION:	AREA M	
ACTIVITY:		
OPENING UP OF FILLED CANAL IN CORDITE CONTAMINATED AREA.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAR '93	31/1373	2
LOCATION:	AREA M	
ACTIVITY:		
OPENING UP OF FILLED CANAL IN CORDITE CONTAMINATED AREA.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAR '93	31/1373	3
LOCATION:	AREA M	
ACTIVITY:		
OPENING UP OF FILLED CANAL IN CORDITE CONTAMINATED AREA.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAR '93	31/1373	4
LOCATION:	AREA M	
ACTIVITY:		
OPENING UP OF FILLED CANAL IN CORDITE CONTAMINATED AREA.		
SPECIAL FEATURES:		

TIMBER PILES.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAR '93	31/1373	5
LOCATION:	AREA M	
ACTIVITY:		
OPENING UP OF FILLED CANAL IN CORDITE CONTAMINATED AREA.		

SPECIAL FEATURES:
TIMBER PILES.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAR '93	31/1373	6


LOCATION:	AREA M	
ACTIVITY:		
OPENING UP OF FILLED CANAL IN CORDITE CONTAMINATED AREA.		
SPECIAL FEATURES:		
TIMBER PILES.		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAR '93	31/1373	7
LOCATION:	AREA M	
ACTIVITY:		
OPENING UP OF FILLED CANAL IN CORDITE CONTAMINATED AREA.		
SPECIAL FEATURES:		



--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAR '93	31/1373	8
LOCATION:	AREA M	
ACTIVITY:		
OPENING UP OF FILLED CANAL IN CORDITE CONTAMINATED AREA.		
SPECIAL FEATURES:		
TIMBER PILED EDGES.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAR '93	31/1373	9
LOCATION:	AREA M	
ACTIVITY:		
OPENING UP OF FILLED CANAL IN CORDITE CONTAMINATED AREA.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAR '93	31/1373	10
LOCATION:	AREA H	
ACTIVITY:		
SERVICE TRENCH ADJACENT TO BUILDING H26.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAR '93	31/1373	11
LOCATION:	AREA H	
ACTIVITY:		
SERVICE TRENCH NORTH OF HIGHBRIDGE STREET GATE.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAR '93	31/1373	12

LOCATION:	AREA P	
ACTIVITY:		
INTERNAL VIEW OF BUILDING A210.		
SPECIAL FEATURES:		
CORDITE CONTAMINATED MATERIAL STOCKPILED FOR DRYING OUT.		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAR '93	31/1373	13
LOCATION:	AREA M	
ACTIVITY:		
INTERNAL VIEW OF BUILDING L168.		
SPECIAL FEATURES:		
STOCKPILING OF CORDITE CONTAMINATED SOIL FOR DRYING OUT.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAR '93	31/1373	14
LOCATION:	AREA M	
ACTIVITY:		
INTERNAL VIEW OF BUILDING L168.		
SPECIAL FEATURES:		
STOCKPILING OF CORDITE CONTAMINATED SOIL FOR DRYING OUT.		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAR '93	31/1373	15
LOCATION:	AREA M	
ACTIVITY:		
REMOVAL OF CORDITE CONTAMINATED GROUND.		
SPECIAL FEATURES:		
TYPICAL CORDITE AS FOUND IN SOIL.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAR '93	31/1373	16
LOCATION:	AREA M	
ACTIVITY:		
REMOVAL OF CORDITE CONTAMINATED GROUND.		
SPECIAL FEATURES:		

TYPICAL CORDITE AS FOUND IN SOIL.




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAR '93	31/1373	17
LOCATION:	AREA M	
ACTIVITY:		
REMOVAL OF CORDITE CONTAMINATED GROUND.		

SPECIAL FEATURES:
TYPICAL CORDITE AS FOUND IN SOIL.


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAR '93	31/1373	18

LOCATION:	AREA H	
ACTIVITY:		
EXCAVATION OF SERVICES ADJACENT TO BUILDING H26.		
SPECIAL FEATURES:		
MILLSTONE FOUND IN USE AS A FOUNDATION.		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAR '93	31/1373	19
LOCATION:	AREA H	
ACTIVITY:		
EXCAVATION OF SERVICES ADJACENT TO BUILDING H26.		
SPECIAL FEATURES:		
MILLSTONE FOUND IN USE AS A FOUNDATION.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAR '93	31/1373	20
LOCATION:	AREA H	
ACTIVITY:		
EXCAVATION FOR SERVICES SOUTH OF BUILDING H26 (BUILDING H26 TO LEFT OF PICTURE).		
SPECIAL FEATURES:		
NOTE POOR CONDITION OF MILLHEAD STREAM CONCRETE EDGE PILES TIE RODS.		




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAR '93	31/1373	21
LOCATION:	AREA H	
ACTIVITY:		
EXCAVATION FOR SERVICES SOUTH OF BUILDING H26.		
SPECIAL FEATURES:		
NOTE POOR CONDITION OF MILLHEAD STREAM CONCRETE EDGE PILES TIE RODS.		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAR '93	31/1373	22
LOCATION:	AREA H	
ACTIVITY:		
EXCAVATION FOR SERVICES SOUTH OF BUILDING H26.		
SPECIAL FEATURES:		

NOTE POOR CONDITION OF MILLHEAD STREAM CONCRETE EDGE PILES  
TIE RODS.



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAR '93	31/1373	23
LOCATION:	AREA H	
ACTIVITY:		
EXPOSED TIE ROD POST FOR MILLHEAD STREAM CONCRETE PILED		

REVTMENT.
SPECIAL FEATURES:
TIE ROD SEVERELY CORRODED.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAR '93	31/1373	24


LOCATION:	AREA M	
ACTIVITY:		
INTERNAL VIEW OF BUILDING L157.		
SPECIAL FEATURES:		
HOLES THROUGH FLOOR HAVE BEEN SEALED TO PREVENT ESCAPE OF ASBESTOS FIBRES.		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAR '93	31/1373	25
LOCATION:	AREA M	
ACTIVITY:		
INTERNAL VIEW OF BUILDING L157 - ASBESTOS REMOVAL.		
SPECIAL FEATURES:		
ASBESTOS PANELLING SEALED FOR DISPOSAL.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAR '93	31/1373	26
LOCATION:	AREA M	
ACTIVITY:		
INTERNAL VIEW OF BUILDING L157 - ASBESTOS REMOVAL.		
SPECIAL FEATURES:		
ASBESTOS CONTAMINATED PIPES SEALED FOR DISPOSAL.		




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAR '93	31/1373	27
LOCATION:	AREA M	
ACTIVITY:		
INTERNAL VIEW OF BUILDING L157 - INITIAL STRIP OUT,		
SPECIAL FEATURES:		
VIEW ALONG MAIN CORRIDOR.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAR '93	31/1373	28
LOCATION:	AREA M	
ACTIVITY:		
INTERNAL VIEW OF BUILDING L157 - ASBESTOS REMOVAL.		
SPECIAL FEATURES:		



SEALED DOORS AND NOTICES AGAINST ASBESTOS.



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAR '93	31/1373	29
LOCATION:	AREA M	
ACTIVITY:		
INTERNAL VIEW OF BUILDING L157.		

SPECIAL FEATURES:
REMOVAL OF ASPHALT FROM CORRIDOR FLOOR.


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAR '93	31/1373	30

LOCATION:	AREA M	
ACTIVITY:		
INTERNAL VIEW OF BUILDING L157.		
SPECIAL FEATURES:		
REMOVAL OF ASPHALT FROM CORRIDOR FLOOR.		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAR '93	31/1373	31
LOCATION:	AREA M	
ACTIVITY:		
INTERNAL VIEW OF BUILDING L157.		
SPECIAL FEATURES:		
REMOVAL OF ASPHALT FROM CORRIDOR FLOOR (SPARK PROOF TOOLS IN USE).		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAR '93	31/1373	32
LOCATION:	AREA M	
ACTIVITY:		
INTERNAL VIEW OF BUILDING L157.		
SPECIAL FEATURES:		
REMOVAL OF ASPHALT FROM CORRIDOR FLOOR (SPARK PROOF TOOLS IN USE).		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAR '93	31/1373	33
LOCATION:	AREA H	
ACTIVITY:		
SERVICES TRENCH FROM BUILDINGS A203 - A200.		
SPECIAL FEATURES:		
NEW SERVICES BEING INSTALLED.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAR '93	31/1373	34
LOCATION:	AREA H	
ACTIVITY:		
SERVICES TRENCH TO BUILDING A200.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAR '93	31/1373	35
LOCATION:	AREA H	
ACTIVITY:		
SERVICES TRENCH TO BUILDING A200.		



SPECIAL FEATURES:
NEW SERVICES BEING INSTALLED.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAR '93	31/1373	36

LOCATION:	AREA H	
ACTIVITY:		
STOCKPILING OF 'SPECIAL WASTE' ON H19 AREA.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAR '93	31/1373	36 A
LOCATION:	AREA H	
ACTIVITY:		
EXCAVATION FOR SERVICES EAST OF BUILDING H26.		
SPECIAL FEATURES:		
NOTE DIVERSION OF TRENCH AROUND MILLSTONE.		




**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDICATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAR '93	32/1374	1
LOCATION:	AREA	
ACTIVITY:		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAR '93	32/1374	2
LOCATION:	AREA H	
ACTIVITY:		
SERVICE TRENCH EAST OF BUILDING H26.		
SPECIAL FEATURES:		
MILLHEAD STREAM WALL TIE ROD POSTS.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAR '93	32/1374	3
LOCATION:	AREA H	
ACTIVITY:		
SERVICE TRENCH EXCAVATION.		
SPECIAL FEATURES:		
MILLHEAD STREAM WALL TIE ROD POSTS.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAR '93	32/1374	4
LOCATION:	AREA H	
ACTIVITY:		
'SPECIAL WASTE' STOCKPILED WEST OF BUILDING H23.		
SPECIAL FEATURES:		




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAR '93	32/1374	5
LOCATION:	AREA H	
ACTIVITY:		
'SPECIAL WASTE' STOCKPILED ON H19 AREA.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAR '93	32/1374	6

LOCATION:	AREA M	
ACTIVITY:		
BUILDING L148 - TIDYING UP EXTERNALLY.		
SPECIAL FEATURES:		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAR '93	32/1374	7
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L153 - TIDYING UP EXTERNALLY.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAR '93	32/1374	8
LOCATION:	AREA M	
ACTIVITY:		
INTERNAL VIEW OF BUILDING L148.		
SPECIAL FEATURES:		
BAGGING ASPHALT FROM CORRIDOR FLOOR.		




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAR '93	32/1374	9
LOCATION:	AREA M	
ACTIVITY:		
INTERNAL VIEW OF BUILDING L148.		
SPECIAL FEATURES:		
REMOVAL OF ASPHALT FROM CORRIDOR FLOOR.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAR '93	32/1374	10
LOCATION:	AREA M	
ACTIVITY:		
INTERNAL VIEW OF BUILDING L148.		
SPECIAL FEATURES:		

REMOVAL OF ASPHALT FROM CORRIDOR



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAR '93	32/1374	11
LOCATION:	AREA M	
ACTIVITY:		
INTERNAL VIEW OF BUILDING L148.		



SPECIAL FEATURES:
VACUUMING ROOF.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAR '93	32/1374	12

LOCATION:	AREA M	
ACTIVITY:		
INTERNAL VIEW OF BUILDING L148.		
SPECIAL FEATURES:		
VACUUMING ROOF AND WALLS - TYPE 'H' VACUUM IN USE.		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAR '93	32/1374	13
LOCATION:	AREA M	
ACTIVITY:		
INTERNAL VIEW OF BUILDING L148.		
SPECIAL FEATURES:		
GENERAL VIEW OF VACUUMING - TYPE 'H' VACUUM IN USE.		



**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAR '93	33/1575	1
LOCATION:	AREA S	
ACTIVITY:		
BAGGED ASBESTOS STOCKPILED AWAITING MOVE TO HOLDING / SAMPLING AREA.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAR '93	33/1575	2
LOCATION:	AREA S	
ACTIVITY:		
BAGGED ASBESTOS STOCKPILED AWAITING MOVE TO HOLDING / SAMPLING AREA.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAR '93	33/1575	3
LOCATION:	AREA S	
ACTIVITY:		
ASBESTOS REMOVAL IN PROGRESS FROM WASTE DUMP.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAR '93	33/1575	4
LOCATION:	AREA B	
ACTIVITY:		
FILLED CANAL - EXCAVATION OF WASTE (BURNING GROUND NORTH).		
SPECIAL FEATURES:		




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAR '93	33/1575	5
LOCATION:	AREA S	
ACTIVITY:		
FILLED CANAL - EXCAVATION OF WASTE (BURNING GROUND NORTH).		

SPECIAL FEATURES:


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAR '93	33/1575	6

LOCATION:	AREA B	
ACTIVITY:		
VARIOUS PRESSURE CYLINDERS FOUND IN WASTE FROM CANAL EXCAVATION, BURNING GROUND NORTH.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAR '93	33/1575	7
LOCATION:	AREA B	
ACTIVITY:		
EXCAVATION OF FILLED CANAL - BURNING GROUND NORTH.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAR '93	33/1575	8
LOCATION:	AREA B	
ACTIVITY:		
TRACKED DUMPER TRANSPORTING WASTE MATERIAL.		
SPECIAL FEATURES:		
BOGGY TERRAIN.		




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAR '93	33/1575	9
LOCATION:	AREA B	
ACTIVITY:		
PRESSURE CYLINDER FOUND IN CANAL WASTE.		
SPECIAL FEATURES:		
POOR CONDITION OF CYLINDER.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAR '93	33/1575	10
LOCATION:	AREA B	
ACTIVITY:		
360 MACHINE CLEARING FILLED CANAL.		
SPECIAL FEATURES:		

BRIDGE No. 16 IN BACKGROUND.



**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAR '93	33/1575	11
LOCATION:	AREA B	
ACTIVITY:		
WASTE DUMP EAST OF BURNING GROUND (REF.: 11038).		



SPECIAL FEATURES:
BUILDING 103 (PRESS HOUSE) IN BACKGROUND.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAR '93	33/1575	12

LOCATION:	AREA B	
ACTIVITY:		
TREE CLEARANCE OVER WASTE TIP.		
SPECIAL FEATURES:		
BRIDGE No. 10 IN BACKGROUND.		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAR '93	33/1575	13
LOCATION:	AREA M	
ACTIVITY:		
CORDITE RECOVERED FROM AREA M.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAR '93	33/1575	14
LOCATION:	AREA M	
ACTIVITY:		
CORDITE RECOVERED FROM AREA M.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAR '93	33/1575	15
LOCATION:	AREA M	
ACTIVITY:		
CORDITE RECOVERED FROM AREA M.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAR '93	33/1575	16
LOCATION:	AREA M	
ACTIVITY:		
CORDITE RECOVERED FROM AREA M.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAR '93	33/1575	17
LOCATION:	AREA M	
ACTIVITY:		
CORDITE RECOVERED FROM AREA M.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAR '93	33/1575	18




LOCATION:	AREA H	
ACTIVITY:		
SERVICE TRENCH WEST BANK OF MILLHEAD STREAM (INSTALLATION OF ISLAND SITE SERVICES).		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAR '93	33/1575	19
LOCATION:	AREA H	
ACTIVITY:		
SERVICE TRENCH WEST BANK OF MILLHEAD STREAM (INSTALLATION OF ISLAND SITE SERVICES).		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAR '93	33/1575	20
LOCATION:	AREA H	
ACTIVITY:		
SERVICE TRENCH WEST BANK OF MILLHEAD STREAM FOR NEW ISLAND SITE SERVICES.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAR '93	33/1575	21
LOCATION:	AREA H	
ACTIVITY:		
SERVICE TRENCH WEST BANK OF MILLHEAD STREAM (FOR INSTALLATION OF ISLAND SITE SERVICES).		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAR '93	33/1575	22
LOCATION:	AREA H	
ACTIVITY:		
SERVICE TRENCH WEST BANK OF MILLHEAD STREAM (FOR INSTALLATION OF ISLAND SITE SERVICES).		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAR '93	33/1575	23
LOCATION:	AREA H	
ACTIVITY:		
NEW SERVICES TRENCH - EXISTING TIMBER BOARDING.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAR '93	33/1575	24

LOCATION:	AREA H	
ACTIVITY:		
SERVICE TRENCH WEST BANK MILLHEAD STREAM (FOR INSTALLATION OF ISLAND SITE SERVICES).		
SPECIAL FEATURES:		



**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAR '93	33/1575	25
LOCATION:	AREA H	
ACTIVITY:		
BUILDING A200 - TRIAL PIT AT CORNER OF BUILDING.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAR '93	33/1575	26
LOCATION:	AREA H	
ACTIVITY:		
TRIAL PIT AT CORNER OF BUILDING A200.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAR '93	33/1575	27
LOCATION:	AREA H	
ACTIVITY:		
TRIAL PIT AT CORNER OF BUILDING A200.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAR '93	33/1575	28
LOCATION:	AREA H	
ACTIVITY:		
TRIAL PIT AT CORNER OF BUILDING A200.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAR '93	33/1575	29
LOCATION:	AREA H	
ACTIVITY:		
TRIAL PIT AT CORNER OF BUILDING A200.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAR '93	33/1575	30

LOCATION:	AREA H	
ACTIVITY:		
TRIAL PIT AT CORNER OF BUILDING A200.		
SPECIAL FEATURES:		


**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAR '93	33/1575	31
LOCATION:	AREA H	
ACTIVITY:		
EXCAVATION OF TRIAL PIT AT BUILDING A200.		
SPECIAL FEATURES:		



--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAR '93	33/1575	32
LOCATION:	AREA H	
ACTIVITY:		
TRIAL PIT AT CORNER OF BUILDING A200.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAR '93	33/1575	33
LOCATION:	AREA H	
ACTIVITY:		
BUILDING A203 - DUCT IN SERVICE TRENCH (INSTALLATION OF ISLAND SITE SERVICES).		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAR '93	33/1575	34
LOCATION:	AREA H	
ACTIVITY:		
BUILDING A203 - DUCT IN SERVICE TRENCH (INSTALLATION OF ISLAND SITE SERVICES).		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAR '93	33/1575	35
LOCATION:	AREA H	
ACTIVITY:		
BUILDING A202 - TELEPHONE DRAW PIT WEST SIDE OF BUILDING		

(INSTALLATION OF ISLAND SITE SERVICES).
SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAR '93	33/1575	36

LOCATION:	AREA H	
ACTIVITY:		
SERVICE TRENCH ON WEST SIDE OF BUILDINGS A202 AND A203 (INSTALLATION OF ISLAND SITE SERVICES).		
SPECIAL FEATURES:		
BRIDGE 17 IN BACKGROUND.		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAR '93	33/1575	36 A
LOCATION:	AREA H	
ACTIVITY:		
SERVICE TRENCH AT BRIDGE No. 17 (INSTALLATION OF ISLAND SITE SERVICES).		
SPECIAL FEATURES:		






FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
10/3/93	34/2032	1
LOCATION:	AREA H	
ACTIVITY:		
VIEW ACROSS MILLHEAD STREAM SHOWING SERVICE TRENCH ON WEST BANK (LOOKING SOUTH WEST).		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
10/3/93	34/2032	2
LOCATION:	AREA S	
ACTIVITY:		
EXCAVATION OF WASTE TIP REF.: 11034 LOOKING SOUTH.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
10/3/93	34/2032	3
LOCATION:	AREA H	
ACTIVITY:		
VIEW OF ROOF OF BUILDING A201/2		
SPECIAL FEATURES:		
DELAPIDATION OF ROOF.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
10/3/93	34/2032	4
LOCATION:	AREA H	
ACTIVITY:		
BUILDINGS A201 AND A202 - FLAT ROOF LOOKING EAST.		
SPECIAL FEATURES:		

POOR CONDITION.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
10/3/93	34/2032	5
LOCATION:	AREA H	
ACTIVITY:		
BUILDINGS A201 AND A202 - FLAT ROOF LOOKING WEST.		

SPECIAL FEATURES:
POOR CONDITION.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
10/3/93	34/2032	6

LOCATION:	AREA H	
ACTIVITY:		
VIEW FROM A201 FLAT ROOF TOWARDS AREA H.		
SPECIAL FEATURES:		
BUILDINGS H11, H66 AND H1 IN VIEW.		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
10/3/93	34/2032	7
LOCATION:	AREA H	
ACTIVITY:		
BUILDING A201 - VALLEY GUTTER SHOWING DAMAGED SLATES (WEST).		
SPECIAL FEATURES:		
POOR CONDITION.		



--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
10/3/93	34/2032	8
LOCATION:	AREA H	
ACTIVITY:		
BUILDING A201 - VALLEY GUTTER SHOWING DAMAGED SLATES (EAST).		
SPECIAL FEATURES:		
POOR CONDITION.		




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
10/3/93	34/2032	9
LOCATION:	AREA H	
ACTIVITY:		
BUILDING A201 - VALLEY GUTTER SHOWING DAMAGED SLATES (EAST).		
SPECIAL FEATURES:		
POOR CONDITION.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
10/3/93	34/2032	10
LOCATION:	AREA H	
ACTIVITY:		
BUILDING A201 - VALLEY GUTTER SHOWING DAMAGED HIP SLATES (BUILDING A200 IN BACKGROUND).		
SPECIAL FEATURES:		

POOR CONDITION.



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
10/3/93	34/2032	11
LOCATION:	AREA H	
ACTIVITY:		
BUILDING A201 - SHOWING DAMAGED HIP SLATES.		

SPECIAL FEATURES:
POOR CONDITION.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
10/3/93	34/2032	12

LOCATION:	AREA H	
ACTIVITY:		
BUILDING A201 - ROOF SHOWING PATCH TO HIP END (BUILDINGS L173 AND L176 IN BACKGROUND).		
SPECIAL FEATURES:		
POOR CONDITION.		




FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
11/3/93	35/2033	1
LOCATION:	AREA H	
ACTIVITY:		
'SPECIAL WASTE' STOCKPILE AT H19 AREA.		
SPECIAL FEATURES:		



--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
11/3/93	35/2033	2
LOCATION:	AREA H	
ACTIVITY:		
'SPECIAL WASTE' STOCKPILE AT H19 AREA.		
SPECIAL FEATURES:		
LOADING OFF SITE TRANSPORT.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
11/3/93	35/2033	3
LOCATION:	AREA H	
ACTIVITY:		
'SPECIAL WASTE' STOCKPILED AT H19 AREA.		
SPECIAL FEATURES:		
LOADING OFF SITE TRANSPORT.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
11/3/93	35/2033	4
LOCATION:	AREA H	
ACTIVITY:		
AIR MONITOR AT H19 'SPECIAL WASTE' STOCKPILE.		
SPECIAL FEATURES:		

AIR MONITORING PUMP.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
11/3/93	35/2033	5
LOCATION:	AREA H	
ACTIVITY:		
AIR MONITOR AT H19 'SPECIAL WASTE' STOCKPILE.		

SPECIAL FEATURES:
AIR MONITORING PUMP.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
11/3/93	35/2033	6

LOCATION:	AREA H	
ACTIVITY:		
AIR MONITOR AT H19 'SPECIAL WASTE' STOCKPILE.		
SPECIAL FEATURES:		
AIR MONITORING PUMP.		


**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
11/3/93	35/2033	7
LOCATION:	AREA H	
ACTIVITY:		
AIR MONITORING AT H19 'SPECIAL WASTE' STOCKPILE.		
SPECIAL FEATURES:		
AIR MONITORING PUMP.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
11/3/93	35/2033	8
LOCATION:	AREA H	
ACTIVITY:		
AIR MONITORING AT H24 LOCATION NEAR 'SPECIAL WASTE' STOCKPILE.		
SPECIAL FEATURES:		
AIR MONITORING PUMP.		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
11/3/93	35/2033	9
LOCATION:	AREA H	
ACTIVITY:		
AIR MONITORING AT H24 LOCATION NEAR 'SPECIAL WASTE' STOCKPILE.		
SPECIAL FEATURES:		
AIR MONITORING PUMP.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
11/3/93	35/2033	10
LOCATION:	AREA H	
ACTIVITY:		
AIR MONITORING AT H19 AREA.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
11/3/93	35/2033	11
LOCATION:	AREA H	
ACTIVITY:		
'SPECIAL WASTE' REMOVAL - LORRY CLEANING.		

SPECIAL FEATURES:
PRESSURE WASHER.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
11/3/93	35/2033	12


LOCATION:	AREA H	
ACTIVITY:		
'SPECIAL WASTE' REMOVAL - LORRY CLEANING.		
SPECIAL FEATURES:		
PRESSURE WASHER.		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
11/3/93	35/2033	13
LOCATION:	AREA H	
ACTIVITY:		
VIEW OF H16 WASTE SAMPLING AREA.		
SPECIAL FEATURES:		
DAMPENING DOWN WASTE TO CONTROL DUST.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/3/93	35/2033	14
LOCATION:	AREA B	
ACTIVITY:		
BURIED STRUCTURE EAST OF BURNING GROUND.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/3/93	35/2033	15
LOCATION:	AREA B	
ACTIVITY:		
BURIED STRUCTURE EAST OF BURNING GROUND.		
SPECIAL FEATURES:		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/3/93	35/2033	16
LOCATION:	AREA B	
ACTIVITY:		
BURIED STRUCTURE EAST OF BURNING GROUND.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/3/93	35/2033	17
LOCATION:	AREA B	
ACTIVITY:		
ASBESTOS DUMP EAST OF BURNING GROUND (TIP REF.: 11038).		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/3/93	35/2033	18

LOCATION:	AREA B	
ACTIVITY:		
ASBESTOS DUMP EAST OF BURNING GROUND (TIP REF.: 11038).		
SPECIAL FEATURES:		
BROKEN BAGS OF ASBESTOS WASTE.		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/3/93	35/2033	19
LOCATION:	AREA B	
ACTIVITY:		
ASBESTOS DUMP EAST OF BURNING GROUND (TIP REF.: 11038).		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/3/93	35/2033	20
LOCATION:	AREA B	
ACTIVITY:		
ASBESTOS DUMP EAST OF BURNING GROUND (TIP REF.: 11038).		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/3/93	35/2033	21
LOCATION:	AREA B	
ACTIVITY:		
ASBESTOS DUMP EAST OF BURNING GROUND (TIP REF.: 11038).		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/3/93	35/2033	22
LOCATION:	AREA B	
ACTIVITY:		
WASTE TIP REF.: 11038 - NORTH BURNING GROUND - REMOVAL.		
SPECIAL FEATURES:		




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/3/93	35/2033	23
LOCATION:	AREA B	
ACTIVITY:		
WASTE TIP REF.: 11038 - NORTH BURNING GROUND - AFTER REMOVAL.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/3/93	35/2033	24


LOCATION:	AREA B	
ACTIVITY:		
WASTE TIP REF.: 11038 NORTH BURNING GROUND		
SPECIAL FEATURES:		
WHITE DEPOSITS IN GRAVELS.		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDICATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/3/93	35/2033	25
LOCATION:	AREA B	
ACTIVITY:		
WASTE TIP REF.: 11038 NORTH BURNING GROUND.		
SPECIAL FEATURES:		
WHITE DEPOSITS IN GRAVELS.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/3/93	35/2033	26
LOCATION:	AREA B	
ACTIVITY:		
WASTE TIP REF.: 11038 NORTH BURNING GROUND.		
SPECIAL FEATURES:		
WHITE DEPOSITS IN GRAVELS.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/3/93	35/2033	27
LOCATION:	AREA B	
ACTIVITY:		
ASBESTOS DUMP SOUTH EAST BURNING GROUND.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/3/93	35/2033	28
LOCATION:	AREA P	
ACTIVITY:		
WASTE FROM AROUND THE SITE BEING SORTED OUT TO RETRIEVE SCRAP METALS.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/3/93	35/2033	29
LOCATION:	AREA H	
ACTIVITY:		
MOBILE SITE LABORATORY - AIR MONITORING.		



SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/3/93	35/2033	30

LOCATION:	AREA H	
ACTIVITY:		
MOBILE SITE LABORATORY - AIR MONITORING.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/3/93	35/2033	31
LOCATION:	AREA H	
ACTIVITY:		
MOBILE SITE LABORATORY - AIR MONITORING.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/3/93	35/2033	32
LOCATION:	AREA H	
ACTIVITY:		
TRIAL PIT AT H19 - LOOKING NORTH EAST TO DETERMINE DEPTH OF FILLED GROUND.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/3/93	35/2033	33
LOCATION:	AREA H	
ACTIVITY:		
TRIAL PIT AT H19 - CLOSE UP OF FILLED LEVELS.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/3/93	35/2033	34
LOCATION:	AREA H	
ACTIVITY:		
TRIAL PIT AT H19 - LOOKING NORTH EAST TO DETERMINE DEPTH OF FILLED GROUND.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/3/93	35/2033	35
LOCATION:	AREA P	
ACTIVITY:		
BUILDING A238 - REFURBISHMENT OF ROOF.		

SPECIAL FEATURES:



**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
8/3/93	36/2034	1
LOCATION:	AREA H	
ACTIVITY:		
'SPECIAL WASTE' LORRIES LEAVING HIGHBRIDGE STREET.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
8/3/93	36/2034	2
LOCATION:	AREA H	
ACTIVITY:		
'SPECIAL WASTE' LORRIES LEAVING HIGHBRIDGE STREET.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
8/3/93	36/2034	3
LOCATION:	AREA H	
ACTIVITY:		
LOADING 'SPECIAL WASTE' ON H19 AREA.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
8/3/93	36/2034	4
LOCATION:	AREA H	
ACTIVITY:		
LOADING 'SPECIAL WASTE' ON H19 AREA.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/3/93	36/2034	5
LOCATION:	AREA H	
ACTIVITY:		
SERVICE TRENCH WEST BANK MILLHEAD STREAM.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/3/93	36/2034	6

LOCATION:	AREA H	
ACTIVITY:		
SERVICE TRENCH SHOWING EXISTING SERVICES.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/3/93	36/2034	7
LOCATION:	AREA H	
ACTIVITY:		
SERVICE TRENCH SHOWING EXISTING SERVICES.		
SPECIAL FEATURES:		



--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/3/93	36/2034	8
LOCATION:	AREA H	
ACTIVITY:		
SERVICE TRENCH SHOWING REVETMENT TIE RODS.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/3/93	36/2034	9
LOCATION:	AREA H	
ACTIVITY:		
SERVICE TRENCH SHOWING EXISTING SERVICES.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/3/93	36/2034	10
LOCATION:	AREA H	
ACTIVITY:		
SERVICE TRENCH SHOWING EXISTING SERVICES.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/3/93	36/2034	11
LOCATION:	AREA H	
ACTIVITY:		
SERVICE TRENCH (WATER ONLY) SOUTH OF H10.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/3/93	36/2034	12


LOCATION:	AREA H	
ACTIVITY:		
SERVICE TRENCH (ELECTRICITY ONLY) EAST OF H10.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/3/93	36/2034	13
LOCATION:	AREA H	
ACTIVITY:		
SERVICE TRENCH (WATER ONLY) SOUTH OF H6 AND H5.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/3/93	36/2034	14
LOCATION:	AREA H	
ACTIVITY:		
SERVICE TRENCH (WATER ONLY) SOUTH OF H10.		
SPECIAL FEATURES:		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/3/93	36/2034	15
LOCATION:	AREA H	
ACTIVITY:		
SERVICE TRENCH (ELECTRICITY ONLY) NORTH OF H10 - H17.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/3/93	36/2034	16
LOCATION:	AREA H	
ACTIVITY:		
SERVICE TRENCH (ELECTRICITY ONLY) NORTH OF H10 - H17.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/3/93	36/2034	17
LOCATION:	AREA H	
ACTIVITY:		
SERVICE TRENCH (ELECTRICITY ONLY) NORTH OF H10 - H17.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/3/93	36/2034	18

LOCATION:	AREA H	
ACTIVITY:		
SERVICE TRENCH (ELECTRICITY ONLY) H17 - H8.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
10/3/93	36/2034	19
LOCATION:	AREA B	
ACTIVITY:		
EXCAVATION OF WASTE TIP REF.: 11032.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
10/3/93	36/2034	20
LOCATION:	AREA B	
ACTIVITY:		
WASTE TIP REF.: 11032		
SPECIAL FEATURES:		




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
10/3/93	36/2034	21
LOCATION:	AREA B	
ACTIVITY:		
EXCAVATION OF WASTE TIP REF.: 11032.		
SPECIAL FEATURES:		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
10/3/93	36/2034	22
LOCATION:	AREAS	
ACTIVITY:		
RCHME SURVEYING.		
SPECIAL FEATURES:		

GRAND MAGAZINE.



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
10/3/93	36/2034	23
LOCATION:	AREA S	
ACTIVITY:		
RCHME SURVEYING.		

SPECIAL FEATURES:
GRAND MAGAZINE.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
10/3/93	36/2034	24


LOCATION:	AREAS	
ACTIVITY:		
GRAND MAGAZINE.		
SPECIAL FEATURES:		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
10/3/93	36/2034	25
LOCATION:	AREA S	
ACTIVITY:		
GRAND MAGAZINE.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
10/3/93	36/2034	26
LOCATION:	AREA S	
ACTIVITY:		
GRAND MAGAZINE.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
10/3/93	36/2034	27
LOCATION:	AREA S	
ACTIVITY:		
GRAND MAGAZINE.		
SPECIAL FEATURES:		
TREE MARKED FOR FELLING.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
10/3/93	36/2034	28
LOCATION:	AREA S	
ACTIVITY:		
TREES ADJACENT TO GRAND MAGAZINE MARKED FOR FELLING.		
SPECIAL FEATURES:		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
10/3/93	36/2034	29
LOCATION:	AREA S	
ACTIVITY:		
GRAND MAGAZINE.		

SPECIAL FEATURES:


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
10/3/93	36/2034	30

LOCATION:	AREAS	
ACTIVITY:		
RCHME PLANE TABLE.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
10/3/93	36/2034	31
LOCATION:	AREA S	
ACTIVITY:		
GRAND MAGAZINE.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
10/3/93	36/2034	32
LOCATION:	AREA S	
ACTIVITY:		
RCHME PLANE TABLE.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
10/3/93	36/2034	33
LOCATION:	AREA S	
ACTIVITY:		
RCHME SURVEYING.		
SPECIAL FEATURES:		
ASBESTOS IN FOREGROUND.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
10/3/93	36/2034	34
LOCATION:	AREA H	
ACTIVITY:		
SERVICE TRENCH (ELECTRICITY ONLY) H8 - H17.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
10/3/93	36/2034	35
LOCATION:	AREA H	
ACTIVITY:		
SERVICE TRENCH (ELECTRICITY ONLY) AT ENTRANCE TO BUILDING H8.		



SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
10/3/93	36/2034	36

LOCATION:	AREA H	
ACTIVITY:		
SERVICE TRENCH BETWEEN BUILDINGS A203 AND A202.		
SPECIAL FEATURES:		
BRIDGE No. 17 ACCESS.		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
10/3/93	36/2034	37
LOCATION:	AREA H	
ACTIVITY:		
'SPECIAL WASTE' ON H16 SAMPLING AREA.		
SPECIAL FEATURES:		



**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDICATION RECORD**

DATE:

NEGATIVE REFERENCE:

FRAME REFERENCE:

15/3/93

37/2613

1

LOCATION:

AREA N


ACTIVITY:

SUSPECT PIT.

SPECIAL FEATURES:

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
15/3/93	37/2613	2
LOCATION:	AREA S	
ACTIVITY:		
VIEW TOWARDS BUILDING 88A.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
15/3/93	37/2613	4
LOCATION:	AREA S	
ACTIVITY:		
VIEW OF OLD RIVER LEA - LOOKING EAST FROM BRIDGE No. 10.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
15/3/93	37/2613	5
LOCATION:	AREA S	
ACTIVITY:		
VIEW LOOKING SOUTH TO WASTE TIP REF.: 11032.		
SPECIAL FEATURES:		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
15/3/93	37/2613	6
LOCATION:	AREAS	
ACTIVITY:		
VIEW FROM REMEDIATED WASTE TIP REF.: 11038 - LOOKING TOWARDS		

BRIDGE No. 16.
SPECIAL FEATURES:


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
15/3/93	37/2613	7

LOCATION:	AREAS	
ACTIVITY:		
PHEASANT.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
19/3/93	37/2613	8
LOCATION:	AREA H	
ACTIVITY:		
INSTALLATION OF NEW WATER MAIN.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
19/3/93	37/2613	9
LOCATION:	AREA H	
ACTIVITY:		
NEW WATER MAIN INSTALLED IN AREA H.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
19/3/93	37/2613	10
LOCATION:	AREA H	
ACTIVITY:		
NEW WATER MAIN INSTALLED IN AREA H.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
19/3/93	37/2613	11
LOCATION:	AREA H	
ACTIVITY:		
SERVICE TRENCH.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
19/3/93	37/2613	12
LOCATION:	AREA H	
ACTIVITY:		
BACKFILLING WATER MAIN TRENCH.		



SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
19/3/93	37/2613	13

LOCATION:	AREA H	
ACTIVITY:		
TRENCH FOR NEW WATER MAIN.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
19/3/93	37/2613	14
LOCATION:	AREA H	
ACTIVITY:		
EXCAVATION FOR NEW WATER MAIN.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
23/3/93	37/2613	15
LOCATION:	AREA H	
ACTIVITY:		
INTERNAL VIEW OF BUILDING A202.		
SPECIAL FEATURES:		
REFURBISHMENT OF FLOOR JOISTS.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
23/3/93	37/2613	16
LOCATION:	AREA H	
ACTIVITY:		
EXISTING SERVICES SOUTH OF BUILDING A202 - UNDER PAVING.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
23/3/93	37/2613	17
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L148 - 1ST STAGE DECONTAMINATION.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
23/3/93	37/2613	18
LOCATION:	AREA M	
ACTIVITY:		
LVRPA IMPORTED SOIL BEING STOCKPILED NORTH OF BUILDING L148.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
23/3/93	37/2613	19




LOCATION:	AREA M	
ACTIVITY:		
BUILDING L153 - 1ST STAGE DECONTAMINATION.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
23/3/93	37/2613	20
LOCATION:	AREA M	
ACTIVITY:		
LVRPA IMPORTED SOIL BEING STOCKPILED NORTH OF BUILDING L148.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
23/3/93	37/2613	21
LOCATION:	AREA M	
ACTIVITY:		
INTERNAL VIEW OF BUILDING L153 - 1ST STAGE DECONTAMINATION.		
SPECIAL FEATURES:		
ROOF STRUCTURE.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
23/3/93	37/2613	22
LOCATION:	AREA M	
ACTIVITY:		
INTERNAL VIEW OF BUILDING L153 - 1ST STAGE DECONTAMINATION IN PROGRESS.		
SPECIAL FEATURES:		
WALL CORING POSITION.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
23/3/93	37/2613	23
LOCATION:	AREA M	
ACTIVITY:		
VIEW FROM BUILDING L153 TOWARDS BUILDING L148.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
23/3/93	37/2613	24
LOCATION:	AREA M	
ACTIVITY:		
VIEW FROM BUILDING L153 TOWARDS BUILDING L157.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
23/3/93	37/2613	25

LOCATION:	AREA M	
ACTIVITY:		
BUILDING L153 - 1ST STAGE DECONTAMINATION.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
23/3/93	37/2613	26
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L153 - 1ST STAGE DECONTAMINATION.		
SPECIAL FEATURES:		
VACUUMING ROOF STRUCTURE.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
23/3/93	37/2613	27
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L153 - 1ST STAGE DECONTAMINATION.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
23/3/93	37/2613	28
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L153 - 1ST STAGE DECONTAMINATION.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
24/3/93	37/2613	29
LOCATION:	AREA H	
ACTIVITY:		
BACKFILLING OF NEW WATER MAIN IN SERVICES TRENCH.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
24/3/93	37/2613	30
LOCATION:	AREA H	
ACTIVITY:		
BACKFILLING OF NEW WATER MAIN IN SERVICES TRENCH.		

SPECIAL FEATURES:
DETECTABLE WARNING TAPE.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
29/3/93	37/2613	31

LOCATION:	AREA H	
ACTIVITY:		
NEW ELECTRICAL CABLE INSTALLATION FOR ISLAND SITE SERVICES.		
SPECIAL FEATURES:		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
29/3/93	37/2613	32
LOCATION:	AREA P	
ACTIVITY:		
TEMPORARY CANOPY OVER BUILDING A269.		
SPECIAL FEATURES:		



--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
29/3/93	37/2613	33
LOCATION:	AREA H	
ACTIVITY:		
B.T. DRAW PIT ON NEW ISLAND SITE SERVICES ROUTE.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
29/3/93	37/2613	34
LOCATION:	AREA H	
ACTIVITY:		
INSTALLATION OF TELECOM'S DUCTING SOUTHERN POINT IN AREA H.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
29/3/93	37/2613	35
LOCATION:	AREA H	
ACTIVITY:		
B.T. DRAW PIT AREA H.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
29/3/93	37/2613	36
LOCATION:	AREA H	
ACTIVITY:		
DUCTS FROM B.T. DRAW PIT.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
29/3/93	37/2613	36A

LOCATION:	AREA H	
ACTIVITY:		
DUCTS FROM B.T. DRAW PIT.		
SPECIAL FEATURES:		




FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAR '93	38/2756	1
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L148 - DRILLING FOR TIMBER SAMPLES.		
SPECIAL FEATURES:		



--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAR '93	38/2756	2
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L148 - DRILLING FOR TIMBER SAMPLES.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAR '93	38/2756	3
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L148 - DRILLING FOR TIMBER SAMPLES.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAR '93	38/2756	4
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L148 - DRILLING FOR TIMBER SAMPLES.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAR '93	38/2756	5
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L148 - DRILLING FOR TIMBER SAMPLES.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAR '93	38/2756	6

LOCATION:	AREA M	
ACTIVITY:		
BUILDING L148 - DRILLING FOR TIMBER SAMPLES.		
SPECIAL FEATURES:		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAR '93	38/2756	7
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L148 - DRILLING FOR TIMBER SAMPLES.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAR '93	38/2756	8
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L145 - WOOD SHAVING SAMPLES.		
SPECIAL FEATURES:		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAR '93	38/2756	9
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L148 - PAINTED NOTICE ON CORRIDOR FLOOR.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAR '93	38/2756	10
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L148 - BAGGED ASBESTOS WASTE AWAITING DISPOSAL.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAR '93	38/2756	11
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L148 - CONTAMINATED METAL AWAITING TREATMENT AND		

DISPOSAL.
SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAR '93	38/2756	12

LOCATION:	AREA M	
ACTIVITY:		
BUILDING L148 - BAGGED WASTE AND OTHER WASTE AWAITING DISPOSAL.		
SPECIAL FEATURES:		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAR '93	38/2756	13
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L148 - BAGGED WASTE AWAITING DISPOSAL.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAR '93	38/2756	14
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L148 - CONTAMINATED TIMBER AWAITING DISPOSAL.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAR '93	38/2756	15
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L148 - BAGGED ASBESTOS WASTE AWAITING DISPOSAL.		
SPECIAL FEATURES:		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAR '93	38/2756	16
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L148 - CONTAMINATED TIMBER AWAITING DISPOSAL.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAR '93	38/2756	17
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L148 - CONTAMINATED RUBBLE AWAITING DISPOSAL.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAR '93	38/2756	18

LOCATION:	AREA M	
ACTIVITY:		
BUILDING L148 - CONTAMINATED METAL AWAITING TREATMENT AND DISPOSAL.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAR '93	39/3132	1
LOCATION:	AREA S	
ACTIVITY:		
WASTE TIP ADJACENT TO WEST BOUNDARY - NEAR EDMONSEY SLUICE.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAR '93	39/3132	2
LOCATION:	AREA S	
ACTIVITY:		
WASTE TIP AT WEST BOUNDARY - SOUTH OF EDMONSEY SLUICE.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAR '93	39/3132	3
LOCATION:	AREA S	
ACTIVITY:		
STEAM MAIN FOUNDATION BASE - NORTH OF BUILDING L128.		
SPECIAL FEATURES:		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAR '93	39/3132	4
LOCATION:	AREA S	
ACTIVITY:		
DRAIN TO DRAINAGE DITCH ADJACENT BRIDGE No. 52.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAR '93	39/3132	5
LOCATION:	AREA S	
ACTIVITY:		
SEPTIC TANK ARRANGEMENT ADJACENT TO BRIDGE No. 52 & BUILDING		

U7.
SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAR '93	39/3132	6

LOCATION:	AREA B	
ACTIVITY:		
BUILDING 96 VIEWED FROM WEST.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAR '93	39/3132	7
LOCATION:	AREA S	
ACTIVITY:		
BUILDING L108 -VIEWED FROM NORTH (BUILDING L136 IN BACKGROUND).		
SPECIAL FEATURES:		
FILLED CANAL TO LEFT OF BUILDING (BENEATH PATHWAY).		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAR '93	39/3132	8
LOCATION:	AREA S	
ACTIVITY:		
WASTE TIP REF.: 11036 - LOOKING WEST.		
SPECIAL FEATURES:		
TREE FELLING TO GAIN ACCESS TO TIP (BAGGED ASBESTOS COLLECTION POINT IN BACKGROUND).		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAR '93	39/3132	9
LOCATION:	AREA S	
ACTIVITY:		
BUILDING RCHME 171 HIDDEN BY UNDERGROWTH.		
SPECIAL FEATURES:		
TIMBERED CANAL EDGE VISIBLE AT BOTTOM RIGHT OF PICTURE AT BRIDGE No. 65. HERONRY DEMARCATION TAPE STRUNG OUT BETWEEN TREES.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAR '93	39/3132	10
LOCATION:	AREA L	
ACTIVITY:		
L.V.R.P.A. IMPORTED SOIL BEING STOCKPILED NORTH OF BUILDING L122.		
SPECIAL FEATURES:		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAR '93	39/3132	F
LOCATION:	AREA S	
ACTIVITY:		
RETAINING WALL SOUTH OF BUILDINGS 107 & 108.		



SPECIAL FEATURES:

BRICK ARCH TO STRUCTURE JUST VISIBLE ABOVE WATER LINE.



**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
31/3/93	40/3131	1
LOCATION:	AREA H	
ACTIVITY:		
REMOVING WASTE FROM H16 SAMPLING AREA.		
SPECIAL FEATURES:		
REMOVING SAMPLED & ANALYSED WASTE TO A HOLDING STOCKPILE.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
31/3/93	40/3131	2
LOCATION:	AREA H	
ACTIVITY:		
LAYING TELECOM DUCTING IN ISLAND SITE SERVICE TRENCH.		
SPECIAL FEATURES:		
BUILDING H13 IN BACKGROUND.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
31/3/93	40/3131	3
LOCATION:	AREA H	
ACTIVITY:		
NEW SERVICE TRENCH FROM A203 - A200.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
31/3/93	40/3131	4
LOCATION:	AREA H	
ACTIVITY:		
NEW SERVICE TRENCH BESIDE A201 / 2.		
SPECIAL FEATURES:		

STEPS TO BRIDGE No. 17.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
31/3/93	40/3131	5
LOCATION:	AREA H	
ACTIVITY:		
NEW SERVICE TRENCH BESIDE BUILDING A201/2.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
31/3/93	40/3131	6



LOCATION:	AREA H	
ACTIVITY:		
NEW SERVICE TRENCH BESIDE A201/2.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
31/3/93	40/3131	7
LOCATION:	AREA H	
ACTIVITY:		
NEW SERVICE TRENCH BESIDE A201/2, VIEWED FROM TOP OF STEPS TO BRIDGE No. 17.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
31/3/93	40/3131	8
LOCATION:	AREA H	
ACTIVITY:		
NEW SERVICE TRENCH AT WEST SIDE OF BRIDGE No. 17.		
SPECIAL FEATURES:		
BRIDGE No. 17 HANDRAIL IN FOREGROUND.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
31/3/93	40/3131	9
LOCATION:	AREA H	
ACTIVITY:		
HOPPITS POOL - LOOKING NORTH.		
SPECIAL FEATURES:		
REMAINS OF GUNPOWDER BUILDINGS AND CANAL INLETS.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
31/3/93	40/3131	10
LOCATION:	AREA H	
ACTIVITY:		
NEW SERVICE TRENCH VIEWED FROM SOUTH SIDE OF H10.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
31/3/93	40/3131	11
LOCATION:	AREA H	
ACTIVITY:		
NEW SERVICE TRENCH.		

SPECIAL FEATURES:
HOPPITS POOL TO LEFT OF PICTURE.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
31/3/93	40/3131	12

LOCATION:	AREA H	
ACTIVITY:		
NEW SERVICE TRENCH - TOWARDS H6.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
31/3/93	40/3131	13
LOCATION:	AREA H	
ACTIVITY:		
NEW SERVICE TRENCH TOWARDS H10 (SOUTH EAST CORNER).		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
31/3/93	40/3131	14
LOCATION:	AREA H	
ACTIVITY:		
NEW SERVICE TRENCH BESIDES H10 (SOUTH EAST CORNER).		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
31/3/93	40/3131	15
LOCATION:	AREA H	
ACTIVITY:		
NEW SERVICE TRENCH FROM H10 - H17.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
31/3/93	40/3131	16
LOCATION:	AREA H	
ACTIVITY:		
SERVICE TRENCH AT H10 - WEST ELEVATION.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
31/3/93	40/3131	17
LOCATION:	AREA H	
ACTIVITY:		
FALLEN PLASTER IN BUILDING A203 LADIES TOILETS.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
31/3/93	40/3131	18


LOCATION:	AREA H	
ACTIVITY:		
SANITARY TOWEL DISPENSER AND BUNNY BURNER IN LADIES TOILET BUILDING A203.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIAATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
1/4/93	40/3131	19
LOCATION:	AREA M	
ACTIVITY:		
TYPICAL INTERNAL VIEW OF BUILDING L145.		
SPECIAL FEATURES:		
OVERHEAD HEATING PANELS BACKED WITH AMOSILE ASBESTOS.		



--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
1/4/93	40/3131	20
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L145 (INTERNAL).		
SPECIAL FEATURES:		
ENCLOSURE FOR ASBESTOS REMOVAL WORKS.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
1/4/93	40/3131	21
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L145 (INTERNAL).		
SPECIAL FEATURES:		
OVERHEAD HEATING PANELS.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
1/4/93	40/3131	22
LOCATION:	AREA M	
ACTIVITY:		
CORRIDOR IN BUILDING L145.		
SPECIAL FEATURES:		

ASBESTOS REMOVAL WORKS - INSPECTION IN PROGRESS.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
1/4/93	40/3131	23
LOCATION:	AREA M	
ACTIVITY:		
CORRIDOR IN BUILDING L145.		

SPECIAL FEATURES:
OVERHEAD HEATING PANELS - ASBESTOS BACKED.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
1/4/93	40/3131	25

LOCATION:	AREA M	
ACTIVITY:		
BUILDING L145 (INTERNAL).		
SPECIAL FEATURES:		
ENCLOSURE FOR ASBESTOS REMOVAL WORKS.		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
1/4/93	40/3131	26
LOCATION:	AREA M	
ACTIVITY:		
CORRIDOR IN BUILDING L145.		
SPECIAL FEATURES:		
1ST STAGE STRIP OUT IN PROGRESS.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
1/4/93	40/3131	27
LOCATION:	AREA M	
ACTIVITY:		
CORRIDOR IN BUILDING L145.		
SPECIAL FEATURES:		
SHOWS TOOLS USED FOR STRIP OUT WORKS.		



--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
2/4/93	40/3131	28
LOCATION:	AREA P	
ACTIVITY:		
BROKEN PIPE IN SERVICE TRENCH (DAMAGED BY ELECTRICITY COMPANY DURING INSTALLATION OF SUPPLY AT BUILDING A269).		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
2/4/93	40/3131	29
LOCATION:	AREA P	
ACTIVITY:		
BROKEN PIPE IN SERVICE TRENCH AT BUILDING A269 (DAMAGED BY ELECTRICITY COMPANY).		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
2/4/93	40/3131	30
LOCATION:	AREA P	
ACTIVITY:		
BROKEN PIPE IN SERVICE TRENCH AT BUILDING A269 (BROKEN BY		

ELECTRICITY COMPANY).
SPECIAL FEATURES:


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
2/4/93	40/3131	31

LOCATION:	AREA H	
ACTIVITY:		
NEW SERVICE TRENCH (SOUTH) HIGHBRIDGE STREET.		
SPECIAL FEATURES:		
DEVIATION OF TRENCH AROUND 'MILLSTONE'.		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
2/4/93	40/3131	32
LOCATION:	AREA S	
ACTIVITY:		
EXCAVATING FILLED CANAL WEST OF BUILDING 103.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
2/4/93	40/3131	33
LOCATION:	AREA B	
ACTIVITY:		
ASBESTOS COLLECTED FROM WASTE TIP REF.: 11036 ADJACENT TO BURNING GROUND.		
SPECIAL FEATURES:		
STOCKPILE OF BAGGED ASBESTOS TO RIGHT OF PICTURE.		




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
2/4/93	40/3131	34
LOCATION:	AREA S	
ACTIVITY:		
VIEW SOUTH FROM PRESS HOUSE TOWARDS BRIDGE No. 8.		
SPECIAL FEATURES:		
TIP CLEARANCE WORK.		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
2/4/93	40/3131	35
LOCATION:	AREAS	
ACTIVITY:		
VIEW TOWARDS PRESS HOUSE BUILDING 103.		
SPECIAL FEATURES:		

CLEARANCE OF TREES FOR ACCESS.



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
7/4/93	40/3131	36
LOCATION:	AREA H	
ACTIVITY:		
NEW SERVICE TRENCH (WATER MAIN) VALVE PIT CONSTRUCTION.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
7/4/93	40/3131	36A

LOCATION:	AREAS	
ACTIVITY:		
WASTE TIP SOUTH OF BURNING GROUND - REMOVAL OF WASTE.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD

DATE:

NEGATIVE REFERENCE:

FRAME REFERENCE:

7/4/93

41/3130

1

LOCATION:

AREA S

ACTIVITY:

BAGGED ASBESTOS IN SOIL WASTE LAID OUT ON SAMPLING SLAB.

SPECIAL FEATURES:

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
7/4/93	41/3130	2
LOCATION:	AREA S	
ACTIVITY:		
BAGGED ASBESTOS IN SOIL WASTE LAID OUT ON SAMPLING SLAB.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
7/4/93	41/3130	3
LOCATION:	AREA S	
ACTIVITY:		
BAGGED ASBESTOS AND SOIL WASTE STOCKPILED WEST OF BUILDING 83B.		
SPECIAL FEATURES:		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
7/4/93	41/3130	4
LOCATION:	AREA S	
ACTIVITY:		
NEWTONS POOL SLUICE VIEWED FROM WEST.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
7/4/93	41/3130	5
LOCATION:	AREAS	
ACTIVITY:		
NEWTONS POOL LOOKING TOWARDS BUILDING S34.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
7/4/93	41/3130	6

LOCATION:	AREAS	
ACTIVITY:		
NEWTONS POOL SLUICE VIEWED FROM WEST.		
SPECIAL FEATURES:		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
7/4/93	41/3130	7
LOCATION:	AREA S	
ACTIVITY:		
NEWTONS POOL VIEWED FROM WEST.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
7/4/93	41/3130	8
LOCATION:	AREA S	
ACTIVITY:		
NEWTONS POOL DISCHARGE INTO OLD RIVER LEA.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
7/4/93	41/3130	9
LOCATION:	AREA S	
ACTIVITY:		
NEWTONS POOL DISCHARGE INTO OLD RIVER LEA.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
7/4/93	41/3130	10
LOCATION:	AREA S	
ACTIVITY:		
VIEW OF BUILDING S34 & CAR PARK LOOKING EAST.		
SPECIAL FEATURES:		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
7/4/93	41/3130	11
LOCATION:	AREA S	
ACTIVITY:		
NEWTONS POOL LOOKING NORTH.		


SPECIAL FEATURES:
BUILDING S34 IN BACKGROUND.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
7/4/93	41/3130	12

LOCATION:	AREAS	
ACTIVITY:		
NEWTONS POOL LOOKING WEST TOWARDS OLD RIVER LEA.		
SPECIAL FEATURES:		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
7/4/93	41/3130	R
LOCATION:	AREA S	
ACTIVITY:		
VIEW OF BUILDING S34 & CAR PARK LOOKING WEST.		
SPECIAL FEATURES:		



**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
14/4/93	42/4690	1
LOCATION:	AREA H	
ACTIVITY:		
STRIPPING ASBESTOS OFF ROOF OF BUILDING H67 - LOOKING WEST.		
SPECIAL FEATURES:		
NOTE: BONDED TO ROOF DECK WITH BITUMEN.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
14/4/93	42/4690	2
LOCATION:	AREA H	
ACTIVITY:		
BUILDING H67 - STRIPPING ASBESTOS OFF OF ROOF - LOOKING WEST.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
14/4/93	42/4690	4
LOCATION:	AREA H	
ACTIVITY:		
BUILDING H67 - STRIPPING ASBESTOS OFF OF ROOF LOOKING SOUTH.		
SPECIAL FEATURES:		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
14/4/93	42/4690	5
LOCATION:	AREA H	
ACTIVITY:		
BUILDING H67 - STRIPPING ASBESTOS OFF OF ROOF - LOOKING EAST.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
14/4/93	42/4690	6
LOCATION:	AREA H	
ACTIVITY:		
BUILDING H67 - STRIPPING ASBESTOS OFF OF ROOF - LOOKING WEST.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
14/4/93	42/4690	7

LOCATION:	AREA H	
ACTIVITY:		
BUILDING H67 - WATER TANK HOUSING ON ROOF.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
14/4/93	42/4690	8
LOCATION:	AREA H	
ACTIVITY:		
ROOF OF BUILDING H67 - LOOKING NORTH TO BUILDING H68.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
14/4/93	42/4690	9
LOCATION:	AREA H	
ACTIVITY:		
LOOKING NORTH TO DISUSED LOCKS BEYOND BUILDING H70.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
19/4/93	42/4690	10
LOCATION:	AREA P	
ACTIVITY:		
EXCAVATION OF FOUNDATION TO FORMER BUILDING A250.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
19/4/93	42/4690	11
LOCATION:	AREA P	
ACTIVITY:		
EXCAVATION OF FOUNDATION TO FORMER BUILDING A250.		
SPECIAL FEATURES:		




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
19/4/93	42/4690	12
LOCATION:	AREA P	
ACTIVITY:		
EXCAVATION OF FOUNDATIONS IN PMLH AREA.		

SPECIAL FEATURES:
STEAM MAIN SUPPORT FOUNDATIONS IN FOREGROUND.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
19/4/93	42/4690	13

LOCATION:	AREA P	
ACTIVITY:		
EXCAVATION OF FOUNDATIONS IN PMLH AREA - LOOKING EAST.		
SPECIAL FEATURES:		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDICATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
19/4/93	42/4690	14
LOCATION:	AREA P	
ACTIVITY:		
VIEW WESTWARDS TO TENNIS COURTS AND MOD HOUSING BEYOND.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
19/4/93	42/4690	15
LOCATION:	AREA P	
ACTIVITY:		
EXCAVATION OF FOUNDATIONS IN PMLH AREA.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
19/4/93	42/4690	16
LOCATION:	AREA P	
ACTIVITY:		
REFURBISHMENT OF BUILDING A269 - LOOKING EAST.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
19/4/93	42/4690	17
LOCATION:	AREA P	
ACTIVITY:		
EXCAVATION OF FOUNDATIONS IN PMLH AREA.		
SPECIAL FEATURES:		



<b>FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD</b>		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
19/4/93	42/4690	18
LOCATION:	AREA P	
ACTIVITY:		
VIEW LOOKING SOUTH ACROSS AREA P TOWARDS TENNIS COURTS.		



SPECIAL FEATURES:
<p>AREA ZONED OFF FOR CONTRACTORS REFURBISHING BUILDING A269/A268.</p>

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
19/4/93	42/4690	19

LOCATION:	AREA P	
ACTIVITY:		
BRIDGE No. 1 - CONSULTANT CARRYING OUT BRIDGE ASSESSMENT.		
SPECIAL FEATURES:		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
19/4/93	42/4690	20
LOCATION:	AREA H	
ACTIVITY:		
VIEW FROM BUILDING A203 TOWARDS BUILDING H12.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
19/4/93	42/4690	21
LOCATION:	AREA H	
ACTIVITY:		
VIEW FROM BUILDING A203 OVER AREA H, TOWARDS BUILDING H16.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
19/4/93	42/4690	22
LOCATION:	AREA H	
ACTIVITY:		
STRIPPING ASBESTOS ROOFING FROM BUILDING H66.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
19/4/93	42/4690	23
LOCATION:	AREA P	
ACTIVITY:		
WASTE MATERIAL STOCKPILED ON A219 CAR PARK.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
19/4/93	42/4690	24
LOCATION:	AREA H	
ACTIVITY:		
WASHING DOWN ROAD SWEEPER BY BUILDING H13.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
19/4/93	42/4690	25



LOCATION:	AREA M	
ACTIVITY:		
ASBESTOS LAGGED HEATING PANELS PRIOR TO WRAPPING - FROM BUILDING L145.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
19/4/93	42/4690	26
LOCATION:	AREA M	
ACTIVITY:		
ASBESTOS LAGGED HEATING PANELS WRAPPED FOR DISPOSAL (BUILDING L145).		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
19/4/93	42/4690	27
LOCATION:	AREA M	
ACTIVITY:		
ASBESTOS COVERED HEATERS - SEALED (BUILDING L145).		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
22/4/93	42/4690	28
LOCATION:	AREA H	
ACTIVITY:		
EXISTING SERVICES IN NEW SERVICES TRENCH - AREA H.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
22/4/93	42/4690	29
LOCATION:	AREA H	
ACTIVITY:		
EXISTING SERVICES IN NEW SERVICES TRENCH - AREA H.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
22/4/93	42/4690	30
LOCATION:	AREA H	
ACTIVITY:		
EXISTING SERVICES IN NEW SERVICES TRENCH - AREA H.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
22/4/93	42/4690	31

LOCATION:	AREA H	
ACTIVITY:		
EXISTING SERVICES IN NEW SERVICES TRENCH - AREA H.		
SPECIAL FEATURES:		




**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
22/4/93	42/4690	32
LOCATION:	AREA H	
ACTIVITY:		
TAPPING OFF EXISTING WATER MAINS.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
22/4/93	42/4690	33
LOCATION:	AREA H	
ACTIVITY:		
TAPPING OFF EXISTING WATER MAINS.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
22/4/93	42/4690	34
LOCATION:	AREA S	
ACTIVITY:		
SAMPLING OF BAGGED ASBESTOS CONTAMINATED SOILS - ON SAMPLING SLAB.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
22/4/93	42/4690	35
LOCATION:	AREA S	
ACTIVITY:		
SAMPLING OF BAGGED ASBESTOS CONTAMINATED SOILS ON - SAMPLING SLAB.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
22/4/93	42/4690	36
LOCATION:	AREA S	
ACTIVITY:		
SAMPLING OF BAGGED ASBESTOS CONTAMINATED SOILS ON -		

SAMPLING SLAB.
SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
22/4/93	42/4690	37

LOCATION:	AREAS	
ACTIVITY:		
SAMPLING OF BAGGED ASBESTOS CONTAMINATED SOILS - ON SAMPLING SLAB.		
SPECIAL FEATURES:		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
23/4/93	43/4689	1
LOCATION:	AREA S	
ACTIVITY:		
STEAM MAIN FOUNDATION BASE NORTH OF BUILDING L128.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
23/4/93	43/4689	2
LOCATION:	AREA S	
ACTIVITY:		
STEAM MAIN FOUNDATION BASE NORTH OF BUILDING L128.		
SPECIAL FEATURES:		


--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
23/4/93	43/4689	3
LOCATION:	AREA H	
ACTIVITY:		
BUILDING H67 - ASBESTOS SHEETS ON ROOF.		
SPECIAL FEATURES:		
NOTE BITUMEN BONDED TO ROOF.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
23/4/93	43/4689	4
LOCATION:	AREA H	
ACTIVITY:		
BUILDING H67 - ASBESTOS SHEET REMOVAL FROM ROOF IN PROGRESS.		
SPECIAL FEATURES:		

NOTE: SHEETS BITUMEN BONDED TO ROOF.



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
23/4/93	43/4689	5
LOCATION:	AREA H	
ACTIVITY:		
BUILDING H67 - ASBESTOS SHEET REMOVAL FROM ROOF.		

SPECIAL FEATURES:
NOTE: SHEETS BITUMEN BONDED TO ROOF.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
26/4/93	43/4689	6

LOCATION:	AREA H	
ACTIVITY:		
BUILDING H67 - DECONTAMINATION BY WASHING OF LIGHT FITTINGS.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
26/4/93	43/4689	7
LOCATION:	AREA H	
ACTIVITY:		
BUILDING H67 - DECONTAMINATION BY WASHING OF LIGHT FITTINGS.		
SPECIAL FEATURES:		



--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/4/93	43/4689	8
LOCATION:	AREA P	
ACTIVITY:		
WOOD CHIPPING IN PROGRESS.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
28/4/93	43/4689	9
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L145 - DECONTAMINATION BY WASHING OF LIGHT FITTINGS.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
28/4/93	43/4689	10
LOCATION:	AREA M	
ACTIVITY:		
SEALED ASBESTOS COVERED HEATERS IN SKIP AWAITING REMOVAL.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
28/4/93	43/4689	11
LOCATION:	AREA M	
ACTIVITY:		
EAST ELEVATION OF BUILDING L145 - STRIPPING OUT IN PROGRESS.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
28/4/93	43/4689	12


LOCATION:	AREA L	
ACTIVITY:		
WATER BOWSER IN ACTION.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
28/4/93	43/4689	13
LOCATION:	AREA S	
ACTIVITY:		
EXCAVATION OF TIP REF.: 11036 - LOOKING WEST.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
28/4/93	43/4689	14
LOCATION:	AREA S	
ACTIVITY:		
EXCAVATION OF TIP REF.: 11036 - LOOKING SOUTH.		
SPECIAL FEATURES:		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
28/4/93	43/4689	15
LOCATION:	AREA S	
ACTIVITY:		
EXCAVATION OF TIP REF.: 11036 - LOOKING SOUTH.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
28/4/93	43/4689	16
LOCATION:	AREA S	
ACTIVITY:		
BAGGED ASBESTOS ON WASTE TIP REF.: 11032 - WITH EXCAVATION OF WASTE TIP REF.: 11036 IN FOREGROUND.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
28/4/93	43/4689	17
LOCATION:	AREA N	
ACTIVITY:		
REMOVAL OF TRANSFORMERS FROM BUILDING S2 IN PROGRESS AT NEW		

HILL.
SPECIAL FEATURES:


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
28/4/93	43/4689	18

LOCATION:	AREA N	
ACTIVITY:		
REMOVAL OF TRANSFORMERS FROM BUILDING S2 IN PROGRESS AT NEW HILL.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
28/4/93	43/4689	19
LOCATION:	AREA H	
ACTIVITY:		
BUILDING H67 - REMOVAL OF PARQUET FLOORING IN PROGRESS.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
28/4/93	43/4689	20
LOCATION:	AREA H	
ACTIVITY:		
BUILDING H67 - REMOVAL OF PARQUET FLOORING IN PROGRESS.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
28/4/93	43/4689	21
LOCATION:	AREA H	
ACTIVITY:		
BUILDING H67 - REMOVAL OF PARQUET FLOORING IN PROGRESS.		
SPECIAL FEATURES:		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
28/4/93	43/4689	22
LOCATION:	AREA H	
ACTIVITY:		
BUILDING H67 - EXPOSED CEILING TIMBERS IN CORRIDOR.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
28/4/93	43/4689	23
LOCATION:	AREA H	
ACTIVITY:		
BUILDING H67 - SHOWING TEST EQUIPMENT.		

SPECIAL FEATURES:


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
28/4/93	43/4689	24

LOCATION:	AREA H	
ACTIVITY:		
BUILDING H67 - ASBESTOS BOARDS STACKED ON ROOF.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
28/4/93	43/4689	25
LOCATION:	AREA H	
ACTIVITY:		
BUILDING H67 - ASBESTOS BOARDS STACKED ON ROOF.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
28/4/93	43/4689	26
LOCATION:	AREA H	
ACTIVITY:		
BUILDING H67 - LIFTING OF ASBESTOS BOARDS ON ROOF.		
SPECIAL FEATURES:		
NOTE: SHEETS BITUMEN BONDED TO ROOF.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
28/4/93	43/4689	27
LOCATION:	AREA P	
ACTIVITY:		
BUILDING A269 - SCAFFOLD AROUND EAST FACE.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
28/4/93	43/4689	28
LOCATION:	AREA P	
ACTIVITY:		
BUILDING A269 - SCAFFOLD AROUND EAST FACE.		
SPECIAL FEATURES:		




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
28/4/93	43/4689	29
LOCATION:	AREA P	
ACTIVITY:		
BUILDING A269 - SCAFFOLD AROUND EAST FACE.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
30/4/93	43/4689	30

LOCATION:	AREA H	
ACTIVITY:		
ARCHAEOLOGICAL EXCAVATION BELOW FORMER BUILDING A292.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
30/4/93	43/4689	31
LOCATION:	AREA H	
ACTIVITY:		
ARCHAEOLOGICAL EXCAVATION BELOW FORMER BUILDING A292.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
1/5/93	43/4689	32
LOCATION:	AREA B	
ACTIVITY:		
WASTE MATERIAL IN BURNING GROUND AWAITING 'HEAT TREATMENT'.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
1/5/93	43/4689	33
LOCATION:	AREA B	
ACTIVITY:		
WASTE MATERIAL IN BURNING GROUND UNDERGOING 'HEAT TREATMENT'.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
1/5/93	43/4689	34
LOCATION:	AREA B	
ACTIVITY:		
WASTE MATERIAL IN BURNING GROUND UNDERGOING 'HEAT TREATMENT'.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
1/5/93	43/4689	35
LOCATION:	AREA B	
ACTIVITY:		
WASTE MATERIAL IN BURNING GROUND SMOULDERING AFTER 'HEAT		



TREATMENT:
SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
5/5/93	43/4689	36

LOCATION:	AREA M	
ACTIVITY:		
EXCAVATION OF MILLHEAD STREAM BANK IN CORDITE CONTAMINATED AREA.		
SPECIAL FEATURES:		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**


DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
5/5/93	43/4689	36A
LOCATION:	AREA T	
ACTIVITY:		
VIEW OF WASTE TIP REF.: 11013.		
SPECIAL FEATURES:		





--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
5/5/93	44/4691	2
LOCATION:	AREA M	
ACTIVITY:		
WIRE CAGES FOR GABION.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
5/5/93	44/4691	3
LOCATION:	AREA M	
ACTIVITY:		
VIEW OF A FILLED GABION.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
5/5/93	44/4691	4
LOCATION:	AREA M	
ACTIVITY:		
THE FILLING OF GABION IN PROGRESS.		
SPECIAL FEATURES:		




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
6/5/93	44/4691	5
LOCATION:	AREA P	
ACTIVITY:		
INSTALLATION OF BORE HOLE SOUTH OF BUILDING A250.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
6/5/93	44/4691	6

LOCATION:	AREA P	
ACTIVITY:		
INSTALLATION OF BORE HOLE SOUTH OF BUILDING A250.		
SPECIAL FEATURES:		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
6/5/93	44/4691	7
LOCATION:	AREA P	
ACTIVITY:		
INSTALLATION OF BORE HOLE SOUTH OF BUILDING A250.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
6/5/93	44/4691	8
LOCATION:	AREA P	
ACTIVITY:		
INSTALLATION OF BORE HOLE SOUTH OF BUILDING A250.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
6/5/93	44/4691	9
LOCATION:	AREA P	
ACTIVITY:		
INSTALLATION OF BORE HOLE SOUTH OF BUILDING A250.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
6/5/93	44/4691	10
LOCATION:	AREA H	
ACTIVITY:		
EXPOSED FOUNDATION OF BUILDING A211 BELOW BUILDING A292.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
6/5/93	44/4691	11
LOCATION:	AREA H	
ACTIVITY:		
EXPOSED FOUNDATION OF BUILDING A211 BELOW BUILDING A292.		



SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
6/5/93	44/4691	12

LOCATION:	AREA H	
ACTIVITY:		
LOADING SPECIAL WASTE ON H19 AREA.		
SPECIAL FEATURES:		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
6/5/93	44/4691	13
LOCATION:	AREA H	
ACTIVITY:		
BUILDING H25 LOOKING SOUTH WEST.		
SPECIAL FEATURES:		




**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAY '93	45/4945	1
LOCATION:	AREA	
ACTIVITY:		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAY '93	45/4945	2
LOCATION:	AREA M	
ACTIVITY:		
RECONSTRUCTION OF RIVER WALL USING STONE FILLED GABIONS.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAY '93	45/4945	3
LOCATION:	AREA M	
ACTIVITY:		
RECONSTRUCTION OF RIVER WALL USING STONE FILLED GABIONS.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAY '93	45/4945	4
LOCATION:	AREA M	
ACTIVITY:		
RECONSTRUCTION OF RIVER WALL USING STONE FILLED GABIONS.		
SPECIAL FEATURES:		




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAY '93	45/4945	5
LOCATION:	AREA M	
ACTIVITY:		
RECONSTRUCTION OF RIVER WALL USING STONE FILLED GABIONS.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAY '93	45/4945	10

LOCATION:	AREA H	
ACTIVITY:		
WEST ELEVATION OF BUILDING A200 - WALTON HOUSE.		
SPECIAL FEATURES:		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAY '93	45/4945	11
LOCATION:	AREA P	
ACTIVITY:		
BOREHOLE RIG.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAY '93	45/4945	12
LOCATION:	AREA P	
ACTIVITY:		
TRIAL PIT EXCAVATION IN PROGRESS PRIOR TO SAMPLING.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
MAY '93	45/4945	R
LOCATION:	AREA M	
ACTIVITY:		
BLUE ASBESTOS IN SIDE OF RIVER BANK EXCAVATION.		
SPECIAL FEATURES:		







--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/5/93	46/5730	2
LOCATION:	AREA H	
ACTIVITY:		
EAST ELEVATION OF BUILDING H25.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/5/93	46/5730	3
LOCATION:	AREA P	
ACTIVITY:		
SAMPLE FROM INSIDE DRAIN PIPE IN EXCAVATED CANAL.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/5/93	46/5730	4
LOCATION:	AREA P	
ACTIVITY:		
SAMPLE OF SOOT FROM EXCAVATED CANAL.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
13/5/93	46/5730	5
LOCATION:	AREA P	
ACTIVITY:		
LOCATION OF SAMPLES TAKEN IN EXCAVATED CANAL.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
13/5/93	46/5730	6

LOCATION:	AREA P	
ACTIVITY:		
LOCATION OF SAMPLE TAKEN FROM EXCAVATED CANAL.		
SPECIAL FEATURES:		


**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
14/5/93	46/5730	7
LOCATION:	AREA P	
ACTIVITY:		
SAW PIT EXCAVATION.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
14/5/93	46/5730	8
LOCATION:	AREA P	
ACTIVITY:		
SAW PIT EXCAVATION.		
SPECIAL FEATURES:		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
17/5/93	46/5730	9
LOCATION:	AREA M	
ACTIVITY:		
ASBESTOS CONTAMINATION IN CANAL EXCAVATION.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
17/5/93	46/5730	10
LOCATION:	AREA M	
ACTIVITY:		
ASBESTOS CONTAMINATION IN CANAL EXCAVATION.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
17/5/93	46/5730	11
LOCATION:	AREA M	
ACTIVITY:		
ASBESTOS CONTAMINATION IN CANAL EXCAVATION.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
17/5/93	46/5730	12

LOCATION:	AREA M	
ACTIVITY:		
ASBESTOS CONTAMINATION IN CANAL EXCAVATION.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
17/5/93	46/5730	R
LOCATION:	AREA M	
ACTIVITY:		
CANAL EXCAVATION LOOKING EAST IN CORDITE CONTAMINATED AREA.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD

DATE:

NEGATIVE REFERENCE:

FRAME REFERENCE:

17/5/93

47/5729

1

LOCATION:

AREA M

ACTIVITY:


CORDITE DISCOVERED IN CANAL EXCAVATION.

SPECIAL FEATURES:



--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
17/5/93	47/5729	2
LOCATION:	AREA M	
ACTIVITY:		
RETRIEVING CORDITE FROM CANAL EXCAVATION.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
17/5/93	47/5729	3
LOCATION:	AREA M	
ACTIVITY:		
RETRIEVING CORDITE FROM CANAL EXCAVATION.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
17/5/93	47/5729	4
LOCATION:	AREA M	
ACTIVITY:		
REMOVAL OF TREE STUMP IN CORDITE CONTAMINATED AREA.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
17/5/93	47/5729	5
LOCATION:	AREA M	
ACTIVITY:		
REMOVAL OF TREE STUMP IN CORDITE CONTAMINATED AREA.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
17/5/93	47/5729	6

LOCATION:	AREA M	
ACTIVITY:		
REMOVED TREE STUMP IN CORDITE CONTAMINATED AREA.		
SPECIAL FEATURES:		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
17/5/93	47/5729	7
LOCATION:	AREA M	
ACTIVITY:		
CORDITE FOUND IN REMOVED TREE STUMP EXCAVATION.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
17/5/93	47/5729	8
LOCATION:	AREA M	
ACTIVITY:		
CORDITE FINDS - DISPLAYED, FROM CORDITE CONTAMINATED AREA.		
SPECIAL FEATURES:		



--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
21/5/93	47/5729	9
LOCATION:	AREA M	
ACTIVITY:		
TRIAL PIT A IN CORDITE CONTAMINATED AREA.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
21/5/93	47/5729	10
LOCATION:	AREA M	
ACTIVITY:		
TRIAL PIT B IN CORDITE CONTAMINATED AREA.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
21/5/93	47/5729	11
LOCATION:	AREA M	
ACTIVITY:		
TRIAL PIT B IN CORDITE CONTAMINATED AREA.		

SPECIAL FEATURES:


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
21/5/93	47/5729	12

LOCATION:	AREA M	
ACTIVITY:		
TRIAL PIT C IN CORDITE CONTAMINATED AREA.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
21/5/93	47/5729	13
LOCATION:	AREA M	
ACTIVITY:		
TRIAL PIT D IN CORDITE CONTAMINATED AREA.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
21/5/93	47/5729	14
LOCATION:	AREA M	
ACTIVITY:		
TRIAL PIT E IN CORDITE CONTAMINATED AREA.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
21/5/93	47/5729	15
LOCATION:	AREA M	
ACTIVITY:		
TRIAL PIT F IN CORDITE CONTAMINATED AREA.		
SPECIAL FEATURES:		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
21/5/93	47/5729	16
LOCATION:	AREA M	
ACTIVITY:		
TRIAL PIT G IN CORDITE CONTAMINATED AREA.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
21/5/93	47/5729	17
LOCATION:	AREA M	
ACTIVITY:		
TRIAL PIT H IN CORDITE CONTAMINATED AREA.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
21/5/93	47/5729	18

LOCATION:	AREA H	
ACTIVITY:		
BUILDING H67 AFTER 'HEAT TREATMENT'.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
21/5/93	47/5729	19
LOCATION:	AREA H	
ACTIVITY:		
WEST END OF BUILDING H67 AFTER 'HEAT TREATMENT' - LOOKING SOUTH.		
SPECIAL FEATURES:		
TARPULINS DRAPED OVER FENCE TO INTERCEPT FLYING DEBRIS.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
21/5/93	47/5729	20
LOCATION:	AREA H	
ACTIVITY:		
WEST END OF BUILDING H67 AFTER 'HEAT TREATMENT' - LOOKING NORTH.		
SPECIAL FEATURES:		
TARPAULINS DRAPED OVER FENCE TO INTERCEPT FLYING DEBRIS.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
21/5/93	47/5729	21
LOCATION:	AREA H	
ACTIVITY:		
BUILDING H67 - CONTAMINATED METALWORK READY FOR 'HEAT TREATMENT'.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
21/5/93	47/5729	22
LOCATION:	AREA H	
ACTIVITY:		
BUILDING H67 - CONTAMINATED METALWORK READY FOR 'HEAT TREATMENT'.		
SPECIAL FEATURES:		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
21/5/93	47/5729	23
LOCATION:	AREA H	
ACTIVITY:		
'HEAT TREATMENT' OF BUILDING H67 - LOOKING NORTH.		

SPECIAL FEATURES:


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
21/5/93	47/5729	24

LOCATION:	AREA H	
ACTIVITY:		
'HEAT TREATMENT' OF BUILDING H67 - LOOKING NORTH.		
SPECIAL FEATURES:		
TARPAULINS DRAPED OVER FENCE TO INTERCEPT FLYING DEBRIS.		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
21/5/93	47/5729	25
LOCATION:	AREA H	
ACTIVITY:		
'HEAT TREATMENT' OF BUILDING H67 - LOOKING NORTH.		
SPECIAL FEATURES:		
TARPAULINS DRAPED OVER FENCE TO INTERCEPT FLYING DEBRIS.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
21/5/93	47/5729	26
LOCATION:	AREA H	
ACTIVITY:		
'HEAT TREATMENT' OF BUILDING H67 - LOOKING NORTH.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
21/5/93	47/5729	27
LOCATION:	AREA H	
ACTIVITY:		
'HEAT TREATMENT' OF BUILDING H67 - LOOKING NORTH.		
SPECIAL FEATURES:		
TARPAULINS DRAPED OVER FENCE TO INTERCEPT FLYING DEBRIS.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
21/5/93	47/5729	28
LOCATION:	AREA H	
ACTIVITY:		
BUILDING H67 AFTER 'HEAT TREATMENT' LOOKING SOUTH WEST.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
21/5/93	47/5729	29
LOCATION:	AREA H	
ACTIVITY:		
'HEAT TREATMENT' OF BUILDING H67 IN PROGRESS.		



SPECIAL FEATURES:


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
21/5/93	47/5729	30

LOCATION:	AREAS	
ACTIVITY:		
BRIDGE No. 8 - HOLE IN DECK REQUIRED BY BRIDGE CONSULTANT.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
24/5/93	47/5729	31
LOCATION:	AREA M	
ACTIVITY:		
CANAL TRIAL PIT 1 IN CORDITE CONTAMINATED AREA.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
24/5/93	47/5729	32
LOCATION:	AREA M	
ACTIVITY:		
CANAL TRIAL PIT 1 IN CORDITE CONTAMINATED AREA.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
24/5/93	47/5729	33
LOCATION:	AREA M	
ACTIVITY:		
CANAL TRIAL PIT 2 IN CORDITE CONTAMINATED AREA.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
24/5/93	47/5729	34
LOCATION:	AREA M	
ACTIVITY:		
CANAL TRIAL PIT 3 IN CORDITE CONTAMINATED AREA.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
24/5/93	47/5729	35
LOCATION:	AREA M	
ACTIVITY:		
CANAL TRIAL PIT 3 IN CORDITE CONTAMINATED AREA.		


SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
24/5/93	47/5729	36



LOCATION:	AREA M	
ACTIVITY:		
CANAL TRIAL PIT 3 IN CORDITE CONTAMINATED AREA.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
24/5/93	47/5729	37
LOCATION:	AREA M	
ACTIVITY:		
CANAL TRIAL PIT 4 IN CORDITE CONTAMINATED AREA.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
24/5/93	48/5898	1
LOCATION:	AREA M	
ACTIVITY:		
CANAL TRIAL PIT 4 IN CORDITE CONTAMINATED AREA.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
25/5/93	48/5898	2
LOCATION:	AREA M	
ACTIVITY:		
EXCAVATION OF CANAL IN CORDITE CONTAMINATED AREA.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
25/5/93	48/5898	3
LOCATION:	AREA M	
ACTIVITY:		
EXCAVATION OF CANAL IN CORDITE CONTAMINATED AREA.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
25/5/93	48/5898	4
LOCATION:	AREA M	
ACTIVITY:		
TREE STUMP REMOVED FROM CANAL IN CORDITE CONTAMINATED AREA.		
SPECIAL FEATURES:		

TIMBER PILE PROTRUDING FROM TREE STUMP.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
25/5/93	48/5898	5
LOCATION:	AREA M	
ACTIVITY:		
TREE STUMP REMOVED FROM CANAL IN CORDITE CONTAMINATED AREA.		



SPECIAL FEATURES:
TIMBER PILE PROTRUDING FROM TREE STUMP.


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
25/5/93	48/5898	6

LOCATION:	AREA M	
ACTIVITY:		
TREE STUMP REMOVED FROM CANAL EXCAVATION IN CORDITE CONTAMINATED AREA.		
SPECIAL FEATURES:		
TIMBER PILE PROTRUDING FROM TREE STUMP.		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
25/5/93	48/5898	7
LOCATION:	AREA P	
ACTIVITY:		
BUILDING A250 - LOOKING SOUTH WEST.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
25/5/93	48/5898	8
LOCATION:	AREA P	
ACTIVITY:		
BUILDING A250 - LOOKING SOUTH EAST.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
25/5/93	48/5898	9
LOCATION:	AREA P	
ACTIVITY:		
EAST ELEVATION OF BUILDING A230 - TENNIS HUT.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
25/5/93	48/5898	10
LOCATION:	AREA P	
ACTIVITY:		
WEST ELEVATION OF BUILDING A230 - TENNIS HUT.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
25/5/93	48/5898	11
LOCATION:	AREA P	
ACTIVITY:		
BASE SLAB OF BUILDING A213.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
25/5/93	48/5898	12



LOCATION:	AREA P	
ACTIVITY:		
NORTH ELEVATION OF BUILDING A234.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
25/5/93	48/5898	13
LOCATION:	AREA P	
ACTIVITY:		
NORTH ELEVATION OF BUILDING A232.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
25/5/93	48/5898	14
LOCATION:	AREA P	
ACTIVITY:		
NORTH ELEVATION OF BUILDING A231.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
25/5/93	48/5898	15
LOCATION:	AREA P	
ACTIVITY:		
NORTH ELEVATION OF BUILDING A231.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
25/5/93	48/5898	16
LOCATION:	AREA P	
ACTIVITY:		
NORTH ELEVATION OF BUILDING A230.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
25/5/93	48/5898	18
LOCATION:	AREA H	
ACTIVITY:		
SUSPECTED CONTAMINATED PIPEWORK FROM BUILDING H67 -		

(RETURNED TO BUILDING FOR 'HEAT TREATMENT').

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/5/93	48/5898	20


LOCATION:	AREA H	
ACTIVITY:		
EXCAVATION FOR NEW DRAIN NORTH OF BUILDING A200.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/5/93	48/5898	21
LOCATION:	AREA H	
ACTIVITY:		
TRAP DOOR IN FLOOR OF BUILDING A201.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/5/93	48/5898	22
LOCATION:	AREA N	
ACTIVITY:		
BUILDING S16 - EXCAVATION OF TRIAL TRENCH IN MOUND IN PROGRESS.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/5/93	48/5898	23
LOCATION:	AREA S	
ACTIVITY:		
EXPOSED FOUNDATIONS OF BUILDING 63.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/5/93	48/5898	24
LOCATION:	AREA S	
ACTIVITY:		
EXPOSED FOUNDATIONS OF BUILDING 63.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/5/93	48/5898	25
LOCATION:	AREA N	
ACTIVITY:		
BUILDING S16 - VIEW OF TRIAL TRENCH IN MOUND.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/5/93	48/5898	26


LOCATION:	AREA N	
ACTIVITY:		
BUILDING S16 - EXCAVATION OF TRIAL TRENCH IN PROGRESS.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/5/93	48/5898	27
LOCATION:	AREA N	
ACTIVITY:		
BUILDING S16 - WASTE TIP ADJACENT TO EAST SIDE OF MOUND.		
SPECIAL FEATURES:		



--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/5/93	48/5898	28
LOCATION:	AREA N	
ACTIVITY:		
BUILDING S16 - EXCAVATION OF TRIAL TRENCH IN NORTH FACE OF MOUND IN PROGRESS.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/5/93	48/5898	29
LOCATION:	AREA N	
ACTIVITY:		
BUILDING S16 - EXCAVATION OF TRIAL TRENCH IN PROGRESS ON NORTH SIDE OF MOUND.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/5/93	48/5898	30
LOCATION:	AREA S	
ACTIVITY:		
REMAINS OF BUILDING 46 FOUNDATION.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/5/93	48/5898	31
LOCATION:	AREA S	
ACTIVITY:		
REMAINS OF BUILDING 46 FOUNDATION.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/5/93	48/5898	32

LOCATION:	AREA H	
ACTIVITY:		
DRAIN LAYING IN PROGRESS NORTH OF BUILDING A200.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/5/93	48/5898	33
LOCATION:	AREA P	
ACTIVITY:		
BUILDING A222 LOOKING NORTH WEST.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/5/93	48/5898	34
LOCATION:	AREA P	
ACTIVITY:		
SOUTH ELEVATION OF BUILDING A234.		
SPECIAL FEATURES:		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/5/93	48/5898	35
LOCATION:	AREA P	
ACTIVITY:		
SOUTH ELEVATION OF BUILDING A231.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/5/93	48/5898	36
LOCATION:	AREA P	
ACTIVITY:		
SOUTH ELEVATION OF BUILDING A232.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/5/93	48/5898	R
LOCATION:	AREA P	
ACTIVITY:		
SOUTH ELEVATION OF BUILDING A230.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
28/5/93	49/5897	1
LOCATION:	AREA S	
ACTIVITY:		
BUILDING S36 AT NEWTONS POOL.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
28/5/93	49/5897	2
LOCATION:	AREA S	
ACTIVITY:		
BUILDING S36 AT NEWTONS POOL.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
28/5/93	49/5897	3
LOCATION:	AREA S	
ACTIVITY:		
BUILDING S50 AT NEWTONS POOL.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
28/5/93	49/5897	4
LOCATION:	AREA S	
ACTIVITY:		
BUILDING S50 AT NEWTONS POOL.		
SPECIAL FEATURES:		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
28/5/93	49/5897	5
LOCATION:	AREA S	
ACTIVITY:		
VIEW LOOKING TOWARDS TRAVERSE AT NEWTONS POOL.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
28/5/93	49/5897	6

LOCATION:	AREA S	
ACTIVITY:		
VIEW LOOKING TOWARDS MAIN ENTRANCE TO BUILDING S34.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
28/5/93	49/5897	7
LOCATION:	AREA S	
ACTIVITY:		
VIEW TOWARDS BUILDING S38 AT NEWTONS POOL.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
28/5/93	49/5897	8
LOCATION:	AREA S	
ACTIVITY:		
VIEW LOOKING TOWARDS BUILDING S38 AT NEWTONS POOL.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
28/5/93	49/5897	9
LOCATION:	AREA S	
ACTIVITY:		
EAST ELEVATION OF BUILDING S34.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
28/5/93	49/5897	10
LOCATION:	AREA S	
ACTIVITY:		
BUILDING S34 LOOKING WEST AT NEWTONS POOL.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
28/5/93	49/5897	11
LOCATION:	AREA S	
ACTIVITY:		
VIEW LOOKING WEST FROM WALL AT NEWTONS POOL.		



SPECIAL FEATURES:


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
28/5/93	49/5897	12

LOCATION:	AREA H	
ACTIVITY:		
WEST ELEVATION OF BUILDING H71.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
28/5/93	49/5897	13
LOCATION:	AREA H	
ACTIVITY:		
BUILDING H71 IN FOREGROUND WITH BUILDING H10 BEYOND.		
SPECIAL FEATURES:		

--


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
28/5/93	49/5897	14
LOCATION:	AREA H	
ACTIVITY:		
EAST ELEVATION OF BUILDING H10.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
28/5/93	49/5897	15
LOCATION:	AREA H	
ACTIVITY:		
NORTH ELEVATION OF BUILDING H10.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
28/5/93	49/5897	16
LOCATION:	AREA H	
ACTIVITY:		
NORTH ELEVATION OF BUILDING H10.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
28/5/93	49/5897	17
LOCATION:	AREA H	
ACTIVITY:		
BUILDING H12 LOOKING FROM TOP OF MOUND.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
28/5/93	49/5897	18



LOCATION:	AREA H	
ACTIVITY:		
BUILDING H12 LOOKING NORTH WEST FROM TOP OF MOUND.		
SPECIAL FEATURES:		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
28/5/93	49/5897	19
LOCATION:	AREA H	
ACTIVITY:		
BUILDING H12 - LOOKING WEST.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
28/5/93	49/5897	20
LOCATION:	AREA H	
ACTIVITY:		
BUILDING H12 - LOOKING SOUTH AT MAIN ENTRANCE.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
28/5/93	49/5897	21
LOCATION:	AREA N	
ACTIVITY:		
WASTE TIP REF.: 11050 - EAST SIDE OF BUILDING S16.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
28/5/93	49/5897	22
LOCATION:	AREA N	
ACTIVITY:		
WASTE TIP REF.: 11050 - EAST SIDE OF BUILDING S16.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
28/5/93	49/5897	23
LOCATION:	AREA N	
ACTIVITY:		
WASTE TIP REF.: 11050 - EAST SIDE OF BUILDING S16.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
28/5/93	49/5897	24

LOCATION:	AREA N	
ACTIVITY:		
WASTE TIP REF.: 11050 - EAST SIDE OF BUILDING S16.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
28/5/93	49/5897	25
LOCATION:	AREA N	
ACTIVITY:		
WASTE TIP REF.: 11050 - EAST SIDE OF BUILDING S16.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
28/5/93	49/5897	26
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L147.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
28/5/93	49/5897	27
LOCATION:	AREA M	
ACTIVITY:		
EAST ELEVATION OF BUILDING L157.		
SPECIAL FEATURES:		
COVERED ASBESTOS SKIPS IN FOREGROUND.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
28/5/93	49/5897	28
LOCATION:	AREA M	
ACTIVITY:		
EAST ELEVATION OF BUILDING L145 AND BUILDING L148.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
28/5/93	49/5897	29
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L140 AMENITIES BLOCK.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
28/5/93	49/5897	30


LOCATION:	AREA M	
ACTIVITY:		
SOUTH ELEVATION OF BUILDING L140.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
28/5/93	49/5897	31
LOCATION:	AREA M	
ACTIVITY:		
DETERIORATION OF FLAT ROOF TO BUILDING L145.		
SPECIAL FEATURES:		



--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
28/5/93	49/5897	32
LOCATION:	AREA M	
ACTIVITY:		
DETERIORATION OF ROOF TO BUILDING L145.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
28/5/93	49/5897	33
LOCATION:	AREA M	
ACTIVITY:		
DETERIORATION OF FLAT ROOF TO BUILDING L145.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
28/5/93	49/5897	34
LOCATION:	AREA M	
ACTIVITY:		
DETERIORATION OF FLAT ROOF TO BUILDING L145.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
28/5/93	49/5897	35
LOCATION:	AREA M	
ACTIVITY:		
DETERIORATION OF FLAT ROOF TO BUILDING L145.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
28/5/93	49/5897	36

LOCATION:	AREA M	
ACTIVITY:		
NORTH ELEVATION OF BUILDING L145 EXTENSION.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
28/5/93	49/5897	36A
LOCATION:	AREA M	
ACTIVITY:		
SCREENING PLANT IN CORDITE CONTAMINATED AREA.		
SPECIAL FEATURES:		






FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
28/5/93	50/6287	1
LOCATION:	AREA S	
ACTIVITY:		
NEWTS RECOVERED FROM NEWTONS POOL PRIOR TO PUMP DOWN.		
SPECIAL FEATURES:		
PREPARATION FOR REMEDIATION.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
2/6/93	50/6287	3
LOCATION:	AREA M	
ACTIVITY:		
STRIP OUT WORKS - BUILDING L148.		
SPECIAL FEATURES:		
TYPE 'H' VACUUM USED IN MILL DECONTAMINATION.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
2/6/93	50/6287	4
LOCATION:	AREA M	
ACTIVITY:		
EXPOSING DRAIN RUN AT BUILDING L145.		
SPECIAL FEATURES:		
TRIAL EXPOSURE OF POTENTIALLY EXPLOSIVELY CONTAMINATED DRAINAGE.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
2/6/93	50/6287	5
LOCATION:	AREA M	
ACTIVITY:		
BROKEN CABLE DUCT COVER AT BUILDING L145.		
SPECIAL FEATURES:		

SITE HAZARD.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
2/6/93	50/6287	6
LOCATION:	AREA M	
ACTIVITY:		
REMOVAL OF CORDITE CONTAMINATED SOILS.		

SPECIAL FEATURES:
NATURE OF CORDITE CONTAMINANT IN SOIL STRUCTURE.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
2/6/93	50/6287	7

LOCATION:	AREA M	
ACTIVITY:		
REMOVAL OF CORDITE CONTAMINATED SOILS.		
SPECIAL FEATURES:		
NATURE OF CORDITE CONTAMINANT IN SOIL STRUCTURE.		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
2/6/93	50/6287	8
LOCATION:	AREA M	
ACTIVITY:		
REMOVAL OF CORDITE CONTAMINATED SOILS.		
SPECIAL FEATURES:		



--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
2/6/93	50/6287	9
LOCATION:	AREA M	
ACTIVITY:		
REMOVAL OF CORDITE CONTAMINATED SOILS.		
SPECIAL FEATURES:		
NATURE OF CORDITE CONTAMINANT IN SOIL STRUCTURE.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
2/6/93	50/6287	10
LOCATION:	AREA M	
ACTIVITY:		
CORDITE FOUND IN EXCAVATION.		
SPECIAL FEATURES:		
NATURE OF CORDITE CONTAMINANT IN SOIL STRUCTURE.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
3/6/93	50/6287	11
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L145 - EXPOSED DRAIN RUN LOOKING WEST.		
SPECIAL FEATURES:		

TRIAL RUN FOR REMOVAL OF EXPLOSIVELY CONTAMINATED DRAINAGE.

Empty rectangular box for notes or details.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
3/6/93	50/6287	12
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L145 - EXPOSED DRAIN RUN.		

SPECIAL FEATURES:
TRIAL RUN FOR REMOVAL OF EXPLOSIVELY CONTAMINATED DRAINAGE.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
3/6/93	50/6287	13

LOCATION:	AREA M	
ACTIVITY:		
BUILDING L145 - EXPOSED DRAIN RUN.		
SPECIAL FEATURES:		
TRIAL RUN FOR REMOVAL OF EXPLOSIVELY CONTAMINATED DRAINAGE.		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
3/6/93	50/6287	14
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L145 - EXPOSED DRAIN RUN.		
SPECIAL FEATURES:		
EXAMPLE OF POTENTIAL ZONE OF EXTERNAL CONTAMINATION VIA PIPE DAMAGE.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
3/6/93	50/6287	15
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L145 - EXPOSED DRAIN RUN.		
SPECIAL FEATURES:		
TRIAL RUN FOR REMOVAL OF EXPLOSIVELY CONTAMINATED DRAINAGE.		



--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
3/6/93	50/6287	16
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L145 - EXPOSED DRAIN RUN.		
SPECIAL FEATURES:		
TRIAL RUN FOR REMOVAL OF EXPLOSIVELY CONTAMINATED DRAINAGE.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
3/6/93	50/6287	17
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L145 - EXPOSED DRAIN RUN.		
SPECIAL FEATURES:		

TRIAL RUN FOR REMOVAL OF EXPLOSIVELY CONTAMINATED DRAINAGE.

Empty rectangular box for notes or details.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
3/6/93	50/6287	18
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L145 - EXPOSED DRAIN RUN.		

SPECIAL FEATURES:
TRIAL RUN FOR REMOVAL OF EXPLOSIVELY CONTAMINATED DRAINAGE.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
3/6/93	50/6287	19

LOCATION:	AREA M	
ACTIVITY:		
BUILDING L145 - EXPOSED DRAIN RUN.		
SPECIAL FEATURES:		
TRIAL RUN FOR REMOVAL OF EXPLOSIVELY CONTAMINATED DRAINAGE.		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
3/6/93	50/6287	20
LOCATION:	AREA L	
ACTIVITY:		
BUILDING L122 - NOTICE BOARD.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
3/6/93	50/6287	21
LOCATION:	AREA L	
ACTIVITY:		
BUILDING L122 - NOTICE BOARD.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
3/6/93	50/6287	22
LOCATION:	AREA H - ISLAND SITE	
ACTIVITY:		
BUILDING A203 - NEW CAVITY TRAY INSTALLATION AT 1ST FLOOR LEVEL.		
SPECIAL FEATURES:		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
3/6/93	50/6287	23
LOCATION:	AREA H - ISLAND SITE	
ACTIVITY:		
BUILDING A203 - NEW CAVITY TRAY INSTALLATION AT 1ST FLOOR LEVEL.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
3/6/93	50/6287	24
LOCATION:	AREA H - ISLAND SITE	
ACTIVITY:		
BUILDING A203 - NEW CAVITY TRAY INSTALLATION AT 1ST FLOOR		

LEVEL:
SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
3/6/93	50/6287	25


LOCATION:	AREA H - ISLAND SITE	
ACTIVITY:		
BUILDING A203 - VIEW OF NEW RAISED PARAPET WALL.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
3/6/93	51/7209	1
LOCATION:	AREA N	
ACTIVITY:		
MOUND OF S16.		
SPECIAL FEATURES:		
TRIAL TRENCHING OF MOUND.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
3/6/93	51/7209	2
LOCATION:	AREA N	
ACTIVITY:		
VIEW TOWARDS BUILDING S16 MOUND.		
SPECIAL FEATURES:		
TRIAL TRENCHING ON MOUND.		




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
3/6/93	51/7209	3
LOCATION:	AREA N	
ACTIVITY:		
VIEW TOWARDS BUILDING S16 MOUND.		
SPECIAL FEATURES:		
TRIAL TRENCHING OF MOUND.		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
3/6/93	51/7209	4
LOCATION:	AREA N	
ACTIVITY:		
BUILDING S16 - EXCAVATED MATERIAL FROM MOUND (SOUTH SIDE).		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
3/6/93	51/7209	5
LOCATION:	AREA N	
ACTIVITY:		
BUILDING S16 - VIEW OF SCRAPED AREA UNDER CONCRETE STRUCTURE.		

SPECIAL FEATURES:
SURFACE CLEARANCE UNDER STRUCTURE.


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
3/6/93	51/7209	6

LOCATION:	AREA N	
ACTIVITY:		
BUILDING S16 - EXCAVATED MATERIAL FROM MOUND - LOOKING WEST.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
3/6/93	51/7209	7
LOCATION:	AREA N	
ACTIVITY:		
STEAM PIPE FOUNDATION BASES ADJACENT TO BUILDING S16.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
3/6/93	51/7209	8
LOCATION:	AREA N	
ACTIVITY:		
STEAM PIPE FOUNDATION BASES ADJACENT TO BUILDING S16.		
SPECIAL FEATURES:		




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
3/6/93	51/7209	9
LOCATION:	AREA N	
ACTIVITY:		
VIEW LOOKING SOUTH WEST BY BUILDING S16.		
SPECIAL FEATURES:		
STRIPPING OF STEAM MAIN ROUTES.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
3/6/93	51/7209	10
LOCATION:	AREA B	
ACTIVITY:		
ASBESTOS FOUND IN SOIL AT WASTE TIP REF.: 11038.		
SPECIAL FEATURES:		



OLD ASBESTOS DUMP - FEATURING BROKEN POLYTHENE BAGS  
CONTAINING THE MATERIAL.



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
3/6/93	51/7209	11
LOCATION:	AREA B	
ACTIVITY:		
ASBESTOS FOUND IN SOIL AT TIP REF.: 11038.		

SPECIAL FEATURES:
OLD ASBESTOS DUMP - FEATURING BROKEN POLYTHENE BAGS CONTAINING THE MATERIAL.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
3/6/93	51/7209	12

LOCATION:	AREA B	
ACTIVITY:		
BAGGING OF ASBESTOS FOUND IN TIP REF.: 11038.		
SPECIAL FEATURES:		
WORK IN PROGRESS BY LICENSED ASBESTOS CONTRACTORS.		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
3/6/93	51/7209	13
LOCATION:	AREAM - SOUTH	
ACTIVITY:		
CONCRETE RUBBLE IN FILLED CANAL.		
SPECIAL FEATURES:		
HIGH WATER TABLE.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
3/6/93	51/7209	14
LOCATION:	AREA M - SOUTH	
ACTIVITY:		
CONCRETE RUBBLE IN FILLED CANAL.		
SPECIAL FEATURES:		
HIGH WATER TABLE.		




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
3/6/93	51/7209	15
LOCATION:	AREA M - SOUTH	
ACTIVITY:		
TYPICAL CANAL INFILL MATERIAL.		
SPECIAL FEATURES:		
NATURE OF INFILL (PARTICULARLY ASBESTOS).		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
3/6/93	51/7209	16
LOCATION:	AREA M - SOUTH	
ACTIVITY:		
CONCRETE RUBBLE IN FILLED CANAL.		
SPECIAL FEATURES:		

HIGH WATER TABLE.



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
3/6/93	51/7209	17
LOCATION:	AREA M - SOUTH	
ACTIVITY:		
REMOVAL OF CORDITE CONTAMINATED SOILS.		



SPECIAL FEATURES:
NEW 'GABION' WALL IN PLACE (BRIDGE No. 4 IN BACKGROUND).

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
3/6/93	51/7209	18

LOCATION:	AREA M - SOUTH	
ACTIVITY:		
REMOVAL OF CORDITE CONTAMINATED SOILS.		
SPECIAL FEATURES:		
NEW 'GABION' WALL IN PLACE (BRIDGE No. 4 IN BACKGROUND).		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
3/6/93	51/7209	19
LOCATION:	AREA M - SOUTH	
ACTIVITY:		
REMOVAL OF CORDITE CONTAMINATED SOILS.		
SPECIAL FEATURES:		
NEW 'GABION' WALL IN PLACE (BRIDGE No. 4 IN BACKGROUND).		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
3/6/93	51/7209	20
LOCATION:	AREA M - SOUTH	
ACTIVITY:		
REMOVAL OF CORDITE CONTAMINATED SOILS.		
SPECIAL FEATURES:		
ELECTRICITY CABLE RECOVERY FOR SCRAP RECEIPTS.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
3/6/93	51/7209	21
LOCATION:	AREA M - SOUTH	
ACTIVITY:		
REMOVAL OF CORDITE CONTAMINATED SOILS.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
3/6/93	51/7209	22
LOCATION:	AREA M - SOUTH	
ACTIVITY:		
TRYING TO RECOVER LOST TWO-WAY RADIO.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
3/6/93	51/7209	23
LOCATION:	AREA M - SOUTH	
ACTIVITY:		
TRYING TO RECOVER TWO-WAY RADIO.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
4/6/93	51/7209	24



LOCATION:	AREA M	
ACTIVITY:		
STEEL SCRAP BEING LOADED FOR DISPOSAL.		
SPECIAL FEATURES:		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
7/6/93	51/7209	25
LOCATION:	AREA P	
ACTIVITY:		
L.G.C. BOREHOLE SAMPLING.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
7/6/93	51/7209	26
LOCATION:	AREA H - ISLAND SITE	
ACTIVITY:		
BUILDING A203 - PARAPET WALL RAISED SHOWING NEW CAVITY TRAY AND DAMP PROOF COURSE.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
7/6/93	51/7209	27
LOCATION:	AREA H - ISLAND SITE	
ACTIVITY:		
BUILDING A203 - PARAPET WALL RAISED SHOWING NEW DAMP PROOF COURSE.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
7/6/93	51/7209	28
LOCATION:	AREA H - ISLAND SITE	
ACTIVITY:	BUILDING A203 - TEMPORARY PROTECTION TO PARAPET WALL.	
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
7/6/93	51/7209	29
LOCATION:	AREA H - ISLAND SITE	
ACTIVITY:		
BUILDING A203 - PARAPET WALL BEING RAISED.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
7/6/93	51/7209	30

LOCATION:	AREA H - ISLAND SITE	
ACTIVITY:		
BUILDING A203 - FINISHED RAISED PARAPET WALL.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
7/6/93	51/7209	31
LOCATION:	AREA H - ISLAND SITE	
ACTIVITY:		
CUT OUTS IN WALL TO TAKE NEW CAVITY TRAYS.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
7/6/93	51/7209	32
LOCATION:	AREA H - ISLAND SITE	
ACTIVITY:		
BUILDING A203 - FINISHED RAISED PARAPET WALL.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
8/6/93	51/7209	33
LOCATION:	AREA H - ISLAND SITE	
ACTIVITY:		
CUT OUTS IN BUILDING A203 - TO TAKE NEW CAVITY TRAYS.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
8/6/93	51/7209	34
LOCATION:	AREA P	
ACTIVITY:		
NORTH EASTERN ASPECT OF BUILDING A270.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
8/6/93	51/7209	35
LOCATION:	AREA P	
ACTIVITY:		
WEST ELEVATION OF BUILDING A270.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
8/6/93	51/7209	36

LOCATION:	AREA P	
ACTIVITY:		
NORTH ELEVATION OF BUILDING A250.		
SPECIAL FEATURES:		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
8/6/93	51/7209	R
LOCATION:	AREA P	
ACTIVITY:		
NORTH EASTERN ASPECT OF BUILDING A250.		
SPECIAL FEATURES:		






FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
8/6/93	52/8086	1
LOCATION:	AREA P	
ACTIVITY:		
EAST ELEVATION OF BUILDING A250.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
8/6/93	52/8086	2
LOCATION:	AREA P	
ACTIVITY:		
VIEW LOOKING NORTH WEST OF BUILDING A250.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
8/6/93	52/8086	3
LOCATION:	AREA P	
ACTIVITY:		
VIEW LOOKING NORTH EAST OF BUILDING A250.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
8/6/93	52/8086	4
LOCATION:	AREA P	
ACTIVITY:		
WEST ELEVATION OF BUILDING A250.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/6/93	52/8086	5
LOCATION:	AREA H - ISLAND SITE	
ACTIVITY:		
BUILDING A203 - INSTALLATION OF NEW CAVITY TRAYS.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
11/6/93	52/8086	10

LOCATION:	AREA M	
ACTIVITY:		
EXCAVATION OF CANAL IN CORDITE CONTAMINATED AREA.		
SPECIAL FEATURES:		



**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
11/6/93	52/8086	11
LOCATION:	AREA M	
ACTIVITY:		
EXCAVATION OF CANAL IN CORDITE CONTAMINATED AREA.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
14/6/93	52/8086	12
LOCATION:	AREA M	
ACTIVITY:		
EXCAVATION OF CANAL IN CORDITE CONTAMINATED AREA.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
14/6/93	52/8086	13
LOCATION:	AREA M	
ACTIVITY:		
VIEW OF CANAL IN CORDITE CONTAMINATED AREA.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
14/6/93	52/8086	14
LOCATION:	AREA M	
ACTIVITY:		
EXCAVATION OF CANAL IN CORDITE CONTAMINATED AREA.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
14/6/93	52/8086	15
LOCATION:	AREA M	
ACTIVITY:		
EXCAVATION OF CANAL IN CORDITE CONTAMINATED AREA.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
14/6/93	52/8086	16

LOCATION:	AREA M	
ACTIVITY:		
GENERAL SURFACE EXCAVATION IN CORDITE CONTAMINATED AREA.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
14/6/93	52/8086	17
LOCATION:	AREA M	
ACTIVITY:		
GENERAL SURFACE EXCAVATION IN CORDITE CONTAMINATED AREA.		
SPECIAL FEATURES:		



--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
14/6/93	52/8086	18
LOCATION:	AREA M	
ACTIVITY:		
GENERAL EXCAVATION IN PROGRESS IN CORDITE CONTAMINATED AREA.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
14/6/93	52/8086	19
LOCATION:	AREA M	
ACTIVITY:		
SCREENING PLANT IN CORDITE CONTAMINATED AREA.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
14/6/93	52/8086	20
LOCATION:	AREA M	
ACTIVITY:		
LORRY TRANSPORTING SCREENED CORDITE CONTAMINATED MATERIAL.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
14/6/93	52/8086	21
LOCATION:	AREA M	
ACTIVITY:		
LORRY TRANSPORTING SCREENED CORDITE CONTAMINATED MATERIAL.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
14/6/93	52/8086	22

LOCATION:	AREA M	
ACTIVITY:		
LORRY TIPPING SCREENED CORDITE CONTAMINATED MATERIAL.		
SPECIAL FEATURES:		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
14/6/93	52/8086	23
LOCATION:	AREA M	
ACTIVITY:		
LORRY TIPPING SCREENED CORDITE CONTAMINATED MATERIAL.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
14/6/93	52/8086	24
LOCATION:	AREA M	
ACTIVITY:		
CORDITE AND ASBESTOS FOUND IN EXCAVATION IN CORDITE CONTAMINATED AREA.		
SPECIAL FEATURES:		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
14/6/93	52/8086	R
LOCATION:	AREA M	
ACTIVITY:		
CORDITE FOUND IN EXCAVATION IN CORDITE CONTAMINATED AREA.		
SPECIAL FEATURES:		



**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
22/6/93	53/9803	1
LOCATION:	AREA M	
ACTIVITY:		
CUTTING DEAD ELECTRICITY CABLES IN CORDITE CONTAMINATED AREA.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
22/6/93	53/9803	2
LOCATION:	AREA M	
ACTIVITY:		
EXCAVATION OF CANAL IN CORDITE CONTAMINATED AREA.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
22/6/93	53/9803	3
LOCATION:	AREA M	
ACTIVITY:		
EXCAVATION OF CANAL AND UNCOVERING OF DEAD ELECTRICITY CABLES IN CORDITE CONTAMINATED AREA.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
22/6/93	53/9803	4
LOCATION:	AREA M	
ACTIVITY:		
EXCAVATION OF CANAL ADJACENT TO 'GABION' WALL IN CORDITE CONTAMINATED AREA.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
22/6/93	53/9803	5
LOCATION:	AREA M	
ACTIVITY:		
EXCAVATION OF CANAL ADJACENT TO 'GABION' WALL IN CORDITE		

CONTAMINATED AREA.
SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
22/6/93	53/9803	6



LOCATION:	AREA M	
ACTIVITY:		
VIEW LOOKING SOUTH WEST TOWARDS BUILDING A214 FROM CORDITE CONTAMINATED AREA.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
22/6/93	53/9803	7
LOCATION:	AREA M	
ACTIVITY:		
EXCAVATION NEAR FOOTBRIDGE IN CORDITE CONTAMINATED AREA.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
24/6/93	53/9803	8
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L145 - EXPOSED DRAIN RUN AFTER EXPLOSIVELY CONTAMINATED PIPEWORK HAS BEEN REMOVED.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
24/6/93	53/9803	9
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L145 - EXPOSED DRAIN RUN AFTER EXPLOSIVELY CONTAMINATED PIPEWORK HAS BEEN REMOVED.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
24/6/93	53/9803	11
LOCATION:	AREA P	
ACTIVITY:		
VIEW OF MAIN ENTRANCE IN POWDERMILL LANE.		
SPECIAL FEATURES:		

SECURITY CHECK IN PROGRESS.



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
26/6/93	53/9803	12
LOCATION:	AREA H	
ACTIVITY:		
CHLORINATION OF NEW WATER MAIN IN PROGRESS AT HIGHBRIDGE		

STREET.
SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
29/6/93	53/9803	13

LOCATION:	AREA H	
ACTIVITY:		
SAMPLING LOCATIONS ON WEST FACE OF H12 MOUND.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
29/6/93	53/9803	14
LOCATION:	AREA H	
ACTIVITY:		
SAMPLING LOCATIONS ON WEST FACE OF H12 MOUND.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
29/6/93	53/9803	15
LOCATION:	AREA H	
ACTIVITY:		
SAMPLING LOCATIONS ON H12 MOUND - LOOKING SOUTH.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
2/7/93	53/9803	21
LOCATION:	AREA M	
ACTIVITY:		
DE-WATERING OF CANAL IN CORDITE CONTAMINATED AREA.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
2/7/93	53/9803	22
LOCATION:	AREA M	
ACTIVITY:		
EXCAVATION OF CANAL BANKS IN CORDITE CONTAMINATED AREA - LOOKING EAST.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
2/7/93	53/9803	23
LOCATION:	AREA M	
ACTIVITY:		
EXCAVATION OF CANAL BANKS IN CORDITE CONTAMINATED AREA -		

LOOKING EAST.
SPECIAL FEATURES:
SCREENING PLANT IN BACKGROUND.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
2/7/93	53/9803	24

LOCATION:	AREA M	
ACTIVITY:		
LOADING SCREENING PLANT IN CORDITE CONTAMINATED AREA.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
2/7/93	53/9803	R
LOCATION:	AREA M	
ACTIVITY:		
EXCAVATION OF CANAL BANKS IN CORDITE CONTAMINATED AREA - LOOKING EAST.		
SPECIAL FEATURES:		






FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
2/7/93	54/9804	1
LOCATION:	AREA M	
ACTIVITY:		
WEST END OF EXCAVATED CANAL IN CORDITE CONTAMINATED AREA.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
2/7/93	54/9804	2
LOCATION:	AREA M	
ACTIVITY:		
EXCAVATION OF CANAL IN PROGRESS IN CORDITE CONTAMINATED AREA.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
2/7/93	54/9804	3
LOCATION:	AREA M	
ACTIVITY:		
EXCAVATION OF CANAL IN PROGRESS IN CORDITE CONTAMINATED AREA.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
2/7/93	54/9804	5
LOCATION:	AREA S	
ACTIVITY:		
BAGGING ASBESTOS ON WASTE TIP REF.: 11032.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
2/7/93	54/9804	6
LOCATION:	AREAS	
ACTIVITY:		
BAGGING ASBESTOS ON WASTE TIP REF.: 11032.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
2/7/93	54/9804	7

LOCATION:	AREAS	
ACTIVITY:		
BAGGING ASBESTOS ON WASTE TIP REF.: 11032.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
3/7/93	54/9804	8
LOCATION:	AREA H - ISLAND SITE	
ACTIVITY:		
EXCAVATION IN PROGRESS FOR NEW ROAD NORTH OF BUILDING A203.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
5/7/93	54/9804	9
LOCATION:	AREA M	
ACTIVITY:		
ASBESTOS UNCOVERED IN SOIL IN CORDITE CONTAMINATED AREA.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
5/7/93	54/9804	10
LOCATION:	AREA M	
ACTIVITY:		
ASBESTOS UNCOVERED IN SOIL IN CORDITE CONTAMINATED AREA.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
5/7/93	54/9804	11
LOCATION:	AREA M	
ACTIVITY:		
ASBESTOS UNCOVERED IN SOIL IN CORDITE CONTAMINATED AREA.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
5/7/93	54/9804	12
LOCATION:	AREA M	
ACTIVITY:		
ASBESTOS UNCOVERED IN SOIL IN CORDITE CONTAMINATED AREA.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
5/7/93	54/9804	13

LOCATION:	AREA M	
ACTIVITY:		
ASBESTOS UNCOVERED IN SOIL IN CORDITE CONTAMINATED AREA.		
SPECIAL FEATURES:		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
5/7/93	54/9804	14
LOCATION:	AREA M	
ACTIVITY:		
COMPLETED EXCAVATION OF CANAL IN CORDITE CONTAMINATED AREA.		
SPECIAL FEATURES:		
SCREENING PLANT IN BACKGROUND.		



--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
5/7/93	54/9804	15
LOCATION:	AREA M	
ACTIVITY:		
COMPLETED EXCAVATION OF CANAL IN CORDITE CONTAMINATED AREA LOOKING EAST.		
SPECIAL FEATURES:		
SCREENING PLANT IN BACKGROUND.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
5/7/93	54/9804	16
LOCATION:	AREA M	
ACTIVITY:		
GENERAL EXCAVATION IN CORDITE CONTAMINATED AREA.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
5/7/93	54/9804	17
LOCATION:	AREA M	
ACTIVITY:		
EXCAVATED MATERIAL LOADED ONTO VOLVO DUMP TRUCK IN CORDITE CONTAMINATED AREA.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
5/7/93	54/9804	18
LOCATION:	AREA M	
ACTIVITY:		
EXCAVATED CANAL IN CORDITE CONTAMINATED AREA - LOOKING WEST.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
5/7/93	54/9804	19

LOCATION:	AREA M	
ACTIVITY:		
GENERAL VIEW OF CANAL AWAITING SURVEYING IN CORDITE CONTAMINATED AREA.		
SPECIAL FEATURES:		


**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
5/7/93	54/9804	20
LOCATION:	AREA M	
ACTIVITY:		
MANOUVERING BOAT TO TAKE LEVELS AND SAMPLES IN CANAL - CORDITE CONTAMINATED AREA.		
SPECIAL FEATURES:		
OPERATIVES WEARING LIFE JACKETS.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
5/7/93	54/9804	21
LOCATION:	AREA M	
ACTIVITY:		
SORTING OUT SAMPLE JARS PRIOR TO SAMPLING CANAL IN CORDITE CONTAMINATED AREA.		
SPECIAL FEATURES:		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
5/7/93	54/9804	22
LOCATION:	AREA M	
ACTIVITY:		
LOCATING BOAT PRIOR TO LEVELLING OF CANAL IN CORDITE CONTAMINATED AREA.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
5/7/93	54/9804	23
LOCATION:	AREA M	
ACTIVITY:		
PUMP USED FOR 'DE WATERING' OF CANAL IN CORDITE CONTAMINATED AREA.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
5/7/93	54/9804	24
LOCATION:	AREA M	
ACTIVITY:		
PUMP USED FOR 'DE WATERING' OF CANAL IN CORDITE CONTAMINATED		

AREA.
SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
5/7/93	54/9804	25

LOCATION:	AREA M	
ACTIVITY:		
SURVEYING OF CANAL IN PROGRESS IN CORDITE CONTAMINATED AREA.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
5/7/93	54/9804	26
LOCATION:	AREA M	
ACTIVITY:		
SAMPLING OF CANAL IN PROGRESS IN CORDITE CONTAMINATED AREA.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
5/7/93	54/9804	27
LOCATION:	AREA M	
ACTIVITY:		
SAMPLING OF CANAL IN PROGRESS IN CORDITE CONTAMINATED AREA.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
6/7/93	54/9804	28
LOCATION:	AREA M	
ACTIVITY:		
BOAT MOORED IN CANAL IN CORDITE CONTAMINATED AREA.		
SPECIAL FEATURES:		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
6/7/93	54/9804	29
LOCATION:	AREA M	
ACTIVITY:		
SAMPLING OF CANAL IN PROGRESS IN CORDITE CONTAMINATED AREA.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
7/7/93	54/9804	30
LOCATION:	AREA H	
ACTIVITY:		
VIEW OF BUILDING H37 FOUNDATION SLAB.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDATION RECORD

DATE:

NEGATIVE REFERENCE:

FRAME REFERENCE:

8/7/93

55/9806

1

LOCATION:

AREA B


ACTIVITY:

VIEW LOOKING NORTH WEST TOWARDS BUILDING L178.

SPECIAL FEATURES:

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
8/7/93	55/9806	2
LOCATION:	AREA B	
ACTIVITY:		
VIEW LOOKING NORTH TOWARDS BUILDINGS L175 AND L178.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
8/7/93	55/9806	3
LOCATION:	AREA B	
ACTIVITY:		
BUNDED BASE ADJACENT TO BURNING GROUND ACCESS ROAD.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
8/7/93	55/9806	4
LOCATION:	AREA B	
ACTIVITY:		
EXCAVATION OF WASTE TIP REF.: 11038 IN PROGRESS.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
8/7/93	55/9806	5
LOCATION:	AREA P	
ACTIVITY:		
EXCAVATED CANAL LOOKING EAST IN PMLH AREA.		



SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
8/7/93	55/9806	6

LOCATION:	AREA P	
ACTIVITY:		
EXCAVATION OF CANAL IN PROGRESS IN AREA P.		
SPECIAL FEATURES:		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
8/7/93	55/9806	7
LOCATION:	AREA P	
ACTIVITY:		
GENERAL EXCAVATION LOOKING SOUTH WEST IN AREA P.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
8/7/93	55/9806	8
LOCATION:	AREA P	
ACTIVITY:		
VIEW LOOKING NORTH TOWARDS BUILDINGS A230 - A234 IN AREA P.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
8/7/93	55/9806	9
LOCATION:	AREA M	
ACTIVITY:		
STOCKPILED MATERIAL ADJACENT TO CANAL IN CORDITE CONTAMINATED AREA.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
8/7/93	55/9806	10
LOCATION:	AREA M	
ACTIVITY:		
STOCKPILED EXCAVATED MATERIAL ADJACENT TO BUILDING L159.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
8/7/93	55/9806	11
LOCATION:	AREA M	
ACTIVITY:		
EXCAVATED MATERIAL LAID OUT TO DRY IN CORDITE CONTAMINATED		

AREA.
SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
8/7/93	55/9806	12




LOCATION:	AREA M	
ACTIVITY:		
EXCAVATED MATERIAL LAID OUT TO DRY IN CORDITE CONTAMINATED AREA.		
SPECIAL FEATURES:		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
14/7/93	55/9806	13
LOCATION:	AREA P	
ACTIVITY:		
GENERAL EXCAVATION WORKS IN PROGRESS IN AREA P.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
14/7/93	55/9806	14
LOCATION:	AREA P	
ACTIVITY:		
GENERAL EXCAVATION WORKS IN PROGRESS IN AREA P.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
14/7/93	55/9806	15
LOCATION:	AREA P	
ACTIVITY:		
VIEW TOWARDS BUILDING A250 SHOWING AREA TO BE SAMPLED.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
14/7/93	55/9806	16
LOCATION:	AREA P	
ACTIVITY:		
GENERAL VIEW OF EXCAVATIONS IN AREA P LOOKING WEST.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
14/7/93	55/9806	17
LOCATION:	AREA P	
ACTIVITY:		
GENERAL VIEW OF EXCAVATION IN AREA P LOOKING SOUTH WEST.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
14/7/93	55/9806	18

LOCATION:	AREA P	
ACTIVITY:		
GENERAL VIEW OF EXCAVATIONS IN AREA P LOOKING SOUTH WEST.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
14/7/93	55/9806	19
LOCATION:	AREA P	
ACTIVITY:		
REPAIRED BURST WATER MAIN IN AREA P.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
14/7/93	55/9806	20
LOCATION:	AREA P	
ACTIVITY:		
GENERAL EXCAVATIONS IN AREA P LOOKING WEST.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
14/7/93	55/9806	21
LOCATION:	AREA P	
ACTIVITY:		
MATERIAL FROM CORDITE CONTAMINATED AREA STOCKPILED EAST OF BUILDING A210.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
14/7/93	55/9806	22
LOCATION:	AREA P	
ACTIVITY:		
MATERIAL FROM CORDITE CONTAMINATED AREA STOCKPILED EAST OF BUILDING A210.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
14/7/93	55/9806	23
LOCATION:	AREA P	
ACTIVITY:		
MATERIAL FROM CORDITE CONTAMINATED AREA STOCKPILED SOUTH		

OF BUILDING A214.
SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
14/7/93	55/9806	24

LOCATION:	AREA P	
ACTIVITY:		
MATERIAL FROM CORDITE CONTAMINATED AREA STOCKPILED SOUTH OF BUILDING A214.		
SPECIAL FEATURES:		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
14/7/93	55/9806	25
LOCATION:	AREA P	
ACTIVITY:		
MATERIAL FROM CORDITE CONTAMINATED AREA STOCKPILED NORTH OF BUILDING A214.		
SPECIAL FEATURES:		



--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
14/7/93	55/9806	26
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L168 - MATERIAL STOCKPILED FROM CORDITE CONTAMINATED AREA.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
14/7/93	55/9806	27
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - REMOVAL OF ASPHALT FLOORING FROM CORRIDOR.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
14/7/93	55/9806	28
LOCATION:	AREA M	
ACTIVITY:		
ORIGINAL SITE NOTICES PLACED ALONGSIDE SITE AMENITIES.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
14/7/93	55/9806	29
LOCATION:	AREA S	
ACTIVITY:		
L.G.C. SAMPLING HORSEMILL STREAM LOOKING EAST.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
14/7/93	55/9806	30


LOCATION:	AREAS	
ACTIVITY:		
L.G.C. SAMPLING HORSEMILL STREAM LOOKING EAST.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
14/7/93	55/9806	31
LOCATION:	AREA S	
ACTIVITY:		
L.G.C. FILLING SAMPLE BOTTLES WITH WATER FROM HORSEMILL STREAM.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
15/7/93	55/9806	32
LOCATION:	AREA H	
ACTIVITY:		
BUILDING H37 - REINFORCEMENT IN CONCRETE FOUNDATION.		
SPECIAL FEATURES:		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
15/7/93	55/9806	33
LOCATION:	AREA H	
ACTIVITY:		
BUILDING H37 - BREAKING OUT CONCRETE FOUNDATION.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
19/7/93	55/9806	34
LOCATION:	AREA P	
ACTIVITY:		
TRIAL TRENCH TT3 NORTH OF BUILDINGS A230 - A234 LOOKING NORTH.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
19/7/93	55/9806	35
LOCATION:	AREA P	
ACTIVITY:		
TRIAL TRENCH TT1 NORTH OF BUILDINGS A230 - A234 LOOKING SOUTH.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
19/7/93	55/9806	36

LOCATION:	AREA H	
ACTIVITY:		
CLEANING KUBOTA AFTER WORKING ON SPECIAL WASTE AT H16 AREA.		
SPECIAL FEATURES:		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
19/7/93	55/9806	37
LOCATION:	AREA H	
ACTIVITY:		
CLEANING KUBOTA AFTER WORKING ON SPECIAL WASTE AT H16 AREA.		
SPECIAL FEATURES:		




**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
20/7/93	56/9805	1
LOCATION:	AREA B	
ACTIVITY:		
WASTE TIP REF.: 11038 - BURNING GROUND NORTH.		
SPECIAL FEATURES:		



--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
20/7/93	56/9805	2
LOCATION:	AREA B	
ACTIVITY:		
WASTE TIP REF.: 11038 - BURNING GROUND NORTH.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
20/7/93	56/9805	3
LOCATION:	AREA B	
ACTIVITY:		
WASTE TIP REF.: 11032 - BURNING GROUND SOUTH SURVEY WORK.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
21/7/93	56/9805	4
LOCATION:	AREA P	
ACTIVITY:		
TRIAL TRENCH TT1 NORTH OF BUILDING A230 - A234 VIEW LOOKING NORTH.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
21/7/93	56/9805	5
LOCATION:	AREA P	
ACTIVITY:		
TRIAL TRENCH TT1 NORTH OF BUILDINGS A230 - A234 VIEW ON EAST		

FACE.
SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
21/7/93	56/9805	6

LOCATION:	AREA P	
ACTIVITY:		
TRIAL TRENCH TT2 NORTH OF BUILDINGS A230 - A234 LOOKING EAST.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
21/7/93	56/9805	7
LOCATION:	AREA P	
ACTIVITY:		
TRIAL TRENCH TT3 NORTH OF BUILDINGS A230 - A234 LOOKING NORTH.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
21/7/93	56/9805	8
LOCATION:	AREA P	
ACTIVITY:		
TRIAL TRENCH TT3 NORTH OF BUILDINGS A230 - A234 LOOKING SOUTH.		
SPECIAL FEATURES:		



--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
21/7/93	56/9805	9
LOCATION:	AREA S	
ACTIVITY:		
WASTE TIP REF.: 11002 - LAGOON NORTH EAST OF BUILDING E2.		
SPECIAL FEATURES:		
THE NATURE OF THE WASTE DUMPED HERE.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
21/7/93	56/9805	10
LOCATION:	AREA S	
ACTIVITY:		
WASTE TIP REF.: 11002 - LAGOON NORTH EAST OF BUILDING E2.		
SPECIAL FEATURES:		

SOME TYPICAL ITEMS FOUND DUMPED.

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
21/7/93	56/9805	11
LOCATION:	AREA S	
ACTIVITY:		
WASTE TIP REF.: 11002 - LAGOON NORTH EAST OF BUILDING E2.		

SPECIAL FEATURES:
NATURE OF THE WASTE:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
21/7/93	56/9805	12

LOCATION:	AREAS	
ACTIVITY:		
WASTE TIP REF.: 11002 - LAGOON NORTH EAST OF BUILDING E2.		
SPECIAL FEATURES:		
NATURE OF THE WASTE.		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
21/7/93	56/9805	13
LOCATION:	AREA S	
ACTIVITY:		
WASTE TIP REF.: 11002.		
SPECIAL FEATURES:		
FULL CONTAINER OF HYDROFLUORIC ACID FOUND IN TIP.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
21/7/93	56/9805	14
LOCATION:	AREA S	
ACTIVITY:		
WASTE TIP REF.: 11002.		
SPECIAL FEATURES:		
'WHITE POWDER FOUND IN TIP'.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
21/7/93	56/9805	15
LOCATION:	AREA S	
ACTIVITY:		
WASTE TIP REF.: 11002.		
SPECIAL FEATURES:		
NATURE OF THE MATERIAL.		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
21/7/93	56/9805	16
LOCATION:	AREA S	
ACTIVITY:		
LAGOON NORTH WEST OF BUILDING E2.		
SPECIAL FEATURES:		

PARTIALLY FILLED WITH WASTE.



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
21/7/93	56/9805	17
LOCATION:	AREA S	
ACTIVITY:		
WASTE TIP REF.: 11002 NORTH EAST OF BUILDING E2.		

SPECIAL FEATURES:
TYPICAL ITEMS FOUND IN THE DUMP.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
23/7/93	56/9805	18

LOCATION:	AREAS	
ACTIVITY:		
'BARREL GRAVEYARD' HAND CLEARANCE.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
23/7/93	56/9805	19
LOCATION:	AREA S	
ACTIVITY:		
'BARREL GRAVEYARD' - HAND CLEARANCE.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
23/7/93	56/9805	20
LOCATION:	AREA S	
ACTIVITY:		
BUILDING U9 NEAR THE 'BARREL GRAVEYARD'.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
23/7/93	56/9805	21
LOCATION:	AREA S	
ACTIVITY:		
'BARREL GRAVEYARD' - CLEARANCE.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
23/7/93	56/9805	22
LOCATION:	AREA S	
ACTIVITY:		
CANAL SOUTH WEST OF BUILDING S34.		
SPECIAL FEATURES:		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
23/7/93	56/9805	23
LOCATION:	AREA S	
ACTIVITY:		
ASBESTOS CLEARANCE FROM WASTE TIP REF.: 11002 NORTH EAST OF		

BUILDING E2.
SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
23/7/93	56/9805	24

LOCATION:	AREAS	
ACTIVITY:		
WASTE TIP REF.: 11002 NORTH EAST OF BUILDING E2.		
SPECIAL FEATURES:		
NATURE OF THE WASTE.		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
23/7/93	56/9805	R
LOCATION:	AREA S	
ACTIVITY:		
WASTE TIP REF.: 11002 - NORTH EAST OF BUILDING E2.		
SPECIAL FEATURES:		
NATURE OF WASTE.		




**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
23/7/93	57/0095	1
LOCATION:	AREA H - ISLAND SITE	
ACTIVITY:		
TORRENTIAL RAIN STORM.		
SPECIAL FEATURES:		
BUILDING A200.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
23/7/93	57/0095	2
LOCATION:	AREA H - ISLAND SITE	
ACTIVITY:		
BUILDING A200 - DURING TORRENTIAL RAIN STORM.		
SPECIAL FEATURES:		
BUILDING A200.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/7/93	57/0095	5
LOCATION:	AREA S	
ACTIVITY:		
SOUTH ELEVATION OF BUILDING 103.		
SPECIAL FEATURES:		
GUNPOWDER PRESS HOUSE.		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/7/93	57/0095	6
LOCATION:	AREA S	
ACTIVITY:		
SOUTH ELEVATION OF BUILDING 103.		
SPECIAL FEATURES:		

WATERWHEEL OF GUNPOWDER PRESS HOUSE.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/7/93	57/0095	7
LOCATION:	AREAS	
ACTIVITY:		
SOUTH ELEVATION OF BUILDING 103.		

SPECIAL FEATURES:
GUNPOWDER PRESS HOUSE.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/7/93	57/0095	8

LOCATION:	AREAS	
ACTIVITY:		
SOUTH ELEVATION OF BUILDING 103.		
SPECIAL FEATURES:		
GUNPOWDER PRESS HOUSE.		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/7/93	57/0095	9
LOCATION:	AREA S	
ACTIVITY:		
SOUTH ELEVATION OF BUILDING 103.		
SPECIAL FEATURES:		
GUNPOWDER PRESS HOUSE.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/7/93	57/0095	10
LOCATION:	AREA S	
ACTIVITY:		
SOUTH EASTERN ASPECT OF BUILDING 103.		
SPECIAL FEATURES:		
GUNPOWDER PRESS HOUSE.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/7/93	57/0095	11
LOCATION:	AREA S	
ACTIVITY:		
PART OF EAST ELEVATION OF BUILDING 103.		
SPECIAL FEATURES:		
GUNPOWDER PRESS HOUSE.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/7/93	57/0095	12
LOCATION:	AREAS	
ACTIVITY:		
EAST ELEVATION OF BUILDING 103.		
SPECIAL FEATURES:		



GUNPOWDER PRESS HOUSE.



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/7/93	57/0095	13
LOCATION:	AREA S	
ACTIVITY:		
EAST ELEVATION OF BUILDING 103.		

SPECIAL FEATURES:
GUNPOWDER PRESS HOUSE.


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/7/93	57/0095	14

LOCATION:	AREAS	
ACTIVITY:		
PART OF THE WEST ELEVATION OF BUILDING 103.		
SPECIAL FEATURES:		
GUNPOWDER PRESS HOUSE.		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/7/93	57/0095	15
LOCATION:	AREA S	
ACTIVITY:		
WEST ELEVATION OF BUILDING 103.		
SPECIAL FEATURES:		
GUNPOWDER PRESS HOUSE.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/7/93	57/0095	16
LOCATION:	AREA S	
ACTIVITY:		
SOUTH WESTERN ASPECT OF BUILDING 103.		
SPECIAL FEATURES:		
GUNPOWDER PRESS HOUSE.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/7/93	57/0095	17
LOCATION:	AREA S	
ACTIVITY:		
SOUTH WESTERN ASPECT OF BUILDING 103.		
SPECIAL FEATURES:		
GUNPOWDER PRESS HOUSE.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/7/93	57/0095	18
LOCATION:	AREAS	
ACTIVITY:		
WEST ELEVATION OF BUILDING 103.		
SPECIAL FEATURES:		

GUNPOWDER PRESS HOUSE.



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/7/93	57/0095	19
LOCATION:	AREA S	
ACTIVITY:		
SOUTH WESTERN ASPECT OF BUILDING 103.		



SPECIAL FEATURES:
GUNPOWDER PRESS HOUSE.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/7/93	57/0095	20

LOCATION:	AREAS	
ACTIVITY:		
SOUTH WESTERN ASPECT OF BUILDING 103.		
SPECIAL FEATURES:		
GUNPOWDER PRESS HOUSE.		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/7/93	57/0095	21
LOCATION:	AREA S	
ACTIVITY:		
SOUTH ELEVATION OF BUILDING 103.		
SPECIAL FEATURES:		
GUNPOWDER PRESS HOUSE.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/7/93	57/0095	22
LOCATION:	AREA S	
ACTIVITY:		
BUILDING 103.		
SPECIAL FEATURES:		
WATERWHEEL OF GUNPOWDER PRESS HOUSE.		




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/7/93	57/0095	24
LOCATION:	AREA S	
ACTIVITY:		
BUILDING 103.		
SPECIAL FEATURES:		
WATERWHEEL OF GUNPOWDER PRESS HOUSE.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/7/93	57/0095	25
LOCATION:	AREA P	
ACTIVITY:		
WATER MAIN REPAIR NORTH OF BUILDING A250.		
SPECIAL FEATURES:		

'VIKING JOHNSON COUPLING'.



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/7/93	57/0095	26
LOCATION:	AREA P	
ACTIVITY:		
WATER MAIN REPAIR NORTH OF BUILDING A250.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/7/93	57/0095	27



LOCATION:	AREA P	
ACTIVITY:		
WATER MAIN REPAIR NORTH OF BUILDING A250.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/7/93	57/0095	28
LOCATION:	AREA P	
ACTIVITY:		
WATER MAIN REPAIR NORTH OF BUILDING A250.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/7/93	57/0095	29
LOCATION:	AREA P	
ACTIVITY:		
WATER MAIN REPAIR NORTH OF BUILDING A250.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/7/93	57/0095	30
LOCATION:	AREA P	
ACTIVITY:		
WATER MAIN REPAIR NORTH OF BUILDING A250.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/7/93	57/0095	31
LOCATION:	AREA P	
ACTIVITY:		
BUILDING A238 - GATE HOUSE.		
SPECIAL FEATURES:		

SECURITY CHECK IN PROGRESS.



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/7/93	57/0095	32
LOCATION:	AREA P	
ACTIVITY:		
VIEW NORTH FROM POWDERMILL LANE.		

SPECIAL FEATURES:


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/7/93	57/0095	33

LOCATION:	AREA P	
ACTIVITY:		
VIEW NORTH FROM POWDERMILL LANE.		
SPECIAL FEATURES:		




**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/7/93	57/0095	34
LOCATION:	AREA P	
ACTIVITY:		
VIEW WEST FROM POWDERMILL LANE.		
SPECIAL FEATURES:		
SEWAGE OUTFALL MEASURING AND SAMPLING CHAMBER - CENTRE BACKGROUND OF PICTURE.		




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/7/93	57/0095	35
LOCATION:	AREA P	
ACTIVITY:		
VIEW NORTH FROM POWDERMILL LANE.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/7/93	57/0095	36
LOCATION:	AREA P	
ACTIVITY:		
VIEW NORTH FROM POWDERMILL LANE.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/7/93	57/0095	R
LOCATION:	AREA P	
ACTIVITY:		
VIEW WEST FROM POWDERMILL LANE.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD

DATE:

NEGATIVE REFERENCE:

FRAME REFERENCE:

30/7/93

58/1170

1

LOCATION:

AREA H

ACTIVITY:


HIGHBRIDGE STREET ENTRANCE.

SPECIAL FEATURES:

ARCHAEOLOGICAL FIND (BURIED STRUCTURE).

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
30/7/93	58/1170	2
LOCATION:	AREA H	
ACTIVITY:		
HIGHBRIDGE STREET ENTRANCE.		
SPECIAL FEATURES:		
ARCHAEOLOGICAL FIND (BURIED STRUCTURE).		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
30/7/93	58/1170	3
LOCATION:	AREA H	
ACTIVITY:		
HIGHBRIDGE STREET ENTRANCE.		
SPECIAL FEATURES:		
ARCHAEOLOGICAL FIND (BURIED STRUCTURE).		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
30/7/93	58/1170	4
LOCATION:	AREA H	
ACTIVITY:		
HIGHBRIDGE STREET ENTRANCE.		
SPECIAL FEATURES:		

ARCHAEOLOGICAL FIND (BURIED STRUCTURE).

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIAION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
30/7/93	58/1170	5
LOCATION:	AREA H	
ACTIVITY:		
BUILDING H25 - INTERNAL ASBESTOS STRIP.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
30/7/93	58/1170	6

LOCATION:	AREA H	
ACTIVITY:		
BUILDING H25 - INTERNAL ASBESTOS WALL PANELS STRIPPED OUT.		
SPECIAL FEATURES:		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
4/8/93	58/1170	7
LOCATION:	AREA H	
ACTIVITY:		
DEMOLITION OF BUILDING H16.		
SPECIAL FEATURES:		
HYDRAULIC PULVERISER.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
4/8/93	58/1170	8
LOCATION:	AREA H	
ACTIVITY:		
DEMOLITION OF BUILDING H16.		
SPECIAL FEATURES:		
HYDRAULIC PULVERISER.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
4/8/93	58/1170	9
LOCATION:	AREA P	
ACTIVITY:		
DEMOLITION OF BUILDING A250.		
SPECIAL FEATURES:		
DAMPING DOWN THE DUST.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
4/8/93	58/1170	10
LOCATION:	AREA P	
ACTIVITY:		
DEMOLITION OF BUILDING A250.		
SPECIAL FEATURES:		




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
4/8/93	58/1170	11
LOCATION:	AREA H	
ACTIVITY:		
DEMOLITION CONTRACTORS PLANT - VOLVO DUMP TRUCK.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
4/8/93	58/1170	12


LOCATION:	AREA H	
ACTIVITY:		
DEMOLITION OF BUILDING H67.		
SPECIAL FEATURES:		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
4/8/93	58/1170	13
LOCATION:	AREA H	
ACTIVITY:		
DEMOLITION OF BUILDING H67.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
5/8/93	58/1170	14
LOCATION:	AREA H	
ACTIVITY:		
DEMOLITION OF BUILDING H25.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
5/8/93	58/1170	15
LOCATION:	AREA H	
ACTIVITY:		
DEMOLITION OF BUILDING H25.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
5/8/93	58/1170	16
LOCATION:	AREA H	
ACTIVITY:		
DEMOLITION OF BUILDING H25.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
5/8/93	58/1170	17
LOCATION:	AREA H	
ACTIVITY:		
DEMOLITION OF BUILDING H25.		



SPECIAL FEATURES:
HYDRAULIC PULVERISER.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
5/8/93	58/1170	18

LOCATION:	AREA H	
ACTIVITY:		
DEMOLITION OF BUILDING H25.		
SPECIAL FEATURES:		
HYDRAULIC PULVERISER.		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
5/8/93	58/1170	19
LOCATION:	AREA H	
ACTIVITY:		
DEMOLITION OF BUILDING H25.		
SPECIAL FEATURES:		
HYDRAULIC PULVERISER.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
5/8/93	58/1170	20
LOCATION:	AREA H	
ACTIVITY:		
DEMOLITION OF BUILDING H25.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
5/8/93	58/1170	21
LOCATION:	AREA H	
ACTIVITY:		
DEMOLITION OF BUILDING H25.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
5/8/93	58/1170	22
LOCATION:	AREA H	
ACTIVITY:		
DEMOLITION OF BUILDING H25.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
5/8/93	58/1170	23
LOCATION:	AREA H	
ACTIVITY:		
DEMOLITION OF BUILDING H25.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
5/8/93	58/1170	24



LOCATION:	AREA H	
ACTIVITY:		
DEMOLITION OF BUILDING H25.		
SPECIAL FEATURES:		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
5/8/93	58/1170	25
LOCATION:	AREA H	
ACTIVITY:		
DEMOLITION OF BUILDING H25.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
5/8/93	58/1170	26
LOCATION:	AREA H	
ACTIVITY:		
DEMOLITION OF BUILDING H25.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
5/8/93	58/1170	27
LOCATION:	AREA H	
ACTIVITY:		
DEMOLITION OF BUILDING H25.		
SPECIAL FEATURES:		
DAMPENING DOWN THE DUST.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/8/93	58/1170	28
LOCATION:	AREA H	
ACTIVITY:		
STENT FOUNDATIONS: - PLANT ARRIVAL.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/8/93	58/1170	29
LOCATION:	AREA H	
ACTIVITY:		
STENT FOUNDATIONS: - PLANT ARRIVAL.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/8/93	58/1170	30

LOCATION:	AREA H	
ACTIVITY:		
VOLVO DUMP TRUCK - 20 TONNE.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/8/93	58/1170	31
LOCATION:	AREA H	
ACTIVITY:		
DEMOLITION ARISINGS STOCKPILED AT H67.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/8/93	58/1170	32
LOCATION:	AREA H	
ACTIVITY:		
DEMOLISHED BUILDING H69.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/8/93	58/1170	33
LOCATION:	AREA H	
ACTIVITY:		
DEMOLITION ARISINGS STOCKPILED AT H67.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/8/93	58/1170	34
LOCATION:	AREA H	
ACTIVITY:		
AREA ADJACENT TO H10 PREPARED FOR MATERIAL STOCKPILING.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/8/93	58/1170	35
LOCATION:	AREA H	
ACTIVITY:		
BUILDING H30 SLAB ( AFTER DEMOLITION).		

SPECIAL FEATURES:


FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/8/93	59/1171	1
LOCATION:	AREA S	
ACTIVITY:		
NEWTONS POOL - COFFERDAM INSTALLATION.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/8/93	59/1171	2
LOCATION:	AREA S	
ACTIVITY:		
NEWTONS POOL - COFFERDAM INSTALLATION.		
SPECIAL FEATURES:		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/8/93	59/1171	3
LOCATION:	AREAS	
ACTIVITY:		
NEWTONS POOL - COFFERDAM INSTALLATION.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/8/93	59/1171	4
LOCATION:	AREA S	
ACTIVITY:		
NEWTONS POOL - COFFERDAM INSTALLATION.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
13/8/93	59/1171	5
LOCATION:	AREAS	
ACTIVITY:		
NEWTONS POOL - COFFERDAM INSTALLATION.		

SPECIAL FEATURES:


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
13/8/93	59/1171	6

LOCATION:	AREAS	
ACTIVITY:		
NEWTONS POOL - COFFERDAM INSTALLATION.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
13/8/93	59/1171	7
LOCATION:	AREAS	
ACTIVITY:		
NEWTONS POOL - COFFERDAM INSTALLATION.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
13/8/93	59/1171	8
LOCATION:	AREA S	
ACTIVITY:		
NEWTONS POOL - COFFERDAM INSTALLATION.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
13/8/93	59/1171	9
LOCATION:	AREA S	
ACTIVITY:		
NEWTONS POOL - COFFERDAM INSTALLATION.		
SPECIAL FEATURES:		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
13/8/93	59/1171	10
LOCATION:	AREAS	
ACTIVITY:		
NEWTONS POOL - COFFERDAM INSTALLATION.		
SPECIAL FEATURES:		

SHEET PILES USED FOR THE COFFERDAM.

--


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
13/8/93	59/1171	11
LOCATION:	AREA S	
ACTIVITY:		
NEWTONS POOL - COFFERDAM INSTALLATION.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
13/8/93	59/1171	12

LOCATION:	AREAS	
ACTIVITY:		
NEWTONS POOL - COFFERDAM INSTALLATION.		
SPECIAL FEATURES:		
CONTRACTORS ACCOMMODATION.		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
13/8/93	59/1171	R
LOCATION:	AREAS	
ACTIVITY:		
LAGOON NORTH WEST OF BUILDING E2.		
SPECIAL FEATURES:		




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
16/8/93	60/1772	1
LOCATION:	AREA S	
ACTIVITY:		
NEWTONS POOL - VIEWED FROM EAST SIDE.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
16/8/93	60/1772	2
LOCATION:	AREA S	
ACTIVITY:		
NEWTONS POOL - COFFERDAM.		
SPECIAL FEATURES:		
WATER INGRESS.		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
16/8/93	60/1772	3
LOCATION:	AREAS	
ACTIVITY:		
NEWTONS POOL - COFFERDAM.		
SPECIAL FEATURES:		
WATER INGRESS.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
16/8/93	60/1772	4
LOCATION:	AREA S	
ACTIVITY:		
NEWTONS POOL - COFFERDAM.		
SPECIAL FEATURES:		

WATER INGRESS.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
16/8/93	60/1772	5
LOCATION:	AREAS	
ACTIVITY:		
NEWTONS POOL - COFFERDAM.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
16/8/93	60/1772	6


LOCATION:	AREAS	
ACTIVITY:		
NEWTONS POOL - COFFERDAM INSTALLATION.		
SPECIAL FEATURES:		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
16/8/93	60/1772	7
LOCATION:	AREA S	
ACTIVITY:		
ROAD REPAIR AT NEWTONS POOL TO ASSIST ACCESS FOR HEAVY PLANT.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
16/8/93	60/1772	8
LOCATION:	AREA S	
ACTIVITY:		
ACCESS ROUTE TO NEWTONS POOL.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
16/8/93	60/1772	9
LOCATION:	AREA S	
ACTIVITY:		
LAGOON NORTH WEST OF BUILDING E2.		
SPECIAL FEATURES:		
DISCOLOURATION OF WATER.		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
16/8/93	60/1772	10
LOCATION:	AREA S	
ACTIVITY:		
LAGOON NORTH WEST OF BUILDING E2.		
SPECIAL FEATURES:		

DISCOLOURATION OF WATER.



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
16/8/93	60/1772	11
LOCATION:	AREA T	
ACTIVITY:		
BLUE ASBESTOS AND TETRYL CONTAMINATION DISCOVERED.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
16/8/93	60/1772	12

LOCATION:	AREA T	
ACTIVITY:		
BLUE ASBESTOS AND TETRYL CONTAMINATION DISCOVERED.		
SPECIAL FEATURES:		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
16/8/93	60/1772	13
LOCATION:	AREA S	
ACTIVITY:		
LAGOON NORTH WEST OF BUILDING E2.		
SPECIAL FEATURES:		
DISCOLOURATION OF WATER.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
16/8/93	60/1772	14
LOCATION:	AREA T	
ACTIVITY:		
BAGGING ASBESTOS CONTAMINATED SOIL.		
SPECIAL FEATURES:		
WORK BEING CARRIED OUT BY LICENSED ASBESTOS CONTRACTOR.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
16/8/93	60/1772	15
LOCATION:	AREA T	
ACTIVITY:		
BAGGING ASBESTOS CONTAMINATED SOIL.		
SPECIAL FEATURES:		
WORK BEING CARRIED OUT BY LICENSED ASBESTOS CONTRACTORS.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
16/8/93	60/1772	16
LOCATION:	AREA S	
ACTIVITY:		
CANAL CLEARANCE ADJACENT TO BUILDINGS E2 AND E3.		
SPECIAL FEATURES:		




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
16/8/93	60/1772	17
LOCATION:	AREA S	
ACTIVITY:		
CANAL CLEARANCE NORTH OF BUILDINGS E2 AND E3.		

SPECIAL FEATURES:
VIEWED FROM EAST.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
16/8/93	60/1772	18

LOCATION:	AREAS	
ACTIVITY:		
CANAL CLEARED SOUTH WEST OF BUILDING S34.		
SPECIAL FEATURES:		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
19/8/93	60/1772	19
LOCATION:	AREAS	
ACTIVITY:		
'BARREL GRAVEYARD' TRIAL HOLES.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
19/8/93	60/1772	20
LOCATION:	AREA S	
ACTIVITY:		
'BARREL GRAVEYARD' TRIAL HOLES.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
19/8/93	60/1772	21
LOCATION:	AREA S	
ACTIVITY:		
'BARREL GRAVEYARD' TRIAL HOLES.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
19/8/93	60/1772	22
LOCATION:	AREAS	
ACTIVITY:		
'BARREL GRAVEYARD' TRIAL HOLES.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
19/8/93	60/1772	24
LOCATION:	AREA S	
ACTIVITY:		
'BARREL GRAVEYARD' TRIAL HOLES.		



SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
20/8/93	60/1772	25


LOCATION:	AREA B	
ACTIVITY:		
WASTE CORDITE LAID OUT FOR FIRING.		
SPECIAL FEATURES:		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
20/8/93	60/1772	26
LOCATION:	AREA B	
ACTIVITY:		
WASTE CORDITE LAID OUT FOR FIRING.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
20/8/93	60/1772	27
LOCATION:	AREA B	
ACTIVITY:		
WASTE CORDITE LAID OUT FOR FIRING.		
SPECIAL FEATURES:		
COMMENCEMENT OF FIRING.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
20/8/93	60/1772	28
LOCATION:	AREA B	
ACTIVITY:		
WASTE CORDITE.		
SPECIAL FEATURES:		
COMMENCEMENT OF FIRING.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
20/8/93	60/1772	29
LOCATION:	AREA B	
ACTIVITY:		
WASTE CORDITE BEING FIRED.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
20/8/93	60/1772	30
LOCATION:	AREA B	
ACTIVITY:		
WASTE CORDITE BEING FIRED.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
20/8/93	60/1772	31



LOCATION:	AREA B	
ACTIVITY:		
WASTE CORDITE BEING FIRED.		
SPECIAL FEATURES:		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
20/8/93	60/1772	32
LOCATION:	AREA B	
ACTIVITY:		
WASTE CORDITE BEING FIRED.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
20/8/93	60/1772	33
LOCATION:	AREA S	
ACTIVITY:		
LAGOON WEST OF BUILDING E2.		
SPECIAL FEATURES:		




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
20/8/93	60/1772	34
LOCATION:	AREA S	
ACTIVITY:		
LAGOON WEST OF BUILDING E2 - EXCAVATION OF WASTE.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
20/8/93	60/1772	35
LOCATION:	AREA S	
ACTIVITY:		
CANAL CLEARANCE BETWEEN BUILDINGS E2 AND E3 - REFUELLING MACHINERY.		
SPECIAL FEATURES:		

NOTE LARGE BOULDERS OF MASONRY WITHIN THE FILL.



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
20/8/93	60/1772	36
LOCATION:	AREA S	
ACTIVITY:		
CANAL CLEARANCE BETWEEN BUILDINGS E2 AND E3.		

SPECIAL FEATURES:
NOTE LARGE BOULDERS OF MASONRY WITHIN THE FILL.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
20/8/93	60/1772	R

LOCATION:	AREA S	
ACTIVITY:		
CANAL CLEARANCE BETWEEN BUILDINGS E2 AND E3 - ARTIFACTS FOUND.		
SPECIAL FEATURES:		
POTENTIALLY CONTAMINATED PROCESS PIPEWORK.		





FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDICATION RECORD

DATE:

NEGATIVE REFERENCE:

FRAME REFERENCE:

23/8/93

61/3712

1

LOCATION:

AREA P


ACTIVITY:

EXCAVATION OF TRIAL PIT P10 - NORTH OF BUILDING A232.

SPECIAL FEATURES:

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
23/8/93	61/3712	2
LOCATION:	AREA P	
ACTIVITY:		
EXCAVATION OF TRIAL PIT P10 - NORTH OF BUILDING A232.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
23/8/93	61/3712	3
LOCATION:	AREA P	
ACTIVITY:		
EXCAVATION OF TRIAL PIT P10 - NORTH OF BUILDING A232.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
23/8/93	61/3712	4
LOCATION:	AREA P	
ACTIVITY:		
EXCAVATION OF TRIAL PIT P10 - NORTH OF BUILDING A232.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
23/8/93	61/3712	5
LOCATION:	AREA P	
ACTIVITY:		
EXCAVATION OF TRIAL PIT P10 - NORTH OF BUILDING A232.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
23/8/93	61/3712	6

LOCATION:	AREA P	
ACTIVITY:		
EXCAVATION OF TRIAL PIT P10 - NORTH OF BUILDING A232.		
SPECIAL FEATURES:		



**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
23/8/93	61/3712	7
LOCATION:	AREA P	
ACTIVITY:		
EXCAVATION OF TRIAL PIT P10 - NORTH OF BUILDING A232.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
26/8/93	61/3712	8
LOCATION:	AREA B	
ACTIVITY:		
CLEARANCE OF CONCRETE AND MASONRY FROM BURNING GROUND.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
26/8/93	61/3712	9
LOCATION:	AREA B	
ACTIVITY:		
STOCKPILED WASTE MATERIAL ON BURNING GROUND.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
26/8/93	61/3712	10
LOCATION:	AREA P	
ACTIVITY:		
TRIAL PIT P10 - NORTH OF BUILDING A232.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
26/8/93	61/3712	11
LOCATION:	AREA P	
ACTIVITY:		
TRIAL PIT P10 - NORTH OF BUILDING A232.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
26/8/93	61/3712	12


LOCATION:	AREA P	
ACTIVITY:		
TRIAL PIT P10 - NORTH OF BUILDING A232.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
26/8/93	61/3712	13
LOCATION:	AREA P	
ACTIVITY:		
BUILDING A250 - BREAKING OUT OF SLAB AND FOUNDATIONS IN PROGRESS.		
SPECIAL FEATURES:		



--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
26/8/93	61/3712	14
LOCATION:	AREA P	
ACTIVITY:		
BUILDING A250 - PARTIAL REMAINS OF CONCRETE SLAB.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
26/8/93	61/3712	15
LOCATION:	AREA P	
ACTIVITY:		
EXCAVATION OF CANAL NORTH OF BUILDINGS A230 - A234.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
26/8/93	61/3712	16
LOCATION:	AREA P	
ACTIVITY:		
EXCAVATION OF CANAL NORTH OF BUILDINGS A230 - A234.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
26/8/93	61/3712	17
LOCATION:	AREA P	
ACTIVITY:		
EXCAVATION OF CANAL NORTH OF BUILDINGS A230 - A234.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
2/9/93	61/3712	18

LOCATION:	AREAS	
ACTIVITY:		
NEWTONS POOL - SETTING UP PUMPS PRIOR TO DE-WATERING.		
SPECIAL FEATURES:		


**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
2/9/93	61/3712	19
LOCATION:	AREA S	
ACTIVITY:		
NEWTONS POOL - DE-WATERING IN PROGRESS.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
2/9/93	61/3712	20
LOCATION:	AREA S	
ACTIVITY:		
CANAL NORTH OF BUILDING E2, RECEIVING SCREENED WATER FROM NEWTONS POOL.		
SPECIAL FEATURES:		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
2/9/93	61/3712	21
LOCATION:	AREA S	
ACTIVITY:		
GRAVEL FILTER IN CANAL NORTH OF NEWTONS POOL.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
2/9/93	61/3712	22
LOCATION:	AREAS	
ACTIVITY:		
AQUEDUCT NORTH OF BUILDING 46A.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
2/9/93	61/3712	23
LOCATION:	AREA S	
ACTIVITY:		
NEWTONS POOL - VIEW LOOKING EAST.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
2/9/93	61/3712	24

LOCATION:	AREAS	
ACTIVITY:		
NEWTONS POOL - SCREENING PLANT.		
SPECIAL FEATURES:		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
2/9/93	61/3712	25
LOCATION:	AREA S	
ACTIVITY:		
PUMPS SET UP ON NORTH SIDE OF NEWTONS POOL.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
2/9/93	61/3712	26
LOCATION:	AREA S	
ACTIVITY:		
NEWTONS POOL - GENERAL VIEW OF PUMPS AND SCREENING PLANT.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
2/9/93	61/3712	27
LOCATION:	AREA S	
ACTIVITY:		
NEWTONS POOL - CLOGGED PUMP STRAINER.		
SPECIAL FEATURES:		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
2/9/93	61/3712	28
LOCATION:	AREAS	
ACTIVITY:		
NEWTONS POOL - KEEPING AN EYE ON PROGRESS.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
6/9/93	61/3712	29
LOCATION:	AREA S	
ACTIVITY:		
NEWTONS POOL - SHELL CASE RECOVERED.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
6/9/93	61/3712	30

LOCATION:	AREAS	
ACTIVITY:		
NEWTONS POOL - SHELL CASE RECOVERED.		
SPECIAL FEATURES:		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
6/9/93	61/3712	31
LOCATION:	AREAS	
ACTIVITY:		
NEWTONS POOL - DE-WATERING IN PROGRESS.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
6/9/93	61/3712	32
LOCATION:	AREA S	
ACTIVITY:		
NEWTONS POOL - GENERAL VIEW OF PUMPS AND PERSONNEL.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
6/9/93	61/3712	33
LOCATION:	AREA S	
ACTIVITY:		
NEWTONS POOL - SHELL CASING REMOVED.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
6/9/93	61/3712	34
LOCATION:	AREAS	
ACTIVITY:		
NEWTONS POOL - DE-WATERING IN PROGRESS.		
SPECIAL FEATURES:		




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
6/9/93	61/3712	35
LOCATION:	AREA S	
ACTIVITY:		
NEWTONS POOL - SHELL CASING RECOVERED.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
6/9/93	61/3712	36

LOCATION:	AREAS	
ACTIVITY:		
NEWTONS POOL - SCREENING PLANT IN OPERATION.		
SPECIAL FEATURES:		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDICATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
6/9/93	61/3712	36A
LOCATION:	AREA S	
ACTIVITY:		
NEWTONS POOL - VIEW TOWARDS GRAVEL FILTER.		
SPECIAL FEATURES:		




**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
7/9/93	62/3714	1
LOCATION:	AREA	
ACTIVITY:		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
7/9/93	62/3714	5
LOCATION:	AREA S	
ACTIVITY:		
NEWTONS POOL - RETRIEVING FISH PRIOR TO DECONTAMINATION.		
SPECIAL FEATURES:		
NATIONAL RIVERS AUTHORITY CARRYING OUT FISH RETRIEVAL.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
7/9/93	62/3714	6
LOCATION:	AREA S	
ACTIVITY:		
NEWTONS POOL - RETRIEVING FISH PRIOR TO DECONTAMINATION.		
SPECIAL FEATURES:		
NATIONAL RIVERS AUTHORITY CARRYING OUT FISH RETRIEVAL.		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
7/9/93	62/3714	7
LOCATION:	AREA S	
ACTIVITY:		
NEWTONS POOL - RETRIEVING FISH PRIOR TO DECONTAMINATION.		
SPECIAL FEATURES:		

NATIONAL RIVERS AUTHORITY CARRYING OUT FISH RETRIEVAL.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
7/9/93	62/3714	8
LOCATION:	AREAS	
ACTIVITY:		
NEWTONS POOL - RETRIEVING FISH PRIOR TO DECONTAMINATION.		

SPECIAL FEATURES:
NATIONAL RIVERS AUTHORITY CARRYING OUT FISH RETRIEVAL.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
7/9/93	62/3714	9


LOCATION:	AREAS	
ACTIVITY:		
NEWTONS POOL - RETRIEVING FISH PRIOR TO DECONTAMINATION.		
SPECIAL FEATURES:		
NATIONAL RIVERS AUTHORITY CARRYING OUT FISH RETRIEVAL.		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
7/9/93	62/3714	10
LOCATION:	AREA S	
ACTIVITY:		
NEWTONS POOL - RETRIEVING FISH PRIOR TO DECONTAMINATION.		
SPECIAL FEATURES:		
NATIONAL RIVERS AUTHORITY CARRYING OUT FISH RETRIEVAL.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
7/9/93	62/3714	11
LOCATION:	AREA S	
ACTIVITY:		
NEWTONS POOL - RETRIEVING FISH PRIOR TO DECONTAMINATION.		
SPECIAL FEATURES:		
NATIONAL RIVERS AUTHORITY CARRYING OUT FISH RETRIEVAL.		




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
7/9/93	62/3714	12
LOCATION:	AREA S	
ACTIVITY:		
NEWTONS POOL - RETRIEVING FISH PRIOR TO DECONTAMINATION.		
SPECIAL FEATURES:		
NATIONAL RIVERS AUTHORITY CARRYING OUT FISH RETRIEVAL.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
7/9/93	62/3714	13
LOCATION:	AREA S	
ACTIVITY:		
NEWTONS POOL - RETRIEVING FISH PRIOR TO DECONTAMINATION.		
SPECIAL FEATURES:		



NATIONAL RIVERS AUTHORITY CARRYING OUT FISH RETRIEVAL.



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
7/9/93	62/3714	14
LOCATION:	AREA S	
ACTIVITY:		
NEWTONS POOL - FISH BEING EMPTIED INTO CONTAINERS.		

SPECIAL FEATURES:
NATIONAL RIVERS AUTHORITY CARRYING OUT FISH RETRIEVAL.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
7/9/93	62/3714	15

LOCATION:	AREAS	
ACTIVITY:		
NEWTONS POOL - FISH BEING EMPTIED INTO CONTAINERS.		
SPECIAL FEATURES:		
NATIONAL RIVERS AUTHORITY CARRYING OUT FISH RETRIEVAL.		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
8/9/93	62/3714	16
LOCATION:	AREA P	
ACTIVITY:		
BOREHOLE IN CANAL BANK NORTH OF BUILDINGS A230 - A234.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
8/9/93	62/3714	17
LOCATION:	AREA P	
ACTIVITY:		
BOREHOLE IN CANAL BANK NORTH OF BUILDINGS A230 - A234.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
8/9/93	62/3714	18
LOCATION:	AREA P	
ACTIVITY:		
BOREHOLE IN CANAL BANK NORTH OF BUILDINGS A230 - A234.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
8/9/93	62/3714	19
LOCATION:	AREA P	
ACTIVITY:		
BOREHOLE IN CANAL BANK NORTH OF BUILDINGS A230 - A234.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
8/9/93	62/3714	20
LOCATION:	AREA P	
ACTIVITY:		
VIEW OF CANAL NORTH OF BUILDINGS A230 - A234 - LOOKING WEST.		



SPECIAL FEATURES:
AFTER COMPLETION OF REMOVAL OF INFILL MATERIALS.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
8/9/93	62/3714	21


LOCATION:	AREA P	
ACTIVITY:		
SCRAP METALS ACCUMULATED IN STOCKPILE.		
SPECIAL FEATURES:		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
8/9/93	62/3714	22
LOCATION:	AREA S	
ACTIVITY:		
EXCAVATION OF CANAL IN PROGRESS.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
8/9/93	62/3714	23
LOCATION:	AREA S	
ACTIVITY:		
NEWTONS POOL - DECONTAMINATION WORKS.		
SPECIAL FEATURES:		
FILTER SYSTEM SET UP FOR FILTERING DEBRIS RETRIEVED FROM NEWTONS POOL.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
8/9/93	62/3714	24
LOCATION:	AREA H	
ACTIVITY:		
DEMOLITION ARISINGS STOCKPILE.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
8/9/93	62/3714	25
LOCATION:	AREA H	
ACTIVITY:		
DEMOLITION ARISINGS STOCKPILE.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
8/9/93	62/3714	26
LOCATION:	AREA H	
ACTIVITY:		
DEMOLITION ARISINGS STOCKPILE.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
8/9/93	62/3714	27




LOCATION:	AREA P	
ACTIVITY:		
CLEARANCE OF BUILDING A250 SUB STRUCTURE.		
SPECIAL FEATURES:		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
8/9/93	62/3714	28
LOCATION:	AREA P	
ACTIVITY:		
CLEARANCE OF BUILDING A250 SUB STRUCTURE.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/9/93	62/3714	29
LOCATION:	AREA H	
ACTIVITY:		
CONTAMINATED WASTE ON H67 SAMPLING AREA.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/9/93	62/3714	30
LOCATION:	AREA P	
ACTIVITY:		
REMOVAL OF BUILDING A250 SUB STRUCTURE.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/9/93	62/3714	31
LOCATION:	AREA P	
ACTIVITY:		
REMOVAL OF BUILDING A250 SUB STRUCTURE.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/9/93	62/3714	32
LOCATION:	AREA T	
ACTIVITY:		
REMEDICATION OF TETRYL FACTORY SITE.		

SPECIAL FEATURES:
HISTORIC CRANE BASE.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/9/93	62/3714	33

LOCATION:	AREA T	
ACTIVITY:		
REMEDIATION OF TETRYL FACTORY SITE.		
SPECIAL FEATURES:		
HISTORIC CRANE BASE.		



**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/9/93	62/3714	34
LOCATION:	AREA T	
ACTIVITY:		
EXPOSURE OF SUSPECT PIT AREA T, NORTH.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/9/93	62/3714	35
LOCATION:	AREA T	
ACTIVITY:		
REMEDICATION OF TETRYL FACTORY SITE.		
SPECIAL FEATURES:		
FOUNDATION TO FORMER GUNPOWDER STOVE.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/9/93	62/3714	36
LOCATION:	AREA T	
ACTIVITY:		
REMEDICATION OF TETRYL FACTORY SITE.		
SPECIAL FEATURES:		
FOUNDATIONS TO FORMER GUNPOWDER STOVE.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
13/9/93	62/3714	R
LOCATION:	AREA P	
ACTIVITY:		
EXCAVATION ADJACENT TO BUILDINGS A230 - A234.		
SPECIAL FEATURES:		

REMEDIATION OF NITRO-GLYCERINE CONTAMINATION.

FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
15/9/93	63/4532	1
LOCATION:	AREA T	
ACTIVITY:		
CONTAMINATED MATERIAL BEING STOCKPILED.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
15/9/93	63/4532	2
LOCATION:	AREA T	
ACTIVITY:		
ASBESTOS BEING BAGGED.		
SPECIAL FEATURES:		
WORK IN PROGRESS BY LICENSED ASBESTOS CONTRACTORS.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
15/9/93	63/4532	3
LOCATION:	AREAS	
ACTIVITY:		
NEWTONS POOL - SCREENING PLANT.		
SPECIAL FEATURES:		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
15/9/93	63/4532	4
LOCATION:	AREA S	
ACTIVITY:		
NEWTONS POOL - TYPICAL SCREEN, REMOVED FOR REPAIRS.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
15/9/93	63/4532	5
LOCATION:	AREAS	
ACTIVITY:		
NEWTONS POOL - EXCAVATION.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
15/9/93	63/4532	6

LOCATION:	AREA S	
ACTIVITY:		
NEWTONS POOL - VIEW FROM NORTH OF BUILDING S34.		
SPECIAL FEATURES:		
SLUDGE FROM NEWTONS POOL BEING STOCKPILED (IN FOREGROUND).		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
15/9/93	63/4532	7
LOCATION:	AREA S	
ACTIVITY:		
NEWTONS POOL - VIEW NORTH OF BUILDING S34.		
SPECIAL FEATURES:		
SHADED HOLDING TANKS FOR PLANT LIFE EXAMPLES RETRIEVED FROM NEWTONS POOL FOR SUBSEQUENT REHABILITATION OF THE POOL.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
15/9/93	63/4532	8
LOCATION:	AREA S	
ACTIVITY:		
NEWTONS POOL - VIEW EAST OF BUILDING S34.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
17/9/93	63/4532	10
LOCATION:	AREA S	
ACTIVITY:		
BARGE HOUSE FOUNDATIONS ON SIDE OF CANAL ADJACENT TO BUILDING E2.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
17/9/93	63/4532	11
LOCATION:	AREA S	
ACTIVITY:		
BARGE HOUSE FOUNDATIONS ON SIDE OF CANAL ADJACENT TO BUILDING E2.		
SPECIAL FEATURES:		




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
17/9/93	63/4532	12
LOCATION:	AREA T	
ACTIVITY:		
EXCAVATED CANAL ADJACENT TO BUILDING E2.		

SPECIAL FEATURES:


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
17/9/93	63/4532	13

LOCATION:	AREAS	
ACTIVITY:		
BARGE HOUSE TO SIDE OF EXCAVATED CANAL ADJACENT TO BUILDING E2.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
18/9/93	63/4532	14
LOCATION:	AREA S	
ACTIVITY:		
<p>NEWTONS POOL - SHINGLE DAM / FILTER - TO RETAIN SIEVED SLUDGE REMOVED FROM NEWTONS POOL.</p>		
SPECIAL FEATURES:		
<p>HERONRY DEMARCATION TAPE STRUNG BETWEEN TREES.</p>		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
18/9/93	63/4532	15
LOCATION:	AREA S	
ACTIVITY:		
NEWTONS POOL - SCREENING PLANT FOR SIEVING SLUDGE REMOVED FROM NEWTONS POOL.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
18/9/93	63/4532	16
LOCATION:	AREA S	
ACTIVITY:		
NEWTONS POOL - REMEDIATION.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
20/9/93	63/4532	17
LOCATION:	AREAS	
ACTIVITY:		
NEWTONS POOL - REMEDIATION.		
SPECIAL FEATURES:		

PUMP ARRANGEMENT.

Empty rectangular box for drawing or notes.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
20/9/93	63/4532	18
LOCATION:	AREA S	
ACTIVITY:		
NEWTONS POOL - REMEDIATION.		



SPECIAL FEATURES:
LONG REACH EXCAVATOR IN USE.


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
20/9/93	63/4532	19

LOCATION:	AREAS	
ACTIVITY:		
NEWTONS POOL - REMEDIATION.		
SPECIAL FEATURES:		
LONG REACH EXCAVATOR IN USE.		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
20/9/93	63/4532	20
LOCATION:	AREA S	
ACTIVITY:		
NEWTONS POOL - REMEDIATION.		
SPECIAL FEATURES:		
LONG REACH EXCAVATOR IN USE.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
22/9/93	63/4532	21
LOCATION:	AREA S	
ACTIVITY:		
NEWTONS POOL - REMEDIATION.		
SPECIAL FEATURES:		
SUSPECT OBJECT REMOVED FROM THE POOL.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
22/9/93	63/4532	22
LOCATION:	AREA S	
ACTIVITY:		
NEWTONS POOL - REMEDIATION.		
SPECIAL FEATURES:		
SUSPECT OBJECT REMOVED FROM THE POOL.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
24/9/93	63/4532	23
LOCATION:	AREAS	
ACTIVITY:		
NEWTONS POOL - REMEDIATION.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
24/9/93	63/4532	24
LOCATION:	AREA S	
ACTIVITY:		
NEWTONS POOL - REMEDIATION.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
24/9/93	63/4532	25




LOCATION:	AREAS	
ACTIVITY:		
NEWTONS POOL - REMEDIATION.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
24/9/93	63/4532	26
LOCATION:	AREA S	
ACTIVITY:		
NEWTONS POOL - REMEDIATION.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
24/9/93	63/4532	27
LOCATION:	AREA S	
ACTIVITY:		
NEWTONS POOL - REMEDIATION.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
24/9/93	63/4532	28
LOCATION:	AREA S	
ACTIVITY:		
NEWTONS POOL - REMEDIATION.		
SPECIAL FEATURES:		
SUSPECT OBJECTS RETRIEVED FROM POOL.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
24/9/93	63/4532	29
LOCATION:	AREA S	
ACTIVITY:		
NEWTONS POOL - REMEDIATION.		
SPECIAL FEATURES:		

SUSPECT OBJECTS RETRIEVED FROM POOL.



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
24/9/93	63/4532	30
LOCATION:	AREA S	
ACTIVITY:		
NEWTONS POOL - REMEDIATION.		

SPECIAL FEATURES:
SUSPECT OBJECTS RETRIEVED FROM POOL.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
25/9/93	63/4532	32

LOCATION:	AREA M	
ACTIVITY:		
NEWTONS POOL REMEDIATION - PREPARING PRECAST CONCRETE MANHOLE RINGS FOR USE AS 'PUMP SUMPS'.		
SPECIAL FEATURES:		
ROYAL ORDNANCE CORING RIG ASSEMBLY.		




**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
25/9/93	63/4532	33
LOCATION:	AREA S	
ACTIVITY:		
NEWTONS POOL - REMEDIATION.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
25/9/93	63/4532	34
LOCATION:	AREA S	
ACTIVITY:		
NEWTONS POOL - REMEDIATION.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
25/9/93	63/4532	35
LOCATION:	AREA S	
ACTIVITY:		
NEWTONS POOL - REMEDIATION.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
25/9/93	63/4532	36
LOCATION:	AREAS	
ACTIVITY:		
NEWTONS POOL - REMEDIATION.		
SPECIAL FEATURES:		

PUMP ARRANGEMENT.

Empty rectangular box for drawing or notes.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
25/9/93	63/4532	37
LOCATION:	AREA S	
ACTIVITY:		
NEWTONS POOL - REMEDIATION.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
25/9/93	64/4533	1
LOCATION:	AREA S	
ACTIVITY:		
NEWTONS POOL - REMEDIATION.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
25/9/93	64/4533	2
LOCATION:	AREA S	
ACTIVITY:		
NEWTONS POOL - REMEDIATION.		
SPECIAL FEATURES:		




--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
25/9/93	64/4533	3
LOCATION:	AREA S	
ACTIVITY:		
NEWTONS POOL - REMEDIATION.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
25/9/93	64/4533	4
LOCATION:	AREAS	
ACTIVITY:		
NEWTONS POOL - REMEDIATION.		
SPECIAL FEATURES:		
PREPARING BUNDED AREA FOR STOCKPILING ARISINGS.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
25/9/93	64/4533	5
LOCATION:	AREA M	
ACTIVITY:		
NEWTONS POOL REMEDIATION.		
SPECIAL FEATURES:		
CORING PRECAST MANHOLE RINGS TO USE AS 'PUMP SUMPS'.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
25/9/93	64/4533	6
LOCATION:	AREA S	
ACTIVITY:		
NEWTONS POOL - REMEDIATION.		
SPECIAL FEATURES:		
RE-ARRANGING PUMP SUCTION LINES.		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
25/9/93	64/4533	7
LOCATION:	AREAS	
ACTIVITY:		
NEWTONS POOL - REMEDIATION.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
25/9/93	64/4533	8
LOCATION:	AREA S	
ACTIVITY:		
NEWTONS POOL - REMEDIATION.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
25/9/93	64/4533	9
LOCATION:	AREA S	

ACTIVITY:
NEWTONS POOL - REMEDIATION.
SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
26/9/93	64/4533	10



LOCATION:	AREAS	
ACTIVITY:		
NEWTONS POOL - REMEDIATION.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE

REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
26/9/93	64/4533	11
LOCATION:	AREA S	
ACTIVITY:		
NEWTONS POOL - REMEDIATION.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
26/9/93	64/4533	12
LOCATION:	AREAS	
ACTIVITY:		
NEWTONS POOL - REMEDIATION.		
SPECIAL FEATURES:		

--


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
26/9/93	64/4533	13
LOCATION:	AREA S	
ACTIVITY:		
NEWTONS POOL - REMEDIATION.		
SPECIAL FEATURES:		
LONG REACH EXCAVATOR IN USE.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
26/9/93	64/4533	14
LOCATION:	AREA S	
ACTIVITY:		
NEWTONS POOL - REMEDIATION.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
26/9/93	64/4533	15
LOCATION:	AREAS	
ACTIVITY:		
NEWTONS POOL - REMEDIATION.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
26/9/93	64/4533	16
LOCATION:	AREA S	
ACTIVITY:		
NEWTONS POOL - REMEDIATION.		
SPECIAL FEATURES:		
GROUND WATER INGRESS FROM GRAVEL SUB-STRATA.		





**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
26/9/93	65/2767	1
LOCATION:	AREA S	
ACTIVITY:		
NEWTONS POOL - REMEDIATION.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
26/9/93	65/2767	2
LOCATION:	AREA S	
ACTIVITY:		
NEWTONS POOL - REMEDIATION.		
SPECIAL FEATURES:		
GROUND WATER INGRESS FROM GRAVEL STRATUM.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
26/9/93	65/2767	3
LOCATION:	AREAS	
ACTIVITY:		
NEWTONS POOL - REMEDIATION.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
26/9/93	65/2767	4
LOCATION:	AREA S	
ACTIVITY:		
NEWTONS POOL - REMEDIATION.		
SPECIAL FEATURES:		

GROUND WATER INGRESS FROM GRAVEL STRATUM.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
26/9/93	65/2767	5
LOCATION:	AREAS	
ACTIVITY:		
NEWTONS POOL - REMEDIATION.		

SPECIAL FEATURES:
GROUND WATER INGRESS FROM GRAVEL STRATUM.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
26/9/93	65/2767	6


LOCATION:	AREAS	
ACTIVITY:		
NEWTONS POOL - REMEDIATION.		
SPECIAL FEATURES:		
GROUND WATER INGRESS FROM GRAVEL STRATUM.		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
26/9/93	65/2767	7
LOCATION:	AREA S	
ACTIVITY:		
NEWTONS POOL - REMEDIATION.		
SPECIAL FEATURES:		
GROUND WATER INGRESS FROM GRAVEL STRATUM.		



--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
26/9/93	65/2767	8
LOCATION:	AREA S	
ACTIVITY:		
NEWTONS POOL - REMEDIATION.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
26/9/93	65/2767	9
LOCATION:	AREA S	
ACTIVITY:		
NEWTONS POOL - REMEDIATION.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
26/9/93	65/2767	10
LOCATION:	AREAS	
ACTIVITY:		
NEWTONS POOL - REMEDIATION.		
SPECIAL FEATURES:		

GROUND WATER INGRESS FROM GRAVEL STRATUM.



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
26/9/93	65/2767	11
LOCATION:	AREA S	
ACTIVITY:		
NEWTONS POOL - REMEDIATION.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
26/9/93	65/2767	12


LOCATION:	AREAS	
ACTIVITY:		
NEWTONS POOL - REMEDIATION.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
26/9/93	65/2767	13
LOCATION:	AREA S	
ACTIVITY:		
NEWTONS POOL - REMEDIATION.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
26/9/93	65/2767	14
LOCATION:	AREA S	
ACTIVITY:		
NEWTONS POOL - REMEDIATION.		
SPECIAL FEATURES:		
GROUND WATER INGRESS FROM GRAVEL STRATUM.		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/9/93	65/2767	15
LOCATION:	AREA S	
ACTIVITY:		
NEWTONS POOL - REMEDIATION.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/9/93	65/2767	16
LOCATION:	AREAS	
ACTIVITY:		
NEWTONS POOL - REMEDIATION.		
SPECIAL FEATURES:		

BLUE ASBESTOS FOUND.

Empty rectangular box for additional information or notes.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
28/9/93	65/2767	17
LOCATION:	AREA S	
ACTIVITY:		
NEWTONS POOL - REMEDIATION.		

SPECIAL FEATURES:
ORIGINAL TIMBER PILES TO SLUICE.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
28/9/93	65/2767	18

LOCATION:	AREAS	
ACTIVITY:		
NEWTONS POOL - REMEDIATION.		
SPECIAL FEATURES:		
ORIGINAL TIMBER PILES TO SLUICE.		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
28/9/93	65/2767	19
LOCATION:	AREA S	
ACTIVITY:		
NEWTONS POOL - REMEDIATION.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
28/9/93	65/2767	20
LOCATION:	AREA S	
ACTIVITY:		
NEWTONS POOL - REMEDIATION.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
28/9/93	65/2767	21
LOCATION:	AREA S	
ACTIVITY:		
NEWTONS POOL - REMEDIATION.		
SPECIAL FEATURES:		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
28/9/93	65/2767	22
LOCATION:	AREAS	
ACTIVITY:		
NEWTONS POOL - REMEDIATION.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
28/9/93	65/2767	23
LOCATION:	AREA S	
ACTIVITY:		
NEWTONS POOL - REMEDIATION.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
28/9/93	65/2767	24

LOCATION:	AREAS	
ACTIVITY:		
NEWTONS POOL - REMEDIATION.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
28/9/93	65/2767	25
LOCATION:	AREA S	
ACTIVITY:		
NEWTONS POOL - REMEDIATION.		
SPECIAL FEATURES:		




FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
29/9/93	66/2768	1
LOCATION:	AREA P	
ACTIVITY:		
REMEDIATION IN PROGRESS - LOOKING NORTH.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
29/9/93	66/2768	2
LOCATION:	AREA P	
ACTIVITY:		
REMEDATION IN PROGRESS - LOOKING NORTH.		
SPECIAL FEATURES:		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
29/9/93	66/2768	3
LOCATION:	AREA P	
ACTIVITY:		
REMEDIATION LOOKING WEST.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
29/9/93	66/2768	4
LOCATION:	AREA P	
ACTIVITY:		
REMEDIATION.		
SPECIAL FEATURES:		

ANCIENT FOUNDATION REVEALED.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
29/9/93	66/2768	5
LOCATION:	AREA P	
ACTIVITY:		
REMEDICATION.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
29/9/93	66/2768	6

LOCATION:	AREA P	
ACTIVITY:		
REMEDATION.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
30/9/93	66/2768	7
LOCATION:	AREA P	
ACTIVITY:		
REMEDICATION.		
SPECIAL FEATURES:		
INGRESS OF WATER FROM MILLHEAD STREAM THROUGH FAULTY EMBANKMENT.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
30/9/93	66/2768	8
LOCATION:	AREA P	
ACTIVITY:		
REMEDICATION.		
SPECIAL FEATURES:		
INGRESS OF WATER FROM MILLHEAD STREAM THROUGH FAULTY EMBANKMENT.		




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
5/10/93	66/2768	9
LOCATION:	AREA S	
ACTIVITY:		
NEWTONS POOL - REMEDIATION.		
SPECIAL FEATURES:		
'DEFLATED FOOTBALL RECOVERED'.		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
5/10/93	66/2768	10
LOCATION:	AREA S	
ACTIVITY:		
NEWTONS POOL - REMEDIATION.		
SPECIAL FEATURES:		

'DEFLATED FOOTBALL RECOVERED'.



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
5/10/93	66/2768	11
LOCATION:	AREA S	
ACTIVITY:		
NEWTONS POOL - REMEDIATION.		

SPECIAL FEATURES:
'DEFLATED FOOTBALL RECOVERED'.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
7/10/93	66/2768	13

LOCATION:	AREA H	
ACTIVITY:		
VIEW FROM BUILDING A201 LOOKING WEST TO BUILDING H10.		
SPECIAL FEATURES:		
HOPPITS POOL (BEFORE REMEDIATION).		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
7/10/93	66/2768	14
LOCATION:	AREA H	
ACTIVITY:		
VIEW FROM BUILDING A201LOOKING WEST TO BUILDING H10.		
SPECIAL FEATURES:		
HOPPITS POOL (BEFORE REMEDIATION).		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
7/10/93	66/2768	15
LOCATION:	AREA H	
ACTIVITY:		
VIEW FROM BUILDING A201 LOOKING WEST TO BUILDING H10.		
SPECIAL FEATURES:		
HOPPITS POOL (BEFORE REMEDIATION).		




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
7/10/93	66/2768	16
LOCATION:	AREA H	
ACTIVITY:		
VIEW FROM BUILDING A201LOOKING WEST TO BUILDING H10.		
SPECIAL FEATURES:		
HOPPITS POOL (BEFORE REMEDIATION).		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
8/10/93	66/2768	17
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - REMEDIATION.		
SPECIAL FEATURES:		



DRIVE SHAFT IN UNDERCROFT ZONE.



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
8/10/93	66/2768	18
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - REMEDIATION.		

SPECIAL FEATURES:
DRIVE SHAFT IN UNDERCROFT ZONE.


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
8/10/93	66/2768	19

LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - REMEDIATION.		
SPECIAL FEATURES:		
DRIVE SHAFT IN UNDERCROFT ZONE.		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
8/10/93	66/2768	20
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - REMEDIATION.		
SPECIAL FEATURES:		
DRIVE SHAFT IN UNDERCROFT ZONE.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
8/10/93	66/2768	21
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - REMEDIATION.		
SPECIAL FEATURES:		
DRIVE SHAFT IN UNDERCROFT ZONE.		




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
8/10/93	66/2768	22
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - REMEDIATION.		
SPECIAL FEATURES:		
DRIVE SHAFT IN UNDERCROFT ZONE.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
8/10/93	66/2768	23
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - REMEDIATION.		
SPECIAL FEATURES:		

DRIVE SHAFT IN UNDERCROFT ZONE.




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
8/10/93	66/2768	24
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - REMEDIATION.		





SPECIAL FEATURES:

DRIVE SHAFT IN UNDERCROFT ZONE.




**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
11/10/93	67/2769	1
LOCATION:	AREA	
ACTIVITY:		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
11/10/93	67/2769	2
LOCATION:	AREA P	
ACTIVITY:		
EXCAVATED CANAL NORTH OF BUILDINGS A230 - A234.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
11/10/93	67/2769	3
LOCATION:	AREA P	
ACTIVITY:		
EXCAVATION OF CANAL NORTH OF BUILDINGS A230 - A234.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
11/10/93	67/2769	4
LOCATION:	AREA P	
ACTIVITY:		
EXCAVATED CANAL NORTH OF BUILDING A230 - A234.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
11/10/93	67/2769	5
LOCATION:	AREA P	
ACTIVITY:		
REMEDATION.		

SPECIAL FEATURES:
REMAINS OF ANCIENT STRUCTURES EXPOSED.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
11/10/93	67/2769	6

LOCATION:	AREA P	
ACTIVITY:		
REMEDATION.		
SPECIAL FEATURES:		
REMAINS OF ANCIENT STRUCTURES EXPOSED.		



**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDICATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
11/10/93	67/2769	7
LOCATION:	AREA P	
ACTIVITY:		
REMEDICATION.		
SPECIAL FEATURES:		
REMAINS OF ANCIENT STRUCTURES EXPOSED.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
11/10/93	67/2769	8
LOCATION:	AREA P	
ACTIVITY:		
REMEDIATION.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
11/10/93	67/2769	9
LOCATION:	AREA P	
ACTIVITY:		
REMEDIATION - LOOKING SOUTH EAST.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
11/10/93	67/2769	10
LOCATION:	AREA P	
ACTIVITY:		
REMEDIATION.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
11/10/93	67/2769	11
LOCATION:	AREA P	
ACTIVITY:		
REMEDICATION.		

SPECIAL FEATURES:
SAMPLING PEGS IN POSITION (BUILDING A269 IN BACKGROUND).

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
11/10/93	67/2769	12


LOCATION:	AREA P	
ACTIVITY:		
REMEDIATION.		
SPECIAL FEATURES:		
SAMPLING PEGS IN POSITION (BUILDINGS A230 - A234 IN BACKGROUND).		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
11/10/93	67/2769	13
LOCATION:	AREA P	
ACTIVITY:		
REMEDIATION.		
SPECIAL FEATURES:		
SAMPLING PEGS IN POSITION (BUILDINGS A230 - A234 IN BACKGROUND).		



--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
11/10/93	67/2769	14
LOCATION:	AREA P	
ACTIVITY:		
REMEDICATION.		
SPECIAL FEATURES:		
SAMPLING PEGS IN POSITION (BUILDINGS A230 - A234 IN BACKGROUND).		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
11/10/93	67/2769	15
LOCATION:	AREA P	
ACTIVITY:		
REMEDICATION.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
11/10/93	67/2769	16
LOCATION:	AREA T	
ACTIVITY:		
REMEDIATION.		
SPECIAL FEATURES:		

ROUTE OF FILLED CANAL DEFINED BY CLAYWARE AND BRICK INFILL  
(CONTAINING BLUE ASBESTOS).



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
11/10/93	67/2769	17
LOCATION:	AREA T	
ACTIVITY:		
REMEDICATION.		


SPECIAL FEATURES:
ROUTE OF FILLED CANAL DEFINED BY CLAYWARE AND BRICK INFILL (CONTAINING BLUE ASBESTOS).

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
11/10/93	67/2769	18

LOCATION:	AREAT	
ACTIVITY:		
REMEDATION.		
SPECIAL FEATURES:		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDiation RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
11/10/93	67/2769	19
LOCATION:	AREA T	
ACTIVITY:		
REMEDIATION.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
11/10/93	67/2769	20
LOCATION:	AREA T	
ACTIVITY:		
REMEDIATION.		
SPECIAL FEATURES:		
SUBSTRUCTURE OF FORMER GUNPOWDER STOVE EXPOSED. YELLOW AIR MONITORING STATION AT TOP RIGHT OF PICTURE.		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
11/10/93	67/2769	21
LOCATION:	AREA T	
ACTIVITY:		
REMEDICATION.		
SPECIAL FEATURES:		
SUBSTRUCTURE OF FORMER GUNPOWDER STOVE EXPOSED.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
11/10/93	67/2769	22
LOCATION:	AREA T	
ACTIVITY:		
REMEDIATION.		
SPECIAL FEATURES:		

NOTE YELLOW DISCOLOURATION OF SURFACE WATER.




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
11/10/93	67/2769	23
LOCATION:	AREA T	
ACTIVITY:		
REMEDIATION.		

SPECIAL FEATURES:
CONTAMINATED PIPEWORK SEPARATED OUT AS WORK PROCEEDS.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
11/10/93	67/2769	24

LOCATION:	AREAT	
ACTIVITY:		
REMEDATION.		
SPECIAL FEATURES:		
CLEAR DEFINITION OF CANAL INFILL.		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
11/10/93	67/2769	25
LOCATION:	AREA P	
ACTIVITY:		
EXCAVATION OF CANAL NORTH OF BUILDINGS A230 - A234.		
SPECIAL FEATURES:		




FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
14/10/93	68/3118	1
LOCATION:	AREA S	
ACTIVITY:		
EDMONSEY SLUICE LOOKING WEST.		
SPECIAL FEATURES:		



--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
14/10/93	68/3118	2
LOCATION:	AREA S	
ACTIVITY:		
EDMONSEY SLUICE LOOKING WEST.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
14/10/93	68/3118	3
LOCATION:	AREAS	
ACTIVITY:		
EDMONSEY SLUICE LOOKING WEST.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
14/10/93	68/3118	4
LOCATION:	AREA S	
ACTIVITY:		
EDMONSEY SLUICE LOOKING WEST - IN FLOOD.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
14/10/93	68/3118	5
LOCATION:	AREAS	
ACTIVITY:		
EDMONSEY SLUICE LOOKING NORTH WEST - IN FLOOD.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
14/10/93	68/3118	6

LOCATION:	AREAS	
ACTIVITY:		
EDMONSEY SLUICE LOOKING NORTH WEST - IN FLOOD.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
14/10/93	68/3118	7
LOCATION:	AREA S	
ACTIVITY:		
EDMONSEY SLUICE LOOKING NORTH WEST - IN FLOOD.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
14/10/93	68/3118	8
LOCATION:	AREA S	
ACTIVITY:		
NEWTONS POOL - TEMPORARY SHEET PILING IN PLACE.		
SPECIAL FEATURES:		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
14/10/93	68/3118	9
LOCATION:	AREA S	
ACTIVITY:		
NEWTONS POOL - VIEW LOOKING WEST.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
14/10/93	68/3118	10
LOCATION:	AREAS	
ACTIVITY:		
NEWTONS POOL - VIEW LOOKING WEST.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
14/10/93	68/3118	11
LOCATION:	AREA S	
ACTIVITY:		
AREA NORTH OF BUILDING S34 BEING SCRAPED.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
14/10/93	68/3118	12


LOCATION:	AREA T	
ACTIVITY:		
VIEW OF HORSEMILL STREAM LOOKING SOUTH.		
SPECIAL FEATURES:		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
14/10/93	68/3118	13
LOCATION:	AREA T	
ACTIVITY:		
VIEW OF TETRYL AREA LOOKING SOUTH.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
14/10/93	68/3118	14
LOCATION:	AREA T	
ACTIVITY:		
VIEW ACROSS HORSEMILL STREAM FROM TETRYL AREA LOOKING WEST.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
14/10/93	68/3118	15
LOCATION:	AREA S	
ACTIVITY:		
BRIDGE No. 11 LEADING TO NEW HILL.		
SPECIAL FEATURES:		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
14/10/93	68/3118	16
LOCATION:	AREA S	
ACTIVITY:		
OLD RIVER LEA IN FLOOD WEST OF NEWTONS POOL.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
14/10/93	68/3118	17
LOCATION:	AREA S	
ACTIVITY:		
BUILDINGS 148 AND 149 IN 'BARREL GRAVEYARD'.		

SPECIAL FEATURES:
OLD TIMBER STEAM MAIN SUPPORTS.


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
14/10/93	68/3118	18

LOCATION:	AREAS	
ACTIVITY:		
GENERAL VIEW OF WOODED AREA.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
14/10/93	68/3118	19
LOCATION:	AREAS	
ACTIVITY:		
GENERAL VIEW OF WOODED AREA.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
14/10/93	68/3118	20
LOCATION:	AREA S	
ACTIVITY:		
GENERAL VIEW OF WOODED AREA.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
14/10/93	68/3118	21
LOCATION:	AREA S	
ACTIVITY:		
VIEW TOWARDS BUILDING U6 IN 'BARREL GRAVEYARD'.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
14/10/93	68/3118	22
LOCATION:	AREAS	
ACTIVITY:		
L.G.C. PERSONNEL PREPARING FOR SAMPLING.		
SPECIAL FEATURES:		





<b>FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD</b>		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
14/10/93	68/3118	23
LOCATION:	AREA M	
ACTIVITY:		
BRIDGE No. 6 LOOKING TOWARDS BUILDINGS L143 AND L134.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
14/10/93	68/3118	24

LOCATION:	AREA M	
ACTIVITY:		
MILLHEAD STREAM LOOKING SOUTH EAST, ACROSS CORDITE CONTAMINATED AREA.		
SPECIAL FEATURES:		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
14/10/93	68/3118	25
LOCATION:	AREA M	
ACTIVITY:		
SCREENED CORDITE CONTAMINATED MATERIAL AWAITING SAMPLING.		
SPECIAL FEATURES:		
BUILDINGS L159 AND L151 IN BACKGROUND.		




FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
14/10/93	69/3115	1
LOCATION:	AREA S	
ACTIVITY:		
EDMONSEY SLUICE - LOOKING WEST.		
SPECIAL FEATURES:		
RIVER IN FLOOD.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
14/10/93	69/3115	2
LOCATION:	AREA S	
ACTIVITY:		
EDMONSEY SLUICE - LOOKING WEST.		
SPECIAL FEATURES:		
RIVER IN FLOOD.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
14/10/93	69/3115	3
LOCATION:	AREA S	
ACTIVITY:		
HORSEMILL STREAM (NORTH OF EDMONSEY SLUICE).		
SPECIAL FEATURES:		
RIVER IN FLOOD.		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
14/10/93	69/3115	4
LOCATION:	AREA S	
ACTIVITY:		
EDMONSEY SLUICE - LOOKING WEST.		
SPECIAL FEATURES:		

RIVER IN FLOOD.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
14/10/93	69/3115	5
LOCATION:	AREAS	
ACTIVITY:		
EDMONSEY SLUICE - LOOKING WEST.		

SPECIAL FEATURES:
RIVER IN FLOOD.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
14/10/93	69/3115	6

LOCATION:	AREAS	
ACTIVITY:		
HORSEMILL STREAM SOUTH OF EDMONSEY SLUICE.		
SPECIAL FEATURES:		
RIVER IN FLOOD.		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
14/10/93	69/3115	7
LOCATION:	AREA S	
ACTIVITY:		
HORSEMILL STREAM SOUTH OF EDMONSEY SLUICE.		
SPECIAL FEATURES:		
RIVER IN FLOOD.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
14/10/93	69/3115	8
LOCATION:	AREA P	
ACTIVITY:		
EXCAVATION OF CANAL NORTH OF BUILDINGS A230 - A234.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
14/10/93	69/3115	9
LOCATION:	AREA N	
ACTIVITY:		
L.G.C. SAMPLING AT NEW HILL.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
14/10/93	69/3115	10
LOCATION:	AREA N	
ACTIVITY:		
L.G.C. SAMPLING AT NEW HILL.		
SPECIAL FEATURES:		




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
14/10/93	69/3115	11
LOCATION:	AREA M	
ACTIVITY:		
SCREENED CORDITE CONTAMINATED MATERIAL AWAITING SAMPLING.		

SPECIAL FEATURES:
BUILDING L159 IN BACKGROUND.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
14/10/93	69/3115	12

LOCATION:	AREA M	
ACTIVITY:		
CORDITE SCREENED MATERIAL STOCKPILED AWAITING SAMPLING.		
SPECIAL FEATURES:		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
14/10/93	69/3115	13
LOCATION:	AREA M	
ACTIVITY:		
CORDITE SCREENED MATERIAL STOCKPILED AWAITING SAMPLING.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
14/10/93	69/3115	14
LOCATION:	AREA H	
ACTIVITY:		
H16 AREA - EXCAVATED MATERIAL FROM NEWTONS POOL BEING SCRUTINISED.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
14/10/93	69/3115	15
LOCATION:	AREA H	
ACTIVITY:		
H16 AREA - EXCAVATED MATERIAL FROM NEWTONS POOL BEING SCRUTINISED.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
15/10/93	69/3115	16
LOCATION:	AREA P	
ACTIVITY:		
SITE VEHICLE STUCK.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
15/10/93	69/3115	17
LOCATION:	AREA P	
ACTIVITY:		
SITE VEHICLE AWAITING A TOW.		



SPECIAL FEATURES:


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
15/10/93	69/3115	18

LOCATION:	AREA H	
ACTIVITY:		
SHELL FOUND ON H16 AREA IN MATERIAL FROM NEWTONS POOL.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
15/10/93	69/3115	19
LOCATION:	AREA H	
ACTIVITY:		
SHELL ON H16 AREA FOUND IN MATERIAL FROM NEWTONS POOL.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
15/10/93	69/3115	20
LOCATION:	AREA H	
ACTIVITY:		
MARKINGS ON SHELL FOUND IN MATERIAL ON H16 AREA FROM NEWTONS POOL.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
15/10/93	69/3115	22
LOCATION:	AREA H	
ACTIVITY:		
SHELL FOUND IN MATERIAL FROM NEWTONS POOL ON H16 AREA.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
18/10/93	69/3115	23
LOCATION:	AREA H	
ACTIVITY:		
BUILDING H12 - AFTER 'HEAT TREATMENT'.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
18/10/93	69/3115	24
LOCATION:	AREA H	
ACTIVITY:		
BUILDING H12 - AFTER 'HEAT TREATMENT'.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
18/10/93	69/3115	25



LOCATION:	AREA H	
ACTIVITY:		
BUILDING H12 - AFTER 'HEAT TREATMENT'.		
SPECIAL FEATURES:		




FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/10/93	70/6136	1
LOCATION:	AREA H	
ACTIVITY:		
LAYING OUT CONTAMINATED WASTE ON H16 AREA FOR SAMPLING.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/10/93	70/6136	2
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - BREAKING OUT CONCRETE FLOOR.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/10/93	70/6136	3
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - EXTERNAL VIEW OF UNDERCROFT.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/10/93	70/6136	4
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - SOUTH EAST CORNER.		
SPECIAL FEATURES:		

STRUCTURAL DEFECTS IN PARAPET BRICKWORK.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/10/93	70/6136	5
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - REMEDIATION.		

SPECIAL FEATURES:
ARISINGS STOCKPILED OUTSIDE BUILDING.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/10/93	70/6136	6



LOCATION:	AREA M	
ACTIVITY:		
BUILDING L145 - SCAFFOLDING FOR ROOF WORKS.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/10/93	70/6136	7
LOCATION:	AREA S	
ACTIVITY:		
CANAL REMEDIATION ADJACENT TO BUILDING E14.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/10/93	70/6136	8
LOCATION:	AREA S	
ACTIVITY:		
WASTE MATERIAL BEING EXCAVATED FROM BUILDINGS 88A TO E14.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/10/93	70/6136	9
LOCATION:	AREA S	
ACTIVITY:		
CANAL REMEDIATION NORTH OF BUILDING 88A.		
SPECIAL FEATURES:		
RED BAGS INDICATE BAGGED ASBESTOS WASTE.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/10/93	70/6136	10
LOCATION:	AREAS	
ACTIVITY:		
NEWTONS POOL.		
SPECIAL FEATURES:		

NEW SLUICE WORKS IN PROGRESS.

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/10/93	70/6136	11
LOCATION:	AREA S	
ACTIVITY:		
NEWTONS POOL.		

SPECIAL FEATURES:
NEW SLUICE WORKS IN PROGRESS.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/10/93	70/6136	12

LOCATION:	AREAS	
ACTIVITY:		
NEWTONS POOL - REMEDIATION.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/10/93	70/6136	13
LOCATION:	AREA S	
ACTIVITY:		
NEWTONS POOL - REMEDIATION.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/10/93	70/6136	14
LOCATION:	AREA S	
ACTIVITY:		
NEWTONS POOL - NEW SLUICE WORKS IN PROGRESS.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/10/93	70/6136	15
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - UNDERCROFT EXPOSED.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/10/93	70/6136	16
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - UNDERCROFT EXPOSED.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/10/93	70/6136	17
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - REMEDIATION.		

SPECIAL FEATURES:
UNDERCROFT INFILL MATERIAL.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/10/93	70/6136	18

LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - REMEDIATION.		
SPECIAL FEATURES:		
DRIVE SHAFT IN UNDERCROFT.		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/10/93	70/6136	19
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - REMEDIATION.		
SPECIAL FEATURES:		
COLLAPSING TIMBER SHORING TO UNDERCROFT.		



--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/10/93	70/6136	20
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - REMEDIATION.		
SPECIAL FEATURES:		
UNDERCROFT.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/10/93	70/6136	21
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - REMEDIATION.		
SPECIAL FEATURES:		
UNDERCROFT.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/10/93	70/6136	22
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - REMEDIATION.		
SPECIAL FEATURES:		

UNDERCROFT.



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/10/93	70/6136	23
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - REMEDIATION.		

SPECIAL FEATURES:
UNDERCROFT.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/10/93	70/6136	24


LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - REMEDIATION.		
SPECIAL FEATURES:		
UNDERCROFT.		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
28/10/93	70/6136	25
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - REMEDIATION.		
SPECIAL FEATURES:		
ASBESTOS LAGGED SERVICES IN CEILING VOID.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
28/10/93	70/6136	26
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - REMEDIATION.		
SPECIAL FEATURES:		
ASBESTOS LAGGED SERVICES IN CEILING VOID.		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
28/10/93	70/6136	27
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - REMEDIATION.		
SPECIAL FEATURES:		
ASBESTOS LAGGED SERVICES IN CEILING VOID.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
30/10/93	70/6136	28
LOCATION:	AREA B	
ACTIVITY:		
WASTE TIMBER STACKED AS FUEL FOR 'HEAT TREATMENT'.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
30/10/93	70/6136	29
LOCATION:	AREA B	
ACTIVITY:		
WASTE TIMBER FROM REMEDIATION WORKS IN INCORPORATING MILLS.		

SPECIAL FEATURES:
PREPARATION FOR BURNING POTENTIALLY EXPLOSIVELY CONTAMINATED MATERIALS.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
30/10/93	70/6136	30


LOCATION:	AREA B	
ACTIVITY:		
FIRING IN PROGRESS.		
SPECIAL FEATURES:		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
30/10/93	70/6136	31
LOCATION:	AREA B	
ACTIVITY:		
FIRING IN PROGRESS.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
5/11/93	70/6136	32
LOCATION:	AREA B	
ACTIVITY:		
FIRING IN PROGRESS.		
SPECIAL FEATURES:		




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
5/11/93	70/6136	34
LOCATION:	AREA (A201/2)	
ACTIVITY:		
ROYAL ORDNANCE SUPERVISOR DOING PAPERWORK.		
SPECIAL FEATURES:		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
5/11/93	70/6136	35
LOCATION:	AREA (A201/2)	
ACTIVITY:		
SITE ENGINEER GETTING A POINT OVER TO SITE ARCHAEOLOGIST.		
SPECIAL FEATURES:		




**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/11/93	71/6133	1
LOCATION:	AREA S	
ACTIVITY:		
BUILDING 27 - VIEWED FROM ACROSS HORSEMILL STREAM (LOOKING EAST).		
SPECIAL FEATURES:		
CANAL INTERSECTIONS 27 AND 29.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/11/93	71/6133	2
LOCATION:	AREA S	
ACTIVITY:		
VIEW ACROSS HORSEMILL STREAM LOOKING EAST.		
SPECIAL FEATURES:		
AREA S RIVER BANK AND CANAL INTERSECTIONS 27 AND 29.		




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/11/93	71/6133	3
LOCATION:	AREA T	
ACTIVITY:		
VIEW ACROSS HORSEMILL STREAM LOOKING EAST.		
SPECIAL FEATURES:		
AREA T RIVER BANK AND CANAL INTERSECTION 27.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/11/93	71/6133	4
LOCATION:	AREA T	
ACTIVITY:		
VIEW ACROSS HORSEMILL STREAM LOOKING EAST.		
SPECIAL FEATURES:		

AREA T RIVER BANK AND CANAL INTERSECTION 26.



**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDICATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/11/93	71/6133	5
LOCATION:	AREA T	
ACTIVITY:		
VIEW ACROSS HORSEMILL STREAM LOOKING EAST.		

SPECIAL FEATURES:
AREA T RIVER BANK AND CANAL INTERSECTION 25 (TO THE RIGHT).

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/11/93	71/6133	6



LOCATION:	AREA T	
ACTIVITY:		
VIEW ACROSS HORSEMILL STREAM LOOKING EAST.		
SPECIAL FEATURES:		
AREA T RIVER BANK AND CANAL INTERSECTION 25 (TO THE RIGHT).		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/11/93	71/6133	7
LOCATION:	AREA T	
ACTIVITY:		
VIEW ACROSS HORSEMILL STREAM LOOKING EAST.		
SPECIAL FEATURES:		
AREA T RIVER BANK AND CANAL INTERSECTION 26.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/11/93	71/6133	8
LOCATION:	AREA T	
ACTIVITY:		
VIEW ACROSS HORSEMILL STREAM LOOKING EAST.		
SPECIAL FEATURES:		
AREA T RIVER BANK AND CANAL INTERSECTION 26.		




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/11/93	71/6133	9
LOCATION:	AREA T	
ACTIVITY:		
VIEW ACROSS HORSEMILL STREAM LOOKING EAST.		
SPECIAL FEATURES:		
BUILDING E2 IN BACKGROUND WITH AREA T RIVER BANK AND CANAL INTERSECTION 25.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/11/93	71/6133	10
LOCATION:	AREA T	
ACTIVITY:		
VIEW ACROSS HORSEMILL STREAM LOOKING EAST.		
SPECIAL FEATURES:		

BUILDING E2 IN BACKGROUND WITH AREA T RIVER BANK AND CANAL  
INTERSECTION 25.



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/11/93	71/6133	11
LOCATION:	AREA T	
ACTIVITY:		
VIEW ACROSS HORSEMILL STREAM LOOKING EAST.		

SPECIAL FEATURES:
BUILDING E2 IN BACKGROUND WITH AREA T RIVER BANK.


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/11/93	71/6133	12

LOCATION:	AREA T	
ACTIVITY:		
VIEW ACROSS HORSEMILL STREAM LOOKING EAST.		
SPECIAL FEATURES:		
BUILDING E2 IN BACKGROUND WITH AREA T RIVER BANK.		




**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/11/93	71/6133	13
LOCATION:	AREA T	
ACTIVITY:		
VIEW ACROSS HORSEMILL STREAM LOOKING EAST.		
SPECIAL FEATURES:		
BUILDING E2 IN BACKGROUND WITH AREA T RIVER BANK.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/11/93	71/6133	14
LOCATION:	AREA T	
ACTIVITY:		
VIEW ACROSS HORSEMILL STREAM LOOKING EAST.		
SPECIAL FEATURES:		
AREA T RIVER BANK.		




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/11/93	71/6133	15
LOCATION:	AREA T	
ACTIVITY:		
VIEW ACROSS HORSEMILL STREAM LOOKING EAST.		
SPECIAL FEATURES:		
STOCKPILE OF WASTE AND AREA T RIVER BANK.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/11/93	71/6133	16
LOCATION:	AREA T	
ACTIVITY:		
VIEW ACROSS HORSEMILL STREAM LOOKING EAST.		
SPECIAL FEATURES:		

STOCKPILE OF WASTE AND AREA T RIVER BANK.



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/11/93	71/6133	17
LOCATION:	AREA T	
ACTIVITY:		
VIEW ACROSS HORSEMILL STREAM LOOKING EAST.		

SPECIAL FEATURES:
AREA T RIVER BANK.


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/11/93	71/6133	18

LOCATION:	AREA T	
ACTIVITY:		
VIEW ACROSS HORSEMILL STREAM LOOKING EAST.		
SPECIAL FEATURES:		
AREA T RIVER BANK.		


**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/11/93	71/6133	19
LOCATION:	AREA T	
ACTIVITY:		
VIEW ACROSS HORSEMILL STREAM LOOKING EAST.		
SPECIAL FEATURES:		
AREA T RIVER BANK.		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/11/93	71/6133	20
LOCATION:	AREA T	
ACTIVITY:		
VIEW ACROSS HORSEMILL STREAM LOOKING EAST.		
SPECIAL FEATURES:		
AREA T RIVER BANK.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/11/93	71/6133	21
LOCATION:	AREA T	
ACTIVITY:		
VIEW ACROSS HORSEMILL STREAM LOOKING EAST TOWARDS BUILDING E10.		
SPECIAL FEATURES:		
AREA T RIVER BANK.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/11/93	71/6133	22
LOCATION:	AREA T	
ACTIVITY:		
VIEW ACROSS HORSEMILL STREAM LOOKING EAST TOWARDS BUILDING E10.		
SPECIAL FEATURES:		

AREA T RIVER BANK.



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/11/93	71/6133	23
LOCATION:	AREA T	
ACTIVITY:		
VIEW ACROSS HORSEMILL STREAM LOOKING EAST TOWARDS BUILDING		


E10.
SPECIAL FEATURES:
AREA T RIVER BANK.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/11/93	71/6133	24

LOCATION:	AREA S	
ACTIVITY:		
VIEW ACROSS HORSEMILL STREAM LOOKING EAST - SOUTH OF BUILDING E10.		
SPECIAL FEATURES:		
RIVER BANK TO ACID FACTORY AND CANAL INTERSECTION 21.		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDICATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/11/93	71/6133	25
LOCATION:	AREA S	
ACTIVITY:		
VIEW ACROSS HORSEMILL STREAM LOOKING EAST.		
SPECIAL FEATURES:		
SITE BANK TO EDMONSEY SLUICE, SLUICE BALANCING DRAIN AND CANAL INTERSECTION 18.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/11/93	71/6133	26
LOCATION:	AREA S	
ACTIVITY:		
VIEW ACROSS HORSEMILL STREAM LOOKING EAST.		
SPECIAL FEATURES:		
CANAL INTERSECTION 18.		






FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/11/93	71/6133	27
LOCATION:	AREA S	
ACTIVITY:		
VIEW ACROSS HORSEMILL STREAM LOOKING EAST.		
SPECIAL FEATURES:		
RIVER BANK CONSTRUCTION JUST SOUTH OF EDMONSEY SLUICE.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/11/93	71/6133	28
LOCATION:	AREAS	
ACTIVITY:		
VIEW ACROSS HORSEMILL STREAM LOOKING EAST.		
SPECIAL FEATURES:		

RIVER BANK CONSTRUCTION JUST SOUTH OF EDMONSEY SLUICE.



**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/11/93	71/6133	29
LOCATION:	AREA S	
ACTIVITY:		
VIEW ACROSS HORSEMILL STREAM LOOKING EAST.		

SPECIAL FEATURES:
RIVER BANK CONSTRUCTION JUST SOUTH OF EDMONSEY SLUICE.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/11/93	71/6133	30

LOCATION:	AREA S	
ACTIVITY:		
VIEW ACROSS HORSEMILL STREAM LOOKING EAST.		
SPECIAL FEATURES:		
RIVER BANK CONSTRUCTION JUST SOUTH OF EDMONSEY SLUICE.		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/11/93	71/6133	31
LOCATION:	AREA P	
ACTIVITY:		
EXCAVATION OF CANAL NORTH OF BUILDING A240.		
SPECIAL FEATURES:		




FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
16/11/93	72/6897	1
LOCATION:	AREA P	
ACTIVITY:		
VIEW OF TREE FELLED BY HIGH WIND.		
SPECIAL FEATURES:		



--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
17/11/93	72/6897	2
LOCATION:	AREA S	
ACTIVITY:		
BRIDGE No. 10 - REPAIRS IN PROGRESS.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
17/11/93	72/6897	3
LOCATION:	AREA S	
ACTIVITY:		
NEWTONS POOL.		
SPECIAL FEATURES:		
CONSTRUCTION OF NEW SLUICE.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
17/11/93	72/6897	4
LOCATION:	AREA S	
ACTIVITY:		
NEWTONS POOL.		
SPECIAL FEATURES:		

CONSTRUCTION OF NEW SLUICE.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
17/11/93	72/6897	5
LOCATION:	AREAS	
ACTIVITY:		
SURVEY.		

SPECIAL FEATURES:
TYPICAL EXAMPLE OF DECAYING ASBESTOS CLAD STEAM MAIN PIPE.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
17/11/93	72/6897	6


LOCATION:	AREAS	
ACTIVITY:		
CANAL WEST OF BUILDING 22A.		
SPECIAL FEATURES:		
ALDER GROWTH.		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
17/11/93	72/6897	7
LOCATION:	AREA S	
ACTIVITY:		
CANAL WEST OF BUILDING 22A.		
SPECIAL FEATURES:		
RIVER GRAVEL INFILL AND ALDER GROWTH.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
17/11/93	72/6897	8
LOCATION:	AREA S	
ACTIVITY:		
CANAL FROM BUILDING 22A TO BUILDING 16A.		
SPECIAL FEATURES:		
ALDERS FELLED FOR ACCESS TO FILLED CANAL.		






FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
17/11/93	72/6897	9
LOCATION:	AREA S	
ACTIVITY:		
CANAL FROM BUILDING 22A TO BUILDING 16A.		
SPECIAL FEATURES:		
ALDERS FELLED FOR ACCESS TO FILLED CANAL.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
17/11/93	72/6897	10
LOCATION:	AREA S	
ACTIVITY:		
CANAL FROM BUILDING 22A TO BUILDING 16A.		
SPECIAL FEATURES:		

BUILDING 18A TO RIGHT OF PICTURE.



**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
17/11/93	72/6897	11
LOCATION:	AREA S	
ACTIVITY:		
CANAL FROM BUILDING 22A TO BUILDING 16A.		

SPECIAL FEATURES:
BUILDING 18A TO RIGHT OF PICTURE.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
17/11/93	72/6897	12

LOCATION:	AREAS	
ACTIVITY:		
NEWTONS POOL.		
SPECIAL FEATURES:		
CONSTRUCTION OF NEW SLUICE.		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
17/11/93	72/6897	13
LOCATION:	AREA S	
ACTIVITY:		
PUMP DISCHARGE FROM NEWTONS POOL.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
17/11/93	72/6897	14
LOCATION:	AREA S	
ACTIVITY:		
CANAL REMEDIATION NEAR BUILDING S30.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
22/11/93	72/6897	15
LOCATION:	AREA B	
ACTIVITY:		
DECONTAMINATION OF FLOOR ASPHALT.		
SPECIAL FEATURES:		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
22/11/93	72/6897	16
LOCATION:	AREA P	
ACTIVITY:		
REMEDIATION.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
22/11/93	72/6897	17
LOCATION:	AREA P	
ACTIVITY:		
REMEDICATION.		

SPECIAL FEATURES:
FILLED CANAL LOCATED SOUTH WEST CORNER OF SITE.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
2/12/93	72/6897	19


LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - BAY 3 STICH CORE DRILLING.		
SPECIAL FEATURES:		
ROYAL ORDNANCE REMOTE CONTROLLED CORE DRILLING RIG.		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDICATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
2/12/93	72/6897	20
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - BAY 3 STITCH CORE DRILLING.		
SPECIAL FEATURES:		
ROYAL ORDNANCE REMOTE CONTROLLED CORE DRILLING RIG.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
2/12/93	72/6897	21
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - BAY 3 STITCH CORE DRILLING.		
SPECIAL FEATURES:		
ROYAL ORDNANCE REMOTE CONTROLLED CORE DRILLING RIG.		




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
2/12/93	72/6897	22
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - BAY 3.		
SPECIAL FEATURES:		
UNDERCROFT INFILL PARTIALLY REMOVED.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
2/12/93	72/6897	23
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - BAY 3.		
SPECIAL FEATURES:		



INCORPORATOR PAN BEARING VISIBLE IN UNDERCROFT INFILL.



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
2/12/93	72/6897	24
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - VOID BELOW STEEL CORRIDOR POST BAY 3.		

SPECIAL FEATURES:
POTENTIAL ZONE OF EXPLOSIVES DUST CONTAMINATION.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
2/12/93	72/6897	25

LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - VOID EXTRA AIR BRICK EAST BAY 3.		
SPECIAL FEATURES:		
POTENTIAL ZONE OF EXPLOSIVES DUST CONTAMINATION.		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
2/12/93	72/6897	26
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - BAY 4.		
SPECIAL FEATURES:		
UNDERFLOOR INFILL REMOVAL.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
2/12/93	72/6897	27
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - BAY 4 WALL PAINT STRIP IN PROGRESS.		
SPECIAL FEATURES:		
DEMONSTRATION ONLY - FULL PERSONAL PROTECTION EQUIPMENT IS WORN WHEN WORK IS IN PROGRESS.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
5/12/93	72/6897	28
LOCATION:	AREA P	
ACTIVITY:		
REMEDIATION.		
SPECIAL FEATURES:		
'DECODEX' SEALANT APPLIED TO EARTH FACES AT BOUNDARY OF SITE.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
5/12/93	72/6897	29
LOCATION:	AREA P	
ACTIVITY:		
REMEDIATION.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
5/12/93	72/6897	30
LOCATION:	AREA P	
ACTIVITY:		
REMEDIATION.		



SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
5/12/93	72/6897	31

LOCATION:	AREA P	
ACTIVITY:		
REMEDATION.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
5/12/93	72/6897	32
LOCATION:	AREA P	
ACTIVITY:		
REMEDATION.		
SPECIAL FEATURES:		
'DECODEX' SEALANT APPLIED TO FACES OF TREE ISLAND.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
5/12/93	72/6897	33
LOCATION:	AREA P	
ACTIVITY:		
REMEDIATION.		
SPECIAL FEATURES:		
BUILDINGS A230 - A234 IN BACKGROUND.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
5/12/93	72/6897	34
LOCATION:	AREA P	
ACTIVITY:		
REMEDICATION.		
SPECIAL FEATURES:		
BUILDING H10 CENTRE BACKGROUND.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
5/12/93	72/6897	35
LOCATION:	AREA P	
ACTIVITY:		
REMEDIATION.		
SPECIAL FEATURES:		

'DECODEX' SEALANT TO PERIMETER BANKS.



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
5/12/93	72/6897	36
LOCATION:	AREA P	
ACTIVITY:		
REMEDIATION.		

SPECIAL FEATURES:
'DECODEX' SEALANT TO SOUTH BOUNDARY FACES.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
5/12/93	72/6897	37



LOCATION:	AREA P	
ACTIVITY:		
REMEDICATION.		
SPECIAL FEATURES:		
'DECODEX' SEALANT TO SOUTH AND WEST BOUNDARY FACES.		




**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
6/12/93	73/7514	1
LOCATION:	AREA	
ACTIVITY:		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
6/12/93	73/7514	2
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - CLEARING WASTE MATERIAL FROM UNDERCROFT.		
SPECIAL FEATURES:		
CARE AND ATTENTION WORKING AROUND DRIVE SHAFTING.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
6/12/93	73/7514	3
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - REMOTE CONTROLLED CORING.		
SPECIAL FEATURES:		
ROYAL ORDNANCE REMOTE CORING RIG.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
6/12/93	73/7514	4
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - PAINT STRIPPED WALL.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
6/12/93	73/7514	5
LOCATION:	AREA P	
ACTIVITY:		
REMEDATION.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
6/12/93	73/7514	6




LOCATION:	AREA P	
ACTIVITY:		
REMEDATION.		
SPECIAL FEATURES:		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
6/12/93	73/7514	7
LOCATION:	AREA P	
ACTIVITY:		
REMEDICATION.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
6/12/93	73/7514	8
LOCATION:	AREA P	
ACTIVITY:		
REMEDIATION.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
8/12/93	73/7514	9
LOCATION:	AREA P	
ACTIVITY:		
WATER CONNECTIONS ADJACENT TO BUILDING A238.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
6/12/93	73/7514	10
LOCATION:	AREA H - ISLAND SITE	
ACTIVITY:		
ROYAL ORDNANCE SITE MANAGER IN CHRISTMAS SPIRIT.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
10/12/93	73/7514	11
LOCATION:	AREA P	
ACTIVITY:		
OUTFALL IN RIVER LEA FROM PMLH EXCAVATED CANAL.		

SPECIAL FEATURES:
PRE-CAST CONCRETE MANHOLE RING SECTIONS USED TO BREAK FORCE OF DISCHARGE WATER.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
10/12/93	73/7514	12

LOCATION:	AREA P	
ACTIVITY:		
POWDERMILL LANE - LAYING NEW WATER MAIN (DIVERSION AROUND P SITE).		
SPECIAL FEATURES:		



**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDICATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
10/12/93	73/7514	13
LOCATION:	AREA P	
ACTIVITY:		
DIVERSION OF F.W.D FROM BUILDING A221.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
10/12/93	73/7514	14
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - EXCAVATING UNDERFLOOR FILLING MATERIAL.		
SPECIAL FEATURES:		




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
15/12/93	73/7514	15
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - EXCAVATING UNDERFLOOR FILLING MATERIAL.		
SPECIAL FEATURES:		
LARGE STEAM ENGINE FOUNDATIONS SHOWN.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
15/12/93	73/7514	16
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - EXCAVATING UNDERFLOOR FILLING MATERIAL.		
SPECIAL FEATURES:		

LARGE STEAM ENGINE FOUNDATIONS SHOWN.



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
15/12/93	73/7514	17
LOCATION:	AREA P	
ACTIVITY:		
REMEDIATION.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
15/12/93	73/7514	18

LOCATION:	AREA P	
ACTIVITY:		
REMEDIATION.		
SPECIAL FEATURES:		
POOR WEATHER CONDITIONS AT THIS TIME.		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
15/12/93	73/7514	19
LOCATION:	AREA P	
ACTIVITY:		
REMEDICATION.		
SPECIAL FEATURES:		
POOR WEATHER CONDITIONS AT THIS TIME AND NOTE FORMER CANAL ROUTES OPENED UP.		



--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
15/12/93	73/7514	20
LOCATION:	AREA P	
ACTIVITY:		
REMEDIATION.		
SPECIAL FEATURES:		
POOR WEATHER CONDITIONS AT THIS TIME AND NOTE FORMER CANAL ROUTES OPENED UP.		


--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
17/12/93	73/7514	21
LOCATION:	AREA H	
ACTIVITY:		
REMOVAL OF MOUNDING TO BUILDING H12.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
17/12/93	73/7514	22
LOCATION:	AREA P	
ACTIVITY:		
DEMOLITION OF BUILDINGS A230 - A234.		
SPECIAL FEATURES:		

FRAME SHOWS NORTH ELEVATION.




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
17/12/93	73/7514	23
LOCATION:	AREA P	
ACTIVITY:		
BUILDING A232 ROOFING SLATES BEING REMOVED.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
17/12/93	73/7514	24

LOCATION:	AREA P	
ACTIVITY:		
BUILDING A234 ROOF DEMOLITION IN PROGRESS.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
17/12/93	73/7514	24A
LOCATION:	AREA P	
ACTIVITY:		
BUILDING A231 ROOF DEMOLITION IN PROGRESS.		
SPECIAL FEATURES:		





FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDATION RECORD

DATE:

NEGATIVE REFERENCE:

FRAME REFERENCE:

5/1/94

74/8525

1

LOCATION:

AREA P


ACTIVITY:

REMEDATION.

SPECIAL FEATURES:

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/1/94	74/8525	2
LOCATION:	AREA P	
ACTIVITY:		
REMEDICATION.		
SPECIAL FEATURES:		
FORMER CANALS OPENED UP.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/1/94	74/8525	3
LOCATION:	AREA P	
ACTIVITY:		
REMEDIATION.		
SPECIAL FEATURES:		
POOR WEATHER CONDITIONS AT THIS TIME.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/1/94	74/8525	4
LOCATION:	AREA P	
ACTIVITY:		
REMEDIATION.		
SPECIAL FEATURES:		

POOR WEATHER CONDITIONS AT THIS TIME.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/1/94	74/8525	5
LOCATION:	AREA P	
ACTIVITY:		
REMEDATION.		

SPECIAL FEATURES:
POOR WEATHER CONDITIONS AT THIS TIME.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/1/94	74/8525	6

LOCATION:	AREA P	
ACTIVITY:		
REMEDIATION.		
SPECIAL FEATURES:		
POOR WEATHER CONDITIONS AT THIS TIME.		


**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/1/94	74/8525	7
LOCATION:	AREA P	
ACTIVITY:		
REMEDATION.		
SPECIAL FEATURES:		
PUMP DOWN OF GROUND WATER IN PROGRESS.		



--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/1/94	74/8525	8
LOCATION:	AREA P	
ACTIVITY:		
REMEDIATION.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/1/94	74/8525	9
LOCATION:	AREA P	
ACTIVITY:		
REMEDICATION.		
SPECIAL FEATURES:		
POOR WEATHER CONDITIONS.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/1/94	74/8525	10
LOCATION:	AREA P	
ACTIVITY:		
REMEDIATION.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/1/94	74/8525	11
LOCATION:	AREA P	
ACTIVITY:		
REMEDATION.		

SPECIAL FEATURES:
SAMPLING PEGS IN PLACE.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/1/94	74/8525	12

LOCATION:	AREA P	
ACTIVITY:		
REMEDATION.		
SPECIAL FEATURES:		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDICATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/1/94	74/8525	13
LOCATION:	AREA P	
ACTIVITY:		
REMEDICATION.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/1/94	74/8525	14
LOCATION:	AREA P	
ACTIVITY:		
REMEDICATION.		
SPECIAL FEATURES:		
FWD IN CENTRE OF PICTURE LEFT IN PLACE. EXISTING LIVE GAS MAIN, YELLOW PIPE, LEFT IN PLACE (BOTH SERVING BUILDING A221).		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/1/94	74/8525	15
LOCATION:	AREA P	
ACTIVITY:		
REMEDICATION.		
SPECIAL FEATURES:		
DIFFICULT CONDITIONS.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/1/94	74/8525	16
LOCATION:	AREA P	
ACTIVITY:		
REMEDICATION.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/1/94	74/8525	17
LOCATION:	AREA P	
ACTIVITY:		
REMEDICATION.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/1/94	74/8525	18

LOCATION:	AREA P	
ACTIVITY:		
REMEDATION.		
SPECIAL FEATURES:		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDiation RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/1/94	74/8525	19
LOCATION:	AREA P	
ACTIVITY:		
REMEDIATION.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/1/94	74/8525	20
LOCATION:	AREA P	
ACTIVITY:		
REMEDIATION.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/1/94	74/8525	21
LOCATION:	AREA P	
ACTIVITY:		
REMEDICATION.		
SPECIAL FEATURES:		
BUILDING A269 TO LEFT OF PICTURE.		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/1/94	74/8525	22
LOCATION:	AREA P	
ACTIVITY:		
REMEDIATION.		
SPECIAL FEATURES:		

BUILDING A268 CENTRE RIGHT OF PICTURE.



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/1/94	74/8525	23
LOCATION:	AREA P	
ACTIVITY:		
REMEDIATION.		

SPECIAL FEATURES:
BUILDING A269 TO LEFT OF PICTURE.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/1/94	74/8525	24

LOCATION:	AREA P	
ACTIVITY:		
REMEDATION.		
SPECIAL FEATURES:		
DIFFICULT CONDITIONS.		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDICATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/1/94	74/8525	25
LOCATION:	AREA P	
ACTIVITY:		
REMEDICATION.		
SPECIAL FEATURES:		
DIFFICULT CONDITIONS.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/1/94	74/8525	26
LOCATION:	AREA P	
ACTIVITY:		
REMEDIATION.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/1/94	74/8525	27
LOCATION:	AREA P	
ACTIVITY:		
REMEDIATION.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/1/94	74/8525	28
LOCATION:	AREA P	
ACTIVITY:		
NEW VALVE INSTALLED TO EXISTING WATER MAIN ADJACENT TO BUILDING A238.		
SPECIAL FEATURES:		




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/1/94	74/8525	29
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - PULLING LARGE STONE BLOCKS FROM DEEP		

UNDERFLOOR CAVITY IN STEAM ENGINE HOUSE.
SPECIAL FEATURES:


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/1/94	74/8525	30

LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - PULLING LARGE STONE BLOCKS FROM DEEP UNDERFLOOR CAVITY IN STEAM ENGINE HOUSE.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/1/94	74/8525	31
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - PULLING LARGE STONE BLOCKS FROM DEEP UNDERFLOOR CAVITY IN STEAM ENGINE HOUSE.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/1/94	74/8525	32
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - PULLING LARGE STONE BLOCKS FROM DEEP UNDERFLOOR CAVITY IN STEAM ENGINE HOUSE.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/1/94	74/8525	33
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - PULLING LARGE STONE BLOCKS FROM DEEP UNDERFLOOR CAVITY IN STEAM ENGINE HOUSE.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/1/94	74/8525	34
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - PULLING LARGE STONE BLOCKS FROM DEEP UNDERFLOOR CAVITY IN STEAM ENGINE HOUSE.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/1/94	74/8525	35
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - REMEDIATION.		



SPECIAL FEATURES:
FORMER STEAM ENGINE FOUNDATIONS.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/1/94	74/8525	36

LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - ENGINE HOUSE. REMOVAL OF LARGE STONE BLOCKS FROM UNDERFLOOR CAVITY.		
SPECIAL FEATURES:		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/1/94	74/8525	37
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - REMEDIATION.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/1/94	75/9190	1
LOCATION:	AREA P	
ACTIVITY:		
REMEDICATION.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/1/94	75/9190	2
LOCATION:	AREA P	
ACTIVITY:		
REMEDICATION.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/1/94	75/9190	3
LOCATION:	AREA P	
ACTIVITY:		
REMEDIATION.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/1/94	75/9190	4
LOCATION:	AREA P	
ACTIVITY:		
REMEDIATION.		
SPECIAL FEATURES:		



DIFFICULT GROUND CONDITION.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/1/94	75/9190	5
LOCATION:	AREA P	
ACTIVITY:		
RETRIEVAL OF DEBRIS FROM MILLHEAD STREAM ADJACENT TO BRIDGE		

No. 1.
SPECIAL FEATURES:


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/1/94	75/9190	6

LOCATION:	AREA H	
ACTIVITY:		
BUILDING H12 - DEMOLITION.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
25/1/94	75/9190	8
LOCATION:	AREA H - ENTRANCE	
ACTIVITY:		
ROAD REPAIRS IN PROGRESS.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
25/1/94	75/9190	9
LOCATION:	AREA H	
ACTIVITY:		
DILUTING CONTAMINATED SOILS ON H19 AREA.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
25/1/94	75/9190	10
LOCATION:	AREA H	
ACTIVITY:		
DEMOLITION OF BUILDING H12.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
25/1/94	75/9190	11
LOCATION:	AREA P	
ACTIVITY:		
BUILDING A210 - REMOVAL OF HIGH LEVEL PROJECTIONS.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
25/1/94	75/9190	12
LOCATION:	AREA P	
ACTIVITY:		
REMEDIATED AREA P (SOUTH).		



SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
25/1/94	75/9190	13


LOCATION:	AREA P	
ACTIVITY:		
REMEDIATED AREA P (SOUTH).		
SPECIAL FEATURES:		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
25/1/94	75/9190	14
LOCATION:	AREA P	
ACTIVITY:		
REMEDIATED AREA P (SOUTH).		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
25/1/94	75/9190	15
LOCATION:	AREA P	
ACTIVITY:		
REMEDIATED AREA P (SOUTH).		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
25/1/94	75/9190	16
LOCATION:	AREA S	
ACTIVITY:		
TIMBERS RECLAIMED FROM REMEDIATION WORKS TO CANALS.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/1/94	75/9190	17
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - LAYING OUT EXCAVATED FILL MATERIALS FROM WITHIN BUILDING.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/1/94	75/9190	18
LOCATION:	AREA B	
ACTIVITY:		
ROYAL ORDNANCE ASPHALT MIXING PLANT.		

SPECIAL FEATURES:
USED FOR 'HEAT TREATMENT' OF ASPHALT TAKEN UP FROM FLOORS OF INCORPORATING MILLS.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/1/94	75/9190	19



LOCATION:	AREA B	
ACTIVITY:		
ROYAL ORDNANCE ASPHALT MIXING PLANT.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/1/94	75/9190	20
LOCATION:	AREA B	
ACTIVITY:		
ROYAL ORDNANCE ASPHALT MIXING PLANT.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/1/94	75/9190	21
LOCATION:	AREA B	
ACTIVITY:		
ROYAL ORDNANCE ASPHALT MIXING PLANT.		
SPECIAL FEATURES:		
PAPER DRUMS FOR COLLECTING 'HEAT TREATED' ASPHALT.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/1/94	75/9190	22
LOCATION:	AREA B	
ACTIVITY:		
ROYAL ORDNANCE ASPHALT MIXING PLANT.		
SPECIAL FEATURES:		
PAPER DRUMS FOR COLLECTING 'HEAT TREATED' ASPHALT.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/1/94	75/9190	23
LOCATION:	AREA B	
ACTIVITY:		
ROYAL ORDNANCE ASPHALT MIXING PLANT.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/1/94	75/9190	24
LOCATION:	AREA B	
ACTIVITY:		
ROYAL ORDNANCE ASPHALT MIXING PLANT.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/1/94	75/9190	25

LOCATION:	AREA B	
ACTIVITY:		
ROYAL ORDNANCE ASPHALT MIXING PLANT.		
SPECIAL FEATURES:		






**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/1/94	76/9238	1
LOCATION:	AREA B	
ACTIVITY:		
ROYAL ORDNANCE ASPHALT MIXER FOR HEAT TREATING ASPHALT REMOVED FROM PROCESS BUILDINGS.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/1/94	76/9238	2
LOCATION:	AREA B	
ACTIVITY:		
ROYAL ORDNANCE ASPHALT MIXER - HEAT TREATMENT OF ASPHALT IN PROGRESS.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/1/94	76/9238	3
LOCATION:	AREA B	
ACTIVITY:		
CUT PRESSURE CYLINDERS STOCKPILED.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/1/94	76/9238	4
LOCATION:	AREA B	
ACTIVITY:		
FLOOR SLAB ARISINGS FROM BUILDING L157 LAID OUT FOR 'HEAT TREATMENT'.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/1/94	76/9238	5
LOCATION:	AREA S	
ACTIVITY:		
WIND BLOWN WILLOWS ADJACENT TO BUILDING E9.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/1/94	76/9238	6


LOCATION:	AREA H - ISLAND SITE	
ACTIVITY:		
BUILDING A203 - SQUIRREL ON HANDRAIL.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
31/1/94	76/9238	7
LOCATION:	AREA M	
ACTIVITY:		
AIRSTREAM HELMET.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
31/1/94	76/9238	8
LOCATION:	AREA M	
ACTIVITY:		
AIRSTREAM HELMET.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
31/1/94	76/9238	9
LOCATION:	AREA M	
ACTIVITY:		
AIRSTREAM HELMET.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
31/1/94	76/9238	10
LOCATION:	AREA M	
ACTIVITY:		
AIRSTREAM HELMET AND DISPOSABLE SUIT.		
SPECIAL FEATURES:		

TYPICAL OUTFIT IN USE WHEN CARRYING OUT DECONTAMINATION  
WORKS IN BUILDINGS.



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
31/1/94	76/9238	11
LOCATION:	AREA M	
ACTIVITY:		
AIRSTREAM HELMET AND DISPOSABLE SUIT.		

SPECIAL FEATURES:
TYPICAL OUTFIT IN USE WHEN CARRYING OUT DECONTAMINATION WORKS IN BUILDINGS.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
31/1/94	76/9238	12

LOCATION:	AREA M	
ACTIVITY:		
AIRSTREAM HELMET.		
SPECIAL FEATURES:		






FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDATION RECORD

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
3/2/94	77/9664	1
LOCATION:	AREA S	
ACTIVITY:		
SITE LANDROVER STUCK IN DIFFICULT CONDITIONS.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
3/2/94	77/9664	2
LOCATION:	AREA S	
ACTIVITY:		
SITE LANDROVER STUCK IN DIFFICULT CONDITIONS.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
10/2/94	77/9664	3
LOCATION:	AREA P	
ACTIVITY:		
TEMPORARY FENCING TO SEPARATE NORTH AND SOUTH OF P AREA.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
10/2/94	77/9664	4
LOCATION:	AREA P	
ACTIVITY:		
TEMPORARY FENCING TO SEPARATE NORTH AND SOUTH P AREA LOOKING TOWARDS BRIDGE No. 1.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
10/2/94	77/9664	5
LOCATION:	AREA P	
ACTIVITY:		
MATERIALS SALVAGED FROM THE DEMOLITION OF BUILDINGS A230 -		

A234.

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
10/2/94	77/9664	6

LOCATION:	AREA P	
ACTIVITY:		
MATERIALS SALVAGED FROM THE DEMOLITION OF BUILDINGS A230 - A234.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
10/2/94	77/9664	7
LOCATION:	AREA P	
ACTIVITY:		
MATERIALS SALVAGED FROM THE DEMOLITION OF BUILDINGS A230 - A234.		
SPECIAL FEATURES:		



--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
10/2/94	77/9664	8
LOCATION:	AREA P (NORTH)	
ACTIVITY:		
TRIAL TRENCH ACROSS FILLED CANAL (LOOKING NORTH).		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
10/2/94	77/9664	9
LOCATION:	AREA P	
ACTIVITY:		
TRIAL TRENCH ACROSS FILLED CANAL (LOOKING SOUTH).		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
10/2/94	77/9664	10
LOCATION:	AREA H	
ACTIVITY:		
WEST ELEVATION OF BUILDING H8.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
10/2/94	77/9664	11
LOCATION:	AREA H	
ACTIVITY:		
SOUTH ELEVATION OF BUILDING H8.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
10/2/94	77/9664	12

LOCATION:	AREA H	
ACTIVITY:		
BUILDING H8 - LOOKING SOUTH ALONG WEST ELEVATION.		
SPECIAL FEATURES:		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
10/2/94	77/9664	13
LOCATION:	AREA H	
ACTIVITY:		
NORTH ELEVATION OF BUILDING H8.		
SPECIAL FEATURES:		
ASBESTOS CLAD CANOPY REMOVED.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
10/2/94	77/9664	14
LOCATION:	AREA S	
ACTIVITY:		
NEWTONS POOL - NEW SLUICE.		
SPECIAL FEATURES:		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
10/2/94	77/9664	15
LOCATION:	AREA S	
ACTIVITY:		
NEWTONS POOL - SLUICE HANDRAILING.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
10/2/94	77/9664	16
LOCATION:	AREA N	
ACTIVITY:		
TOP SOIL STRIP IN PROGRESS.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
10/2/94	77/9664	17
LOCATION:	AREA S	
ACTIVITY:		
BRIDGE No. 10 - REPAIRED BRICKWORK (EAST WALL).		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
10/2/94	77/9664	18

LOCATION:	AREAS	
ACTIVITY:		
BRIDGE No. 10 - REPAIRED BRICKWORK (WEST WALL).		
SPECIAL FEATURES:		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
10/2/94	77/9664	19
LOCATION:	AREA S	
ACTIVITY:		
LONG WALK - REMOVAL OF STREET LAMP BULBS.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
10/2/94	77/9664	20
LOCATION:	AREA P (NORTH)	
ACTIVITY:		
NORTH OF BUILDING A219 (CAR PARK).		
SPECIAL FEATURES:		
EXPOSURE OF UNDERGROUND FUEL STORAGE TANKS.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
10/2/94	77/9664	21
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L148 - EXCAVATION OF 'CROWN WHEEL' SHAFT WITHIN UNDERCROFT.		
SPECIAL FEATURES:		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
10/2/94	77/9664	22
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L148 - VIEW SOUTHWARDS IN UNDERCROFT.		
SPECIAL FEATURES:		

NOTE GROUND WATER INGRESS.

Empty rectangular box for notes or details.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
10/2/94	77/9664	23
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L148 UNDERCROFT.		


SPECIAL FEATURES:
TYPICAL 'DUTCH' ARRANGEMENT. NOTE UNDERCROFT FILLING BEHIND.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
10/2/94	77/9664	24

LOCATION:	AREAS	
ACTIVITY:		
RECLAIMED STOCK BRICKS FROM CANAL INFILLS.		
SPECIAL FEATURES:		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
11/2/94	77/9664	25
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L148 - PAINT STRIPPING OF WALLS.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD

DATE:

NEGATIVE REFERENCE:

FRAME REFERENCE:

18/2/94

78/0791

1

LOCATION:

AREA P (SOUTH)

ACTIVITY:


ARCHAEOLOGISTS AT WORK (ESSEX COUNTY COUNCIL).

SPECIAL FEATURES:

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
18/2/94	78/0791	2
LOCATION:	AREA P (SOUTH)	
ACTIVITY:		
ARCHAEOLOGISTS AT WORK (ESSEX COUNTY COUNCIL).		
SPECIAL FEATURES:		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
18/2/94	78/0791	4
LOCATION:	AREA P	
ACTIVITY:		
MOISTURE TEST METER (INVESTIGATION OF BUILDING A221 - STILL OCCUPIED BY CLIENTS TENANT).		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
18/2/94	78/0791	5
LOCATION:	AREA P	
ACTIVITY:		
BUILDING A221 - SOUTH FACING BAY.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
22/2/94	78/0791	6
LOCATION:	AREA P	
ACTIVITY:		
BUILDING A238 - LOCATION OF FAULT IN ROOF.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
22/2/94	78/0791	7

LOCATION:	AREA P	
ACTIVITY:		
BUILDING A238 - WATER PENETRATION INSIDE.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
23/2/94	78/0791	8
LOCATION:	AREA P (NORTH)	
ACTIVITY:		
EXPOSURE OF UNDERGROUND FUEL STORAGE TANKS.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
23/2/94	78/0791	9
LOCATION:	AREA P (NORTH)	
ACTIVITY:		
EXPOSURE OF UNDERGROUND FUEL STORAGE TANKS.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
3/3/94	78/0791	10
LOCATION:	AREA H	
ACTIVITY:		
REMEDIATION, GROUND STRIP IN ZONE OF FORMER BUILDING H25.		
SPECIAL FEATURES:		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
3/3/94	78/0791	11
LOCATION:	AREA H	
ACTIVITY:		
REMEDICATION, GROUND STRIP IN ZONE OF FORMER BUILDING H25.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
3/3/94	78/0791	12
LOCATION:	AREA H	
ACTIVITY:		
EXCAVATION OF EAST - WEST CANAL (SOUTH OF BUILDINGS H25 & H26)		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
3/3/94	78/0791	R

LOCATION:	AREA H	
ACTIVITY:		
EXCAVATION OF EAST - WEST CANAL (SOUTH OF BUILDINGS H25 & H26)		
SPECIAL FEATURES:		
SAMPLING OF BASE.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
3/3/94	79/0814	1
LOCATION:	AREA H	
ACTIVITY:		
EXCAVATION OF FILLED CANAL SOUTH OF BUILDINGS H25 AND H26.		
SPECIAL FEATURES:		
SAMPLING FOUNDATION LEVEL.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
3/3/94	79/0814	2
LOCATION:	AREA H	
ACTIVITY:		
EXCAVATION OF FILLED CANAL SOUTH OF BUILDINGS H25 AND H26.		
SPECIAL FEATURES:		
NOTE CONDITION OF REVETMENT WALL.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
3/3/94	79/0814	3
LOCATION:	AREA H	
ACTIVITY:		
EXCAVATION OF FILLED CANAL SOUTH OF BUILDINGS H25 AND H26.		
SPECIAL FEATURES:		
NOTE NATURE OF INFILL MATERIAL.		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
3/3/94	79/0814	4
LOCATION:	AREA H	
ACTIVITY:		
EXCAVATION OF FILLED CANAL SOUTH OF BUILDINGS H25 AND H26.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
3/3/94	79/0814	5
LOCATION:	AREA H	
ACTIVITY:		
EXCAVATION OF FILLED CANAL SOUTH OF BUILDINGS H25 AND H26.		

SPECIAL FEATURES:
HIGHBRIDGE STREET GATE IN BACKGROUND. SAMPLING PEGS IN POSITION. NOTE CONDITION OF REVETMENT WALLING.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
3/3/94	79/0814	6

LOCATION:	AREA H	
ACTIVITY:		
REMEDIATION OF GROUND IN AREA OF FORMER BUILDING H25.		
SPECIAL FEATURES:		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
3/3/94	79/0814	7
LOCATION:	AREA H	
ACTIVITY:		
PUMP SUCTION LINE CROSS OVER.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
3/3/94	79/0814	8
LOCATION:	AREA H	
ACTIVITY:		
PRE-CAST CONCRETE PERFORATED MANHOLE RING USED AS PUMP LINE STRAINER SUMP.		
SPECIAL FEATURES:		
REDUCTION OF GROUND WATER LEVELS.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
3/3/94	79/0814	9
LOCATION:	AREA H	
ACTIVITY:		
AREA H SPECIAL WASTE STOCKPILE AREA.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
3/3/94	79/0814	10
LOCATION:	AREA H	
ACTIVITY:		
AREA H SPECIAL WASTE STOCKPILE AREA.		
SPECIAL FEATURES:		




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
4/3/94	79/0814	11
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - SHEETED BAY.		

SPECIAL FEATURES:
GRIT BLASTING OF STRUCTURE STEELWORK WITHIN BAY IN PROGRESS.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
4/3/94	79/0814	12

LOCATION:	AREA H	
ACTIVITY:		
REMEDIATION OF GROUND IN ZONE OF FORMER BUILDING H25.		
SPECIAL FEATURES:		
NOTE LINE OF DARK COLOURED SQUARE PITS CONTAINING HYDROCARBON CONTAMINANTS.		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
4/3/94	79/0814	13
LOCATION:	AREA H	
ACTIVITY:		
REMEDATION OF GROUND IN ZONE OF FORMER BUILDING H25.		
SPECIAL FEATURES:		
NOTE LINE OF DARK COLOURED SQUARE PITS CONTAINING HYDROCARBON CONTAMINANTS.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
4/3/94	79/0814	14
LOCATION:	AREA H	
ACTIVITY:		
'CLEAN' INFILLING OF EXCAVATED EAST - WEST CANAL SOUTH OF BUILDINGS H25 AND H26.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
4/3/94	79/0814	15
LOCATION:	AREA H	
ACTIVITY:		
REMEDICATION OF GROUND IN ZONE OF FORMER BUILDING H25.		
SPECIAL FEATURES:		
TYPICAL PIT CONTAINING HYDROCARBON CONTAMINANTS.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
4/3/94	79/0814	16
LOCATION:	AREA H	
ACTIVITY:		
REMEDIATION OF GROUND IN ZONE OF FORMER BUILDING H25.		
SPECIAL FEATURES:		

NOTE DARK COLOURED PIT CONTAINING HYDROCARBON  
CONTAMINANTS.



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
4/3/94	79/0814	17
LOCATION:	AREA H	
ACTIVITY:		
REMEDIATION OF GROUND IN ZONE OF FORMER BUILDING H25.		



SPECIAL FEATURES:
NOTE DARK COLOURED PITS IN EXCAVATION SURFACE CONTAINING HYDROCARBON CONTAMINANTS.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
4/3/94	79/0814	18

LOCATION:	AREA H	
ACTIVITY:		
EXCAVATION OF GROUND IN ZONE OF FORMER BUILDING H25.		
SPECIAL FEATURES:		
NOTE DARK COLOURED PITS IN EXCAVATION SURFACE CONTAINING HYDROCARBON CONTAMINANTS.		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
4/3/94	79/0814	19
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - DRAINAGE IN BOILER ROOM.		
SPECIAL FEATURES:		
TYPICAL OUTLET WASTE PIPES.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
4/3/94	79/0814	20
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - DRAINAGE IN BOILER ROOM.		
SPECIAL FEATURES:		
TYPICAL OUTLET WASTE PIPES.		




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
4/3/94	79/0814	21
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - NORTH OF BOILER HOUSE AREA.		
SPECIAL FEATURES:		
EXPOSURE FOR REMOVAL OF EXISTING EXTERNAL DRAINS.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
4/3/94	79/0814	22
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - NORTH OF BOILER HOUSE AREA.		
SPECIAL FEATURES:		

EXPOSURE FOR REMOVAL OF EXISTING EXTERNAL DRAINS.  
NOTE 'CLEAN' CUT OF PIPE EITHER SIDE OF SUSPECTED CONTAMINATED  
ZONE.



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
4/3/94	79/0814	23
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - DRAINAGE REMOVAL.		

SPECIAL FEATURES:
REMOTE OPERATED HYDRAULIC PIPE CUTTER.


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
4/3/94	79/0814	24



LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - DRAINAGE EXTERIOR VIEW LOOKING NORTH.		
SPECIAL FEATURES:		
TYPICAL EXTERNAL BACK INLET TRAPPED GULLEY ARRANGEMENT.		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
4/3/94	79/0814	R
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - DRAINAGE EXTERIOR VIEW LOOKING NORTH.		
SPECIAL FEATURES:		
TYPICAL EXTERNAL BACK INLET TRAPPED GULLEY ARRANGEMENT.		



FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD

DATE:

NEGATIVE REFERENCE:

FRAME REFERENCE:

9/3/94

80/1089

1

LOCATION:

AREA M


ACTIVITY:

BUILDING L157 - DRAIN REMOVAL.

SPECIAL FEATURES:

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/3/94	80/1089	2
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - DRAIN REMOVAL.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/3/94	80/1089	3
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - DRAIN REMOVAL.		
SPECIAL FEATURES:		
OPERATING, REMOTELY, HYDRAULIC PIPE CUTTER.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/3/94	80/1089	4
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - DRAIN REMOVAL.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/3/94	80/1089	5
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - DRAIN REMOVAL.		



SPECIAL FEATURES:
SETTING UP HYDRAULIC PIPE CUTTER.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/3/94	80/1089	6

LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - DRAIN REMOVAL.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/3/94	80/1089	7
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L148 - INTERNAL VIEW.		
SPECIAL FEATURES:		
WALL CORING POINTS CIRCLED IN YELLOW.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/3/94	80/1089	8
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L148 - INTERNAL VIEW.		
SPECIAL FEATURES:		
WALL CORING POINT CIRCLED IN YELLOW.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/3/94	80/1089	9
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L148 - INTERNAL VIEW.		
SPECIAL FEATURES:		
WALL CORING POINT CIRCLED IN YELLOW.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/3/94	80/1089	10
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L148 - INTERNAL BLAST WALLS AT 'FIRING POINT'.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/3/94	80/1089	11
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L148 - INTERNAL BLAST WALLS AT 'FIRING POINT'.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/3/94	80/1089	12




LOCATION:	AREA M	
ACTIVITY:		
BUILDING L148 - INTERNAL BLAST WALLS AT 'FIRING POINT'.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/3/94	80/1089	13
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L148 - INTERNAL BLAST WALLS AT 'FIRING POINT'.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/3/94	80/1089	14
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L148 - INTERNAL BLAST WALLS (PARTIALLY REMOVED).		
SPECIAL FEATURES:		
UNDERCROFT IN CENTRE OF FLOOR.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/3/94	80/1089	15
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L148 - INTERNAL BLAST WALLS (PARTIALLY REMOVED).		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/3/94	80/1089	16
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L148 - INTERNAL BLAST WALLS (PARTIALLY REMOVED).		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/3/94	80/1089	17
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L148 - INTERNAL BLAST WALLS.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/3/94	80/1089	18

LOCATION:	AREA M	
ACTIVITY:		
BUILDING L148 - 'FORMER ENGINE ROOM' AREA.		
SPECIAL FEATURES:		
WALL CORING POINTS CIRCLED IN YELLOW.		



**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/3/94	80/1089	19
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L148 - 'FORMER ENGINE ROOM' AREA.		
SPECIAL FEATURES:		
WALL CORING POINTS CIRCLED IN YELLOW.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/3/94	80/1089	20
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L148 - INTERNAL BLAST WALLS.		
SPECIAL FEATURES:		
WALL CORING POINTS CIRCLED IN YELLOW.		




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/3/94	80/1089	21
LOCATION:	AREA M	
ACTIVITY:		
OWL FOUND IN BUILDING L148.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/3/94	80/1089	22
LOCATION:	AREA H	
ACTIVITY:		
REMEDIATION OF SITE OF FORMER BUILDING H25.		
SPECIAL FEATURES:		

NOTE PITS CONTAINING HYDROCARBON CONTAMINANTS BEING REMOVED.



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/3/94	80/1089	23
LOCATION:	AREA H	
ACTIVITY:		
REMEDICATION OF SITE OF FORMER BUILDING H25.		

SPECIAL FEATURES:
NOTE PITS CONTAINING HYDROCARBON CONTAMINANTS BEING REMOVED.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/3/94	80/1089	24


LOCATION:	AREA H	
ACTIVITY:		
REMEDIATION OF SITE OF FORMER BUILDING H25.		
SPECIAL FEATURES:		
NOTE PITS CONTAINING HYDROCARBON CONTAMINANTS BEING REMOVED.		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/3/94	80/1089	25
LOCATION:	AREA H	
ACTIVITY:		
REMEDATION OF SITE OF FORMER BUILDING H25.		
SPECIAL FEATURES:		
NOTE PITS CONTAINING HYDROCARBON CONTAMINANTS BEING REMOVED.		



--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/3/94	80/1089	26
LOCATION:	AREA H	
ACTIVITY:		
REMEDATION OF SITE OF FORMER BUILDING H25.		
SPECIAL FEATURES:		
NOTE PITS CONTAINING HYDROCARBON CONTAMINANTS BEING REMOVED.		




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/3/94	80/1089	27
LOCATION:	AREA H	
ACTIVITY:		
SOUTH WALL OF EAST - WEST CANAL, SOUTH OF BUILDINGS H25 & H26 (THE EDGE OF THE SCHEDULED ANCIENT MONUMENT).		
SPECIAL FEATURES:		
NEW ISLAND SITE SERVICES TO LEFT OF PICTURE CROSSING OPENED UP CANAL.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/3/94	80/1089	28
LOCATION:	AREA H	
ACTIVITY:		
EAST - WEST CANAL SOUTH OF BUILDINGS H25 & H26 - REFILLING.		
SPECIAL FEATURES:		

BUILDING H26 TO RIGHT OF PICTURE.  
NOTE POLYTHENE MEMBRANE PLACED AGAINST EXISTING STRATA.



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/3/94	80/1089	29
LOCATION:	AREA H	
ACTIVITY:		
EAST - WEST CANAL SOUTH OF BUILDINGS H25 & H26 - REFILLING.		

SPECIAL FEATURES:
NOTE POLYTHENE MEMBRANE PLACED AGAINST EXISTING STRATA.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/3/94	80/1089	30

LOCATION:	AREA H	
ACTIVITY:		
H19 WASTE STOCKPILING AREA.		
SPECIAL FEATURES:		


**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/3/94	80/1089	31
LOCATION:	AREA H	
ACTIVITY:		
H19 WASTE STOCKPILING AREA.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
10/3/94	80/1089	32
LOCATION:	AREA H	
ACTIVITY:		
REMEDIATION OF AREA BELOW FORMER BUILDING H25.		
SPECIAL FEATURES:		
INVESTIGATING SUSPECT DISCOLOURATION.		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
10/3/94	80/1089	33
LOCATION:	AREA H	
ACTIVITY:		
REMEDICATION OF AREA BELOW FORMER BUILDING H25.		
SPECIAL FEATURES:		
NOTE OUTLINE AND DARK CONTAMINATED MATERIAL.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
10/3/94	80/1089	34
LOCATION:	AREA H	
ACTIVITY:		
REMEDIATION OF AREA BELOW FORMER BUILDING H25.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
10/3/94	80/1089	35
LOCATION:	AREA H	
ACTIVITY:		
REMEDATION OF AREA BELOW FORMER BUILDING H25.		

SPECIAL FEATURES:
NOTE OUTLINE OF DARKER 'PIT' AREAS IN EXCAVATION FACE.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
10/3/94	80/1089	36

LOCATION:	AREA H	
ACTIVITY:		
REMEDIATION OF AREA BELOW FORMER BUILDING H25.		
SPECIAL FEATURES:		
NOTE OUTLINE OF DARKER 'PIT' AREAS IN EXCAVATED FACE.		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
10/3/94	80/1089	37
LOCATION:	AREA H	
ACTIVITY:		
REMEDIATION OF AREA BELOW FORMER BUILDING H25.		
SPECIAL FEATURES:		




**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDICATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/3/94	81/1086	1
LOCATION:	AREA B	
ACTIVITY:		
REMOTE CUTTING (INTO SHORT SECTIONS) OF UNDERGROUND DRAINAGE PIPEWORK REMOVED FROM TETRYL FACTORY AREA (1ST STAGE DECONTAMINATION PROCESS).		
SPECIAL FEATURES:		
VICE AND CUTTER ARRANGEMENT.		



--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/3/94	81/1086	2
LOCATION:	AREA B	
ACTIVITY:		
REMOTE CUTTING (INTO SHORT SECTIONS) OF UNDERGROUND DRAINAGE PIPEWORK REMOVED FROM TETRYL FACTORY AREA (1ST STAGE DECONTAMINATION PROCESS).		
SPECIAL FEATURES:		
VICE AND CUTTER ARRANGEMENT.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/3/94	81/1086	3
LOCATION:	AREA B	
ACTIVITY:		
REMOTE CUTTING (INTO SHORT SECTIONS) OF UNDERGROUND DRAINAGE PIPEWORK REMOVED FROM TETRYL FACTORY AREA (1ST STAGE DECONTAMINATION PROCESS).		
SPECIAL FEATURES:		
VICE AND CUTTER ARRANGEMENT.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/3/94	81/1086	4
LOCATION:	AREA B	
ACTIVITY:		
REMOTE CUTTING (INTO SHORT SECTIONS) OF UNDERGROUND DRAINAGE PIPEWORK REMOVED FROM TETRYL FACTORY AREA (1ST STAGE DECONTAMINATION PROCESS).		
SPECIAL FEATURES:		

VICE AND CUTTER ARRANGEMENT.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/3/94	81/1086	5
LOCATION:	AREA B	
ACTIVITY:		
HOSING DOWN DRAINAGE PIPEWORK RETRIEVED FROM TETRYL FACTORY		

(1ST STAGE DECONTAMINATION PROCESS).
SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/3/94	81/1086	6

LOCATION:	AREA B	
ACTIVITY:		
CONTAMINATED PIPEWORK CUT AND STACKED AWAITING 2ND STAGE OF DECONTAMINATION PROCESS.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/3/94	81/1086	7
LOCATION:	AREA B	
ACTIVITY:		
CONTAMINATED PIPEWORK CUT AND STACKED AWAITING 2ND STAGE OF DECONTAMINATION PROCESS.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/3/94	81/1086	8
LOCATION:	AREA B	
ACTIVITY:		
CONTAMINATED PIPEWORK CUT AND STACKED AWAITING 2ND STAGE OF DECONTAMINATION PROCESS.		
SPECIAL FEATURES:		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/3/94	81/1086	9
LOCATION:	AREA B	
ACTIVITY:		
CONTAMINATED PIPEWORK CUT AND STACKED AWAITING 2ND STAGE OF DECONTAMINATION PROCESS.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/3/94	81/1086	10
LOCATION:	AREA B	
ACTIVITY:		
CONTAMINATED PIPEWORK CUT AND STACKED AWAITING 2ND STAGE OF DECONTAMINATION PROCESS.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/3/94	81/1086	11
LOCATION:	AREA B	
ACTIVITY:		
CONTAMINATED PIPEWORK CUT AND STACKED AWAITING 2ND STAGE		

OF DECONTAMINATION PROCESS.
SPECIAL FEATURES:


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/3/94	81/1086	12

LOCATION:	AREA B	
ACTIVITY:		
CONTAMINATED PIPEWORK CUT AND STACKED AWAITING 2ND STAGE OF DECONTAMINATION PROCESS.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/3/94	81/1086	13
LOCATION:	AREA B	
ACTIVITY:		
CONTAMINATED PIPEWORK CUT AND STACKED AWAITING 2ND STAGE OF DECONTAMINATION PROCESS.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/3/94	81/1086	14
LOCATION:	AREA B	
ACTIVITY:		
CONTAMINATED PIPEWORK CUT AND STACKED AWAITING 2ND STAGE OF DECONTAMINATION PROCESS.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/3/94	81/1086	15
LOCATION:	AREA B	
ACTIVITY:		
CONTAMINATED PIPEWORK CUT AND STACKED AWAITING 2ND STAGE OF DECONTAMINATION PROCESS.		
SPECIAL FEATURES:		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/3/94	81/1086	16
LOCATION:	AREA B	
ACTIVITY:		
CONTAMINATED PIPEWORK CUT AND STACKED AWAITING 2ND STAGE OF DECONTAMINATION PROCESS.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/3/94	81/1086	17
LOCATION:	AREA B	
ACTIVITY:		
CONTAMINATED PIPEWORK CUT AND STACKED AWAITING 2ND STAGE		

OF DECONTAMINATION PROCESS.
SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/3/94	81/1086	18


LOCATION:	AREA B	
ACTIVITY:		
CONTAMINATED PIPEWORK CUT AND STACKED AWAITING 2ND STAGE OF DECONTAMINATION PROCESS.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
16/3/94	82/1767	1
LOCATION:	AREA M	
ACTIVITY:		
REMOVAL OF POTENTIALLY CONTAMINATED DRAINAGE AT BUILDING L157.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
16/3/94	82/1767	2
LOCATION:	AREA M	
ACTIVITY:		
EXPOSED FOUL DRAIN, PRIOR TO DECONTAMINATION, ADJACENT TO BUILDING L157.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
16/3/94	82/1767	3
LOCATION:	AREA M	
ACTIVITY:		
EXPOSED FOUL DRAIN, PRIOR TO DECONTAMINATION, ADJACENT TO BUILDING L157.		
SPECIAL FEATURES:		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
16/3/94	82/1767	4
LOCATION:	AREA M	
ACTIVITY:		
BREAKING OUT FWD MAN HOLE ADJACENT TO BUILDING L157.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
16/3/94	82/1767	5
LOCATION:	AREA M	
ACTIVITY:		
FWD EXPOSED MAN HOLE ADJACENT TO BUILDING L157.		

SPECIAL FEATURES:
CLEARING AWAY CONCRETE SURROUND TO GAIN ACCESS TO REMOTELY CUT PIPE.


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
16/3/94	82/1767	6

LOCATION:	AREA H	
ACTIVITY:		
SITE OF FORMER BUILDING H25, REMOVAL OF HYDROCARBON CONTAMINATED GROUND, VIEWED FROM THE NORTH.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
16/3/94	82/1767	7
LOCATION:	AREA H	
ACTIVITY:		
SITE OF FORMER BUILDING H25, REMOVAL OF HYDROCARBON CONTAMINATED GROUND, VIEWED FROM THE SOUTH.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
16/3/94	82/1767	8
LOCATION:	AREA H	
ACTIVITY:		
EXCAVATION OF EAST / WEST FILLED CANAL SOUTH OF BUILDINGS H25 AND H26.		
SPECIAL FEATURES:		
OLD REVETMENT WALLS EXPOSED.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
16/3/94	82/1767	9
LOCATION:	AREA H	
ACTIVITY:		
EXCAVATION OF EAST / WEST FILLED CANAL SOUTH OF BUILDINGS H25 AND H26.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
16/3/94	82/1767	10
LOCATION:	AREA H	
ACTIVITY:		
EXCAVATION OF EAST / WEST FILLED CANAL SOUTH OF BUILDINGS H25 AND H26.		
SPECIAL FEATURES:		




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
16/3/94	82/1767	11
LOCATION:	AREA H	
ACTIVITY:		
H19 AREA DIFFICULT GROUND CONDITIONS.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
16/3/94	82/1767	12

LOCATION:	AREA H	
ACTIVITY:		
EXPOSING FOUNDATIONS TO BUILDING H31 (SEWER PUMPING STATION).		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
16/3/94	82/1767	13
LOCATION:	AREA H	
ACTIVITY:		
EXPOSING FOUNDATIONS TO BUILDING H31 (SEWER PUMPING STATION).		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
16/3/94	82/1767	14
LOCATION:	AREA H	
ACTIVITY:		
EXPOSING FOUNDATIONS OF BUILDING H31 (SEWER PUMPING STATION).		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
18/3/94	82/1767	15
LOCATION:	AREA H	
ACTIVITY:		
ACOUSTIC WALL TO ABSORB PUMP NOISE.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
18/3/94	82/1767	16
LOCATION:	AREA H	
ACTIVITY:		
CLEARANCE OF EAST / WEST CANAL SOUTH OF BUILDINGS H25 AND H26 - TEMPORARY REMOVAL OF FWD FOR ACCESS.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
18/3/94	82/1767	17
LOCATION:	AREA H	
ACTIVITY:		
CLEARANCE OF EAST / WEST CANAL SOUTH OF BUILDINGS H25 AND		



H26 - TEMPORARY REMOVAL OF FWD FOR ACCESS.
SPECIAL FEATURES:


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
18/3/94	82/1767	18

LOCATION:	AREA H	
ACTIVITY:		
HIGHBRIDGE STREET ENTRANCE - VIEW OF FIBREGLASS PETROL INTERCEPTOR UNIT TO BE USED IN CONJUNCTION WITH SITE VEHICLE WASHDOWN DRAINAGE.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
18/3/94	82/1767	19
LOCATION:	AREA H	
ACTIVITY:		
CLEARANCE OF EAST / WEST CANAL SOUTH OF BUILDINGS H25 AND H26 - TEMPORARY REMOVAL OF FWD FOR ACCESS.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
18/3/94	82/1767	20
LOCATION:	AREA H	
ACTIVITY:		
CLEARANCE OF EAST / WEST CANAL SOUTH OF BUILDINGS H25 AND H26 - TEMPORARY REMOVAL OF FWD FOR ACCESS.		
SPECIAL FEATURES:		
NOTE A201/2 AND A203 BT, ELECTRICITY AND WATER SERVICES SUPPORTED ACROSS THE EXCAVATION.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
18/3/94	82/1767	21
LOCATION:	AREA H	
ACTIVITY:		
EXCAVATION OF EAST / WEST FILLED CANAL SOUTH OF BUILDINGS H25 AND H26 VIEWED FROM THE SOUTH.		
SPECIAL FEATURES:		
BUILDING H26 TO THE RIGHT OF THE PICTURE. MACHINES IN CENTRE BACKGROUND - EXCAVATING HYDROCARBON CONTAMINATED AREA.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
18/3/94	82/1767	22
LOCATION:	AREA H	
ACTIVITY:		
EXCAVATION OF EAST / WEST FILLED CANAL SOUTH OF BUILDINGS H25 AND H26 VIEWED FROM THE SOUTH.		
SPECIAL FEATURES:		

A201/2 AND A203 ELECTRICITY, WATER AND BT SERVICES.



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
18/3/94	82/1767	23
LOCATION:	AREA H	
ACTIVITY:		
EXCAVATION OF EAST / WEST FILLED CANAL SOUTH OF BUILDINGS H25		

AND H26 VIEWED FROM EAST.
SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
18/3/94	82/1767	24



LOCATION:	AREA H	
ACTIVITY:		
EXCAVATION OF EAST / WEST FILLED CANAL SOUTH OF BUILDINGS H25 AND H26.		
SPECIAL FEATURES:		
BASE OF EXCAVATION BEFORE FINAL CLEAN UP PRIOR TO RE - FILLING.		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
18/3/94	82/1767	25
LOCATION:	AREA H	
ACTIVITY:		
EXCAVATION OF EAST / WEST FILLED CANAL SOUTH OF BUILDINGS H25 AND H26.		
SPECIAL FEATURES:		
VIEW OF REVETMENT WALL CONSTRUCTION.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
18/3/94	82/1767	26
LOCATION:	AREA H	
ACTIVITY:		
EXCAVATION OF EAST / WEST FILLED CANAL SOUTH OF BUILDINGS H25 AND H26.		
SPECIAL FEATURES:		
VIEW OF SOUTH REVETMENT WALL (SCHEDULED ANCIENT MONUMENT).		




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
18/3/94	82/1767	27
LOCATION:	AREA H	
ACTIVITY:		
EXCAVATION OF HYDROCARBON CONTAMINATED GROUND ON SITE OF FORMER BUILDING H25 VIEWED FROM THE SOUTH.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
18/3/94	82/1767	28
LOCATION:	AREA H	
ACTIVITY:		
EXCAVATION OF HYDROCARBON CONTAMINATED GROUND ON SITE OF FORMER BUILDING H25 VIEWED FROM THE SOUTH.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
19/3/94	82/1767	29
LOCATION:	AREA H	
ACTIVITY:		
EAST / WEST CANAL SOUTH OF BUILDINGS H25 AND H26 - REFILLING IN		

<p>PROGRESS WITH IMPORTED MATERIAL VIEWED FROM THE SOUTH.</p>
<p>SPECIAL FEATURES:</p>
<p>BUILDING H26 TO RIGHT OF PICTURE. NOTE: POLYTHENE MEMBRANE AGAINST EXISTING GROUND.</p>


<p style="text-align: center;"><b>FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD</b></p>		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
19/3/94	82/1767	30


LOCATION:	AREA H	
ACTIVITY:		
EAST / WEST CANAL SOUTH OF BUILDINGS H25 AND H26 - REFILLING IN PROGRESS WITH IMPORTED MATERIAL VIEWED FROM THE SOUTH.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
21/3/94	82/1767	31
LOCATION:	AREA H	
ACTIVITY:		
EAST / WEST CANAL SOUTH OF BUILDINGS H25 AND H26 - REFILLING IN PROGRESS WITH IMPORTED MATERIAL VIEWED FROM THE SOUTH.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
21/3/94	82/1767	32
LOCATION:	AREA H	
ACTIVITY:		
EAST / WEST CANAL SOUTH OF BUILDINGS H25 AND H26 - REFILLING IN PROGRESS WITH IMPORTED MATERIAL VIEWED FROM THE SOUTH.		
SPECIAL FEATURES:		
STEEL SHEET PILING BETWEEN HORSEMILL STREAM AND OPEN EXCAVATION.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
21/3/94	82/1767	33
LOCATION:	AREA H	
ACTIVITY:		
EAST / WEST CANAL SOUTH OF BUILDINGS H25 AND H26 - REFILLING IN PROGRESS WITH IMPORTED MATERIAL VIEWED FROM THE SOUTH (FINAL 'BOTTOM UP' OF EXCAVATION.		
SPECIAL FEATURES:		
STEEL SHEET PILING BETWEEN HORSEMILL STREAM AND OPEN EXCAVATION.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
21/3/94	82/1767	34
LOCATION:	AREA H	
ACTIVITY:		
EAST / WEST CANAL SOUTH OF BUILDINGS H25 AND H26 - REFILLING IN PROGRESS WITH IMPORTED MATERIAL VIEWED FROM THE SOUTH.		
SPECIAL FEATURES:		

FUNCTION OF STEEL SHEET PILES AND BRICK REVETMENT.

Empty rectangular box for notes or details.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
23/3/94	82/1767	35
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - GULLEY 17 MERCURY FOUND WHILST REMOVING DRAIN.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
23/3/94	82/1767	36

LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - GULLEY 17 MERCURY FOUND WHILST REMOVING DRAIN.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
23/3/94	82/1767	R
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - GULLEY 17 MERCURY FOUND WHILST REMOVING DRAIN.		
SPECIAL FEATURES:		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
23/3/94	83/1771	1
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - DRAINS REMOVAL.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
23/3/94	83/1771	2
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - DRAINS REMOVAL.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
23/3/94	83/1771	3
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - DRAINS REMOVAL.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
23/3/94	83/1771	4
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - DRAINS REMOVAL.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
23/3/94	83/1771	5
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - DRAINS REMOVAL.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
23/3/94	83/1771	6


LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - DRAINS REMOVAL.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
23/3/94	83/1771	7
LOCATION:	AREA B	
ACTIVITY:		
CONTAINER LINED OUT TO RECEIVE ASBESTOS CONTAMINATED SOIL FROM DUMP SITUATED EAST OF BURNING GROUND.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
25/3/94	83/1771	8
LOCATION:	AREA B	
ACTIVITY:		
LOADING OF ASBESTOS CONTAMINATED SOIL FROM DUMP EAST OF BURNING GROUND.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
26/3/94	83/1771	9
LOCATION:	AREA N	
ACTIVITY:		
SUSPECT PIT SOUTH OF BUILDING S43.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
26/3/94	83/1771	10
LOCATION:	AREA N	
ACTIVITY:		
SUSPECT PIT SOUTH OF BUILDING S43.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
26/3/94	83/1771	11
LOCATION:	AREA N	
ACTIVITY:		
SUSPECT PIT SOUTH OF BUILDING S43.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
26/3/94	83/1771	12

LOCATION:	AREA N	
ACTIVITY:		
SUSPECT PITS SOUTH OF BUILDING S43.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
26/3/94	83/1771	13
LOCATION:	AREA N	
ACTIVITY:		
SUSPECT PITS SOUTH OF BUILDING S43 - CONTAMINATED MATERIALS REMOVED AND BAGGED.		
SPECIAL FEATURES:		



--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
26/3/94	83/1771	14
LOCATION:	AREA N	
ACTIVITY:		
SUSPECT PITS SOUTH OF BUILDING S43 - SCRAP METAL RETRIEVED.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
26/3/94	83/1771	15
LOCATION:	AREA N	
ACTIVITY:		
TOP SOIL STRIP IN AREA SOUTH OF BUILDING S13 (PREPARATION FOR WASTE STOCKPILING).		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
26/3/94	83/1771	16
LOCATION:	AREA S	
ACTIVITY:		
S30 - CANAL CLEARING - VIEW LOOKING WEST.		
SPECIAL FEATURES:		

BUILDING S30 TO RIGHT (OUT OF SHOT).



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
26/3/94	83/1771	17
LOCATION:	AREA S	
ACTIVITY:		
S30 / S90 - CANAL CLEARANCE - VIEW LOOKING NORTH.		

SPECIAL FEATURES:
BUILDING S30 TO TOP LEFT (OUT OF SHOT).

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
26/3/94	83/1771	18


LOCATION:	AREA B	
ACTIVITY:		
CUT PIPES FROM TETRYL FACTORY SET FOR 'HEAT TREATMENT'.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
26/3/94	83/1771	19
LOCATION:	AREA B	
ACTIVITY:		
CUT PIPES FROM TETRYL FACTORY SET FOR 'HEAT TREATMENT'.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
26/3/94	83/1771	20
LOCATION:	AREA B	
ACTIVITY:		
CUT PIPES FROM TETRYL FACTORY SET FOR 'HEAT TREATMENT'.		
SPECIAL FEATURES:		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
26/3/94	83/1771	21
LOCATION:	AREA H	
ACTIVITY:		
HYDROCARBON CONTAMINATED AREA, AFTER REMOVAL OF CONTAMINATED GROUND.		
SPECIAL FEATURES:		
BUILDING H26 TO LEFT OF PICTURE.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
26/3/94	83/1771	22
LOCATION:	AREA H	
ACTIVITY:		
HYDROCARBON CONTAMINATED AREA, AFTER REMOVAL OF CONTAMINATED GROUND.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
26/3/94	83/1771	23
LOCATION:	AREA H	
ACTIVITY:		
HYDROCARBON CONTAMINATED AREA, AFTER REMOVAL OF		

CONTAMINATED GROUND.
SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
28/3/94	83/1771	26

LOCATION:	AREA H - ISLAND SITE	
ACTIVITY:		
ADJACENT TO HOPPITS POOL - MALE MANDARIN DUCK.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
28/3/94	83/1771	27
LOCATION:	AREA H - ISLAND SITE	
ACTIVITY:		
ADJACENT TO HOPPITS POOL - MALE MANDARIN DUCK.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
28/3/94	83/1771	28
LOCATION:	AREA H - ISLAND SITE	
ACTIVITY:		
FEMALE MALLARD DUCK ADJACENT TO HOPPITS POOL.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
29/3/94	83/1771	29
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L145 - ROOF VENT TERMINALS.		
SPECIAL FEATURES:		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
29/3/94	83/1771	30
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L148 - ROOF VENT TERMINALS.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
29/3/94	83/1771	31
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L153 - EXTRACT VENT WALL GRILLE.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
29/3/94	83/1771	32

LOCATION:	AREA M	
ACTIVITY:		
BUILDING L149 - ROOF VENT PIPE TERMINALS.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
29/3/94	83/1771	33
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - LOUVRED VENT.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
29/3/94	83/1771	34
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - VENT PIPE TERMINALS.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
29/3/94	83/1771	35
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - EXTRACT VENT TERMINAL AND MOTOR.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
29/3/94	83/1771	36
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - EAST ELEVATION.		
SPECIAL FEATURES:		



INTERNAL DECONTAMINATION WORKS IN PROGRESS.




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
29/3/94	83/1771	R
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L153 - EAST ELEVATION.		



SPECIAL FEATURES:


INTERNAL DECONTAMINATION WORKS IN PROGRESS.



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
29/3/94	84/2475	1
LOCATION:	AREA H	
ACTIVITY:		
REFILLING OF CLEANED OUT EAST / WEST CANAL SOUTH OF BUILDINGS H25 AND H26.		
SPECIAL FEATURES:		
PREPARATION FOR RE-INSTALLING 225 DIA FWD ACROSS THE CANAL.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
29/3/94	84/2475	2
LOCATION:	AREA H	
ACTIVITY:		
REFILLING OF CLEANED OUT EAST / WEST CANAL SOUTH OF BUILDINGS H25 AND H26.		
SPECIAL FEATURES:		
PREPARATION FOR RE-INSTALLING 225 DIA FWD ACROSS THE CANAL.		




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
29/3/94	84/2475	3
LOCATION:	AREA H	
ACTIVITY:		
REFILLING OF CLEANED OUT EAST / WEST CANAL SOUTH OF BUILDINGS H25 AND H26.		
SPECIAL FEATURES:		
225 DIA FWD RE-INSTALLED.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
29/3/94	84/2475	4
LOCATION:	AREA H	
ACTIVITY:		
REFILLING OF CLEANED OUT EAST / WEST CANAL SOUTH OF BUILDINGS H25 AND H26.		
SPECIAL FEATURES:		

225 DIA FWD RE-INSTALLED.



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIAION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
31/3/94	84/2475	5
LOCATION:	AREA H	
ACTIVITY:		
H68 - TYPICAL RUBBLE FILLED PIT.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
31/3/94	84/2475	6




LOCATION:	AREA H	
ACTIVITY:		
PETROL INTERCEPTOR - POCKETS FOR ANCHOR POINTS.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
31/3/94	84/2475	7
LOCATION:	AREA H	
ACTIVITY:		
PETROL INTERCEPTOR - ANCHOR POINTS CAST IN CONCRETE.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
5/4/94	84/2475	8
LOCATION:	AREA P	
ACTIVITY:		
BUILDING A221 - DAMAGE TO GARDEN LANTERN.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
5/4/94	84/2475	9
LOCATION:	AREA P	
ACTIVITY:		
BUILDING A221 - DAMAGE TO GARDEN LANTERN.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
7/4/94	84/2475	10
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - REMOVAL OF POTENTIALLY CONTAMINATED FW DRAINAGE.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
7/4/94	84/2475	11
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - REMOVAL OF POTENTIALLY CONTAMINATED FW		

DRAINAGE.
SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
7/4/94	84/2475	12

LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - REMOVAL OF POTENTIALLY CONTAMINATED FW DRAINAGE.		
SPECIAL FEATURES:		



**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDICATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
7/4/94	84/2475	13
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - 'SINGLE SIZED STONE' IMPORTED FOR DRAIN EXCAVATION BACKFILL.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
7/4/94	84/2475	14
LOCATION:	AREA H	
ACTIVITY:		
PETROL INTERCEPTOR PRIOR TO BACKFILL.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
7/4/94	84/2475	15
LOCATION:	AREA H	
ACTIVITY:		
H19 AREA - ORGANISING STOCKPILED WASTE.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
7/4/94	84/2475	16
LOCATION:	AREA H	
ACTIVITY:		
H16 AREA - STOCKPILING WASTE.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
7/4/94	84/2475	17
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - BACKFILLING OF TRENCHING AFTER REMOVAL OF FW		

DRAINAGE.
SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
7/4/94	84/2475	18

LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - BACKFILLING OF TRENCHING AFTER REMOVAL OF FW DRAINAGE.		
SPECIAL FEATURES:		


**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
7/4/94	84/2475	19
LOCATION:	AREA H	
ACTIVITY:		
H16 AREA - LOADING AWAY ACCUMULATED WASTE.		
SPECIAL FEATURES:		



--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
7/4/94	84/2475	20
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - BACKFILLING OF TRENCHING AFTER REMOVAL OF FW DRAINAGE.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
7/4/94	84/2475	21
LOCATION:	AREA H	
ACTIVITY:		
PETROL INTERCEPTOR BACKFILLING.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
7/4/94	84/2475	22
LOCATION:	AREA H	
ACTIVITY:		
PETROL INTERCEPTOR BACKFILLING.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
7/4/94	84/2475	23
LOCATION:	AREA H	
ACTIVITY:		
H19 AREA - ROYAL ORDNANCE SITE MANAGER SIZING UP WASTE		

STOCKPILE!
SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
7/4/94	84/2475	24


LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - BACKFILLING OF TRENCHING AFTER REMOVAL OF FW DRAINAGE.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
7/4/94	84/2475	25
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - BACKFILLING OF TRENCHING AFTER REMOVAL OF FW DRAINAGE.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
7/4/94	84/2475	26
LOCATION:	AREA H	
ACTIVITY:		
PETROL INTERCEPTOR BACKFILLING.		
SPECIAL FEATURES:		






FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/4/94	84/2475	27
LOCATION:	AREA S	
ACTIVITY:		
BUILDING S90 - SCAFFOLD BRIDGE ACROSS CANAL FOR ACCESS TO BUILDING.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/4/94	84/2475	28
LOCATION:	AREA S	
ACTIVITY:		
BUILDING S90 SCAFFOLD BRIDGE ACROSS CANAL.		
SPECIAL FEATURES:		

S90 - EXTERNAL SCAFFOLD IN PLACE FOR ROOF CLEARANCE AND INSPECTION.



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/4/94	84/2475	29
LOCATION:	AREA H	
ACTIVITY:		
H16 - FLOODED AREA LOOKING NORTH.		

SPECIAL FEATURES:
POOR WEATHER AND GROUND CONDITIONS. BUILDING H10 IN BACKGROUND.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/4/94	84/2475	30

LOCATION:	AREA H	
ACTIVITY:		
H16 - FLOODED AREA.		
SPECIAL FEATURES:		
DRAINAGE SURVEY IN PROGRESS.		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/4/94	84/2475	31
LOCATION:	AREA H	
ACTIVITY:		
H16 - FLOODED AREA.		
SPECIAL FEATURES:		
DIFFICULT GROUND CONDITIONS.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/4/94	84/2475	32
LOCATION:	AREA H	
ACTIVITY:		
H12 - FLOODED AREA (BUILDING A201/2 IN BACKGROUND).		
SPECIAL FEATURES:		
DIFFICULT GROUND CONDITIONS.		




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/4/94	84/2475	33
LOCATION:	AREA H	
ACTIVITY:		
H12 - FLOODED AREA (BRIDGE No. 17 IN BACKGROUND).		
SPECIAL FEATURES:		
DIFFICULT GROUND CONDITIONS.		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/4/94	84/2475	34
LOCATION:	AREA H	
ACTIVITY:		
H16 - FLOODED AREA (SETTING OUT TEMPORARY LAND DRAINS (BUILDING A203 IN BACKGROUND).		
SPECIAL FEATURES:		

DIFFICULT GROUND CONDITIONS.



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/4/94	84/2475	35
LOCATION:	AREA H	
ACTIVITY:		
FLOODED AREA (BUILDING H17 IN BACKGROUND).		


SPECIAL FEATURES:
FLOODED AREA AFTER REMOVAL OF BUILDING H8 FOUNDATIONS.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/4/94	84/2475	36

LOCATION:	AREA H	
ACTIVITY:		
SOIL STRIP PRIOR TO REMOVAL OF 'OLD MILLHEAD STREAM' INFILL.		
SPECIAL FEATURES:		
'ARCHAEOLOGIST WATCHING OVER'.		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/4/94	84/2475	R
LOCATION:	AREA H	
ACTIVITY:		
SOIL STRIP PRIOR TO REMOVAL OF 'OLD MILLHEAD STREAM' INFILL.		
SPECIAL FEATURES:		




FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/4/94	85/4094	1
LOCATION:	AREA S	
ACTIVITY:		
BLACK DUCK WITH BROKEN LEG.		
SPECIAL FEATURES:		
EXAMPLE OF WILDLIFE RESCUE DURING DECONTAMINATION WORKS.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/4/94	85/4094	2
LOCATION:	AREA S	
ACTIVITY:		
BLACK DUCK WITH BROKEN LEG.		
SPECIAL FEATURES:		
EXAMPLE OF WILDLIFE RESCUE DURING DECONTAMINATION WORKS.		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
13/4/94	85/4094	3
LOCATION:	AREA P	
ACTIVITY:		
BT CABLE TRENCH EXCAVATION - POWDERMILL LANE.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
13/4/94	85/4094	4
LOCATION:	AREA P	
ACTIVITY:		
BT CABLE TRENCH EXCAVATION - POWDERMILL LANE.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
13/4/94	85/4094	5
LOCATION:	AREA H	
ACTIVITY:		
BURIED STRUCTURE / PIT ADJACENT WEST ABUTMENT OF BRIDGE No.17.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
13/4/94	85/4094	6

LOCATION:	AREA H	
ACTIVITY:		
BURIED STRUCTURE / PIT ADJACENT WEST ABUTMENT OF BRIDGE No.17.		
SPECIAL FEATURES:		
CONSTRUCT SURFACE WATER RUN OFF TRENCH SOUTH OF BUILDING H10.		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
13/4/94	85/4094	7
LOCATION:	AREA H	
ACTIVITY:		
BURIED STRUCTURE / PIT ADJACENT WEST ABUTMENT OF BRIDGE No.17 (BUILDING A203 IN BACKGROUND).		
SPECIAL FEATURES:		
CONSTRUCT SURFACE WATER RUN OFF TRENCH SOUTH OF BUILDING H10.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
15/4/94	85/4094	8
LOCATION:	AREA S	
ACTIVITY:		
TREE WEST OF BUILDING L190 - BLOWN OVER IN HIGH WINDS.		
SPECIAL FEATURES:		




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
15/4/94	85/4094	9
LOCATION:	AREA S	
ACTIVITY:		
TREE WEST OF BUILDING L190 - BLOWN OVER IN HIGH WINDS.		
SPECIAL FEATURES:		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
15/4/94	85/4094	10
LOCATION:	AREA T	
ACTIVITY:		
VIEW OF SUSPECTED TETRYL FOUND ON FORMER TETRYL FACTORY SITE.		
SPECIAL FEATURES:		

TYPICAL EXAMPLE OF VISUAL APPEARANCE.



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
15/4/94	85/4094	11
LOCATION:	AREA S	
ACTIVITY:		
TREE WEST OF BUILDING L190 BLOWN OVER IN HIGH WINDS.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
15/4/94	85/4094	12

LOCATION:	AREAS	
ACTIVITY:		
EGG FOUND IN BUILDING 14.		
SPECIAL FEATURES:		
UNUSUAL BECAUSE OF ITS LARGE SIZE.		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
25/4/94	85/4094	13
LOCATION:	AREA P	
ACTIVITY:		
REMOVAL OF UNDERGROUND FUEL STORAGE TANKS ADJACENT TO FORMER BUILDING A219.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
25/4/94	85/4094	14
LOCATION:	AREA P	
ACTIVITY:		
REMOVAL OF UNDERGROUND FUEL STORAGE TANKS ADJACENT TO FORMER BUILDING A219.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
25/4/94	85/4094	15
LOCATION:	AREA P	
ACTIVITY:		
REMOVAL OF UNDERGROUND FUEL STORAGE TANKS ADJACENT TO FORMER BUILDING A219.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
25/4/94	85/4094	16
LOCATION:	AREA P	
ACTIVITY:		
REMOVAL OF UNDERGROUND FUEL STORAGE TANKS ADJACENT TO FORMER BUILDING A219.		
SPECIAL FEATURES:		




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
25/4/94	85/4094	17
LOCATION:	AREA P	
ACTIVITY:		
REMOVAL OF UNDERGROUND FUEL STORAGE TANKS ADJACENT TO		

FORMER BUILDING A219.
SPECIAL FEATURES:


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
25/4/94	85/4094	18

LOCATION:	AREA P	
ACTIVITY:		
REMOVAL OF UNDERGROUND FUEL STORAGE TANKS ADJACENT TO FORMER BUILDING A219.		
SPECIAL FEATURES:		
EVIDENCE OF FUEL LEAKAGE INTO SURROUNDING GROUND FROM FUEL STORAGE TANKS.		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
25/4/94	85/4094	19
LOCATION:	AREA P	
ACTIVITY:		
REMOVAL OF UNDERGROUND FUEL STORAGE TANKS ADJACENT TO FORMER BUILDING A219.		
SPECIAL FEATURES:		
CONCRETE TANK SURROUND CONTAMINATED BY FUEL LEAKAGE.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
26/4/94	85/4094	20
LOCATION:	AREA H	
ACTIVITY:		
H16 AREA - STOCKPILING OF 'SPECIAL' WASTE.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
26/4/94	85/4094	21
LOCATION:	AREA H - ISLAND SITE	
ACTIVITY:		
CANAL EXCAVATION NORTH OF BUILDING A201/2.		
SPECIAL FEATURES:		
WEST CHANNEL FLOWING INTO HOPPITS POOL.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
26/4/94	85/4094	22
LOCATION:	AREA H	
ACTIVITY:		
H16 AREA - STOCKPILING OF 'SPECIAL' WASTE AND LOADING AWAY.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/4/94	85/4094	23
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - FWD REMOVAL ORIGINAL TRENCH LINE INDICATED BY		



SHEET PILING INDENTATIONS.
SPECIAL FEATURES:


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/4/94	85/4094	24

LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - FWD REMOVAL ORIGINAL TRENCH LINE INDICATED BY SHEET PILING INDENTATIONS.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
29/4/94	85/4094	25
LOCATION:	AREA H	
ACTIVITY:		
EXCAVATION OF CANAL DISCHARGING INTO HOPPITS POOL.		
SPECIAL FEATURES:		
MILLSTONE LOCATED IN THE EXCAVATION.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
29/4/94	85/4094	26
LOCATION:	AREA H	
ACTIVITY:		
EXCAVATION OF CANAL DISCHARGING INTO HOPPITS POOL.		
SPECIAL FEATURES:		
MILLSTONE LOCATED IN THE EXCAVATION.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
29/4/94	85/4094	27
LOCATION:	AREA H	
ACTIVITY:		
EXCAVATION OF CANAL DISCHARGING INTO HOPPITS POOL.		
SPECIAL FEATURES:		
MILLSTONE LOCATED IN THE EXCAVATION.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
29/4/94	85/4094	28
LOCATION:	AREA S	
ACTIVITY:		
SEMI PERMANENT FENCE NORTH OF BUILDING 83B AT CANAL CROSS OVER.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
29/4/94	85/4094	29
LOCATION:	AREA S	
ACTIVITY:		
HARDCORED ROAD FROM NEWTONS POOL.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
29/4/94	85/4094	30



LOCATION:	AREAS	
ACTIVITY:		
BUILDING S90 ROOF BEFORE STRIP OFF.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
29/4/94	85/4094	31
LOCATION:	AREA S	
ACTIVITY:		
BUILDING S90 ROOF BEFORE STRIP OFF.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
3/5/94	85/4094	32
LOCATION:	AREA H	
ACTIVITY:		
HYDROCARBON CONTAMINATED AREA NORTH OF FORMER BUILDING H25 FINAL CLEARANCE.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
3/5/94	85/4094	33
LOCATION:	AREA H	
ACTIVITY:		
BUILDING H8 - BREAKING OUT OF ENTRANCE RETAINING WALLS IN MOUND.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
3/5/94	85/4094	34
LOCATION:	AREA P	
ACTIVITY:		
FINAL CLEAR UP OF EXCAVATION FOLLOWING REMOVAL OF BURIED FUEL STORAGE TANKS ADJACENT TO FORMER BUILDING A219.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
3/5/94	85/4094	35
LOCATION:	AREA S	
ACTIVITY:		
CLEARANCE OF CONTAMINATED GROUND TO THE EAST OF FORMER		

TETRYL FACTORY SITE.


SPECIAL FEATURES:






--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/5/94	86/4835	2
LOCATION:	AREA T	
ACTIVITY:		
EXPOSURE OF BURIED REMAINS TO FORMER GUNPOWDER DRYING STOVE LOOKING SOUTH TOWARDS BUILDING E10.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/5/94	86/4835	3
LOCATION:	AREA T	
ACTIVITY:		
LOOKING SOUTH EAST ACROSS FORMER TETRYL FACTORY SITE.		
SPECIAL FEATURES:		
FILLED CANAL IN CENTRE OF SHOT, MOUNDED BUILDING E2 AT TOP LEFT.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/5/94	86/4835	4
LOCATION:	AREA T	
ACTIVITY:		
EXPOSURE OF BURIED REMAINS TO FORMER GUNPOWDER DRYING STOVE LOOKING SOUTH TOWARDS BUILDING E10.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/5/94	86/4835	5
LOCATION:	AREAS	
ACTIVITY:		
RESIDENT FOX.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/5/94	86/4835	6

LOCATION:	AREAS	
ACTIVITY:		
RESIDENT FOX.		
SPECIAL FEATURES:		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/5/94	86/4835	7
LOCATION:	AREA S	
ACTIVITY:		
RESIDENT FOX.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/5/94	86/4835	8
LOCATION:	AREA S	
ACTIVITY:		
RESIDENT FOX.		
SPECIAL FEATURES:		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/5/94	86/4835	9
LOCATION:	AREA S	
ACTIVITY:		
RE-EXCAVATED FILLED BORROW PIT WEST OF BUILDING E2.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/5/94	86/4835	10
LOCATION:	AREA M	
ACTIVITY:		
SOUTH EAST CORNER OF BUILDING L157 - BACKFILLING TO FORMER FWD TRENCH.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/5/94	86/4835	11
LOCATION:	AREA M	
ACTIVITY:		
FWD MANHOLE NORTH OF PUMPING CHAMBER (L170) REMOVED.		

SPECIAL FEATURES:
PUMP CHAMBER WALL TO LEFT OF SHOT.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/5/94	86/4835	12


LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - CORRIDOR PREPARATION BEFORE GRIT BLASTING OF STRUCTURAL STEELWORK.		
SPECIAL FEATURES:		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDICATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/5/94	86/4835	13
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - CORRIDOR PREPARATION BEFORE GRIT BLASTING OF STRUCTURAL STEELWORK.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/5/94	86/4835	14
LOCATION:	AREA H	
ACTIVITY:		
PUMPING GROUND WATER INGRESS FROM HYDROCARBON CONTAMINATED AREA WEST OF BUILDING H26.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/5/94	86/4835	15
LOCATION:	AREA H	
ACTIVITY:		
PUMPING GROUND WATER INGRESS FROM HYDROCARBON CONTAMINATED AREA WEST OF BUILDING H26.		
SPECIAL FEATURES:		
PUMP DISCHARGING OVER GRASS AREA TO FILTER OILS FROM THE WATER BEFORE IT ENTERS MILLHEAD STREAM (NOTE OIL ABSORBING 'SAUSAGES' IN CENTRE OF SHOT).		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/5/94	86/4835	16
LOCATION:	AREA H	
ACTIVITY:		
PUMPING GROUND WATER INGRESS FROM HYDROCARBON CONTAMINATED AREA WEST OF BUILDING H26.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/5/94	86/4835	17
LOCATION:	AREA H	
ACTIVITY:		
PUMPING GROUND WATER INGRESS FROM HYDROCARBON		

CONTAMINATED AREA WEST OF BUILDING H26.
SPECIAL FEATURES:


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/5/94	86/4835	18

LOCATION:	AREA H	
ACTIVITY:		
FILLED CANAL EXCAVATION - HOPPIT ROAD TO H67 - LOOKING NORTH.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/5/94	86/4835	19
LOCATION:	AREA H	
ACTIVITY:		
FILLED CANAL EXCAVATION - HOPPIT ROAD TO H67 - LOOKING NORTH.		
SPECIAL FEATURES:		
NOTE: WALL CONSTRUCTION TO THE RIGHT OF SHOT - BUILT OFF TIMBER PILED FOUNDATIONS.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/5/94	86/4835	20
LOCATION:	AREA H	
ACTIVITY:		
FILLED CANAL EXCAVATION - HOPPIT ROAD TO H67 - LOOKING SOUTH EAST.		
SPECIAL FEATURES:		
NOTE - NATURE OF FILL. - BRICK WALLING CONSTRUCTED ON TIMBER PILED FOUNDATIONS.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/5/94	86/4835	21
LOCATION:	AREA H	
ACTIVITY:		
FILLED CANAL EXCAVATION - HOPPIT ROAD TO H67 - LOOKING EAST.		
SPECIAL FEATURES:		
FILLED WATER DISCHARGE CHANNEL IN CENTRE OF SHOT.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/5/94	86/4835	22
LOCATION:	AREA H	
ACTIVITY:		
FILLED CANAL EXCAVATION - HOPPIT ROAD TO H67 - LOOKING NORTH EAST.		
SPECIAL FEATURES:		



TIMBERED REVETMENTS.




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/5/94	86/4835	23
LOCATION:	AREA H	
ACTIVITY:		
FILLED CANAL EXCAVATION - HOPPIT ROAD TO H67 - LOOKING NORTH		

EAST.
SPECIAL FEATURES:
TIMBERED REVETMENTS.


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
13/5/94	86/4835	24

LOCATION:	AREA T	
ACTIVITY:		
ADJACENT BUILDING E2 - SUSPECTED TNT FIND.		
SPECIAL FEATURES:		
SAMPLING PEGS IN POSITION.		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
13/5/94	86/4835	25
LOCATION:	AREA H	
ACTIVITY:		
REMOVAL OF BUILDING H31 - PUMPING STATION FOUNDATIONS.		
SPECIAL FEATURES:		
BUILDING H10 IN BACKGROUND. WASTE LAID OUT FOR SAMPLING ON H16 SLAB CENTRE / TOP OF SHOT.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
13/5/94	86/4835	26
LOCATION:	AREA H	
ACTIVITY:		
REMOVAL OF BUILDING H31 - PUMPING STATION FOUNDATIONS - LOOKING SOUTH.		
SPECIAL FEATURES:		
'SPECIAL' WASTE STOCKPILED TOP RIGHT OF SHOT.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
13/5/94	86/4835	27
LOCATION:	AREA H	
ACTIVITY:		
REMOVAL OF BUILDING H31 - PUMPING STATION FOUNDATIONS - LOOKING SOUTH.		
SPECIAL FEATURES:		
RAPID GROUND WATER INGRESS.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
13/5/94	86/4835	28
LOCATION:	AREA H	
ACTIVITY:		
HYDROCARBON CONTAMINATED AREA NORTH OF BUILDING H25 LAYING LAND DRAINAGE.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
13/5/94	86/4835	29
LOCATION:	AREA H	
ACTIVITY:		
HYDROCARBON CONTAMINATED AREA NORTH OF BUILDING H25 LAYING		



LAND DRAINAGE - LOOKING NORTH / WEST.
SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
16/5/94	86/4835	30

LOCATION:	AREA H	
ACTIVITY:		
12 TONNE DUMP TRUCK STUCK IN DIFFICULT CONDITIONS.		
SPECIAL FEATURES:		
BUILDING A269 IN BACKGROUND.		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
16/5/94	86/4835	31
LOCATION:	AREA H	
ACTIVITY:		
12 TONNE DUMP TRUCK STUCK IN DIFFICULT CONDITIONS.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
16/5/94	86/4835	32
LOCATION:	AREA S	
ACTIVITY:		
BUILDING S90 - ROOF CLEARED OF UNDERGROWTH.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
16/5/94	86/4835	33
LOCATION:	AREA S	
ACTIVITY:		
BUILDING S90 - ROOF CLEARED OF UNDERGROWTH.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
18/5/94	86/4835	34
LOCATION:	AREA H	
ACTIVITY:		
H31 - BACKFILLING AFTER REMOVAL OF PUMPING CHAMBER (BASE SLAB LEFT IN SITU).		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
18/5/94	86/4835	35
LOCATION:	AREA H	
ACTIVITY:		
H31 - BACKFILLING AFTER REMOVAL OF PUMPING CHAMBER (BASE SLAB		

LEFT IN SITU).
SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
18/5/94	86/4835	36



LOCATION:	AREA H	
ACTIVITY:		
H31 - BACKFILLING AFTER REMOVAL OF PUMPING CHAMBER (BASE SLAB LEFT IN SITU).		
SPECIAL FEATURES:		
SINGLE SIZED STONE FILLING USED UP TO WATER TABLE LEVEL.		




**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDICATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
13/9/94	100/3548	1
LOCATION:	AREA P	
ACTIVITY:		
BARGE RECOVERED FROM MILLHEAD STREAM - PREPARATION FOR LOADING ONTO TRANSPORT.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
13/9/94	100/3548	2
LOCATION:	AREA P	
ACTIVITY:		
BARGE RECOVERED FROM MILLHEAD STREAM - LOADING ONTO TRANSPORT.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
13/9/94	100/3548	3
LOCATION:	AREA P	
ACTIVITY:		
BARGE RECOVERED FROM MILLHEAD STREAM - LOADING ONTO TRANSPORT.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
13/9/94	100/3548	4
LOCATION:	AREA P	
ACTIVITY:		
BARGE RECOVERED FROM MILLHEAD STREAM - LOADING ONTO TRANSPORT.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
13/9/94	100/3548	5
LOCATION:	AREA P	
ACTIVITY:		
BARGE RECOVERED FROM MILLHEAD STREAM - LOADING ONTO		

TRANSPORT.
SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
13/9/94	100/3548	6



LOCATION:	AREA M	
ACTIVITY:		
BARGE RECOVERED FROM MILLHEAD STREAM - UNLOADING AT BUILDING L157.		
SPECIAL FEATURES:		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
13/9/94	100/3548	7
LOCATION:	AREA M	
ACTIVITY:		
CORDITE FOUND IN CANAL ADJACENT BUILDING L145.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
13/9/94	100/3548	8
LOCATION:	AREA M	
ACTIVITY:		
BARGE RECOVERED FROM MILLHEAD STREAM BEING LOWERED INTO MIDDLE STREAM.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
13/9/94	100/3548	9
LOCATION:	AREA M	
ACTIVITY:		
BARGE RECOVERED FROM MILLHEAD STREAM BEING LOWERED INTO MIDDLE STREAM.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
13/9/94	100/3548	10
LOCATION:	AREA M	
ACTIVITY:		
BARGE RECOVERED FROM MILLHEAD STREAM BEING LOWERED INTO MIDDLE STREAM.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
13/9/94	100/3548	11
LOCATION:	AREA M	
ACTIVITY:		
BARGE RECOVERED FROM MILLHEAD STREAM BEING LOWERED INTO		

MIDDLE STREAM.
SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
13/9/94	100/3548	12

LOCATION:	AREA M	
ACTIVITY:		
BUILDING L145 - PREPARATION FOR REMOVAL OF ROOF STEELWORK.		
SPECIAL FEATURES:		



**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
13/9/94	100/3548	13
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L145 - REMOVAL OF ROOF STEELWORK.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
13/9/94	100/3548	14
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L145 - REMOVAL OF ROOF STEELWORK.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
13/9/94	100/3548	15
LOCATION:	AREA P	
ACTIVITY:		
REMOVAL OF BRICK REVETMENT WALLING SOUTH OF BRIDGE No. 1.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
13/9/94	100/3548	16
LOCATION:	AREA P	
ACTIVITY:		
SHEET PILING TO REVETMENT OF MILLHEAD STREAM.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
15/9/94	100/3548	17
LOCATION:	AREA P	
ACTIVITY:		
BRIDGE No. 1 - PREPARATION FOR BRICK ABUTMENT REPAIRS.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
15/9/94	100/3548	18


LOCATION:	AREA P	
ACTIVITY:		
BRIDGE No. 1 - CLOSE UP OF DRAIN CHANNEL WITHIN BRICK ABUTMENT WALLING.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
15/9/94	100/3548	20
LOCATION:	AREA P	
ACTIVITY:		
EXCAVATION OF FILLED GROUND EAST OF BUILDING A214.		
SPECIAL FEATURES:		



--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
15/9/94	100/3548	21
LOCATION:	AREA P	
ACTIVITY:		
EXCAVATION OF FILLED GROUND SOUTH OF BUILDING A214.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
15/9/94	100/3548	23
LOCATION:	AREA P	
ACTIVITY:		
SERVICE TRENCH ON NORTH SIDE OF BUILDING A210.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
15/9/94	100/3548	24
LOCATION:	AREA P	
ACTIVITY:		
SUMP AT NORTH FACE OF BUILDING A210.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
15/9/94	100/3548	25
LOCATION:	AREA P	
ACTIVITY:		
SERVICE TRENCH NORTH OF BUILDING A210.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
16/9/94	100/3548	26

LOCATION:	AREA H	
ACTIVITY:		
REMOVAL OF HYDROCARBON CONTAMINATED GROUND ADJACENT BUILDING H26.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
16/9/94	100/3548	27
LOCATION:	AREA H	
ACTIVITY:		
REMOVAL OF HYDROCARBON CONTAMINATED GROUND ADJACENT BUILDING H26.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
18/9/94	100/3548	28
LOCATION:	AREA P	
ACTIVITY:		
BRIDGE No. 1 - SOUTH EAST ABUTMENT - BRICKWORK REPAIRED.		
SPECIAL FEATURES:		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
18/9/94	100/3548	29
LOCATION:	AREA P	
ACTIVITY:		
BRIDGE No. 1 - SOUTH EAST ABUTMENT - BRICKWORK REPAIRED.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
19/9/94	100/3548	30
LOCATION:	AREA P	
ACTIVITY:		
BRIDGE No. 1 - GENERAL VIEW.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
19/9/94	100/3548	31
LOCATION:	AREA P	
ACTIVITY:		
BRIDGE No. 1 - GENERAL VIEW.		

SPECIAL FEATURES:


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
19/9/94	100/3548	32

LOCATION:	AREA P	
ACTIVITY:		
BRIDGE No. 1 - GENERAL VIEW.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
19/9/94	100/3548	33
LOCATION:	AREA P	
ACTIVITY:		
SHEET PILING TO MILLHEAD STREAM REVETMENT SOUTH OF BRIDGE No. 1.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
19/9/94	100/3548	34
LOCATION:	AREA P	
ACTIVITY:		
SHEET PILING TO MILLHEAD STREAM REVETMENT SOUTH OF BRIDGE No. 1.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
20/9/94	100/3548	35
LOCATION:	AREA H	
ACTIVITY:		
MILLHEAD STREAM - WEST BANK (ADJACENT BUILDING H26) - REMOVAL OF CONTAMINATED GROUND AND REPLACEMENT WITH IMPORTED FILL.		
SPECIAL FEATURES:		






FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
20/9/94	100/3548	37
LOCATION:	AREA H	
ACTIVITY:		
MILLHEAD STREAM - WEST BANK (ADJACENT BUILDING H26) - REMOVAL OF CONTAMINATED GROUND AND REPLACEMENT WITH IMPORTED FILL.		
SPECIAL FEATURES:		

ISLAND SITE SERVICES ROUTE VISIBLE.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
21/9/94	101/7574	1
LOCATION:	AREA H	
ACTIVITY:		
VIEW OF COLLAPSED CANAL WALL EAST OF BUILDING H26.		
SPECIAL FEATURES:		
CAUSED BY ROTTED TIMBER REVETMENT PILES.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
21/9/94	101/7574	2
LOCATION:	AREA H	
ACTIVITY:		
VIEW OF COLLAPSED CANAL WALL EAST OF BUILDING H26.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
21/9/94	101/7574	3
LOCATION:	AREA H	
ACTIVITY:		
VIEW OF CANAL WALL - EAST OF BUILDING H26 WHERE COLLAPSE HAS OCCURRED.		
SPECIAL FEATURES:		
NOTE: NEW IMPORTED GRANULAR FILLING BEHIND CANAL WALL AFTER REMOVAL OF CONTAMINATED GROUND.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
21/9/94	101/7574	5
LOCATION:	AREA S	
ACTIVITY:		
CANAL INTERSECTION 27 LOOKING NORTH.		
SPECIAL FEATURES:		

TRIAL PIT ACROSS FILLED CANAL.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
21/9/94	101/7574	6
LOCATION:	AREAS	
ACTIVITY:		
CANAL INTERSECTION 27 LOOKING SOUTH.		

SPECIAL FEATURES:
TRIAL PIT ACROSS FILLED CANAL.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
21/9/94	101/7574	7




LOCATION:	AREAS	
ACTIVITY:		
CANAL INTERSECTION 29 LOOKING NORTH.		
SPECIAL FEATURES:		
TRIAL PIT ACROSS FILLED CANAL.		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
21/9/94	101/7574	8
LOCATION:	AREA S	
ACTIVITY:		
CANAL INTERSECTION 29 LOOKING SOUTH.		
SPECIAL FEATURES:		
TRIAL PIT ACROSS FILLED CANAL.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
22/9/94	101/7574	9
LOCATION:	AREA P	
ACTIVITY:		
MILLHEAD STREAM JUNCTION WITH BRIDGE No. 1 SOUTH EAST ABUTMENT.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
22/9/94	101/7574	11
LOCATION:	AREA P	
ACTIVITY:		
REMOVAL OF CONTAMINATED GROUND EAST OF BUILDING A210.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
22/9/94	101/7574	12
LOCATION:	AREA P	
ACTIVITY:		
REMOVAL OF CONTAMINATED GROUND EAST OF BUILDING A210.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
22/9/94	101/7574	13
LOCATION:	AREA T	
ACTIVITY:		
CANAL INTERSECTION 26 LOOKING NORTH.		

SPECIAL FEATURES:
TRIAL PIT ACROSS FILLED CANAL.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
22/9/94	101/7574	14

LOCATION:	AREA T	
ACTIVITY:		
CANAL INTERSECTION 26 LOOKING SOUTH.		
SPECIAL FEATURES:		
TRIAL PIT ACROSS FILLED CANAL.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
22/9/94	101/7574	15
LOCATION:	AREA T	
ACTIVITY:		
CANAL INTERSECTION 25 LOOKING NORTH.		
SPECIAL FEATURES:		
TRIAL PIT ACROSS FILLED CANAL.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
22/9/94	101/7574	16
LOCATION:	AREA T	
ACTIVITY:		
CANAL INTERSECTION 25 LOOKING SOUTH.		
SPECIAL FEATURES:		
TRIAL PIT ACROSS FILLED CANAL.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
23/9/94	101/7574	17
LOCATION:	AREA S	
ACTIVITY:		
CANAL INTERSECTION 22 LOOKING NORTH.		
SPECIAL FEATURES:		
TRIAL PIT.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
23/9/94	101/7574	18
LOCATION:	AREAS	
ACTIVITY:		
CANAL INTERSECTION 22 LOOKING SOUTH.		
SPECIAL FEATURES:		

TRIAL PIT.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
23/9/94	101/7574	19
LOCATION:	AREA S	
ACTIVITY:		
CANAL INTERSECTION 21 LOOKING NORTH.		

SPECIAL FEATURES:
TRIAL PIT ACROSS FILLED CANAL.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
23/9/94	101/7574	20


LOCATION:	AREAS	
ACTIVITY:		
CANAL INTERSECTION 21 LOOKING SOUTH.		
SPECIAL FEATURES:		
TRIAL PIT ACROSS FILLED CANAL.		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
26/9/94	101/7574	21
LOCATION:	AREA P	
ACTIVITY:		
DORMER WINDOW - BUILDING A221.		
SPECIAL FEATURES:		



--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
26/9/94	101/7574	23
LOCATION:	AREA P	
ACTIVITY:		
SOUTH WEST VIEW ACROSS AREA P NORTH.		
SPECIAL FEATURES:		
NOTE: LIVE GAS MAIN CROSSING THE SITE.		




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
26/9/94	101/7574	24
LOCATION:	AREA P	
ACTIVITY:		
AREA P SOUTH - MILLHEAD STREAM EAST BANK EXCAVATED BEHIND NEW SHEET PILING.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/9/94	101/7574	25
LOCATION:	AREAS	
ACTIVITY:		
CANAL INTERSECTION 11 LOOKING NORTH.		
SPECIAL FEATURES:		

TRIAL PIT ACROSS FILLED CANAL.



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/9/94	101/7574	26
LOCATION:	AREA S	
ACTIVITY:		
CANAL INTERSECTION 11 LOOKING SOUTH.		


SPECIAL FEATURES:
TRIAL PIT ACROSS FILLED CANAL.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/9/94	101/7574	27

LOCATION:	AREAS	
ACTIVITY:		
CANAL INTERSECTION 15 LOOKING NORTH.		
SPECIAL FEATURES:		
TRIAL PIT ACROSS FILLED CANAL.		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/9/94	101/7574	28
LOCATION:	AREA S	
ACTIVITY:		
CANAL INTERSECTION 15 LOOKING SOUTH.		
SPECIAL FEATURES:		
TRIAL PIT ACROSS FILLED CANAL.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/9/94	101/7574	29
LOCATION:	AREA S	
ACTIVITY:		
CANAL INTERSECTION 17 LOOKING NORTH.		
SPECIAL FEATURES:		
TRIAL PIT ACROSS FILLED CANAL.		






FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/9/94	101/7574	30
LOCATION:	AREA S	
ACTIVITY:		
CANAL INTERSECTION 17 LOOKING SOUTH.		
SPECIAL FEATURES:		
TRIAL PIT ACROSS FILLED CANAL.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
28/9/94	101/7574	31
LOCATION:	AREAS	
ACTIVITY:		
CANAL INTERSECTION 8 LOOKING NORTH.		
SPECIAL FEATURES:		

TRIAL PIT ACROSS FILLED CANAL.



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
28/9/94	101/7574	32
LOCATION:	AREA S	
ACTIVITY:		
CANAL INTERSECTION 8 LOOKING SOUTH.		

SPECIAL FEATURES:
TRIAL PIT ACROSS FILLED CANAL.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
28/9/94	101/7574	33

LOCATION:	AREAS	
ACTIVITY:		
CANAL INTERSECTION 10 LOOKING NORTH.		
SPECIAL FEATURES:		
TRIAL PIT ACROSS FILLED CANAL.		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
28/9/94	101/7574	34
LOCATION:	AREA S	
ACTIVITY:		
CANAL INTERSECTION 10 LOOKING SOUTH.		
SPECIAL FEATURES:		
TRIAL PIT ACROSS FILLED CANAL.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
29/9/94	101/7574	35
LOCATION:	AREA S	
ACTIVITY:		
CANAL INTERSECTION 16 LOOKING EAST.		
SPECIAL FEATURES:		
TRIAL PIT ACROSS FILLED CANAL.		




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
29/9/94	101/7574	36
LOCATION:	AREA S	
ACTIVITY:		
CANAL INTERSECTION 16 LOOKING WEST.		
SPECIAL FEATURES:		
TRIAL PIT ACROSS FILLED CANAL.		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
30/9/94	101/7574	37
LOCATION:	AREA H	
ACTIVITY:		
REMOVAL OF DEEP FOUNDATIONS TO BUILDING H10.		
SPECIAL FEATURES:		




**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
30/9/94	102/7781	1
LOCATION:	AREA H	
ACTIVITY:		
BUILDING H8 - VIEW OF EXCAVATION AFTER REMOVAL OF FOUNDATIONS.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
30/9/94	102/7781	2
LOCATION:	AREA H	
ACTIVITY:		
BUILDING H10 - VIEW OF EXCAVATION AFTER REMOVAL OF FOUNDATIONS.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
30/9/94	102/7781	3
LOCATION:	AREA H	
ACTIVITY:		
STOCKPILE OF EXCAVATED MATERIAL AT BUILDING H10.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
30/9/94	102/7781	4
LOCATION:	AREA H	
ACTIVITY:		
BUILDING H8 - VIEW OF EXCAVATION AFTER REMOVAL OF FOUNDATIONS.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
30/9/94	102/7781	5
LOCATION:	AREA H	
ACTIVITY:		
BUILDING H8 - VIEW OF EXCAVATION AFTER REMOVAL OF		

FOUNDATIONS.
SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
30/9/94	102/7781	6




LOCATION:	AREA H	
ACTIVITY:		
BUILDING H8 - VIEW OF EXCAVATION AFTER REMOVAL OF FOOTING.		
SPECIAL FEATURES:		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
30/9/94	102/7781	7
LOCATION:	AREA H	
ACTIVITY:		
FORKLIFT ON VEHICLE WASHDOWN AREA.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
30/9/94	102/7781	8
LOCATION:	AREA H	
ACTIVITY:		
FORKLIFT ON VEHICLE WASHDOWN AREA.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
4/10/94	102/7781	9
LOCATION:	AREA H	
ACTIVITY:		
SUSPECT CYLINDER RETRIEVED DURING DREDGING OPERATIONS NORTH OF BRIDGE No. 3.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
4/10/94	102/7781	10
LOCATION:	AREA H	
ACTIVITY:		
SUSPECT CYLINDER RETRIEVED DURING DREDGING OPERATIONS NORTH OF BRIDGE No. 3.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
4/10/94	102/7781	11
LOCATION:	AREA H	
ACTIVITY:		
SUSPECT CYLINDER RETRIEVED DURING DREDGING OPERATIONS NORTH		

OF BRIDGE No. 3.
SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
4/10/94	102/7781	12

LOCATION:	AREA H	
ACTIVITY:		
SUSPECT CYLINDER RETRIEVED DURING DREDGING OPERATIONS NORTH OF BRIDGE No. 3.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
4/10/94	102/7781	13
LOCATION:	AREA H	
ACTIVITY:		
SUSPECT CYLINDER RETRIEVED DURING DREDGING OPERATIONS NORTH OF BRIDGE No. 3.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
5/10/94	102/7781	15
LOCATION:	AREA P	
ACTIVITY:		
CLAY PLACEMENT BEHIND MILLHEAD STREAM SHEET PILING.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
5/10/94	102/7781	16
LOCATION:	AREA P	
ACTIVITY:		
CLAY PLACEMENT BEHIND MILLHEAD STREAM SHEET PILING.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
5/10/94	102/7781	17
LOCATION:	AREA H	
ACTIVITY:		
BUILDING H8 - BACKFILLING EXCAVATION.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
5/10/94	102/7781	18
LOCATION:	AREA H	
ACTIVITY:		
BUILDING H8 - BACKFILLING EXCAVATION.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
8/10/94	102/7781	19

LOCATION:	AREA H - ISLAND SITE	
ACTIVITY:		
TREE PRIOR TO FELLING, NORTH OF BRIDGE No. 3.		
SPECIAL FEATURES:		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDICATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
8/10/94	102/7781	20
LOCATION:	AREA H - ISLAND SITE	
ACTIVITY:		
TREE FELLING IN PROGRESS NORTH OF BRIDGE No. 3.		
SPECIAL FEATURES:		



--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/10/94	102/7781	21
LOCATION:	AREA H - ISLAND SITE	
ACTIVITY:		
TREE FELLING COMPLETED NORTH OF BRIDGE No. 3.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
11/10/94	102/7781	22
LOCATION:	AREA P	
ACTIVITY:		
PUMPING OVER SHEET PILE WALL OF MILLHEAD STREAM.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
11/10/94	102/7781	23
LOCATION:	AREA P	
ACTIVITY:		
PIPE IN PLACE FOR PUMPING OVER SHEET PILE WALL AT MILLHEAD STREAM.		
SPECIAL FEATURES:		



<b>FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD</b>		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
11/10/94	102/7781	24
LOCATION:	AREA P	
ACTIVITY:		
VIEW OF SHEET PILE WALL TO MILLHEAD STREAM.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
11/10/94	102/7781	25

LOCATION:	AREA P	
ACTIVITY:		
REMOVAL OF DRAIN RUN WEST OF BUILDING A221.		
SPECIAL FEATURES:		


**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
11/10/94	102/7781	26
LOCATION:	AREA P	
ACTIVITY:		
SHEET PILE WALL TO MILLHEAD STREAM.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
14/10/94	102/7781	27
LOCATION:	AREA S	
ACTIVITY:		
CANAL INTERSECTION 31 LOOKING NORTH.		
SPECIAL FEATURES:		
TRIAL PIT ACROSS FILLED CANAL.		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
14/10/94	102/7781	28
LOCATION:	AREA S	
ACTIVITY:		
CANAL INTERSECTION 31 LOOKING SOUTH.		
SPECIAL FEATURES:		
TRIAL TRENCH ACROSS FILLED CANAL.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
14/10/94	102/7781	29
LOCATION:	AREA S	
ACTIVITY:		
CONSTRUCTION OF NEW ROAD WEST OF BUILDING 103.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
14/10/94	102/7781	30
LOCATION:	AREA P	
ACTIVITY:		
CONSTRUCTION OF NEW ROAD SOUTH OF BRIDGE No. 2.		

SPECIAL FEATURES:
TERRAM FILTER MEMBRANE IN FOREGROUND.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
14/10/94	102/7781	31

LOCATION:	AREA P	
ACTIVITY:		
AREA P NORTH - REMEDIATION OF DITCH ADJACENT TO CONSTRUCTION NEW ACCESS ROAD.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
14/10/94	102/7781	32
LOCATION:	AREA P	
ACTIVITY:		
AREA P NORTH - REMEDIATED DITCH EAST OF ACCESS ROAD CONSTRUCTION SOUTH OF BRIDGE No. 2.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
14/10/94	102/7781	33
LOCATION:	AREA P	
ACTIVITY:		
SETTING OUT OF NEW ACCESS ROAD TO BRIDGE No. 2.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
14/10/94	102/7781	34
LOCATION:	AREA H - ISLAND SITE	
ACTIVITY:		
BUOYANCY TANKS BEING LIFTED INTO HOPPITS POOL NORTH OF BUILDING A201/2.		
SPECIAL FEATURES:		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
14/10/94	102/7781	35
LOCATION:	AREA H - ISLAND SITE	
ACTIVITY:	SETTING UP PUMP ON BUOYANCY TANKS IN HOPPITS POOL.	
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
14/10/94	102/7781	36
LOCATION:	AREA P	
ACTIVITY:		
NEW ACCESS ROAD UNDER CONSTRUCTION TO BRIDGE No. 2.		

--

SPECIAL FEATURES:

--


--

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
19/10/94	103/8702	1
LOCATION:	AREA	
ACTIVITY:		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
19/10/94	103/8702	2
LOCATION:	AREA T	
ACTIVITY:		
OVERTURNED TRACTOR IN TETRYL FACTORY AREA.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
19/10/94	103/8702	5
LOCATION:	AREA H	
ACTIVITY:		
CLAY FILL WEST OF BUILDING H26.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
19/10/94	103/8702	6
LOCATION:	AREA H	
ACTIVITY:		
CLAY FILL NORTH OF BUILDING H26.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
19/10/94	103/8702	7
LOCATION:	AREA H	
ACTIVITY:		
CLAY FILL NORTH OF BUILDING H26.		



SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
19/10/94	103/8702	8

LOCATION:	AREA P	
ACTIVITY:		
NEW ACCESS ROAD TO BRIDGE No. 2 LOOKING SOUTH.		
SPECIAL FEATURES:		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
19/10/94	103/8702	9
LOCATION:	AREA P	
ACTIVITY:		
NEW ACCESS ROAD TO BRIDGE No. 2 LOOKING SOUTH WEST.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
19/10/94	103/8702	10
LOCATION:	AREA P	
ACTIVITY:		
NEW ACCESS ROAD TO BRIDGE No. 2 LOOKING NORTH WEST.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
19/10/94	103/8702	11
LOCATION:	AREA M	
ACTIVITY:		
900MM LONG PIKE FOUND OPPOSITE BUILDING L148.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
19/10/94	103/8702	12
LOCATION:	AREA H	
ACTIVITY:		
DAMAGE TO SECURITY BARRIER AT HIGHBRIDGE STREET ENTRANCE.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
19/10/94	103/8702	13
LOCATION:	AREA H	
ACTIVITY:		
DAMAGE TO SECURITY BARRIER AT HIGHBRIDGE STREET ENTRANCE.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
20/10/94	103/8702	14



LOCATION:	AREA M	
ACTIVITY:		
SCRAP METAL STOCKPILED BY ROUNDABOUT.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
20/10/94	103/8702	15
LOCATION:	AREA M	
ACTIVITY:		
SCRAP METAL STOCKPILED AT ROUNDABOUT.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
20/10/94	103/8702	16
LOCATION:	AREA H	
ACTIVITY:		
DAMAGE TO SECURITY FENCE WEST OF BUILDING H8.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
20/10/94	103/8702	17
LOCATION:	AREA H	
ACTIVITY:		
DAMAGE TO SECURITY FENCE WEST OF BUILDING H8.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
21/10/94	103/8702	18
LOCATION:	AREA T	
ACTIVITY:		
GULLY POT CONTAINING DEPOSITS OF EXPLOSIVE IN TETRYL FACTORY.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
21/10/94	103/8702	19
LOCATION:	AREA T	
ACTIVITY:		
GULLY POT EXCAVATION CONTAINING DEPOSITS OF EXPLOSIVE IN		

TETRYL FACTORY.
SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
25/10/94	103/8702	22

LOCATION:	AREA P	
ACTIVITY:		
ROAD CONSTRUCTION WEST OF BUILDING A221.		
SPECIAL FEATURES:		




**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
26/10/94	103/8702	23
LOCATION:	AREA P	
ACTIVITY:		
STEEL TANKS WELDED TO SHEET PILE PRIOR TO RETRIEVING CONCRETE.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
26/10/94	103/8702	24
LOCATION:	AREA S	
ACTIVITY:		
CHECKING THE DEPTH PRIOR TO THE INSTALLATION OF A PORTADAM NORTH OF BUILDING L136.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
26/10/94	103/8702	25
LOCATION:	AREA S	
ACTIVITY:		
PORTADAM UNDER CONSTRUCTION NORTH OF BUILDING L136.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
26/10/94	103/8702	27
LOCATION:	AREA S	
ACTIVITY:		
PORTADAM UNDER CONSTRUCTION NORTH OF BUILDING L136.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
26/10/94	103/8702	28
LOCATION:	AREA S	
ACTIVITY:		
PORTADAM UNDER CONSTRUCTION.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
26/10/94	103/8702	29

LOCATION:	AREAS	
ACTIVITY:		
PORTADAM UNDER CONSTRUCTION NORTH OF BUILDING L136.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
26/10/94	103/8702	30
LOCATION:	AREA S	
ACTIVITY:		
COMPLETED INSTALLATION OF PORTADAM.		
SPECIAL FEATURES:		



--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/10/94	103/8702	31
LOCATION:	AREA P	
ACTIVITY:		
NEW ACCESS ROAD TO BRIDGE No. 2 LOOKING NORTH.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/10/94	103/8702	32
LOCATION:	AREA P	
ACTIVITY:		
NEW ACCESS ROAD FROM BRIDGE No. 2 LOOKING SOUTH.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
2/11/94	103/8702	33
LOCATION:	AREA H	
ACTIVITY:		
NEW ROAD CONSTRUCTION.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
2/11/94	103/8702	34
LOCATION:	AREA H	
ACTIVITY:		
DREDGING MILLHEAD STREAM.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
3/11/94	103/8702	35


LOCATION:	AREA P	
ACTIVITY:		
PLACING OF LOGS TO EDGE NEW ROAD.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
3/11/94	103/8702	36
LOCATION:	AREA P	
ACTIVITY:		
NEW ROAD CONSTRUCTION TO BUILDING A210.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
3/11/94	103/8702	37
LOCATION:	AREA P	
ACTIVITY:		
REMEDIATING RIVER BANK EAST OF BUILDING A200.		
SPECIAL FEATURES:		






FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
3/11/94	104/9710	1
LOCATION:	AREA L	
ACTIVITY:		
SATURATED CANAL DREDGINGS STOCKPILED ON QUEENS MEAD.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
3/11/94	104/9710	2
LOCATION:	AREA L	
ACTIVITY:		
SATURATED CANAL DREDGINGS STOCKPILED ON QUEENS MEAD.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
3/11/94	104/9710	3
LOCATION:	AREA L	
ACTIVITY:		
SATURATED CANAL DREDGINGS STOCKPILED ON QUEENS MEAD.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
4/11/94	104/9710	4
LOCATION:	AREA M	
ACTIVITY:		
WATER OUTFALL INTO RIVER LEA EAST OF BUILDING A210.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
4/11/94	104/9710	5
LOCATION:	AREA M	
ACTIVITY:		
WATER OUTFALL TO RIVER LEA.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
4/11/94	104/9710	7

LOCATION:	AREA N	
ACTIVITY:		
STAG BURIED AT NEW HILL.		
SPECIAL FEATURES:		




**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDICATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
4/11/94	104/9710	8
LOCATION:	AREA S	
ACTIVITY:		
CLAY BRIDGE ACROSS DRAINAGE DITCH WEST OF LONG WALK.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
4/11/94	104/9710	9
LOCATION:	AREA H	
ACTIVITY:		
TEMPORARY ROAD NORTH OF H67 TOWARDS LOCK.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
8/11/94	104/9710	10
LOCATION:	AREA H	
ACTIVITY:		
KOCUREK MACHINE ON MILLHEAD STREAM BANK.		
SPECIAL FEATURES:		
WIDE TRACKS AND ELEVATED LEVEL OF CAB TO ALLOW IT TO ENTER CANALS.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
8/11/94	104/9710	12
LOCATION:	AREA P	
ACTIVITY:		
CULVERT AND DRAIN UNDER GARDEN WALL TO BUILDING A221.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
8/11/94	104/9710	13
LOCATION:	AREA P	
ACTIVITY:		
WORK ON NEW ROAD LOOKING NORTH TO BRIDGE No. 2.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
11/11/94	104/9710	14

LOCATION:	AREA H	
ACTIVITY:		
NEW ROAD LAYOUT UNDER CONSTRUCTION.		
SPECIAL FEATURES:		


**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
11/11/94	104/9710	15
LOCATION:	AREA H	
ACTIVITY:		
NEW ROAD LAYOUT UNDER CONSTRUCTION.		
SPECIAL FEATURES:		



--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
11/11/94	104/9710	16
LOCATION:	AREA H	
ACTIVITY:		
H10 - BREAKING OUT CONCRETE FOUNDATION SLAB.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
15/11/94	104/9710	17
LOCATION:	AREA P	
ACTIVITY:		
BREAKING OUT MANHOLE AT REAR OF BUILDING A214.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
15/11/94	104/9710	18
LOCATION:	AREA P	
ACTIVITY:		
DRAIN EXPOSED EAST OF BUILDING A210.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
15/11/94	104/9710	19
LOCATION:	AREA L	
ACTIVITY:		
RUBBLE BENEATH UNDERGROWTH ON BANKS OF DRAINAGE DITCH WEST		

OF LONG WALK.
SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
15/11/94	104/9710	20


LOCATION:	AREA L	
ACTIVITY:		
RUBBLE BENEATH UNDERGROWTH ON BANKS OF DRAINAGE DITCH WEST OF LONG WALK.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
16/11/94	104/9710	21
LOCATION:	AREA P	
ACTIVITY:		
ASBESTOS FOUND IN SERVICE DUCT SOUTH OF BUILDING A210 MACHINE SHOP.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
16/11/94	104/9710	22
LOCATION:	AREA P	
ACTIVITY:		
EXCAVATED ASH PIT SOUTH OF BUILDING A210.		
SPECIAL FEATURES:		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
16/11/94	104/9710	23
LOCATION:	AREA P	
ACTIVITY:		
EXCAVATED ASH PIT SOUTH OF BUILDING A210.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
17/11/94	104/9710	25
LOCATION:	AREA H	
ACTIVITY:		
CHECKING PROGRESS WEST OF HOPPITS POOL.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
17/11/94	104/9710	26
LOCATION:	AREA P	
ACTIVITY:		
EXCAVATED ASH PIT SOUTH OF BUILDING A210.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
17/11/94	104/9710	27

LOCATION:	AREA P	
ACTIVITY:		
MEN DIGGING AND BAGGING ASBESTOS FROM SERVICE TRENCH SOUTH BUILDING A210 MACHINE SHOP.		
SPECIAL FEATURES:		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
17/11/94	104/9710	28
LOCATION:	AREA P	
ACTIVITY:		
REMOVAL OF ASBESTOS FROM SERVICE TRENCH SOUTH OF BUILDING A210 MACHINE SHOP.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
17/11/94	104/9710	29
LOCATION:	AREA P	
ACTIVITY:		
DUCT CLEANED OUT OF ASBESTOS SOUTH OF BUILDING A210 MACHINE SHOP.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
21/11/94	104/9710	30
LOCATION:	AREA P	
ACTIVITY:		
LINING EXCAVATED ASH PIT WITH CLAY SOUTH OF BUILDING A210.		
SPECIAL FEATURES:		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
21/11/94	104/9710	31
LOCATION:	AREA M	
ACTIVITY:		
VIEW OF BRIDGE No. 30 - DERELICT PEDESTRIAN SERVICE BRIDGE.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
21/11/94	104/9710	32
LOCATION:	AREA P	
ACTIVITY:		
CLAY INFILL TO EXCAVATED ASH PIT SOUTH OF BUILDING A210.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
21/11/94	104/9710	33

LOCATION:	AREA H	
ACTIVITY:		
CONSTRUCTION OF NEW ROAD.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
22/11/94	104/9710	34
LOCATION:	AREA M	
ACTIVITY:		
GENERAL VIEW FROM ELEVATED PLATFORM - REPAIRS TO ROOF OF BUILDING L168.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
22/11/94	104/9710	35
LOCATION:	AREA L	
ACTIVITY:		
GENERAL VIEW FROM ELEVATED PLATFORM LOOKING NORTH ACROSS QUEENS MEAD.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
22/11/94	104/9710	36
LOCATION:	AREA P	
ACTIVITY:		
GENERAL VIEW FROM ELEVATED PLATFORM LOOKING SOUTH.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
22/11/94	104/9710	37
LOCATION:	AREA P	
ACTIVITY:		
GENERAL VIEW FROM ELEVATED PLATFORM LOOKING SOUTH.		
SPECIAL FEATURES:		





FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
22/11/94	105/9709	1
LOCATION:	AREA H	
ACTIVITY:		
GENERAL VIEW FROM ELEVATED PLATFORM LOOKING WEST.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
22/11/94	105/9709	2
LOCATION:	AREA P	
ACTIVITY:		
GENERAL VIEW FROM ELEVATED PLATFORM LOOKING SOUTH EAST.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
22/11/94	105/9709	3
LOCATION:	AREA L / M	
ACTIVITY:		
GENERAL VIEW FROM ELEVATED PLATFORM LOOKING NORTH EAST.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
22/11/94	105/9709	4
LOCATION:	AREA H - ISLAND SITE	
ACTIVITY:		
GENERAL VIEW FROM ELEVATED PLATFORM LOOKING SOUTH WEST.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
22/11/94	105/9709	5
LOCATION:	AREA P	
ACTIVITY:		
GENERAL VIEW FROM ELEVATED PLATFORM LOOKING SOUTH.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
23/11/94	105/9709	7

LOCATION:	AREA S	
ACTIVITY:		
MOVING BARGE IN CANAL NORTH OF BUILDING L136.		
SPECIAL FEATURES:		




**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
23/11/94	105/9709	8
LOCATION:	AREA S	
ACTIVITY:		
MOVING BARGE IN CANAL NORTH OF BUILDING L136.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
24/11/94	105/9709	11
LOCATION:	AREA M	
ACTIVITY:		
TYPICAL VIEW OF DUMP TRUCK.		
SPECIAL FEATURES:		





--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
25/11/94	106/5253	2
LOCATION:	AREA H	
ACTIVITY:		
FOUL WATER MANHOLE REMOVED NORTH OF H17.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
25/11/94	106/5253	3
LOCATION:	AREA H	
ACTIVITY:		
FOUL WATER MANHOLE REMOVED NORTH OF H17.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
28/11/94	106/5253	5
LOCATION:	AREA P	
ACTIVITY:		
SOUTH SIDE OF BUILDING A210 - EXCAVATING PRIOR TO CLAY LINING.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
28/11/94	106/5253	6
LOCATION:	AREAS	
ACTIVITY:		
BUILDING E7 - EXCAVATED BRICKWORK PAVEMENT / WALKWAY.		



SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
28/11/94	106/5253	7

LOCATION:	AREAS	
ACTIVITY:		
BUILDING E7 - EXCAVATED BRICKWORK PAVEMENT / WALKWAY.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
28/11/94	106/5253	8
LOCATION:	AREA S	
ACTIVITY:		
CLEANING OUT LOCK NORTH OF BUILDING L136.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
28/11/94	106/5253	9
LOCATION:	AREA S	
ACTIVITY:		
CLEANING OUT LOCK NORTH OF BUILDING L136.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
28/11/94	106/5253	10
LOCATION:	AREA S	
ACTIVITY:		
FOUNDATIONS EXCAVATED BY BARGES IN CANAL EAST OF BUILDING L100.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
28/11/94	106/5253	11
LOCATION:	AREA S	
ACTIVITY:		
FOUNDATIONS EXCAVATED BY BARGES IN CANAL EAST OF BUILDING L100.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
28/11/94	106/5253	12
LOCATION:	AREA S	
ACTIVITY:		
1ST BARGE MOVED NORTH OF BUILDING L136.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
28/11/94	106/5253	R



LOCATION:	AREAS	
ACTIVITY:		
BARGES WAITING TO BE MOVED IN CANAL NORTH OF BUILDING L136.		
SPECIAL FEATURES:		




**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
1/12/94	107/6238	1
LOCATION:	AREA	
ACTIVITY:		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
1/12/94	107/6238	2
LOCATION:	AREA H	
ACTIVITY:		
ROAD CROSSING UNDER CONSTRUCTION IN CANAL NORTH OF HOPPITS POOL.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
1/12/94	107/6238	3
LOCATION:	AREA M	
ACTIVITY:		
ROAD CROSSING UNDER CONSTRUCTION IN CANAL NORTH OF HOPPITS POOL.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
1/12/94	107/6238	4
LOCATION:	AREA P	
ACTIVITY:		
BUILDING A210 - NEW ROAD TO MACHINE SHOP.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
1/12/94	107/6238	5
LOCATION:	AREA P	
ACTIVITY:		
BUILDING A210 - NEW ROAD TO MACHINE SHOP.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
6/12/94	107/6238	12




LOCATION:	AREA M	
ACTIVITY:		
EXPLOSIVES IGNITER SYSTEM FOUND IN SPOIL ADJACENT TO BUILDING L110.		
SPECIAL FEATURES:		
HEAT TREATED ON BURNING GROUND.		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
6/12/94	107/6238	13
LOCATION:	AREA M	
ACTIVITY:		
DISCARDED BATTERY PACK FOUND IN SPOIL ADJACENT TO BUILDING L110.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
13/12/94	107/6238	14
LOCATION:	AREA B	
ACTIVITY:		
CONTROLLED FIRE ON BURNING GROUND.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
13/12/94	107/6238	15
LOCATION:	AREA B	
ACTIVITY:		
CONTROLLED FIRE ON BURNING GROUND.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
16/12/94	107/6238	16
LOCATION:	AREA S	
ACTIVITY:		
LOCK CLEANED OUT NORTH OF BUILDING L136.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
16/12/94	107/6238	17
LOCATION:	AREA M	
ACTIVITY:		
EXCAVATION AROUND BUILDING L110.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
16/12/94	107/6238	18


LOCATION:	AREAS	
ACTIVITY:		
BARGES IN CANAL EAST OF BUILDING L109.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
16/12/94	107/6238	19
LOCATION:	AREA M	
ACTIVITY:		
EXCAVATION OF CANAL SOUTH OF BUILDING L109.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
16/12/94	107/6238	20
LOCATION:	AREA S	
ACTIVITY:		
CLEARING CAUSEWAY EAST OF BUILDING L111.		
SPECIAL FEATURES:		




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
16/12/94	107/6238	21
LOCATION:	AREA H	
ACTIVITY:		
COMPLETED ROAD CROSSING OF CANAL NORTH OF HOPPITS POOL.		
SPECIAL FEATURES:		





--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
4/1/95	108/8183	2
LOCATION:	AREA H	
ACTIVITY:		
EXCAVATION ADJACENT TO WEST BOUNDARY FENCE.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
4/1/95	108/8183	3
LOCATION:	AREA H	
ACTIVITY:		
RUBBLE INFILL FOUND IN TRENCH ADJACENT TO BOUNDARY FENCE.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
4/1/95	108/8183	4
LOCATION:	AREA P	
ACTIVITY:		
ASH PIT EXCAVATION EAST OF BUILDING A210 - LOOKING EAST.		
SPECIAL FEATURES:		




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
4/1/95	108/8183	5
LOCATION:	AREA P	
ACTIVITY:		
ASH PIT EXCAVATION LOOKING WEST TOWARDS BUILDING A210.		

SPECIAL FEATURES:


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
4/1/95	108/8183	6

LOCATION:	AREA P	
ACTIVITY:		
ASH PIT EXCAVATION LOOKING WEST TOWARDS BUILDING A210.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
4/1/95	108/8183	7
LOCATION:	AREA P	
ACTIVITY:		
ASH PIT EXCAVATION LOOKING NORTH ADJACENT TO BUILDING A210.		
SPECIAL FEATURES:		
PUMPS DE-WATERING ASH PIT.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
4/1/95	108/8183	8
LOCATION:	AREA P	
ACTIVITY:		
ASH PIT EXCAVATION LOOKING WEST TOWARDS BUILDING A210.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
4/1/95	108/8183	9
LOCATION:	AREA P	
ACTIVITY:		
EAST END OF ASH PIT LOOKING NORTH TO BUILDING A214.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
4/1/95	108/8183	10
LOCATION:	AREA P	
ACTIVITY:		
ASH PIT EXCAVATION EAST OF BUILDING A210.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
4/1/95	108/8183	11
LOCATION:	AREA P	
ACTIVITY:		
EXCAVATION OF DRAIN ADJACENT TO BUILDING A214.		



SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
4/1/95	108/8183	12


LOCATION:	AREA S	
ACTIVITY:		
SSSI - SOUTH WEST OF BUILDING S31 - TEMPORARY ACCESS BRIDGE FOR MATERIAL TO STEAM MAIN ROUTES.		
SPECIAL FEATURES:		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
4/1/95	108/8183	13
LOCATION:	AREA S	
ACTIVITY:		
SSSI - COVERING STEAM MAIN ROUTES.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
4/1/95	108/8183	14
LOCATION:	AREA S	
ACTIVITY:		
SCRUTINY EXERCISE IN HERONRY AREA.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/1/95	108/8183	15
LOCATION:	AREA S	
ACTIVITY:		
BUILDING E14 MOUND AFTER CLEARANCE.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/1/95	108/8183	16
LOCATION:	AREA S	
ACTIVITY:		
BUILDING 88A MOUND AFTER CLEARANCE.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/1/95	108/8183	17
LOCATION:	AREA S	
ACTIVITY:		
BUILDING 88A MOUND AFTER CLEARANCE.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/1/95	108/8183	18



LOCATION:	AREAS	
ACTIVITY:		
MOUND WEST OF BUILDING S30 AFTER CLEARANCE.		
SPECIAL FEATURES:		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/1/95	108/8183	19
LOCATION:	AREA S	
ACTIVITY:		
ACCESS TO SSSI FOR SCRUTINY WORKS.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/1/95	108/8183	20
LOCATION:	AREA S	
ACTIVITY:		
MOUND WEST OF BUILDING S30 AFTER CLEARANCE.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/1/95	108/8183	21
LOCATION:	AREA S	
ACTIVITY:		
BUILDING S31 - MOUND CLEARANCE IN PROGRESS.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/1/95	108/8183	22
LOCATION:	AREA S	
ACTIVITY:		
GENERAL VIEW SOUTHWARDS FROM BUILDING 88A.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/1/95	108/8183	23
LOCATION:	AREA S	
ACTIVITY:		
HERONRY SCRUTINY IN PROGRESS.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/1/95	108/8183	24

LOCATION:	AREAS	
ACTIVITY:		
BUILDING S30 MOUND AFTER CLEARANCE.		
SPECIAL FEATURES:		




**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/1/95	108/8183	25
LOCATION:	AREA S	
ACTIVITY:		
BUILDING S90 MOUND AFTER CLEARANCE.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/1/95	108/8183	26
LOCATION:	AREA S	
ACTIVITY:		
CLEARED CANAL FROM BUILDING S90 NORTHWARDS.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
20/1/95	108/8183	27
LOCATION:	AREA P	
ACTIVITY:		
BUILDING A210 EAST (BETWEEN BUILDING A210 AND BUILDING A214).		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
20/1/95	108/8183	28
LOCATION:	AREA P	
ACTIVITY:		
BUILDING A210 EAST (BETWEEN BUILDING A210 AND BUILDING A214).		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
20/1/95	108/8183	29
LOCATION:	AREA P	
ACTIVITY:		
BUILDING A210 EAST (BETWEEN BUILDING A210 AND BUILDING A214).		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
20/1/95	108/8183	30

LOCATION:	AREA P	
ACTIVITY:		
BUILDING A210 EAST (BETWEEN BUILDING A210 AND BUILDING A214).		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
30/1/95	108/8183	33
LOCATION:	AREA H	
ACTIVITY:		
VIEW LOOKING NORTH SHOWING FLOODING DUE TO HEAVY RAIN.		
SPECIAL FEATURES:		



--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
30/1/95	108/8183	34
LOCATION:	AREA P	
ACTIVITY:		
REMEDIATION NORTH EAST OF BUILDING A214.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
30/1/95	108/8183	35
LOCATION:	AREA P	
ACTIVITY:		
REMEDIATION NORTH EAST OF BUILDING A214.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
30/1/95	108/8183	36
LOCATION:	AREAS	
ACTIVITY:		
REMEDIATION AROUND PRESS HOUSE.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
30/1/95	108/8183	37
LOCATION:	AREA S	
ACTIVITY:		
COVERING STEAM MAIN ROUTE EAST OF BUILDING 88A.		


SPECIAL FEATURES:

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
18/5/94	87/1042	1
LOCATION:	AREA	
ACTIVITY:		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
18/5/94	87/1042	2
LOCATION:	AREA H	
ACTIVITY:		
H16 AREA - GENERAL ACTIVITIES: - STOCKPILING WASTE (IN BACKGROUND) - INFILLING H31 PIT (CENTRE / LEFT).		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
18/5/94	87/1042	3
LOCATION:	AREA H	
ACTIVITY:		
H16 AREA - SURFACE SCRAPING TO REMOVE CONTAMINATED GROUND.		
SPECIAL FEATURES:		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
18/5/94	87/1042	4
LOCATION:	AREA H	
ACTIVITY:		
H16 AREA - SURFACE SCRAPING TO REMOVE CONTAMINATED GROUND.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
18/5/94	87/1042	5
LOCATION:	AREA M	
ACTIVITY:		
SOUTH OF BUILDING L157 - FWD PRESSURE GROUTING.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
18/5/94	87/1042	6


LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - PAINT SPRAYING OF GRIT BLASTED STRUCTURAL STEELWORK.		
SPECIAL FEATURES:		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
18/5/94	87/1042	7
LOCATION:	AREA M	
ACTIVITY:		
SOUTH OF BUILDING L157 - FWD - PRESSURE GROUTING.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
18/5/94	87/1042	8
LOCATION:	AREA M	
ACTIVITY:		
SOUTH OF BUILDING L157 - FWD - PRESSURE GROUTING.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
25/5/94	87/1042	11
LOCATION:	AREA H	
ACTIVITY:		
SOIL STRIPPING AREA H.		
SPECIAL FEATURES:		
DIFFICULT GROUND CONDITIONS.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
25/5/94	87/1042	12
LOCATION:	AREA H	
ACTIVITY:		
H31 EXCAVATION BACKFILLED.		
SPECIAL FEATURES:		




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
25/5/94	87/1042	13
LOCATION:	AREA H	
ACTIVITY:		
WATER PIPE REPAIR - SOUTH OF H31.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
25/5/94	87/1042	14

LOCATION:	AREA H	
ACTIVITY:		
BACKFILLING OF REMEDIATED HYDROCARBON CONTAMINATED AREA NORTH OF BUILDING H25.		
SPECIAL FEATURES:		
CLAY PUDDING TO SEAL IN GRAVELS AND SMALL AMOUNT OF RESIDUAL CONTAMINATION.		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
25/5/94	87/1042	15
LOCATION:	AREA H	
ACTIVITY:		
BACKFILLING OF REMEDIATED HYDROCARBON CONTAMINATED AREA NORTH OF BUILDING H25.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
25/5/94	87/1042	16
LOCATION:	AREA H	
ACTIVITY:		
BACKFILLING OF REMEDIATED HYDROCARBON CONTAMINATED AREA NORTH OF BUILDING H25.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
25/5/94	87/1042	17
LOCATION:	AREA H	
ACTIVITY:		
BACKFILLING OF REMEDIATED HYDROCARBON CONTAMINATED AREA NORTH OF BUILDING H25.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
25/5/94	87/1042	18
LOCATION:	AREA P	
ACTIVITY:		
SOIL STRIPPING AREA P NORTH - LOOKING EAST.		
SPECIAL FEATURES:		



<b>FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD</b>		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
25/5/94	87/1042	19
LOCATION:	AREA P	
ACTIVITY:		
SOIL STRIPPING AREA P NORTH - LOOKING WEST.		



SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
25/5/94	87/1042	20


LOCATION:	AREA P	
ACTIVITY:		
AREA P NORTH - EXCAVATION OF FILLED CANAL LOOKING TOWARDS POWDERMILL LANE SITE ENTRANCE.		
SPECIAL FEATURES:		
BRICK CULVERT.		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
25/5/94	87/1042	22
LOCATION:	AREA M	
ACTIVITY:		
L169 - LOADING AWAY STOCKPILED WASTE.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
25/5/94	87/1042	23
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - GRIT BLASTING OF STRUCTURAL STEELWORK.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
25/5/94	87/1042	24
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - BAY PREPARED FOR GRIT BLASTING OF STRUCTURAL STEELWORK.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
25/5/94	87/1042	25
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - REMEDIATION INTERNALLY ALMOST COMPLETE.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
25/5/94	87/1042	26
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - INTERNAL REMEDIATION IN PROGRESS.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/5/94	87/1042	27



LOCATION:	AREA N	
ACTIVITY:		
CLAY WINNING IN PROGRESS FOR INFILL OF EXCAVATIONS IN AREA H.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/5/94	87/1042	28
LOCATION:	AREA N	
ACTIVITY:		
CLAY WINNING IN PROGRESS FOR INFILL OF EXCAVATIONS IN AREA H.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
1/6/94	87/1042	29
LOCATION:	AREA P	
ACTIVITY:		
AREA P NORTH - FOUNDATIONS TO FORMER BUILDING, SOUTH OF BUILDING A219, DISCOVERED.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
1/6/94	87/1042	30
LOCATION:	AREA P	
ACTIVITY:		
AREA P NORTH - FOUNDATIONS TO FORMER BUILDING, SOUTH OF BUILDING A219, DISCOVERED.		
SPECIAL FEATURES:		
BUILDING A221 IN BACKGROUND.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
1/6/94	87/1042	31
LOCATION:	AREA P	
ACTIVITY:		
AREA P NORTH - FOUNDATIONS TO FORMER BUILDING, SOUTH OF BUILDING A219, DISCOVERED.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
2/6/94	87/1042	32
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - FWD - 'REMOTE' CUTTING OF POTENTIALLY		

CONTAMINATED PIPEWORK.
SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
2/6/94	87/1042	33


LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - FWD - 'REMOTE' CUTTING OF POTENTIALLY CONTAMINATED PIPEWORK.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
2/6/94	87/1042	34
LOCATION:	AREA P	
ACTIVITY:		
BREAKING UP FOUNDATIONS TO FORMER BUILDING SOUTH OF BUILDING A219.		
SPECIAL FEATURES:		

--


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
2/6/94	87/1042	35
LOCATION:	AREA H	
ACTIVITY:		
INFILL TO FORMER HYDROCARBON CONTAMINATED AREA NORTH OF BUILDING H25.		
SPECIAL FEATURES:		
BASE PUDDLE CLAY IN PLACEMENT IN PROGRESS.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
2/6/94	87/1042	36
LOCATION:	AREA H	
ACTIVITY:		
INFILL TO FORMER HYDROCARBON CONTAMINATED AREA NORTH OF BUILDING H25.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
2/6/94	87/1042	R
LOCATION:	AREA H	
ACTIVITY:		
INFILL TO FORMER HYDROCARBON CONTAMINATED AREA NORTH OF BUILDING H25.		
SPECIAL FEATURES:		



**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
3/6/94	88/1040	1
LOCATION:	AREA H	
ACTIVITY:		
HYDROCARBON CONTAMINATED AREA REMEDIATED - CLAY FILLING IN PROGRESS.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
3/6/94	88/1040	2
LOCATION:	AREA H	
ACTIVITY:		
HYDROCARBON CONTAMINATED AREA REMEDIATED - CLAY FILLING IN PROGRESS.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
3/6/94	88/1040	3
LOCATION:	AREA H	
ACTIVITY:		
HYDROCARBON CONTAMINATED AREA REMEDIATED - CLAY FILLING IN PROGRESS.		
SPECIAL FEATURES:		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
7/6/94	88/1040	4
LOCATION:	AREA H	
ACTIVITY:		
HYDROCARBON CONTAMINATED AREA REMEDIATED - CLAY FILLING IN PROGRESS.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
7/6/94	88/1040	5
LOCATION:	AREA H	
ACTIVITY:		
HYDROCARBON CONTAMINATED AREA REMEDIATED - CLAY FILLING IN		

PROGRESS.
SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
7/6/94	88/1040	6


LOCATION:	AREA H	
ACTIVITY:		
HYDROCARBON CONTAMINATED AREA REMEDIATED - CLAY FILLING IN PROGRESS.		
SPECIAL FEATURES:		
GROUND WATER PRESSURE CAUSING LEAKAGE THROUGH CLAY BASE.		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
7/6/94	88/1040	8
LOCATION:	AREA H	
ACTIVITY:		
HYDROCARBON CONTAMINATED AREA REMEDIATED - CLAY FILLING IN PROGRESS.		
SPECIAL FEATURES:		
FORMING BUND WALL SOUTH END OF AREA.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
7/6/94	88/1040	9
LOCATION:	AREA H	
ACTIVITY:		
HYDROCARBON CONTAMINATED AREA REMEDIATED - CLAY FILLING IN PROGRESS.		
SPECIAL FEATURES:		
FORMING BUND WALL SOUTH END OF AREA.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
7/6/94	88/1040	10
LOCATION:	AREA H	
ACTIVITY:		
HYDROCARBON CONTAMINATED AREA REMEDIATED - CLAY FILLING IN PROGRESS.		
SPECIAL FEATURES:		
FORMING BUND WALL SOUTH END OF AREA.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
7/6/94	88/1040	11
LOCATION:	AREA H	
ACTIVITY:		
STOCKPILE OF HYDROCARBON CONTAMINATED WASTE AND BAGGED WASTE BLAST GRIT FROM BUILDING L157 / L153 WORKS.		
SPECIAL FEATURES:		




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
7/6/94	88/1040	12
LOCATION:	AREA H	
ACTIVITY:		
STOCKPILE - 'SPECIAL WASTE'.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
8/6/94	88/1040	13

LOCATION:	AREA H	
ACTIVITY:		
HYDROCARBON CONTAMINATED AREA REMEDIATED - CLAY FILLING IN PROGRESS.		
SPECIAL FEATURES:		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
8/6/94	88/1040	14
LOCATION:	AREA H	
ACTIVITY:		
HYDROCARBON CONTAMINATED AREA REMEDIATED - CLAY FILLING IN PROGRESS.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
8/6/94	88/1040	15
LOCATION:	AREA H	
ACTIVITY:		
HYDROCARBON CONTAMINATED AREA REMEDIATED - CLAY FILLING IN PROGRESS.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
8/6/94	88/1040	16
LOCATION:	AREA S	
ACTIVITY:		
CANAL EXCAVATION ADJACENT TO BUILDING L105 LOOKING NORTH.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
8/6/94	88/1040	17
LOCATION:	AREA S	
ACTIVITY:		
CANAL EXCAVATION ADJACENT TO BUILDING L105 LOOKING SOUTH.		
SPECIAL FEATURES:		

BUILDING L108 IN BACKGROUND.



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
8/6/94	88/1040	18
LOCATION:	AREA S	
ACTIVITY:		
EAST / WEST CANAL NORTH OF BUILDING E2 - CLEARANCE IN PROGRESS		



LOOKING WEST.
SPECIAL FEATURES:

<b>FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD</b>		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
8/6/94	88/1040	19

LOCATION:	AREAS	
ACTIVITY:		
EAST / WEST CANAL NORTH OF BUILDING E2 - CLEARANCE IN PROGRESS LOOKING EAST.		
SPECIAL FEATURES:		
NOTE PUDDLE CLAY OUTLINE AT EDGES OF CANAL BASE.		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
8/6/94	88/1040	20
LOCATION:	AREA S	
ACTIVITY:		
CANAL CLEARANCE WEST OF BUILDING S34.		
SPECIAL FEATURES:		
NEWTONS POOL IN BACKGROUND.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
8/6/94	88/1040	21
LOCATION:	AREA P	
ACTIVITY:		
TEMPORARY CLAY DAM.		
SPECIAL FEATURES:		
TO HOLD BACK CONTAMINATED FILL.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
8/6/94	88/1040	22
LOCATION:	AREA P	
ACTIVITY:		
SURFACE STRIPPING TO REMOVE CONTAMINATED GROUND.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
8/6/94	88/1040	23
LOCATION:	AREA P	
ACTIVITY:		
SURFACE STRIPPING TO REMOVE CONTAMINATED GROUND.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/6/94	88/1040	24
LOCATION:	AREA H	
ACTIVITY:		
TIMBER LINED PIT EAST OF H16.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/6/94	88/1040	25




LOCATION:	AREA H	
ACTIVITY:		
TIMBER LINED PIT EAST OF H16.		
SPECIAL FEATURES:		
BUILDING A203 IN BACKGROUND. BRIDGE No. 17 IN BACKGROUND.		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/6/94	88/1040	27
LOCATION:	AREA H	
ACTIVITY:		
PUDDLE CLAY PLACEMENT WEST OF BUILDING H26.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/6/94	88/1040	28
LOCATION:	AREA H	
ACTIVITY:		
H67 - WASTE FROM CANAL NORTH OF AREA T.		
SPECIAL FEATURES:		
TO BE SPREAD OUT FOR SAMPLING AND INSPECTION.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/6/94	88/1040	29
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L153 - MERCURY AND GREEN DEPOSIT WITHIN EXTERNAL GULLY POT.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/6/94	88/1040	31
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L153 - MERCURY AND GREEN DEPOSIT ADJACENT EXTERNAL GULLY POT.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/6/94	88/1040	32
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L153 - MERCURY AND GREEN DEPOSIT ADJACENT EXTERNAL		

GULLY POT.
SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/6/94	88/1040	33


LOCATION:	AREA M	
ACTIVITY:		
BUILDING L153 - REMOVAL OF POTENTIALLY CONTAMINATED FWD'S.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
10/6/94	88/1040	35
LOCATION:	AREA H	
ACTIVITY:		
HYDROCARBON CONTAMINATED AREA REMEDIATED - CLAY FILLING IN PROGRESS.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
10/6/94	88/1040	36
LOCATION:	AREA H	
ACTIVITY:		
HYDROCARBON CONTAMINATED AREA REMEDIATED - CLAY FILLING IN PROGRESS.		
SPECIAL FEATURES:		



**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
13/6/94	89/2596	1
LOCATION:	AREA P	
ACTIVITY:		
BACKFILLING OF CLEANED EAST / WEST CANAL PARALLEL WITH FLAGSTAFF ROAD.		
SPECIAL FEATURES:		
BRIDGE No. 1 IN BACKGROUND.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
13/6/94	89/2596	2
LOCATION:	AREA P	
ACTIVITY:		
BACKFILLING OF CLEANED EAST / WEST CANAL PARALLEL WITH FLAGSTAFF ROAD.		
SPECIAL FEATURES:		


--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
13/6/94	89/2596	3
LOCATION:	AREA P	
ACTIVITY:		
BACKFILLING OF CLEANED EAST / WEST CANAL PARALLEL WITH FLAGSTAFF ROAD.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
13/6/94	89/2596	4
LOCATION:	AREA H	
ACTIVITY:		
FILLING OF REMEDIATED HYDROCARBON CONTAMINATED AREA WEST OF BUILDING H26.		
SPECIAL FEATURES:		

VEHICLE WASHDOWN PETROL INTERCEPTOR IN FOREGROUND.



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
13/6/94	89/2596	5
LOCATION:	AREA H	
ACTIVITY:		
FILLING OF REMEDIATED HYDROCARBON CONTAMINATED AREA WEST		



OF BUILDING H26.
SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
13/6/94	89/2596	6

LOCATION:	AREA H	
ACTIVITY:		
FILLING OF REMEDIATED HYDROCARBON CONTAMINATED AREA WEST OF BUILDING H26.		
SPECIAL FEATURES:		
GRANULAR FILL USED OVER PUDDLE CLAY MEMBRANE.		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
15/6/94	89/2596	7
LOCATION:	AREA H	
ACTIVITY:		
FILLING OF REMEDIATED HYDROCARBON CONTAMINATED AREA WEST OF BUILDING H26.		
SPECIAL FEATURES:		
GRANULAR FILL USED OVER PUDDLE CLAY MEMBRANE.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
15/6/94	89/2596	8
LOCATION:	AREA S	
ACTIVITY:		
REMOVAL OF 'TIPPED' WASTE FROM AROUND TREES ADJACENT TO EDMONSEY SLUICE.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
15/6/94	89/2596	9
LOCATION:	AREA S	
ACTIVITY:		
REMOVAL OF 'TIPPED' WASTE FROM AROUND TREES ADJACENT TO EDMONSEY SLUICE.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
16/6/94	89/2596	10
LOCATION:	AREA P	
ACTIVITY:		
BRIDGE No. 31 - REMOVAL.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
16/6/94	89/2596	11
LOCATION:	AREA P	
ACTIVITY:		
BRIDGE No. 31 - REMOVAL.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
16/6/94	89/2596	12




LOCATION:	AREA P	
ACTIVITY:		
BRIDGE No. 31 - REMOVAL.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
16/6/94	89/2596	13
LOCATION:	AREA P	
ACTIVITY:		
BRIDGE No. 31 - REMOVAL.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
16/6/94	89/2596	14
LOCATION:	AREA P	
ACTIVITY:		
BRIDGE No. 31 - REMOVAL.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
16/6/94	89/2596	15
LOCATION:	AREA P	
ACTIVITY:		
BRIDGE No. 31 - REMOVAL.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
16/6/94	89/2596	16
LOCATION:	AREA P	
ACTIVITY:		
BRIDGE No. 11 - REMOVAL.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
16/6/94	89/2596	17
LOCATION:	AREA P	
ACTIVITY:		
BRIDGE No. 11 - REMOVAL.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
16/6/94	89/2596	18

LOCATION:	AREA P	
ACTIVITY:		
BRIDGE No. 11 - REMOVAL.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
16/6/94	89/2596	19
LOCATION:	AREA H	
ACTIVITY:		
REMOVAL OF HYDROCARBON CONTAMINATED GROUND WEST OF BUILDING H26.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
16/6/94	89/2596	20
LOCATION:	AREA H	
ACTIVITY:		
REMOVAL OF HYDROCARBON CONTAMINATED GROUND WEST OF BUILDING H26.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
16/6/94	89/2596	21
LOCATION:	AREA H	
ACTIVITY:		
REMOVAL OF HYDROCARBON CONTAMINATED GROUND WEST OF BUILDING H26.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
16/6/94	89/2596	22
LOCATION:	AREA H	
ACTIVITY:		
REMOVAL OF HYDROCARBON CONTAMINATED GROUND WEST OF BUILDING H26.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
21/6/94	89/2596	23
LOCATION:	AREA P	
ACTIVITY:		
SHEET PILING AT BRIDGE No. 1 - CANAL INTERSECTION POINT No. 4.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
21/6/94	89/2596	24


LOCATION:	AREA P	
ACTIVITY:		
SHEET PILING AT BRIDGE No. 1 - CANAL INTERSECTION POINT No. 4.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
21/6/94	89/2596	25
LOCATION:	AREA P	
ACTIVITY:		
SHEET PILING AT BRIDGE No. 1 - CANAL INTERSECTION POINT No. 4.		
SPECIAL FEATURES:		



--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
21/6/94	89/2596	26
LOCATION:	AREA P	
ACTIVITY:		
SHEET PILING AT BRIDGE No. 1 - CANAL INTERSECTION POINT No. 4.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
21/6/94	89/2596	27
LOCATION:	AREA P	
ACTIVITY:		
SHEET PILING AT BRIDGE No. 1 - CANAL INTERSECTION POINT No. 4.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
21/6/94	89/2596	28
LOCATION:	AREA P	
ACTIVITY:		
SHEET PILING AT BRIDGE No. 1 - CANAL INTERSECTION POINT No. 4.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
21/6/94	89/2596	29
LOCATION:	AREA S	
ACTIVITY:		
REMEDICATION OF FILLED BORROW PITS WEST OF BUILDING E2.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
21/6/94	89/2596	30

LOCATION:	AREAS	
ACTIVITY:		
REMEDIATION OF FILLED BORROW PITS WEST OF BUILDING E2.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
21/6/94	89/2596	31
LOCATION:	AREA H	
ACTIVITY:		
CONSTRUCTION COMMENCEMENT FOR BLOCK PAVED ROADWAY OVER REMEDiated AREA - LOOKING SOUTH.		
SPECIAL FEATURES:		
BUILDING H26 TO LEFT OF SHOT.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
21/6/94	89/2596	32
LOCATION:	AREA H	
ACTIVITY:		
CONSTRUCTION COMMENCEMENT FOR BLOCK PAVED ROADWAY OVER REMEDIATED AREA - LOOKING NORTH.		
SPECIAL FEATURES:		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
22/6/94	89/2596	33
LOCATION:	AREA P	
ACTIVITY:		
SHEET PILING AT BRIDGE No. 1 - COMPLETE AND CANAL INTERSECTION No. 4.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
22/6/94	89/2596	34
LOCATION:	AREA P	
ACTIVITY:		
REMOVAL OF CONTAMINATED GROUND LOOKING WEST.		
SPECIAL FEATURES:		

BUILDING A203 IN BACKGROUND.



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
22/6/94	89/2596	35
LOCATION:	AREA S	
ACTIVITY:		
DUMPED WASTE REMOVED FROM AROUND TREES ADJACENT TO		

EDMONSEY SLUICE.

SPECIAL FEATURES:

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
23/6/94	90/2598	1
LOCATION:	AREA	
ACTIVITY:		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
23/6/94	90/2598	2
LOCATION:	AREA H	
ACTIVITY:		
SUB BASE CONSTRUCTION FOR BLOCK PAVED ROADWAY WEST OF BUILDING H26.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
23/6/94	90/2598	3
LOCATION:	AREA S	
ACTIVITY:		
SHEET PILING ADJACENT TO BUILDING S90.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
23/6/94	90/2598	4
LOCATION:	AREA S	
ACTIVITY:		
SHEET PILING BY BUILDING S90.		
SPECIAL FEATURES:		




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
24/6/94	90/2598	9
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L153 - REMOVAL OF FWD'S.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
24/6/94	90/2598	10

LOCATION:	AREA M	
ACTIVITY:		
BUILDING L153 - REMOVAL OF FWD'S.		
SPECIAL FEATURES:		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDICATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
24/6/94	90/2598	11
LOCATION:	AREA S	
ACTIVITY:		
SHEET PILING BY BUILDING S90.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
24/6/94	90/2598	12
LOCATION:	AREA S	
ACTIVITY:		
SHEET PILING BY BUILDING S90.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
24/6/94	90/2598	13
LOCATION:	AREA S	
ACTIVITY:		
SHEET PILING BY BUILDING S90.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
28/6/94	90/2598	15
LOCATION:	AREA P	
ACTIVITY:		
INSPECTION OF NORTH EAST ABUTMENT TO BRIDGE No. 1.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
28/6/94	90/2598	16
LOCATION:	AREA H	
ACTIVITY:		
ROAD CONSTRUCTION WEST OF BUILDING H26.		



SPECIAL FEATURES:


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
28/6/94	90/2598	17

LOCATION:	AREA H	
ACTIVITY:		
ROAD CONSTRUCTION WEST OF BUILDING H26.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
28/6/94	90/2598	18
LOCATION:	AREA S	
ACTIVITY:		
EDMONSEY SLUICE - EXPOSED TREE ROOTS AFTER REMOVAL OF TIPPED WASTE.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
28/6/94	90/2598	19
LOCATION:	AREA T	
ACTIVITY:		
GENERAL VIEW NORTHWARDS ACROSS AREA T.		
SPECIAL FEATURES:		




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
28/6/94	90/2598	20
LOCATION:	AREA T	
ACTIVITY:		
GENERAL VIEW TO THE NORTH EAST ACROSS AREA T.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
28/6/94	90/2598	21
LOCATION:	AREA S	
ACTIVITY:		
CANAL CLEARANCE FROM BUILDING S34 WESTWARDS.		
SPECIAL FEATURES:		

NEWTONS POOL IS TO THE LEFT JUST OUT OF SHOT.



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
28/6/94	90/2598	22
LOCATION:	AREA S	
ACTIVITY:		
SHEET PILING BY BUILDING S90.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
28/6/94	90/2598	24




LOCATION:	AREA P	
ACTIVITY:		
REFILLING OF AREA SOUTH OF BUILDING A221.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
30/6/94	90/2598	25
LOCATION:	AREA H	
ACTIVITY:		
VEHICLE WASHDOWN AREA UNDER CONSTRUCTION.		
SPECIAL FEATURES:		
LAYING OF DRAINAGE CHANNEL.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
30/6/94	90/2598	26
LOCATION:	AREA H	
ACTIVITY:		
CONSTRUCTION OF ROADWAY WEST OF BUILDING H26.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
30/6/94	90/2598	27
LOCATION:	AREA M	
ACTIVITY:		
CANAL CLEARANCE IN PROGRESS VIEWED FROM BUILDING L136 NORTHWARDS (BUILDING L109 TO RIGHT OF SHOT).		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
30/6/94	90/2598	28
LOCATION:	AREA M	
ACTIVITY:		
CANAL CLEARANCE BETWEEN BUILDINGS L109 AND L108 (BUILDING L108 IN SHOT).		
SPECIAL FEATURES:		



<b>FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD</b>		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
30/6/94	90/2598	29
LOCATION:	AREA M	
ACTIVITY:		
CANAL CLEARANCE LOOKING SOUTHWARDS TOWARDS BUILDING L136.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
30/6/94	90/2598	30


LOCATION:	AREA P	
ACTIVITY:		
BUILDING A210 - CHECKING CONTINUITY OF ROOF STRUCTURE.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
30/6/94	90/2598	31
LOCATION:	AREA P	
ACTIVITY:		
CANAL CLEARANCE AT INTERSECTION No. 4.		
SPECIAL FEATURES:		
BRIDGE No. 1 TO RIGHT OF SHOT. NOTE: LIVE GAS MAIN CROSSING CANAL.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
30/6/94	90/2598	32
LOCATION:	AREA P	
ACTIVITY:		
CANAL CLEARANCE AT INTERSECTION No. 4.		
SPECIAL FEATURES:		
BRIDGE No. 1 IN BACKGROUND.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
30/6/94	90/2598	33
LOCATION:	AREA P	
ACTIVITY:		
CANAL CLEARANCE AT INTERSECTION No. 4.		
SPECIAL FEATURES:		
BRIDGE No. 1 IN BACKGROUND.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
30/6/94	90/2598	34
LOCATION:	AREA P	
ACTIVITY:		
CONSTRUCTION OF NEW ENTRANCE ROAD (POWDERMILL LANE ENTRANCE).		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
30/6/94	90/2598	35
LOCATION:	AREA P	
ACTIVITY:		
CONSTRUCTION OF NEW ENTRANCE ROAD (POWDERMILL LANE		

ENTRANCE).
SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
30/6/94	90/2598	36

LOCATION:	AREA P	
ACTIVITY:		
CANAL CLEARANCE AT INTERSECTION No. 4.		
SPECIAL FEATURES:		
BRIDGE No. 1 IN BACKGROUND.		





FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
30/6/94	91/3740	1
LOCATION:	AREA S	
ACTIVITY:		
CANAL CLEARANCE SOUTH OF THE GRAND MAGAZINE.		
SPECIAL FEATURES:		
BRIDGE No. 21.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
30/6/94	91/3740	2
LOCATION:	AREA S	
ACTIVITY:		
SHEET PILING BY BUILDING S90 COMPLETE.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
1/7/94	91/3740	4
LOCATION:	AREA P	
ACTIVITY:		
TYPICAL SAMPLING POINT IN CLEARED CANAL.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
1/7/94	91/3740	5
LOCATION:	AREA P	
ACTIVITY:		
CULVERT AT EAST END OF CLEARED CANAL ADJACENT TO POWDERMILL LANE ENTRANCE.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
5/7/94	91/3740	6
LOCATION:	AREA T	
ACTIVITY:		
CONSTRUCTION OF NEW TEMPORARY ROAD ACROSS REMEDIATED		

GROUND.
SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
5/7/94	91/3740	7

LOCATION:	AREA P - NORTH	
ACTIVITY:		
CONSTRUCTION OF NEW CAR PARK AT POWDERMILL LANE ENTRANCE.		
SPECIAL FEATURES:		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
5/7/94	91/3740	8
LOCATION:	AREA H	
ACTIVITY:		
CONSTRUCTION OF NEW ACCESS ROAD WEST OF BUILDING H26.		
SPECIAL FEATURES:		



--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
5/7/94	91/3740	9
LOCATION:	AREA H	
ACTIVITY:		
VEHICLE WASHDOWN AREA CONSTRUCTION OF DRAINAGE CHANNEL.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
6/7/94	91/3740	10
LOCATION:	AREA P	
ACTIVITY:		
CONSTRUCTION OF NEW CAR PARK AT POWDERMILL LANE ENTRANCE.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
6/7/94	91/3740	11
LOCATION:	AREA H - ISLAND SITE	
ACTIVITY:		
BUILDING A203 - TABLE LAID FOR SPECIAL VISITORS ON 7/7/94.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
11/7/94	91/3740	12
LOCATION:	AREA P	
ACTIVITY:		
ARTIST AT WORK.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
11/7/94	91/3740	13

LOCATION:	AREA P	
ACTIVITY:		
BUILDING A210 - INSPECTION OF GUTTERING (VALLEY).		
SPECIAL FEATURES:		


**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
11/7/94	91/3740	14
LOCATION:	AREA H	
ACTIVITY:		
CONSTRUCTION OF VEHICLE WASHDOWN AREA.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
11/7/94	91/3740	15
LOCATION:	AREA H	
ACTIVITY:		
ROAD CONSTRUCTION WEST OF BUILDING H26.		
SPECIAL FEATURES:		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/7/94	91/3740	22
LOCATION:	AREA P	
ACTIVITY:		
ARTIST AT WORK.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
13/7/94	91/3740	23
LOCATION:	AREA P	
ACTIVITY:		
BRICK CULVERT AT POWDERMILL LANE ENTRANCE - PLUGGED WITH CONCRETE.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
13/7/94	91/3740	24
LOCATION:	AREA H	
ACTIVITY:		
CONCRETE MANHOLE BETWEEN H10 AND H17.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
13/7/94	91/3740	25

LOCATION:	AREA H	
ACTIVITY:		
H16 SLAB - BREAKING FOR REMOVAL.		
SPECIAL FEATURES:		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
13/7/94	91/3740	26
LOCATION:	AREA H	
ACTIVITY:		
H16 SLAB - BREAKING FOR REMOVAL.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
13/7/94	91/3740	27
LOCATION:	AREA H	
ACTIVITY:		
BLOCK PAVING TO ROAD WEST OF BUILDING H26.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
13/7/94	91/3740	28
LOCATION:	AREA H	
ACTIVITY:		
BUILDING H10 - ASBESTOS REMOVAL IN PROGRESS.		
SPECIAL FEATURES:		
AIR LOCK UNIT.		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
13/7/94	91/3740	29
LOCATION:	AREA S	
ACTIVITY:		
BRIDGE No. 10 - EXCAVATED ROAD LEADING TO BRIDGE (SOUTH SIDE).		
SPECIAL FEATURES:		




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
13/7/94	91/3740	30
LOCATION:	AREA S	
ACTIVITY:		
VIEW OF EXCAVATED ROAD FROM BRIDGE No. 10 LOOKING SOUTH.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
15/7/94	91/3740	31

LOCATION:	AREA H	
ACTIVITY:		
BUILDING H16 - SLAB REMOVAL.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
15/7/94	91/3740	32
LOCATION:	AREA H	
ACTIVITY:		
BUILDING H16 - SLAB REMOVAL.		
SPECIAL FEATURES:		




FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
19/7/94	92/0308	1
LOCATION:	AREA H	
ACTIVITY:		
NEW BLOCK PAVED ROAD WEST OF BUILDING H26.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
19/7/94	92/0308	2
LOCATION:	AREA H	
ACTIVITY:		
VEHICLE WASH DOWN AREA UNDER CONSTRUCTION.		
SPECIAL FEATURES:		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
19/7/94	92/0308	3
LOCATION:	AREA H	
ACTIVITY:		
WASTE STOCKPILE - NORTH OF BUILDING H26.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
19/7/94	92/0308	4
LOCATION:	AREA S	
ACTIVITY:		
REMOVAL OF ROAD WEST OF PRESS HOUSE.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
19/7/94	92/0308	5
LOCATION:	AREA T	
ACTIVITY:		
NEW ACCESS ROAD FINISHED - LOOKING NORTH.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
19/7/94	92/0308	6

LOCATION:	AREAS	
ACTIVITY:		
EXCAVATED CANAL WEST OF BUILDING S34.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
19/7/94	92/0308	7
LOCATION:	AREA P	
ACTIVITY:		
RECONSTRUCTED ENTRANCE AND CAR PARK AT POWDERMILL LANE ENTRANCE.		
SPECIAL FEATURES:		
BUILDING A238 IN BACKGROUND.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
19/7/94	92/0308	8
LOCATION:	AREA P	
ACTIVITY:		
BUILDING A210 - WINDOW MESH (PREVENTION OF PIGEON INGRESS) SOUTH EAST ELEVATION.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
19/7/94	92/0308	9
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - WOOD SAMPLES FROM FLOORING AND ROOF BOARDING.		
SPECIAL FEATURES:		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
19/7/94	92/0308	10
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - WOOD CORE SAMPLES (EXAMPLE OF SPLIT CORE).		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
19/7/94	92/0308	11
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - WOOD CORE SAMPLES (EXAMPLE OF SPLIT CORE).		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
19/7/94	92/0308	12

LOCATION:	AREA M	
ACTIVITY:		
'LEAD IN AIR' MONITORING SAMPLES (FILTERS FROM AIR PUMPS).		
SPECIAL FEATURES:		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
21/7/94	92/0308	13
LOCATION:	AREA H	
ACTIVITY:		
REMOVAL OF FLOOR SLAB TO BUILDING H16.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
21/7/94	92/0308	14
LOCATION:	AREA H	
ACTIVITY:		
REMOVAL OF BUILDING H16 FLOOR SLABS.		
SPECIAL FEATURES:		




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
21/7/94	92/0308	15
LOCATION:	AREA H	
ACTIVITY:		
GENERAL SCRAPE - NORTH AREA H.		
SPECIAL FEATURES:		
BUILDING H17 IN BACKGROUND. MOUNDING TO BUILDING H8 TO LEFT OF SHOT.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
21/7/94	92/0308	16
LOCATION:	AREA M	
ACTIVITY:		
EXCAVATED CANAL NORTH OF BUILDING L136.		
SPECIAL FEATURES:		



BUILDING L108 IN BACKGROUND.



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
21/7/94	92/0308	17
LOCATION:	AREA B	
ACTIVITY:		
REMOVAL OF ACCESS ROAD FROM BRIDGE No. 10 TO BRIDGE No. 8.		

SPECIAL FEATURES:
BURNING GROUND EAST ENTRANCE TO LEFT OF SHOT.


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
21/7/94	92/0308	18

LOCATION:	AREA B	
ACTIVITY:		
REMOVAL OF ACCESS ROAD FROM BRIDGE No. 10 TO BRIDGE No. 8.		
SPECIAL FEATURES:		
BURNING GROUND EAST ENTRANCE TO LEFT OF SHOT.		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
21/7/94	92/0308	19
LOCATION:	AREA S	
ACTIVITY:		
REMOVAL OF CONTAMINATED GROUND ADJACENT TO EDMONSEY SLUICE.		
SPECIAL FEATURES:		
EDMONSEY SLUICE TO RIGHT (OUT OF SHOT).		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
21/7/94	92/0308	20
LOCATION:	AREA S	
ACTIVITY:		
EXCAVATED CANAL NORTH WEST OF NEWTONS POOL.		
SPECIAL FEATURES:		
BUILDING A234 IN BACKGROUND.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
21/7/94	92/0308	21
LOCATION:	AREA S	
ACTIVITY:		
EXCAVATED CANAL VIEWED FROM BRIDGE No. 23 NORTHWARDS.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
21/7/94	92/0308	22
LOCATION:	AREA S	
ACTIVITY:		
EXCAVATION OF CONTAMINATED WASTE FROM NITRO GLYCERINE POPPING POND SOUTH OF BUILDING E2.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
21/7/94	92/0308	23
LOCATION:	AREA S	
ACTIVITY:		
EXCAVATION OF CONTAMINATED WASTE FROM NITRO GLYCERINE		



POPPING POND SOUTH OF BUILDING E2.
SPECIAL FEATURES:


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/7/94	92/0308	25

LOCATION:	AREA P	
ACTIVITY:		
AREA P NORTH - GENERAL VIEW AFTER REMOVAL OF FILLED GROUND.		
SPECIAL FEATURES:		
BUILDING A200 CENTRE/LEFT OF SHOT.		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/7/94	92/0308	26
LOCATION:	AREA P	
ACTIVITY:		
AREA P NORTH - GENERAL VIEW AFTER REMOVAL OF FILLED GROUND.		
SPECIAL FEATURES:		
BUILDING A269 IN BACKGROUND / LEFT.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/7/94	92/0308	27
LOCATION:	AREA P	
ACTIVITY:		
OIL / PETROL INTERCEPTOR ADJACENT FORMER BUILDING A220.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/7/94	92/0308	28
LOCATION:	AREA H	
ACTIVITY:		
REMOVAL OF CONTAMINATED GROUND AT SITE OF FORMER BUILDING H16.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/7/94	92/0308	29
LOCATION:	AREA H	
ACTIVITY:		
REMOVAL OF CONTAMINATED GROUND AT SITE OF FORMER BUILDING H16 - LOOKING SOUTH.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/7/94	92/0308	30
LOCATION:	AREA H	
ACTIVITY:		
VEHICLE WASHDOWN CONSTRUCTION (PRIOR TO BLOCK PAVING).		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/7/94	92/0308	31




LOCATION:	AREA H	
ACTIVITY:		
VEHICLE WASHDOWN - PETROL INTERCEPTOR ACCESS COVERS.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/7/94	92/0308	32
LOCATION:	AREA H	
ACTIVITY:		
BLOCK PAVING TO NEW ACCESS ROAD WEST OF BUILDING H26.		
SPECIAL FEATURES:		

--


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/7/94	92/0308	33
LOCATION:	AREA S	
ACTIVITY:		
CLEARED CANAL LOOKING SOUTH TOWARDS BUILDING E14 (IN BACKGROUND).		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/7/94	92/0308	34
LOCATION:	AREA T	
ACTIVITY:		
CLEARED CANAL - LOOKING TOWARDS INTERSECTION No. 26.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/7/94	92/0308	35
LOCATION:	AREA T	
ACTIVITY:		
RECONSTRUCTED ACCESS ROAD THROUGH AREA T - LOOKING SOUTH.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/7/94	93/0753	1
LOCATION:	AREA S	
ACTIVITY:		
CANAL EXCAVATION AT BRIDGE No. 21.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/7/94	93/0753	2
LOCATION:	AREA S	
ACTIVITY:		
CANAL EXCAVATION AT BRIDGE No. 21 LOOKING SOUTH TOWARDS BRIDGE No. 23.		
SPECIAL FEATURES:		



--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/7/94	93/0753	3
LOCATION:	AREAS	
ACTIVITY:		
EXCAVATED CANAL WEST OF BUILDING S34.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
3/8/94	93/0753	6
LOCATION:	AREA P	
ACTIVITY:		
REMOVAL OF FILLED GROUND.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
3/8/94	93/0753	7
LOCATION:	AREA P	
ACTIVITY:		
GENERAL VIEW ACROSS AREA P.		


SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
3/8/94	93/0753	8

LOCATION:	AREA P	
ACTIVITY:		
GENERAL VIEW ACROSS AREA P SHOWING EXCAVATED FILLED CANAL.		
SPECIAL FEATURES:		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
3/8/94	93/0753	9
LOCATION:	AREA H	
ACTIVITY:		
GENERAL VIEW ACROSS AREA H WITH BUILDING H10 IN BACKGROUND.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
3/8/94	93/0753	10
LOCATION:	AREA H	
ACTIVITY:		
GENERAL VIEW ACROSS AREA H LOOKING NORTH.		
SPECIAL FEATURES:		
BUILDING A203 IN BACKGROUND.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
3/8/94	93/0753	11
LOCATION:	AREA H	
ACTIVITY:		
GENERAL VIEW ACROSS AREA H.		
SPECIAL FEATURES:		
ACCUMULATED SPOIL / WASTE.		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
3/8/94	93/0753	12
LOCATION:	AREA H	
ACTIVITY:		
LOADING AWAY ACCUMULATED WASTE.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
3/8/94	93/0753	13
LOCATION:	AREA H	
ACTIVITY:		
BUILDING H10 BEING DISMANTLED PRIOR TO FIRING.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
3/8/94	93/0753	14

LOCATION:	AREA H	
ACTIVITY:		
BUILDING H10 DISMANTLE PRIOR TO FIRING.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
3/8/94	93/0753	15
LOCATION:	AREA H	
ACTIVITY:		
BUILDING H10 DISMANTLE PRIOR TO FIRING.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
3/8/94	93/0753	16
LOCATION:	AREA H	
ACTIVITY:		
BUILDING H10 DISMANTLE PRIOR TO FIRING.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
3/8/94	93/0753	17
LOCATION:	AREA H	
ACTIVITY:		
BUILDING H10 DISMANTLE PRIOR TO FIRING.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
10/8/94	93/0753	19
LOCATION:	AREA H	
ACTIVITY:		
COMMENCEMENT OF EXCAVATION OF CANAL NORTH OF HOPPITS POOL.		
SPECIAL FEATURES:		





<b>FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD</b>		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
10/8/94	93/0753	21
LOCATION:	AREA H	
ACTIVITY:		
GENERAL VIEW LOOKING SOUTH TOWARDS ISLAND SITE -		

COMMENCEMENT OF CANAL RE-OPENING.
SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
10/8/94	93/0753	22


LOCATION:	AREA H	
ACTIVITY:		
EXCAVATION OF FILLED CANAL EAST OF BUILDING H67.		
SPECIAL FEATURES:		
DISUSED LOCK IN BACKGROUND.		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
13/8/94	93/0753	23
LOCATION:	AREA H	
ACTIVITY:		
BUILDING H10 - PREPARATION FOR FIRING.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
13/8/94	93/0753	24
LOCATION:	AREA H	
ACTIVITY:		
BUILDING H10 - PREPARATION FOR FIRING.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
13/8/94	93/0753	25
LOCATION:	AREA H	
ACTIVITY:		
BUILDING H10 - FIRING IN PROGRESS.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
13/8/94	93/0753	26
LOCATION:	AREA H	
ACTIVITY:		
BUILDING H10 - FIRING IN PROGRESS.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
13/8/94	93/0753	27
LOCATION:	AREA H	
ACTIVITY:		
BUILDING H10 - FIRING IN PROGRESS.		



SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
16/8/94	93/0753	31

LOCATION:	AREA H	
ACTIVITY:		
EXCAVATION OF FILLED CANAL NORTH OF HOPPITS POOL (LOOKING NORTH).		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
16/8/94	93/0753	32
LOCATION:	AREA H	
ACTIVITY:		
EXCAVATION OF FILLED CANAL NORTH OF HOPPITS POOL (LOOKING NORTH).		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
16/8/94	93/0753	33
LOCATION:	AREA H	
ACTIVITY:		
CANAL CLEARANCE NORTH OF HOPPITS POOL.		
SPECIAL FEATURES:		
HOPPITS POOL IN BACKGROUND.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
16/8/94	93/0753	34
LOCATION:	AREA H	
ACTIVITY:		
CANAL CLEARANCE NORTH OF HOPPITS POOL.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
16/8/94	93/0753	35
LOCATION:	AREA H	
ACTIVITY:		
CANAL CLEARANCE NORTH OF HOPPITS POOL.		
SPECIAL FEATURES:		

CLAY DAM INSTALLED TO 'HOLD BACK' HOPPITS POOL.



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
16/8/94	93/0753	36
LOCATION:	AREA H	
ACTIVITY:		
BUILDING H10 READY FOR DEMOLITION AFTER FIRING.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
16/8/94	93/0753	37



LOCATION:	AREA H	
ACTIVITY:		
BUILDING H71 / H10 PARTLY DEMOLISHED.		
SPECIAL FEATURES:		




**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
16/8/94	94/1031	1
LOCATION:	AREA H	
ACTIVITY:		
NEW ACCESS ROAD AND VEHICLE WASHDOWN AREAS COMPLETE.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
16/8/94	94/1031	2
LOCATION:	AREA H	
ACTIVITY:		
NEW ACCESS ROAD COMPETE.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
16/8/94	94/1031	3
LOCATION:	AREA H	
ACTIVITY:		
VIEW SOUTH - EAST OF BUILDING H26 VEGETATION CLEARED.		
SPECIAL FEATURES:		
MILLHEAD STREAM TO LEFT OF SHOT.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
16/8/94	94/1031	4
LOCATION:	AREA H	
ACTIVITY:		
EAST OF BUILDING H26 - VEGETATION CLEARED VIEW NORTH.		
SPECIAL FEATURES:		

MILLHEAD STREAM TO RIGHT OF SHOT.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
16/8/94	94/1031	5
LOCATION:	AREA H	
ACTIVITY:		
DISMANTLING ROOF OF BUILDING H8 - LOOKING EAST.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
16/8/94	94/1031	6



LOCATION:	AREA H	
ACTIVITY:		
DISMANTLING ROOF OF BUILDING H8 - LOOKING SOUTH.		
SPECIAL FEATURES:		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
16/8/94	94/1031	7
LOCATION:	AREA S	
ACTIVITY:		
<p>TRIAL PIT No. 3 CANAL REF.: Y NORTH OF BUILDING 22A.</p>		
SPECIAL FEATURES:		
<p>CANAL EDGE TIMBERING VISIBLE AT BOTTOM OF PICTURE.</p>		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
16/8/94	94/1031	8
LOCATION:	AREA S	
ACTIVITY:		
TRIAL PIT No. 3 CANAL REF.: Y NORTH OF BUILDING 22A.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
16/8/94	94/1031	9
LOCATION:	AREA S	
ACTIVITY:		
TRIAL PIT No. 3 CANAL REF.: Y NORTH OF BUILDING 22A.		
SPECIAL FEATURES:		
CANAL EDGE TIMBERING VISIBLE.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
16/8/94	94/1031	10
LOCATION:	AREA S	
ACTIVITY:		
TRIAL PIT No. 4 (NORTH FACE) CANAL REF.: Y NORTH OF BUILDING 22A.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
16/8/94	94/1031	11
LOCATION:	AREA S	
ACTIVITY:		
TRIAL PIT No. 4 (SOUTH FACE)		

CANAL REF.: Y NORTH OF BUILDING 22A.
SPECIAL FEATURES:
NOTE - CEMENT BONDED ASBESTOS SHEETING IN EXCAVATION FACE.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
16/8/94	94/1031	12

LOCATION:	AREAS	
ACTIVITY:		
TRIAL PIT No. 5 (NORTH FACE) CANAL REF.: Y NORTH OF BUILDING 22A.		
SPECIAL FEATURES:		





--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
17/8/94	94/1031	14
LOCATION:	AREA S	
ACTIVITY:		
TRIAL PIT No. 2 (NORTH FACE) CANAL REF.: Y NORTH OF BUILDING 22A.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
17/8/94	94/1031	15
LOCATION:	AREA S	
ACTIVITY:		
TRIAL PIT No. 2 (SOUTH FACE) CANAL REF.: Y NORTH OF BUILDING 22A.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
17/8/94	94/1031	16
LOCATION:	AREA S	
ACTIVITY:		
TRIAL PIT No. 1 (NORTH FACE) CANAL REF.: Y NORTH OF BUILDING 22A.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
17/8/94	94/1031	17
LOCATION:	AREA S	
ACTIVITY:		
TRIAL PIT No. 1 (SOUTH FACE)		

CANAL REF.: Y NORTH OF BUILDING 22A.
SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
17/8/94	94/1031	18



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
17/8/94	94/1031	19
LOCATION:	AREA H	
ACTIVITY:		
DEMOLITION OF BUILDING H10 - NORTH EAST VIEW.		
SPECIAL FEATURES:		



--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
17/8/94	94/1031	20
LOCATION:	AREA H	
ACTIVITY:		
DEMOLITION OF BUILDING H10 - EAST VIEW.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
17/8/94	94/1031	21
LOCATION:	AREA H	
ACTIVITY:		
DEMOLITION OF BUILDING H10 - EAST VIEW.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
17/8/94	94/1031	22
LOCATION:	AREA H	
ACTIVITY:		
DEMOLITION OF BUILDING H10 - SOUTH EAST VIEW.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
17/8/94	94/1031	23
LOCATION:	AREA H	
ACTIVITY:		
DEMOLITION OF BUILDING H10 - SOUTH VIEW.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
18/8/94	94/1031	24

LOCATION:	AREA H	
ACTIVITY:		
NEARING COMPLETION OF DEMOLITION OF BUILDING H10 - NORTH WEST VIEW.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
18/8/94	94/1031	25
LOCATION:	AREA H	
ACTIVITY:		
DEMOLITION OF BUILDING H10 - WEST VIEW.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
18/8/94	94/1031	26
LOCATION:	AREA H	
ACTIVITY:		
BUILDING H10 - DEMOLITION IN PROGRESS.		
SPECIAL FEATURES:		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
18/8/94	94/1031	27
LOCATION:	AREA H	
ACTIVITY:		
BUILDING H10 - DEMOLITION IN PROGRESS.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
18/8/94	94/1031	31
LOCATION:	AREA H	
ACTIVITY:		
MILLHEAD STREAM SECURITY FENCE.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
18/8/94	94/1031	32
LOCATION:	AREA H	
ACTIVITY:		
MILLHEAD STREAM SECURITY FENCE.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
19/8/94	94/1031	33


LOCATION:	AREA H	
ACTIVITY:		
BREAKING UP FLOOR SLAB OF BUILDING H10.		
SPECIAL FEATURES:		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
19/8/94	94/1031	34
LOCATION:	AREA H	
ACTIVITY:		
BREAKING UP FLOOR SLAB OF BUILDING H10.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
19/8/94	94/1031	35
LOCATION:	AREA H	
ACTIVITY:		
CANAL SOUTH OF H67 - REMEDIAL WORKS.		
SPECIAL FEATURES:		
EXPOSED WATER AND GAS MAINS. SEGMENTS OF MILLSTONE RECOVERED FROM CANAL EXCAVATIONS.		




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
19/8/94	94/1031	36
LOCATION:	AREA H	
ACTIVITY:		
CANAL SOUTH OF H67 - REMEDIAL WORKS.		
SPECIAL FEATURES:		
EXPOSED WATER AND GAS MAINS. SEGMENTS OF MILLSTONE RECOVERED FROM CANAL EXCAVATIONS.		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
19/8/94	94/1031	R
LOCATION:	AREA P	
ACTIVITY:		
TEMPORARY SAFETY FENCING AT POWDERMILL ENTRANCE - LOOKING SOUTH WEST.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
20/8/94	95/1262	1
LOCATION:	AREA H	
ACTIVITY:		
BUILDING H8 PREPARED FOR FIRING.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
20/8/94	95/1262	2
LOCATION:	AREA H	
ACTIVITY:		
BUILDING H8 PREPARED FOR FIRING.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
20/8/94	95/1262	3
LOCATION:	AREA H	
ACTIVITY:		
BUILDING H8 PREPARED FOR FIRING.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
20/8/94	95/1262	4
LOCATION:	AREA H	
ACTIVITY:		
BUILDING H8 - FIRING IN PROGRESS.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
22/8/94	95/1262	5
LOCATION:	AREA P	
ACTIVITY:		
BRIDGE No. 2.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
22/8/94	95/1262	7



LOCATION:	AREA P	
ACTIVITY:		
SURFACE STRIPPING AREA P NORTH.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
22/8/94	95/1262	8
LOCATION:	AREA S	
ACTIVITY:		
SECTION OF EXCAVATED CANAL AT BUILDING 16A ENTRANCE (TO REMOVE BURIED ASBESTOS BOARDING).		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
22/8/94	95/1262	9
LOCATION:	AREA S	
ACTIVITY:		
SECTION OF EXCAVATED CANAL AT BUILDING 16A ENTRANCE (TO REMOVE BURIED ASBESTOS BOARDING).		
SPECIAL FEATURES:		
SEAM OF ASBESTOS SHEETING IN FACE OF EXCAVATION.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
23/8/94	95/1262	10
LOCATION:	AREA P	
ACTIVITY:		
AERIAL VIEW OF AREA P LOOKING SOUTH - BUILDING A210 IN FOREGROUND.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
23/8/94	95/1262	11
LOCATION:	AREA H	
ACTIVITY:		
AERIAL VIEW OF AREA H LOOKING SOUTH.		
SPECIAL FEATURES:		

BUILDINGS A203 AND A200 IN FOREGROUND.



**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
23/8/94	95/1262	12
LOCATION:	AREA H	
ACTIVITY:		
AERIAL VIEW OF AREA H LOOKING WEST.		

SPECIAL FEATURES:
HOPPITS POOL IN CENTRE OF SHOT.


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
23/8/94	95/1262	13

LOCATION:	AREA H	
ACTIVITY:		
AERIAL VIEW OF BUILDING H67.		
SPECIAL FEATURES:		




**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
23/8/94	95/1262	14
LOCATION:	AREA L / M	
ACTIVITY:		
AERIAL VIEW OF AREA L / M LOOKING NORTH.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
23/8/94	95/1262	15
LOCATION:	AREA P	
ACTIVITY:		
AERIAL VIEW TOWARDS WALTHAM ABBEY.		
SPECIAL FEATURES:		
BUILDING A214 IN FOREGROUND.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
23/8/94	95/1262	16
LOCATION:	AREA M	
ACTIVITY:		
AERIAL VIEW OF WEST ELEVATION OF BUILDINGS L167 / L159 / L160.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
23/8/94	95/1262	17
LOCATION:	AREA M	
ACTIVITY:		
AERIAL VIEW OF THE ROOF OF BUILDING L168.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
23/8/94	95/1262	18
LOCATION:	AREA M	
ACTIVITY:		
AERIAL VIEW OF THE ROOF ON BUILDING L168.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
23/8/94	95/1262	19


LOCATION:	AREA M	
ACTIVITY:		
AERIAL VIEW OF BUILDINGS L176 / L177 / L180 (NORTH ELEVATION).		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
23/8/94	95/1262	20
LOCATION:	AREA M	
ACTIVITY:		
VIEW OF 'BRONTO' ELEVATED PLATFORM AT BUILDING L168.		
SPECIAL FEATURES:		



--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
23/8/94	95/1262	21
LOCATION:	AREA M	
ACTIVITY:		
VIEW OF ELEVATED PLATFORM AT BUILDING L168.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
23/8/94	95/1262	22
LOCATION:	AREA P	
ACTIVITY:		
BREAKING OUT FOUNDATIONS ADJACENT BUILDING A210.		
SPECIAL FEATURES:		
BUILDING A221 IN BACKGROUND / RIGHT.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
23/8/94	95/1262	23
LOCATION:	AREA P	
ACTIVITY:		
LOADING AWAY WASTE FROM AREA P NORTH.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
23/8/94	95/1262	24
LOCATION:	AREA T	
ACTIVITY:		
AERIAL VIEW OF REMAINS OF FORMER GUNPOWDER DRYING STOVE.		


SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
23/8/94	95/1262	25

LOCATION:	AREA T	
ACTIVITY:		
AERIAL VIEW OF AREA T LOOKING SOUTH.		
SPECIAL FEATURES:		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
23/8/94	95/1262	26
LOCATION:	AREA S	
ACTIVITY:		
AERIAL VIEW OF AREA S - LOOKING SOUTH EAST (MOUNDED BUILDING E2 JUST VISIBLE).		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
23/8/94	95/1262	27
LOCATION:	AREA S	
ACTIVITY:		
AERIAL VIEW OF AREA S - LOOKING SOUTH EAST (MOUNDED BUILDING E2 JUST VISIBLE).		
SPECIAL FEATURES:		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
23/8/94	95/1262	28
LOCATION:	AREA S	
ACTIVITY:		
AERIAL VIEW TOWARDS NEWTONS POOL.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
23/8/94	95/1262	29
LOCATION:	AREAS	
ACTIVITY:		
AERIAL VIEW OF BUILDING 22A.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
23/8/94	95/1262	30
LOCATION:	AREA S	
ACTIVITY:		
AERIAL VIEW OF BUILDING 22A.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
23/8/94	95/1262	31


LOCATION:	AREA S	
ACTIVITY:		
AERIAL VIEW NORTHWARDS FROM AREA T TO GRAND MAGAZINE.		
SPECIAL FEATURES:		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
23/8/94	95/1262	33
LOCATION:	AREA T	
ACTIVITY:		
AERIAL VIEW OF SOUTHERN END OF AREA T.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
23/8/94	95/1262	34
LOCATION:	AREA T	
ACTIVITY:		
AERIAL VIEW OF HORSEMILL STREAM AT AREA T.		
SPECIAL FEATURES:		






FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDICATION RECORD

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
23/8/94	96/1261	1
LOCATION:	AREA T	
ACTIVITY:		
AERIAL VIEW - REMAINS OF FORMER GUNPOWDER STOVE.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
23/8/94	96/1261	2
LOCATION:	AREA T	
ACTIVITY:		
AERIAL VIEW - REMAINS OF FORMER GUNPOWDER STOVE.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
23/8/94	96/1261	3
LOCATION:	AREA T	
ACTIVITY:		
AERIAL VIEW SHOWING FILLED CANAL CLEARANCE.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
23/8/94	96/1261	4
LOCATION:	AREA T	
ACTIVITY:		
AERIAL VIEW, SOUTH END OF AREA T.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
23/8/94	96/1261	5
LOCATION:	AREA T	
ACTIVITY:		
AERIAL VIEW TO SOUTH OF BUILDING E2.		

SPECIAL FEATURES:
NITRO GLYCERINE 'POPPING POND'.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
23/8/94	96/1261	8


LOCATION:	AREA T	
ACTIVITY:		
AERIAL VIEW OF BUILDING 22A.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
23/8/94	96/1261	9
LOCATION:	AREA T	
ACTIVITY:		
AERIAL VIEW OF BUILDING 22A.		
SPECIAL FEATURES:		



--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
23/8/94	96/1261	12
LOCATION:	AREA T	
ACTIVITY:		
AERIAL VIEW OF SITE ARCHAEOLOGIST AND SITE LANDROVER.		
SPECIAL FEATURES:		




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
23/8/94	96/1261	R
LOCATION:	AREA T	
ACTIVITY:		
AERIAL VIEW OF NORTHERN END OF AREA T.		
SPECIAL FEATURES:		





--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
24/8/94	97/1869	2
LOCATION:	AREA H	
ACTIVITY:		
DEMOLITION OF BUILDING H8.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
24/8/94	97/1869	3
LOCATION:	AREA H	
ACTIVITY:		
DEMOLITION OF BUILDING H8.		
SPECIAL FEATURES:		
STOCKPILE FROM BUILDING H10 IN BACKGROUND.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
24/8/94	97/1869	4
LOCATION:	AREA P	
ACTIVITY:		
SOUTH EAST VIEW OF MILLSTONE UNCOVERED EAST OF BUILDING A203.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
24/8/94	97/1869	5
LOCATION:	AREA P	
ACTIVITY:		
NORTH WEST VIEW OF MILLSTONE UNCOVERED EAST OF BUILDING A203.		



SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
24/8/94	97/1869	6

LOCATION:	AREA M	
ACTIVITY:		
BUILDING L168 (MACHINE SHOP INTERNALS NORTH) - VIEW OF ROOF STRUCTURE.		
SPECIAL FEATURES:		
PIGEON DROPPINGS ON LEDGES AND CRANE RAILS.		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
24/8/94	97/1869	7
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L168 (MACHINE SHOP INTERNALS NORTH) - VIEW OF ROOF STRUCTURE.		
SPECIAL FEATURES:		
PIGEON DROPPINGS ON LEDGES AND CRANE RAILS.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
24/8/94	97/1869	8
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L168 (MACHINE SHOP INTERNALS) - FLOOR AREA.		
SPECIAL FEATURES:		
'KNEE DEEP IN PIGEON DROPPINGS'.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
25/8/94	97/1869	9
LOCATION:	AREA P	
ACTIVITY:		
BRIDGE No. 1 - SOUTH EAST ABUTMENT.		
SPECIAL FEATURES:		
WALL TO MILLHEAD STREAM (ON THE RIGHT) IN STATE OF COLLAPSE.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
25/8/94	97/1869	10
LOCATION:	AREA P	
ACTIVITY:		
BRIDGE No. 1 - NORTH WEST ABUTMENT.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
25/8/94	97/1869	11
LOCATION:	AREA P	
ACTIVITY:		
BRIDGE No. 1 - SOUTH EAST ABUTMENT.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
25/8/94	97/1869	12




LOCATION:	AREAS	
ACTIVITY:		
BUILDING L108 - CANAL EXCAVATION.		
SPECIAL FEATURES:		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
25/8/94	97/1869	13
LOCATION:	AREA S	
ACTIVITY:		
BUILDING L108 - CANAL CLEARANCE.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
25/8/94	97/1869	14
LOCATION:	AREA S	
ACTIVITY:		
BRIDGE No. 27 - CANAL CLEARANCE.		
SPECIAL FEATURES:		
SWIVEL BUCKET FITTED TO SHAPE REVETMENTS.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
25/8/94	97/1869	15
LOCATION:	AREA S	
ACTIVITY:		
BRIDGE No. 27 - CANAL CLEARANCE.		
SPECIAL FEATURES:		
SWIVEL BUCKET FITTED TO SHAPE REVETMENTS.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
25/8/94	97/1869	16
LOCATION:	AREA H - ISLAND SITE	
ACTIVITY:		
MICRON SITE LABORATORY - VAPORISING ACETONE ON ASBESTOS FIBRE AIR MONITORING FILTER.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
25/8/94	97/1869	17
LOCATION:	AREA H - ISLAND SITE	
ACTIVITY:		
MICRON SITE LABORATORY - VAPORISING ACETONE ON ASBESTOS		

FIBRE AIR MONITORING FILTER.
SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
25/8/94	97/1869	18


LOCATION:	AREA H - ISLAND SITE	
ACTIVITY:		
MICRON SITE LABORATORY - VAPORISING ACETONE ON ASBESTOS FIBRE AIR MONITORING FILTER.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/8/94	97/1869	19
LOCATION:	AREA P	
ACTIVITY:		
FELLING LARGE ASH TREE AT BRIDGE No. 1.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/8/94	97/1869	20
LOCATION:	AREA M	
ACTIVITY:		
IMPORTED PIPES FOR CANAL ROAD CROSSINGS.		
SPECIAL FEATURES:		
BUILDING L165 IN SHOT.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/8/94	97/1869	21
LOCATION:	AREA H	
ACTIVITY:		
PLACING PIPES AT CANAL ROAD CROSSINGS ADJACENT BUILDING H67.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/8/94	97/1869	22
LOCATION:	AREA H	
ACTIVITY:		
PLACING PIPES AT CANAL ROAD CROSSINGS ADJACENT BUILDING H67.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/8/94	97/1869	25
LOCATION:	AREA S	
ACTIVITY:		
VIEW TOWARDS BURNING GROUND - LOOKING NORTH WEST ACROSS		

REMEDIATED GROUND.
SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/8/94	97/1869	26


LOCATION:	AREA M	
ACTIVITY:		
BUILDING L155 - STRIP OUT IN PROGRESS.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
28/8/94	97/1869	27
LOCATION:	AREA P	
ACTIVITY:		
BRIDGE No. 1 - ASH TREE FELLED.		
SPECIAL FEATURES:		



--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
28/8/94	97/1869	29
LOCATION:	AREA M	
ACTIVITY:		
SITE DUMP TRUCK ADAPTION (TAIL GATE FITTING).		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
30/8/94	97/1869	30
LOCATION:	AREA S	
ACTIVITY:		
BUILDING 18A - EXCAVATED PIT IN CANAL ZONE TO REMOVE BURIED ASBESTOS.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
30/8/94	97/1869	31
LOCATION:	AREA S	
ACTIVITY:		
BUILDING 18A - EXCAVATED PIT IN CANAL ZONE TO REMOVE BURIED ASBESTOS.		
SPECIAL FEATURES:		



<b>FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD</b>		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
30/8/94	97/1869	32
LOCATION:	AREA H	
ACTIVITY:		
CANAL ROAD CROSSING CONSTRUCTED ADJACENT BUILDING H67 VIEW		

LOOKING SOUTH TOWARDS HOPPITS POOL.
SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
30/8/94	97/1869	34


LOCATION:	AREA H	
ACTIVITY:		
CANAL ROAD CROSSING EAST OF BUILDING H67.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
30/8/94	97/1869	35
LOCATION:	AREA P	
ACTIVITY:		
BRIDGE No. 1 - TREE REMOVED TO ALLOW ACCESS FOR REMEDIAL WORKS.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
30/8/94	97/1869	37
LOCATION:	AREA P	
ACTIVITY:		
TREE FELLING AREA P NORTH.		
SPECIAL FEATURES:		








--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
31/8/94	98/2529	2
LOCATION:	AREA P	
ACTIVITY:		
AREA P SOUTH - CONSTRUCTION OF ACCESS ROAD FOR RIVER REVTMENT WORKS.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
31/8/94	98/2529	3
LOCATION:	AREA P	
ACTIVITY:		
AREA P SOUTH - CONSTRUCTION OF ACCESS ROAD FOR RIVER REVTMENT WORKS.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
31/8/94	98/2529	4
LOCATION:	AREA P	
ACTIVITY:		
SITE ARCHAEOLOGIST INSPECTING CANALS ADJACENT TO BUILDING A203.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
31/8/94	98/2529	5
LOCATION:	AREA P	
ACTIVITY:		
AREA P NORTH - REMOVAL OF ACCESS ROAD TO BRIDGE No. 2.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
1/9/94	98/2529	10

LOCATION:	AREA H
ACTIVITY:	
TRACING WATER MAIN ACROSS ROAD NORTH OF BUILDING H8.	
SPECIAL FEATURES:	



FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD

DATE:

NEGATIVE REFERENCE:

FRAME REFERENCE:

1/9/94

98/2529

11

LOCATION:

AREA M


ACTIVITY:

'LONG REACH' EXCAVATOR DREDGING 'MIDDLE STREAM' EAST OF  
BUILDING L157.

SPECIAL FEATURES:

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
1/9/94	98/2529	12
LOCATION:	AREA S	
ACTIVITY:		
CANAL CLEARANCE NORTH OF BUILDING L136.		
SPECIAL FEATURES:		
BUILDING L109 VISIBLE.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
2/9/94	98/2529	14
LOCATION:	AREA P	
ACTIVITY:		
BRIDGE No. 2 - LOOKING AT HANDRAIL No. 1.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
2/9/94	98/2529	15
LOCATION:	AREA P	
ACTIVITY:		
BRIDGE No. 2 - LOOKING AT HANDRAIL No. 2.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
2/9/94	98/2529	16
LOCATION:	AREA P	
ACTIVITY:		
BRIDGE No. 2 - FOOTWAY BOARDING CONDITION.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
2/9/94	98/2529	17

LOCATION:	AREA P	
ACTIVITY:		
BRIDGE No. 2 - LOOKING NORTH.		
SPECIAL FEATURES:		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
5/9/94	98/2529	18
LOCATION:	AREA P	
ACTIVITY:		
AREA P SOUTH - CONSTRUCTION OF ACCESS ROAD FOR HORSEMILL STREAM REVETMENT WORKS.		
SPECIAL FEATURES:		



--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
5/9/94	98/2529	19
LOCATION:	AREA S	
ACTIVITY:		
OTTER HOLES THROUGH EAST FENCE AT GRAND MAGAZINE.		
SPECIAL FEATURES:		




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
5/9/94	98/2529	20
LOCATION:	AREA S	
ACTIVITY:		
OTTER HOLES THROUGH EAST FENCE AT GRAND MAGAZINE.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
5/9/94	98/2529	21
LOCATION:	AREA T	
ACTIVITY:		
GUNPOWDER STOVE AFTER FINAL CLEAR.		
SPECIAL FEATURES:		

SAMPLING PEGS PAINTED.



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
5/9/94	98/2529	22
LOCATION:	AREA T	
ACTIVITY:		
GUNPOWDER STOVE AFTER FINAL CLEAR UP.		

SPECIAL FEATURES:
SAMPLING PEGS PAINTED.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
5/9/94	98/2529	23



**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
5/9/94	98/2529	24
LOCATION:	AREA T	
ACTIVITY:		
GUNPOWDER STOVE AFTER FINAL CLEAR UP.		
SPECIAL FEATURES:		
SAMPLING PEGS PAINTED.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
5/9/94	98/2529	25
LOCATION:	AREA T	
ACTIVITY:		
GUNPOWDER STOVE AFTER FINAL CLEAR.		
SPECIAL FEATURES:		
SAMPLE PEGS PAINTED.		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
5/9/94	98/2529	26
LOCATION:	AREA S	
ACTIVITY:		
TRIAL TRENCH No. 7 CANAL REF.: Y NORTH OF BUILDING 22A.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
5/9/94	98/2529	27
LOCATION:	AREA S	
ACTIVITY:		
TRIAL TRENCH No. 6 CANAL REF.: Y NORTH OF BUILDING 22A.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
6/9/94	98/2529	28
LOCATION:	AREA S	
ACTIVITY:		
TRIAL TRENCH No. 9		

CANAL REF.: Y NORTH OF BUILDING 22A.
SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
6/9/94	98/2529	29



**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
6/9/94	98/2529	30
LOCATION:	AREA S	
ACTIVITY:		
DEBRIS FOUND IN TRIAL PIT No. 10.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
6/9/94	98/2529	31
LOCATION:	AREA P	
ACTIVITY:		
STUMP GRINDING PMLH AREA SOUTH OF BRIDGE No. 1 (FORMER ASH TREE).		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
6/9/94	98/2529	32
LOCATION:	AREA S	
ACTIVITY:		
TRIAL TRENCH No. 10 CANAL REF.: Y NORTH OF BUILDING 22A.		
SPECIAL FEATURES:		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
7/9/94	98/2529	35
LOCATION:	AREA T	
ACTIVITY:		
LAYING TERRAM OVER GUNPOWDER STOVES PRIOR TO COVERING.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
7/9/94	98/2529	36
LOCATION:	AREA P	
ACTIVITY:		
WEST VIEW BY BUILDINGS A210 / A214 SHOWING REDUCTION OF		

GROUND LEVEL.
SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
7/9/94	98/2529	R

LOCATION:	AREA P	
ACTIVITY:		
NORTH WEST VIEW BY BUILDINGS A214/A210 - SHOWING BREAKING OUT OF FORMER GROUND FLOOR SLABS.		
SPECIAL FEATURES:		




**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
8/9/94	99/2979	1
LOCATION:	AREA M	
ACTIVITY:		
REMOVED UNDER ROOF INSULATION MATERIAL FROM BUILDING L159 - BEING STORED.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
8/9/94	99/2979	2
LOCATION:	AREA M	
ACTIVITY:		
REMOVED UNDER ROOF INSULATION MATERIAL FROM BUILDING L159 - BEING STORED.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
8/9/94	99/2979	4
LOCATION:	AREA M	
ACTIVITY:		
WATER TANK IN BUILDING L155 TO BE REMOVED.		
SPECIAL FEATURES:		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
8/9/94	99/2979	5
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L151 - BAY READY FOR STRIPPING OUT.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
8/9/94	99/2979	6
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L149 - TYPICAL BAY MID WAY THROUGH STRIPPING OUT.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
8/9/94	99/2979	8


LOCATION:	AREA M	
ACTIVITY:		
BUILDING L149 - INTERNAL WALL DEMOLITION.		
SPECIAL FEATURES:		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
8/9/94	99/2979	9
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L143 - STORAGE OF DOORS AND CARPET.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
8/9/94	99/2979	10
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L137 - INTERNAL WARNING SIGNS RE. PACEMAKERS.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
8/9/94	99/2979	11
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L145 - INTERNAL CORRIDOR WALL DEMOLISHED.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
8/9/94	99/2979	12
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L145 - TEMPORARY ROOF SUPPORT IN PLACE.		
SPECIAL FEATURES:		




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
8/9/94	99/2979	13
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L145 (WEST SIDE) - FWD DRAIN REMOVAL AND WRAPPING.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
8/9/94	99/2979	14

LOCATION:	AREA M	
ACTIVITY:		
BUILDING L153 - GRIT BLASTING TEMPORARY EXTRACT DUCTWORK.		
SPECIAL FEATURES:		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
8/9/94	99/2979	15
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - COMPLETED GRIT BLASTING TO STRUCTURAL STEELWORK.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
8/9/94	99/2979	16
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - TEMPORARY SUPPORT TO ROOF TRUSS BEARING, DURING REMOVAL OF CONNECTING SHOE.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
8/9/94	99/2979	17
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L153 - GRIT BLASTED ROOF TRUSS MEMBERS.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
8/9/94	99/2979	18
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L153 - GRIT BLASTING OPERATION - SCAFFOLD ACCESS.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
8/9/94	99/2979	19
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L153 - GRIT BLASTING OPERATION - TYPICAL ROOF TRUSS		



SUPPORT SHOE ARRANGEMENT.
SPECIAL FEATURES:
TEMPORARY AIR INLET / EXTRACT DUCTWORK.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
8/9/94	99/2979	20

LOCATION:	AREA M	
ACTIVITY:		
BUILDING L153 - GRIT BLASTING OPERATION - TEMPORARY AIR INLET / EXTRACT DUCTWORK.		
SPECIAL FEATURES:		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
8/9/94	99/2979	22
LOCATION:	AREA P	
ACTIVITY:		
INSPECTION OF SUNKEN BARGE - MILLHEAD STREAM SOUTH OF BRIDGE No. 1.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
8/9/94	99/2979	23
LOCATION:	AREA P	
ACTIVITY:		
INSPECTION OF SUNKEN BARGE - MILLHEAD STREAM SOUTH OF BRIDGE No. 1.		
SPECIAL FEATURES:		
SITE ARCHAEOLOGIST - 'HANDS ON' SUPERVISION.		




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/9/94	99/2979	24
LOCATION:	AREA P	
ACTIVITY:		
INSPECTION OF SUNKEN BARGE - MILLHEAD STREAM SOUTH OF BRIDGE No. 1.		
SPECIAL FEATURES:		
CLEANING OUT DEBRIS (INCLUDING CORDITE).		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/9/94	99/2979	25
LOCATION:	AREA P	
ACTIVITY:		
INSPECTION OF SUNKEN BARGE - MILLHEAD STREAM SOUTH OF BRIDGE No. 1.		
SPECIAL FEATURES:		

REMOVAL FROM THE WATER.



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
10/9/94	99/2979	26
LOCATION:	AREA P	
ACTIVITY:		
INSPECTION OF SUNKEN BARGE - MILLHEAD STREAM SOUTH OF BRIDGE		

No. 1.
SPECIAL FEATURES:
REMOVAL FROM THE WATER.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
10/9/94	99/2979	27




LOCATION:	AREA P	
ACTIVITY:		
INSPECTION OF SUNKEN BARGE - MILLHEAD STREAM SOUTH OF BRIDGE No. 1.		
SPECIAL FEATURES:		
REMOVAL FROM THE WATER.		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
10/9/94	99/2979	28
LOCATION:	AREA P	
ACTIVITY:		
INSPECTION OF SUNKEN BARGE - MILLHEAD STREAM SOUTH OF BRIDGE No. 1.		
SPECIAL FEATURES:		
REMOVAL FROM THE WATER.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
10/9/94	99/2979	29
LOCATION:	AREA P	
ACTIVITY:		
INSPECTION OF SUNKEN BARGE - MILLHEAD STREAM SOUTH OF BRIDGE No. 1.		
SPECIAL FEATURES:		
REMOVAL FROM THE WATER.		




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
10/9/94	99/2979	30
LOCATION:	AREA P	
ACTIVITY:		
INSPECTION OF SUNKEN BARGE - MILLHEAD STREAM SOUTH OF BRIDGE No. 1.		
SPECIAL FEATURES:		
REMOVAL FROM THE WATER.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
10/9/94	99/2979	31
LOCATION:	AREA P	
ACTIVITY:		
CLOSER INSPECTION OF BARGE RECOVERED FROM MILLHEAD STREAM.		
SPECIAL FEATURES:		

CORDITE FOUND IN SIGNIFICANT QUANTITIES.



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
10/9/94	99/2979	32
LOCATION:	AREA P	
ACTIVITY:		
SUPPORTING OF RECOVERED BARGE FROM MILLHEAD STREAM ON DRY		

LAND.
SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/9/94	99/2979	33

LOCATION:	AREA P	
ACTIVITY:		
FILL BEHIND SOUTH EAST BRICK ABUTMENT TO BRIDGE No. 1.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/9/94	99/2979	34
LOCATION:	AREA P	
ACTIVITY:		
BRIDGE No. 1 - SOUTH EAST ABUTMENT - SEVERE CRACKING TO BRICKWORK.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/9/94	99/2979	35
LOCATION:	AREA P	
ACTIVITY:		
SHEET PILING TO MILLHEAD STREAM REVETMENT SOUTH OF BRIDGE No. 1.		
SPECIAL FEATURES:		
RECOVERED BARGE SHEETED OVER TO RETAIN MOISTURE WITHIN TIMBER STRUCTURE.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/9/94	99/2979	36
LOCATION:	AREA S	
ACTIVITY:		
SAMPLING PEG POSITIONS IN EXCAVATED ROADWAY ADJACENT TO EDMONSEY SLUICE.		
SPECIAL FEATURES:		




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/9/94	99/2979	37
LOCATION:	AREA P	
ACTIVITY:		
STEEL SHEET PILING WORKS TO MILLHEAD STREAM REVETMENT SOUTH OF BRIDGE No. 1.		
SPECIAL FEATURES:		


**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
30/1/95	109/9392	1
LOCATION:	AREA S	
ACTIVITY:		
EXCAVATION TO REMOVE TNT CONTAMINATION ADJACENT TO NORTH WEST SIDE OF BUILDING E2.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
30/1/95	109/9392	2
LOCATION:	AREA S	
ACTIVITY:		
EXCAVATION TO REMOVE TNT CONTAMINATION ADJACENT TO NORTH WEST SIDE OF BUILDING E2.		
SPECIAL FEATURES:		




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
7/2/95	109/9392	3
LOCATION:	AREA H	
ACTIVITY:		
CLEARANCE OF PIT CONTAINING WASTE - SOUTH WEST OF BUILDING H7 (WEST FENCELINE VISIBLE).		
SPECIAL FEATURES:		
REINSTATED HORSEMILL STREAM BANK WITH NEW CLAY.		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
7/2/95	109/9392	4
LOCATION:	AREA H	
ACTIVITY:		
CLEARANCE OF PIT CONTAINING WASTE - SOUTH WEST OF BUILDING H7 (WEST FENCELINE VISIBLE).		
SPECIAL FEATURES:		

REINSTATED HORSEMILL STREAM BANK WITH NEW CLAY.  
 CLAY 'CUT OFF WALL' SHOWN PRIOR TO REINSTATEMENT OF BANK TO  
 STREAM.



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
7/2/95	109/9392	5
LOCATION:	AREA H	
ACTIVITY:		
CLEARANCE OF PIT CONTAINING WASTE - SOUTH WEST OF BUILDING H7		

(WEST FENCELINE VISIBLE).
SPECIAL FEATURES:
'PEAT' STRATA VISIBLE.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
7/2/95	109/9392	6

LOCATION:	AREA H	
ACTIVITY:		
CLEARANCE OF PIT CONTAINING WASTE - SOUTH WEST OF BUILDING H7 (WEST FENCELINE VISIBLE).		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
7/2/95	109/9392	7
LOCATION:	AREA H	
ACTIVITY:		
CLEARANCE OF PIT CONTAINING WASTE - SOUTH WEST OF BUILDING H7 (WEST FENCELINE VISIBLE).		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
7/2/95	109/9392	8
LOCATION:	AREA H	
ACTIVITY:		
CLEARANCE OF PIT CONTAINING WASTE - SOUTH WEST OF BUILDING H7.		
SPECIAL FEATURES:		
SIMPLE STRAINING DEVICE TO HOLD BACK FLOATING DEBRIS TO MINIMISE PUMP SUCTION HEAD BLOCKAGE.		




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
7/2/95	109/9392	10
LOCATION:	AREA H	
ACTIVITY:		
HORSEMILL STREAM BANK REINSTATEMENT (AT FENCE LINE ONLY) WEST OF FORMER BUILDING H8.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
7/2/95	109/9392	11
LOCATION:	AREA H	
ACTIVITY:		
CLEARANCE OF PIT CONTAINING WASTE - SOUTH WEST OF BUILDING H7 (WEST FENCELINE VISIBLE).		
SPECIAL FEATURES:		



REINSTATED HORSEMILL STREAM BANK WITH NEW CLAY.



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
7/2/95	109/9392	12
LOCATION:	AREA H	
ACTIVITY:		
GENERAL VIEW LOOKING SOUTH ACROSS STRIPPED AREA H.		

SPECIAL FEATURES:
<p>WET AREA INDICATES THE POSITION OF REMOVED FOUNDATIONS TO FORMER BUILDING H8. BUILDING H17 TO LEFT OF SHOT.</p>

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
7/2/95	109/9392	13

LOCATION:	AREA H	
ACTIVITY:		
WASTE STOCKPILE NORTH OF BUILDING H7.		
SPECIAL FEATURES:		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
7/2/95	109/9392	14
LOCATION:	AREA N	
ACTIVITY:		
'CLAY PIT' DURING CLAY WINNING PROCESS.		
SPECIAL FEATURES:		
POOR WEATHER CONDITIONS.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
7/2/95	109/9392	15
LOCATION:	AREA N	
ACTIVITY:		
'CLAY PIT' DURING CLAY WINNING PROCESS.		
SPECIAL FEATURES:		
POOR WEATHER CONDITIONS.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
7/2/95	109/9392	16
LOCATION:	AREA N	
ACTIVITY:		
'CLAY PIT' DURING CLAY WINNING PROCESS.		
SPECIAL FEATURES:		
POOR WEATHER CONDITIONS.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
7/2/95	109/9392	17
LOCATION:	AREA N	
ACTIVITY:		
'CLAY PIT' DURING CLAY WINNING PROCESS.		
SPECIAL FEATURES:		

POOR WEATHER CONDITIONS.  
NOTE : 'SAFETY STEPS'.

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
7/2/95	109/9392	18
LOCATION:	AREA S	
ACTIVITY:		
REMEDATION AROUND WATER POWERED PRESS HOUSE (BUILDING 103).		



SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
10/2/95	109/9392	19

LOCATION:	AREA H	
ACTIVITY:		
CLEARANCE OF PIT CONTAINING WASTE - SOUTH WEST OF BUILDING H7 (WEST FENCELINE VISIBLE).		
SPECIAL FEATURES:		
REINSTATED HORSEMILL STREAM BANK WITH NEW CLAY. PUMPING BELOW WATER TABLE.		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
16/2/95	109/9392	20
LOCATION:	AREA S	
ACTIVITY:		
DISCOVERY OF EXPERIMENTAL HOUSE FOUNDATIONS EAST OF BUILDING L189.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
16/2/95	109/9392	21
LOCATION:	AREA S	
ACTIVITY:		
DISCOVERY OF EXPERIMENTAL HOUSE FOUNDATIONS EAST OF BUILDING L189.		
SPECIAL FEATURES:		




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
16/2/95	109/9392	22
LOCATION:	AREA S	
ACTIVITY:		
'BARREL GRAVEYARD' - STEAM MAIN ROUTE EXCAVATED.		
SPECIAL FEATURES:		
BUILDING U9 IN BACKGROUND.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
16/2/95	109/9392	23
LOCATION:	AREA S	
ACTIVITY:		
CLEARANCE OF FORMER STEAM MAIN ROUTE.		
SPECIAL FEATURES:		

BUILDING S31 IN DISTANCE BEHIND TREES.  
BUILDINGS S39 AND S40 FOUNDATIONS VISIBLE NEAR THE SMALL  
EXCAVATION.



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
21/2/95	109/9392	24
LOCATION:	AREA S	
ACTIVITY:		
'BARREL GRAVEYARD' - CAPPED STEAM MAIN ROUTE.		

SPECIAL FEATURES:
BUILDING U9 IN BACKGROUND.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
21/2/95	109/9392	25



LOCATION:	AREAS	
ACTIVITY:		
BUILDING S31 AND BRIDGE No. 10 - GENERAL VIEW SHOWING REMEDIATION TO ROAD EMBANKMENT AND BUILDING S31 TETRYL CONTAMINATED AREA.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
21/2/95	109/9392	26
LOCATION:	AREA S	
ACTIVITY:		
BRIDGE No. 10 CLEARANCE WORKS LOOKING SOUTH - REMEDIATION TO ROAD EMBANKMENT.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
21/2/95	109/9392	27
LOCATION:	AREA S	
ACTIVITY:		
BUILDING S31 - REMEDIATION OF TETRYL CONTAMINATED AREA LOOKING WEST.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
21/2/95	109/9392	28
LOCATION:	AREA S	
ACTIVITY:		
BRIDGE No. 10 - NORTH EAST ROAD EMBANKMENT REMEDIAL WORK.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
21/2/95	109/9392	29
LOCATION:	AREA S	
ACTIVITY:		
EAST OF BUILDING S31 - LOOKING TOWARDS BUILDING 88A.		
SPECIAL FEATURES:		

REMEDIATED CANAL AREA.



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
21/2/95	109/9392	30
LOCATION:	AREA S	
ACTIVITY:		
BUILDING S31 / 95A - HEXAGONAL STRUCTURE, RODDING OUT		

DRAINAGE.
SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
21/2/95	109/9392	33

LOCATION:	AREA H	
ACTIVITY:		
LOOKING NORTH - GROUND STRIPPING IN PROGRESS.		
SPECIAL FEATURES:		
POOR GROUND CONDITIONS. BUILDING H7 IN BACKGROUND.		




**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDICATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
6/3/95	109/9392	34
LOCATION:	AREA H - ISLAND SITE	
ACTIVITY:		
HOPPITS POOL - PORTADAM LTD SURVEYING DEPTH PRIOR TO INSTALLATION OF TEMPORARY DAM.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
6/3/95	109/9392	35
LOCATION:	AREA H - ISLAND SITE	
ACTIVITY:		
HOPPITS POOL (BRIDGE No. 17) - INSTALLATION OF TEMPORARY DAM.		
SPECIAL FEATURES:		




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
6/3/95	109/9392	36
LOCATION:	AREA H - ISLAND SITE	
ACTIVITY:		
HOPPITS POOL (BRIDGE No. 17) - INSTALLATION OF TEMPORARY DAM.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
7/3/95	110/9709	1
LOCATION:	AREA H - ISLAND SITE	
ACTIVITY:		
TEMPORARY DAM AT HOPPITS POOL.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
7/3/95	110/9709	2
LOCATION:	AREA H - ISLAND SITE	
ACTIVITY:		
TEMPORARY DAM AT HOPPITS POOL.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
7/3/95	110/9709	3
LOCATION:	AREA H - ISLAND SITE	
ACTIVITY:		
EXCAVATION OF CANAL NORTH OF HOPPITS POOL.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
7/3/95	110/9709	4
LOCATION:	AREA H - ISLAND SITE	
ACTIVITY:		
LICENSED ASBESTOS CONTRACTOR CLEANING CANAL NORTH OF HOPPITS POOL.		
SPECIAL FEATURES:		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
7/3/95	110/9709	5
LOCATION:	AREA H	
ACTIVITY:		
VIEW OF DE-WATERING OF HOPPITS POOL - LOOKING SOUTH.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
7/3/95	110/9709	6

LOCATION:	AREA H	
ACTIVITY:		
HOPPITS POOL LOOKING NORTH TO CANAL ENTRANCE.		
SPECIAL FEATURES:		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
8/3/95	110/9709	7
LOCATION:	AREA H	
ACTIVITY:		
NATIONAL RIVERS AUTHORITY CATCHING FISH AT HOPPITS POOL.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
8/3/95	110/9709	8
LOCATION:	AREA H	
ACTIVITY:		
BRIDGE No. 17 FOUNDATIONS ON WEST SIDE.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
8/3/95	110/9709	9
LOCATION:	AREA H	
ACTIVITY:		
BRIDGE No. 17 FOUNDATIONS ON EAST SIDE.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
8/3/95	110/9709	10
LOCATION:	AREA H	
ACTIVITY:		
VIEW LOOKING NORTH TOWARDS BRIDGE No. 17 SHOWING TEMPORARY DAM.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/3/95	110/9709	11
LOCATION:	AREA H	
ACTIVITY:		
EXCAVATION OF HOPPITS POOL IN PROGRESS.		



SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/3/95	110/9709	12

LOCATION:	AREA H	
ACTIVITY:		
HOPPITS POOL - CANAL ENTRANCE LOOKING SOUTH.		
SPECIAL FEATURES:		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/3/95	110/9709	13
LOCATION:	AREA P	
ACTIVITY:		
COMPLETED CLAY REMEDIATION TO SHEET PILE WALL.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/3/95	110/9709	14
LOCATION:	AREA H	
ACTIVITY:		
HOPPITS POOL - PIPE SUCTION GUARD.		
SPECIAL FEATURES:		




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/3/95	110/9709	15
LOCATION:	AREA H	
ACTIVITY:		
HOPPITS POOL - RAMP CONSTRUCTION IN PROGRESS.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
10/3/95	110/9709	17
LOCATION:	AREA H	
ACTIVITY:		
HOPPITS POOL - EXCAVATION IN PROGRESS.		
SPECIAL FEATURES:		

OPERATIVES WEARING LIFEJACKETS.



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
10/3/95	110/9709	18
LOCATION:	AREA M	
ACTIVITY:		
CORDITE AREA - SCRAPE LOOKING EAST.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
16/3/95	110/9709	27



LOCATION:	AREA H	
ACTIVITY:		
CLEARED CANAL LOOKING SOUTH TO HOPPITS POOL.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
16/3/95	110/9709	28
LOCATION:	AREA H	
ACTIVITY:		
EXCAVATION OF CANAL LOOKING NORTH FROM HOPPITS POOL IN PROGRESS.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
16/3/95	110/9709	29
LOCATION:	AREA H	
ACTIVITY:		
HOPPITS POOL - LOOKING SOUTH.		
SPECIAL FEATURES:		
ALL OPERATIVES WEARING LIFEJACKETS.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
16/3/95	110/9709	30
LOCATION:	AREA P	
ACTIVITY:		
WORK IN PROGRESS WEST OF BUILDING A221 BOUNDARY WALL.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
16/3/95	110/9709	31
LOCATION:	AREA M	
ACTIVITY:		
SCRAPED DITCH IN CORDITE AREA LOOKING EAST.		
SPECIAL FEATURES:		



<b>FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD</b>		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
16/3/95	110/9709	32
LOCATION:	AREA M	
ACTIVITY:		
SCRAPED DITCH IN CORDITE AREA LOOKING EAST.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
16/3/95	110/9709	33

LOCATION:	AREA M	
ACTIVITY:		
WEST END OF MAIN DITCH IN CORDITE AREA.		
SPECIAL FEATURES:		



**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
16/3/95	110/9709	34
LOCATION:	AREA H	
ACTIVITY:		
EXPLOSIVES FIND FROM HOPPITS POOL.		
SPECIAL FEATURES:		




**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
17/3/95	111/9913	1
LOCATION:	AREA	
ACTIVITY:		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
17/3/95	111/9913	6
LOCATION:	AREA B	
ACTIVITY:		
BURNING GROUND - 'HEAT TREATMENT' OF EXPLOSIVELY CONTAMINATED SOILS.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
17/3/95	111/9913	7
LOCATION:	AREA H	
ACTIVITY:		
HOPPITS POOL - REMEDIATION AND RECOVERY OF 'MILLSTONES'.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
17/3/95	111/9913	8
LOCATION:	AREA H	
ACTIVITY:		
HOPPITS POOL - REMEDIATION AND RECOVERY OF ARTIFACTS.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
17/3/95	111/9913	9
LOCATION:	AREAS	
ACTIVITY:		
IGNITER WIRE / GLASS FOUND BY BUILDING S90.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
20/3/95	111/9913	11




LOCATION:	AREA H	
ACTIVITY:		
HOPPITS POOL REMEDIATION - WATER JETTING EAST REVETMENT TO REMOVE CONTAMINATED SEDIMENT.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
20/3/95	111/9913	12
LOCATION:	AREA H	
ACTIVITY:		
HOPPITS POOL - REMEDIATION LOOKING NORTH.		
SPECIAL FEATURES:		

--


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
20/3/95	111/9913	R
LOCATION:	AREA H	
ACTIVITY:		
HOPPITS POOL REMEDIATION - WATER JETTING EAST REVETMENT TO REMOVE CONTAMINATED SEDIMENT.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
29/3/95	112/0858	1
LOCATION:	AREA H	
ACTIVITY:		
HOPPITS POOL REMEDIATION - EAST REVETMENT WALL.		
SPECIAL FEATURES:		
VOID FOUND UNDER WALL FOUNDATION ADJACENT TO BRIDGE No. 17. NOTE: TIMBER PILES.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
29/3/95	112/0858	2
LOCATION:	AREA H	
ACTIVITY:		
HOPPITS POOL REMEDIATION - EAST REVETMENT WALL.		
SPECIAL FEATURES:		
VOID FOUND UNDER WALL FOUNDATION ADJACENT TO BRIDGE No. 17. NOTE: TIMBER PILES.		




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
29/3/95	112/0858	3
LOCATION:	AREA H	
ACTIVITY:		
HOPPITS POOL REMEDIATION.		
SPECIAL FEATURES:		
REAR VIEW OF TEMPORARY SPECIALIST DAM. BRIDGE No. 17 WEST ABUTMENT VISIBLE.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
29/3/95	112/0858	4
LOCATION:	AREA H	
ACTIVITY:		
HOPPITS POOL REMEDIATION.		
SPECIAL FEATURES:		



BRIDGE No. 17 WEST ABUTMENT AND HOPPITS POOL WEST BANK.



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
29/3/95	112/0858	5
LOCATION:	AREA H	
ACTIVITY:		
HOPPITS POOL REMEDIATION LOOKING NORTH.		

SPECIAL FEATURES:


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
29/3/95	112/0858	6

LOCATION:	AREA H	
ACTIVITY:		
BRIDGE No. 17 - VIEW OF UNDERSIDE OF THE STRUCTURE - LOOKING TOWARDS WEST ABUTMENT.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
29/3/95	112/0858	8
LOCATION:	AREA H	
ACTIVITY:		
BRIDGE No. 17 - VIEW OF UNDERSIDE OF STRUCTURE LOOKING TOWARDS EAST ABUTMENT.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
29/3/95	112/0858	9
LOCATION:	AREA H	
ACTIVITY:		
HOPPITS POOL REMEDIATION - VOID BENEATH BRIDGE No. 17 EAST ABUTMENT.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
29/3/95	112/0858	10
LOCATION:	AREA H	
ACTIVITY:		
HOPPITS POOL REMEDIATION - VIEW OF LOCKS AT NORTHERN END.		
SPECIAL FEATURES:		
TOPS OF TIMBER PILES VISIBLE.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
29/3/95	112/0858	11
LOCATION:	AREA H	
ACTIVITY:		
AREA H REMEDIATION / CLAY PLACEMENT OVER FORMER BUILDING H10 AREA.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
29/3/95	112/0858	13
LOCATION:	AREA H	
ACTIVITY:		
BUILDING H17 - MANHOLE EXPOSED TO EAST OF BUILDING (REMOVAL OF		



CONNECTING DRAINS).
SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
29/3/95	112/0858	14

LOCATION:	AREA H	
ACTIVITY:		
BRIDGE No. 17 EASTERN ABUTMENT.		
SPECIAL FEATURES:		
CONCRETE DRY PACKING OF VOID BENEATH ABUTMENT FOUNDATION.		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
29/3/95	112/0858	15
LOCATION:	AREA H	
ACTIVITY:		
BRIDGE No. 17 WESTERN ABUTMENT.		
SPECIAL FEATURES:		

--


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
29/3/95	112/0858	16
LOCATION:	AREA H	
ACTIVITY:		
CLAY BANKING ADJACENT TO BRIDGE No. 17.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
31/3/95	112/0858	17
LOCATION:	AREA H	
ACTIVITY:		
HOPPITS POOL REMEDIATION - BRIDGE No. 17.		
SPECIAL FEATURES:		
NOTE: TEMPORARY FRAMEWORK IN PLACE FOR CONCRETE DRY PACKING OF VOID BELOW BRIDGE AND WALL FOUNDATIONS.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
31/3/95	112/0858	18
LOCATION:	AREA H	
ACTIVITY:		
HOPPITS POOL - GENERAL VIEW OF WORKS FROM WITHIN POOL.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
31/3/95	112/0858	19
LOCATION:	AREA P	
ACTIVITY:		
REMEDIATION ADJACENT TO BUILDING A221 WEST BOUNDARY - LOOKING NORTH.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
31/3/95	112/0858	20




LOCATION:	AREA P
ACTIVITY:	
DRAINAGE INTO MAN HOLE ADJACENT TO BUILDING A221 WEST BOUNDARY.	
SPECIAL FEATURES:	

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
31/3/95	112/0858	21
LOCATION:	AREA P	
ACTIVITY:		
BUILDING A238 POLICE LODGE - CLEARED OUT SERVICES TRENCH NORTH OF THE BUILDING - VIEW LOOKING SOUTH.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
31/3/95	112/0858	22
LOCATION:	AREA H	
ACTIVITY:		
HOPPITS POOL REMEDIATION - LOOKING SOUTH TOWARDS TEMPORARY DAM.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
31/3/95	112/0858	23
LOCATION:	AREA S	
ACTIVITY:		
WATER TANK BASE NORTH OF BUILDING E12.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
31/3/95	112/0858	24
LOCATION:	AREA S	
ACTIVITY:		
BUILDING E2 MOUND - REMOVAL OF ASBESTOS CONTAMINATED SURFACE (NORTH FACE OF MOUND).		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
31/3/95	112/0858	25
LOCATION:	AREA S	
ACTIVITY:		
BUILDING E2 MOUND - REMOVAL OF ASBESTOS CONTAMINATED		

SURFACE (NORTH FACE OF MOUND).
SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
31/3/95	112/0858	26


LOCATION:	AREA N	
ACTIVITY:		
LOADING CLAY FOR TRANSPORTATION TO OTHER PARTS OF THE SITE AS FILL MEDIA.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
31/3/95	112/0858	27
LOCATION:	AREA N	
ACTIVITY:		
LOADING CLAY FOR TRANSPORTATION TO OTHER PARTS OF THE SITE AS FILL MEDIA.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
3/4/95	112/0858	28
LOCATION:	AREA H	
ACTIVITY:		
HOPPITS POOL REMEDIATION - BRIDGE No. 17 WEST ABUTMENT.		
SPECIAL FEATURES:		
CLAY FILLING PLACED TO PREVENT FURTHER EROSION OF FOUNDATIONS.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
3/4/95	112/0858	29
LOCATION:	AREA H	
ACTIVITY:		
HOPPITS POOL REMEDIATION - BRIDGE No. 17 EAST ABUTMENT.		
SPECIAL FEATURES:		
VIEW AFTER CONCRETE DRY PACKING OF VOID BELOW FOUNDATION.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
3/4/95	112/0858	30
LOCATION:	AREA H	
ACTIVITY:		
HOPPITS POOL REMEDIATION - VIEW LOOKING SOUTH.		
SPECIAL FEATURES:		



<b>FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD</b>		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
3/4/95	112/0858	31
LOCATION:	AREA H	
ACTIVITY:		
HOPPITS POOL REMEDIATION - VIEW LOOKING SOUTH.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
5/4/95	112/0858	32


LOCATION:	AREA H	
ACTIVITY:		
HOPPITS POOL REMEDIATION.		
SPECIAL FEATURES:		
GRAVEL PLACEMENT TO PREVENT FURTHER EROSION OF WALL FOUNDATION SUPPORT.		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
5/4/95	112/0858	33
LOCATION:	AREA H	
ACTIVITY:		
HOPPITS POOL REMEDIATION - GENERAL VIEW LOOKING SOUTH WEST.		
SPECIAL FEATURES:		
WEST BANK OF POOL REMEDIATED AND REPLACED WITH CLAY.		



--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
5/4/95	112/0858	34
LOCATION:	AREA H	
ACTIVITY:		
HOPPITS POOL REMEDIATION - NORTH EAST CORNER.		
SPECIAL FEATURES:		
NOTE: TOPS OF VERTICAL TIMBER PILES EXPOSED AND LABELLED BY THE SITE ARCHAEOLOGIST.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
5/4/95	112/0858	35
LOCATION:	AREA H	
ACTIVITY:		
HOPPITS POOL REMEDIATION IN NORTH WEST CORNER - WORKS IN PROGRESS.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
5/4/95	112/0858	36
LOCATION:	AREA H	
ACTIVITY:		
HOPPITS POOL REMEDIATION - GENERAL VIEW LOOKING SOUTH TOWARDS TEMPORARY DAM.		
SPECIAL FEATURES:		

WORKS COMPLETED AT SOUTHERN END OF POOL.



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
5/4/95	112/0858	37
LOCATION:	AREA H	
ACTIVITY:		
HOPPITS POOL REMEDIATION - NORTH EAST CORNER SHOWING		

EXCAVATION.

SPECIAL FEATURES:


VERTICAL TIMBER PILES EXPOSED AND LABELLED BY SITE  
ARCHAEOLOGIST.

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
6/4/95	113/1871	1
LOCATION:	AREA H	
ACTIVITY:		
HOPPITS POOL REMEDIATION - NORTH END.		
SPECIAL FEATURES:		
HAND EXCAVATION AROUND ARCHAEOLOGICALLY SENSITIVE REMAINS.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
6/4/95	113/1871	2
LOCATION:	AREA H	
ACTIVITY:		
HOPPITS POOL REMEDIATION - NORTH END.		
SPECIAL FEATURES:		
HAND EXCAVATION AROUND ARCHAEOLOGICALLY SENSITIVE REMAINS.		




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
7/4/95	113/1871	3
LOCATION:	AREA H	
ACTIVITY:		
HOPPITS POOL REMEDIATION - NORTH WEST CORNER.		
SPECIAL FEATURES:		
CLAY COVERING TO ARCHAEOLOGICALLY SENSITIVE REMAINS.		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
7/4/95	113/1871	4
LOCATION:	AREA H	
ACTIVITY:		
HOPPITS POOL - REMEDIATION.		
SPECIAL FEATURES:		

BRIDGE No. 17 - WEST ABUTMENT.  
 STONE CAPPING TO HELP PREVENT EROSION OF BANKING.



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
7/4/95	113/1871	5
LOCATION:	AREAS	
ACTIVITY:		
WELL NORTH OF BUILDING ARS 2.		

SPECIAL FEATURES:
150 DIA PUMP REQUIRED TO PUMP DOWN AND HOLD BACK GROUND WATER WHILE CLEAR OUT IS IN PROGRESS.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
7/4/95	113/1871	6

LOCATION:	AREA S	
ACTIVITY:		
WELL NORTH OF BUILDING ARS 2.		
SPECIAL FEATURES:		
NOTE: OIL FILM ON SURFACE OF WATER CAUSED BY CONTAMINANTS DUMPED IN THE WELL.		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
10/4/95	113/1871	7
LOCATION:	AREA P	
ACTIVITY:		
SEPTIC TANK BEING DELIVERED FOR BUILDING A221 (ASSOCIATED WITH WIMPEY DEVELOPMENT OF AREA P SOUTH).		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
11/4/95	113/1871	8
LOCATION:	AREA H	
ACTIVITY:		
HOPPITS POOL REMEDIATION - NORTH WEST CORNER.		
SPECIAL FEATURES:		
CLAY PLACEMENT OVER ARCHAEOLOGICALLY SENSITIVE REMAINS. BUILDING H17 TO RIGHT IN BACKGROUND.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
13/4/95	113/1871	9
LOCATION:	AREA H	
ACTIVITY:		
HOPPITS POOL REMEDIATION - WEST BANK.		
SPECIAL FEATURES:		
GRAVEL PLACEMENT OVER NEW CLAY BANK.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
13/4/95	113/1871	10
LOCATION:	AREA H	
ACTIVITY:		
HOPPITS POOL REMEDIATION - LOOKING NORTH WEST.		
SPECIAL FEATURES:		



REMEDATION NEARING COMPLETION.



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
13/4/95	113/1871	11
LOCATION:	AREA H	
ACTIVITY:		
HOPPITS POOL REMEDIATION - LOOKING SOUTH (JOB NEARING		

COMPLETION).
SPECIAL FEATURES:
TEMPORARY DAM IN BACKGROUND.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
13/4/95	113/1871	12

LOCATION:	AREA H	
ACTIVITY:		
HOPPITS POOL REMEDIATION - NORTH WEST CORNER, COMPLETING LAST SECTION OF WALL.		
SPECIAL FEATURES:		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
13/4/95	113/1871	13
LOCATION:	AREA H	
ACTIVITY:		
HOPPITS POOL REMEDIATION - LOOKING NORTH.		
SPECIAL FEATURES:		
NOTE: CLAY DAM HOLDING BACK CANAL DISCHARGE.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
13/4/95	113/1871	14
LOCATION:	AREA H	
ACTIVITY:		
HOPPITS POOL REMEDIATION - PROPPING OF WALLS IN SLUICE IN PROGRESS.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
13/4/95	113/1871	15
LOCATION:	AREA H	
ACTIVITY:		
HOPPITS POOL REMEDIATION - DISMANTLING PUMP SUCTION PIPEWORK.		
SPECIAL FEATURES:		
REMEDATION COMPLETE.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
19/4/95	113/1871	17
LOCATION:	AREAS	
ACTIVITY:		
BUILDING S33 - EAST.		
SPECIAL FEATURES:		

TETRYL DEPOSITS IN GROUND (YELLOW MATERIAL).



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
19/4/95	113/1871	18
LOCATION:	AREA S	
ACTIVITY:		
BUILDING S33 - EAST.		




SPECIAL FEATURES:
TETRYL DEPOSITS IN GROUND (YELLOW MATERIAL).

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
19/4/95	113/1871	19

LOCATION:	AREAS	
ACTIVITY:		
BUILDING S33 - EAST.		
SPECIAL FEATURES:		
TETRYL DEPOSITS IN GROUND (YELLOW MATERIAL).		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
19/4/95	113/1871	20
LOCATION:	AREA P	
ACTIVITY:		
AREA P NORTH - REFILLING OF REDUCED GROUND SOUTH OF BUILDING A221.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
19/4/95	113/1871	21
LOCATION:	AREA P	
ACTIVITY:		
AREA P NORTH - GENERAL VIEW LOOKING SOUTH.		
SPECIAL FEATURES:		
NEW ACCESS ROAD, GROUND REDUCED TO CLEAN VIRGIN STRATA.		




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/4/95	113/1871	23
LOCATION:	AREA H	
ACTIVITY:		
REMOVAL OF FWD'S ADJACENT BUILDING H17.		
SPECIAL FEATURES:		
HOPPITS POOL IN BACKGROUND.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/4/95	113/1871	24
LOCATION:	AREA H	
ACTIVITY:		
REMOVAL OF FWD'S ADJACENT TO BUILDING H17.		
SPECIAL FEATURES:		

HOPPITS POOL IN BACKGROUND.



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/4/95	113/1871	25
LOCATION:	AREA S	
ACTIVITY:		
SETTLING TANKS - NORTH WEST OF BUILDING 83B - CLEANING OUT		

TANKS.
SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/4/95	113/1871	26




LOCATION:	AREAS	
ACTIVITY:		
SETTLING TANKS NORTH WEST OF BUILDING 83B - MANHOLE ADJACENT.		
SPECIAL FEATURES:		
NOTE: OILY DEPOSITS ON SURFACE OF WATER.		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/4/95	113/1871	27
LOCATION:	AREA S	
ACTIVITY:		
SETTLING TANKS - NORTH WEST OF BUILDING 83B FIRST CHAMBER.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/4/95	113/1871	28
LOCATION:	AREA S	
ACTIVITY:		
CANAL INTERSECTION 26 - COFFERDAM INSTALLATION PILING RIG IN POSITION.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/4/95	113/1871	29
LOCATION:	AREA S	
ACTIVITY:		
BUILDING S31 - TETRYL CONTAMINATION - REMOVAL.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/4/95	113/1871	30
LOCATION:	AREA S	
ACTIVITY:		
BUILDING S31 - TETRYL CONTAMINATION - REMOVAL.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
28/4/95	113/1871	33
LOCATION:	AREA H	
ACTIVITY:		
BUILDING H17 - FWD REMOVAL.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
28/4/95	113/1871	34

LOCATION:	AREAS	
ACTIVITY:		
REMOVAL OF CORDITE CONTAMINATED GROUND SOUTH OF BUILDING L189.		
SPECIAL FEATURES:		




**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
28/4/95	113/1871	35
LOCATION:	AREA S	
ACTIVITY:		
CANAL - PARTIAL CLEARANCE ADJACENT TO ACCESS ROAD - EAST OF BUILDING L189.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
28/4/95	113/1871	36
LOCATION:	AREA T	
ACTIVITY:		
CANAL INTERSECTION 26 - INSTALLATION OF COFFERDAM.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
28/4/95	113/1871	R
LOCATION:	AREA T	
ACTIVITY:		
CANAL INTERSECTION 26 - INSTALLATION OF COFFERDAM.		
SPECIAL FEATURES:		




**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
1/5/95	114/2412	1
LOCATION:	AREA	
ACTIVITY:		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
2/5/95	114/2412	2
LOCATION:	AREA S	
ACTIVITY:		
BUILDING S90 - CLEANING OUT BRICK WELL ADJACENT S90.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
2/5/95	114/2412	3
LOCATION:	AREA H	
ACTIVITY:		
H17 - FWD CAPPED OFF AT NORTH EAST CORNER.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
4/5/95	114/2412	4
LOCATION:	AREA T	
ACTIVITY:		
INTERSECTION 26 - EXCAVATION AROUND BARGE.		
SPECIAL FEATURES:		




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
4/5/95	114/2412	5
LOCATION:	AREA T	
ACTIVITY:		
INTERSECTION 26 - EXCAVATION AROUND BARGE.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
5/5/95	114/2412	6


LOCATION:	AREA T	
ACTIVITY:		
INTERSECTION 26 - MOVING BARGE OUT OF EXCAVATION AREA.		
SPECIAL FEATURES:		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDICATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
5/5/95	114/2412	7
LOCATION:	AREA T	
ACTIVITY:		
INTERSECTION 26 - LIFTING BARGE OUT OF EXCAVATION.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
5/5/95	114/2412	8
LOCATION:	AREA T	
ACTIVITY:		
INTERSECTION 26 - BARGE REMOVED FROM THE EXCAVATION.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
6/5/95	114/2412	9
LOCATION:	AREA T	
ACTIVITY:		
INTERSECTION 26 - EXCAVATION OF CONTAMINATED GROUND BEHIND COFFERDAM.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
6/5/95	114/2412	10
LOCATION:	AREA T	
ACTIVITY:		
INTERSECTION 26 - EXCAVATION OF CONTAMINATED GROUND BEHIND COFFERDAM.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
6/5/95	114/2412	11
LOCATION:	AREA T	
ACTIVITY:		
INTERSECTION 26 - EXCAVATION OF CONTAMINATED GROUND BEHIND		



COFFERDAM.
SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
6/5/95	114/2412	12

LOCATION:	AREA T	
ACTIVITY:		
INTERSECTION 26 - CLAY FILL REINSTATEMENT OF MILLHEAD STREAM BANK.		
SPECIAL FEATURES:		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
6/5/95	114/2412	13
LOCATION:	AREA T	
ACTIVITY:		
INTERSECTION 26 - CLAY FILL REINSTATEMENT OF MILLHEAD STREAM BANK.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/5/95	114/2412	14
LOCATION:	AREA T	
ACTIVITY:		
INTERSECTION 25 - EXCAVATION OF CONTAMINATED GROUND FROM BEHIND COFFERDAM.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/5/95	114/2412	15
LOCATION:	AREA B	
ACTIVITY:		
CORDITE RECOVERED FROM CANAL EXCAVATIONS PREPARATION FOR FIRING ON BURNING GROUND.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/5/95	114/2412	16
LOCATION:	AREA B	
ACTIVITY:		
CORDITE FIRING ON BURNING GROUND - COMMENCEMENT.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/5/95	114/2412	17
LOCATION:	AREA B	
ACTIVITY:		
CORDITE FIRING ON BURNING GROUND.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/5/95	114/2412	18



LOCATION:	AREA B	
ACTIVITY:		
CORDITE FIRING ON BURNING GROUND.		
SPECIAL FEATURES:		
NOTE: RAPID BURN.		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDICATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/5/95	114/2412	19
LOCATION:	AREA B	
ACTIVITY:		
CORDITE FIRING ON BURNING GROUND.		
SPECIAL FEATURES:		
NOTE: RAPID BURN.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/5/95	114/2412	20
LOCATION:	AREA B	
ACTIVITY:		
CORDITE FIRING ON BURNING GROUND.		
SPECIAL FEATURES:		
NOTE: RAPID BURN.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/5/95	114/2412	21
LOCATION:	AREA T	
ACTIVITY:		
INTERSECTION 26 - CLAY FILLING AS REINSTATEMENT TO HORSEMILL STREAM BANK.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/5/95	114/2412	22
LOCATION:	AREA T	
ACTIVITY:		
INTERSECTION 25 - CLAY FILLING AS REINSTATEMENT TO HORSEMILL STREAM BANK.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/5/95	114/2412	23
LOCATION:	AREA P	
ACTIVITY:		
ENLARGING APPROACH ROAD TO BUILDING A210.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
11/5/95	114/2412	24

LOCATION:	AREA T	
ACTIVITY:		
INTERSECTION 25 - FINISHED CLAY BANK.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
11/5/95	114/2412	25
LOCATION:	AREA S	
ACTIVITY:		
INTERSECTION 21 - EXCAVATION OF CANAL BANK.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
11/5/95	114/2412	26
LOCATION:	AREA S	
ACTIVITY:		
INTERSECTION 21 - REMOVAL OF CONTAMINATED GROUND.		
SPECIAL FEATURES:		
LARGE DEPOSITS OF BRICK AND CONCRETE IN BANK.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
11/5/95	114/2412	27
LOCATION:	AREA M	
ACTIVITY:		
EAST OF BUILDING L160 - CANAL EXCAVATION.		
SPECIAL FEATURES:		
OIL / TAR CONTAMINATION FOUND.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
11/5/95	114/2412	28
LOCATION:	AREA M	
ACTIVITY:		
EAST OF BUILDING L160 - CANAL EXCAVATION.		
SPECIAL FEATURES:		

OIL / TAR CONTAMINATION FOUND.

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
11/5/95	114/2412	29
LOCATION:	AREA M	
ACTIVITY:		
EAST OF BUILDING L160 - CANAL EXCAVATION.		

SPECIAL FEATURES:
OIL / TAR CONTAMINATION FOUND.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
11/5/95	114/2412	30

LOCATION:	AREA M	
ACTIVITY:		
EAST OF BUILDING L160 - CANAL EXCAVATION.		
SPECIAL FEATURES:		
OIL / TAR CONTAMINATION FOUND.		


**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
11/5/95	114/2412	31
LOCATION:	AREA M	
ACTIVITY:		
EAST OF BUILDING L160 - CANAL EXCAVATION.		
SPECIAL FEATURES:		
OIL / TAR CONTAMINATION FOUND.		



--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
11/5/95	114/2412	32
LOCATION:	AREA P	
ACTIVITY:		
SAMPLE No. 41196.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/5/95	114/2412	33
LOCATION:	AREA S	
ACTIVITY:		
INTERSECTION 21 - EXCAVATION AROUND BURIED BARGE.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/5/95	114/2412	34
LOCATION:	AREA S	
ACTIVITY:		
INTERSECTION 21 - EXCAVATION AROUND BURIED BARGE.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/5/95	114/2412	35
LOCATION:	AREA M	
ACTIVITY:		
EAST OF BUILDING L160 - CANAL EXCAVATION.		

SPECIAL FEATURES:
OIL / TAR CONTAMINATION FOUND.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/5/95	114/2412	36

LOCATION:	AREA M	
ACTIVITY:		
EAST OF BUILDING L160 - CANAL EXCAVATION.		
SPECIAL FEATURES:		
NOTE: CONCRETE BASE TO 'TAR PIT STRUCTURE'. HEAVY OIL / TAR IN SOIL, CONCRETE AND GROUND WATER.		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/5/95	114/2412	37
LOCATION:	AREA M	
ACTIVITY:		
EAST OF BUILDING L160 - CANAL EXCAVATION.		
SPECIAL FEATURES:		
NOTE: 'OIL RETAINING SAUSAGE' IN PLACE TO PREVENT MIGRATION OF SURFACE OILS.		






**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/5/95	115/3019	1
LOCATION:	AREA M	
ACTIVITY:		
CANAL EXCAVATION EAST OF BUILDING L160 - REMOVAL OF OIL / TAR CONTAMINATED GROUND.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/5/95	115/3019	2
LOCATION:	AREA M	
ACTIVITY:		
CANAL EXCAVATION EAST OF BUILDING L160 - REMOVAL OF OIL / TAR CONTAMINATED GROUND.		
SPECIAL FEATURES:		
NOTE: MACHINE OPERATOR P.P.E.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/5/95	115/3019	3
LOCATION:	AREA M	
ACTIVITY:		
CANAL EXCAVATION EAST OF BUILDING L160 - REMOVAL OF OIL / TAR CONTAMINATED GROUND.		
SPECIAL FEATURES:		
FOUNDATION BASE TO 'TAR PIT'.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/5/95	115/3019	4
LOCATION:	AREA M	
ACTIVITY:		
CANAL EXCAVATION EAST OF BUILDING L160 - REMOVAL OF OIL / TAR CONTAMINATED GROUND.		
SPECIAL FEATURES:		

FOUNDATION BASE TO 'TAR PIT'.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/5/95	115/3019	5
LOCATION:	AREA M	
ACTIVITY:		
CANAL EXCAVATION EAST OF BUILDING L160 - REMOVAL OF OIL / TAR		

CONTAMINATED GROUND.
SPECIAL FEATURES:
NOTE: FOUNDATION BASE TO 'TAR PIT'. OVAL SHAPED TAR RECEPTACLE LOCATED.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/5/95	115/3019	6


LOCATION:	AREA M	
ACTIVITY:		
CANAL EXCAVATION EAST OF BUILDING L160 - REMOVAL OF OIL / TAR CONTAMINATED GROUND.		
SPECIAL FEATURES:		
TAR / OIL DEPOSITS IN SOILS AND WATER.		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/5/95	115/3019	7
LOCATION:	AREA M	
ACTIVITY:		
CANAL EXCAVATION EAST OF BUILDING L160 - REMOVAL OF OIL / TAR CONTAMINATED GROUND.		
SPECIAL FEATURES:		
BUILDING L159 IN BACKGROUND.		



--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/5/95	115/3019	8
LOCATION:	AREA S	
ACTIVITY:		
INTERSECTION 21 - BARGE REMOVAL.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/5/95	115/3019	9
LOCATION:	AREA S	
ACTIVITY:		
INTERSECTION 21 - BARGE REMOVAL.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/5/95	115/3019	10
LOCATION:	AREAS	
ACTIVITY:		
INTERSECTION 21 - BARGE REMOVAL.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/5/95	115/3019	11
LOCATION:	AREA S	
ACTIVITY:		
INTERSECTION 21 - BARGE REMOVAL.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/5/95	115/3019	12

LOCATION:	AREAS	
ACTIVITY:		
INTERSECTION 21 - BARGE REMOVAL.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/5/95	115/3019	13
LOCATION:	AREA M	
ACTIVITY:		
CANAL EXCAVATION EAST OF BUILDING L160 - REMOVAL OF OIL / TAR CONTAMINATED GROUND.		
SPECIAL FEATURES:		
OVAL METALLIC TAR RECEPTACLE.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
13/5/95	115/3019	14
LOCATION:	AREA S	
ACTIVITY:		
INTERSECTION 21 - CLAY INFILLING TO REINSTATE EMBANKMENT.		
SPECIAL FEATURES:		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
13/5/95	115/3019	15
LOCATION:	AREA S	
ACTIVITY:		
INTERSECTION 21 - CLAY INFILLING TO REINSTATE EMBANKMENT.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
16/5/95	115/3019	16
LOCATION:	AREA M	
ACTIVITY:		
BARGE FROM INTERSECTION 21 IN TRANSIT TO BUILDING L157.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
16/5/95	115/3019	17
LOCATION:	AREA M	
ACTIVITY:		
BARGE FROM INTERSECTION 21 IN TRANSIT TO BUILDING L157.		

SPECIAL FEATURES:


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
18/5/95	115/3019	19

LOCATION:	AREA M	
ACTIVITY:		
GAS WORKS SITE - EAST OF BUILDING L159.		
SPECIAL FEATURES:		
GROUND LEVELS REDUCED SHOWING FORMER STRUCTURE FOUNDATIONS.		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
18/5/95	115/3019	20
LOCATION:	AREA M	
ACTIVITY:		
GAS WORKS SITE - EAST OF BUILDING L159.		
SPECIAL FEATURES:		
GROUND LEVEL REDUCED SHOWING FORMER STRUCTURE FOUNDATIONS.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
18/5/95	115/3019	21
LOCATION:	AREA M	
ACTIVITY:		
CANAL EXCAVATION EAST OF BUILDING L160 - REMOVAL OF OIL / TAR CONTAMINATED GROUND.		
SPECIAL FEATURES:		
TAR PIT BARE TO RIGHT OF SHOT.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
18/5/95	115/3019	22
LOCATION:	AREA M	
ACTIVITY:		
CANAL EXCAVATION EAST OF BUILDING L160 - REMOVAL OF OIL / TAR CONTAMINATED GROUND.		
SPECIAL FEATURES:		
TAR RECEPTACLE.		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
18/5/95	115/3019	23
LOCATION:	AREA M	
ACTIVITY:		
GAS WORKS AREA - LOOKING NORTH.		
SPECIAL FEATURES:		

BUILDING L160 TO LEFT OF SHOT.



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
18/5/95	115/3019	24
LOCATION:	AREA B	
ACTIVITY:		
TREE PLANTING EAST OF BURNING GROUND - SOUTH OF BRIDGE No. 10.		

SPECIAL FEATURES:


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
18/5/95	115/3019	25

LOCATION:	AREAS	
ACTIVITY:		
REMEDATION SOUTH OF BUILDING S31.		
SPECIAL FEATURES:		
REMOVAL OF TETRYL CONTAMINATED SOILS.		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
18/5/95	115/3019	26
LOCATION:	AREA L	
ACTIVITY:		
CANAL DREDGINGS - DRIED AND STOCKPILED ON QUEENS MEAD.		
SPECIAL FEATURES:		
OFF SITE DISPOSAL.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
18/5/95	115/3019	28
LOCATION:	AREA H	
ACTIVITY:		
AREA H SOUTH - ACCESS ROAD REINSTATEMENT FOLLOWING REMOVAL OF CONTAMINATED GROUND.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
18/5/95	115/3019	29
LOCATION:	AREA H	
ACTIVITY:		
AREA H SOUTH - ACCESS ROAD REINSTATEMENT FOLLOWING REMOVAL OF CONTAMINATED GROUND.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
19/5/95	115/3019	30
LOCATION:	AREA M	
ACTIVITY:		
BARGE - EX INTERSECTION 21.		
SPECIAL FEATURES:		




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
19/5/95	115/3019	31
LOCATION:	AREA M	
ACTIVITY:		
BARGE - EX INTERSECTION 21.		

SPECIAL FEATURES:
ARCHAEOLOGIST RECORDING DIMENSIONS ETC.


<b>FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD</b>		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:

19/5/95	115/3019	32
LOCATION:	AREA M	
ACTIVITY:		
BARGE - EX INTERSECTION 21.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
19/5/95	115/3019	33
LOCATION:	AREA B	
ACTIVITY:		
BURNING GROUND REMEDIATION IN PROGRESS.		
SPECIAL FEATURES:		
REMOVAL OF ASH FILL.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
19/5/95	115/3019	34
LOCATION:	AREA B	
ACTIVITY:		
BURNING GROUND REMEDIATION IN PROGRESS.		
SPECIAL FEATURES:		
REMOVAL OF ASH FILL.		




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
23/5/95	116/4287	1
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L160 / L159 - FWD REMOVAL.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
24/5/95	116/4287	4
LOCATION:	AREA S	
ACTIVITY:		
WEST OF BUILDING E12 - REMOVAL OF ASBESTOS CONTAMINATED SOIL.		
SPECIAL FEATURES:		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
24/5/95	116/4287	5
LOCATION:	AREA S	
ACTIVITY:		
WEST OF BUILDING E12 - SUSPECT 'YELLOW DEPOSITS'.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
24/5/95	116/4287	6
LOCATION:	AREA B	
ACTIVITY:		
EXCAVATED BURNING GROUND FILL MATERIAL LAID OUT FOR SAMPLING.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/5/95	116/4287	7
LOCATION:	AREAS	
ACTIVITY:		
BURNT OUT BARGE AT BUILDING 88A.		

SPECIAL FEATURES:
SUBJECT OF VANDALISM.


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/5/95	116/4287	8

LOCATION:	AREAS	
ACTIVITY:		
BURNT OUT BARGE AT BUILDING 88A.		
SPECIAL FEATURES:		
SUBJECT OF VANDALISM.		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/5/95	116/4287	9
LOCATION:	AREA S	
ACTIVITY:		
BURNT OUT BARGE AT BUILDING 88A.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
31/5/95	116/4287	10
LOCATION:	AREA H	
ACTIVITY:		
HOPPITS ROAD / HOPPIT CANAL SHOWING UNSTABLE EAST WALL AT ROAD CROSSING.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
31/5/95	116/4287	11
LOCATION:	AREA S	
ACTIVITY:		
INTERSECTION 21 - NORTH BANK BEFORE REFILLING.		
SPECIAL FEATURES:		
NOTE: HORSEMILL STREAM BANK REINSTATEMENT WITH CLAY.		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
31/5/95	116/4287	12
LOCATION:	AREAS	
ACTIVITY:		
INTERSECTION 21 - NORTH BANK BEFORE REFILLING.		
SPECIAL FEATURES:		

NOTE: FORMER CANAL TIMBER PILES.

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
31/5/95	116/4287	13
LOCATION:	AREA S	
ACTIVITY:		
INTERSECTION 27 - EXCAVATION AROUND BURIED BARGE.		

SPECIAL FEATURES:


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
31/5/95	116/4287	14

LOCATION:	AREAS	
ACTIVITY:		
INTERSECTION 27 - EXCAVATION AROUND BURIED BARGE.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
1/6/95	116/4287	15
LOCATION:	AREA H	
ACTIVITY:		
REMAINS OF BURIED ANIMAL CARCASES LOCATED IN PIT NORTH WEST OF BUILDING H17.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
1/6/95	116/4287	16
LOCATION:	AREA H	
ACTIVITY:		
REMAINS OF BURIED ANIMAL CARCASES LOCATED IN PIT NORTH WEST OF BUILDING H17.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
5/6/95	116/4287	17
LOCATION:	AREA H	
ACTIVITY:		
REINSTATEMENT OF EXCAVATED CANAL BANK LOOKING SOUTH TOWARDS HOPPITS POOL.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
5/6/95	116/4287	18
LOCATION:	AREA S	
ACTIVITY:		
INTERSECTION 27 - LOCATION OF 2ND BARGE IN FACE OF CANAL - LOOKING EAST.		
SPECIAL FEATURES:		




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
5/6/95	116/4287	19
LOCATION:	AREA S	
ACTIVITY:		
INTERSECTION 27 - LOCATION OF 1ST BARGE CLEANED OUT LOOKING		

WEST.
SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
7/6/95	116/4287	20

LOCATION:	AREA N	
ACTIVITY:		
YOUNG HERON FOUND AT NEW HILL BEFORE PLACING BACK IN HERONRY.		
SPECIAL FEATURES:		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDICATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
8/6/95	116/4287	21
LOCATION:	AREA S	
ACTIVITY:		
INTERSECTION 27 - PRIOR TO BACKFILL.		
SPECIAL FEATURES:		
BARGE - AFTER CLEANING AND INSPECTION - LEFT IN SITU.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
8/6/95	116/4287	22
LOCATION:	AREA T	
ACTIVITY:		
INTERSECTION 26 LOOKING SOUTH.		
SPECIAL FEATURES:		
CLAY REINSTATEMENT COMPLETE.		




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/6/95	116/4287	25
LOCATION:	AREA H	
ACTIVITY:		
DECONTAMINATION OF ANIMAL BONES FOUND IN PIT ADJACENT BUILDING H17.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/6/95	116/4287	26
LOCATION:	AREA H	
ACTIVITY:		
VIEW NORTH OF WESTERN HOPPIT CANAL.		
SPECIAL FEATURES:		

DECONTAMINATION OF 'BONES PIT' IN PROGRESS.



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/6/95	116/4287	27
LOCATION:	AREA H	
ACTIVITY:		
DECONTAMINATION OF ANIMAL BONES FOUND IN PIT ADJACENT		



BUILDING H17.
SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/6/95	116/4287	28

LOCATION:	AREAS	
ACTIVITY:		
INTERSECTION 29 - HORSEMILL STREAM.		
SPECIAL FEATURES:		
CONTAMINATED GROUND REMOVED.		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/6/95	116/4287	29
LOCATION:	AREA S	
ACTIVITY:		
INTERSECTION 29 - REMOVAL OF CONTAMINATED MATERIAL FROM BEHIND HORSEMILL STREAM BANK.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/6/95	116/4287	30
LOCATION:	AREA M	
ACTIVITY:		
REMOVAL OF OIL / TAR CONTAMINATED GROUND EAST OF BUILDINGS L160 / L159.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
13/6/95	116/4287	31
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - SWAB SAMPLE LOCATION 18039.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
13/6/95	116/4287	32
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - SWAB SAMPLE LOCATION 18040.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
13/6/95	116/4287	33
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - SWAB SAMPLE LOCATION 18041.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
13/6/95	116/4287	34




LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - SWAB SAMPLE LOCATION 18042.		
SPECIAL FEATURES:		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
13/6/95	116/4287	35
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - SWAB SAMPLE LOCATION 18043.		
SPECIAL FEATURES:		
NOTE: ROOF TIMBER CORE POSITION IN CENTRE OF SHOT.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
13/6/95	116/4287	36
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - SWAB SAMPLE LOCATION 18044.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
13/6/95	116/4287	R
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - SWAB SAMPLE LOCATION 18045.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD

DATE:

NEGATIVE REFERENCE:

FRAME REFERENCE:

13/6/95

117/4631

1

LOCATION:

AREA M


ACTIVITY:

BUILDING L157 - SWAB SAMPLE LOCATION 18046.

SPECIAL FEATURES:

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
13/6/95	117/4631	2
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - SWAB SAMPLE LOCATION 18047.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
13/6/95	117/4631	3
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - SWAB SAMPLE LOCATION 18048.		
SPECIAL FEATURES:		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
13/6/95	117/4631	4
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - SWAB SAMPLE LOCATION 18049.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
13/6/95	117/4631	5
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - SWAB SAMPLE LOCATION 18050.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
13/6/95	117/4631	6

LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - SWAB SAMPLE LOCATION 18051.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
13/6/95	117/4631	7
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - SWAB SAMPLE LOCATION 18052.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
13/6/95	117/4631	8
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - SWAB SAMPLE LOCATION 18053.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
13/6/95	117/4631	11
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - SWAB SAMPLE LOCATION 18054.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
13/6/95	117/4631	12
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - SWAB SAMPLE LOCATION 18055.		
SPECIAL FEATURES:		




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
13/6/95	117/4631	13
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - SWAB SAMPLE LOCATION 18056.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
13/6/95	117/4631	14

LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - SWAB SAMPLE LOCATION 18057.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
13/6/95	117/4631	15
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - SWAB SAMPLE LOCATION 18058.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
13/6/95	117/4631	16
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - SWAB SAMPLE LOCATION 18059.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
13/6/95	117/4631	17
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - SWAB SAMPLE LOCATION 18060.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
14/6/95	117/4631	18
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L157 - SWAB SAMPLE LOCATION 18061.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
14/6/95	117/4631	19
LOCATION:	AREA P	
ACTIVITY:		
REMOVAL OF BRIDGE No. 2 - LOOKING SOUTH.		



SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
15/6/95	117/4631	20


LOCATION:	AREA P	
ACTIVITY:		
REMOVAL OF BRIDGE No. 2 - LOOKING NORTH.		
SPECIAL FEATURES:		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
15/6/95	117/4631	21
LOCATION:	AREA M	
ACTIVITY:		
REMOVAL OF OIL / TAR CONTAMINATION FROM OLD GASWORKS EXCAVATIONS.		
SPECIAL FEATURES:		
BOWSER UNIT USED FOR DISPOSAL OF OIL AND TAR.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
20/6/95	117/4631	22
LOCATION:	AREA M	
ACTIVITY:		
REMOVAL OF OIL / TAR CONTAMINATION FROM OLD GASWORKS EXCAVATIONS.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
20/6/95	117/4631	23
LOCATION:	AREA M	
ACTIVITY:		
EXCAVATED CANAL IN CORDITE CONTAMINATED AREA.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
20/6/95	117/4631	24
LOCATION:	AREA M	
ACTIVITY:		
DEEP EXCAVATION LOOKING EAST IN OLD GASWORKS AREA.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
26/6/95	117/4631	25
LOCATION:	AREA M	
ACTIVITY:		
DEEP EXCAVATION LOOKING SOUTH IN OLD GASWORKS AREA.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
26/6/95	117/4631	26




LOCATION:	AREA M	
ACTIVITY:		
DE-WATERING SUMP - LOOKING NORTH IN OLD GASWORKS AREA.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
26/6/95	117/4631	27
LOCATION:	AREA H	
ACTIVITY:		
TRIAL PIT 1 - OUTSIDE SECURITY FENCE.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
26/6/95	117/4631	28
LOCATION:	AREA H	
ACTIVITY:		
TRIAL PIT 1 - OUTSIDE SECURITY FENCE.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
26/6/95	117/4631	29
LOCATION:	AREA H	
ACTIVITY:		
TRIAL PIT 1 - OUTSIDE SECURITY FENCE.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
26/6/95	117/4631	30
LOCATION:	AREA H	
ACTIVITY:		
TRIAL PIT 2 - OUTSIDE SECURITY FENCE.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
26/6/95	117/4631	31
LOCATION:	AREA H	
ACTIVITY:		
TRIAL PIT 3 - OUTSIDE SECURITY FENCE.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/6/95	117/4631	32


LOCATION:	AREA H	
ACTIVITY:		
TRIAL PIT 4 - OUTSIDE SECURITY FENCE.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/6/95	117/4631	33
LOCATION:	AREA H	
ACTIVITY:		
TRIAL PIT 5 - OUTSIDE SECURITY FENCE.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/6/95	117/4631	34
LOCATION:	AREA H	
ACTIVITY:		
TRIAL PIT 6 - OUTSIDE SECURITY FENCE.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/6/95	117/4631	35
LOCATION:	AREA H	
ACTIVITY:		
TRIAL PIT 7 - OUTSIDE SECURITY FENCE.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/6/95	118/5828	1
LOCATION:	AREA B	
ACTIVITY:		
'HEAT TREATMENT' OF TNT CONTAMINATED CHANNEL BLOCKS FROM EX BUILDING E2.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/6/95	118/5828	2
LOCATION:	AREA S	
ACTIVITY:		
ACID FACTORY CLEARANCE.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/6/95	118/5828	3
LOCATION:	AREAS	
ACTIVITY:		
ACID FACTORY CLEARANCE.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
27/6/95	118/5828	4
LOCATION:	AREA S	
ACTIVITY:		
ACID FACTORY CLEARANCE.		
SPECIAL FEATURES:		




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
6/7/95	118/5828	5
LOCATION:	AREA H	
ACTIVITY:		
HOPPITS PENINSULAR - TREE STUMP GRINDING MACHINE.		

SPECIAL FEATURES:


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
6/7/95	118/5828	6

LOCATION:	AREA H	
ACTIVITY:		
HOPPITS PENINSULAR - TREE STUMP GRINDING MACHINE.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
6/7/95	118/5828	7
LOCATION:	AREA M	
ACTIVITY:		
VIEW LOOKING NORTH FROM BRIDGE No. 6 SHOWING EXCAVATED CANAL.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
6/7/95	118/5828	8
LOCATION:	AREA S	
ACTIVITY:		
EXCAVATING CANAL NORTH OF BRIDGE No. 6.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
6/7/95	118/5828	9
LOCATION:	AREA T	
ACTIVITY:		
TETRYL FACTORY SITE - GENERAL VIEW LOOKING NORTH BEFORE CAPPING MATERIAL PLACEMENT.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
6/7/95	118/5828	10
LOCATION:	AREAS	
ACTIVITY:		
EAST SIDE OF BUILDING E10 LOOKING SOUTH TOWARDS ACID FACTORY.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
6/7/95	118/5828	11
LOCATION:	AREA S	
ACTIVITY:		
ACID FACTORY LOOKING SOUTH EAST.		



SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
6/7/95	118/5828	12

LOCATION:	AREAS	
ACTIVITY:		
ACID FACTORY LOOKING SOUTH.		
SPECIAL FEATURES:		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
6/7/95	118/5828	13
LOCATION:	AREA S	
ACTIVITY:		
ACID FACTORY LOOKING NORTH EAST.		
SPECIAL FEATURES:		
BUILDING E10 IN BACKGROUND.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
6/7/95	118/5828	14
LOCATION:	AREA S	
ACTIVITY:		
ACID FACTORY LOOKING NORTH.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
7/7/95	118/5828	15
LOCATION:	AREA B	
ACTIVITY:		
27MM AMMUNITION FOUND IN BURNING GROUND DIG.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
7/7/95	118/5828	16
LOCATION:	AREA B	
ACTIVITY:		
27MM AMMUNITION FOUND IN BURNING GROUND DIG.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
7/7/95	118/5828	17
LOCATION:	AREA B	
ACTIVITY:		
27MM AMMUNITION FOUND IN BURNING GROUND DIG.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
7/7/95	118/5828	18




LOCATION:	AREA B	
ACTIVITY:		
27MM AMMUNITION FOUND IN BURNING GROUND DIG.		
SPECIAL FEATURES:		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
7/7/95	118/5828	19
LOCATION:	AREA H	
ACTIVITY:		
HIGHBRIDGE STREET ENTRANCE SHOWING COMPLETED CAPPING OF ANCIEN T MONUMENT.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
7/7/95	118/5828	20
LOCATION:	AREA H	
ACTIVITY:		
HIGHBRIDGE STREET ENTRANCE AREA - CAPPING OF ANCIENT MONUMENT IN PROGRESS.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
7/7/95	118/5828	21
LOCATION:	AREA B	
ACTIVITY:		
BUILDING L101 - VIEW OF CANAL EXCAVATION LOOKING SOUTH.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
7/7/95	118/5828	22
LOCATION:	AREA B	
ACTIVITY:		
VIEW OF EXCAVATED CANAL NORTH OF BUILDING L101.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
11/7/95	118/5828	23
LOCATION:	AREA M	
ACTIVITY:		
VIEW OF CANAL CLEARANCE NORTH FROM BRIDGE No. 6.		

SPECIAL FEATURES:
BUILDING L136 TO LEFT OF SHOT.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
11/7/95	118/5828	24

LOCATION:	AREA M	
ACTIVITY:		
VIEW OF CANAL CLEARANCE SOUTH FROM BRIDGE No. 6.		
SPECIAL FEATURES:		
INCORPORATING MILLS L145 / L148 / L153 / L157 TO RIGHT OF SHOT.		



**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
11/7/95	118/5828	25
LOCATION:	AREA M	
ACTIVITY:		
FORMED ACCESS RAMP INTO CANAL BETWEEN BUILDINGS L135 AND L133.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
11/7/95	118/5828	26
LOCATION:	AREA M	
ACTIVITY:		
EAST OF BUILDING L155 - DITCH CLEARED, CONFIRMATORY SAMPLING OF BED.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/7/95	118/5828	27
LOCATION:	AREA P	
ACTIVITY:		
BRIDGE No. 2 IN PROCESS OF BEING ASSEMBLED.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/7/95	118/5828	28
LOCATION:	AREA P	
ACTIVITY:		
BRIDGE No. 2 IN PROCESS OF BEING BUILT.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
12/7/95	118/5828	29
LOCATION:	AREA P	
ACTIVITY:		
BRIDGE No. 2 - OLD BRIDGE DECK STRIPPED OFF.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
14/7/95	118/5828	30

LOCATION:	AREA P	
ACTIVITY:		
MIDDLE STREAM NORTH OF BRIDGE No. 1 PREPARATIONS FOR 'DRAIN DOWN'.		
SPECIAL FEATURES:		
CLAY DAM IN PLACE.		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
14/7/95	118/5828	31
LOCATION:	AREA P	
ACTIVITY:		
COLLECTING FISH FROM MIDDLE STREAM DURING 'PUMP DOWN' PROCEDURE.		
SPECIAL FEATURES:		



--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
14/7/95	118/5828	32
LOCATION:	AREA P	
ACTIVITY:		
BUCKET OF FISH RETRIEVED FROM MIDDLE STREAM.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
14/7/95	118/5828	33
LOCATION:	AREA P	
ACTIVITY:		
TYPICAL SPECIMEN OF FISH RETRIEVED FROM MIDDLE STREAM.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
15/7/95	118/5828	34
LOCATION:	AREA S	
ACTIVITY:		
INTERSECTION 16 - REMOVAL OF CONTAMINATED FILL.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
17/7/95	118/5828	35
LOCATION:	AREA S	
ACTIVITY:		
INTERSECTION 31 - REMOVAL OF CONTAMINATED FILL - NORTH END.		


SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
17/7/95	118/5828	36

LOCATION:	AREAS	
ACTIVITY:		
INTERSECTION 31 - REMOVAL OF CONTAMINATED FILL - SOUTH END.		
SPECIAL FEATURES:		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
17/7/95	118/5828	R
LOCATION:	AREA S	
ACTIVITY:		
INTERSECTION 16 - REMOVAL OF CONTAMINATED FILL.		
SPECIAL FEATURES:		






FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
17/7/95	119/7185	1
LOCATION:	AREA T	
ACTIVITY:		
EXPLOSIVE OBJECTS FOUND - NORTH AREA T AND BURNING GROUND.		
SPECIAL FEATURES:		

--


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
17/7/95	119/7185	2
LOCATION:	AREA T	
ACTIVITY:		
EXPLOSIVE OBJECT FOUND - NORTH AREA T.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
17/7/95	119/7185	3
LOCATION:	AREA B	
ACTIVITY:		
EXPLOSIVE OBJECT FOUND IN BURNING GROUND.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
18/7/95	119/7185	4
LOCATION:	AREA P	
ACTIVITY:		
NEW BRIDGE No. 2 IN POSITION.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
18/7/95	119/7185	5
LOCATION:	AREA M	
ACTIVITY:		
REMEDIATED CANAL EAST OF BUILDING L140 - LOOKING NORTH.		

SPECIAL FEATURES:
TEMPORARY DAM IN FOREGROUND.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
18/7/95	119/7185	6


LOCATION:	AREA M	
ACTIVITY:		
REMEDIATED CANAL EAST OF BUILDING L136 - LOOKING SOUTH.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
18/7/95	119/7185	7
LOCATION:	AREA S	
ACTIVITY:		
REMEDIATED CANAL LOOKING EAST FROM BUILDING L126 TOWARDS BRIDGE No. 8.		
SPECIAL FEATURES:		
DISCOLOURING OF WATER BY IRON PYRITES.		



--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
18/7/95	119/7185	8
LOCATION:	AREA P	
ACTIVITY:		
DE-WATERING OF STREAM EAST OF BUILDING A200.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
19/7/95	119/7185	9
LOCATION:	AREA P	
ACTIVITY:		
MACHINE AND DUMPER IN STREAM EAST OF BUILDING A203.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
19/7/95	119/7185	10
LOCATION:	AREA H	
ACTIVITY:		
PLACING BALLAST OVERLAY ON ANCIENT MONUMENT ADJACENT MILLHEAD STREAM.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
19/7/95	119/7185	11
LOCATION:	AREA H	
ACTIVITY:		
RAKING BALLAST OVERLAY ON ANCIENT MONUMENT ADJACENT		

MILLHEAD STREAM.
SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
24/7/95	119/7185	14


LOCATION:	AREA S	
ACTIVITY:		
EXCAVATED STEEL TROUGH NORTH OF BUILDING 83B IN ACID FACTORY.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
24/7/95	119/7185	15
LOCATION:	AREA S	
ACTIVITY:		
EXCAVATED TROUGH NORTH OF BUILDING 83B IN ACID FACTORY.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
24/7/95	119/7185	16
LOCATION:	AREA S	
ACTIVITY:		
EXCAVATED STEEL LINED WELL BEFORE FILLING - NORTH OF BUILDING 83B.		
SPECIAL FEATURES:		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
26/7/95	119/7185	17
LOCATION:	AREA B	
ACTIVITY:		
EXPOSED FOOTINGS IN SOUTH WEST CORNER OF BURNING GROUND.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
26/7/95	119/7185	18
LOCATION:	AREA B	
ACTIVITY:		
EXPOSED FOOTINGS IN SOUTH WEST CORNER OF BURNING GROUND.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
26/7/95	119/7185	19
LOCATION:	AREA B	
ACTIVITY:		
EXCAVATED CANAL IN BURNING GROUND.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
26/7/95	119/7185	20

LOCATION:	AREA B	
ACTIVITY:		
EXCAVATED CANAL IN BURNING GROUND NORTH OF BUILDING L101.		
SPECIAL FEATURES:		
WATER MAIN CROSSING CANAL.		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
26/7/95	119/7185	21
LOCATION:	AREA B	
ACTIVITY:		
EXPOSED ENTRANCE TO CANAL IN BURNING GROUND.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
26/7/95	119/7185	22
LOCATION:	AREA T	
ACTIVITY:		
GENERAL VIEW OF AREA T LOOKING NORTH.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
26/7/95	119/7185	23
LOCATION:	AREA T	
ACTIVITY:		
GENERAL VIEW OF AREA T LOOKING SOUTH.		
SPECIAL FEATURES:		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
26/7/95	119/7185	24
LOCATION:	AREA T	
ACTIVITY:		
GENERAL VIEW OF AREA T LOOKING SOUTH.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
26/7/95	119/7185	25
LOCATION:	AREA S	
ACTIVITY:		
EXCAVATIONS AROUND BUILDING S31 LOOKING NORTH.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
26/7/95	119/7185	26


LOCATION:	AREAS	
ACTIVITY:		
EXCAVATIONS AROUND BUILDING S31 LOOKING SOUTH.		
SPECIAL FEATURES:		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
26/7/95	119/7185	27
LOCATION:	AREA S	
ACTIVITY:		
EXCAVATIONS AROUND BUILDING S31 LOOKING SOUTH.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
28/7/95	119/7185	29
LOCATION:	AREA H	
ACTIVITY:		
EXCAVATED CANAL NORTH EAST OF H67 LOOKING SOUTH.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
28/7/95	119/7185	30
LOCATION:	AREA H	
ACTIVITY:		
EXCAVATED CANAL NORTH OF H67 LOOKING NORTH.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
28/7/95	119/7185	31
LOCATION:	AREA S	
ACTIVITY:		
EXCAVATED CANAL WEST OF BUILDING L123 LOOKING NORTH.		
SPECIAL FEATURES:		




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
29/7/95	119/7185	32
LOCATION:	AREA S	
ACTIVITY:		
INTERSECTION No. 10 REDUCED LEVEL IN TRACK AREA.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
29/7/95	119/7185	33

LOCATION:	AREAS	
ACTIVITY:		
INTERSECTION 10 - VIEW OF EXCAVATED MILLHEAD STREAM.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
29/7/95	119/7185	34
LOCATION:	AREA S	
ACTIVITY:		
INTERSECTION 10 - VIEW OF EXCAVATED MILLHEAD STREAM.		
SPECIAL FEATURES:		



**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/8/95	120/8062	1
LOCATION:	AREA B	
ACTIVITY:		
BURNING GROUND - REFILLED CANAL / EAST ENTRANCE ROAD CROSSING.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/8/95	120/8062	2
LOCATION:	AREA B	
ACTIVITY:		
BURNING GROUND - REFILLED CANAL / EAST ENTRANCE ROAD CROSSING.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/8/95	120/8062	3
LOCATION:	AREA S	
ACTIVITY:		
BUILDING S31 - REFILLED AREA AFTER REMOVAL OF TETRYL CONTAMINATED GROUND.		
SPECIAL FEATURES:		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/8/95	120/8062	4
LOCATION:	AREA S	
ACTIVITY:		
BUILDING S31 - REFILLED AREA AFTER REMOVAL OF TETRYL CONTAMINATED GROUND.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/8/95	120/8062	5
LOCATION:	AREA S	
ACTIVITY:		
BUILDING S31 - REFILLED AREA AFTER REMOVAL OF TETRYL		

CONTAMINATED GROUND.
SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/8/95	120/8062	6


LOCATION:	AREA T	
ACTIVITY:		
FORMER TETRYL FACTORY SITE - REMEDIATION COMPLETE.		
SPECIAL FEATURES:		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/8/95	120/8062	7
LOCATION:	AREA T	
ACTIVITY:		
FORMER TETRYL FACTORY SITE - REMEDIATION COMPLETE.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
10/8/95	120/8062	8
LOCATION:	AREA H	
ACTIVITY:		
EXCAVATED CANAL AT INTERSECTION No. 8.		
SPECIAL FEATURES:		
BOREHOLE No. 13 IN CENTRE OF SHOT.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
10/8/95	120/8062	9
LOCATION:	AREA H	
ACTIVITY:		
INTERSECTION No. 8 LOOKING EAST - EXCAVATED CANAL.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
10/8/95	120/8062	10
LOCATION:	AREA S	
ACTIVITY:		
BUILDING L128 EXCAVATED CANAL LOOKING SOUTH EAST.		
SPECIAL FEATURES:		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
10/8/95	120/8062	11
LOCATION:	AREA M	
ACTIVITY:		
CANAL EXCAVATION LOOKING SOUTH FROM BRIDGE No. 6.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
10/8/95	120/8062	12

LOCATION:	AREA M	
ACTIVITY:		
BUILDING L143 - SURFACE SCRAPE TO REMOVE VEGETATION FOR GROUND INSPECTION.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
10/8/95	120/8062	13
LOCATION:	AREA M	
ACTIVITY:		
SURFACE SCRAPE ADJACENT BUILDING L146.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
10/8/95	120/8062	14
LOCATION:	AREA S	
ACTIVITY:		
BRIDGE No. 8 CANAL EXCAVATION LOOKING SOUTH.		
SPECIAL FEATURES:		
BURIED BARGE UNCOVERED.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
10/8/95	120/8062	15
LOCATION:	AREA S	
ACTIVITY:		
BRIDGE No. 8 CANAL EXCAVATION LOOKING NORTH.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
10/8/95	120/8062	16
LOCATION:	AREA S	
ACTIVITY:		
BRIDGE No. 8 - REFURBISHMENT WORK.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
10/8/95	120/8062	17
LOCATION:	AREA M	
ACTIVITY:		
SURFACE SCRAPE ADJACENT BUILDING L149.		



SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
10/8/95	120/8062	18


LOCATION:	AREA M	
ACTIVITY:		
SURFACE SCRAPE ADJACENT BUILDING L151.		
SPECIAL FEATURES:		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
10/8/95	120/8062	19
LOCATION:	AREA M	
ACTIVITY:		
REMEDIATED GAS WORKS AREA (PART) ADJACENT BUILDING L155.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
10/8/95	120/8062	20
LOCATION:	AREA M	
ACTIVITY:		
REMEDIATED GAS WORKS AREA ADJACENT BUILDING L160.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
10/8/95	120/8062	21
LOCATION:	AREA M	
ACTIVITY:		
MIDDLE STREAM CANAL DREDGING BRIDGE No. 4 TO BRIDGE No. 6 - LOOKING NORTH.		
SPECIAL FEATURES:		
NOTE: RECOVERED BARGES PLACED HERE FOR PRESERVATION.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
10/8/95	120/8062	22
LOCATION:	AREA M	
ACTIVITY:		
MIDDLE STREAM CANAL DREDGING BY BRIDGE No. 5 LOOKING NORTH.		
SPECIAL FEATURES:		

CLOSE UP OF PRESERVED BARGES.



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
10/8/95	120/8062	23
LOCATION:	AREA M	
ACTIVITY:		
MIDDLE STREAM CANAL DREDGING BY BRIDGE No. 5 LOOKING SOUTH.		

SPECIAL FEATURES:
CLOSE UP OF PRESERVED BARGES.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
10/8/95	120/8062	24



LOCATION:	AREA M	
ACTIVITY:		
MIDDLE STREAM CANAL DREDGING BY BRIDGE No. 4 LOOKING SOUTH.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
10/8/95	120/8062	25
LOCATION:	AREA M	
ACTIVITY:		
MIDDLE STREAM CANAL DREDGING BY BRIDGE No. 4 LOOKING NORTH.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
10/8/95	120/8062	26
LOCATION:	AREA M	
ACTIVITY:		
MIDDLE STREAM CANAL DREDGING LOOKING WEST TOWARDS BRIDGE No. 2.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
11/8/95	120/8062	27
LOCATION:	AREA S	
ACTIVITY:		
CORDITE RECOVERED FROM CANAL AT BRIDGE No. 8.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
11/8/95	120/8062	28
LOCATION:	AREA S	
ACTIVITY:		
CORDITE REMOVED FROM CANAL AT BRIDGE No. 8.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
11/8/95	120/8062	29
LOCATION:	AREA S	
ACTIVITY:		
CORDITE IN CANAL SOUTH OF BRIDGE No.8.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
11/8/95	120/8062	30

LOCATION:	AREAS	
ACTIVITY:		
BURIED BARGE IN CANAL BY BRIDGE No. 8.		
SPECIAL FEATURES:		




**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
11/8/95	120/8062	31
LOCATION:	AREA S	
ACTIVITY:		
ACID FACTORY - CAPPING LAYERS BEING PLACED.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
11/8/95	120/8062	32
LOCATION:	AREA S	
ACTIVITY:		
ACID FACTORY - CAPPING LAYERS BEING PLACED.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
11/8/95	120/8062	33
LOCATION:	AREA S	
ACTIVITY:		
ACID FACTORY - CAPPING LAYERS BEING PLACED.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
11/8/95	120/8062	34
LOCATION:	AREA S	
ACTIVITY:		
ACID FACTORY - CAPPING LAYERS BEING PLACED.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
22/8/95	120/8062	35
LOCATION:	AREA H	
ACTIVITY:		
MILLHEAD STREAM LOCK - SITUATED NORTH OF FORMER BUILDING H67.		

SPECIAL FEATURES:
CLEAN OUT COMPLETE.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
22/8/95	120/8062	36

LOCATION:	AREA H	
ACTIVITY:		
MILLHEAD STREAM LOCK - SITUATED NORTH OF FORMER BUILDING H67.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
22/8/95	120/8062	R
LOCATION:	AREA S	
ACTIVITY:		
BRIDGE No. 8 LOOKING EAST.		
SPECIAL FEATURES:		





**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
*	121/9359	1
LOCATION:	AREA	
ACTIVITY:		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
*	121/9359	2
LOCATION:	AREA	
ACTIVITY:		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
24/8/95	121/9359	3
LOCATION:	AREA S	
ACTIVITY:		
NEW ROAD EAST OF BRIDGE No. 11 - BETWEEN BUILDING S27 AND BRIDGE No. 36.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
4/9/95	121/9359	4
LOCATION:	AREA N	
ACTIVITY:		
SUSPECT 4" SHELL BASE FOUND 65M NORTH WEST OF THE CENTRE OF BUILDING S16.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
4/9/95	121/9359	5
LOCATION:	AREA N	
ACTIVITY:		
SUSPECT 4" SHELL BASE FOUND 65M NORTH WEST OF THE CENTRE OF		

BUILDING S16.
SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
4/9/95	121/9359	6


LOCATION:	AREA N	
ACTIVITY:		
SUSPECT 4" SHELL BASE FOUND 65M NORTH WEST OF THE CENTRE OF BUILDING S16.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
4/9/95	121/9359	7
LOCATION:	AREA N	
ACTIVITY:		
CONCRETE BASE FOUND 60M NORTH WEST OF THE CENTRE OF BUILDING S16.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
4/9/95	121/9359	8
LOCATION:	AREA N	
ACTIVITY:		
'PROPELLANT' FOUND IN PIT WITHIN BUILDING S16.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
7/9/95	121/9359	10
LOCATION:	AREA M	
ACTIVITY:		
WHEEL SHOT FOR SMEATONS MILL - EAST OF MILLHEAD STREAM LOOKING NORTH.		
SPECIAL FEATURES:		
SHUTTLE PLATE FOR MILL IN FOREGROUND.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
7/9/95	121/9359	11
LOCATION:	AREA M	
ACTIVITY:		
WHEEL SHOT FOR SMEATONS MILL - EAST OF MILLHEAD STREAM LOOKING SOUTH.		
SPECIAL FEATURES:		

SHUTTLE PLATE FOR MILL IN BACKGROUND.



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
7/9/95	121/9359	12
LOCATION:	AREA M	
ACTIVITY:		
WHEEL SHOT FOR SMEATONS MILL EAST OF MILLHEAD STREAM		

LOOKING EAST.
SPECIAL FEATURES:
SHUTTLE PLATE FOR MILL IN FOREGROUND.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
8/9/95	121/9359	13

LOCATION:	AREA H	
ACTIVITY:		
GENERAL VIEW OF HOPPITS POOL LOOKING NORTH FROM BRIDGE No. 17.		
SPECIAL FEATURES:		


**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
8/9/95	121/9359	14
LOCATION:	AREA H	
ACTIVITY:		
GENERAL VIEW OF AREA H TAKEN FROM HIGHBRIDGE STREET ENTRANCE.		
SPECIAL FEATURES:		



--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/9/95	121/9359	15
LOCATION:	AREA H	
ACTIVITY:		
GENERAL VIEW NORTH EAST ACROSS THE SITE OF FORMER BUILDING H67.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/9/95	121/9359	16
LOCATION:	AREA S	
ACTIVITY:		
GENERAL VIEW NORTH OVER FORMER POWER HOUSE AREA.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/9/95	121/9359	17
LOCATION:	AREA S	
ACTIVITY:		
GENERAL VIEW SOUTH OVER FORMER POWER HOUSE AREA.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/9/95	121/9359	18
LOCATION:	AREA S	
ACTIVITY:		
GENERAL VIEW NORTH OVER FORMER 'ACID FACTORY' AREA.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/9/95	121/9359	19

LOCATION:	AREAS	
ACTIVITY:		
GENERAL VIEW NORTH EAST OVER FORMER 'ACID FACTORY' AREA.		
SPECIAL FEATURES:		


**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/9/95	121/9359	20
LOCATION:	AREA S	
ACTIVITY:		
GENERAL VIEW SOUTH WEST ACROSS FROM 83B OVER ADJACENT FOUNDATION SLABS.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/9/95	121/9359	21
LOCATION:	AREA S	
ACTIVITY:		
GENERAL VIEW SOUTH OF REMEDIATED STEAM MAIN ROUTE SOUTH OF BUILDING 83B.		
SPECIAL FEATURES:		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/9/95	121/9359	22
LOCATION:	AREA B	
ACTIVITY:		
GENERAL VIEW NORTH WEST OF BURNING GROUND.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/9/95	121/9359	23
LOCATION:	AREA S	
ACTIVITY:		
GENERAL VIEW NORTH SHOWING REMEDIATED AREA AROUND BUILDING S31.		
SPECIAL FEATURES:		



<b>FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD</b>		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/9/95	121/9359	24
LOCATION:	AREA N	
ACTIVITY:		
GENERAL VIEW SOUTH SHOWING REMEDIATED STEAM MAIN ROUTE		

SOUTH OF BUILDING S16.
SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/9/95	121/9359	25

LOCATION:	AREA N	
ACTIVITY:		
GENERAL VIEW EAST SHOWING REMEDIATED STEAM MAIN ROUTE EAST OF BUILDING S5.		
SPECIAL FEATURES:		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/9/95	121/9359	26
LOCATION:	AREA N	
ACTIVITY:		
VIEW NORTH ACROSS CLAY WINNING PIT.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/9/95	121/9359	27
LOCATION:	AREA N	
ACTIVITY:		
PROPELLANT FOUND IN VICINITY OF BUILDING S16 & SUSPICIOUS OBJECT WITH WHITE MATERIAL IN END - FOUND BY BUILDING S16.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/9/95	121/9359	28
LOCATION:	AREA L	
ACTIVITY:		
GENERAL VIEW OF QUEENS MEAD LOOKING NORTH.		
SPECIAL FEATURES:		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/9/95	121/9359	29
LOCATION:	AREA L	
ACTIVITY:		
GENERAL VIEW OF NORTH END OF QUEENS MEAD AND STEAM MAIN ROUTES - LOOKING EAST.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/9/95	121/9359	30
LOCATION:	AREA H	
ACTIVITY:		
GENERAL VIEW SOUTH EAST FROM FORMER BUILDING H67 TO THE		



LOCATION:	AREA M / S	
ACTIVITY:		
GENERAL VIEW NORTH OF THE WORKS TO THE SOUTH OF BRIDGE No. 8.		
SPECIAL FEATURES:		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/9/95	121/9359	32
LOCATION:	AREA S	
ACTIVITY:		
GENERAL VIEW LOOKING NORTH WEST TOWARDS BUILDING S33.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/9/95	121/9359	33
LOCATION:	AREA S	
ACTIVITY:		
GENERAL VIEW OF FORMER BUILDING 63 AFTER REMEDIATION.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/9/95	121/9359	34
LOCATION:	AREA S	
ACTIVITY:		
GENERAL VIEW OF CANAL AFTER REMEDIATION LOOKING NORTH TOWARDS BUILDING 22A.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/9/95	121/9359	35
LOCATION:	AREA S	
ACTIVITY:		
VIEW OF REMEDIATED CANAL WEST OF BUILDING 22A.		
SPECIAL FEATURES:		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/9/95	121/9359	36
LOCATION:	AREA P	
ACTIVITY:		
VIEW OF EAST BANK OF MIDDLE STREAM AFTER REMEDIATION.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
9/9/95	121/9359	37

LOCATION:	AREA H - ISLAND SITE	
ACTIVITY:		
WEST ELEVATION OF BUILDING A200.		
SPECIAL FEATURES:		
WINDOW BOARDED UP AFTER REMOVAL OF FRAME DUE TO DRY ROT.		




**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	A	1
LOCATION:	AREA H	
ACTIVITY:		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	A	2
LOCATION:	AREA H	
ACTIVITY:		
H16 FOUNDATION SLAB PRIOR TO USE AS WASTE SAMPLING AREA.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	A	3
LOCATION:	AREA H	
ACTIVITY:		
VIEW NORTH ACROSS H16 FOUNDATION SLAB WITH BUILDING H12 IN CENTRE OF PHOTOGRAPH.		
SPECIAL FEATURES:		
STEAM MAIN ROUTE SUPPORT POSTS.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	A	4
LOCATION:	AREA H	
ACTIVITY:		
SOUTHERLY VIEW ACROSS SITE OF FORMER BUILDING H19 WITH BUILDING H25 IN BACKGROUND.		
SPECIAL FEATURES:		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	A	5
LOCATION:	AREA H	
ACTIVITY:		
WEST VIEW ACROSS SITE OF FORMER BUILDING H19 TOWARDS		

HOUSING IN WALTON GARDENS.
SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	A	6

LOCATION:	AREA H	
ACTIVITY:		
INTERNAL VIEW OF BUILDING H12.		
SPECIAL FEATURES:		
FIRING POINT / ROCKET MOTOR TEST BED.		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	A	7
LOCATION:	AREA H	
ACTIVITY:		
NORTH ENTRANCE TO BUILDING H12.		
SPECIAL FEATURES:		
BUILDING A203 IN BACKGROUND.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	A	8
LOCATION:	AREA H	
ACTIVITY:		
HOPPITS POOL SLUICES VIEWED FROM BRIDGE No. 17.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	A	9
LOCATION:	AREA H	
ACTIVITY:		
BUILDING H8 - SOUTH ELEVATION.		
SPECIAL FEATURES:		
STEAM MAIN ROUTE IN FOREGROUND AND BACKGROUND (RIGHT).		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	A	10
LOCATION:	AREA H	
ACTIVITY:		
BUILDING H8 SOUTH ENTRANCE.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	A	11
LOCATION:	AREA H	
ACTIVITY:		
BUILDING H7 SOUTH ELEVATION.		



SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	A	12


LOCATION:	AREA H	
ACTIVITY:		
MILLHEAD LOCK SITUATED NORTH EAST OF BUILDING H67.		
SPECIAL FEATURES:		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	A	13
LOCATION:	AREA S	
ACTIVITY:		
MILLHEAD STREAM NORTH OF MILLHEAD LOCK.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
OCT '92	A	14
LOCATION:	AREA S	
ACTIVITY:		
TYPICAL WASTE TIP SITUATED WITHIN SSSI.		
SPECIAL FEATURES:		




FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
SEPT '91	B	1
LOCATION:	AREA P	
ACTIVITY:		
AREA P SOUTH - LOOKING NORTH.		
SPECIAL FEATURES:		
BUILDING A238 TO RIGHT OF SHOT.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
SEPT '91	B	3
LOCATION:	AREA M	
ACTIVITY:		
SOUTH ELEVATION OF BUILDING L137.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
SEPT '91	B	4
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L149 PART EAST ELEVATION.		
SPECIAL FEATURES:		
MILLSTONE IN FOREGROUND.		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
SEPT '91	B	5
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L149 SOUTH ELEVATION.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
SEPT '91	B	6
LOCATION:	AREA L / M	
ACTIVITY:		
NORTHERN VIEW ACROSS QUEENS MEAD TOWARDS BUILDING L148.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
SEPT '91	B	7

LOCATION:	AREAS	
ACTIVITY:		
BRIDGE No. 29 - EAST OF BUILDING L136.		
SPECIAL FEATURES:		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
SEPT '91	B	8
LOCATION:	AREA S	
ACTIVITY:		
BARGES NORTH OF BUILDING L136.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
SEPT '91	B	9
LOCATION:	AREA S	
ACTIVITY:		
BARGE ADJACENT TO BUILDING L111.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
SEPT '91	B	10
LOCATION:	AREA S	
ACTIVITY:		
BARGE ADJACENT TO BUILDING L111.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
SEPT '91	B	11
LOCATION:	AREAS	
ACTIVITY:		
BUILDING L109 TRAVERSE.		
SPECIAL FEATURES:		




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
SEPT '91	B	12
LOCATION:	AREA M	
ACTIVITY:		
EAST ELEVATION OF BUILDING L108 AND ASBESTOS LAGGED STEAM		

MAIN PIPE (IN FOREGROUND).
SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
SEPT '91	B	13

LOCATION:	AREAS	
ACTIVITY:		
BUILDING L199 (SOUTH WEST CORNER).		
SPECIAL FEATURES:		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
SEPT '91	B	14
LOCATION:	AREA B	
ACTIVITY:		
TIP REF.: 11038 NORTH OF BURNING GROUND.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
SEPT '91	B	15
LOCATION:	AREA S	
ACTIVITY:		
TYPICAL EARTH CLOSET ADJACENT BUILDING U9.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
SEPT '91	B	16
LOCATION:	AREA S	
ACTIVITY:		
TYPICAL CHEMICAL TOILET.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
SEPT '91	B	17
LOCATION:	AREAS	
ACTIVITY:		
'BARREL GRAVEYARD'.		
SPECIAL FEATURES:		

TYPICAL VIEW OF ROTTING STEEL BARRELS.



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
SEPT '91	B	18
LOCATION:	AREA H	
ACTIVITY:		
WEST ELEVATION OF BUILDING H26.		



SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
SEPT '91	B	19

LOCATION:	AREAS	
ACTIVITY:		
WATER POWERED PRESS HOUSE - BUILDING 103.		
SPECIAL FEATURES:		
HYDRAULIC GUNPOWDER PRESS.		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
SEPT '91	B	20
LOCATION:	AREA S	
ACTIVITY:		
WATER POWERED PRESS HOUSE - BUILDING 103.		
SPECIAL FEATURES:		
INTERNAL VIEW OF WATER WHEEL DRIVE SHAFT.		

--


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
SEPT '91	B	21
LOCATION:	AREA S	
ACTIVITY:		
WATER POWERED PRESS HOUSE - BUILDING 103.		
SPECIAL FEATURES:		
WATER WHEEL AND SUSPICIOUS CANISTER.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
SEPT '91	B	22
LOCATION:	AREA S	
ACTIVITY:		
INFORMAL TIP.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
SEPT '91	B	23
LOCATION:	AREA S	
ACTIVITY:		
INFORMAL TIP - VARIOUS CONSTITUENTS INCLUDING CHEMICAL / LABORATORY WARE.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
SEPT '91	B	24
LOCATION:	AREA B	
ACTIVITY:		
BURNING GROUND - LOOKING NORTH EAST.		

SPECIAL FEATURES:
TIP REF.: 11038 IN BACKGROUND.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
SEPT '91	B	24a



LOCATION:	AREA S	
ACTIVITY:		
PART VIEW LOOKING WEST ACROSS ACID FACTORY.		
SPECIAL FEATURES:		
SUPPORT STEELWORK FROM SOME EXPERIMENTAL USAGE OF THIS AREA.		




**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
SEPT'91	C	1
LOCATION:	AREA	
ACTIVITY:		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
SEPT'91	C	9
LOCATION:	AREA S	
ACTIVITY:		
MILLHEAD STREAM.		
SPECIAL FEATURES:		
BURIED ASBESTOS SHEETING.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
SEPT'91	C	10
LOCATION:	AREAS	
ACTIVITY:		
ENTRANCE TO BUILDING E2.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
SEPT'91	C	11
LOCATION:	AREA S	
ACTIVITY:		
BUILDING S31.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
SEPT'91	C	12
LOCATION:	AREAS	
ACTIVITY:		
BUILDING E2.		

SPECIAL FEATURES:
TREES GROWING IN 'CHUTE' EXIT AREA.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
SEPT'91	C	13




LOCATION:	AREAS	
ACTIVITY:		
NITRO GLYCERINE CHUTE - BUILDING E2 - E3.		
SPECIAL FEATURES:		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
SEPT'91	C	14
LOCATION:	AREAS	
ACTIVITY:		
BUILDING E2, NITRO GLYCERINE POPPING POND.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
SEPT'91	C	15
LOCATION:	AREA S	
ACTIVITY:		
BUILDING E3 (INTERNAL).		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
SEPT'91	C	16
LOCATION:	AREA S	
ACTIVITY:		
PART FILLED CANAL ADJACENT BUILDING 62.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
SEPT'91	C	17
LOCATION:	AREAS	
ACTIVITY:		
BUILDING 73 - EDMONSEY MEAD.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
SEPT'91	C	18
LOCATION:	AREA S	
ACTIVITY:		
TRAVERSE 76 (ADJACENT BUILDING E14).		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
SEPT'91	C	19

LOCATION:	AREAS	
ACTIVITY:		
BARGE 101 NEAR TRAVERSE 76.		
SPECIAL FEATURES:		



**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDICATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
SEPT'91	C	20
LOCATION:	AREAS	
ACTIVITY:		
BARGE 101 (INTERNAL).		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
SEPT'91	C	21
LOCATION:	AREA S	
ACTIVITY:		
BRIDGE No. 15.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
SEPT'91	C	22
LOCATION:	AREA H - ISLAND SITE	
ACTIVITY:		
BUILDINGS A201 / 202.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
SEPT'91	C	23
LOCATION:	AREA N	
ACTIVITY:		
BUILDING S16 SOUTH ELEVATION.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
SEPT'91	C	24
LOCATION:	AREA N	
ACTIVITY:		
NEW HILL - LOOKING SOUTH.		


SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
SEPT'91	D	1
LOCATION:	AREA N	
ACTIVITY:		
BUILDING S25 CHANNEL.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
SEPT'91	D	2
LOCATION:	AREA N	
ACTIVITY:		
CHANNEL EXITING BUILDING S16 (WEST).		
SPECIAL FEATURES:		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
SEPT'91	D	3
LOCATION:	AREA N	
ACTIVITY:		
INTERNAL VIEW OF BUILDING S25.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
SEPT'91	D	4
LOCATION:	AREA N	
ACTIVITY:		
NEW HILL - BUILDING S16 ENTRANCE.		
SPECIAL FEATURES:		

STEAM MAIN ROUTE POSTS VISIBLE.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
SEPT'91	D	5
LOCATION:	AREA N	
ACTIVITY:		
MANHOLE NEAR BUILDING S16.		

SPECIAL FEATURES:


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
SEPT'91	D	6

LOCATION:	AREA N	
ACTIVITY:		
CATTLEGATE WAY LOOKING EAST.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
SEPT'91	D	7
LOCATION:	AREA N	
ACTIVITY:		
NEW HILL - BUILDINGS S10 AND S11.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
SEPT'91	D	8
LOCATION:	AREA N	
ACTIVITY:		
NEW HILL - BUILDING S13.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
SEPT'91	D	9
LOCATION:	AREA N	
ACTIVITY:		
NEW HILL - BUILDING S5 LOOKING WEST ALONG CATTLEGATE WAY.		
SPECIAL FEATURES:		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
SEPT'91	D	10
LOCATION:	AREAS	
ACTIVITY:		
GRAND MAGAZINE.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
SEPT'91	D	16
LOCATION:	AREA P	
ACTIVITY:		
SOCIAL CLUB - BUILDING A250.		

SPECIAL FEATURES:


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
SEPT'91	D	17

LOCATION:	AREA P	
ACTIVITY:		
AREA P TENNIS COURTS.		
SPECIAL FEATURES:		

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
SEPT'91	D	18
LOCATION:	AREA P	
ACTIVITY:		
VIEW NORTH TOWARDS BUILDING A282.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
SEPT'91	D	19
LOCATION:	AREA P	
ACTIVITY:		
TENNIS COURTS.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
SEPT'91	D	20
LOCATION:	AREA P	
ACTIVITY:		
BUILDING A210.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
SEPT'91	D	21
LOCATION:	AREA P	
ACTIVITY:		
BUILDING A210.		
SPECIAL FEATURES:		




FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
SEPT'91	D	22
LOCATION:	AREA P	
ACTIVITY:		
BUILDINGS A210 AND A214.		

SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
SEPT'91	D	23


LOCATION:	AREA P	
ACTIVITY:		
BUILDING A214 (TO RIGHT OF SHOT) WITH BUILDING A221 IN DISTANCE.		
SPECIAL FEATURES:		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
SEPT'91	D	24
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L162 IN BACKGROUND (CORDITE CONTAMINATED AREA).		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
SEPT'91	D	25
LOCATION:	AREA M	
ACTIVITY:		
BUILDING L160 IN THE GASWORKS AREA.		
SPECIAL FEATURES:		



**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
SEPT' 91	E	1
LOCATION:	AREA H - ISLAND SITE	

ACTIVITY:


NORTH ELEVATION OF BUILDING A200.

SPECIAL FEATURES:

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
SEPT' 91	E	2
LOCATION:	AREA M	
ACTIVITY:		
EAST ELEVATIONS OF BUILDINGS L176 AND L168.		
SPECIAL FEATURES:		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
SEPT' 91	E	3
LOCATION:	AREA M	
ACTIVITY:		
LOOKING NORTH AT ROUNDABOUT WITH LONG WALK IN BACKGROUND.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
SEPT' 91	E	4
LOCATION:	AREA M	
ACTIVITY:		
LOOKING EAST AT ROUNDABOUT WITH AREA H IN BACKGROUND.		
SPECIAL FEATURES:		


FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
SEPT '91	E	5
LOCATION:	AREA M	
ACTIVITY:		
BRIDGE No. 4.		

BUILDING L167. BUILDING L170.
SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
SEPT' 91	E	6

LOCATION:	AREA L	
ACTIVITY:		
LONG WALK LOOKING NORTH.		
SPECIAL FEATURES:		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
SEPT' 91	E	7
LOCATION:	AREA H	
ACTIVITY:		
VIEW LOOKING SOUTH ACROSS AREA H FROM HOPPITS ROAD - BUILDING H8 TO RIGHT OF SHOT.		
SPECIAL FEATURES:		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
SEPT' 91	E	8
LOCATION:	AREA S	
ACTIVITY:		
ASBESTOS FOUND LYING ON SURFACE. (GENERAL PROBLEMS WHERE OVERGROWN STEAM MAIN ROUTES AREA).		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
SEPT' 91	E	9
LOCATION:	AREA H	
ACTIVITY:		
MILLHEAD LOCK.		
SPECIAL FEATURES:		





FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
SEPT' 91	E	10
LOCATION:	AREA H	
ACTIVITY:		
BUILDING H67 SOUTH ELEVATION.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
SEPT' 91	E	11
LOCATION:	AREA H	
ACTIVITY:		
VIEW OF NORTH ELEVATIONS OF BUILDINGS H17 AND H10 VIEWED FROM		

BUILDING H8.
SPECIAL FEATURES:
STEAM MAIN ROUTE.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
SEPT' 91	E	12

LOCATION:	AREA H /M	
ACTIVITY:		
ROUNDAABOUT VIEWED FROM BUILDING H8 AND HOPPIT ROAD.		
SPECIAL FEATURES:		
STEAM MAIN ROUTE.		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
SEPT' 91	E	13
LOCATION:	AREA H	
ACTIVITY:		
BUILDINGS H17 AND H10 VIEWED FROM BUILDING H8.		
SPECIAL FEATURES:		
STEAM MAIN ROUTES.		

--

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
SEPT' 91	E	14
LOCATION:	AREA H	
ACTIVITY:		
OVER GROWN CANAL NORTH OF HOPPITS POOL.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
SEPT' 91	E	15
LOCATION:	AREA H	
ACTIVITY:		
NORTH OF HOPPITS POOL - BUILDING A292 IN BACKGROUND.		
SPECIAL FEATURES:		
STEAM MAIN ROUTE.		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
SEPT' 91	E	16
LOCATION:	AREA H	
ACTIVITY:		
NORTH OF HOPPITS POOL.		
SPECIAL FEATURES:		



STEAM MAIN ROUTE.



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
SEPT' 91	E	17
LOCATION:	AREA H	
ACTIVITY:		
BUILDING H72 AND H10 - NORTH ELEVATIONS.		


SPECIAL FEATURES:
STEAM MAIN ROUTE.

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDICATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
SEPT' 91	E	18


LOCATION:	AREA H	
ACTIVITY:		
BUILDING H12 - LOOKING SOUTH.		
SPECIAL FEATURES:		
STEAM MAIN ROUTE.		

**FORMER RARDE WALTHAM ABBEY NORTH SITE  
REMEDIATION RECORD**

DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
SEPT' 91	E	19
LOCATION:	AREA H	
ACTIVITY:		
BUILDING H13 - LOOKING SOUTH TOWARDS HIGHBRIDGE STREET.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
SEPT' 91	E	20
LOCATION:	AREA P	
ACTIVITY:		
NORTH AREA P - BUILDING A234 TO RIGHT OF PICTURE.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
SEPT' 91	E	21
LOCATION:	AREA B	
ACTIVITY:		
BURNING GROUND - BUILDINGS L102 AND L103 IN BACKGROUND.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
SEPT' 91	E	22
LOCATION:	AREA T	
ACTIVITY:		
TETRYL FACTORY AREA - SUSPECT PIT.		
SPECIAL FEATURES:		



FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
SEPT' 91	E	23
LOCATION:	AREA S	
ACTIVITY:		
TETRYL FACTORY AREA LOOKING SOUTH.		



SPECIAL FEATURES:

FORMER RARDE WALTHAM ABBEY NORTH SITE REMEDIATION RECORD		
DATE:	NEGATIVE REFERENCE:	FRAME REFERENCE:
SEPT' 91	E	24

LOCATION:	AREA B	
ACTIVITY:		
BURNING GROUND LOOKING SOUTH - BUILDING L102 TO RIGHT OF PICTURE.		
SPECIAL FEATURES:		





RARDE-ESG-Photo-Log-Disk-7-Backup-FileList

13/09/1995	18:36	361,118	REMREC5.SAM
14/09/1995	13:40	415,637	REMREC6.SAM
15/09/1995	15:02	224,027	SPAREPH1.SAM
15/09/1995	14:59	223,636	SPAREPH2.SAM
15/09/1995	14:54	223,007	SPAREPH3.SAM

RARDE-ESG-Photo-Log-Disk-8-Backup-FileList

15/09/1995	14:53	224,581	SPAREPH4.SAM
15/09/1995	14:51	225,850	SPAREPH5.SAM
15/09/1995	11:58	237,580	SPAREPH6.SAM

RARDE-ESG-Photo-Log-Disk-9-Backup-FileList

26/08/1995	13:39	375,807	REMREC.SAM
02/09/1995	09:42	343,474	REMREC2.SAM
12/09/1995	13:20	331,333	REMREC3.SAM
12/09/1995	14:38	326,999	REMREC4.SAM